Palm Beach County Fleet Management Asset Maintenance History 10199116 2016 FORD F150 Pickup, 1/2 Ton

Total Hours: 81.05 Labor: 5,330.50 Parts: 3,455.79 Comm: 1,117.07 Charged: 9903.36

Work Order: 1600608 Meter: 328 In Date: 01/20/2016 Closed: 01/20/2016

Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1603910 Meter: 5270 In Date: 04/14/2016 Closed: 04/22/2016

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. Service.		5w20 Engine Oil	5w20 Engine Oil	
- Rotate and balance all tires.		Washer Fluid Con	centr	1.00
- Shop Supplies		Napagold Oil Filte	er	1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 21.89	Total: 201.89

Work Order: 1607660 Meter: 9900 In Date: 07/27/2016 Closed: 07/29/2016

Problem: P.M. service

Work Completed	d .		Parts Issued	Quantity
- P.m. Service.			5w20 Engine Oil	6.00
- Rotate and bala	ance all tires.		Napagold Oil Filter	1.00
- Shop Supplies			Wd40 16oz	1.00
			Shop Supplies	1.00
	Hours: 3.00	Comm: 0.00	Labor: 180.00 Parts: 2	24.89 Total: 204.89

Palm Beach County Fleet Management Asset Maintenance History 10199116 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 1611522 Meter: 15433 In Date: 11/08/2016 Closed: 11/29/2016

Problem: P.M. Service.

Work Completed		Parts Issued		Quantity
- P.m. Service.		5w20 Engine Oil		7.00
- Rotate and balance all tires.		Napagold Oil Filter		1.00
- Shop Supplies		Washer Fluid Conce	entr	1.00
		Used Fire X Refurbished		1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 38.35	Total: 218.35

Work Order: 1702408 Meter: 20053 In Date: 03/09/2017 Closed: 03/30/2017

Problem: P.M. service ,trailer not charging,topper side doors hard to lock,recall 16B32.

Work Completed	Parts Issued	Quantity
- P.m. Service.	5w20 Engine Oil	7.00
- Rotate and balance tires.	Napagold Oil Filter	1.00
- Replace and rewire corroded trailer plug.	Napagold Air Filter	1.00
- Check side doors on topper.adjust and lube latches.	22" Wiper Blade	2.00
- Transport vehicle to dealer for recall #16s32	Washer Fluid Concentr	1.00
- Shop Supplies	Floor Mat-2pc Rub Bk	1.00
	Shop Supplies	1.00
Hours: 6.75 Comm: 0.0	00 Labor: 405.00 Parts: 65.92	Total: 470.92

Work Order: 1706616 Meter: 24582 In Date: 07/06/2017 Closed: 07/10/2017

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service.		5w20 Engine Oil		7.00
- Rotate and high speed balance all four tires.		Napagold Oil Filte	r	1.00
- Shop Supplies		22" Wiper Blade		2.00
		Used Fire X Refurb	pished	1.00
		Stg Wheel Cov - F	ord	1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 58.18	Total: 238.18

Palm Beach County Fleet Management Asset Maintenance History 10199116 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 1709185 Meter: 27359 In Date: 09/21/2017 Closed: 09/21/2017

Problem: 2 - Wash ticket(s) issued

Work Completed

- 2 - Wash ticket(s) issued

Hours: 0.00 Comm: 19.08 Labor: 0.00 Parts: 0.00 Total: 19.08

Labor: 60.00

Parts: 2.00

Total: 62.00

Work Order: 1710716 Meter: 29565 In Date: 10/31/2017 Closed: 11/09/2017

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service.		5w20 Engine Oil		6.00
- Rotate and balance four tires.nitrofill.		Napagold Oil Filte	r	1.00
- Shop Supplies		22" Wiper Blade		2.00
		Washer Fluid Cond	centr	1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 27.01	Total: 207.01

Work Order: 1801064 Meter: 32805 In Date: 01/29/2018 Closed: 01/30/2018

Problem: Right front tire going flat.

Hours: 1.00

Work Completed	Parts Issued	Quantity
- Repair right front tire and balance.	Shop Supplies	1.00
- Shop Supplies		

Comm: 0.00

Palm Beach County Fleet Management Asset Maintenance History 10199116 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 1802445 Meter: 34739 In Date: 03/05/2018 Closed: 03/15/2018

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service.		5w20 Engine Oil		7.00
- Replace broken glove box stop with new.		Napagold Oil Filte	r	1.00
- Fabricate and install rear light bar inside trucl	k bed topper .install light bar	Washer Fluid Cond	centr	1.00
switch box inside cab and wire all . - Repair right rear tire and rotate and balance all four .		22" Wiper Blade		2.00
		Primary Wire		3.00
- Shop Supplies		Fab Loom-split Po	ly	4.00
		Retainer Glove		1.00
		Sleeve Glove Box		1.00
		8 Pod Light Bar Bracket Switch Panel Shop Supplies		1.00
				2.00
				1.00
				1.00
		Freight Charge		1.00
		Freight Charge		1.00
Hours: 8.30	Comm: 0.00	Labor: 498.00	Parts: 765.90	Total: 1,263.90

Work Order: 1803052 Meter: 35019 In Date: 03/22/2018 Closed: 03/22/2018

Problem: 2 - Wash ticket(s) issued

Work Completed

- 2 - Wash ticket(s) issued

Hours: 0.00 Comm: 19.08 Labor: 0.00 Parts: 0.00 Total: 19.08

Palm Beach County Fleet Management Asset Maintenance History 10199116 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 1806083 Meter: 40028 In Date: 06/14/2018 Closed: 06/28/2018

Problem: PM Service, Replace wipers

Work Completed		Parts Issued		Quantity
P.m. Service.Replace and balance four new tires.Complete wheel alignment.test drive.		Napagold Oil Filte	r	1.00
		5w20 Engine Oil Used Fire X Refurbished		7.00
				1.00
- Shop Supplies		22" Wiper Blade		2.00
		Washer Fluid Cond	centr	1.00
		183114470 P245-	70r17	4.00
		Napagold Oil Filte	r	1.00
		Shop Supplies		1.00
		Tire Disposal Fee		4.00
Hours: 6.50	Comm: 0.00	Labor: 390.00	Parts: 872.73	Total: 1,262.73

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filte	r	1.00
- Rotate and high speed balance all four tires. Nitrofill a	ıll.	Napa Quart 5w20		7.00
- Shop Supplies		22" Wiper Blade		2.00
		Napagold Air Filte	er	1.00
		Used Fire X Refurb	pished	1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 201.00	Parts: 65.27	Total: 266.27

Palm Beach County Fleet Management Asset Maintenance History 10199116 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 1902382 Meter: 49789 In Date: 03/04/2019 Closed: 03/13/2019

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
 P.m. service. Pressure test and inspect cooling system . Flush and refill coolant . Rotate and high speed balance all four tires . Nitrofill all. Shop Supplies 		Napagold Oil Filter 5w20 Engine Oil 22" Wiper Blade Anti Freeze Motorcraft		1.00
				6.00
				2.00
				2.00
		Shop Supplies		1.00
Hours: 5.00	Comm: 0.00	Labor: 335.00	Parts: 84.69	Total: 419.69

Work Order: 1908919 Meter: 54133 In Date: 08/26/2019 Closed: 09/11/2019

Problem: P.M. Service.

Work Completed		Parts Issued		Quantity
- P.m. service.		Drain Plug		1.00
 Perform battery analizing load and charge test . Battery failed . R&r defective battery . Rotate and high speed balance all four tires . Nitrofill all. Shop Supplies 		Napagold Oil Filter		1.00
		5w20 Engine Oil		6.00
		22" Wiper Blade Washer Fluid Concentr Used Fire X Refurbished Battry Motorcraft		2.00
				1.00
				1.00
				1.00
		Shop Supplies		1.00
Hours: 4.00	Comm: 0.00	Labor: 268.00	Parts: 227.76	Total: 495.76

Work Order: 1910237 Meter: 54268 In Date: 10/03/2019 Closed: 10/03/2019

Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 9.54 Labor: 0.00 Parts: 0.00 Total: 9.54

Palm Beach County Fleet Management Asset Maintenance History 10199116 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 2002015 Meter: 56106 In Date: 02/27/2020 Closed: 03/05/2020

Problem: PM Service

Work Completed		Parts Issued		Quantity	
- P.m. service.		Napagold Oil Filte	r	1.00	
Replace cabin air filter and clean fresh air intake .Rotate and high speed balance all four tires . Nitrofill all.		5w20 Engine Oil Engine Oil Stop Leak		6.00 1.00	
	V	1.00			
		22" Wiper Blade		2.00	
		Cabin Air Filter Ford Triton Pvc Swc		1.00	
				1.00	
		Shop Supplies		1.00	
Hours: 3.50	Comm: 0.00	Labor: 255.50	Parts: 87.09	Total: 342.59	

Problem: P.M .service and recalls 17S33 and 18S27.

Work Completed	Parts Issued	Quantity
- P.m. service.	Macs Battery Cleaner	1.00
- Rotate and balance all four tires . Nitrofill all.	Mac Wite Lithium Gres	1.00
- Transport to and from dealerfor recalls 17s33, 18s27 and rear main seal oil	22" Wiper Blade	2.00
leak .	Used Fire X Refurbished	1.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Shop Supplies	1.00
Hours: 5.00 Comm: 0.00	Labor: 365.00 Parts: 40.74	Total: 405.74

Palm Beach County Fleet Management Asset Maintenance History 10199116 2016 FORD F150 Pickup, 1/2 Ton

Work Order:	2102568	Meter:	61346		In Date:	03/08/2021 Closed:	03/15/2021
Problem:	P.M. service and rear end damage .						
Work Com	pleted			Parts Issued		Q	uantity

work Completed		raits issueu		Quantity
- Preventive Maint. Service		Napagold Oil Filter		1.00
- Rotate and speed balance all four tires , nitro fill - Check circuit to strobe light switch, inop. R & I new strobe switch		5w20 Engine Oil Washer Fluid Concentr		6.00 1.00
Led Rocker Switch Round		1.00		
		Shop Supplies		1.00
Hours: 3.50	Comm: 0.00	Labor: 255.50	Parts: 36.91	Total: 292.41

Work Order: 2104979 Meter: 61612 In Date: 03/16/2021 Closed: 05/04/2021

Problem: damage to rear bumper & cover

Work Completed

- damage to rear bumper & cover

Hours: 0.00 Comm: 1,069.37 Labor: 0.00 Parts: 0.00 Total: 1,069.37

Work Order: 2109505 Meter: 62025 In Date: 08/31/2021 Closed: 08/31/2021

Problem: right rear tire going flat

Work Completed		Parts Issued		Quantity
- Repair right rear tire and balance . Nitro fill all.		Shop Supplies		1.00
- Shop Supplies				
Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 2.65	Total: 75.65

Palm Beach County Fleet Management Asset Maintenance History 10199116 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 2110397 Meter: 63158 In Date: 09/27/2021 Closed: 10/06/2021

Problem: PM Service.

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	Napagold Oil Filter	1.00
- Check all, R & I two new tires on front, Rotate and speed balance, nitro	5w20 Engine Oil	6.00
- Perform complete alignment, road test	Washer Fluid Concentr	1.00
- Shop Supplies	22" Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	245/70/17 Tire Mich	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours: 6.50 Comm: 0.00	Labor: 474.50 Pa	arts: 450.31 Total: 924.81

Work Order: 2202776 Meter: 65698 In Date: 03/15/2022 Closed: 03/17/2022

Problem: PM Service.

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	Napagold Oil Filter	1.00
- Check all, R & I two new on front, rotate and speed balance, nitro ill	5w20 Engine Oil	6.00
- Check & R & I new cabin filter	Washer Fluid Concentr	1.00
- heck and R & I new rear brake, Resurface both rear rotors, service calipe	22" Wiper Blade	2.00
slide pins, Bleed brakes, road test	245/70/17 Tire Mich	2.00
- Shop Supplies	Cabin Air Filter	1.00
	Brake Pad	1.00
	Brk Fluid Dot 4-12oz	1.00
	Non-chlor Brake Clnr	1.00
	lube	1.00
	Permatex	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours: 8.00 Comm: 0.00	Labor: 584.00 Parts: 583.53	Total: 1,167.53

Palm Beach County Fleet Management Asset Maintenance History 10199116 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 2203456 Meter: 65698 In Date: 03/30/2022 Closed: 03/30/2022

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 81.05 Total Labor: 5,330.50 Total Comm: 1,117.07 Total Parts: 3,455.79