

2/1/2017
9:52:45AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10125257 1999 CROSLEY CR81X22TG Trailer, 81" X 22 Ft., Dual Axle

Workorder: 32993

Problem: TOOL BOX

Meter Reading: 0	Labor	Parts
In Date: 01/13/2000	Hours	Description
Close Date: 02/08/2000		Quantity
- Mount Tool Box	1.50	SHOP SUPPLIES
- Welding Supplies		TOOL BOX 1701285
Parts Charge: 502.75	Labor Charge: 67.50	

Workorder: 35734

Problem: PRE-DELIVERY

Meter Reading: 0	Labor	Parts
In Date: 03/03/2000	Hours	Description
Close Date: 03/03/2000		Quantity
- Pre-Delivery Inspection (Heavy Equipment)	2.00	
Parts Charge: 0.00	Labor Charge: 90.00	

Workorder: 36004

Problem: CHARGE OUT 2/5.16 HITCH ACCESSORIES

Meter Reading: 0	Labor	Parts
In Date: 03/09/2000	Hours	Description
Close Date: 03/21/2000		Quantity
- Parts Only		PINTLE HITCH ASSY
Parts Charge: 49.50	Labor Charge: 0.00	

Workorder: 37708

Problem: RELOCATE WINCH

Meter Reading: 0	Labor	Parts
In Date: 04/10/2000	Hours	Description
Close Date: 04/13/2000		Quantity
- Relocate Winch.	5.00	1/8X1-1/2X24 SQ TUBING
- Welding Supplies		1/2X5X20 STEEL FLAT BAR
		1/8 4X8 SHEET STEEL
		3/8X3X20 STEEL FLAT BAR
		SHOP SUPPLIES
		T-29 YELLOW PAINT SCHOOL BUS
		T-235 GRAY PRIMER
Parts Charge: 81.03	Labor Charge: 225.00	

2/1/2017
9:52:45AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10125257 1999 CROSLEY CR81X22TG Trailer, 81" X 22 Ft., Dual Axle

Workorder: 39457

Problem: TRAILER BRAKES LOCK UP

Meter Reading: 0	Labor	Parts	Quantity
In Date: 05/12/2000	Hours	Description	
- Check Wire Harness. Check Brakes & Brake Actuators. All Systems O.K. Found Brake Box Out Of Adjustment In Vehicle	1.00		
Parts Charge:	0.00	Labor Charge:	45.00

Workorder: 140280

Problem: CHECK LIGHTS

Meter Reading: 0	Labor	Parts	Quantity
In Date: 05/24/2001	Hours	Description	
- Check All Lights. R/R Right Rear Tail Light Bulb.	0.50		
Parts Charge:	0.00	Labor Charge:	22.50

Workorder: 150991

Problem: FLAT TIRE

Meter Reading: 0	Labor	Parts	Quantity
In Date: 11/30/2001	Hours	Description	
- Plug & Patch Several Holes In Tire.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	50.00

Workorder: 151417

Problem: TRAILER PLUG PULLED OFF

Meter Reading: 0	Labor	Parts	Quantity
In Date: 12/07/2001	Hours	Description	
- Repaired Trailer Connector. Checked All Lights. R/R Bulbs As Needed. Repaired Open In R/R Tail Lamp Wiring.	1.50	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	75.00

2/1/2017
9:52:45AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10125257 1999 CROSLEY CR81X22TG Trailer, 81" X 22 Ft., Dual Axle

Workorder: 232405 **Problem:** PM SERVICE SEE NOTE

Meter Reading: 0	Labor	Parts
In Date: 01/07/2002	Hours	Description
Close Date: 01/16/2002		Quantity
- P.M. Service	9.00	1.00
- Replaced Winch & Cable & All Related Parts.		1.00
- Travel From Sr Shop To Pick Up Parts.		1.00
- Replace 4 Tires		1.00
- Parts Onlytires		4.00
- Shop Supplies		1.00
Parts Charge: 419.99		Labor Charge: 450.00

Workorder: 234662 **Problem:** LEFT TAIL LIGHT OUT

Meter Reading: 0	Labor	Parts
In Date: 02/12/2002	Hours	Description
Close Date: 02/19/2002		Quantity
- Wire To Light, Repair Contact.	0.50	
Parts Charge: 0.00		Labor Charge: 25.00

Workorder: 236826 **Problem:** CHECK ALL LIGHTS

Meter Reading: 0	Labor	Parts
In Date: 03/21/2002	Hours	Description
Close Date: 03/28/2002		Quantity
- Test Light Circuits. Found Damaged Tail Lamp Causing Short. R/R Lamp & Bracket Assembly.	2.50	1.00
- Travel From Sr Shop To Pick Up Parts.		1.00
- Shop Supplies		1.00
Parts Charge: 9.97		Labor Charge: 125.00

Workorder: 237189 **Problem:** RIGHT TAIL LIGHT OUT

Meter Reading: 0	Labor	Parts
In Date: 03/27/2002	Hours	Description
Close Date: 03/28/2002		Quantity
- Check All Lights. Trace Wiring For Turn Signal. Replace Bulbs As Required.	1.00	1.00
- Shop Supplies		
Parts Charge: 2.00		Labor Charge: 50.00

2/1/2017
9:52:45AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10125257 1999 CROSLEY CR81X22TG Trailer, 81" X 22 Ft., Dual Axle

Workorder: 243552

Problem: CHECK LIGHTS

Meter Reading: 0	Labor	Parts	
In Date: 07/08/2002	Hours	Description	Quantity
- Check & Trace Wiring Harness For Opens Or Shorts In Light Circuit.Rewire Pigtail.Repair Short In Wiring Harness.Replace 2 Bulbs.	1.80	4086 SWITCH CABLE	1.00
- R/R Brake-Away Switch Cable.		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	4.94	Labor Charge:	90.00

Workorder: 247872

Problem: CHECK TRALER LIGHTS

Meter Reading: 0	Labor	Parts	
In Date: 09/16/2002	Hours	Description	Quantity
- Ck All Lights Replace Bulbs As Required	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	50.00

Workorder: 332801

Problem: PM SERVICE SEE NOTE

Meter Reading: 0	Labor	Parts	
In Date: 01/13/2003	Hours	Description	Quantity
- Pm	6.00	SHOP SUPPLIES	1.00
- Replace Rewire R-Rear Light		TAIL LIGHT 002641	1.00
- Travel From Sr Shop To Pick Up Parts			
- Shop Supplies			
Parts Charge:	8.48	Labor Charge:	300.00

Workorder: 345533

Problem: CHECK LIGHTS

Meter Reading: 0	Labor	Parts	
In Date: 08/07/2003	Hours	Description	Quantity
- Repair Tail Light(Rr)	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	50.00

2/1/2017
9:52:45AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10125257 1999 CROSLEY CR81X22TG Trailer, 81" X 22 Ft., Dual Axle

Workorder: 345824

Problem: LEFT SIDE BRAKES DRAGGING

Meter Reading: 0	Labor	Parts	Quantity
In Date: 08/12/2003	Hours	Description	
- Rr Lf Brake Drum Remove Foreign Object & Safety Ck All Brakes Adj.	1.50	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	75.00

Workorder: 349857

Problem: CHECK TIRES

Meter Reading: 0	Labor	Parts	Quantity
In Date: 10/15/2003	Hours	Description	
- Inspect Axle And Replace One Tire	1.10	SHOP SUPPLIES	1.00
- Shop Supplies		762173137 0 MTHN TRLR TIRE	1.00
Parts Charge:	80.82	Labor Charge:	55.00

Workorder: 432466

Problem: FLAT TIRE

Meter Reading: 0	Labor	Parts	Quantity
In Date: 01/07/2004	Hours	Description	
- Repair Rr Tire	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	50.00

Workorder: 432980

Problem: FLAT TIRE

Meter Reading: 0	Labor	Parts	Quantity
In Date: 01/13/2004	Hours	Description	
- Repair Rr Tire	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	50.00

2/1/2017
9:52:45AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10125257 1999 CROSLY CR81X22TG Trailer, 81" X 22 Ft., Dual Axle

Workorder: 444494

Problem: P.M SERVICE

Meter Reading: 0	Labor	Parts	
In Date: 05/13/2004	Hours	Description	Quantity
- Pm	9.00	171104 BRAKE MAGNET	4.00
- Replace 2 Tires Mount And Balance		SHOP SUPPLIES	1.00
- Replace 4 Brake Magnets One Per Wheel Clean And Adj Brakes Test Operation		ST225/75R15D TIRES	2.00
- Reweld Both And Reith Fenders Where It Connects To Frame At Front Of Fender Pull Fender Into Place			
- Shop Supplies			
Parts Charge:	257.66	Labor Charge:	450.00

Workorder: 454551

Problem: CHECK TIRES

Meter Reading: 0	Labor	Parts	
In Date: 08/19/2004	Hours	Description	Quantity
- Set Up Elpex To Replace Tire	0.50	ST225/75R15D TRAILER TIRE	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	80.82	Labor Charge:	25.00

Workorder: 454783

Problem: TIRESOLES OF BROWARD INC 072158

Meter Reading: 0	Labor	Parts	
In Date: 08/19/2004	Hours	Description	Quantity
- Tiresoles Of Broward Inc 072158			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	12.00

Workorder: 533267

Problem: R/R TIRE FLAT

Meter Reading: 0	Labor	Parts	
In Date: 01/13/2005	Hours	Description	Quantity
- Repair 1 Tire	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	4.00	Labor Charge:	50.00

2/1/2017
9:52:45AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10125257 1999 CROSLEY CR81X22TG Trailer, 81" X 22 Ft., Dual Axle

Workorder: 536499

Problem: TRAILER BRAKES NOT WORKING

Meter Reading: 0	Labor	Parts	
In Date: 02/17/2005	Hours	Description	Quantity
- Test Trailer Brake Repair Plug Connector For Trailer And Retest Brakes Operation	1.50	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	75.00

Workorder: 545803

Problem: P.M SERVICE,REPAIR TAIL GATE

Meter Reading: 0	Labor	Parts	
In Date: 05/25/2005	Hours	Description	Quantity
- Pm Service	12.00	3/4#9 RAISED EXP METAL	32.00
- Cut And Grind Welds Removed Old Metal, Cut Weld And Painted New Metal		762-173-137 MARATHAN ST225/7515D	1.00
- Replace Tire		SHOP SUPPLIES	1.00
- Shop Supplies		56521 THREAD SEALANT HI TEMP THREAD SEALANT	2.00
Parts Charge:	153.11	Labor Charge:	600.00

Workorder: 558880

Problem: CHECK TIRES

Meter Reading: 0	Labor	Parts	
In Date: 12/01/2005	Hours	Description	Quantity
- Mount Tire L/R	1.00	ST225/75R15D MARATHON	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	85.10	Labor Charge:	50.00

Workorder: 559765

Problem: RIGHT FRONT TIRE FLAT

Meter Reading: 0	Labor	Parts	
In Date: 12/16/2005	Hours	Description	Quantity
- Repair Tire	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	50.00

2/1/2017
9:52:45AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10125257 1999 CROSLEY CR81X22TG Trailer, 81" X 22 Ft., Dual Axle

Workorder: 640207 **Problem:** NAIL IN R/R TIRE

Meter Reading: 0	Labor	Parts	
In Date: 06/01/2006	Hours	Description	Quantity
- Repair Flat R / R	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	50.00

Workorder: 645695 **Problem:** R/R TIRE GOING FLAT

Meter Reading: 0	Labor	Parts	
In Date: 09/18/2006	Hours	Description	Quantity
- R&R Tire And Patch	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	50.00

Workorder: 647411 **Problem:** CHECK TRAILER LIGHTS

Meter Reading: 0	Labor	Parts	
In Date: 10/19/2006	Hours	Description	Quantity
- Repair Connection & Replace Bulb	0.75		
Parts Charge:	0.00	Labor Charge:	41.25

Workorder: 647712 **Problem:** P.M SERVICE

Meter Reading: 0	Labor	Parts	
In Date: 10/25/2006	Hours	Description	Quantity
- Pm Service	5.75	GROUP 58 BATTERY (MTC BXT-58)	1.00
- Fill Tires W/Nitrogen		BRG PKG 004645	1.00
- Service 4 Brakes; Replace R/F Bearings & Seals		DUST COVER 121041	1.00
- Shop Supplies		SEAL 058856	1.00
		SHOP SUPPLIES	1.00
		GROUP 58 BATTERY (MTC BXT-58)	-1.00
Parts Charge:	71.69	Labor Charge:	55.00

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10125257 1999 CROSLEY CR81X22TG Trailer, 81" X 22 Ft., Dual Axle

Workorder: 649751

Problem: MINOR WELD REPAIR OR MACHINING.

Meter Reading: 0	Labor	Parts
In Date: 12/11/2006	Hours	Description
Close Date: 12/11/2006		Quantity
- Minor Weld Repair Or Machining.	3.00	
Parts Charge: 0.00	Labor Charge: 82.50	

Workorder: 733935

Problem: L/REAR TIRE LOW ON AIR

Meter Reading: 0	Labor	Parts
In Date: 02/07/2007	Hours	Description
Close Date: 02/08/2007		Quantity
- Repair Nail In L/R Tire	1.00	SHOP SUPPLIES
- Shop Supplies		1.00
Parts Charge: 2.00	Labor Charge: 55.00	

Workorder: 740189

Problem: R/REAR TIRE FLAT

Meter Reading: 0	Labor	Parts
In Date: 06/18/2007	Hours	Description
Close Date: 06/19/2007		Quantity
- Diagnose & Repair Patch On R/R Tire; Add Nitrogen	1.00	SHOP SUPPLIES
- Shop Supplies		1.00
Parts Charge: 2.00	Labor Charge: 55.00	

Workorder: 741573

Problem: TAIL GATE SPRING

Meter Reading: 0	Labor	Parts
In Date: 07/17/2007	Hours	Description
Close Date: 08/30/2007		Quantity
- Tailgate Spring Broken.Replaced Springs (Both Sides)	2.00	CS100LH COIL SPRING
- Shop Supplies		CS100RH COIL SPRING
		SHOP SUPPLIES
		1.00
		1.00
		1.00
Parts Charge: 105.43	Labor Charge: 110.00	

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10125257 1999 CROSLEY CR81X22TG Trailer, 81" X 22 Ft., Dual Axle

Workorder: 745253

Problem: P.M.SERVICE/FLAT TIRE

Meter Reading: 0	Labor	Parts		
In Date: 10/05/2007	Hours	Description	Quantity	
- Pm Service	7.50	TIRE DISPOSAL FEE	2.00	
- Mount & Balance 4 Tires; Fill W/Nitrogen		TIRE DISPOSAL FEE	2.00	
- Ck & Replace Breakaway Battery		WASTE FEES	4.00	
- Replace L/F Taillight Assy		PS1250F1 BATTERY (POWER SONIC PS-1250-F1)	1.00	
- Shop Supplies		2641 RH TAIL LIGHT GROTE# 52302	1.00	
		SHOP SUPPLIES	1.00	
		TIRES 225/75R15 762173406	4.00	
Parts Charge:	440.76	Labor Charge:	45.00	

Workorder: 748921

Problem: L/SIGNAL LIIGHT INOP.

Meter Reading: 0	Labor	Parts		
In Date: 12/20/2007	Hours	Description	Quantity	
- Repair L/R Signal Light	0.50			
Parts Charge:	0.00	Labor Charge:	30.00	

Workorder: 835122

Problem: R/REAR TAIL LIGHT INOP.

Meter Reading: 0	Labor	Parts		
In Date: 03/06/2008	Hours	Description	Quantity	
- Repair R/R Trailer Wiring Circuit; Replace Bulb	1.00	SHOP SUPPLIES	1.00	
- Shop Supplies				
Parts Charge:	2.00	Labor Charge:	60.00	

Workorder: 842384

Problem: RT TAILLIGHT OUT; R/R TIRE SLOW LEAK

Meter Reading: 0	Labor	Parts		
In Date: 08/05/2008	Hours	Description	Quantity	
- C/S Right Taillight Out; R&R Bulb	1.75	SHOP SUPPLIES	1.00	
- C/S R/R Tire Has Slow Leak; Remove Nail & Patch; Mount & Addnitrogen				
- Shop Supplies				
Parts Charge:	2.00	Labor Charge:	60.00	

2/1/2017
9:52:45AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10125257 1999 CROSLEY CR81X22TG Trailer, 81" X 22 Ft., Dual Axle

Workorder: 843505 **Problem:** L/TAIL LIGHT INOP.

Meter Reading: 0	Labor	Parts
In Date: 08/29/2008	Hours	Quantity
Close Date: 08/29/2008	Description	
- Replace L/R Taillight	0.50	
Parts Charge: 0.00	Labor Charge: 30.00	

Workorder: 844379 **Problem:** P.M.SERVICE,R/REAR SIGNAL LIGHT INOP.,NEEDS TIRES

Meter Reading: 0	Labor	Parts
In Date: 09/18/2008	Hours	Quantity
Close Date: 09/29/2008	Description	
- R&R 3 Tires	12.50	3.00
- Pm Service		2.00
- R&R All Brake Assy; Clean, Repack & Replace Seals & Brgs		3.00
- Remove & Charge Breakaway Battery; Test		2.00
- Repair R/R Signal Light		1.00
- Shop Supplies		3.00
		4.00
Parts Charge: 554.30	Labor Charge: 30.00	

Workorder: 936654 **Problem:** R/FRONT TIRE BALD

Meter Reading: 0	Labor	Parts
In Date: 04/20/2009	Hours	Quantity
Close Date: 04/30/2009	Description	
- R&R R/F Tire	1.00	1.00
- Shop Supplies		1.00
		1.00
		1.00
Parts Charge: 105.26	Labor Charge: 60.00	

Workorder: 937657 **Problem:** SCREW IN TIRE/TAIL LIGHT INOP.

Meter Reading: 0	Labor	Parts
In Date: 05/12/2009	Hours	Quantity
Close Date: 05/15/2009	Description	
- Repair Screw In R/R Tire	1.75	1.00
- Repair R/R Taillight & Wiring Circuits		
- Shop Supplies		
Parts Charge: 2.00	Labor Charge: 105.00	

2/1/2017
9:52:45AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10125257 1999 CROSLEY CR81X22TG Trailer, 81" X 22 Ft., Dual Axle

Workorder: 938007

Problem: LEAF SPRINGS BAD.

Meter Reading: 0	Labor	Parts
In Date: 05/20/2009	Hours	Description
Close Date: 05/29/2009		Quantity
- Replace Clevis Slip Hooks & Grease Caps	6.00	SLIP HOOKS 2.00
- C/S Leaf Spring Bad; Verify Concern; Ck		SHOP SUPPLIES 1.00
Suspension-Found Loose Ubolts & Free Play In Whl		GREASE CAPS 2.00
Brg; Align Spring & Torque Ubolts & Whl Brgsq		
- Replace L/F Tire		
- Shop Supplies		
Parts Charge:	26.54	Labor Charge: 360.00

Workorder: 938583

Problem: BAD LEAF SPRING RT SIDE,CHECK SUSPENSION

Meter Reading: 0	Labor	Parts
In Date: 06/03/2009	Hours	Description
Close Date: 06/16/2009		Quantity
- R&R Rear Axle To Replace Rear Springs & Bolts	4.00	U-BOLT 4.00
- Shop Supplies		SHOP SUPPLIES 1.00
		SPRING 2.00
Parts Charge:	75.05	Labor Charge: 240.00

Workorder: 941456

Problem: TAIL LIGHTS INOP.

Meter Reading: 0	Labor	Parts
In Date: 07/31/2009	Hours	Description
Close Date: 07/31/2009		Quantity
- C/S Tail Lights Inop.;Repair Tail Light Wiring Harness;	1.00	SHOP SUPPLIES 1.00
Replace Light Bulb.		
- Shop Supplies		
Parts Charge:	2.00	Labor Charge: 60.00

2/1/2017
9:52:45AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10125257 1999 CROSLEY CR81X22TG Trailer, 81" X 22 Ft., Dual Axle

Workorder: 942592

Problem: check tires and axel

Meter Reading: 0	Labor	Parts		
In Date: 08/26/2009	Hours	Description	Quantity	
- Replace Both Axles ,Springs,Shackles,Wheel Bearings And Related Parts	31.00	BOLTS // 14068	14.00	
		NUTS / 4123-TLZ	14.00	
- Commercial Workorder Entry Replace All 4 Tires		SET 4 BEARING SET TIMKEN L44649/L44610	2.00	
225/75R-15 Elpex		SET 17 BEARING SET TIMKIN L68149/L68111	1.00	
- Pm Service		58856 SEAL	1.00	
- Repair Ground Circuit For Brakes		SHOP SUPPLIES	1.00	
- Nitro All Tires		AXLES 3500 LB / 35S9580	2.00	
- Shop Supplies		81733 GREASE CAP	1.00	
		TIRE	4.00	
		EQUALIZER / 14259	2.00	
		BUSHINGS / 14612	14.00	
		58856 SEAL	3.00	
Parts Charge:	709.95	Labor Charge:	1,860.00	Commercial Charge: 144.00

Workorder: 943900

Problem: SIGNAL LIGHT INOP.

Meter Reading: 0	Labor	Parts		
In Date: 09/30/2009	Hours	Description	Quantity	
- Repair Short Out In Tail Light Wiring Circuits	1.50	SHOP SUPPLIES	1.00	
- Shop Supplies				
Parts Charge:	2.00	Labor Charge:	90.00	

Workorder: 1004819

Problem: Tail light out

Meter Reading: 0	Labor	Parts		
In Date: 05/10/2010	Hours	Description	Quantity	
- Replace R/R Brake Light Bulb.	0.50			
Parts Charge:	0.00	Labor Charge:	30.00	

2/1/2017
9:52:45AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10125257 1999 CROSLEY CR81X22TG Trailer, 81" X 22 Ft., Dual Axle

Workorder: 1006488 **Problem:** TAIL LIGHTS NOT WORKING

Meter Reading: 0	Labor	Parts	
In Date: 06/21/2010	Hours	Description	Quantity
- Replace Shorted Right Rear Tail Light Assembly.	1.50	2641 RH TAIL LIGHT GROTE# 52302	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge: 12.49		Labor Charge: 90.00	

Workorder: 1009402 **Problem:** Tail light out

Meter Reading: 0	Labor	Parts	
In Date: 08/30/2010	Hours	Description	Quantity
- Repair Wire For Left Rear Marker Light. Replace Right Rear Brake Light Bulb.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 2.00		Labor Charge: 60.00	

Workorder: 1009632 **Problem:** P. M. SERVICE

Meter Reading: 0	Labor	Parts	
In Date: 09/02/2010	Hours	Description	Quantity
- P. M.	10.50	AXLE SEALS	3.00
- Verify R/R Cotter Pin Not In Place, Damaged Bearings, Races, Seals. R&R Bearings, Race & 4 Seals. Install 2 Grease Caps, Replack All Wheel Bearings.		SHOP SUPPLIES	1.00
		BEARING KIT	1.00
		1066 WHITE LITHIUM (CRC 05037)	1.00
- Service Front & Rear Drum Brakes, Reassemble.		GREASE CAPS	2.00
- Verify Two Tires Have A Nail In Each. Dismount Two Tires, Patch, Mount, Add 70 Psi Of Nitrogen.			
- Verify. F/L Running Light Out. Remove Assy, Repair Wiring & Ground, Reassemble.			
- Shop Supplies			
Parts Charge: 27.46		Labor Charge: 630.00	

2/1/2017
9:52:45AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10125257 1999 CROSLEY CR81X22TG Trailer, 81" X 22 Ft., Dual Axle

Workorder: 1012386

Problem: TAIL LIGHT INOP.

Meter Reading: 0	Labor	Parts	Quantity
In Date: 11/04/2010	Hours	Description	
- Replace Right Rear Tail Light Bulb & Repair Short Circuit That Caused Truck Fuse To Blow.	1.50	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	90.00

Workorder: 1012493

Problem: see request

Meter Reading: 0	Labor	Parts	Quantity
In Date: 11/08/2010	Hours	Description	
- Ck Secure Parts For Eqpt	0.50	1/2 DOUBLE CLEVIS CHAIN SHACKLES	4.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	62.42	Labor Charge:	30.00

Workorder: 1102213

Problem: TAIL LIGHT OUT

Meter Reading: 0	Labor	Parts	Quantity
In Date: 02/28/2011	Hours	Description	
- Replace Rr Tail Light Bulb. Replace Lr Park Light Bulb.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

Workorder: 1102860

Problem: PARKING LIGHTS NOT WORKING

Meter Reading: 0	Labor	Parts	Quantity
In Date: 03/16/2011	Hours	Description	
- C/S: Parking Lights Not Working. Perform Pinpoint Test, Found Blown Park Light Fuse On Truck & Damaged Trailer Plug On Trailer. Replace Fuse, Male Connector On Trailer & Retest All Lights.	2.00	755-5046 MALE CONNECTOR SHOP SUPPLIES	1.00 1.00
- Shop Supplies			
Parts Charge:	8.83	Labor Charge:	120.00

2/1/2017
9:52:45AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10125257 1999 CROSLEY CR81X22TG Trailer, 81" X 22 Ft., Dual Axle

Workorder: 1111934

Problem: P. M. , right rear tire leaks air, & check grease cap

Meter Reading: 0 In Date: 11/07/2011	Close Date: 11/28/2011	Labor Hours	Description	Parts	Quantity
- P. M. Service.		12.00	GREASE SEAL		2.00
- Replace Brake Away Battery, & Check Charging System.			GREASE CAP		1.00
- Replace Right Brake Drum & Both Inner & Outer Bearing On Right Side, Replace All Grease Seals, 2 Grease Caps On Right Side & Service Both Front & Rear Brakes.			PS1250F1 BATTERY (POWER SONIC PS-1250-F1)		1.00
			09997 BRAKE CLEAN		2.00
			4086 SWITCH CABLE		1.00
- Replace Both Rear Tires.			TIRE DISPOSAL FEE		2.00
- Replace Both Front Marker Lights & Right Rear Brake Light Bulb.			R/REAR BRAKE DRUM ASSY.		1.00
			ST225/75R15 D-GOOD YEAR MARATHON		2.00
- Shop Supplies			WASTE FEE		2.00
			SHOP SUPPLIES		1.00
			BEARING KIT		1.00
			LIGHT SIDE MARKER		2.00
	Parts Charge: 474.99	Labor Charge: 720.00			

Workorder: 1113281

Problem: Right rear tire flat

Meter Reading: 0 In Date: 12/19/2011	Close Date: 12/30/2011	Labor Hours	Description	Parts	Quantity
- C/C: Flat Tire. Verify, Right Rear Tire Has A Nail In Side Wall, Unable To Repair. R&R Tire, Mount, Add N2.		1.00	ST225/75R15-D,GOOD YEAR MARATHON		1.00
			TIRE DISPOSAL FEE		1.00
- Shop Supplies			SHOP SUPPLIES		1.00
			WASTE FEE		1.00
	Parts Charge: 125.92	Labor Charge: 60.00			

Workorder: 1205209

Problem: Repair accident damage

Meter Reading: 0 In Date: 06/04/2012	Close Date: 06/21/2012	Labor Hours	Description	Parts	Quantity
- Replace Damaged Cycle		4.50	SHOP SUPPLIES		1.00
- R&R Brake Drum And Backing Plate Assemblies			U-BOLT KIT		1.00
- Replace Damaged Safety Chain Hook Safety Latch			SAFETY HOOK		1.00
- Shop Supplies			AXLE ASSY		1.00
	Parts Charge: 164.50	Labor Charge: 270.00			

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10125257 1999 CROSLEY CR81X22TG Trailer, 81" X 22 Ft., Dual Axle

Workorder: 1205217 **Problem:** accident/ front axle bent

Meter Reading: 0	Labor	Parts
In Date: 06/04/2012	Hours	Description
Close Date: 06/04/2012	Quantity	
- Tow From: Atlantic And Congress, Delray To: 2601 Vista		
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 104.15

Workorder: 1205948 **Problem:** flat tire

Meter Reading: 0	Labor	Parts
In Date: 06/25/2012	Hours	Description
Close Date: 06/28/2012	Quantity	
- Repair Right Rear Tire		
	3.00	SHOP SUPPLIES
- Flip Front Shackle To Correct Positoin Of Axle		
- Shop Supplies		
Parts Charge: 2.00	Labor Charge: 180.00	

Workorder: 1212076 **Problem:** pm

Meter Reading: 0	Labor	Parts
In Date: 12/14/2012	Hours	Description
Close Date: 01/10/2013	Quantity	
- Pm		
	8.00	TIRE DISPOSAL FEE
- Clean Out Adj Front And Rear Brakes Repack Wheel		
		SHOP SUPPLIES
		762173406 225-75R15
		05088 BRAKE CLEAN
- Replace 4 Tires And Fill With Nitrogen		
- Replace Right Rear Park Light		
- Shop Supplies		
Parts Charge: 497.96	Labor Charge: 480.00	

Workorder: 1305968 **Problem:** rear left tail light not working

Meter Reading: 0	Labor	Parts
In Date: 06/17/2013	Hours	Description
Close Date: 06/20/2013	Quantity	
- Ck 4 R Tail Light Replace Bulb Clean Connections On Light		
	0.50	
Parts Charge: 0.00	Labor Charge: 30.00	

2/1/2017
9:52:45AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10125257 1999 CROSLEY CR81X22TG Trailer, 81" X 22 Ft., Dual Axle

Workorder: 1401207

Problem: pm/ lights/ weld ramp/ see notes

Meter Reading: 0		Labor	Parts	
In Date: 02/05/2014	Close Date: 02/25/2014	Hours	Description	Quantity
- Pm		33.00	762173406 225-75R15	2.00
- Replace All Board W/New Bolts			SHOP SUPPLIES	1.00
- Install 8 New O'Rings			2"X6"-16' PT DECK WOOD	1.00
- Service Winch			12V5AMP/HOUR BATTERY	1.00
- Replace 2 Back Lights And 2 Side Marker Lights And License Plate Holder			LICENSE PLATE BRKT	1.00
			TIRE DISPOSAL FEE	2.00
- Replace Brake Away Battery And Charger			2X8-12FT PT WOOD	5.00
- Replace Trailer Plug, Repair Wiring Harness			SEAL 1.719 2.561 .500	4.00
- Repair Right Front Brakes Activator Harness			BLASTER PENETRANT	1.00
- Service Front And Rear Brakes			TRICKLE CHARGER	1.00
- Mound And Nitro Fill Two New Tires W/Valve Stem			5/16-18X3 DECK SCREWS	150.00
- Replace Left Rear Inner, Outer Bearings With Drum			2X8-16FT PT DECK WOOD	10.00
- Repair Tailgate Expanded Metal			LH LED TAIL LIGHT	1.00
- Shop Supplies			AMBER MARKER LIGHT	2.00
			TRAILER CONN PLUG	1.00
			TAPPERED BEARING SET	1.00
			D-RING W/BOLT ON BRACKET	8.00
			SET 4 BEARING SET TI	1.00
			HUB/DRUM ASSY	1.00
			RH LED TAIL LIGHT	1.00
	Parts Charge: 1,120.21	Labor Charge: 1,980.00		

Workorder: 1501633

Problem: back left tire needs repair on trailer

Meter Reading: 0		Labor	Parts	
In Date: 02/13/2015	Close Date: 02/24/2015	Hours	Description	Quantity
- Repair Back Left Tire		1.00	SHOP SUPPLIES	1.00
- Shop Supplies				
	Parts Charge: 2.00	Labor Charge: 60.00		

2/1/2017
9:52:45AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10125257 1999 CROSLEY CR81X22TG Trailer, 81" X 22 Ft., Dual Axle

Workorder: 1503319

Problem: pm, broken hook on trailer

Meter Reading: 0	Labor	Parts	
In Date: 03/31/2015	Hours	Description	Quantity
- Pm	17.00	TIRE DISPOSAL FEE	2.00
- Svc Brakes Oth Axles		SEAL 1.719 2.561 .500	4.00
- Rr Two Tires		BRAKE CLEANER	2.00
- Tire Repair		SHOP SUPPLIES	1.00
- Repaired Wiring For Lights		762173406 225-75R15	2.00
- Repaired Spindle Surface And Threads			
- Repaired Wiring For Brakes			
- Lubed And Shimmed Winch			
- Removed Broken O Ring			
- Shop Supplies			
Parts Charge: 335.11		Labor Charge: 1,020.00	

Workorder: 1505033

Problem: right rear tire on trailer passenger side

Meter Reading: 0	Labor	Parts	
In Date: 05/18/2015	Hours	Description	Quantity
- Right Rear Tire Flat Repair Tire Mount Add N2	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 2.00		Labor Charge: 60.00	

Workorder: 1512682

Problem: r/rear tire bad

Meter Reading: 0	Labor	Parts	
In Date: 12/16/2015	Hours	Description	Quantity
- Replace Bad Tire With Good Used Tire No Charge	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 2.00		Labor Charge: 60.00	

2/1/2017
9:52:45AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10125257 1999 CROSLEY CR81X22TG Trailer, 81" X 22 Ft., Dual Axle

Workorder: 1604163

Problem: Pm service.Cut broken D Ring.Safety pin at hitch.

Meter Reading: 0			Labor	Parts	
In Date: 04/20/2016	Close Date: 05/31/2016		Hours	Description	Quantity
- Pm Service.			18.50	LOCK PIN	1.00
- Install New Brake Box Assy.				SHOP SUPPLIES	1.00
- R&R Four Light Assembly And Repair Wiring.				BATTERY	1.00
- Break Away Switch & Trailer Plug & Pig Tail.				BEARING KIT	4.00
- Installed Bearings And Races On Both Axles.				BULK TRAILER WIRE	12.00
- R& R Two Tires.				BREAK AWAY SYSTEM	1.00
- Brake Service Two Axles.				CLR MKR LAMP	2.00
- Repair Right Front Tire.				VINYL ELECTRICAL TAPE	2.00
- Straightened Two Fenders Hitting Tires.				MALE TRAILER CONNECTOR	1.00
- Shop Supplies				TIRE DISPOSAL FEE	2.00
				BRAKE CLEANER	2.00
				762173406 225-75R15	2.00
				GREASE CAP	4.00
				TAPPERED BEARING SET	4.00
				SEAL 1.719 2.561 .500	4.00
				MARK LMP	2.00
	Parts Charge:	524.04	Labor Charge:	1,110.00	

Workorder: 1611033

Problem: Transition Prep Charge

Meter Reading: 0			Labor	Parts	
In Date: 10/26/2016	Close Date: 10/26/2016		Hours	Description	Quantity
- Transition Prep Charge			2.00		
	Parts Charge:	0.00	Labor Charge:	0.00	

Total Parts Charges:	7,233.08	Total Labor Charges:	13,913.75	Total Comm. Charges:	260.15
----------------------	-----------------	----------------------	------------------	----------------------	---------------