

6/6/2022
9:03:41 AM

Palm Beach County Fleet Management Asset Maintenance History
10195556 2014 FORD EXPLORER Suv, Lg Mid Size

Total Hours: 76.60 Labor: 5,064.45 Parts: 4,022.00 Comm: 8,179.62 Charged: 17266.08

Work Order: 1411745 **Meter:** 213 **In Date:** 11/19/2014 **Closed:** 11/19/2014
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1504299 **Meter:** 4028 **In Date:** 04/27/2015 **Closed:** 04/30/2015
Problem: Pm service.

Work Completed

- Pm service.
- Rotate and balance all four tires.
- Shop Supplies

Parts Issued Quantity

5w20 Engine Oil 6.00
Napagold Oil Filter 1.00
Washer Fluid Concentr 1.00
Shop Supplies 1.00

Hours: 3.75 Comm: 0.00 Labor: 225.00 Parts: 22.91 Total: 247.91

Work Order: 1511629 **Meter:** 9560 **In Date:** 11/13/2015 **Closed:** 11/23/2015
Problem: Pm service.Rear bumper repair.Detail.

Work Completed

- Pm service.
- Rotate and balance all four tires.
- Shop Supplies

Parts Issued Quantity

5w20 Engine Oil 6.00
Napagold Oil Filter 1.00
Accufit Beam 1.00
Accufit Beam 1.00
Shop Supplies 1.00

Hours: 3.00 Comm: 0.00 Labor: 180.00 Parts: 54.37 Total: 234.37

Work Order: 1512831 **Meter:** 9810 **In Date:** 11/20/2015 **Closed:** 12/18/2015
Problem: damage to rear bumper

Work Completed

- damage to rear bumper

Hours: 0.00 Comm: 357.60 Labor: 0.00 Parts: 0.00 Total: 357.60

6/6/2022
9:03:41 AM

Palm Beach County Fleet Management Asset Maintenance History
10195556 2014 FORD EXPLORER Suv, Lg Mid Size

Work Order: 1702812 **Meter:** 19969 **In Date:** 03/20/2017 **Closed:** 04/10/2017
Problem: Check engine lighton.Fluid leak.

Work Completed

Parts Issued

Quantity

- Transport vehicle to dealer for check engine light and leaking rear main seal.
- Shop Supplies

Shop Supplies 1.00

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 2.00 Total: 122.00

Work Order: 1708721 **Meter:** 24462 **In Date:** 09/01/2017 **Closed:** 09/28/2017
Problem: PM Service, Exhaust/Cab leak inspection, Transmission seems to jerk at times, Detail.

Work Completed

Parts Issued

Quantity

- P.m. service.
- Repair right front flat tire .rotate and balance four tires.
- Inspect all seals and plugs for exhaust leaks into cab area.reprogram Hvac with latest calibration Per Tsb 16-0166.
- Shop Supplies

5w20 Engine Oil 6.00

Napagold Oil Filter 1.00

Washer Fluid Concentr 1.00

Napa Cabin Air Filter 1.00

Accufit Beam 1.00

Accufit Beam 1.00

Wpr/blde 1.00

Shop Supplies 1.00

Hours: 4.50 Comm: 0.00 Labor: 270.00 Parts: 64.19 Total: 334.19

Work Order: 1711761 **Meter:** 26186 **In Date:** 11/29/2017 **Closed:** 11/30/2017
Problem: Accident

Work Completed

- Tow From: On ramp of 45th Sb To: Accident Line

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 1712741 **Meter:** 26390 **In Date:** 12/28/2017 **Closed:** 01/08/2018
Problem: Recall,Inspect body sealing.17N04.

Work Completed

Parts Issued

Quantity

- Transport to and from dealer for recall 17n04 and 17n03.
- Shop Supplies

Shop Supplies 1.00

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 2.00 Total: 122.00

6/6/2022
9:03:41 AM

Palm Beach County Fleet Management Asset Maintenance History
10195556 2014 FORD EXPLORER Suv, Lg Mid Size

Work Order: 1911931 **Meter:** 40943 **In Date:** 11/18/2019 **Closed:** 11/27/2019
Problem: P.m. service and recall 19S17 .

Work Completed

- P.m. Service.
- Replace cabin filter.clean debris from duct.
- Rotate and balance tires.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
11in Exactfit-rear	1.00
22in Exactfit-beam	1.00
26in Exactfit-beam	1.00
Napa Cabin Air Filter	1.00
Ford Triton Pvc Swc	1.00
Shop Supplies	1.00

Hours: 3.50

Comm: 0.00

Labor: 255.50

Parts: 88.53

Total: 344.03

Work Order: 1912648 **Meter:** 40953 **In Date:** 12/10/2019 **Closed:** 12/10/2019
Problem: Recall 19S17B.

Work Completed

- Transport vehicle to dealer for recall #19s17b.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 4.00

Total: 150.00

6/6/2022
9:03:41 AM

Palm Beach County Fleet Management Asset Maintenance History
10195556 2014 FORD EXPLORER Suv, Lg Mid Size

Work Order: 2112157 **Meter:** 61650 **In Date:** 11/12/2021 **Closed:** 11/18/2021
Problem: PM Service. rear hatch inop and detail .

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- rotate and balance all 4 tires nitro fill all
- Force entry into rear hatch . replace tail gate lock actuator after tailgate was found inoperative . Retest
- R&r front brake pads cut front rotors bleed and flush brake system. test drive vehicle after repair are completed
- Shop Supplies

Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
11in Exactfit-rear	1.00
22in Exactfit-beam	1.00
26in Exactfit-beam	1.00
Brk Fluid Dot 4-32oz	1.00
Non-chlor Brake Clnr	1.00
Latch Assy	1.00
Front Brake Pad	1.00
Shop Supplies	1.00

Hours: 8.00 Comm: 0.00

Labor: 584.00 Parts: 207.68 Total: 791.68

Work Order: 2112367 **Meter:** 61650 **In Date:** 11/18/2021 **Closed:** 11/18/2021
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 90.40

Labor: 0.00 Parts: 0.00 Total: 90.40

Work Order: 2205482 **Meter:** 67292 **In Date:** 05/24/2022 **Closed:** 05/24/2022
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00

Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 76.60

Total Labor: 5,064.45

Total Comm: 8,179.62

Total Parts: 4,022.00