

6/6/2022
9:21:58 AM

Palm Beach County Fleet Management Asset Maintenance History
10198934 2015 FORD F150 Pickup, 1/2 Ton

Total Hours: 132.15 Labor: 8,918.60 Parts: 8,300.55 Comm: 15,763.03 Charged: 32982.17

Work Order: 1509566 **Meter:** 335 **In Date:** 09/22/2015 **Closed:** 09/22/2015
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection
- Wash Vehicle

Hours: 3.00 Comm: 0.00 Labor: 180.00 Parts: 0.00 Total: 180.00

Work Order: 1509668 **Meter:** 335 **In Date:** 09/24/2015 **Closed:** 09/24/2015
Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 9.54 Labor: 0.00 Parts: 0.00 Total: 9.54

Work Order: 1603209 **Meter:** 4230 **In Date:** 03/28/2016 **Closed:** 04/06/2016
Problem: P.M. service and trim loose right b-pillar outside.

Work Completed

- P.m. Service.
- Rotate and balance all tires.
- Shop Supplies

Hours: 3.00 Comm: 0.00

Parts Issued

Quantity

Dickies Floormat	1.00
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00
Labor: 180.00 Parts: 76.25 Total: 256.25	

6/6/2022
9:21:58 AM

Palm Beach County Fleet Management Asset Maintenance History
10198934 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1609089 **Meter:** 9106 **In Date:** 08/31/2016 **Closed:** 09/21/2016
Problem: P.M. Service.Install strobe lights.

Work Completed

- P.m. Service.
- Replace and rewire corroded trailer plug.
- Install four corner strobe lights.fabricate and install wiring and switch.
- Rotate and balance all tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
trailer plug	1.00
Vtx609a Led Strobe Am	2.00
Vtx609c Led Strobe Cl	2.00
Fuse Holder	1.00
Rocker Led Blk Ambe	1.00
Clr Rtv Silcn Sealant	1.00
Fab Loom-split Poly	40.00
Shop Supplies	1.00

Hours: 12.25

Comm: 0.00

Labor: 735.00

Parts: 530.08

Total: 1,265.08

Work Order: 1701496 **Meter:** 14414 **In Date:** 02/10/2017 **Closed:** 02/14/2017
Problem: Accident

Work Completed

- Tow From: Sr7 & Lakeridge

Hours: 0.00

Comm: 96.00

Labor: 0.00

Parts: 0.00

Total: 96.00

Work Order: 1704730 **Meter:** 14528 **In Date:** 05/11/2017 **Closed:** 05/18/2017
Problem: P.M. Service.Had major body damage,check repairs.

Work Completed

- P.m. service.
- Performed hydraulic brake bleed at all four wheels.due to spongy brake pedal detected during road test.
- Balance and rotate all four tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Brk Fluid Dot 4-12oz	3.00
Shop Supplies	1.00

Hours: 4.00

Comm: 0.00

Labor: 240.00

Parts: 52.72

Total: 292.72

6/6/2022
9:21:58 AM

Palm Beach County Fleet Management Asset Maintenance History
10198934 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1704932 **Meter:** 14414 **In Date:** 02/13/2017 **Closed:** 05/17/2017
Problem: : Damage to right door, right front fender, headlight, front bumper, steering, tire, rim, hood & p

Work Completed

- : Damage to right door, right front fender, headlight, front bumper, steering, tire, rim, hood & p

Hours: 0.00 Comm: 13,588.40 Labor: 0.00 Parts: 0.00 Total: 13,588.40

Work Order: 1708915 **Meter:** 17298 **In Date:** 09/15/2017 **Closed:** 09/15/2017
Problem: 2 - Wash ticket(s) issued

Work Completed

- 2 - Wash ticket(s) issued

Hours: 0.00 Comm: 19.08 Labor: 0.00 Parts: 0.00 Total: 19.08

Work Order: 1710317 **Meter:** 19653 **In Date:** 10/20/2017 **Closed:** 11/02/2017
Problem: PM Service, Right mirror, Antenna loose (in cab), Laptop stand does'nt lock & finish mounting brace

Work Completed

- P.m. service.

- Check and replace broken rright outside mirror

assembly.secureantenna.mount brace for computer stand.remove computer mount to adjust locking system.

- Balance and rotate all four tires.

- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil 6.00

Napagold Oil Filter 1.00

22" Wiper Blade 2.00

Mirror Asy 1.00

Shop Supplies 1.00

Hours: 5.00 Comm: 0.00 Labor: 300.00 Parts: 288.53 Total: 588.53

Work Order: 1711795 **Meter:** 20776 **In Date:** 12/01/2017 **Closed:** 12/01/2017
Problem: No start

Work Completed

- Tow From: 2300 Jog Rd next to Dumpster To: Lv shop

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

6/6/2022
9:21:58 AM

Palm Beach County Fleet Management Asset Maintenance History
10198934 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1711812 **Meter:** 20784 **In Date:** 12/01/2017 **Closed:** 12/07/2017

Problem: Towed in for no start.

Work Completed

Parts Issued

Quantity

- Charge battery fully .test battery and charging system. Battery failed load test.&r defective battery.

Battery Motorcraft 1.00

Shop Supplies 1.00

- Shop Supplies

Hours: 1.00

Comm: 0.00

Labor: 60.00

Parts: 180.40

Total: 240.40

Work Order: 1802298 **Meter:** 24794 **In Date:** 03/01/2018 **Closed:** 03/08/2018

Problem: P.M. Service.Check lap top tray.Noise in left front wheel.

Work Completed

Parts Issued

Quantity

- P.m. service.

5w20 Engine Oil 6.00

- Rotated and balanced all four tires.nitrogen fill tires.

Napagold Oil Filter 1.00

- Diagnose computer stand top not locking .disassemble top to adjust locking tab.retest. Diagnose noise over bumps .retorque left side swaybar link top nut. Test drive.

Napagold Air Filter 1.00

Used Fire X Refurbished 1.00

Washer Fluid Concentr 1.00

- Shop Supplies

22" Wiper Blade 2.00

Shop Supplies 1.00

Hours: 4.00

Comm: 0.00

Labor: 240.00

Parts: 50.23

Total: 290.23

Work Order: 1802691 **Meter:** 25035 **In Date:** 03/12/2018 **Closed:** 03/12/2018

Problem: 2 - Wash ticket(s) issued

Work Completed

- 2 - Wash ticket(s) issued

Hours: 0.00

Comm: 19.08

Labor: 0.00

Parts: 0.00

Total: 19.08

Work Order: 1803122 **Meter:** 25947 **In Date:** 03/26/2018 **Closed:** 03/29/2018

Problem: Screw in tire.

Work Completed

Parts Issued

Quantity

- Repair right front tire and balance and nitro service.

Shop Supplies 1.00

- Shop Supplies

Hours: 1.00

Comm: 0.00

Labor: 60.00

Parts: 2.00

Total: 62.00

6/6/2022
9:21:58 AM

Palm Beach County Fleet Management Asset Maintenance History
10198934 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1806770 **Meter:** 31234 **In Date:** 07/02/2018 **Closed:** 07/12/2018
Problem: P.M. service , computer stand not locking in place and detail.

Work Completed

- P.m. service.
- Replace all four worn tires .balance all four tires and Nitrogen fill tires.
- Resurface both rear rotors .replace rear brake pads and service calipers .flush and bleed brake system .road test.
- Remove computer stand to replace missing lock nut and adjust locking slide. Retest.
- Complete front end alignment . Road test.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Ford Triton Pvc Swc	1.00
Non-chlor Brake Clnr	1.00
Brk Fluid Dot 4-12oz	1.00
Brake Pad	1.00
245 70r17 At Adventure	4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 10.50

Comm: 0.00

Labor: 630.00

Parts: 1,075.50

Total: 1,705.50

Work Order: 1807059 **Meter:** 13440 **In Date:** 07/11/2018 **Closed:** 07/11/2018
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00

Comm: 96.00

Labor: 0.00

Parts: 0.00

Total: 96.00

Work Order: 1811608 **Meter:** 36811 **In Date:** 11/13/2018 **Closed:** 11/26/2018
Problem: P.M. service , check speedometer , had to jump start and setail.

Work Completed

- P.m. service. Road test several times and scan for codes for speedometer issue . Could not duplicate at this time.
- Check battery and charging system . Charge battery . Battery failed load test. R&r defective battery.
- Balance and rotate all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w20	6.00
Used Fire X Refurbished	1.00
22" Wiper Blade	2.00
Battry Motorcraft	1.00
Shop Supplies	1.00

Hours: 4.00

Comm: 0.00

Labor: 268.00

Parts: 230.48

Total: 498.48

6/6/2022
9:21:58 AM

Palm Beach County Fleet Management Asset Maintenance History
10198934 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1811820 **Meter:** 36494 **In Date:** 11/16/2018 **Closed:** 11/16/2018
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 1903503 **Meter:** 42602 **In Date:** 04/01/2019 **Closed:** 04/08/2019
Problem: P.M. service Right front tire going flat .

Work Completed

- P.m. service.

- Repair left front tire . Rotate and high speed balance all four tires . Nitrofill all.

- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter 1.00

5w20 Engine Oil 6.00

Napagold Air Filter 1.00

Washer Fluid Concentr 1.00

22" Wiper Blade 2.00

Used Fire X Refurbished 1.00

Wd40 Spr 1.00

Shop Supplies 1.00

Hours: 4.00 Comm: 0.00 Labor: 268.00 Parts: 61.58 Total: 329.58

Work Order: 1907526 **Meter:** 47602 **In Date:** 07/22/2019 **Closed:** 07/23/2019
Problem: Right front tire going flat.

Work Completed

- Repair right front tire and balance . Nitrofill all.

- Shop Supplies

Parts Issued

Quantity

Shop Supplies 1.00

Hours: 1.00 Comm: 0.00 Labor: 67.00 Parts: 3.00 Total: 70.00

6/6/2022
9:21:58 AM

Palm Beach County Fleet Management Asset Maintenance History
10198934 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1908499 **Meter:** 48775 **In Date:** 08/14/2019 **Closed:** 09/26/2019
Problem: PM Service, Broekn mirror, Center display not working (AC, Radio, etc). Recalls 17s33 ,18S27 .

Work Completed

Parts Issued

Quantity

- P.m. service.
- Replace two tires . Rotate and balance all four tires . Nitrofill all and replace right front Tpms sensor . Retrain all sensors .
- Replace damaged left outside mirror assembly . Test and replace defective trailer plug connector and rewire as needed .
- Computer diagnose center display and rodio inop ,code U250. Perform pinpoint test . R&r defective front eletrics module . Pmi module and retest .
- Resurface both front brake rotors and service calipers . Replace brake pads . Flush and bleed brake system . Road test .
- Check and replace right side inner tie rod end .
- Perform complete front end alignment and road test .
- Transport to and from dealer for recalls 17s33 and 18s27 .
- Shop Supplies

trailer plug	1.00
Mirror	1.00
Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
183114470 P245-70r17	2.00
Tpms Sens Kit	1.00
Brake Pad	1.00
Tie Rod	1.00
Fcim	1.00
Ford Triton Pvc Swc	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 17.60

Comm: 0.00

Labor: 1,179.20

Parts: 1,265.40

Total: 2,444.60

6/6/2022
9:21:58 AM

Palm Beach County Fleet Management Asset Maintenance History
10198934 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 2000974 **Meter:** 54080 **In Date:** 01/29/2020 **Closed:** 02/11/2020

Problem: P.M. service, speedometer wrong , trailer warning on dash ,left rear tire going flat .

Work Completed

Parts Issued

Quantity

- P.m. service.
- Replace two tires . Rotate and balance all four tires . Nitrofill all.
- Vehicle smells of smoke . Replace cabin air foilter and clean fresh air intake .
- Diagnose trailer warning on dash . Replace defective trailer plug connector and rewire as needed and seal .
- Computer diagnose misfire . Perform tune up . replace all six spark plugs . Retest .
- Perform complete air intake decarb and cleaning . clean trhottle body . Flush injectors .
- Inspect and service rear differential .
- Diagnose speedometer sticking . R&r defective cluster per Tsb 15-0193 . Hook upm Ids to Pmi cluster . Retest . Replace defective shifter interlock and shifter lever .retest .
- Perform complete front end alignment and road test .
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Napagold Air Filter	1.00
Air Freshener	1.00
245/70/17 Tire Mich	2.00
Cabin Air Filter	1.00
trailer plug	1.00
Spark Plugs	6.00
Motor Tune-up 16oz	1.00
Intake Cleaner Kit	1.00
Napa Gear 80w-90 Qt	3.00
Px Grey Rtv Silicone	1.00
75w140 Ford Axle Lube	3.00
Instrument Cluster	1.00
Shift Kit Tram	1.00
Lever	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 17.10

Comm: 0.00

Labor: 1,248.30

Parts: 1,622.99

Total: 2,871.29

Work Order: 2002262 **Meter:** 55399 **In Date:** 03/04/2020 **Closed:** 03/05/2020

Problem: Left front tire going flat and right rear tire low .

Work Completed

Parts Issued

Quantity

- Replace left front tire and repair right rear tire . Balance both tires . Nitrofill all tires.
- Shop Supplies

245/70/17 Tire Mich	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 1.50

Comm: 0.00

Labor: 109.50

Parts: 238.86

Total: 348.36

6/6/2022
9:21:58 AM

Palm Beach County Fleet Management Asset Maintenance History
10198934 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 2003568 **Meter:** 57109 **In Date:** 04/09/2020 **Closed:** 04/09/2020
Problem: Left rear tire going flat .

Work Completed

- Replace left rear tire and balance . Nitrofill all .
- Shop Supplies

Parts Issued

	Quantity
Shop Supplies	1.00
P245/70r17 Tire	1.00
Tire Disposal Fee	1.00

Hours: 0.50 Comm: 0.00 Labor: 36.50 Parts: 125.99 Total: 162.49

Work Order: 2004993 **Meter:** 59293 **In Date:** 05/18/2020 **Closed:** 05/27/2020
Problem: P.M. service ,check engine light , trailer light ,e-brake fault and A/T tires .

Work Completed

- P.m. service.
- Test and replace defective trailer plug connector and rewire as needed .
- Computer diagnose check engine , code P0455 . Perform evap test . R&r defective purge valve . Clear codes and retest .
- Rotate and high speed balance all four wheels . Nitrofill all.
- Adjust shifter cable to align indicator .
- Shop Supplies

Parts Issued

	Quantity
Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
trailer plug	1.00
Purge Valve	1.00
Shop Supplies	1.00

Hours: 6.50 Comm: 0.00 Labor: 474.50 Parts: 111.73 Total: 586.23

Work Order: 2006355 **Meter:** 59413 **In Date:** 05/26/2020 **Closed:** 06/26/2020
Problem: Rust on front bumper, damage on hood, upper right of tailgate, and rear bumper.

Work Completed

- Rust on front bumper, damage on hood, upper right of tailgate, and rear bumper.

Hours: 0.00 Comm: 1,724.40 Labor: 0.00 Parts: 0.00 Total: 1,724.40

6/6/2022
9:21:58 AM

Palm Beach County Fleet Management Asset Maintenance History
10198934 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 2008848 **Meter:** 62690 **In Date:** 09/02/2020 **Closed:** 09/02/2020

Problem: Spare on left rear . tire flat .

Work Completed

- Repair left rear tire and balance . Nitrofill all . Remount spare .
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 4.00	Total: 77.00
-------------	------------	--------------	-------------	--------------

Work Order: 2010780 **Meter:** 64589 **In Date:** 10/27/2020 **Closed:** 11/04/2020

Problem: P.M. Service

Work Completed

- Performed Pm Service
- Check Performed Coolant Pressure Test,r@r Defective Water Pump.thermostat Housing,o-ring,drive @ A/c Belts,then Flush And Refill Coolant
- check ,pin Point Test Blown Fuse For Strobes Light System,,then R@r R/r Strobe Light Due To Light Short To Ground At Body
- Replace Two Front Tires ,also Replace One Tire Sensor L/f Tire,balance And Rotate 4
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Anti Freeze Motorcraft	2.00
245/70/17 Tire Mich	2.00
Water Pump	1.00
Tmermostat Housing	1.00
V Belt	1.00
V Belt	1.00
Gasket	1.00
Wrn Ambr	1.00
Tpms Sens Kit	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 12.40	Comm: 0.00	Labor: 905.20	Parts: 1,342.72	Total: 2,247.92
--------------	------------	---------------	-----------------	-----------------

6/6/2022
9:21:58 AM

Palm Beach County Fleet Management Asset Maintenance History
10198934 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 2102659 **Meter:** 71522 **In Date:** 03/09/2021 **Closed:** 03/18/2021
Problem: P.M. Service

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- R&r Cabin Air Filter, Clean Evaporator With Cleaner/ Deoterizer Spray And Clean
- R&r Rear Brake Pads, Remove Rotors And Resurface Remeasuare After Completion Brake Bleed System and road test .
- Repair left front tire and Rotate And Balance All four tires . Nitro Fill
- Shop Supplies

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Napagold Air Filter	1.00
Cabin Filter	1.00
Brk Fluid Dot 4-12oz	1.00
Brake Pads	1.00
Shop Supplies	1.00
Labor: 584.00 Parts: 171.94 Total: 755.94	

Hours: 8.00

Comm: 0.00

Labor: 584.00

Parts: 171.94

Total: 755.94

Work Order: 2103171 **Meter:** 71681 **In Date:** 03/17/2021 **Closed:** 03/22/2021
Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00

Comm: 9.54

Labor: 0.00

Parts: 0.00

Total: 9.54

6/6/2022
9:21:58 AM

Palm Beach County Fleet Management Asset Maintenance History
10198934 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 2107373 **Meter:** 78958 **In Date:** 07/08/2021 **Closed:** 07/15/2021
Problem: PM Service and check lights

Work Completed

- Performed P.m. Service & Inspection.
- Performed Tire Rotation Balance On All 4 Wheels, Reset Tpms.
- Load Test Battery, Test Recommend Charge, Charged Battery And Retest. Battery Failed, Bad Cells Recommend R & R. Removed And Replaced Then Reset To Bsm .
- L/r Tail Light Bulb Inop. Check Power And Ground Bulb Filament Distorted Replaced Then Check.
- Check Engine Light On, Connect Ids And Scan For Faults, Found Fault Code P0442 Related To Concern, Perform Evap Smoke Test And Found Evap Vent Valve Canister Defective Removed And Replaced. Clear Codes & Test Drove Vehicle. Working As Design.
- Shop Supplies

Hours: 8.00

Comm: 0.00

Parts Issued

	Quantity
5w20 Engine Oil	6.00
Napagold Oil Filter	2.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Battry Motorcraft	1.00
Boxed Miniatures	1.00
Cannister	1.00
Permatex	1.00
Permatex	1.00
Shop Supplies	1.00

Labor: 584.00

Parts: 275.65

Total: 859.65

Work Order: 2111828 **Meter:** 86013 **In Date:** 11/02/2021 **Closed:** 11/09/2021
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Mount Two New Tires, Rotate And Balance Four. Nitro Fill All .
- Shop Supplies

Hours: 4.00

Comm: 0.00

Parts Issued

	Quantity
Steering Wheel Cover Large	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
245/70/17 Tire Mich	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Labor: 292.00

Parts: 497.91

Total: 789.91

6/6/2022
9:21:58 AM

Palm Beach County Fleet Management Asset Maintenance History
10198934 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 2112139 **Meter:** 86017 **In Date:** 11/09/2021 **Closed:** 11/12/2021
Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 8.98 Labor: 0.00 Parts: 0.00 Total: 8.98

Work Order: 2202684 **Meter:** 92533 **In Date:** 03/10/2022 **Closed:** 03/10/2022
Problem: left rear tire flat , spare on vehicle

Work Completed

- Replace left rear tire and balance . Remount spare under vehicle .
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
245/70r17	1.00
Tire Disposal Fee	1.00

Hours: 0.80 Comm: 0.00 Labor: 58.40 Parts: 92.64 Total: 151.04

Work Order: 2203470 **Meter:** 93526 **In Date:** 03/30/2022 **Closed:** 03/30/2022
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 132.15 Total Labor: 8,918.60 Total Comm: 15,763.03 Total Parts: 8,300.55