

6/6/2022
10:20:43 AM

Palm Beach County Fleet Management Asset Maintenance History
10201852 2016 JACOBSON GROOM MASTER II Ballfield Groomer

Total Hours: 84.75 Labor: 5,932.50 Parts: 3,922.18 Comm: 0.00 Charged: 9854.68

Work Order: 1604746 **Meter:** 1 **In Date:** 05/05/2016 **Closed:** 05/05/2016
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1703892 **Meter:** 115 **In Date:** 04/18/2017 **Closed:** 05/15/2017
Problem: PM service,Fan noisy.

Work Completed

- Pm Service.
- Service Hyd.system.inspect lines,hoses,fittings etc..replace filter and correct fluid level.
- Wash equipment.
- Verify alternator hitting bracket.worn through alt..instructed by Dealer to replace worn belt.r/r belt...adjust alternator not to touch bracket.
- C/c fan hitting schroud.call dealer.repaired under warranty.
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Napagold Fuel Filter	1.00
Napagold Oil Filter	1.00
15w40 Bulk South Reg	3.00
Napa Trans Filter	1.00
Aw68 Bulk Sr	2.00
V Belt	1.00
Shop Supplies	1.00

Hours: 8.00 Comm: 0.00 Labor: 480.00 Parts: 92.71 Total: 572.71

Work Order: 1808053 **Meter:** 294 **In Date:** 08/06/2018 **Closed:** 09/27/2018
Problem: PM Service.Will not shut off..

Work Completed

- Pm Service
- C/c Wont shut off.verify fuel shut off solenoid bracket broken.replace bracket and arm.
- Service hyd. system.
- Wash equipment.
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Fuel Element	1.00
15w40 Bulk South Reg	3.00
Napagold Oil Filter	1.00
Solenoid Rod	1.00
Hex Nut 1/4-28	1.00
Solenoid Bracket	1.00
Shop Supplies	1.00

Hours: 8.25 Comm: 0.00 Labor: 495.00 Parts: 135.70 Total: 630.70

6/6/2022
10:20:43 AM

Palm Beach County Fleet Management Asset Maintenance History
10201852 2016 JACOBSON GROOM MASTER II Ballfield Groomer

Work Order: 1809720 **Meter:** 294 **In Date:** 09/20/2018 **Closed:** 09/27/2018
Problem: fuel solenoid

Work Completed

- C/c fuel solenoid.verify new solenoid out of adjustment.reinstall with locktite and adjust linkage.

Hours: 0.50 Comm: 0.00 Labor: 30.00 Parts: 0.00 Total: 30.00

Work Order: 1903183 **Meter:** 362 **In Date:** 03/25/2019 **Closed:** 03/28/2019
Problem: Control linkage joint fell off.

Work Completed

Parts Issued

Quantity

- C/c control linkage fell off.adjust traction pedal.repair linkage.test run.

Shop Supplies 1.00

- Shop Supplies

Hours: 1.75 Comm: 0.00 Labor: 117.25 Parts: 3.00 Total: 120.25

Work Order: 1910086 **Meter:** 435 **In Date:** 09/30/2019 **Closed:** 10/28/2019
Problem: PM Service.Check wont start,tires and bracket

Work Completed

Parts Issued

Quantity

- Pm Service.

Napagold Air Filter 1.00

- Service Hyd.system.replace filter.correct fluid level.

Fuel Element 1.00

- Replace three tires.mount,add N2

15w40 Bulk South Reg 4.00

- C/c wont start.replace broken fuel shut off solenoid bracket.

Napagold Oil Filter 1.00

- Replace battery and terminals.

Aw68 Bulk Sr 1.00

- Wash equipment.

Napa Trans Filter 1.00

- Shop Supplies

Battery Terminals 1.00

Battery 1.00

Clean-r-carb 20oz 1.00

20x11.00-10 4ply Carl Turf Tamer 3.00

Solenoid Bracket 1.00

Shop Supplies 1.00

Tire Disposal Fee 3.00

Freight Charge 1.00

Hours: 11.50 Comm: 0.00 Labor: 839.50 Parts: 730.21 Total: 1,569.71

6/6/2022
10:20:43 AM

Palm Beach County Fleet Management Asset Maintenance History
10201852 2016 JACOBSON GROOM MASTER II Ballfield Groomer

Work Order: 1911929 **Meter:** 448 **In Date:** 11/18/2019 **Closed:** 11/25/2019

Problem: Wont turn off. See notes on hood.

Work Completed

- C/c wont turn off.replace broken shut off solenoid rod.install adjust and reassemble.test run.
- C/c Fix hood.repair hood falling apart.
- Shop Supplies

Parts Issued

Quantity

Hex Nut 1/4-28	1.00
Threaded Rod	1.00
Jb Weld	1.00
Solenoid Rod	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 4.50

Comm: 0.00

Labor: 328.50 Parts: 72.19 Total: 400.69

Work Order: 2000288 **Meter:** 462 **In Date:** 01/09/2020 **Closed:** 01/27/2020

Problem: wont turn off/ fuel solenoid rod

Work Completed

- replace fuel cutoff solenoid and rod
- Shop Supplies

Parts Issued

Quantity

Hex Nut 1/4-28	1.00
Solenoid Rod	1.00
Solenoid Fuel	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 2.00

Comm: 0.00

Labor: 146.00 Parts: 330.68 Total: 476.68

Work Order: 2001112 **Meter:** 467 **In Date:** 01/31/2020 **Closed:** 02/18/2020

Problem: Idle solenoid bracket broken.

Work Completed

- Replace fuel shut off solenoid bracket.adjust linkage.retap threads on head.
- Shop Supplies

Parts Issued

Quantity

Solenoid Bracket	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 3.25

Comm: 0.00

Labor: 237.25 Parts: 66.94 Total: 304.19

6/6/2022
10:20:43 AM

Palm Beach County Fleet Management Asset Maintenance History
10201852 2016 JACOBSON GROOM MASTER II Ballfield Groomer

Work Order: 2005144 **Meter:** 504 **In Date:** 05/21/2020 **Closed:** 05/29/2020
Problem: PM Service

Work Completed

- Pm Service.
- Service Hyd system,r/r filter,inspect all ,correct fluid level.
- Wash equipment.
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Fuel Element	1.00
15w40 Bulk South Reg	4.00
Napagold Oil Filter	1.00
Aw68 Bulk Sr	2.00
Napa Trans Filter	1.00
Shop Supplies	1.00

Hours: 6.00

Comm: 0.00

Labor: 438.00 Parts: 50.04 Total: 488.04

Work Order: 2009163 **Meter:** 548 **In Date:** 09/14/2020 **Closed:** 09/28/2020
Problem: PM Service.Check left rear tire leaking.

Work Completed

- Pm Service.
- Hyd.service.replace filters Repair leaking fitting.
- C/c left tire.repair tire.correct all N2 levels.
- Wash Equipment.
- Replace safety switches and hardware.replace seat switch and harness.test drive.
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Napagold Air Filter	1.00
Fuel Element	1.00
15w40 Bulk South Reg	4.00
Napagold Oil Filter	1.00
Napa Trans Filter	1.00
Aw68 Bulk Sr	1.00
Screw	4.00
Switch, Prox	3.00
Washer	8.00
Lock Washer	4.00
Seat Switch	1.00
Hex Nut	4.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 9.50

Comm: 0.00

Labor: 693.50 Parts: 670.62 Total: 1,364.12

6/6/2022
10:20:43 AM

Palm Beach County Fleet Management Asset Maintenance History
10201852 2016 JACOBSON GROOM MASTER II Ballfield Groomer

Work Order: 2100820 **Meter:** 603 **In Date:** 01/25/2021 **Closed:** 02/10/2021
Problem: Traction link banjo

Work Completed

- Replace rod ends on traction pedal linkage, adjust and test run.
- Shop Supplies

Parts Issued

Quantity

End Control Rod	2.00
Hex Nut 5/16-24	2.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 88.07 Total: 234.07

Work Order: 2103159 **Meter:** 604 **In Date:** 03/22/2021 **Closed:** 03/26/2021
Problem: Hard to start.

Work Completed

- Load test battery. Passed load test.
- Customers complaint will not restart when hot. Remove fuel shut off solenoid. Clean connections and internals, reassemble and set linkage adjustments.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 3.00 Comm: 0.00 Labor: 219.00 Parts: 4.00 Total: 223.00

6/6/2022
10:20:43 AM

Palm Beach County Fleet Management Asset Maintenance History
10201852 2016 JACOBSON GROOM MASTER II Ballfield Groomer

Work Order: 2109716 **Meter:** 656 **In Date:** 09/07/2021 **Closed:** 12/09/2021
Problem: PM Service.Leaking fluid

Work Completed

- Customers complaint leaking hydraulic fluid. Verify front wheel motor is leaking fluid from seal and there is play in the shaft. Replace front wheel motor assembly.
- Pm Service
- Service hydraulic system, replace filter, inspect all correct fluid level.
- Wash unit of clay and debris to better perform repairs, service and lubricate.
- Shop Supplies

Parts Issued

Quantity

Aw68 Bulk Sr	3.00
15w40 Bulk South Reg	4.00
Napagold Oil Filter	1.00
Fuel Element	1.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Aw68 Bulk Sr	2.00
Napa Trans Filter	1.00
Front Wheel Motor	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 10.00

Comm: 0.00

Labor: 730.00 Parts: 1,335.01 Total: 2,065.01

Work Order: 2202170 **Meter:** 707 **In Date:** 02/25/2022 **Closed:** 03/04/2022
Problem: Will not start.Has to drive to South Reginal Park to install new battery.Bracket for shutoff solenoid broke off.

Work Completed

- Customers complaint will not start. Verify fuel shut off solenoid bracket broke. Remove and fabricate bracket, adjust solenoid linkage. test run
- Verify battery died under excessive cranking, remove, recharge and load test, failed test, replace battery.
- Verify engine v-belt is loose. loosen alternator and bend bracket back to allow room to tighten alternator.
- Travel to southern regional park to repair a ball field groomer broke down on the field. Travel back to the shop after repairs.
- Shop Supplies

Parts Issued

Quantity

Non-chlor Brake Clnr	1.00
Battery	1.00
Shop Supplies	1.00

Hours: 6.00

Comm: 0.00

Labor: 438.00 Parts: 113.22 Total: 551.22

6/6/2022
10:20:43 AM

Palm Beach County Fleet Management Asset Maintenance History
10201852 2016 JACOBSON GROOM MASTER II Ballfield Groomer

Work Order: 2203074 **Meter:** 744 **In Date:** 03/22/2022 **Closed:** 04/27/2022

Problem: Broken bracket for shut off solenoid assembly.

Work Completed

- C/c bracket broken. Verify Fuel solenoid bracket broken. Replace bracket and rod. adjust linkage and lubricate solenoid. test start and shut down multiple times.

- Verify front tire is worn. Replace front tire. correct all Nitrogen levels.

- Verify unit creeps in forward. Jack up unit and adjust traction linkage for hydraulic motor. Test drive.

- Shop Supplies

Hours: 4.50

Comm: 0.00

Parts Issued

Quantity

Bracket	1.00
Solenoid Rod	1.00
20x11-10 Tires	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00
Freight Charge	1.00

Labor: 328.50

Parts: 229.82

Total: 558.32

Work Order: 2205435 **Meter:** 744 **In Date:** 05/24/2022 **Closed:** 05/24/2022

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 0.00

Total: 146.00

Total Hours: 84.75

Total Labor: 5,932.50

Total Comm: 0.00

Total Parts: 3,922.18