

6/6/2022
10:28:25 AM

Palm Beach County Fleet Management Asset Maintenance History
10209125 2018 JACOBSON 088043 Ballfield Groomer

Total Hours: 33.00		Labor: 2,359.00		Parts: 1,922.51		Comm: 0.00		Charged: 4281.51	
Work Order: 1809892		Meter: 1				In Date: 09/25/2018		Closed: 09/25/2018	
Problem: pre delivery inspection									
Work Completed				Parts Issued		Quantity			
- pre delivery inspection				Shop Supplies		1.00			
- Shop Supplies									
Hours: 2.00		Comm: 0.00		Labor: 120.00		Parts: 2.00		Total: 122.00	
Work Order: 1810763		Meter: 39				In Date: 10/18/2018		Closed: 10/30/2018	
Problem: runs slow and cuts off									
Work Completed				Parts Issued		Quantity			
- diagnose. tighten 12volt connections. adjust foot pedal and verify running speed				Shop Supplies		1.00			
- Shop Supplies									
Hours: 1.50		Comm: 0.00		Labor: 100.50		Parts: 3.00		Total: 103.50	
Work Order: 1812210		Meter: 73				In Date: 11/29/2018		Closed: 12/07/2018	
Problem: broken fuel shut off bracket									
Work Completed									
- inspect and have Jacobson replace fuel bracket under warranty									
Hours: 0.50		Comm: 0.00		Labor: 33.50		Parts: 0.00		Total: 33.50	
Work Order: 1904335		Meter: 73				In Date: 04/22/2019		Closed: 04/26/2019	
Problem: brakes are hard & engine cuts off									
Work Completed				Parts Issued		Quantity			
- Repl. broken proximity switch on brake pedal & readjust parking brake				Switch, Prox		1.00			
- Shop Supplies				Shop Supplies		1.00			
Hours: 2.00		Comm: 0.00		Labor: 134.00		Parts: 106.83		Total: 240.83	

6/6/2022
10:28:26 AM

Palm Beach County Fleet Management Asset Maintenance History
10209125 2018 JACOBSON 088043 Ballfield Groomer

Work Order: 2000973 **Meter:** 529 **In Date:** 01/29/2020 **Closed:** 02/12/2020

Problem: pm service

Work Completed

- pm service
- hydraulic service
- replace front tires
- replace traction pedal proximity switch and adjust
- Shop Supplies

Parts Issued

Quantity

Napa Qt 15w40	3.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Napagold Air Filter	1.00
Napa Trans Filter	1.00
Aw68 Hydro Fluid Hydr	2.00
20x11.00-10 4ply Carl Turf Tamer	1.00
Switch, Prox	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 7.50

Comm: 0.00

Labor: 547.50

Parts: 328.97

Total: 876.47

Work Order: 2007161 **Meter:** 697 **In Date:** 07/22/2020 **Closed:** 07/29/2020

Problem: fuel shut off/ rear tires

Work Completed

- replace all 3 tires
- Shop Supplies

Parts Issued

Quantity

20x11.00-10 4ply Carl Turf Tamer	3.00
Shop Supplies	1.00
Tire Disposal Fee	3.00

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 507.84

Total: 653.84

Work Order: 2009873 **Meter:** 776 **In Date:** 09/30/2020 **Closed:** 01/27/2021

Problem: hydraulic leak left rear

Work Completed

- replace leaking lr wheel motor
- Perform Pm service
- Shop Supplies

Parts Issued

Quantity

Aw68 Hydro Fluid Hydr	4.00
Napagold Oil Filter	1.00
Napa Qt 15w40	3.00
Napagold Fuel Filter	1.00
Napagold Air Filter	1.00
Shop Supplies	1.00

Hours: 8.00

Comm: 0.00

Labor: 584.00

Parts: 45.49

Total: 629.49

6/6/2022
10:28:26 AM

Palm Beach County Fleet Management Asset Maintenance History
10209125 2018 JACOBSON 088043 Ballfield Groomer

Work Order: 2101050 **Meter:** 776 **In Date:** 01/28/2021 **Closed:** 01/29/2021
Problem: wont start

Work Completed

Parts Issued

Quantity

- charge & load test battery, ng, replaced battery & check charging system
- Shop Supplies

Battery	1.00
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 135.33 Total: 208.33

Work Order: 2102363 **Meter:** 807 **In Date:** 03/02/2021 **Closed:** 03/12/2021
Problem: fluid leaking by left rear wheel

Work Completed

Parts Issued

Quantity

- Fluid leak at lr wheel, traced to line fittings on motor, R&r lines to tighten fittings & test run
- Shop Supplies

Non-chlor Brake Clnr	1.00
Shop Supplies	1.00

Hours: 1.50 Comm: 0.00 Labor: 109.50 Parts: 7.44 Total: 116.94

Work Order: 2110979 **Meter:** 1043 **In Date:** 10/12/2021 **Closed:** 11/30/2021
Problem: no forwer action and dont shut off

Work Completed

Parts Issued

Quantity

- Check Won't Shut Off, Repair Starter Solenoid Bracket And Re-attach Starter Solenoid, Replaced Damaged Pedal Proximity Switch
- Replaced Damaged Forward/reverse Pedal And Hardware, Adjusted All Pedal Linkages
- Adjusted Parking Brake
- Shop Supplies

Switch, Prox	1.00
Pedal Bracket	1.00
Clevis Pin	1.00
Pedal Assy	1.00
Tread Pedal	1.00
Shop Supplies	1.00

Hours: 5.00 Comm: 0.00 Labor: 365.00 Parts: 785.63 Total: 1,150.63

Work Order: 2205436 **Meter:** 1043 **In Date:** 05/24/2022 **Closed:** 05/24/2022
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 33.00 Total Labor: 2,359.00 Total Comm: 0.00 Total Parts: 1,922.51