Total Hours: 106.50	Labor: 6,697.50	Parts: 2,878.75	Comm: 0.00		Charge	1: 9576.25	
	Labor. 0,097.50	Falls. 2,070.75			Charged	1. 9570.25	
Work Order: 9389 Problem: PRE-	86 Met DELIVERY INSPECTI	er: 0 ON		In Date:	06/15/2009	Closed:	06/15/2009
Work Completed	d						
- Pre-delivery Ins	spection						
	Hours: 2.00	Comm: 0.00	Labor: 120.00	Parts: 0.0	0	Total:	120.00
Work Order: 9390 Problem: INST	31 Met ALL TRAILER PLUG	er: 0		In Date:	06/16/2009	Closed:	06/17/2009
Work Completed	d		Parts Issued			Q	uantity
- Change Trailer	Plug, Rewire & Test Ol	(Shop Supplies				1.00
- Shop Supplies	0		755-5046 Male Co	onnector			1.00
	Hours: 1.50	Comm: 0.00	Labor: 90.00	Parts: 8.8	3	Total:	98.83
Nork Order: 1008 Problem: pm/ l		er: 0		In Date:	07/30/2010	Closed:	08/17/2010
Work Completed	d		Parts Issued			Q	uantity
- Pm Service			Shop Supplies				1.00
- Nitro 5 tires							
- Shop Supplies							
	Hours: 5.00	Comm: 0.00	Labor: 300.00	Parts: 2.0	0	Total:	302.00
Nork Order: 1109 Problem: PM	872 Met	er: 0		In Date:	09/15/2011	Closed:	10/27/2011
Work Completed	d		Parts Issued			Q	uantity
- Pm 2 axle traile	r		Shop Supplies				1.00
- Service onboar	d generator		42385 Seal				4.00
- R&r Generator	box floor to gain acces	s to brake away bottom	10w30 Motor Oil				1.00
- Charge and ck	brakaway battery		Bpr5es Spark Plug	7734			1.00
- Shop Supplies							
	Hours: 7.50	Comm: 0.00	Labor: 450.00	Parts: 12.	20	Total	462.38

10179563

Palm Beach County Fleet Management Asset Maintenance History 2009 CARGO MATE TRAILERS CM8X20 Trailer, Enclosed Storage

Work Order: Problem:	1210192 pm service	Meter:	0		In Date:	10/23/2012	Closed:	11/16/2012
Work Com	pleted			Parts Issued			Qu	uantity
- Pm				Wg16 White Lithiur	n Cr			1.00
- Service tr	ailer			Carb-choke Clnr 13	OZ			1.00
- Fuel sys s	ervice flush			Napa Heavy Duty 3	0qt			1.00
- Carb clea	n and rebuild			Shop Supplies				1.00
- Shop Sup	oplies							
	Hours: 7.50		Comm: 0.00	Labor: 450.00	Parts: 14.	39	Total:	464.39
Nork Order: Problem:	1312553 pm service	Meter:	0		In Date:	12/17/2013	Closed:	12/20/2013
Work Com	pleted			Parts Issued			Qı	uantity
- Pm Traile	r			10w30 Motor Oil				1.00
- R&r gene	erator platform to repalce break	kaway battery		12v5amp/hour Batt	ery			1.00
- Service G		, ,		Shop Supplies				1.00
- Shop Sup	oplies							
	Hours: 7.00		Comm: 0.00	Labor: 420.00	Parts: 23.	95	Total:	443.95
Vork Order: Problem:	1504005 pm service/ check turn signal	Meter:	0		In Date:	04/17/2015	Closed:	04/27/201
Work Com	pleted			Parts Issued			Qı	uantity
- Pm				Seal 2.250x3.371x.3	75			4.00
- Service G	enerator			Brake Cleaner				2.00
- Mount 4	new tires and nitro fill			Napa Quart 5w20				1.00
- Flush fue	sys and servic			Tr416 Valve Stem				4.00
- Shop Sup	•			762173406 225-75	r15			4.00
				Shop Supplies				1.00
				Tire Disposal Fee				4.00
	Hours: 9.00		Comm: 0.00	Labor: 540.00	Parts: 638	3.71	Total:	1,178.71

10179563

Palm Beach County Fleet Management Asset Maintenance History 2009 CARGO MATE TRAILERS CM8X20 Trailer, Enclosed Storage

Work Order: 1604021 Meter: 0 Problem: pm service, jack foot plate, check brake light wiring

In Date: 04/15/2016 **Closed:** 04/28/2016

Work Com	pleted			Parts Issued			Qı	uantity
- Pm				Seal 2.250x3.371x.37	5			4.00
- Service G	Generator			Napa 10w30 Qt				1.00
- r/r 2 red	Marker lights			M C Lamp				2.00
- R/r rottin	ng trailer jack and foot			Jac 5k Tw A Frame				1.00
- Shop Sup	oplies			Jack Support				1.00
				Shop Supplies				1.00
	Hours: 7.00		Comm: 0.00	Labor: 420.00	Parts: 50.	29	Total:	470.29
Nork Order: Problem:	1604545 trailer plug not working	Meter:	0		In Date:	04/29/2016	Closed:	05/12/2016
Work Com	pleted			Parts Issued			Qı	antity
- Replace t	trailer plug			Male Trailer Connect	or			1.00
- Shop Sup	oplies			Shop Supplies				1.00
	Hours: 1.50		Comm: 0.00	Labor: 90.00	Parts: 9.5	2	Total:	99.52
Vork Order: Problem:	1608619 replace side rollout vinyl	Meter:	0		In Date:	08/18/2016	Closed:	09/22/2016
Work Com	pleted			Parts Issued			Qı	antity
- Mount 2	2 new brackets and replace rolo	ut vinyl		Jb Weld Kwik Weld				1.00
- Shop Sup	oplies			Bottom Brkt				2.00
				Bottom Brkt				2.00
				Fabric Awning 16 Ft				1.00
				Shop Supplies				1.00
				Freight Charge				1.00
	Hours: 4.50		Comm: 0.00	Labor: 270.00	Parts: 624			894.31

7/5/2022 12:14:01 PM

Work Order: 1704213 Problem: pm service/ check awning post	Meter: 0		In Date: 04/26/20	17 Closed:	05/08/2017
Work Completed		Parts Issued		Q	uantity
- Pm		Seal 2.250x3.371x	.375		4.00
- Service Gen and replace fuel lines		Non-chlor Brake (Clnr		1.00
- Check all 2 post repair frt post. Slides repla	ice rear post handle lock	Napa 10w30 Qt			1.00
- Replace male trailer plug		Clean-r-carb 20oz			1.00
- Replace brake away cable		Spark Plug			1.00
- Shop Supplies		Male Trailer Conn	ector		1.00
		Grease Cap Plug			4.00
		Rv Trailer Handle			1.00
		Shop Supplies			1.00
Hours: 10.50	Comm: 0.00	Labor: 630.00	Parts: 61.28	Total:	691.28
Work Order: 1706186 Problem: repair canopy mechanism and ta	Meter: 0		In Date: 06/22/20	17 Closed:	06/27/2017
Work Completed		Parts Issued		Q	uantity
- Readjust spring and go over unit		Shop Supplies			1.00
- Shop Supplies					
Hours: 1.00	Comm: 0.00	Labor: 60.00	Parts: 2.00	Total:	62.00

10179563

Palm Beach County Fleet Management Asset Maintenance History 2009 CARGO MATE TRAILERS CM8X20 Trailer, Enclosed Storage

/ork Order: 1804716 Problem: pm service	Meter: 0	In Dat	e: 05/	/04/2018 C	losed:	05/18/201
Work Completed		Parts Issued			Qı	antity
- pm service		Seal 2.250x3.371x.375				4.00
- service gerator on trailer tongue		Grease Cap Plug				1.00
- service all brakes, clean and adjust		Non-chlor Brake Clnr				3.00
- replace breakaway battery		12v5amp/hour Battery				1.00
- replace trailer plug and repair wire from	m battery to harness	Spark Plug				1.00
- replace fuel shut oof, fuel line and carb	o on generator	Male Trailer Connector				1.00
- Shop Supplies		Fuel Shutoff Valve				1.00
		Carb W/ Gaskets				1.00
		Shop Supplies				1.00
		Freight Charge				1.00
Hours: 11.00 ork Order: 1905422 Problem: pm service	Comm: 0.00 Meter: 0	Labor: 660.00 Parts:	265.51 e: 05/	/20/2019 C		925.51 05/30/20
ork Order: 1905422 Problem: pm service				/20/2019 C	losed:	05/30/20
ork Order: 1905422 Problem: pm service Work Completed		In Dat		/20/2019 C	losed:	
ork Order: 1905422 Problem: pm service Work Completed - pm service		In Dat Parts Issued		/20/2019 C	losed:	05/30/20 antity
ork Order: 1905422 Problem: pm service Work Completed		In Dat Parts Issued Spark Plug		/20/2019 C	losed:	05/30/20 iantity 1.00
ork Order: 1905422 Problem: pm service Work Completed - pm service - service generator on tongue	Meter: 0	In Dat Parts Issued Spark Plug Napa 10w30 Qt		/20/2019 C	losed:	05/30/20 antity 1.00 1.00
ork Order: 1905422 Problem: pm service Work Completed - pm service - service generator on tongue - replace all brakes and drums	Meter: 0	In Dat Parts Issued Spark Plug Napa 10w30 Qt 12v5amp/hour Battery		/20/2019 C	losed:	05/30/20 iantity 1.00 1.00 1.00
ork Order: 1905422 Problem: pm service Work Completed - pm service - service generator on tongue - replace all brakes and drums - remove platform. replace breakaway b	Meter: 0	In Dat Parts Issued Spark Plug Napa 10w30 Qt 12v5amp/hour Battery Breakaway Switch		/20/2019 C	losed:	05/30/20 antity 1.00 1.00 1.00 1.00
ork Order: 1905422 Problem: pm service Work Completed - pm service - service generator on tongue - replace all brakes and drums - remove platform. replace breakaway b - replace spot light unit	Meter: 0	In Dat Parts Issued Spark Plug Napa 10w30 Qt 12v5amp/hour Battery Breakaway Switch Rh Brake Assy		/20/2019 C	losed:	05/30/20 antity 1.00 1.00 1.00 1.00 2.00
ork Order: 1905422 Problem: pm service Work Completed - pm service - service generator on tongue - replace all brakes and drums - remove platform. replace breakaway b - replace spot light unit - replace top side marker	Meter: 0	In Date Parts Issued Spark Plug Napa 10w30 Qt 12v5amp/hour Battery Breakaway Switch Rh Brake Assy Lh Brake Assy		/20/2019 C	losed:	05/30/20 antity 1.00 1.00 1.00 2.00 2.00
ork Order: 1905422 Problem: pm service Work Completed - pm service - service generator on tongue - replace all brakes and drums - remove platform. replace breakaway b - replace spot light unit - replace top side marker - drain fuel tank add fresh fuel	Meter: 0	In Dat Parts Issued Spark Plug Napa 10w30 Qt 12v5amp/hour Battery Breakaway Switch Rh Brake Assy Lh Brake Assy Spark Plug		/20/2019 C	losed:	05/30/20 antity 1.00 1.00 1.00 2.00 2.00 1.00
ork Order: 1905422 Problem: pm service Work Completed - pm service - service generator on tongue - replace all brakes and drums - remove platform. replace breakaway b - replace spot light unit - replace top side marker - drain fuel tank add fresh fuel	Meter: 0	In Dat Parts Issued Spark Plug Napa 10w30 Qt 12v5amp/hour Battery Breakaway Switch Rh Brake Assy Lh Brake Assy Spark Plug M C Lamp		/20/2019 C	losed:	05/30/20 antity 1.00 1.00 1.00 2.00 2.00 1.00 1.00 1.00
York Order: 1905422 Problem: pm service Work Completed - pm service - service generator on tongue - replace all brakes and drums - remove platform. replace breakaway b - replace spot light unit - replace top side marker - drain fuel tank add fresh fuel	Meter: 0	In Date Parts Issued Spark Plug Napa 10w30 Qt 12v5amp/hour Battery Breakaway Switch Rh Brake Assy Lh Brake Assy Lh Brake Assy Spark Plug M C Lamp Floodlight		/20/2019 C	losed:	05/30/20 antity 1.00 1.00 1.00 2.00 2.00 1.00 1.00 1.00 1.00

Labor: 1,139.00

Parts: 1,040.22

Total: 2,179.22

Vork Order: 20062 Problem: pm se		leter: 0		In Date:	06/23/2020	Closed:	07/22/2020
Work Completed			Parts Issued			Qı	antity
- pm service			Seal 2.250x3.371x.37	75			4.00
- service tongue g	ienerator		Non-chlor Brake Cln	r			2.00
	d trailer connector		Spark Plug				1.00
- Shop Supplies			Napa 10w30 Qt				1.00
			Male Trailer Connect	tor			1.00
			Shop Supplies				1.00
	Hours: 7.50	Comm: 0.00	Labor: 547.50	Parts: 33.	30	Total:	580.80
ork Order: 20125		fleter: 0		In Date:	12/16/2020	Closed:	12/18/2020
Problem: Replace	ce both roof vents	on trailer. One is disintegrated allowing	g rain to get into trailer.				
Work Completed			Parts Issued			Qı	antity
Increase And Dec			Roof Ventdome 14x	11 Mbita			2.00
- inspect And Rep	lace Both Rotted R	loof Vents	ROOT VEHILUOITIE 14X	14 white			2.00
- Inspect And Rep - Shop Supplies	lace Both Rotted R	loof Vents	Shop Supplies	14 White			1.00
	Hours: 1.50	Comm: 0.00		Parts: 88.0	09	Total:	
	Hours: 1.50		Shop Supplies		09 02/17/2021		1.00
- Shop Supplies	Hours: 1.50 90 N	Comm: 0.00	Shop Supplies Labor: 109.50	Parts: 88.			1.00 197.59
- Shop Supplies Vork Order: 21017	Hours: 1.50 90 N oor not closing/ sta	Comm: 0.00	Shop Supplies Labor: 109.50	Parts: 88.		Closed:	1.00 197.59
- Shop Supplies Vork Order: 21017 Problem: Side d Work Completed	Hours: 1.50 90 N oor not closing/ sta	Comm: 0.00	Shop Supplies Labor: 109.50 bent. Asset is at Fleet.	Parts: 88.		Closed:	1.00 197.59 03/12/2021
- Shop Supplies Vork Order: 21017 Problem: Side d Work Completed - remove all 3 side	Hours: 1.50 90 N oor not closing/ sta e door hinges n str	Comm: 0.00 leter: 0 aying shut. Looks like the top hinge is	Shop Supplies Labor: 109.50 bent. Asset is at Fleet. Parts Issued	Parts: 88.		Closed:	1.00 197.59 03/12/2021 uantity
- Shop Supplies Vork Order: 21017 Problem: Side d Work Completed - remove all 3 side	Hours: 1.50 90 N oor not closing/ sta e door hinges n str	Comm: 0.00 Meter: 0 aying shut. Looks like the top hinge is aighten out - disassemble door lock	Shop Supplies Labor: 109.50 bent. Asset is at Fleet. Parts Issued	Parts: 88.		Closed:	1.00 197.59 03/12/2021 uantity
- Shop Supplies Vork Order: 21017 Problem: Side d Work Completed - remove all 3 side replace spring for	Hours: 1.50 90 N oor not closing/ sta e door hinges n str	Comm: 0.00 Meter: 0 aying shut. Looks like the top hinge is aighten out - disassemble door lock	Shop Supplies Labor: 109.50 bent. Asset is at Fleet. Parts Issued	Parts: 88.	02/17/2021	Closed: Qu	1.00 197.59 03/12/2021 uantity
- Shop Supplies Vork Order: 21017 Problem: Side d Work Completed - remove all 3 side replace spring for - Shop Supplies Vork Order: 21105	Hours: 1.50 90 N oor not closing/ sta e door hinges n str slide lock n grease Hours: 3.50 57 N	Comm: 0.00 Meter: 0 aying shut. Looks like the top hinge is aighten out - disassemble door lock e - make new door stop	Shop Supplies Labor: 109.50 bent. Asset is at Fleet. Parts Issued Shop Supplies	Parts: 88.0 In Date: Parts: 4.00	02/17/2021	Closed: Qu Total:	1.00 197.59 03/12/2021 Jantity 1.00 259.50
- Shop Supplies /ork Order: 21017 Problem: Side d Work Completed - remove all 3 side replace spring for - Shop Supplies	Hours: 1.50 90 N oor not closing/ sta e door hinges n str slide lock n grease Hours: 3.50 57 N	Comm: 0.00 Meter: 0 aying shut. Looks like the top hinge is aighten out - disassemble door lock e - make new door stop Comm: 0.00	Shop Supplies Labor: 109.50 bent. Asset is at Fleet. Parts Issued Shop Supplies	Parts: 88.0 In Date: Parts: 4.00	02/17/2021	Closed: Qu Total:	1.00 197.59 03/12/2021 antity 1.00 259.50
- Shop Supplies Vork Order: 21017 Problem: Side d Work Completed - remove all 3 side replace spring for - Shop Supplies Vork Order: 21105	Hours: 1.50 90 N oor not closing/ sta e door hinges n str slide lock n grease Hours: 3.50 57 N tion Prep Charge	Comm: 0.00 Meter: 0 aying shut. Looks like the top hinge is aighten out - disassemble door lock e - make new door stop Comm: 0.00	Shop Supplies Labor: 109.50 bent. Asset is at Fleet. Parts Issued Shop Supplies	Parts: 88.0 In Date: Parts: 4.00	02/17/2021	Closed: Qu Total:	1.00 197.59 03/12/2021 antity 1.00 259.50
- Shop Supplies /ork Order: 21017 Problem: Side d Work Completed - remove all 3 side replace spring for - Shop Supplies /ork Order: 21105 Problem: Transi	Hours: 1.50 90 N oor not closing/ sta e door hinges n str slide lock n grease Hours: 3.50 57 N tion Prep Charge	Comm: 0.00 Meter: 0 aying shut. Looks like the top hinge is aighten out - disassemble door lock e - make new door stop Comm: 0.00	Shop Supplies Labor: 109.50 bent. Asset is at Fleet. Parts Issued Shop Supplies	Parts: 88.0 In Date: Parts: 4.00	02/17/2021	Closed: Qu Total:	1.00 197.59 03/12/2021 Jantity 1.00 259.50