### Palm Beach County Fleet Management Asset Maintenance History 10187834 2012 FORD F150 Pickup, 1/2 Ton

Total Hours: 111.30 Labor: 7,282.20 Parts: 6,036.68	Comm: 192.00	Charged: 13510.88
---	--------------	-------------------

Work Order: 1208238 Meter: 360 In Date: 08/30/2012 Closed: 09/04/2012

Problem: paint rust on braket

 Work Completed
 Parts Issued
 Quantity

 - Parts only
 T-1 Black Paint Gloss
 1.00

 Hours: 0.00
 Comm: 0.00
 Labor: 0.00
 Parts: 6.77
 Total: 6.77

Work Order: 1208248 Meter: 360 In Date: 08/31/2012 Closed: 08/31/2012

Problem: 1061 - Pre Delivery Inspection

#### **Work Completed**

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1302589 Meter: 2032 In Date: 03/15/2013 Closed: 03/20/2013

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. Service.		5w20 Engine Oil		6.00
- Rotate and balance all tires.		Napagold Oil Filte	r	1.00
- Install new fire extinguisher with brack	et.	Floor Mat-2pc Rul	o Bk	1.00
- Shop Supplies		Fire Extinguisher		1.00
		Custom Bracket Fi	re Ex	1.00
		Used Firex Refurb	ed F	1.00
		Shop Supplies		1.00
Hours: 3.50	Comm: 0.00	Labor: 210.00	Parts: 196.12	Total: 406.12

Work Order: 1304855 Meter: 2556 In Date: 05/15/2013 Closed: 05/16/2013

Problem: Bulbs on arrow board inop.

Work Complete	d		Parts Issued		Quantity
- Test and replac	ce four failed amber b	ulbs on arrow board with new.note	7414y Amber Lig	ht Arr	4.00
pins broken off fi	rom back of bulbs.		Shop Supplies		1.00
- Shop Supplies					
	Hours: 1.00	Comm: 0.00	Labor: 60.00	Parts: 38.12	Total: 98.12

### Palm Beach County Fleet Management Asset Maintenance History 10187834 2012 FORD F150 Pickup, 1/2 Ton

Work Order: 1310723 Meter: 3820 10/25/2013 **Closed:** 10/31/2013 In Date: Problem: Pm service. **Work Completed Parts Issued** Quantity Used Fire X Refurbished 1.00 - P.m. Service. 1.00 Custom Bracket Fire Ex - Replace seal beam in arrow board. Floor Mat-2pc Rub Bk 1.00 - install new fire extinguisher with bracket. Bulb 1.00 - Rotate and balance all tires. 5w20 Engine Oil 7.00 - Shop Supplies

Napagold Oil Filter

**Brake Cleaner** 

Washer Fl

1.00

1.00

1.00

Work Order: 1403811 Meter: 5368 In Date: 03/18/2014 Closed: 04/30/2014

Problem: Pm service

Work Completed		Parts Issued		Quantity
- P.m. Service.		5w20 Engine Oil		7.00
- Rotate and balance all tires.		Napagold Oil Filte	er	1.00
- Shop Supplies		Mac Wite Lithium	Gres	1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 29.12	Total: 209.12

Work Order: 1403812 Meter: 5367 In Date: 03/18/2014 Closed:

Problem: Pm service

#### **Work Completed**

-

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

### Palm Beach County Fleet Management Asset Maintenance History 10187834 2012 FORD F150 Pickup, 1/2 Ton

Work Order: 1412677 Meter: 10109 In Date: 12/18/2014 Closed: 12/29/2014

Problem: P.M. service.

Work Completed		<b>Parts Issued</b>		Quantity
- Pm service.		5w20 Engine Oil		7.00
- Rotate and balance all four tires.		Napagold Oil Filter		1.00
- Shop Supplies		Used Fire X Refurbi	ished	1.00
		Washer Fluid Conce	entr	1.00
		Wiper Blade		2.00
		Stg Wheel Cov - Fo	ord	1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 69.71	Total: 249.71

Work Order: 1500228 Meter: 10258 In Date: 01/07/2015 Closed: 01/15/2015

**Problem:** A/c blows warm only.

Work CompletedParts IssuedQuantity- Transport vehicle to and from dealer for repairing Ac leak between suction hose and compressor.Shop Supplies1.00

- Shop Supplies

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 2.00 Total: 122.00

Work Order: 1502914 Meter: 11018 In Date: 03/20/2015 Closed: 03/26/2015

Problem: Driver side mirror fell off

Work Completed		Parts Issued		Quantity
- Replace boken driver side rear view mirror.		Mirror Asy		1.00
- Shop Supplies		Shop Supplies		1.00
Hours: 0.50	Comm: 0.00	Labor: 30.00	Parts: 291.89	Total: 321.89

### Palm Beach County Fleet Management Asset Maintenance History 10187834 2012 FORD F150 Pickup, 1/2 Ton

Work Order: 1507491 Meter: 12661 In Date: 07/28/2015 Closed: 08/11/2015

**Problem:** P.M. service and check A/C.

Work Completed		Parts Issued		Quantity
- P.m. Service.		5w20 Engine Oil		7.00
- Test battery and charging system.recharge and retest battery,failed loa		Napagold Oil Filte	r	1.00
test.replace defective battery.	,	Napagold Air Filt	er	1.00
- A/c performance test.compessor noisy and suction side pressure remains low.replace defective compressor,accumulator and expansion valve.flush		Wiper Blade		2.00
		Battery 65		1.00
system.vacuum and recharge to specs.  - Rotate and balance all btitres.		R134a Lv Shop 2 E8 A/c Oil Univ W Dye		2.00
				1.00
- Shop Supplies		Compressor		1.00
		Accumulator		1.00
		Valve Assy		1.00
		Seal Kits		1.00
		Seal		1.00
		A/cv Belt		1.00
		Shop Supplies		1.00
Hours: 9.00	Comm: 0.00	Labor: 540.00	Parts: 905.06	Total: 1,445.00

Work Order: 1511616 Meter: 13150 In Date: 11/13/2015 Closed: 11/23/2015

**Problem:** Tail lamps stolen. Vandalised.

Troblem Tair lampe etelem variationes.				
Work Completed		Parts Issued		Quantity
- Fabricate and replace left and right tail lamp assemblies.	replace left and	screw		4.00
right rear Led strobe lights and wiring.		Ptex Ultra Grey 30	Z	1.00
- Shop Supplies		Bulb		4.00
		Fab Loom-split Po	oly	6.00
		Vtx609c Led Strob	oe Cl	2.00
		Tail Ligth Ass		1.00
		Lamp Assembly		1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 573.07	Total: 753.07

### Palm Beach County Fleet Management Asset Maintenance History 10187834 2012 FORD F150 Pickup, 1/2 Ton

Work Order: 1602900 Meter: 14178 In Date: 03/18/2016 Closed: 03/23/2016

Problem: Pm service

Work Completed		Parts Issued		Quantity
- Pm service.		5w20 Engine Oil		7.00
- Resurface both front brake rotors due to pulsation	on when braking.service	Napagold Oil Filte	er	1.00
pads and calipers.		Used Fire X Refurb	oished	1.00
- Rotate and balance all four tires.		22" Wiper Blade		2.00
- Shop Supplies		Brake Cleaner		2.00
		Shop Supplies		1.00
Hours: 5.50	Comm: 0.00	Labor: 330.00	Parts: 50.51	Total: 380.51

Work Order: 1609954 Meter: 16183 In Date: 09/23/2016 Closed: 09/29/2016

**Problem:** P.M. service and towed in for no start.

Work Completed		Parts Issued		Quantity
- P.m. Service.		Napagold Oil Filter		1.00
- Rotate and balance all tires.		5w20 Engine Oil		6.00
- Replace trailer light fuse		Washer Fluid Conc	entr	1.00
- Ddiagnose and replace defective fuel pump relay.		22" Wiper Blade		2.00
- Shop Supplies		Mac Wite Lithium	Gres	1.00
		Bp Fmx-lp F Mx Fu	se	1.00
		Relay		1.00
		Shop Supplies		1.00
Hours: 4.50	Comm: 0.00	Labor: 270.00	Parts: 55.87	Total: 325.87

Work Order: 1610015 Meter: 16175 In Date: 09/23/2016 Closed: 09/23/2016

Problem: crank but wont start

#### **Work Completed**

- Tow From: Roads Lot To: vista

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

#### Palm Beach County Fleet Management Asset Maintenance History 10187834 2012 FORD F150 Pickup, 1/2 Ton

Work Order: 1704335 Meter: 18066 In Date: 04/28/2017 Closed: 05/05/2017

**Problem:** P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service.		5w20 Engine Oil		6.00
- Check strobe light switch ,no display.replace switch and i	install ground	Napagold Oil Filte	r	1.00
circuit for switch retest.		22" Wiper Blade		2.00
- Rotate and high speed balance all four wheels. Nitro fill a	all.	Washer Fluid Cond	centr	1.00
- Shop Supplies		Used Fire X Refurb	pished	1.00
		Rocker Led Blk Am	nbe	1.00
		Shop Supplies		1.00
Hours: 3.50	Comm: 0.00	Labor: 210.00	Parts: 48.41	Total: 258.41

Work Order: 1710957 Meter: 20536 In Date: 11/03/2017 Closed: 11/09/2017

Problem: PM Service

Work Completed	Parts Issued	Quantity
- P.m. service.	5w20 Engine Oil	6.00
- R&r right front door panel and replace damaged lock cylinder ar	d key Napagold Oil Filter	1.00
cylinder to vehicle.	22" Wiper Blade	2.00
- Rotate and high speed balance all four tires.	Used Fire X Refurbished	1.00
- Shop Supplies	Stg Wheel Cov - Ford	1.00
	Floor Mat-2pc Rub Bk	1.00
	Lock Cylinder	1.00
	Shop Supplies	1.00
Hours: 4.50 Comm: 0	.00 Labor: 270.00 Parts: 165.	.94 Total: 435.9

### Palm Beach County Fleet Management Asset Maintenance History 10187834 2012 FORD F150 Pickup, 1/2 Ton

Work Order: 1804721 Meter: 22766 In Date: 05/04/2018 Closed: 05/09/2018

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filte	r	1.00
- Rotate and balance all four tires.nitrogen fill and reset Tpms Shop Supplies		5w20 Engine Oil		6.00
		22" Wiper Blade		2.00
		Used Fire X Refurbished  Mac Wite Lithium Gres  Light Socket		1.00
				1.00
				1.00
		Shop Supplies		1.00
Hours: 3.50	Comm: 0.00	Labor: 210.00	Parts: 58.60	Total: 268.60

Work Order: 1807165 Meter: 23831 In Date: 07/13/2018 Closed: 07/18/2018

Problem: TPMS light on.

Work Completed		Parts Issued		Quantity
- Repair right front tire and balance .nitrogen fill tires.		Shop Supplies		1.00
- Shop Supplies				
Hours: 1.00	Comm: 0.00	Labor: 60.00	Parts: 2.00	Total: 62.00

Work Order: 1807652 Meter: 23991 In Date: 07/27/2018 Closed: 07/31/2018

Problem: Check wipers, driver side bad.

#### **Work Completed**

- Test and replace defective wiper blades. Retest

Hours: 0.20 Comm: 0.00 Labor: 12.00 Parts: 0.00 Total: 12.00

# Palm Beach County Fleet Management Asset Maintenance History 10187834 2012 FORD F150 Pickup, 1/2 Ton

Problem: P.M. service.

Work Completed		Parts Issued		Quantity					
<ul> <li>P.m. service.</li> <li>Charge battery fully . Test starting and charging systems. Battery failed load test . R&amp;r defective battery .</li> <li>Rotate and balance all four tires. Nitrogen fill all.</li> <li>Shop Supplies</li> </ul>		Napagold Oil Filter  Napa Quart 5w20  Napagold Air Filter  22" Wiper Blade  Used Fire X Refurbished		1.00 6.00 1.00 2.00					
					1.00				
							Battery 65		1.00
							Shop Supplies		1.00
				Hours: 4.00 Comn	m: 0.00	Labor: 268.00	Parts: 238.16	Total: 506.16	

Work Order: 1902928 Meter: 25643 In Date: 03/15/2019 Closed: 03/19/2019

Problem: Wipers inop.

Work Completed		Parts Issued		Quantity
<ul><li>Diagnose wiper circuit.replace defective wiper relay.</li><li>Shop Supplies</li></ul>		Relay		1.00
		Shop Supplies		1.00
Hours: 1.00	Comm: 0.00	Labor: 67.00	Parts: 21.56	Total: 88.56

Work Order: 1904040 Meter: 26059 In Date: 04/12/2019 Closed: 04/17/2019

**Problem:** Power shutting down for message board, Sign not staying in locked position.

Work Completed		Parts Issued		Quantity
- Test arrow board operation .r&r melted inline fuse holder and retest operation .		Fuse Holder		1.00
		Wire Asy		1.00
- Computer diagnose airbag light , Code b0091 . Test and I door harness . Clear code and retest .	replace left front	Shop Supplies		1.00
- Shop Supplies				
Harris 2 00	20,000	Labor 407 CO	Darte: 20 20	Total: 000.00

Hours: 2.80 Comm: 0.00 Labor: 187.60 Parts: 36.39 Total: 223.99

### Palm Beach County Fleet Management Asset Maintenance History 10187834 2012 FORD F150 Pickup, 1/2 Ton

Work Order: 1905358 Meter: 26188 In Date: 05/17/2019 Closed: 05/20/2019

Problem: Repair right rear tire.

Work CompletedParts IssuedQuantity- Repair right rear tire and balance . Nitrofill all.Shop Supplies1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 67.00 Parts: 3.00 Total: 70.00

Work Order: 1905763 Meter: 26345 In Date: 05/31/2019 Closed: 06/05/2019

Problem: Check fan operation.

 Work Completed
 Parts Issued
 Quantity

 - Test and replace blower resistor and retest .
 Blower Resistor
 1.00

 - Shop Supplies
 Shop Supplies
 1.00

 Hours: 0.80
 Comm: 0.00
 Labor: 53.60
 Parts: 33.75
 Total: 87.35

Work Order: 1906824 Meter: 26429 In Date: 06/28/2019 Closed: 07/09/2019

Problem: PM Service, Transmission slipping.

Work Completed		Parts Issued		Quantity
- P.m. service.			ſ	1.00
- Test drive for transmission concern . Computer diagnose , no codes . Serrvice and inspect transmission . Flush and refill and road test . Could not dupicate slipping concern at this time .	5w20 Engine Oil		7.00	
	22" Wiper Blade		2.00	
	Washer Fluid Concentr		1.00	
- Mount and balance all four tires . Nitrofill all.	all. oil auto		14.00	
- Computer diagnose code P0480 . Perform pinpoint test . R8 cooling fan assembly . Clear code and retest .	क्षेr defective	Hankook P235 75r	17 Dp At	4.00
- Complete front end alignment and road test Shop Supplies	Fan Assy Shop Supplies		1.00	
			1.00	
	Tire Disposal Fee		4.00	
Hours: 11.00 Cor	mm: 0.00	Labor: 737.00	Parts: 1,336.34	Total: 2,073.34

### Palm Beach County Fleet Management Asset Maintenance History 10187834 2012 FORD F150 Pickup, 1/2 Ton

Work Order: 1909232 Meter: 26894 In Date: 09/06/2019 Closed: 09/16/2019

Problem: Check speedometer.

Work Completed	Parts Issued	Quantity
- Computer diagnose speedometer wrong . Perform pinpoint test . R&r	Instrument Cluster	1.00
defective cluster and Pmi module . Retest .	Purge Valve	1.00
	Shop Supplies	1.00
test . R&r defective purge valve . Clear codes and retest .		

- Shop Supplies

Hours: 3.50 Comm: 0.00 Labor: 234.50 Parts: 560.37 Total: 794.87

Work Order: 2001373 Meter: 29019 In Date: 02/07/2020 Closed: 02/11/2020

Problem: PM Service

Work Completed	Parts Issued		Quantity
- P.m. service.	Napagold Oil Filter		1.00
- Resurface both rear brake rotors and service calipers . Replace brake pads .	5w20 Engine Oil  22" Wiper Blade  Washer Fluid Concentr  Used Fire X Refurbished  Non-chlor Brake Clnr  Brk Fluid Dot 4-12oz  Brake Pad		6.00
Flush and bleed brake system . Road test .			2.00
<ul><li>Rotate and high speed balance all four wheels . Nitrofill all.</li><li>Shop Supplies</li></ul>			1.00
			1.00
			1.00
			1.00
			1.00
	Shop Supplies		1.00
Hours: 6.50 Comm: 0.00	Labor: 474.50	Parts: 126.15	Total: 600.65

Work Order: 2001592 Meter: 29074 In Date: 02/13/2020 Closed: 02/20/2020

**Problem:** Arrow board will not go to up postion .

Work Completed		Parts Issued		Quantity
- Diagnose arrow board actuator inop . R&r defecti	ive linear actuator and	Linear Actuator		1.00
retest .		Shop Supplies		1.00
- Shop Supplies				
Hours: 1.50	Comm: 0.00	Labor: 109.50	Parts: 673.53	Total: 783.03

## Palm Beach County Fleet Management Asset Maintenance History 10187834 2012 FORD F150 Pickup, 1/2 Ton

Work Order: 2010001 Meter: 33994 In Date: 10/02/2020 Closed: 10/08/2020

Problem: P.M. service and recall 19S07.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filte	1.00	
- Diagnose clunk and bump on road test . Perform T	5w20 Engine Oil 22" Wiper Blade Washer Fluid Concentr		2.00	
drive shaft slip yoke . Retest .  - Rotate and high speed balance all fou rtires . Nitrofill all.  - Transport to and from dealer for recall 19s07 .  - Shop Supplies				
			1.00	
		Repair Kit		1.00
		Shop Supplies		1.00
Hours: 5.80	Comm: 0.00	Labor: 423.40	Parts: 48.88	Total: 472.28

Work Order: 2104548 Meter: 35901 In Date: 04/23/2021 Closed: 04/27/2021

Problem: PM Service. will turn in on Friday

Work Completed		Parts Issued		Quantity
<ul> <li>- Preventive Maint. Service</li> <li>- Rotate and speed balance all. nitro fill</li> <li>- Check all brakes, R &amp; I new front brake pads, Resurface front rotors,</li> </ul>		Used Fire X Refurbished  Napagold Oil Filter  5w20 Engine Oil		1.00
				1.00
				6.00
service caliper slide pins Road test - Shop Supplies		Washer Fluid Concentr  22" Wiper Blade  Brk Fluid Dot 4-12oz  Non-chlor Brake Clnr		1.00
				2.00
				1.00
				1.00
		Brake Pad		1.00
		Shop Supplies		1.00
Hours: 6.50	Comm: 0.00	Labor: 474.50	Parts: 122.80	Total: 597.30

Work Order: 2105628 Meter: 36183 In Date: 05/20/2021 Closed: 05/24/2021

**Problem:** Bridge Chris, truck has a check engine light and when in drive will not move ,will be towed in

Work Completed	Parts Issued	Quantity
- Diagnose Cel on. Scan for code P2111, Perform pin point test. Identify b	ad Throttle Body	1.00
throttle body, Replace throttle body, Clean intake, test drive and clear cod	e. Gasket	1.00
- Shop Supplies	Throttle Body Cleaner	1.00
	Shop Supplies	1.00
Hours: 2.00 Comm: 0.00	Labor: 146.00 Parts: 94.20	Total: 240.20

#### Palm Beach County Fleet Management Asset Maintenance History 10187834 2012 FORD F150 Pickup, 1/2 Ton

Work Order: 2105717 Meter: 36149 In Date: 05/20/2021 Closed: 05/24/2021

Problem: engine light on wont move forward

**Work Completed** 

- Tow From: flavor pic rd east of jog To: 2601 vista

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 2107630 Meter: 36825 In Date: 07/14/2021 Closed: 07/15/2021

**Problem:** Bridge need wiper blades

Work Completed Parts Issued Quantity

- wipers not clearing windshield. Replace wiper blades and clean windshield 22" Wiper Blade 2.00

. Retest .

Hours: 0.20 Comm: 0.00 Labor: 14.60 Parts: 6.12 Total: 20.72

Work Order: 2112850 Meter: 37940 In Date: 12/03/2021 Closed: 12/07/2021

Problem: PM Service.

**Work Completed Parts Issued** Quantity 5w20 Engine Oil 6.00 - Performed P.m. Service & Inspection. Filter 1.00 - Performed Tire Rotation Balance On All 4wheels, Reset Tpms. 22" Wiper Blade 2.00 - Trailer Plug Corroded, Removed & Rewire New Trailer Plug And Check. trailer plug 1.00 - Shop Supplies 1.00

Shop Supplies 1.00
Hours: 4.00 Comm: 0.00 Labor: 292.00 Parts: 36.78 Total: 328.78

#### Palm Beach County Fleet Management Asset Maintenance History

2012 FORD F150 Pickup, 1/2 Ton 10187834

Work Order: 2204629 Meter: 39610 04/28/2022 **Closed**: 05/10/2022 In Date:

Problem: P.M. service Bridge Chris, truck is losing power and there is a noise going from the Lt. side

Work Completed		Parts Issued		Quantity
- Perform pm service		Relay		1.00
- Rotate and speed balance, nitro fill		Napagold Oil Filter		1.00
- Road test and Perform Ids diagnostic	5w20 Engine Oil		6.00	
27 Reference # 15-0137 Bjb fuse Relo	Washer Fluid Concentr		1.00	
shrink wiring - Shop Supplies		22" Wiper Blade		2.00
		Used Fire X Refurbished		1.00
		Fuse Relocate Kit		1.00
		Shop Supplies		1.00
Hours: 5.00	Comm: 0.00	Labor: 365.00	Parts: 74.63	Total: 439.63

Work Order: 2207925 Meter: 39927 In Date: 07/29/2022 **Closed**: 07/29/2022

**Problem:** Transition Prep Charge

#### **Work Completed**

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 111.30 Total Comm: 192.00 Total Labor: 7,282.20 **Total Parts: 6,036.68**