

10/24/2022
4:44:33 PM

Palm Beach County Fleet Management Asset Maintenance History
10202221 2017 FORD F150 Pickup, 1/2 Ton

Total Hours: 114.20 Labor: 7,854.20 Parts: 5,574.94 Comm: 4,515.09 Charged: 17944.23

Work Order: 1700311 **Meter:** 323 **In Date:** 01/10/2017 **Closed:** 01/10/2017
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1701267 **Meter:** 1401 **In Date:** 02/07/2017 **Closed:** 03/01/2017
Problem: Install strobe lights and bar across back of topper.

Work Completed

- Install front strobe lights and rear traffic advisor bar across rear window.fabricate and install wiring and switch.

- Shop Supplies

Parts Issued

Quantity

Vtx609c Led Strobe Cl	2.00
Vtx609a Led Strobe Am	2.00
Light Dominatir	1.00
Bracket	2.00
Fuse Holder	1.00
Rocker Led Blk Ambe	1.00
Clr Rtv Silcn Sealant	1.00
Fab Loom-split Poly	20.00
Primary Wire	20.00
Shop Supplies	1.00

Hours: 8.00 Comm: 0.00 Labor: 480.00 Parts: 962.81 Total: 1,442.81

Work Order: 1702301 **Meter:** 2102 **In Date:** 03/07/2017 **Closed:** 03/27/2017
Problem: Power outlet on dash inop.

Work Completed

- Power outlet inop.test and replace blown fuse.diagnose and replace defective outlets.

- Shop Supplies

Parts Issued

Quantity

Ring	3.00
20amp Mcase Fuse	1.00
Cover	1.00
Socket	2.00
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 121.39 Total: 181.39

10/24/2022
4:44:33 PM

Palm Beach County Fleet Management Asset Maintenance History
10202221 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 1704772 **Meter:** 4383 **In Date:** 05/12/2017 **Closed:** 05/22/2017
Problem: order spare key & program

Work Completed

Parts Issued

Quantity

- order and program 1 extra key
- Shop Supplies

ford side key	1.00
Shop Supplies	1.00

Hours: 0.50 Comm: 0.00 Labor: 30.00 Parts: 84.29 Total: 114.29

Work Order: 1705279 **Meter:** 5330 **In Date:** 05/30/2017 **Closed:** 06/02/2017
Problem: P.M. service and right rear tire going flat and left side topper lock rod loose.

Work Completed

Parts Issued

Quantity

- P.m. service.
- Resecure left side of topper lock rod by installing four new screws.
- Inspect and service winch.
- Repair right rear tire.balance and rotate all four.
- Shop Supplies

Napa Quart 5w30	6.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Shop Supplies	1.00

Hours: 5.50 Comm: 0.00 Labor: 330.00 Parts: 29.69 Total: 359.69

Work Order: 1709458 **Meter:** 11164 **In Date:** 09/28/2017 **Closed:** 09/28/2017
Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 9.54 Labor: 0.00 Parts: 0.00 Total: 9.54

Work Order: 1709841 **Meter:** 11872 **In Date:** 10/06/2017 **Closed:** 10/25/2017
Problem: PM Service, Pass door stays ajar, Rear window flasher bar comes loose.

Work Completed

Parts Issued

Quantity

- P.m. service.
- Inspect and service winch.
- Rotate and high speed balance all four tires Repair left rear flat tire.
- Shop Supplies

Napa Quart 5w30	6.00
Napagold Oil Filter	1.00
Mac Wite Lithium Gres	1.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours: 5.00 Comm: 0.00 Labor: 300.00 Parts: 47.30 Total: 347.30

10/24/2022
4:44:33 PM

Palm Beach County Fleet Management Asset Maintenance History
10202221 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 1910343 **Meter:** 41559 **In Date:** 10/04/2019 **Closed:** 10/21/2019
Problem: P.M. service.

Work Completed

- P.m. service.
- Resurface both rear rotors and service calipers . Replace rear brake pads .
Flush and bleed brake system . Road test.
- Charge battery fully . Test battery and charging system . Battery failed load
test . R&r defective battery .
- Inspect and service winch .
- Rotate and high speed balance all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Mac Wite Lithium Gres	1.00
22" Wiper Blade	2.00
Napagold Air Filter	1.00
Brk Fluid Dot 4-12oz	1.00
Battry Motorcraft	1.00
Brake Pad	1.00
Shop Supplies	1.00

Hours: 8.50

Comm: 0.00

Labor: 620.50 Parts: 322.66 Total: 943.16

Work Order: 2002149 **Meter:** 47110 **In Date:** 03/02/2020 **Closed:** 03/11/2020
Problem: P.M. service and install inverter .

Work Completed

- P.m. service.
- Replace cabin air filter and clean fresh air intake .
- Fabricate and install power inverter and Wire as needed .
- Balance and rotate all four tires . Nitrofill all.
- Inspect and service winch .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Wd40 Spr	1.00
Cabin Air Filter	1.00
Inverter Cable End 4ga	2.00
Fab Loom-split Poly	25.00
Cb185-100 Cir Brkr	1.00
Bulk Welding Cable	10.00
Bulk Battery Cable	20.00
Cpi 1575 Inverter 1500 W	1.00
Shop Supplies	1.00

Hours: 8.50

Comm: 0.00

Labor: 620.50 Parts: 514.26 Total: 1,134.76

10/24/2022
4:44:33 PM

Palm Beach County Fleet Management Asset Maintenance History
10202221 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 2104656 **Meter:** 64375 **In Date:** 04/27/2021 **Closed:** 05/05/2021
Problem: PM

Work Completed

- Preventive Maint. Service
- Inspect and service winches
- Pressure test cooling system, R & I new water pump asm. R & I thermostat housing and seal, Drain and flush coolant, R & I serp belt & a/c belt
- Inspect all, R & I four new tires, speed balance , nitro fill
- Perform front end alignment, road test
- Check and replace cabin filter Clean fresh air intake .
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
V Belt	1.00
V Belt	1.00
Gasket	1.00
Tmermostat Housing	1.00
Anti Freeze Motorcraft	2.00
Water Pump	1.00
245/70/17tire Contact	4.00
Cabin Air Filter	1.00
Tpms Sens Kit	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 14.00

Comm: 0.00

Labor: 1,022.00

Parts: 1,767.75

Total: 2,789.75

Work Order: 2108450 **Meter:** 69711 **In Date:** 08/04/2021 **Closed:** 08/05/2021
Problem: remove/plug nail front passenger tire

Work Completed

- Repair right front tire, balance and nitro service
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 2.65

Total: 75.65

10/24/2022
4:44:33 PM

Palm Beach County Fleet Management Asset Maintenance History
10202221 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 2205463 **Meter:** 82730 **In Date:** 05/12/2022 **Closed:** 05/24/2022
Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 8.98 Labor: 0.00 Parts: 0.00 Total: 8.98

Work Order: 2209512 **Meter:** 86723 **In Date:** 09/13/2022 **Closed:** 09/13/2022
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 114.20 Total Labor: 7,854.20 Total Comm: 4,515.09 Total Parts: 5,574.94