Total Hours: 171.25 Labor: 10,958.25 Parts: 8,194.67		Parts: 8,194.67	Comm: 485.90		Charged	: 19638.82		
Work Order: 838 Problem: PR	8608 E-DELIVERY INSF	Meter: PECTION	•		In Date:	05/15/2008	Closed:	05/15/2008
Work Complet	ted							
- Pre-delivery I	nspection							
	Hours: 2.00		Comm: 0.00	Labor: 120.00	Parts: 0.0	00	Total:	120.00
Nork Order: 932 Problem: P.N		Meter:	2551		In Date:	01/05/2009	Closed:	01/12/2009
Work Complet	ted			Parts Issued			Qı	ıantity
- Pm Service				Shop Supplies				1.00
- Road Test				1372 Oil Filter Frr	n Ph2 Wix 51	372		1.00
- Shop Supplie	es			5w20 Engine Oil				8.00
				Nb-19 Wiper Blad	les 19" Anco 3	31-19		2.00
				Used Firex Refurbe	ed Fire Extings	shers		1.00
	Hours: 3.50		Comm: 0.00	Labor: 210.00	Parts: 65.	.47	Total:	275.47
Work Order: 942 Problem: P.N		Meter:	4449		In Date:	08/21/2009	Closed:	08/21/2009
Work Complet	ted			Parts Issued			Qı	ıantity
- Pm Service				Shop Supplies				1.00
- Shop Supplie	es			1372 Oil Filter Frr	n Ph2 Wix 51	372		1.00
				5w20 Engine Oil				8.00
				Used Firex Refurbe	ed Fire Extings	shers		1.00
	Hours: 2.75		Comm: 0.00	Labor: 165.00	Parts: 55.	.80	Total:	220.80
Work Order: 946 Problem: Rep	6964 place passenger re	Meter: ar view n			In Date:	12/11/2009	Closed:	12/15/2009
Work Complet	ted			Parts Issued			Qı	ıantity
- R/r damaged	right side door vie	w mirror.		Shop Supplies				1.00
	_							
- Shop Supplie	es			Passenger Door Vi	ew Mirror			1.00

Work Order: Problem:	1002634 P. M. SERVICE	Meter:	6247		In Date:	03/15/2010	Closed:	03/23/2010
Work Com	pleted			Parts Issued			Qı	uantity
- P. M.				Shop Supplies				1.00
- Shop Sup	pplies			1372 Oil Filter Frr	m Ph2 Wix 51	372		1.00
				G10166 Fuel Filter	Mtc Fg1083 V	Vix 33243		1.00
				5w20 Engine Oil				8.00
				Used Firex Refurbe	ed Fire Extings	hers		1.00
	Hours: 2.75		Comm: 0.00	Labor: 165.00	Parts: 75.	07	Total:	240.07
Work Order: Problem:	1010572 P. M. SERVICE	Meter:	8682		In Date:	09/27/2010	Closed:	09/30/2010
Work Com	pleted			Parts Issued			Qı	uantity
- P. M. Ser	vice.			Shop Supplies				1.00
- Shop Sup	pplies			1372 Oil Filter Frr	m Ph2 Wix 51	372		1.00
				5w20 Engine Oil				8.00
	Hours: 2.75		Comm: 0.00	Labor: 165.00	Parts: 43.	46	Total:	208.46
Work Order: Problem:	1011076 flash canceiver	Meter:	8815		In Date:	10/07/2010	Closed:	10/08/2010
Work Com	pleted			Parts Issued			Qı	uantity
- Flash Car	nceiver			Shop Supplies				1.00
- Shop Sup	pplies							
•	Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 2.0	0	Total:	62.00

Palm Beach County Fleet Management Asset Maintenance History 10174391 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

 Work Order:
 1103990
 Meter:
 10611
 In Date:
 04/13/2011
 Closed:
 04/20/2011

 Problem:
 P. M. SERVICE

Work Completed		Parts Issued		Quantity
- P. M. Service.		Shop Supplies		1.00
- Replace 4 itres, fill with Nitrogen & reprogram T.	p.m.	Ca10262 Air Filter	Mtc Fa1883 Wix 49883	1.00
- Replace Rr reverse light bulb.		1372 Oil Filter Fr	m Ph2 Wix 51372	1.00
- Shop Supplies		G10166 Fuel Filter	Mtc Fg1083 Wix 33243	1.00
		5w20 Engine Oil		8.00
		Used Firex Refurb	ed Fire Extingshers	1.00
		Nb-19 Wiper Blac	des 19" Anco 31-19	2.00
		179636492 Lt245/	75r17 Wrangler Sr-a E	4.00
		Tire Disposal Fee		4.00
Hours: 5.75	Comm: 0.00	Labor: 345.00	Parts: 826.29	Total: 1,171.29

Work Order: 1111143 Meter: 13018 In Date: 10/20/2011 Closed: 10/31/2011

Problem: P. M. Service, & Water drips under dash when A/C is running.

Work Completed		Parts Issued		Quantity	
- P. M. Service.	Service.		Shop Supplies		
- C/s: A/c leak water inside vehicle. Inspect evapo	1372 Oil Filter Frm Ph2 Wix 51372		1.00		
clean A/c drain hose.	·			8.00	
- Shop Supplies		Used Firex Refurbed Fire Extingshers		1.00	
Hours: 3.75	Comm: 0.00	Labor: 225.00	Parts: 57.01	Total: 282.01	

Work Order: 1204124 Meter: 15417 In Date: 05/01/2012 Closed: 05/04/2012

Problem: pm service, also cup holder spring is broken on drive side

Work Completed		Parts Issued		Quantity
- pm		Shop Supplies		1.00
- ck d/s cup holder broken unable to repair replace cu	o holder assy	G10166 Fuel Filter	Mtc Fg1083 Wix 33243	1.00
- Shop Supplies	•	1372 Oil Filter Frn	n Ph2 Wix 51372	1.00
		5w20 Engine Oil		8.00
		Cup Holder Assy.		1.00
Hours: 3.25	Comm: 0.00	Labor: 195.00	Parts: 129.81	Total: 324.81

Hours: 2.75

Palm Beach County Fleet Management Asset Maintenance History 10174391 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Work Order: 1212175 Meter: 18285 12/18/2012 **Closed**: 12/20/2012 In Date: Problem: P.M.SERVICE **Parts Issued Work Completed** Quantity Ph2 Oil Filter Lbf Ph 1.00 - pm 00.8 Napa Quart 5w20 - verify nail in fl tire dismount patch mount balance add n2 31-19 Wiper Blades 19 2.00 - Shop Supplies **Shop Supplies** 1.00 Hours: 3.75 Comm: 0.00 Labor: 225.00 Parts: 50.05 Total: 275.05 Work Order: 1301969 Meter: 19192 In Date: 02/26/2013 **Closed**: 03/13/2013 Problem: fan speed ac 1 & 2 not working. ac, wiper wont work while truck is running unless you move ingitio **Work Completed Parts Issued** Quantity Blower Motor Resistor 1.00 - ck blower only work on 3,4 speed verify concern ck and replace bad blower resistor **Shop Supplies** 1.00 - ck some times ac and wiper wont work while truck is running ck and lube ignition switch - Shop Supplies Hours: 2.75 Comm: 0.00 Labor: 165.00 Parts: 23.51 Total: 188.51 Work Order: 1303104 Meter: 19507 In Date: 03/29/2013 Closed: 04/09/2013 **Problem:** left brake light out **Parts Issued Work Completed** Quantity Bulb 1.00 - replace left brake light bulb Hours: 0.50 Comm: 0.00 Labor: 30.00 Parts: 0.99 Total: 30.99 Work Order: 1310401 Meter: 22296 In Date: 10/16/2013 **Closed:** 10/23/2013 **Problem:** P.M.SERVICE **Parts Issued Work Completed** Quantity Napagold Fuel Filter 1.00 - pm Napagold Oil Filter 1.00 - Shop Supplies Napa Quart 5w20 00.8

Washer Fl

Comm: 0.00

Shop Supplies

Labor: 165.00

Parts: 44.14

1.00

1.00

Total: 209.14

Work Order:	1311356	Meter:	22488		In Date:	11/08/2013	Closed:	11/14/2013
Problem:	battery going dead, right windship	eld wiper ne	eds replacing					
Work Com	npleted			Parts Issued			Qı	uantity
- replace b	ooth wiper blades			Wiper Blade				2.00
·	battery ck charging sys in and fou	nd bad batt	ery replace battery	Battery				1.00
- Shop Su				Shop Supplies				1.00
	Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 130).10	Total:	190.10
Work Order: Problem:	1404436 pm/ install customers inverter	Meter:	24550		In Date:	05/06/2014	Closed:	05/15/2014
Work Com	npleted			Parts Issued			Qı	uantity
- Pm Servi	ice			Napagold Oil Filter				1.00
- Install Cเ	ustomer inverter and wire in			Napa Quart 5w20				8.00
- Shop Su	pplies			Cb185-100 Cir Brkr				1.00
				Cs4l Cable 4				10.00
				Cabl/lug				5.00
				Electrical Tape				1.00
				Shop Supplies				1.00
	Hours: 6.75		Comm: 0.00	Labor: 405.00	Parts: 124	1.87	Total:	529.87
Work Order:		Meter:	25290		In Date:	06/18/2014	Closed:	06/18/2014
Problem:	rear pass tire leak at valve stem							
Work Com	npleted			Parts Issued			Qı	uantity
- repair ric	ght rear tire			Shop Supplies				1.00
- Shop Su								
	Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 2.0	0	Total:	62.00
Work Order: Problem:		Meter:	26016		In Date:	08/18/2014	Closed:	08/19/2014
Work Com	npleted			Parts Issued			Qı	uantity
- ck low tii	re dismount patch mount balance	add n2 rr va	lve stem	Shop Supplies				1.00
- Shop Su	pplies							
	Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 2.0	0	Total:	62.00

Palm Beach County Fleet Management Asset Maintenance History 10174391 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Work Order: 1500873 Meter: 27751 In Date: 01/26/2015 Closed: 01/28/2015

Problem: rr turn signal

Work Completed		Parts Issued		Quantity
- repair rr signal light		Bulb		1.00
. 5		Bulb		1.00
Hours: 0.50	Comm: 0.00	Labor: 30.00	Parts: 1.11	Total: 31.11

Work Order: 1501634 Meter: 28128 In Date: 02/13/2015 Closed: 02/24/2015

Problem: pm

Work Completed		Parts Issued		Quantity
- pm		Napagold Oil Filter	r	1.00
- replace all tires		Napa Quart 5w20		8.00
- fill tires with nitrogen		Napagold Fuel Filt	er	1.00
- Shop Supplies		Wiper Blade		2.00
		Napagold Air Filter	ſ	1.00
		Washer Fl		1.00
		Used Fire X Refurbished 179636492 Lt245-75r17 Napagold Air Filter Shop Supplies		1.00
				4.00
				1.00
				1.00
		Tire Disposal Fee		4.00
Hours: 5.25	Comm: 0.00	Labor: 315.00	Parts: 1,161.19	Total: 1,476.19

Work Order: 1508246 Meter: 30789 In Date: 08/18/2015 Closed: 08/25/2015

Problem: P.M.SERVICE,BROKEN MIRROR PASSENGER SIDE

Work Completed		Parts Issued		Quantity
- pm		Napa Quart 5w20		8.00
- replace broken dright side rear view mirror assem	nbly	Napagold Oil Filte	r	1.00
- Shop Supplies		Washer Fluid Con-	centr	1.00
		Mirror Assembly		1.00
		Shop Supplies		1.00
Hours: 3.75	Comm: 0.00	Labor: 225.00	Parts: 229.01	Total: 454.01

Palm Beach County Fleet Management Asset Maintenance History 10174391 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Work Order: 1604055 Meter: 33051 In Date: 04/18/2016 Closed: 04/29/2016

Problem: Pm service.Low tire pressure warning light on.

Work Completed		Parts Issued	Quantity
- Pm service.		Napa Quart 5w20	8.00
- Replace all six body mounts		Napagold Oil Filter	1.00
- Repair right front tire.		Washer Fluid Concentr	1.00
- Rotate and balance.		Napagold Fuel Filter	1.00
- Shop Supplies		Napagold Air Filter	1.00
		Used Fire X Refurbished	1.00
		Wiper Blade	2.00
		Body Mount Kit	2.00
		Body Mount Kit	4.00
		Shop Supplies	1.00
Hours: 10.50	Comm: 0.00	Labor: 630.00 Parts: 563.98	Total: 1,193.98

Work Order: 1611504 Meter: 34485 In Date: 11/07/2016 Closed: 11/28/2016

Problem: PM service. Check engine light on.

Work Completed	Parts Issued	Quantity
- P.m.service	Napa Quart 5w20	8.00
- Ck Engine Light On,scan,found Code#po455. Perform Evap. System	Test Napagold Oil Filter	1.00
W/scanner, Inspect System&was Unable To Find Evap. Leak At This Tir	me. Washer Fluid Concentr	1.00
- Test Drive Before And After Repair.	Wiper Blade Anco	2.00
- Shop Supplies	Floor Mat-2pc Rub Bk	1.00
	Drain Plug	1.00
	Shop Supplies	1.00
Hours: 5.50 Comm: 0.0	D Labor: 330.00 Parts: 73.57	Total: 403.57

Palm Beach County Fleet Management Asset Maintenance History 10174391 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Work Order: 1700328 Meter: 35067 In Date: 01/11/2017 Closed: 01/25/2017

Problem: check engine light on

Work Completed		Parts Issued		Quantity
- Diagnose for check engine light on remove spare tire replace canister assembly and purge valve clear codes with scan tool and retest.		Valve		1.00
		Cannister		1.00
- Install and rewire trailer 6 way socket.		trailer plug		1.00
- Shop Supplies		Shop Supplies		1.00
Hours: 6.50	Comm: 0.00	Labor: 390.00	Parts: 238.46	Total: 628.46

Work Order: 1704505 Meter: 36099 In Date: 05/04/2017 Closed: 05/15/2017

Problem: PM Service.ABS light on.Pulls to left when braking.

Work Completed	Parts Issued	Quantity
- Pm Service.	Napa Quart 5w20	8.00
- C/s Abs light is on.test drive,scan found codes 1145,c1264.perform	Napagold Oil Filter	1.00
pinpoint test and found front wheel speed sensors failed.replace both f	ront Washer Fluid Concentr	1.00
wheel speed sensors.clear codes and test drive.	Napagold Fuel Filter	1.00
- Repair tailgate.	Used Fire X Refurbished	1.00 2.00 2.00 1.00
- Rotate and balance tires.	Wiper Blade Anco	
- Shop Supplies	Sensor Asy	
	Insert	
	Insert	1.00
	Shop Supplies	1.00
Hours: 8.50 Comm: 0.00	Labor: 510.00 Parts: 230.77	Total: 740.77

Palm Beach County Fleet Management Asset Maintenance History 10174391 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Work Order: 1708895 Meter: 36807 In Date: 09/15/2017 Closed: 09/27/2017

Problem: LEFT REAR BRAKE WAS STUCK, TRUCK PULLING TO RIGHT&ABS LIGHT WAS ON.

Work Completed

- C/s left rear brake was stuck and truck pulls to the right.perform brake inspection.scan and test drive.found bad calipers. Replace front and rear brake rotors, calipers, wheel bearings, clear codes. flush brake fluid.

- Test drive before and after repairs.
- Shop Supplies

Parts Issued		Quantity
Caliper w/ Hardwar	e - Left Front (eclips	1.00
Caliper w/ Hardwar	e - Right Front (eclip	1.00
Brake Rotor Hub		2.00
Caliper w/ Hardwar	e - Left Rear (eclipse	1.00
Caliper w/ Hardwar	e - Right Rear (eclips	1.00
Brake Rotor		2.00
Non-chlor Brake Cl	nr	2.00
B Fluid Dot 3-32oz		2.00
Pads		1.00
Rear Pads		1.00
Napa Bearing Cone		2.00
Napa Bearing Cup		2.00
Wheel Bearing Con	e - Inner - Front Wheel	2.00
Napa Bearing Cup		2.00
Wheel Seal - Front	Wheel	2.00
Shop Supplies		1.00
Labor: 660.00	Dorto: 1 025 91	Total: 1 605 0

Hours: 11.00 Comm: 0.00 Labor: 660.00 Parts: 1,025.81 Total: 1,685.81

Palm Beach County Fleet Management Asset Maintenance History 10174391 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Work Order: 1711198 Meter: 37070 In Date: 11/14/2017 Closed: 11/27/2017

Problem: PM Service

Work Completed		Parts Issued		Quantity
- Pm Service.		Napa Quart 5w20		8.00
- Repair third brake and utility bed lights.		Napagold Oil Filte	r	1.00
- Repair head light.		Washer Fluid Cond	centr	1.00
- Shop Supplies		Wiper Blade Anco		2.00
		Bulb		3.00
		Halogen Lamp Napagold Fuel Filter		1.00
				1.00
		Napagold Air Filte	er	1.00
		Shop Supplies		1.00
Hours: 4.75	Comm: 0.00	Labor: 285.00	Parts: 71.77	Total: 356.77

Work Order: 1805497 Meter: 37929 In Date: 05/30/2018 Closed: 06/12/2018

Problem: PM Service.Ac blower speed.

Work Completed	Parts Issued	Quantity
- Pm Service.	Napagold Oil Filter	1.00
- C/c ac does not work on low.perform pinpoint test and found b	ad ac Napa Quart 5w20	8.00
blower resistor.replace ac blower resistor.	Wiper Blade Anco	2.00
- Replace pintle pin.	Washer Fluid Concentr	1.00
- Shop Supplies	Used Fire X Refurbished	1.00
	Blower Resistor	1.00
	Pintle Pin W/clip	1.00
	Shop Supplies	1.00
Hours: 5.50 Comm	0.00 Labor: 330.00 Parts: 96.08	Total: 426.08

Palm Beach County Fleet Management Asset Maintenance History 10174391 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Work Order: 1812890 Meter: 38652 In Date: 12/19/2018 Closed: 01/22/2019

Problem: PM Service.

Work Completed		Parts Issued		Quantity
- Pm Service.		Napa Quart 5w20		8.00
 Rotate and balance four tires.correct N2 levels.relearn Tpms Clean debris from engine compartment and vents.clean exterior. Shop Supplies 		Napagold Oil Filter Napagold Fuel Filter		1.00
				1.00
		Shop Supplies		1.00
Hours: 4.75	Comm: 0.00	Labor: 318.25	Parts: 46.28	Total: 364.53

Work Order: 1906588 Meter: 39444 In Date: 06/24/2019 Closed: 06/28/2019

Problem: Right front tire flat.Left rear signal lamp bulb inop.

Work Completed	Parts Issued	Quantity
- Test and replace tail lamp bulbs.	Boxed Miniatures	2.00
- Repair and balance right front tire.	Shop Supplies	1.00
CI C I'		

- Shop Supplies

Hours: 1.50 Comm: 0.00 Labor: 100.50 Parts: 4.53 Total: 105.03

Work Order: 1906941 Meter: 39494 In Date: 07/03/2019 Closed: 07/22/2019

Problem: PM Service.Rear shocks broken..

Work Completed		Parts Issued		Quantity
- Pm Service.		Napa Quart 5w20		7.00
- Replace right side headlamp.		Napagold Oil Filte	r	1.00
- Replace both rear shocks.		Used Fire X Refurb	oished	1.00
- Balance and rotate four tires.		Napagold Air Filte	er	1.00
- Clean debris from engine compartment.		Washer Fluid Con-	centr	1.00
- Shop Supplies		Wiper Blade Anco		2.00
		Halogen Sealed B	eams	1.00
		Gas Grande Shock	(2.00
		Shop Supplies		1.00
Hours: 5.75	Comm: 0.00	Labor: 385.25	Parts: 196.20	Total: 581.45

Palm Beach County Fleet Management Asset Maintenance History 10174391 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Work Order: 1909286 Meter: 39705 In Date: 09/09/2019 Closed: 09/23/2019

Problem: Right front brake locking up.

Work Completed	Parts Issued	Quantity
- Replace both front calipers, pads, brake hoses, clean and repack v	rheel Permatex	1.00
bearings and flush brake fluid.	Non-chlor Brake Clnr	1.00
- Replace four tires and two Tpms sensors.	B Fluid Dot 3-32oz	1.00
- Test drive before and after repairs.	Brake Hose	1.00
- Shop Supplies	Brake Hose	1.00
	Wheel Seal - Front Wheel	2.00
	Pads	1.00
	Caliper w/ Hardware - Left F	ront (eclips 1.00
	Caliper w/ Hardware - Right	Front (eclip 1.00
	Tpms5 Sensor Tire Pre	2.00
	179636492 Lt245-75r17	4.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours: 9.00 Comm:	0.00 Labor: 603.00 Parts	: 1,408.55 Total: 2,011.5

Work Order: 1913034 Meter: 40460 In Date: 12/20/2019 Closed: 12/26/2019

Problem: Right rear signal light inop.

Work Completed		Parts Issued		Quantity
- Repair right rear signal lights.		Boxed Miniatures	3	2.00
Hours: 0.50	Comm: 0.00	Labor: 36.50	Parts: 1.53	Total: 38.03

Palm Beach County Fleet Management Asset Maintenance History 10174391 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Work Order: 1913221 Meter: 40544 In Date: 12/31/2019 Closed: 01/27/2020

Problem: PM Service. Wiper blades.

Work Completed		Parts Issued		Quantity
- Pm Service.		Battery		1.00
- Replace both headlamps.		Napagold Oil Filte	er	1.00
- Disassemble tailgate to service latches to open	properly.	Napa Quart 5w20		8.00
- Service tool box.adjust latches.		Napagold Fuel Fil	ter	1.00
- Rotate and balance four tires.		Washer Fluid Con-	centr	1.00
- Shop Supplies		Wiper Blade Anco		2.00
		Halogen Sealed B	eams	2.00
		Shop Supplies		1.00
Hours: 7.25	Comm: 0.00	Labor: 529.25	Parts: 220.63	Total: 749.88

Work Order: 2005456 Meter: 41099 In Date: 06/01/2020 Closed: 06/09/2020

Problem: Has to jump start all the time. Right rear tire flat.

Work Completed	Parts Issued	Quantity
- Jumpstart vehicle at system 3test starting and charging system.battery	Battery	1.00
failed loadtest.replace battery.	Shop Supplies	1.00

- Repair and balance right rear tire.

- Shop Supplies

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 147.81 Total: 293.81

Work Order: 2007974 Meter: 41224 In Date: 08/11/2020 Closed: 08/25/2020

Problem: PM Service.AC blows warm air.

Work Completed		Parts Issued		Quantity					
 - Pm Service. - Evacuate and recharge Ac Test system for leaks and functionality. - Rotate and balance 4 tires and repaired right front tire. - Service tool box and adjust latches. 		Used Fire X Refurbished		1.00					
		Napa Quart 5w20 Napagold Oil Filter Wiper Blade Anco		8.00 1.00 2.00					
					- Clean engine compartment.		Freon Sr Shop		2.00
					- Shop Supplies		Shop Supplies		1.00
Hours: 9.50	Comm: 0.00	Labor: 693.50	Parts: 76.41	Total: 769.91					

Work Order: 2101535 Problem: PM Service	Meter:	41487		In Date:	02/10/2021	Closed:	02/12/2021
Work Completed			Parts Issued		Quantity		
- Preventive Maint. Service			Napagold Oil Filter				1.00
- Repair right rear taillight.			Napa Quart 5w20				8.00
- Replace how's my driving decal.			Napagold Air Filter				1.00
- Rotate and balance tires.			Napagold Fuel Filte	r			1.00
- Shop Supplies			Washer Fluid Conce	entr			1.00
			Wiper Blade Anco				2.00
			Shop Supplies				1.00
Hours: 5.00		Comm: 0.00	Labor: 365.00	Parts: 68.	10	Total:	433.10
Work Order: 2108200 Problem: PM Service.	Meter:	41795		In Date:	07/29/2021	Closed:	08/06/2021
Work Completed			Parts Issued			Qı	uantity
- Preventive Maint. Service			Wiper Blade Anco				2.00
- Rotate/balanced 4 Tires			Washer Fluid Conce	entr			1.00
- Performed Road Test			Drain Plug				1.00
- Shop Supplies			Napagold Oil Filter			1.00	
			Napa Quart 5w20		8.00		
			Used Fire X Refurbished			1.00	
			Shop Supplies				1.00
Hours: 4.25		Comm: 0.00	Labor: 310.25	Parts: 52.	22	Total:	362.47
Work Order: 2111925 Problem: Transition Prep Charge	Meter:	42355		In Date:	11/04/2021	Closed:	11/04/2021
Work Completed							
- Transition Prep Charge							
Hours: 2.00		Comm: 0.00	Labor: 146.00	Parts: 0.0	0	Total:	146.00

Palm Beach County Fleet Management Asset Maintenance History 10174391 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Work Order: 2200580 Meter: 42355 In Date: 01/19/2022 Closed: 01/19/2022

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 90.40 Labor: 0.00 Parts: 0.00 Total: 90.40

Work Order: 2201419 Meter: 42355 In Date: 02/08/2022 Closed: 02/08/2022

Problem: transport

Work Completed

- Tow From: Vista To: pa shop

Hours: 0.00 Comm: 84.75 Labor: 0.00 Parts: 0.00 Total: 84.75

Work Order: 2201551 Meter: 42355 In Date: 02/10/2022 Closed: 02/23/2022

Problem: Pm service, noise coming from cab

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napagold Oil Filter		1.00
- front shocks bad replaced both front shocks an	nd bump stops	Napa Quart 5w20	8.00	
- test drive	Washer Fluid Cond	1.00		
- rotate balance	Wiper Blade Anco	2.00		
- rear bump stops missing		Used Fire X Refurbished Body Mount Kit Reflex Truck Shock Body Mount Kit 5w20 Oil Bulk Real Suspension Bumpstops		1.00
				2.00
				2.00
				2.00
				8.00
				2.00
		bumper		2.00
Hours: 6.75	Comm: 0.00	Labor: 492.75	Parts: 583.46	Total: 1,076.21

Work Order: 2209484 Meter: 43117 In Date: 09/06/2022 Closed: 09/12/2022

Problem: transport

Work Completed

- Tow From: pa shop To: Vista

Hours: 0.00 Comm: 310.75 Labor: 0.00 Parts: 0.00 Total: 310.75

Palm Beach County Fleet Management Asset Maintenance History 10174391 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Work Order: 2209606 Meter: 43117 In Date: 09/14/2022 Closed: 09/14/2022

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Work Order: 2209704 Meter: 43117 In Date: 09/19/2022 Closed: 09/19/2022

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 171.25 Total Labor: 10,958.25 Total Comm: 485.90 Total Parts: 8,194.67