Total Hours: 138	3.10 Labor: 9,371	.00	Parts: 6,638.38	Comm: 2,704.80		Charged	: 18714.18	
Work Order: 15 Problem: 10	511290 061 - Pre Delivery In	Meter: spection	303		In Date:	11/03/2015	Closed:	11/03/2015
Work Comple	eted							
- Pre Delivery	Inspection							
	Hours: 2.00		Comm: 0.00	Labor: 120.00	Parts: 0.0	0	Total:	120.00
Nork Order: 15 Problem: tai	-	Meter:	303		In Date:	11/06/2015	Closed:	11/18/2015
Work Comple	eted			Parts Issued			Qı	uantity
- Replace tail	light lens, strobes ar	nd bulb s	ockets	Bulb				2.00
- Shop Suppli	ies			Lamp				1.00
				Rear Tail Lamp Asse	mbly			1.00
				Vtx609c Led Strobe	Cl			2.00
				Wire Assy				2.00
				Sockey Assy				2.00
				Shop Supplies				1.00
	Hours: 2.00		Comm: 0.00	Labor: 120.00	Parts: 287	7.01	Total:	407.01
Nork Order: 16 Problem: P.		Meter:	2733		In Date:	05/24/2016	Closed:	05/31/2016
Work Comple	eted			Parts Issued			Qı	uantity
- P.m. Service	·.			5w20 Engine Oil				7.00
- Rotate and I	balance tiores.			Napagold Oil Filter				1.00
- Shop Suppli	ies			Washer Fluid Conce	ntr			1.00
				22" Wiper Blade				2.00
				Shop Supplies				1.00
	Hours: 3.75		Comm: 0.00	Labor: 225.00	Parts: 28.	48	Total:	253.48

### Palm Beach County Elect Management Asset Maintenance History

### Palm Beach County Fleet Management Asset Maintenance History 10198377 2015 FORD F250 Pickup, 3/4 Ton, 4X4

#### Work Order: 1612369 Meter: 6052 12/01/2016 Closed: 12/14/2016 In Date: Problem: P.M. service and tool box loose. Parts Issued Quantity **Work Completed** 5w20 Engine Oil 7.00 - P.m. Service. Napagold Oil Filter 1.00 - Fabricate and repair toolbox prop. Washer Fluid Concentr 1.00 - Rotate and balance tires. Used Fire X Refurbished 1.00 - Shop Supplies 22" Wiper Blade 2.00 Shop Supplies 1.00 Hours: 4.25 Comm: 0.00 Labor: 255.00 Parts: 44.99 Total: 299.99 Work Order: 1706146 Meter: 10957 In Date: 06/21/2017 **Closed:** 07/06/2017 Problem: P.M. Service.Windshield moulding coming loose. **Work Completed** Quantity Parts Issued Battery 65 1.00 - P.m. Service. Moulding 1.00 - Check loose windshield moulding.refer to glass shop. 5w20 Engine Oil 7.00 - Replace damage tool box lid props. Napagold Oil Filter 1.00 - Replace anfd balance four new tires. Napagold Air Filter 1.00 - Replace broken pintle pin. 22" Wiper Blade 2.00 - Engine cranks slow.recharge battery and load test.failed load test.replace defective battery. Floor Mat-2pc Rub Bk 1.00 - Complete wheel alignment.test drive. Stg Wheel Cov - Ford 1.00 - Shop Supplies Pintle Pin W/clip 1.00 Support 2.00 Tire 4.00 Shop Supplies 1.00 4.00 **Tire Disposal Fee** Comm: 0.00 Labor: 555.00 Parts: 1,474.78 Total: 2,029.78 Hours: 9.25

Nork Order: Problem:		Meter: 10937 eild & replace molding supplied by F	Fleet	In Date:	06/28/2017	Closed:	07/11/201
Work Con	npleted		Parts Issued			Qı	uantity
- Set up re	epairs and have inspection		Shop Supplies				1.00
- Shop Su	pplies						
·	Hours: 1.00	Comm: 74.40	Labor: 60.00	Parts: 2.0	00	Total:	136.40
Nork Order: Problem:	1711468 P.M. service.	<b>Meter:</b> 17141		In Date:	11/20/2017	Closed:	12/04/201
Work Con	npleted		Parts Issued			Qı	uantity
- P.m. serv	vice.		5w20 Engine Oil				7.00
- Replace faulty left rear turn signal lamp bulb with new.replace broken			Napagold Oil Filter				1.00
pintle pin v		Washer Fluid Conce	entr			1.00	
- Rotate a	nd balance four tires.	22" Wiper Blade				2.00	
	and adjust rear bumper to original	ginal position due to inpacrt	Used Fire X Refurbis	shed			1.00
0	downward.		Pintle Pin W/clip				1.00
- Shop Su	pplies		Bulb				1.00
			Shop Supplies				1.00
	Hours: 5.35	Comm: 0.00	Labor: 321.00	Parts: 46	.31	Total:	367.31
Vork Order:		Meter: 24373		In Date:	04/18/2018	Closed:	04/25/201
Problem:	P.M. service and slow crank.						
Work Con	npleted		Parts Issued			Qı	uantity
- P.m. serv	vice.		Battery 65				1.00
- Test and	l replace fauly trailer plug sock	et and rewire as needed.	5w20 Engine Oil				7.00
		rake pads and service calipers .	Napagold Oil Filter				1.00
Flush and	bleed brake system .test drive.		Napagold Air Filter 22" Wiper Blade			1.00	
	, , , , , , , , , , , , , , , , , , , ,	rge battery fullybattery failed with				2.00	
	&r defective battery .		trailer plug				1.00
	nd balance all four tires . Nitro	gen filled all tires.	Brake Pad				1.00
- Shop Su	pplies		Shop Supplies				1.00
	Hours: 9.75	Comm: 0.00	Labor: 585.00	Parts: 30		<b></b>	890.90

#### Work Order: 1808085 Meter: 30425 In Date: 08/07/2018 **Closed:** 08/16/2018 Problem: P.M. service and cracked windshield. **Work Completed** Parts Issued Quantity Napagold Oil Filter 1.00 - P.m. service. 5w20 Engine Oil 7.00 - Inspect and replace all four tires .balance and nitrofill all four tires. 22" Wiper Blade 2.00 - Replace both support shocks on tool box . Washer Fluid Concentr 1.00 - Perform complete front end alignment. Road test. Used Fire X Refurbished 1.00 - Shop Supplies Tire 4.00 Support 2.00 Shop Supplies 1.00 Tire Disposal Fee 4.00 Hours: 7.75 Comm: 0.00 Labor: 465.00 Parts: 1,036.23 Total: 1,501.23 Work Order: 1808444 Meter: 30298 08/16/2018 **Closed:** 08/21/2018 In Date: Problem: repair chipped windsheild Quantity Parts Issued Work Completed Shop Supplies 1.00 - set up repairs & inspect - Shop Supplies Hours: 1.00 Comm: 60.00 Labor: 60.00 Parts: 2.00 Total: 122.00 Work Order: 1811876 Meter: 35753 In Date: 11/20/2018 Closed: 11/30/2018 Problem: Wiper blades broken. **Work Completed** Parts Issued Quantity 22" Wiper Blade 2.00 - Replace broken wiper blades Hours: 0.25 Comm: 0.00 Labor: 16.75 Parts: 6.96 Total: 23.71

# Palm Beach CountyFleet Management Asset Maintenance History101983772015 FORD F250 Pickup, 3/4 Ton, 4X4

Nork Order: 18 Problem: P.		Meter:	36922		In Date:	12/21/2018	Closed:	01/07/2019
Work Comple	eted			Parts Issued			Qı	uantity
- P.m. service				Napagold Oil Filter				1.00
- Perform tun	e up . Replace all sixteen wo	rn spark plugs	and eight wires .	Napa Quart 5w20				8.00
- Resurface b	oth rear rotors . Replace bra	ke pads and ser	vice calipers . Flush	22" Wiper Blade				2.00
and bleed bra	ke system . Road test.			Washer Fluid Concer	ntr			1.00
- Perform fue	l injector flush and service a	r intake decarb		Espak Plug Wire				4.00
- Rotate and	balance all four tires. Nitrofil	l all.		Espak Plug Wire				4.00
- Shop Suppl	ies			Spark Plug				16.00
				Real Brake Pad				1.00
				Injector Cleaner				1.00
				Intake Cleaner Kit				1.00
				Brake Pedal Pad				1.00
				Shop Supplies				1.00
	Hours: 13.75		Comm: 0.00	Labor: 921.25	Parts: 448	5.25	Total:	1,366.50
<b>ork Order:</b> 19 <b>Problem:</b> P.		Meter:	41803		In Date:	05/22/2019	Closed:	05/30/201
Work Comple	eted			Parts Issued			Q	uantity
- Pm Service				Napa Quart 5w20				8.00
- Check and r	eplace bad battery.			Napagold Oil Filter				1.00
- Shop Suppli	ies			Washer Fluid Concer	ntr			1.00
				22" Wiper Blade				2.00
				Battery				1.00
				Shop Supplies				1.00
	Hours: 3.50		Comm: 0.00	Labor: 234.50	Parts: 172	2.55	Total:	407.05

10/24/2022 4:52:06 PM

Work Order: 1908924	Meter:	41809		In Date:	08/26/2019	Closed:	08/30/2019
Problem: Battery is dead in	WUD parking lot.						
Work Completed			Parts Issued			Qı	antity
- Had to jump start vehicle in batteryokvehicle was parked		e and retest	Shop Supplies				1.00
- Shop Supplies							
Hours: 1.0	00	Comm: 0.00	Labor: 67.00	Parts: 3.0	0	Total:	70.00
Work Order: 1911783 Problem: PM Service.Turnsi	Meter: ignal inop	44767		In Date:	11/13/2019	Closed:	11/25/2019
Work Completed			Parts Issued			Qı	uantity
- Pm Service.			Washer Fluid Conc	entr			1.00
- Replace both brake lamp bu	lbs.		22" Wiper Blade				2.00
- Reset rear strobe light patter	rn to flash correctly		Napagold Oil Filter	r			1.00
- Rotate and balance 4 tires.	-		Napa Quart 5w20				8.00
- Clear radiator debris to cool	properly.		Used Fire X Refurb	ished			1.00
- Service tool box,adjust latche	es to close properly.		Napagold Air Filte	er			1.00
- Clean engine compartment.			Boxed Miniatures				2.00
- Shop Supplies			Shop Supplies				1.00
Hours: 7.	75	Comm: 0.00	Labor: 565.75	Parts: 80.	10	Total:	645.85
Work Order: 2000846 Problem: Right front tire flat.	Meter:	47500		In Date:	01/27/2020	Closed:	01/31/2020
Work Completed			Parts Issued			Qı	antity
- Repair and balance right from	nt tire.nitrogen fill all tires.		Shop Supplies				1.00
- Shop Supplies							
Hours: 1.0	00	Comm: 0.00	Labor: 73.00	Parts: 4.0	0	Total:	77.00

Vork Order: 2 Problem: 1	2002436 PM Service.Light bar inop.	<b>Meter:</b> 49696		In Date:	03/10/2020 (	Closed:	03/17/2020
Work Comp	leted		Parts Issued			Qı	uantity
- Pm Service	2.		Napa Quart 5w20				8.00
- Replace ba	attery,clean and service tray.		Napagold Oil Filte	r			1.00
- Replace fro	ont brake pads.service rotors,ca	ipers and slide mounts.bleed	22" Wiper Blade				2.00
system.			Washer Fluid Cond	centr			1.00
·	eering wheel cover.brake pedal	pad and how is my driving	Battery				1.00
sticker.			Non-chlor Brake C	Inr			1.00
	ght bar control unit.		Front Brake Pad				1.00
- Rotate and	d balance four tires.		Brake Pedal Pad				1.00
- Wash vehicle engine compartment. - Shop Supplies			Ford Triton Pvc Sw		1.00		
			Lighted Switchbox	(			1.00
			Shop Supplies				1.00
	Hours: 12.00	Comm: 0.00	Labor: 876.00	Parts: 51	5.20	Total:	1,391.20
/ork Order: 2 Problem: /	2004343 AC blows hot air.	<b>Meter:</b> 51679		In Date:	04/30/2020 (	Closed:	05/26/2020
Work Comp	leted		Parts Issued			Oı	uantity
			i alto issued			4.	
- Diagnose t	for Ac blowing hot air.ac perfori	nance and leak	E8 A/c Oil Univ W	Dye		4.	1.00
5	for Ac blowing hot air.ac perform reseal and recharge system to s			Dye			•
5	reseal and recharge system to s		E8 A/c Oil Univ W				1.00
test.recover,	reseal and recharge system to s		E8 A/c Oil Univ W Freon Sr Shop				1.00 2.00
test.recover,	reseal and recharge system to s		E8 A/c Oil Univ W Freon Sr Shop Red Angel Ac Stop		23		1.00 2.00 1.00
test.recover, - Shop Supp	reseal and recharge system to solies Hours: 2.50	becs.retest Ac system.	E8 A/c Oil Univ W Freon Sr Shop Red Angel Ac Stop Shop Supplies	) Leak	23 07/01/2020 <b>(</b>	Total:	1.00 2.00 1.00 1.00 255.73
test.recover, - Shop Supp	Hours: 2.50 2006551 prder 2 spare keys	becs.retest Ac system. Comm: 0.00	E8 A/c Oil Univ W Freon Sr Shop Red Angel Ac Stop Shop Supplies	D Leak Parts: 73.		Total: Closed:	1.00 2.00 1.00 1.00 255.73
test.recover, - Shop Supp /ork Order: 2 Problem: 0 Work Comp	Hours: 2.50 2006551 prder 2 spare keys	becs.retest Ac system. Comm: 0.00	E8 A/c Oil Univ W Freon Sr Shop Red Angel Ac Stop Shop Supplies Labor: 182.50	D Leak Parts: 73. In Date:		Total: Closed:	1.00 2.00 1.00 255.73 07/07/2020
test.recover, - Shop Supp Vork Order: 2 Problem: 0 Work Comp	Hours: 2.50 Hours: 2.50 2006551 order 2 spare keys eleted and program	becs.retest Ac system. Comm: 0.00	E8 A/c Oil Univ W Freon Sr Shop Red Angel Ac Stop Shop Supplies Labor: 182.50	D Leak Parts: 73. In Date:		Total: Closed:	1.00 2.00 1.00 255.73 07/07/2020

# Palm Beach CountyFleet Management Asset Maintenance History101983772015 FORD F250 Pickup, 3/4 Ton, 4X4

Nork Order: 2007426 Problem: PM Service.	Meter:	55149		In Date:	07/29/2020	Closed:	08/17/202
Work Completed			Parts Issued			Qı	uantity
- Pm Service.			Napagold Oil Filter	r			1.00
- Rotate and balance 4 tires.			Napa Quart 5w20				7.00
- Service tool box and adjust latches.			Washer Fluid Conc	entr			1.00
- Wash engine compartment.			22" Wiper Blade				2.00
- Shop Supplies			Shop Supplies				1.00
Hours: 5.00		Comm: 0.00	Labor: 365.00	Parts: 46.	75	Total:	411.75
Problem: P.M.SERVICE, CHECK TIRES Work Completed			Parts Issued			Qı	uantity
Work Completed						Qı	•
- Preventive Maint. Service			Used Fire X Refurb				1.00
- mount and balance 4 new tires reset tpms			Napagold Oil Filter	<u></u>			1.00
- service tool box adjust latches to close prop	erly		Napa Quart 5w20				7.00
- clean engine compartment			Napagold Air Filte	r			1.00
- replaced How's My Driving sticker and cal-s	tart decal		Washer Fluid Conc	entr			1.00
- Shop Supplies			22" Wiper Blade				2.00
			Tire				4.00
			Shop Supplies				1.00
			T' D' IF				1.00
			Tire Disposal Fee				4.00

# Palm Beach CountyFleet Management Asset Maintenance History101983772015 FORD F250 Pickup, 3/4 Ton, 4X4

Work Order: Problem:	2104285 PM Service	Meter:	64842		In Date:	04/15/2021	Closed:	04/23/202
Work Com	pleted			Parts Issued			Qı	uantity
- Preventiv	ve Maint. Service			22" Wiper Blade				2.00
- Replace l	how's my driving decal.			Washer Fluid Concer	ntr			1.00
- Shop Sup	pplies			Napagold Oil Filter				1.00
				Napa Quart 5w20				7.00
				Shop Supplies				1.00
	Hours: 3.00		Comm: 0.00	Labor: 219.00	Parts: 48.	01	Total:	267.01
Work Order: Problem:	2105744 Damage to left front door,left side o	Meter: of can, left		tep	In Date:	05/03/2021	Closed:	05/25/202
Work Com	•							
	to left front door,left side of can, lef	t side of be	•					
- Damage	to left front door,left side of can, lef Hours: 0.00		Comm: 2,570.40	Labor: 0.00	Parts: 0.0			2,570.40
- Damage Work Order:	to left front door,left side of can, lef Hours: 0.00	Meter:	Comm: 2,570.40 69987	Labor: 0.00	Parts: 0.0	0 09/09/2021		2,570.40 09/17/202
- Damage Work Order:	to left front door,left side of can, lef Hours: 0.00 2109761 PM Service.Check for squeaks and	Meter:	Comm: 2,570.40 69987	Labor: 0.00 Parts Issued			Closed:	-
- Damage Work Order: Problem: Work Com	to left front door,left side of can, lef Hours: 0.00 2109761 PM Service.Check for squeaks and	Meter:	Comm: 2,570.40 69987		In Date:		Closed:	09/17/202
- Damage Work Order: Problem: Work Com - Preventiv	to left front door,left side of can, lef Hours: 0.00 2109761 PM Service.Check for squeaks and	Meter:	Comm: 2,570.40 69987	Parts Issued	In Date:		Closed:	09/17/202
- Damage Work Order: Problem: Work Com - Preventiv - r&r rear	to left front door,left side of can, lef Hours: 0.00 2109761 PM Service.Check for squeaks and <b>ppleted</b> ve Maint. Service	Meter:	Comm: 2,570.40 69987	<b>Parts Issued</b> Washer Fluid Concer	In Date:		Closed:	09/17/202 Jantity 1.00
- Damage Work Order: Problem: Work Com - Preventiv - r&r rear	to left front door,left side of can, left Hours: 0.00 2109761 PM Service.Check for squeaks and pleted ve Maint. Service drive shaft to press fit both u-joints alanced 4 tires	Meter:	Comm: 2,570.40 69987	<b>Parts Issued</b> Washer Fluid Concer 22" Wiper Blade	In Date:		Closed:	09/17/202 Jantity 1.00 2.00
- Damage Work Order: Problem: Work Com - Preventiv - r&r rear - rotate/ba	to left front door,left side of can, left Hours: 0.00 2109761 PM Service.Check for squeaks and pleted ve Maint. Service drive shaft to press fit both u-joints alanced 4 tires	Meter:	Comm: 2,570.40 69987	<b>Parts Issued</b> Washer Fluid Concer 22" Wiper Blade Napa Quart 5w20	In Date:		Closed:	09/17/202 Jantity 1.00 2.00 7.00
- Damage Work Order: Problem: Work Com - Preventiv - r&r rear - rotate/ba	to left front door,left side of can, left Hours: 0.00 2109761 PM Service.Check for squeaks and pleted ve Maint. Service drive shaft to press fit both u-joints alanced 4 tires	Meter:	Comm: 2,570.40 69987	<b>Parts Issued</b> Washer Fluid Concer 22" Wiper Blade Napa Quart 5w20 Napagold Oil Filter	In Date:		Closed:	09/17/202 Jantity 1.00 2.00 7.00 1.00
- Damage Work Order: Problem: Work Com - Preventiv - r&r rear - rotate/ba	to left front door,left side of can, left Hours: 0.00 2109761 PM Service.Check for squeaks and pleted ve Maint. Service drive shaft to press fit both u-joints alanced 4 tires	Meter:	Comm: 2,570.40 69987	Parts Issued Washer Fluid Concer 22" Wiper Blade Napa Quart 5w20 Napagold Oil Filter Napagold Air Filter	In Date:		Closed:	09/17/202 <b>Jantity</b> 1.00 2.00 7.00 1.00 1.00

Work Order: Problem:	2110657 Passenger rear tire flat.	Meter:	70481		In Date:	09/30/2021	Closed:	10/01/2021
Work Com				Parts Issued			Qı	uantity
- Repair ar	nd balance right rear tire.nitro	gen fill all.reset T	pms.	Shop Supplies				1.00
- Shop Sup								
	Hours: 1.00		Comm: 0.00	Labor: 73.00	Parts: 2.6	5	Total:	75.65
Work Order: Problem:	2200232 PM Service.	Meter:	75200		In Date:	01/07/2022	Closed:	01/27/2022
Work Com	npleted			Parts Issued			Qı	uantity
- Preventiv	ve Maint. Service			Washer Fluid Conce	ntr			1.00
- jump sta	rt, Fully recharge battery and I	oad test. Battery	failed load test and	22" Wiper Blade				2.00
replaced fa	ailed battery	-		Napa Quart 5w20				7.00
- rotate/ba	alanced 4 tires. Nitrogen fill. Re	eset Tpms.		Used Fire X Refurbis	shed			1.00
	Ignition coil arcing. Replaced	failed ignition co	il , 16 spark plugs	Battery				1.00
and 8 wires				Spark Plug				16.00
- flush/clea	an fuel injection and intake sy	stem		Coil				1.00
- Shop Sup	pplies			Espak Plug Wire				4.00
				Espak Plug Wire				4.00
				Intake Cleaner Kit				1.00
				Shop Supplies				1.00
	Hours: 10.75		Comm: 0.00	Labor: 784.75	Parts: 458	3.03	Total:	1,242.78

Work Order: 2204271 Problem: PM Service		er: 80166		In Date:	04/22/2022	Closed:	04/29/2022
Work Completed			Parts Issued			Qı	uantity
- Preventive Maint. Se	rvice		Napagold Oil Filte	er			1.00
- replaced turn signal/	brake lamp bulbs	s on both sides	Napa Quart 5w20				7.00
- r&r air intake asseml	oly to replace arci	ng #6 coil	Napagold Air Filte	er			1.00
	· ·	rvice rotors calipers and slides	Washer Fluid Cond	centr			1.00
- replaced worn brake	pedal pad	·	22" Wiper Blade				2.00
- replaced worn how's		er	Boxed Miniatures				2.00
- rotate balanced 4 tire	, ,		Coil				1.00
- Shop Supplies			Brake Pad				1.00
			Brake Pads				1.00
			Brake Pedal Pad				1.00
			Shop Supplies				1.00
н	ours: 13.50	Comm: 0.00	Labor: 985.50	Parts: 303	3.90	Total:	1,289.40
Work Order: 2207999 Problem: Transition		er: 83558		In Date:	08/02/2022	Closed:	08/02/2022
Work Completed							
- Transition Prep Char	ge						
н	ours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 0.0	0	Total:	146.00
Total Hours: 138.10	Total Labor	: 9,371.00	Total Comm: 2,7	04.80	Total Parts	: 6,638.38	