



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V9884

In Date: 08/13/2007
Close Date: 08/13/2007

Meter Reading: 3,660.00

Problem?

B INSPECTION Q-47

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V9717

In Date: 08/03/2007
Close Date: 08/21/2007

Meter Reading: 3,660.00

Problem?

B inspection and related repairs-set up new unit (new Q47)

Task performed:

Parts

Quantity

1. B-Inspection, Levy	0714021GASKET 2 1/2"	4
2. B-Inspection, George	071704214035 GASKET 1 1/2	3
3. Assist u-bolt torque	14-7014HGR-1 HELMET HOOK	4
4. Reroute fuel line arnd 120V conduit	1654-8FERRULE .718	2
5. Replc wiper blades	180R002HURST HYD. FLUID QT	4
6. Adj cab latch switch	31-24WIPER BLADES	2
7. sealed L-1 compt (leaking)	5269LPVM-5 SM MOUNT	12
8. Equipped new truck	680-10LAMERICAN FLAG W UV CLEAR LEFT	1
9. Toque u-bolts	680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
10. Chkd Q. siron - works only when brake released	LPVM-7LG MOUNT	9
11. Filled washer reservoir	M-284-01SWITCH BATTERY MASTER	1
12. Put spotlight in cab	PS683033442 FUEL FILTER	1
13. Monitor L/R on boom control backwards; rewired ckt in box on boom	REDG6S14023 GASKET 6 IN	1
14. Called Allison for trans coldes was told to clear & monitor	17211-2L8-02330-347 HURST UNITS 06 HONDA	1
15. Adj pump packing	33063FUEL FILTER ONAN	1
16. Water proofed term under cab	BM7A6521 SPARKPLUG	1
17. Rerouted btry cable to clear rub points; clnd & tighten all term	601601 MALE HOSE END	2
18. Adj exh heat shield & rerouted air lines	P1147GFUEL FILTER 33120 WIX DELCO TP916	1
19. Adj air pack brkts & mnt air tanks	S775COUPLER	2
20. install all decals & signage	S777COUPLING NIPPLE	2
21. Paint scratches on boom	UMVS-0811-11STRAP ZICO	11
22. mnt all accessories & tools	UMVS111611STRAP	1
23. Mnt accessories	UMVS162511STRAP	3
24. Assist ladder service		



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V9759

In Date: 08/07/2007 Meter Reading: 3,660.00
Close Date: 08/28/2007

Problem?

tint windows Q47 (outside agency-60 minute window tint)

Task performed:

Tint windows Q47 - 60-minute window tint

Parts

NO PARTS USED

Quantity

Vendor?: 60-MINUTE

Workorder: V10134

In Date: 08/27/2007 Meter Reading: 130.00
Close Date: 09/18/2007

Problem?

a/c blowing hot Q47

Task performed:

1. Recharged sys; chkd for leaks
2. installed "keep back 500 feet" in rear of truck
3. Adj all shelving in compt
4. Mounted hose brake in compt

Parts

NO PARTS USED

Quantity

Workorder: V10135

In Date: 08/27/2007 Meter Reading: 130.00
Close Date: 09/18/2007

Problem?

mirrors Q47

Task performed:

1. Installed (2) convey mirrors
2. Adj all air pack brackets

Parts

980-412173 MIRROR 8 IN

2

Quantity

Workorder: V10331

In Date: 09/09/2007 Meter Reading: 169.00
Close Date: 09/20/2007

Problem?

discharge handle for #3 on the pump panel is very hard to pull out. a couple more nozzles needs to be secured. thank you - Patric Lobsinger q47

Task performed:

CIn/lube linkage; need to chk linkage at svc

Parts

NO PARTS USED

Quantity



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V10462

In Date: 09/17/2007

Meter Reading: 188.00

Close Date: 09/20/2007

Problem?

ladder locks on Q47 did not disengage when changing between reacqu and water mode, when ladder was raised the locks bent and broke. mechanic came out and and put the ladder back in rescue mode only. still needs repair.

Task performed:

Parts

Quantity

Inspected ladder-damage

NO PARTS USED

Workorder: V10212

In Date: 09/02/2007

Meter Reading: 130.00

Close Date: 09/25/2007

Problem?

Driver's side Q2B floor button not working. When tested, speaker 2 light does not come on on the siren panel, E47

Task performed:

Parts

Quantity

1. Found no problem with Siren.

NO PARTS USED

Workorder: V10388

In Date: 09/11/2007

Meter Reading: 174.00

Close Date: 09/25/2007

Problem?

doors stick especially lt. door. mobile radio has a lot of static and does not transmit.

Task performed:

Parts

Quantity

1. Lubed and Adjusted doors.

NO PARTS USED

Workorder: V10396

In Date: 09/12/2007

Meter Reading: 3,987.00

Close Date: 09/25/2007

Problem?

mount 2 nozzle holders, move 1 shelf up approx. 1 inch (Q47)

Task performed:

Parts

Quantity

1. Adjust compartment shelves.

2. Mounted 2 nozzles.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V10433

In Date: 09/13/2007

Meter Reading: 185.00

Close Date: 09/27/2007

Problem?

need 4 helmet hooks 2 short velcro straps 2 long velcro strap move siren and air horn foot control on Lt side forward (stomping on i all day)Q47

Task performed:

Parts

Quantity

1. Ladder locks; damaged due to operator; order parts
2. Rem hor/siren from floor & install; wired on dash
3. Installed velcro strap for high rise pack
4. installed hooks in cab & hooks in compartment

NO PARTS USED

Workorder: V10502

In Date: 09/18/2007

Meter Reading: 201.00

Close Date: 09/27/2007

Problem?

THE AIR CONDITIONING DOES NOT WORK ON QUINT 47

Task performed:

Parts

Quantity

Factory contacted

SAHSVS2510STRAP

5

UMVS111611STRAP

2

UMVS162511STRAP

2

UMVS254411STRAP 46 IN

6

Workorder: V10533

In Date: 09/18/2007

Meter Reading: 194.00

Close Date: 09/27/2007

Problem?

Could you install a window wipers control that has mist speed up to full speed? Also, can we have the headlights turn on automatically with start up? Thank you - you all are great. Q-47

Task performed:

Parts

Quantity

Not dooing at all

NO PARTS USED

Workorder: V10652

In Date: 09/25/2007

Meter Reading: 4,303.00

Close Date: 10/01/2007

Problem?

AIR LEAK Q-47

Task performed:

Parts

Quantity

1. TRACED OUT AIR LEAK FOUND AT REAR TANK AND REPAIRED

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V10683

In Date: 09/26/2007

Meter Reading: 210.00

Close Date: 10/01/2007

Problem?

waterway nozzle will not switch between straight stream and fog at joy stick Q47

Task performed:

Parts

Quantity

1. TRACED OUT PROBLEM WITH NOZZLE, FOUND UNIT IN MANUAL.

NO PARTS USED

Workorder: V10707

In Date: 09/27/2007

Meter Reading: 210.00

Close Date: 10/01/2007

Problem?

HURST SPREADER IS LEAKING HYDRALIC FLUID FROM THE SUPPLY HOSE CONNECTION AT HANDLE Q47

Task performed:

Parts

Quantity

1. DROPPED OFF SPARE HURST

NO PARTS USED

Workorder: V10682

In Date: 09/26/2007

Meter Reading: 210.00

Close Date: 10/02/2007

Problem?

primer doesn't work Q47

Task performed:

Parts

Quantity

1. TRACED OUT PROBLEM, FOUND RELAY BAD, FERRARA ORDER PARTS

NO PARTS USED

Workorder: V10684

In Date: 09/26/2007

Meter Reading: 210.00

Close Date: 10/02/2007

Problem?

pump overheat light always on Q47

Task performed:

Parts

Quantity

1. TRACED OUT PROBLEM WITH OVER HEAT LIGHT, FOUND SENDER BAD, FERRARA ORDER PART

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V10685

In Date: 09/26/2007

Meter Reading: 210.00

Close Date: 10/02/2007

Problem?

cab won't tilt Q47

Task performed:

Parts

Quantity

1. CHECKED PROBLEM WITH CAB TILT, TRACED OUT PRBLEM TO CAB LOCKS

NO PARTS USED

Workorder: V10801

In Date: 10/03/2007

Meter Reading: 4,601.00

Close Date: 10/22/2007

Problem?

replace ladder lock Q47

Task performed:

Parts

Quantity

- 1. installed new ladder locks on ladder.
- 2. primer motor inoperable. replaced primer motor solenoid.
- 3. l side tip quartz light inoperable. replaced bulb.

2000071102000072100 SOLENOID HALE PRIMER

1

740-1032LOCKING ARN LH SMEAL

1

740-1075LOCKING ARM RH SMEAL

1

FREIGHTSHIPPING CHARGES

1

Workorder: V10804

In Date: 10/03/2007

Meter Reading: 248.00

Close Date: 10/22/2007

Problem?

halogen light on left side of tip broken

Task performed:

Parts

Quantity

replaced right side bulb

Q500T3CLBULB HALOGEN 120V 500WATT 4 11/16 LONG

3



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V10910

In Date: 10/09/2007

Meter Reading: 4,601.00

Close Date: 10/22/2007

Problem?

repair foam leak and back up cam q47

Task performed:

Parts

Quantity

1.glove box holder/fabricated glove holder. painted and installed.

NO PARTS USED

2. flow meter inoperable. found wires ripped out in ladder compartment. reinstalled new wires and connectors.

3.rear back up camera, found bad connection.

4.foam leak repaired fitting that was leaking

Workorder: V10980

In Date: 10/10/2007

Meter Reading: 4,835.00

Close Date: 10/22/2007

Problem?

BROKEN DOOR ON 110V AUTO EJECT Q-47

Task performed:

Parts

Quantity

repaired broken door installed new screws

NO PARTS USED

Workorder: V11054

In Date: 10/16/2007

Meter Reading: 301.00

Close Date: 10/23/2007

Problem?

flow meter wiring is wrapping around centerpost (waterway) and being ripped out when the ladder is turned.

Task performed:

Parts

Quantity

1. rewired flow meter and rerouted wire

NO PARTS USED

Workorder: V10681

In Date: 09/26/2007

Meter Reading: 210.00

Close Date: 10/26/2007

Problem?

intercom at pump panel broken E47

Task performed:

Parts

Quantity

1. repaired bad connection for intercom.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V11205

In Date: 10/23/2007
Close Date: 10/26/2007

Meter Reading: 5,077.00

Problem?

assist Ferrara tech with cab lift problem Q47

Task performed:

Parts

Quantity

1. assist ferrera tech with cab lift cyl install
2. shop meeting all personel 07:30

NO PARTS USED

Workorder: V11257

In Date: 10/26/2007
Close Date: 11/06/2007

Meter Reading: 5,148.00

Problem?

ladder wont retract q47

Task performed:

Parts

Quantity

1. Chkd problem w/ladder not retracting; fnd to be driver's error
2. water leak; adj pump packing & ran pump

NO PARTS USED

Workorder: V11266

In Date: 10/26/2007
Close Date: 11/06/2007

Meter Reading: 316.00

Problem?

Federal Q button on lt's side does not work q47

Task performed:

Parts

Quantity

Traced problem w/siren; fnd bad connection

NO PARTS USED

Workorder: V11286

In Date: 10/28/2007
Close Date: 11/09/2007

Meter Reading: 316.00

Problem?

step light on base of ladder broken needs new outer case front a/c not working Q-47

Task performed:

Parts

Quantity

WARRANTY

50-24WIPER BLADE - KME

2

1. Wiper blades; replc
2. Chkd cab A/C - NPF



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V11380

In Date: 11/01/2007

Meter Reading: 344.00

Close Date: 11/14/2007

Problem?

The drivers side latch to the mapbook compartment is broke. Q-47

Task performed:

Parts

Quantity

1. Installed two new latches in map box.
2. Worked on reprograming node 4 for head light but had problem getting program.

LTC5993SSM1-63-8 LATCH STAINLESS

4

Workorder: V11412

In Date: 11/03/2007

Meter Reading: 344.00

Close Date: 11/14/2007

Problem?

nozzle will raise/lower and left/right from operator switches at tip and joystick at base. will not go fog/straight stream at either. Q47

Task performed:

Parts

Quantity

1. Found no problem with nozzle.

NO PARTS USED

Workorder: V11420

In Date: 11/04/2007

Meter Reading: 344.00

Close Date: 11/14/2007

Problem?

map light broken Q47

Task performed:

Parts

Quantity

1. Repaired broken map light.
2. Installed perceiving nozzle in rear.
3. Train crew on how to grease ladder.

NO PARTS USED

Workorder: V11425

In Date: 11/04/2007

Meter Reading: 344.00

Close Date: 11/14/2007

Problem?

Center horn button on the steering wheel intermittent when put into use. Selected the airhorn for the center button and when depressed, it would only give me a short burst some of the times. Other times it would not work Q47

Task performed:

Parts

Quantity

1. Repaired bad connection in horn button.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V11430

In Date: 11/05/2007 Meter Reading: 5,493.00
Close Date: 11/14/2007

Problem?

DOWN LOAD NODE FOR V-MUX Q-47

Task performed:

Parts

Quantity

1. Working on downloading Node 4 trying to get program from factory.

NO PARTS USED

Workorder: V11557

In Date: 11/10/2007 Meter Reading: 374.00
Close Date: 11/14/2007

Problem?

The hands free set for the siren and air horn work is working intermitently. The siren works from control panel with no problems. Q47

Task performed:

Parts

Quantity

1. Checked operation of horn and siren botton and found no problem.

37099SHOCK FRONT

2

Workorder: V11281

In Date: 10/27/2007 Meter Reading: 5,235.00
Close Date: 11/21/2007

Problem?

flow meter is not working Q47

Task performed:

Parts

Quantity

WARRANTY - contacted Ferrara 10/29/07
j

NO PARTS USED

Workorder: V11469

In Date: 11/06/2007 Meter Reading: 5,537.00
Close Date: 11/29/2007

Problem?

Mount piercing nozzle in high side compartment. q47

Task performed:

Parts

Quantity

1. Cover over right side jack hitting body of truck, readjusted brackets and tested
2. Truck leaking air/traced out air leaks found main air tank leaking- repaired.
3. Refilled rear tires that were low on air
4. Cleaned and lubed ladder.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V11611

In Date: 11/14/2007

Meter Reading: 384.00

Close Date: 11/29/2007

Problem?

We have the scene lights, left and right go on automatically, but not the headlights. Q47

Task performed:

Parts

Quantity

1. Will get program at later time.
2. Door open alarm on, readjusted door switches.

NO PARTS USED

Workorder: V11676

In Date: 11/19/2007

Meter Reading: 389.00

Close Date: 11/29/2007

Problem?

We need the baffle in the front bumper compartment installed. Baffle is in the front compartment. q47

Task performed:

Parts

Quantity

1. Reinstalled baffle in front jump line compt.

NO PARTS USED

Workorder: V11677

In Date: 11/19/2007

Meter Reading: 389.00

Close Date: 11/29/2007

Problem?

Engine overheat light is on continually, even when cab sensor and governor smart panel lists engine temp is in normal range. q47

Task performed:

Parts

Quantity

1. Pump over heat light stays on, removed sencer and cleaned, reinstaled tested ok.

NO PARTS USED

Workorder: V11678

In Date: 11/19/2007

Meter Reading: 389.00

Close Date: 11/29/2007

Problem?

Hands free siren on steering wheel of Q47 is not working.

Task performed:

Parts

Quantity

1. Reajusted connection and tested.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V11711

In Date: 11/21/2007
Close Date: 11/29/2007

Meter Reading: 410.00

Problem?

When we went to set up at DCS the alarm on rear panel was on and had to use over ride to set up ladder. q47

Task performed:

Parts

Quantity

1. Traced out problem with ladder found no problem at this time...

NO PARTS USED

Workorder: V11742

In Date: 11/26/2007
Close Date: 11/29/2007

Meter Reading: 6,020.00

Problem?

on call q47 ladder wont work

Task performed:

Parts

Quantity

1. Ladder won't work/ wire ripper out @ swivel, repaired wiring.

NO PARTS USED

Workorder: V11730

In Date: 11/23/2007
Close Date: 11/30/2007

Meter Reading: 418.00

Problem?

Engine overheat warning light on pump panel is continuously on, hands free siren on steering wheel is not working Q47

Task performed:

Parts

Quantity

1. Removed over heat sender and cleaned replaced and tested.

NO PARTS USED

2. Repaired hand free siren button.

Workorder: V11737

In Date: 11/24/2007
Close Date: 12/06/2007

Meter Reading: 418.00

Problem?

missing screen out of middle intake. Q47

Task performed:

Parts

Quantity

1. Horn and siren botton lnop. repaired connection in steering colum.

5269LPVM-5 SM MOUNT

5

2. Adjusted air horns

3. Recharged cab A/C.



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V11097

In Date: 10/17/2007
Close Date: 12/17/2007

Meter Reading: 301.00

Problem?

AS SOON AS PTO IS ENGAGED WARNING BEEPER COMES ON. OUTRIGGER LIGHT DOES NOT COME ON AND OUTRIGGERS ONLY COME OUT WHEN IN OVERRIDE. QUINT KEPT BEEPING UNTIL TRUCK AND BATTERIES SHUT OFF. T NEXT TIME PTO ENGAGED IT HAP

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V11923

In Date: 12/04/2007
Close Date: 12/19/2007

Meter Reading: 455.00

Problem?

We have a burnt out light bulb in one of our Circle D portable lights. It is 500 W. q47

Task performed:

1. Checked problem with circle D-light found short in light, repaired and tested.

Parts	Quantity
NO PARTS USED	

Workorder: V11995

In Date: 12/10/2007
Close Date: 12/31/2007

Meter Reading: 471.00

Problem?

The light switch for the rear scene lights do not operate the rear scene lights. To turn on rear scene lights you must turn on turntable lights. q47

Task performed:

1. Officers side radio has no volume control, rewired radios from left to right.

Parts	Quantity
NO PARTS USED	

Workorder: V12083

In Date: 12/15/2007
Close Date: 12/31/2007

Meter Reading: 486.00

Problem?

BAY FLOORS CLEANED YESTERDAY AND THIS MORNING SMALL OIL SPOT FOUND UNDER QUINT UNSURE WERE IT IS COMING FROM Q-47

Task performed:

1. Checked for leak found foam leak. repaired.

Parts	Quantity
NO PARTS USED	



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V12386

In Date: 01/06/2008

Meter Reading: 535.00

Close Date: 01/08/2008

Problem?

The primer will not shut off with lever, have to use toggle off/on switch. Also, water in leaking from primer.

Task performed:

Flushed system and check ok.

j

Parts

NO PARTS USED

Quantity

Workorder: V12109

In Date: 12/17/2007

Meter Reading: 486.00

Close Date: 01/15/2008

Problem?

Have on going oil leak leaving small spot on bay floor.

Task performed:

Parts

NO PARTS USED

Quantity

Workorder: V12388

In Date: 01/07/2008

Meter Reading: 535.00

Close Date: 01/16/2008

Problem?

One of the GFI's has a broken wire inside cord. If the GFI is moved the electric flow is interrupted and GFI resets.Q47

Task performed:

1. Foam leak, found fitting O/Y tank leaking factory will repair.
2. Horn siren Inop, repaired broken wire.
3. Air pack brackets need to be adjusted....adjusted brackets.
4. Primer leaking, found no leaks..

Parts

NO PARTS USED

Quantity

Workorder: V12432

In Date: 01/08/2008

Meter Reading: 7,354.00

Close Date: 01/16/2008

Problem?

DISCHARGE VALVES HARD TO OPEN Q47

Task performed:

1. Cleaned discharge linkage and lubed.

Parts

NO PARTS USED

Quantity



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V12555

In Date: 01/14/2008
Close Date: 01/24/2008

Meter Reading: 7,526.00

Problem?

ON CALL Q47 DOOR OPEN LT ON

Task performed:

Parts

Quantity

1. Found bad connection on qurtc light repaired and tested.

NO PARTS USED

Workorder: V13269

In Date: 02/14/2008
Close Date: 02/15/2008

Meter Reading: 653.00

Problem?

SMOKE COMING FROM ROOF AC Q47

Task performed:

Parts

Quantity

1. Smoke from A/C, pin hole in condensor, check check for cause of smoke
2. water leak, primer valve, located leak, will bring in for repair

NO PARTS USED

Workorder: V13267

In Date: 02/14/2008
Close Date: 02/20/2008

Meter Reading: 653.00

Problem?

Q47 WATER LEAKING UNDER TRUCK

Task performed:

Parts

Quantity

1. Water leaking under truck, found pump packing leaking and adjusted packing
2. A/C unit inop, will send factory

NO PARTS USED

Workorder: V13340

In Date: 02/19/2008
Close Date: 03/03/2008

Meter Reading: 663.00

Problem?

pump leaking after you run pump. tryed primer no help. q47

Task performed:

Parts

Quantity

1. Primer valve needs to be rebuilt, will have factory repair
2. Air horn foot switch

7605-666764-0023 SWITCH FOOT SIREN

1



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V13774

In Date: 03/10/2008 Meter Reading: 9,277.00
Close Date: 03/10/2008

Problem?

ON CALL Q47 HEADLIGHT 10-7

Task performed:	Parts	Quantity
Call out; left headlight out; R/R left headlight. H4656 j	H4656USE CV TYPE HEAD LIGHT	1

Workorder: V13628

In Date: 03/01/2008 Meter Reading: 707.00
Close Date: 03/19/2008

Problem?

The seal around compartment L1 (driver side) has a leak. When it rains or when filling the tank, water gets into compartment L1. Q47

Task performed:	Parts	Quantity
1. Repaired leak in L-1 compartment	NO PARTS USED	

Workorder: V13807

In Date: 03/11/2008 Meter Reading: 732.00
Close Date: 03/19/2008

Problem?

flow meter for waterway appears to need calibrated q47

Task performed:	Parts	Quantity
1. Flow meter inop, recalibrated flow meter	NO PARTS USED	

Workorder: V13839

In Date: 03/12/2008 Meter Reading: 732.00
Close Date: 03/19/2008

Problem?

Passenger side moves towards the interior of the truck when moving, either from the wind or vibration. Mirror can be moved back with electronic switch, but will move back towards the truck when driving. Q-47

Task performed:	Parts	Quantity
1. Adjusted mirrors that were loose	NO PARTS USED	



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V13811

In Date: 03/11/2008

Meter Reading: 9,305.00

Close Date: 03/26/2008

Problem?

repair flat at sta 47 callaghan

Task performed:

Parts

Quantity

Repair flat Stn47 - Callaghan j

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V14404

In Date: 04/10/2008

Meter Reading: 824.00

Close Date: 04/22/2008

Problem?

front steamer swivel lock nut cross treaded Q47

Task performed:

Parts

Quantity

1. repaired swivel for front suction.

NO PARTS USED

Workorder: V14405

In Date: 04/10/2008

Meter Reading: 824.00

Close Date: 04/22/2008

Problem?

passenger side mirror loose Q47

Task performed:

Parts

Quantity

1. repaired mirror that was lose.

NO PARTS USED

Workorder: V14600

In Date: 04/21/2008

Meter Reading: 10,535.00

Close Date: 05/02/2008

Problem?

replace rear tires at st 47 callaghan

Task performed:

Parts

Quantity

Replace rear tires at Stn47 - Callaghan j

NO PARTS USED

Vendor?: CALLAGHAN



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V14716

In Date: 04/28/2008

Meter Reading: 10,671.00

Close Date: 05/09/2008

Problem?

CALIBRATE LOAD MINDER Q47

Task performed:

Parts

Quantity

1. drive to Stn; check connection & look in book for set up; fly ladder light went out; got update info; called Ferrara.

NO PARTS USED

2. Calibrated load minder & tested. j

Workorder: V14752

In Date: 04/29/2008

Meter Reading: 882.00

Close Date: 05/09/2008

Problem?

A/C COMPRESSOR BELT IS LOOSE Q47

Task performed:

Parts

Quantity

1. Rear backup lights out; chkd lights; fnd bad connection.

NO PARTS USED

2. Chkd for belt noise; fnd A/C compressor brckt brkn; will send to shop. j

Workorder: V15142

In Date: 05/16/2008

Meter Reading: 11,218.00

Close Date: 06/03/2008

Problem?

CHECK OVERHEAT CONDITION, E-47

Task performed:

Parts

Quantity

Drive to Stn23; chk for codes, belts & fan; test run ok. j

NO PARTS USED

Workorder: V15226

In Date: 05/20/2008

Meter Reading: 950.00

Close Date: 06/05/2008

Problem?

GENERATOR SHUTS OFF AFTER RUNNING A FEW MINUTES q47

Task performed:

Parts

Quantity

Fnd no problem with generator shutting off. j

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V14944

In Date: 05/08/2008
Close Date: 06/17/2008

Meter Reading: 907.00

Problem?

The green light on the ignition switch is burnt out. When the ignition is on the light on the switch does not light up. Q47

Task performed:

Parts

Quantity

1. repaired grnd. wire for switch that wasntlighting up.

NO PARTS USED

Workorder: V14945

In Date: 05/08/2008
Close Date: 06/17/2008

Meter Reading: 907.00

Problem?

The seal around drivers side compartment #1 needs to be replaced. When water comes out of the tank overflow, all the equipmer in the DS compartment #1 gets wet (the generator control panel is in this compartment). Q47

Task performed:

Parts

Quantity

1. checked for leaks at L-1 COMPT. RESEALED TOP COMPARTMENT..

NO PARTS USED

Workorder: V14946

In Date: 05/08/2008
Close Date: 06/17/2008

Meter Reading: 907.00

Problem?

The light box is missing the toggle nut that holds the head lamp in place. Q47

Task performed:

Parts

Quantity

1. replaced switch for spot lite that was broken.

NO PARTS USED

Workorder: V15921

In Date: 06/23/2008
Close Date: 06/23/2008

Meter Reading: 12,596.00

Problem?

on call engine wont shut off q47

Task performed:

Parts

Quantity

Chk out eng problem; replc ignition swtch & rep freaking out electrical lighting & wipers. j

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V15830

In Date: 06/19/2008
Close Date: 07/09/2008

Meter Reading: 12,361.00

Problem?

CHECK BRAKES Q47

Task performed:

1. brakes checked = ok

Parts

NO PARTS USED

Quantity

Workorder: V15841

In Date: 06/19/2008
Close Date: 07/09/2008

Meter Reading: 1,042.00

Problem?

The flow meter on the turntable stopped working while performing a pumping operation this am. Neither flowmeter on Q47 is working now.

Task performed:

1. tested flow meter and both working @ this time.

Parts

NO PARTS USED

Quantity

Workorder: V15126

In Date: 05/15/2008
Close Date: 07/11/2008

Meter Reading: 930.00

Problem?

hinge broke on top of door of engineer's compartment q47

Task performed:

1. Latch broken; replc L-1 compt brkt that holds open door.
2. Replc bulb (strobe). j

Parts

101305002DH0007-5 BRACKET RIGHT
2057LIGHT BULB
HA49102C2-32-15 LATCH NON LOCKING
TURBO5TUBE - STROBE

Quantity

1
10
2
1

Workorder: V14947

In Date: 05/08/2008
Close Date: 07/31/2008

Meter Reading: 907.00

Problem?

On crosslay #2 guage, the needle is behind the zero stop. Q47

Task performed:

Refer to W/O 15980. j

Parts

101305001BRACKET LEFT DH0008-5
91523933 GAUGE VAC/PRESS.

Quantity

1
1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V15980

In Date: 06/25/2008

Meter Reading: 1,062.00

Close Date: 07/31/2008

Problem?

Crosslay 2 gauges needle is behind the stop pin. q47

Task performed:

Replace #2 crosslay gauge in pump panel. j

Parts

Quantity

NO PARTS USED

Workorder: V15955

In Date: 06/24/2008

Meter Reading: 1,058.00

Close Date: 08/01/2008

Problem?

Right Quartz light is out. Moisture inside the light. Q47

Task performed:

Replc quartz light bulb twice; first new bulb-NG; rep sealin ring around lens to seal out moisture. j

Parts

Quantity

NO PARTS USED

Workorder: V15979

In Date: 06/25/2008

Meter Reading: 1,062.00

Close Date: 08/01/2008

Problem?

Passenger side front quartz light is out. Both flowmeters are not working, read 0 all the time. Driver side rear electric outlet is cracked. Screws are out/missing from aerial turntable steps. q47

Task performed:

1. Rem/install new electrical outlet receptacle.
 2. Mounted hand spotlight.
 3. Reinstall msng screw in aerial turntable steps; tightened all others including all platform screws.
- j

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V15531

In Date: 06/04/2008

Meter Reading: 12,019.00

Close Date: 08/04/2008

Problem?

C inspection and repairs as needed q47

Task performed:

Parts

Quantity



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

1. C-Inspection - Murray	107796DRYER KIT AD9 -NEW	1
2. Cab won't raise; motor burnt.	107800VALVE CHECK AD9	1
3. Assist Ken from Ferrara w/ladder ext cyl replacement.	11011FILTER B/S	1
4. Svc ladder.	17220-Z0D-000AIR FILTER BACK PLATE	1
5. Svc generator	800405PURGE VALVE KIT	1
6. Svc generator	P1147GFUEL FILTER 33120 WIX DELCO TP916	1
7. Svc air dryer	1250E473PLUG DRAIN REAR END FREIGHTLINER	1
8. Svc Hurst tools	29526898 29548988 TRANS FILTER ALLISON	2
9. Failed vac test.	5008414CARTRIDGE DC100	1
10. Rear brakes worn; replc brakes; seals cln & inspect bearings.	800404USE K022105 PURGE KIT AD-IP-IS	1
11. C-Inspection - Larson	CC109C10HYD FILTER 57316 WIX AIRPORT TRUCK	1
12. Readjust mirror brkts(twisted); set straight with frames (both sides).	130-8174-01COOLANT BOTTLE ONAN	1
13. Makeup new RPM-pump panel cable & install.	140-2897AIR FILTER ONAN 49697	1
14. Rep coolant overflow tank; fitting bad; retap tank threads.	75W90GEAR OIL SYN QT	21
15. Locking ring pin was left unlocked & pump packing adjusting sleeve back out; adj pump packing & ensure locking ring pin is set.	15W40BSYN OIL BULK QTS	40
16. Failed vac test; pressure test sys; fnd both R&L intake valves bad; rem panel on left side; rem valve assemble & rebuild both valves on bench; reinstall/retest ; test- now holding good.	17211-2L8-02330-347 HURST UNITS 06 HONDA	1
17. failed vac test; rem right side pump panel & rem R-intake valve for rebuilding; reinstall.	33063FUEL FILTER ONAN	1
18. help John Murray w/removal of primer valve; transfer all fittings & help John M. w/install process.	CA7230WA10116 AIR FILTER 46893 WIX	1
19. Rem pump panel primer valve; reinstall new primer vlave.	180R002HURST HYD. FLUID QT	1
20. water/foam valve pressure supply line kinked; rem line; cut off band end; replc fittings from straight to 45 degrees.	359-5990PLUG - HUB OIL CAP	2
21. R/Intake drain valve leaking; rem valve & replc fitting; reinstall valve.	LFP210GAUGE NEW STYLE	1
22. Rem twist control handle from Hurst spreader; polish down burrs & rough surface for handle to move freely; reassemble.	3202059SEAL QUINT	1
23. Rep brkn wiring for cab lock light.	3202099SEAL WITH RACE QUINT	1
24. Replc coolant level sensor & splice in new snesor wiring connector; NOTE: these parts were taken from this veh to fix Spec Ops.	538028052VALVE PRIMER PUMP W/HARDWARE	1
25. Rep frnt intake swivel; rem swivel head & rep; twist lock assy; stripped out base; drill & Heli-coil brass base; reassemble w/new lock stud & handle.	70002629109041 BEARING 025 IN 50 PK	6
26. Svc Hurst tool - due svc.	FT4471BDQUINT REAR BRAKE SHOES	4
27. Replc wiper blades - worn.	KIT9081BRAKE HARDWARE KIT	2
28. Tag light inop; installed new bulb.	3219F4972BRAKE DRUM QUINT	2
29. Aerial remote inop; low btry; installed new btry.	91388906 VALVE KIT 2.5 IN AKRON	3
30. Rem drive shaft to gain the only access to a factory installed foam tank drain valve; add a drain line to existing valve; to drain out foam tank so foam doesn't cover over pump; after draining tank plug off this drain & install a new drain sys that is accessible from outside	401581GASKET AXLE FL80 R002435	2
	50-24WIPER BLADE - KME	2
	51064OIL FILTER ONAN	1
	6535SPARK PLUG CR5HSB	1
	A06-24733-000WIRE HARNESS	1
	C10FILTER Q47	1
	E-600013-3052 NUT	10
	J254HALOGEN BULB 1000 WATT WPB	1
	HA24063HOOK WHEELED COACH	1
	LABORHOURLY LABOR CHARGE	5
	PH47 51758 L/F PH725 OIL FILTERL	1
	PH7405 51971 OIL FILTER WIX	2
	TRANSYNDALLISON TRANS FLUID GAL	9
	REDG6S14023 GASKET 6 IN	2



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

veh.

31. Cln out cab A/C condenser evaporator; plugged w/dust & dirt; mk up a filter type sys to keep evap cln.

32. Side panel foam fill sys inop; rem pump motor & selector actuator asy; diss on bench & install new motor assy.

33. Install new air filter housing on Hurst Power unit; mk a new support brkt behind housing to help stabilize.

34. Rep latches on top of dash compt.

35. Replc defective map light;

36. Svc trans.

37. Svc T-case.

38. Svc diff.

39. Frnt wheel bearing hubs way over filled throwing out oil; suck out oil to proper level & install new cap seals.

40. Cln up. j



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V16520

In Date: 07/22/2008

Meter Reading: 12,774.00

Close Date: 08/08/2008

Problem?

repair foam leak repair load minder repair flow meter repair pump tach cable Q47

Task performed:

WARRANTY

1. Drain foam tank; rem main feed hose from tank; fnd hose cross threaded in tank; rep tank threads; reseal tank fitting; also tank fill fitting leaking; reseal this hose & fittings as well; cln corrosion from alum framing.
2. Rem old cable/gear asy; (rusted/corroded); make up new cable hsnng & inner cable; isntall new gear asy.
3. Ladder bed scuff pads; Rep stripped out screws on left side ladder, "Bed schuff pads"; mod a new scuff pad to fit ladder support frame; (msng-brkn screws); drill out & retap holes; install new pad.
4. Flow meters inop; neither aerial or pump panel meters light up; trace wiring & fnd bad grnd; NOTE: aerial panel meter operates & shows flow; pump panel meter just shows "O"; no flow rate; parts dept did not have proper paddle wheel sender for this veh; will need to have factory mechanic to order & install.
5. Load minder inop; Set up veh in lot to prepare for calibration; NOTE: factory mech had replc the panel module a week before but did not calibrate; new module would not except pass code therefore, would not enter calibration mode; after calling Class-One & intense research, we fnd that wiring had been cut & spliced back tog improperly; after making rep now it would enter into calibration mode; set all peramaters; retest; all worked ok except when entering overloaded status only alarm sounded & NOT the fly section warning lights; chk out this sys & fnd wiring to relay was also cut & spliced wrong; rewire properly; retest; now all is working properly.
6. Assisted Larson w/load minder problem. Murray
7. Assisted Larson w/flowmeter repairs. Murray

Parts

Quantity

048009000SPEEDCOUNTER PUMP PANEL

1

752-0001NYLA WEAR PADS

1

Workorder: V16911

In Date: 08/08/2008

Meter Reading: 13,039.00

Close Date: 08/14/2008

Problem?

AIR LEAK, Q-47

Task performed:

Traced out air leaks; fnd rear tank drain leaking; rep fitting. j

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V16870

In Date: 08/06/2008

Meter Reading: 1,098.00

Close Date: 08/15/2008

Problem?

The cab lift indicator light is burnt out. Light does not come on when cab lift is in action. Also. had to "jiggle" the cord to operate ca lift. Q47

Task performed:

Tested cab lift & tested ok.

j

Parts

NO PARTS USED

Quantity

Workorder: V16873

In Date: 08/06/2008

Meter Reading: 1,098.00

Close Date: 08/15/2008

Problem?

Flowmeter is not working on the pump panel. Flowmeter registers 0 when flowing water through pump to the waterway.Q47

Task performed:

Tested flow meter; needs new sender; will order.

j

Parts

NO PARTS USED

Quantity

Workorder: V16977

In Date: 08/12/2008

Meter Reading: 1,125.00

Close Date: 08/22/2008

Problem?

Lever on 13/4 valve on the tip is almost frozen Q47

Task performed:

1. operated valve and grease valve and tested

Parts

NO PARTS USED

Quantity

Workorder: V17204

In Date: 08/21/2008

Meter Reading: 13,529.00

Close Date: 08/29/2008

Problem?

REPAIR DISCHARGE VALVE Q47

Task performed:

1. Rem valve; need to replc with new 2-1/2 valve.
2. R/R ball valve on ladder; change both ends to install other valve. j

Parts

91388906 VALVE KIT 2.5 IN AKRON

Quantity

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V17519

In Date: 09/05/2008
Close Date: 09/30/2008

Meter Reading: 1,184.00

Problem?

There is a bracket on the upper r hand corner of the driver side compartment #2 that is broke. This brackets hold the piston arm that does not allow the door to open more than 90 degrees. Was replace 2 months ago by Tom. q47

Task performed:

Install new bracket for L-1 Compartment Door.
Adjust all ladder cables.

Parts	Quantity
101305001BRACKET LEFT DH0008-5	1
101305002DH0007-5 BRACKET RIGHT	1

Workorder: V17693

In Date: 09/14/2008
Close Date: 09/30/2008

Meter Reading: 1,209.00

Problem?

Passenger rear deck light burnt out Q47

Task performed:

replace deck light bulb

Parts	Quantity
4537BULB 100W SPOT	2

Workorder: V18035

In Date: 09/29/2008
Close Date: 10/07/2008

Meter Reading: 1,257.00

Problem?

generator on Q47 stopped working after approx 25 mins of use. After got back to St47 approx 1 hr, generator was working again. q47

Task performed:

1- RAN GENERATOR FOR 345 MINUTES AND UNIT RAN OK CHECKED ALL FLUIDS.
2- LADDER MAKING NOISE,LOBED LADDER AND ADJUSTED LADDER CABLES.

Parts	Quantity
NO PARTS USED	

Workorder: V18179

In Date: 10/07/2008
Close Date: 10/15/2008

Meter Reading: 14,734.00

Problem?

VEHICLE PULLS TO THE RIGHT, Q-47

Task performed:

1-Road tested will send truck for wheel alignment.

Parts	Quantity
15W40QSYN OIL QT	12



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V18185

In Date: 10/07/2008

Meter Reading: 1,273.00

Close Date: 10/15/2008

Problem?

front quartz light is not working Q-47

Task performed:

Parts

Quantity

1-Cab a/c inop, vaccumed down system and recharged and tested temp. tested ok.

NO PARTS USED

Workorder: V18211

In Date: 10/08/2008

Meter Reading: 1,278.00

Close Date: 10/15/2008

Problem?

the AC in Q47 is blowing hot air when both units are on AC

Task performed:

Parts

Quantity

1-A/C inop-vaccum down system and recharge and tested.

NO PARTS USED

Workorder: V15129

In Date: 05/16/2008

Meter Reading: 930.00

Close Date: 10/20/2008

Problem?

door latch on drivers cabinet broken q47

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V18210

In Date: 10/08/2008

Meter Reading: 1,278.00

Close Date: 10/28/2008

Problem?

the passenger side quartz light mounted on the front of the cab is not working. Q47

Task performed:

Parts

Quantity

rear door hard to open; adj rear door linkage. j

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V18276

In Date: 10/11/2008

Meter Reading: 1,285.00

Close Date: 10/28/2008

Problem?

Quartz light located on front top of passenger side is not working. Q-47

Task performed:

Quartz light out; replcd bulb & tested. j

Parts

Quantity

15W40BSYN OIL BULK QTS

24

J254HALOGEN BULB 1000 WATT WPB

1

Workorder: V18344

In Date: 10/15/2008

Meter Reading: 1,288.00

Close Date: 10/28/2008

Problem?

GENERATOR WON'T RUN CONSISTENTLY Q47

Task performed:

Generator inop; ran generator & rep bad connection. j

Parts

Quantity

NO PARTS USED

Workorder: V18428

In Date: 10/20/2008

Meter Reading: 15,014.00

Close Date: 10/28/2008

Problem?

nozzel inop at tip q47

Task performed:

1. Nozzle tip inop; traced problem; fnd bad connetion in switch; rep & tested.

2. Door open light on; fnd L-1 compt SW shorted to grnd repaired. j

Parts

Quantity

NO PARTS USED

Workorder: V18907

In Date: 11/07/2008

Meter Reading: 15,434.00

Close Date: 12/01/2008

Problem?

OVERHEAD LIGHTS INOP, Q-47

Task performed:

Truck overheating; road tested & chkd ok. j

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V18966

In Date: 11/10/2008
Close Date: 12/01/2008

Meter Reading: 1,355.00

Problem?

Need approx 3 qts of motor oil for the quint Q-47

Task performed:

Dropped off oil. j

Parts

NO PARTS USED

Quantity

Workorder: V19270

In Date: 11/22/2008
Close Date: 12/01/2008

Meter Reading: 1,392.00

Problem?

The quartz lights on the driver side telescope and top front cab passenger side are not working. Q47

Task performed:

1. Replcd bulbs in quartz lights.
2. Foam PU inop; fnd bad connection on pump. j

Parts

NO PARTS USED

Quantity

Workorder: V18559

In Date: 10/24/2008
Close Date: 12/02/2008

Meter Reading: 1,305.00

Problem?

FLOW METER AT PANEL NOT WORKING CAN'T TALK FROM PANEL INTERCOM, ONLY LISTEN q47

Task performed:

1. Traced out problem w/intercom; fnd bad connection at turn table.
2. Tested flow meter & tested ok. j

Parts

1157BULB
91-22WIPER BLADE

Quantity

10
2

Workorder: V18263

In Date: 10/10/2008
Close Date: 12/05/2008

Meter Reading: 14,820.00

Problem?

REPLACE 2 FRONT TIRES, Q-47 (CALLAGHAN TIRE)

Task performed:

replace 2 front tires q-47

Parts

NO PARTS USED

Quantity

Vendor?: CALLAGHAN



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V18775

In Date: 11/01/2008

Meter Reading: 1,330.00

Close Date: 01/05/2009

Problem?

the quartz light located front top drivers side left bracket is broken. Q47

Task performed:

1. installed new brkt for qtz light.
 2. A/C warm; rechrgd A/C & tested.
 3. No primer; fnd bad connection on primer solenoid.
- j

Parts

Quantity

X-OP250-12MOUNT FOR OPA810 LEFT

1

Workorder: V19653

In Date: 12/10/2008

Meter Reading: 16,529.00

Close Date: 01/05/2009

Problem?

repair comp dor q47

Task performed:

Rep compt door holdopn that broke off door. j

Parts

Quantity

NO PARTS USED

Workorder: V19703

In Date: 12/12/2008

Meter Reading: 1,457.00

Close Date: 01/05/2009

Problem?

Quartz light abobe drivers side front window out. Q-47

Task performed:

Replcd bulb in quartz light. j

Parts

Quantity

NO PARTS USED

Workorder: V19735

In Date: 12/14/2008

Meter Reading: 1,461.00

Close Date: 01/05/2009

Problem?

Found bracket underneath vehicle on 12/14 in the morning. Don't know where it came from would like mechanic to look at. On officers desk in station. Vehicle is operating properly Q-47

Task performed:

Bracket was for garage door. j

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V19772

In Date: 12/16/2008

Meter Reading: 16,737.00

Close Date: 01/05/2009

Problem?

REPAIR WATERWAY HANDLE Q47

Task performed:

waterway handle fell off; reinstalled. j

Parts

NO PARTS USED

Quantity

Workorder: V19955

In Date: 12/24/2008

Meter Reading: 1,480.00

Close Date: 01/05/2009

Problem?

OFFICER SIDE DRIVING HEADLIGHT OUT Q-47

Task performed:

Chkd headlights; fnd no lights out at this time. j

Parts

NO PARTS USED

Quantity

Workorder: V20000

In Date: 12/29/2008

Meter Reading: 17,152.00

Close Date: 01/06/2009

Problem?

ON CALL Q 47 HEADLIGHT 10-7

Task performed:

Replc R/F headlight. j

Parts

H4656USE CV TYPE HEAD LIGHT

Quantity

1

Workorder: V20196

In Date: 01/07/2009

Meter Reading: 1,524.00

Close Date: 01/07/2009

Problem?

head phones behind Lt seat doesn't work. q47

Task performed:

contacted mike goad

Parts

NO PARTS USED

Quantity



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V20096

In Date: 01/03/2009

Meter Reading: 1,507.00

Close Date: 01/27/2009

Problem?

Passenger side rear deck light is not working q47

Task performed:

Parts

Quantity

- 1- Rear light out, found bad connection on ground.
- 2- Ladder making noise, adjusted ladder cables and lube ladder.

NO PARTS USED

Workorder: V20314

In Date: 01/13/2009

Meter Reading: 1,548.00

Close Date: 01/27/2009

Problem?

LDH has pin holes by hydrant connection Q-47

Task performed:

Parts

Quantity

- 1- Dropped off new hose.

NO PARTS USED

Workorder: V20253

In Date: 01/09/2009

Meter Reading: 1,527.00

Close Date: 01/28/2009

Problem?

passenger side rear deck light out Q47

Task performed:

Parts

Quantity

- 1- Repaired bad ground in light.

NO PARTS USED

Workorder: V20623

In Date: 01/27/2009

Meter Reading: 18,264.00

Close Date: 02/12/2009

Problem?

A/C COMP BRAKET BROKEN Q47

Task performed:

Parts

Quantity

- 1- belt making noise, found a/c bracket broken. removed belts to a/c secured a/c compres.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V20717

In Date: 01/30/2009

Meter Reading: 1,611.00

Close Date: 02/19/2009

Problem?

Drivers side front running light and rear passenger side scene lights are burnt out. q47

Task performed:

rear tail light inop; fnd bad connection. j

Parts

Quantity

NO PARTS USED

Workorder: V20805

In Date: 02/02/2009

Meter Reading: 18,604.00

Close Date: 02/19/2009

Problem?

REPAIR OIL LEAK AT HUB

Task performed:

1. Ladder making noise; grease ladder & tested.
 2. Hub leaking oil; Replcd hub seal.
 3. Rear spotlights inop; fnd bad connection in spotlight.
- j

Parts

Quantity

NO PARTS USED

Workorder: V20932

In Date: 02/06/2009

Meter Reading: 18,672.00

Close Date: 02/19/2009

Problem?

Officer's side rear work light is inop. Q47

Task performed:

Fnd all lights working at this time. j

Parts

Quantity

NO PARTS USED

Workorder: V20761

In Date: 01/31/2009

Meter Reading: 1,616.00

Close Date: 02/23/2009

Problem?

Right Rear tire/rim has some minor damage(dents in the rim). Q-47

Task performed:

Fnd small dents in right rear wheel cover; no rep needed. j

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V20974

In Date: 02/09/2009
Close Date: 02/23/2009

Meter Reading: 1,634.00

Problem?

Equipment tray is hard to pull out. q47

Task performed:

Parts

Quantity

Fnd tray jammed; traylock bent; straightened lock; ck
opn; ck ok. j

NO PARTS USED

Workorder: V21004

In Date: 02/10/2009
Close Date: 02/23/2009

Meter Reading: 18,672.00

Problem?

NO BRAKE LIGHTS, Q-47

Task performed:

Parts

Quantity

No brake lights; reprogrammed node & retested. j

NO PARTS USED

Workorder: V17557

In Date: 09/08/2008
Close Date: 03/02/2009

Meter Reading: 13,802.00

Problem?

BRAKES SMOKING Q47

Task performed:

Parts

Quantity

Checked brakes, found driver did not have brake retarter
on.

NO PARTS USED

Workorder: V20043

In Date: 12/31/2008
Close Date: 03/02/2009

Meter Reading: 17,152.00

Problem?

door open alarm staing on q47

Task performed:

Parts

Quantity

1- door alarm on- readjusted all doors switches.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V20506

In Date: 01/22/2009 Meter Reading: 18,092.00
Close Date: 03/10/2009

Problem?

QUARTZ LIGHT INOP, Q-47

Task performed:

1- replaced bulb on quartz light.

Parts

NO PARTS USED

Quantity

Workorder: V21127

In Date: 02/16/2009 Meter Reading: 1,672.00
Close Date: 03/13/2009

Problem?

Front right and left scene lights stay on at start up. Q-47

Task performed:

1. Fnd light goes on at startup but shuts off.
2. Brkn quartz light; rem light; will order new light. j

Parts

1245-P-1030USE 13047
 OP-204-MBEZEL KIT FOR FIRE RESEARCH LIGHT
 OPP-503MLENSE FOR FIRE RESEARCH
 X-OP250-12MOUNT FOR OPA810 LEFT

Quantity

1
1
1
1

Workorder: V21255

In Date: 02/21/2009 Meter Reading: 1,692.00
Close Date: 03/16/2009

Problem?

Flowmeter not working on the quint. Q47

Task performed:

Flowed water & tested flow meter. j

Parts

NO PARTS USED

Quantity

Workorder: V21352

In Date: 02/26/2009 Meter Reading: 1,705.00
Close Date: 03/16/2009

Problem?

Front preconnect valve has slow leak that fills hose with water Q47

Task performed:

1. Pump leaking water; adj pump packing & ran pump.
2. Rear spotlights out; rep broken wire on rear spotlight.
3. Ladder making noise; adj ladder cables & greased ladder. j

Parts

4537BULB 100W SPOT

Quantity

2



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V21433

In Date: 03/01/2009

Meter Reading: 1,717.00

Close Date: 03/16/2009

Problem?

Lights out: amber running light on top of the front cab (drivers side), rear passenger deck light, drivers side front quartz light. Q-47

Task performed:

Parts

Quantity

1. Amber marker light out; rep bad grd on marker light.
2. Replcd quartz light w/new one that was ordered. j

NO PARTS USED

Workorder: V21434

In Date: 03/01/2009

Meter Reading: 1,717.00

Close Date: 03/16/2009

Problem?

Front jump line vale is leaking from pump to discharge. The line is filled with water and the first 6" of jumpline is charged. When drain is open a steady flow of water comes out when valve is closed. Q-47

Task performed:

Parts

Quantity

1. Ran pump & chkd for leaks & fnd no leak at this time. j

NO PARTS USED

Workorder: V21485

In Date: 03/02/2009

Meter Reading: 1,720.00

Close Date: 03/16/2009

Problem?

RIGHT REAR TIRES - THIN TREAD q47

Task performed:

Parts

Quantity

1. Replace all (4) rear tires. j

NO PARTS USED

Workorder: V21779

In Date: 03/13/2009

Meter Reading: 19,788.00

Close Date: 03/20/2009

Problem?

need to secure high rise pack Q47

Task performed:

Parts

Quantity

1. SECURE HIGH RISE PACK. J

UMVS162511STRAP

2



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V21723

In Date: 03/11/2009

Meter Reading: 1,750.00

Close Date: 03/26/2009

Problem?

cab lift remote / outlet not working. mechanic was here today and knows about it. said our quint will be going to shop in morning (t shift, march 12. q47

Task performed:

Cab lift inop; fnd bad connection in remote cable.
j

Parts

NO PARTS USED

Quantity

Workorder: V21194

In Date: 02/19/2009

Meter Reading: 1,682.00

Close Date: 04/01/2009

Problem?

REAR AC NOT COLD. FRONT AC WORKING FINE. Q47

Task performed:

1. Drive to stn; inspected A/C brckt; raise ladder & cab; electric lift inop for cab; manually lifted; Tommy ordered new controll.
2. Replc A/C comp brkt. j

Parts

851001-009A/C BRACKET
 9420BELT
 9435BELT
 FREIGHTSHIPPING CHARGES

Quantity

1
1
1
1

Workorder: V21785

In Date: 03/13/2009

Meter Reading: 1,753.00

Close Date: 04/03/2009

Problem?

Front jump line (orange) valve is leaking. Line is getting slowly charged when valve is shut all the way. Quint 47

Task performed:

1. Vac tested pump & passed; chkd frnt trash line & fnd no leaks.
2. Roof mntd quartz light brkn; rem light & isntalled new parts on light.
3. Air leak; fnd fitting on frnt suction valve leaking; rep.

Parts

NO PARTS USED

Quantity

Workorder: V21806

In Date: 03/14/2009

Meter Reading: 1,755.00

Close Date: 04/03/2009

Problem?

Neither flowmeter work on the quint. Both read zero with water flowing. q47

Task performed:

Tested flow meters & fnd both flow meters working. j

Parts

NO PARTS USED

Quantity



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V22064

In Date: 03/25/2009

Meter Reading: 20,207.00

Close Date: 04/06/2009

Problem?

wont pull draft q 47

Task performed:

Parts

Quantity

1. Perform pump; tested with crew.

NO PARTS USED

2. Monitor inop; rep bad connection. j

Workorder: V21559

In Date: 03/05/2009

Meter Reading: 19,606.00

Close Date: 04/13/2009

Problem?

replace tires at sta callaghan

Task performed:

Parts

Quantity

Replace tires at Stn - Callaghan j

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V22199

In Date: 03/30/2009

Meter Reading: 1,815.00

Close Date: 04/13/2009

Problem?

Recirculation valve does not close all the way.

Task performed:

Parts

Quantity

Tank fill leaking; rep valve that was not closing. j

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V22033

In Date: 03/23/2009

Meter Reading: 20,207.00

Close Date: 05/07/2009

Problem?

C INSPECTION AND REPAIRS AS NEEDED Q47

Task performed:

Parts

Quantity



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

C-Inspection	05-17223-000CAP RADIATOR 10 LB	1
2. Review ladder inspection procedures.	0769027STRAINER 2.5 IN	2
3. Svc aerial; c/n slide track & lube; lube cables, grease rotation gears; adj slides.	102D-158AHOSE GAUGE	1
4. C/n btrys, cables, test btrys.	827009-002CAB LIFT CYL	1
5. Belts, rem fan, hub & bracket.	FREIGHTSHIPPING CHARGES	3
6. Safety meeting.	PL-10057SEAL KIT 4 IN ELBOW	1
7. Raise ladder & cab; rem electrical separator frm gov control head for Ken Flerx; repositioned pin.	PS683033442 FUEL FILTER	2
8. Svc auto lube; makeup fittings for easy drain.	12-0612AUSE 1600 VALVE EXPANSION RED DOT HOSELIN	1
9. Rep PTO u-joint grease fitting.	20036BRACKET BALL MT	1
10. Chk/erase eng inactive codes; charge laptop; chk ABS codes-ok; cld not connect w/trans.	23532155OIL DIPSTICK ASSBLY	1
11. C-Inspection.	291525END STANCHION	1
12. Meeting.	EAA-8350-30UGSS1783UQ STRUT-LIFT	1
13. Air all tires.	MF15PSENSOR PADDLEWHEEL	1
14. Rep circle "D" brkt.	2960030100PACKING PUMP	1
15. Svc ram fan.	47913MARKER LIGHT LED NEWER QUINTS	1
16. Replcd rear inlet strainers; rep L-intake coupling, true up brass pipe & lube bearings; rep discharge cap chains.	5008414CARTRIDGE DC100	1
17. Dia L-side marker inop; fnd no grnd due to grnd being hooked up to an insulated member; run aux grnd.	828001002SIGHT GLASS SAME AS 17KP655	1
18. Rep R-window squirter; rep hose/adj.	K022105PURGE VALVE AD-IP-IS	1
19. Makeup safety support rod for removing cab lift cyl.	51064OIL FILTER ONAN	1
20. R/R r-cab lift cyl; mod cyl head for clearance & operate lift & add oil to reservoir.	C10FILTER Q47	1
21. Replcd air line fittings & do WO's.	68298406330CLEAR DOME LENSE L31	1
22. Compt time.	7001-30ESEAL	1
23. Order parts.	91378905 VALVE KIT 2 IN AKRON	1
24. Replcd frnt/rear A/C filters; R/R frt dash panel & rear door latches; cut filter to size.	7001-40ESEAL 4 IN	1
25. Replcd msgng A/C register.	740-WWS75WATERWAY SEAL KIT	1
26. Search arnd shop for laptop, V-mux & interface module.	74R258607-2613A RED DOT DRIER 7127	1
27. Chk problem on rear A/C.	91368904 VALVE KIT 1 1/2 IN	1
28. Work on discharge #3.	91388906 VALVE KIT 2.5 IN AKRON	2
29. Rebuild valves.	91398907 VALVE KIT 3 IN AKRON	2
30. Comp time.	9435BELT	3
31. Order handrail.	K080570BELT	1
32. International training.	BPR6ESSPARK PLUG 7131	1
33. Dia rear A/c inop; fnd bad T-stat & exp valve closed; tighten rear fan swtch brkt; replcd dryer & exp valve; evac/recharge.	CA7230WA10116 AIR FILTER 46893 WIX	1
34. Chk trans codes; cld not connect to trans; need updated version.	FG-Q59278P/S GASKET	1
35. Charge A/C sys & chk pressures & temp at outlet; leak chk.	FG87904MFG3937557S FILTER P/S NEW STYLE	1
36. Rem SCBA release brackets/cables.	MWAB-PRSEAT STRAP ZICO	1
37. Rebuild waterway.	P1147GFUEL FILTER 33120 WIX DELCO TP916	1
38. Rebuild swivel.	PH47 51758 L/F PH725 OIL FILTERL	1
39. Work on blue lift.	PH7405 51971 OIL FILTER WIX	2
40. Install aerial flow sensor, saddle, valve & vitaulic coupler.		



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

41. Drain motor oil; replcd dipstick & tube; refill crankcase.
 42. Perform dry vac test-ok.
 43. Fill watertank & test waterway & cnhk for leaks; test tri-mese & pump panel flow meter.
 44. Erase trans codes.
 45. Cutoff loose rubber hand grip on aerial handrail.
 46. Pump test Q47 & E35.
 47. Replace L-frt clearance light.
 48. Replcd pump packing & adj.
 49. Sand rust on aerial & treat w/acid.
 50. Dia PTo leak; fnd leak at gskt; rem bolts; sealed & retighten; chk for leaks-ok.
 51. Touch up paint on aerial.
 52. Wash eng off.
 53. Drive to Stn23 for fuel & back.
 54. Fnd veh able to go into gear w/aerial up & outriggers out/down; called Ferrara to chk if normal; no call back; Tommy said already been addressed normal.
 55. Svc gen set.
 56. Svc dryer; install upgrade components.
 57. Replc brkn hyd filter compound gauge.
 58. Adj pump packing.
 59. Rep threads in panel wall to take new screws that were stripped ut.
 60. Tighten holdopen shock pin on L-2 compt.
 61. Rep threads in panel wall to take new screws & reinstall helmet hooks.
 62. Rep lens for corner light - compt lite.
 63. Cab lift remote box connector brkn; rem frm side panel & install new style connectors on panel & on remote box connector; rewire.
 64. Install new style remote warning lite in pump panel; rewire.
 65. Shop safety meeting on fire extinguisher.
 66. Rep exh rattle; clamp loose & brkt brkn; rem/weld & reinstall.
 67. Rep eng oil leak; fitting loose in block; retighten & wash down side of eng.
 68. Rep rad leak & install new sight glass asy & rad cap.
 69. Shop meeting on sexual harassment.
 70. C/O size of door panel plugs; fnd vendor to order; ordered parts parts came in; chk/fnd (box says 2", content is 2-1/2"); give back to parts dept; reorder.
 71. Wash down P/S res & left side gear box; fnd leak in fittings; rem/reseal.
 72. Rep wiring on pump command control back panel; pin had pushed out of connector; problem was gaining access to plug connector.
 73. Svc P/S sys; rep bent up top cover.
 74. Assist Jeff w/replacement of R-side cab cyl; bleed out & refill sev.
-



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V22589

In Date: 04/21/2009

Meter Reading: 20,442.00

Close Date: 05/08/2009

Problem?

repair vent saw and blower (outside agency-regan's small engine service)

Task performed:

Parts

Quantity

Repair vent saw/blower - Regans j

TBD72TOOL BOX

1

Vendor?: REGANS SMALL ENG

Workorder: V23208

In Date: 05/11/2009

Meter Reading: 20,901.00

Close Date: 05/11/2009

Problem?

REPLACE REAR SPRINGS TOTAL TRUCK

Task performed:

Parts

Quantity

NO PARTS USED

Vendor?: TOTAL TRUCK

Workorder: V23258

In Date: 05/13/2009

Meter Reading: 20,901.00

Close Date: 05/21/2009

Problem?

repair damage to step q47

Task performed:

Parts

Quantity

Rep wire track on ladder. j

NO PARTS USED

Workorder: V23499

In Date: 05/23/2009

Meter Reading: 1,880.00

Close Date: 06/01/2009

Problem?

the door ajar light continues to flash while vehicle is being driven Q47

Task performed:

Parts

Quantity

Door open light; fnd water in sys. j

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V23674

In Date: 05/30/2009 Meter Reading: 1,905.00
Close Date: 06/19/2009

Problem?

right telescope light not working Q47

Task performed:

Replcd bulb in quartz light. j

Parts

Quantity

J254HALOGEN BULB 1000 WATT WPB

4

Workorder: V23770

In Date: 06/03/2009 Meter Reading: 21,642.00
Close Date: 06/19/2009

Problem?

CHECK UNIT FOR DAMAGE Q47

Task performed:

Ladder hit bay door; chkd damage to ladder. j

Parts

Quantity

NO PARTS USED

Workorder: V23890

In Date: 06/08/2009 Meter Reading: 21,820.00
Close Date: 06/24/2009

Problem?

ON CALL CHECK SUSPENSION Q47

Task performed:

Fnd loose bolt on shackle pin left rear spring cutter pin;
improperly installed on right side. j

Parts

Quantity

NO PARTS USED

Workorder: V23963

In Date: 06/10/2009 Meter Reading: 1,940.00
Close Date: 07/06/2009

Problem?

L2 door (driver's compartment) hinge broke again. Q47

Task performed:

Installed new hinge on L-1 door. j

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V24056

In Date: 06/14/2009
Close Date: 07/06/2009

Meter Reading: 1,952.00

Problem?

Driver compartment door strut broken off at one end. Not repairable, needs replacement. Q47

Task performed:

1. Ladder making noise; grease turntable.
2. Rear spotlight out; rep brkn wire. j

Parts

NO PARTS USED

Quantity

Workorder: V24246

In Date: 06/22/2009
Close Date: 07/06/2009

Meter Reading: 1,974.00

Problem?

officer side dome light Q47

Task performed:

1. Replcd bulb in right side spotlight & rep wires.
2. Intercom on ladder inop; rep bad connec tion on ladder. j

Parts

Q1500T3/CL-1BULB QUARTZ 120V

3

Quantity

Workorder: V24332

In Date: 06/24/2009
Close Date: 07/06/2009

Meter Reading: 1,983.00

Problem?

the pump works, we get water, but when the primer is pulled we get no sound, we the switch for primer was on. Q47

Task performed:

1. Primer inop; replcd primer switch & solenoid.
2. Ladder making noise; greased ladder & adj cables. j

Parts

200-2450-00NC SWITCH OK TO PUMP

2000071102000072100 SOLENOID HALE PRIMER

1

1

Quantity

Workorder: V24333

In Date: 06/24/2009
Close Date: 07/06/2009

Meter Reading: 1,983.00

Problem?

The PTO buttun had to be pushed a few times to get it to light up and turn on. Q47

Task performed:

1. Chkd opn of pump & tested ok.
2. A/C inop; recharged sys. j

Parts

NO PARTS USED

Quantity



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V24410

In Date: 06/28/2009

Meter Reading: 1,993.00

Close Date: 07/06/2009

Problem?

Knocking sound coming from steering at low speeds. Performance not effected, but something sounds like it came loose. Q47

Task performed:

1. Need oil at Stn; dropped off.
2. No going into pump; tested sys & tested ok.
3. road tested for noise in frnt; fnd no noise. j

Parts

15W40QSYN OIL QT

Quantity

12

Workorder: V24367

In Date: 06/26/2009

Meter Reading: 22,406.00

Close Date: 07/08/2009

Problem?

A/C IN CAB INOP, Q-47

Task performed:

recharged front/rear A/C j

Parts

NO PARTS USED

Quantity

Workorder: V24487

In Date: 07/01/2009

Meter Reading: 22,563.00

Close Date: 07/17/2009

Problem?

CAB LEAKS WATER Q 47

Task performed:

Resealed top of roof where water was leaking. j

Parts

NO PARTS USED

Quantity

Workorder: V24551

In Date: 07/02/2009

Meter Reading: 22,563.00

Close Date: 07/17/2009

Problem?

RAM FAN STALLS OUT UNDER LOAD

Task performed:

1. Ram fan stalls under load/carb jet clogged; clnd carb & replcd fuel plug & eng oil.
2. Pull cord brkn; replcd ull cord; deliver to stn. j

Parts

BPR6ESSPARK PLUG 7131

FZ51368FEET RUBBER RAM-FAN

Quantity

1

4



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V24866

In Date: 07/18/2009

Meter Reading: 2,062.00

Close Date: 07/20/2009

Problem?

Mechanic was here and fixed the cab lift, repaired a loose wire, replaced the small light bulb which indicated cab is ready to be lifted. Also added coolant. Q47

Task performed:

Parts

Quantity

Call out repair.
Rep plug & installed light in cab tilt; add coolant; chk for leak. j

NO PARTS USED

Workorder: V24838

In Date: 07/17/2009

Meter Reading: 22,923.00

Close Date: 07/24/2009

Problem?

repair blower Sta 47 (outside agency-regan's small engine service)

Task performed:

Parts

Quantity

Repair blow Stn47 - Regans j

NO PARTS USED

Vendor?: REGAN SMALL ENG

Workorder: V25423

In Date: 08/10/2009

Meter Reading: 23,609.00

Close Date: 08/13/2009

Problem?

OJN CALL Q47 OVERHEATING

Task performed:

Parts

Quantity

Went to Stn47; overheating; fnd bad cap; installed new; went to chk w/computer; wld not work on truck; computer needs work on program. j

05-17223-000CAP RADIATOR 10 LB

1

Workorder: V25104

In Date: 07/27/2009

Meter Reading: 2,076.00

Close Date: 08/18/2009

Problem?

Officer side scene light not working.Q-47

Task performed:

Parts

Quantity

1. Scene light inop; replc bulb & rep wire.
2. Pump leak; adj pump packing.
3. Ladder making noise; greased waterway. j

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V25213

In Date: 08/01/2009

Meter Reading: 2,092.00

Close Date: 08/18/2009

Problem?

Q47 Jake Brake Out of Service. Transmission Retarder is working.

Task performed:

Parts

Quantity

1. Jake brake inop; traced out problem; fnd bad connection on engine.
2. Monitor inop; fnd bad connection.
3. Rear A/C inop; recharged rear A/C. j

NO PARTS USED

Workorder: V25235

In Date: 08/03/2009

Meter Reading: 23,559.00

Close Date: 08/18/2009

Problem?

Q47 mount tools on veh

Task performed:

Parts

Quantity

Mounted tools in L-1 compt. j

6807200575HANDLE DOOR

1

Workorder: V24971

In Date: 07/22/2009

Meter Reading: 23,199.00

Close Date: 08/19/2009

Problem?

INSTALL PLACKARD Q47

Task performed:

Parts

Quantity

1. Ladder noise; greased ladder & tested.
2. Rear spotlights out; rep brkn wire in lights. j

ADPDATA PLATE QUINTS

1

FREIGHTSHIPPING CHARGES

1

Workorder: V26049

In Date: 09/04/2009

Meter Reading: 2,193.00

Close Date: 09/21/2009

Problem?

Brakes on the Quint are VERY bad (loose and slow to engage.) I have to depress the brake pedal practically to the floorboard to get them to react. Thanks. Q47

Task performed:

Parts

Quantity

1. Chkd brakes-still abt 55-60% material left; fnd Jake brake on med w/trans retarder off; chkd adjustment & turned on trans retarder; all ok.
2. Hi-temp coolant light came on; chkd coolant level-eng fan opn; unplugged sensor on chk connection; light stayed off.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V25475

In Date: 08/12/2009

Meter Reading: 2,125.00

Close Date: 09/30/2009

Problem?

Right Telescoping scene light is out. Q-47

Task performed:

Parts

Quantity

1. Rep brkn cab release cable.
2. Rep rear spotlight that was not working.
3. Adj ladder cables. j

NO PARTS USED

Workorder: V25721

In Date: 08/23/2009

Meter Reading: 2,162.00

Close Date: 09/30/2009

Problem?

Front Right spot light and Right Telescope light out. Q47

Task performed:

Parts

Quantity

- Jake brake inop; rep bad connection on switch. j

NO PARTS USED

Workorder: V26458

In Date: 09/25/2009

Meter Reading: 24,930.00

Close Date: 09/30/2009

Problem?

SMOKE FROM ENGINE, A/C INOP, LADDER NOT STOW LIGHT ON, Q-47

Task performed:

Parts

Quantity

1. A/C inop; fnd condensor fans inop; rep bad connection.
2. Ladder light stays on; fnd bad connection. j

NO PARTS USED

Workorder: V25709

In Date: 08/22/2009

Meter Reading: 2,134.00

Close Date: 10/01/2009

Problem?

Right scene light burnt out. Q47

Task performed:

Parts

Quantity

1. Rep short in R/side spotlight.
2. Air leak at rear of truck; fnd no leaks at this time. j

J254HALOGEN BULB 1000 WATT WPB

1

Q1500T3/CL-1BULB QUARTZ 120V

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V26436

In Date: 09/24/2009

Meter Reading: 24,930.00

Close Date: 10/08/2009

Problem?

UNIT WONT START Q47

Task performed:

Parts

Quantity

1. Travel to Stn47; attempted fo find no start problem; cld not find; truck started on its own.
2. Assist Rob with no start. Murray

NO PARTS USED

Workorder: V26228

In Date: 09/14/2009

Meter Reading: 24,769.00

Close Date: 10/22/2009

Problem?

ON CALL Q47 DOOR OPEN LT 10-7

Task performed:

Parts

Quantity

1. Door open lite on-fnd bad grnd.
2. Ladder light stahys on; rep connection at ladder switch. j

NO PARTS USED

Workorder: V26806

In Date: 10/10/2009

Meter Reading: 2,264.00

Close Date: 10/27/2009

Problem?

There's a screw in the driver outer rear tire. Q47

Task performed:

Parts

Quantity

- Screw in L/R/O tire; rem screw - no leak or DMG. j

NO PARTS USED

Workorder: V26972

In Date: 10/19/2009

Meter Reading: 25,375.00

Close Date: 10/27/2009

Problem?

ON CALL WONT START Q 47

Task performed:

Parts

Quantity

- Chk starting sys btry fault; chk fuel sys; no fault; chk ECM power failure; btry chk; replc, install (6) btrys; did A-inspection prior to release to crew.

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

6

HP-31DBATTERY 950CCA HP-31D

6



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V26518

In Date: 09/28/2009
Close Date: 11/06/2009

Meter Reading: 2,239.00

Problem?

dripping water under quint. q47

Task performed:

- 1. Adj pump packing.
- 2. Rebuilt primer valve. j

Parts

Quantity

538028052VALVE PRIMER PUMP W/HARDWARE

1

Workorder: V27167

In Date: 10/26/2009
Close Date: 11/16/2009

Meter Reading: 25,731.00

Problem?

replace front tires callaghan

Task performed:

- Replc frnt tires - Callaghan j

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V27396

In Date: 11/03/2009
Close Date: 11/16/2009

Meter Reading: 25,816.00

Problem?

replace rear tires at 43 callaghan

Task performed:

- Replc rear tires at Stn43 - Callaghan j

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V27695

In Date: 11/16/2009
Close Date: 11/30/2009

Meter Reading:

Problem?

wont start Q47

Task performed:

- Fnd btrys dead; recharged/tested btrys; fnd trk not plugged in. j

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V23472

In Date: 05/22/2009
Close Date: 12/01/2009

Meter Reading: 21,374.00

Problem?

OUTRIGGER LIGHT ON, Q-47

Task performed:

done on inspection

Parts

Quantity

NO PARTS USED

Workorder: V27232

In Date: 10/28/2009
Close Date: 12/04/2009

Meter Reading: 25,731.00

Problem?

ELECTRICAL SMELL IN CAB Q47

Task performed:

Smoke in cab; fnd marker light shorted out. j

Parts

Quantity

NO PARTS USED

Workorder: V27242

In Date: 10/28/2009
Close Date: 12/08/2009

Meter Reading: 2,319.00

Problem?

you may have this request already, but the right telescope scene light is burnt out. Thank you. q 47

Task performed:

Replcd bulb in unit. j

Parts

Quantity

NO PARTS USED

Workorder: V27432

In Date: 11/04/2009
Close Date: 12/08/2009

Meter Reading: 2,326.00

Problem?

Need new windshield wipers on Q47

Task performed:

Truck making noise frm frame; grease truck & road testd. j

Parts

Quantity

50-24WIPER BLADE - KME

2



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V27566

In Date: 11/10/2009

Meter Reading: 27,566.00

Close Date: 12/08/2009

Problem?

Instruct aerial operators about lubrication information Q47

Task performed:

Parts

Quantity

1. dropped off manuel for ladder.
2. Adj ladder cables. j

NO PARTS USED

Workorder: V27602

In Date: 11/12/2009

Meter Reading: 2,361.00

Close Date: 12/08/2009

Problem?

driver seat, sits low and won't stay high. adjusted it and when i sit down it sinks down too low. asap thanks.

Task performed:

Parts

Quantity

Unit was rep by South shop. j

NO PARTS USED

Workorder: V26925

In Date: 10/16/2009

Meter Reading: 2,286.00

Close Date: 12/09/2009

Problem?

FRONT TRASH LINE VALVE LEAKS q47

Task performed:

Parts

Quantity

1. Readj linkage on trash line.
2. Rep right side spotlight that was out. j

NO PARTS USED

Workorder: V27683

In Date: 11/16/2009

Meter Reading: 2,361.00

Close Date: 12/09/2009

Problem?

One of three (center) emergency LED light covers missing at base of aerial ladder, faces rear to traffic. No broken plastic found. Q47

Task performed:

Parts

Quantity

Rep rear lens. j

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V27922

In Date: 11/24/2009

Meter Reading: 26,554.00

Close Date: 12/11/2009

Problem?

replace windshield q 47 cvag auto glass

Task performed:

Replc windshield Q47 - CharliesAuto Glass j

Parts

Quantity

NO PARTS USED

Vendor?: CHARLIES AUTO GLASS



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V27940

In Date: 11/25/2009

Meter Reading: 26,554.00

Close Date: 01/04/2010

Problem?

C INSPECTION AND REPAIRS AS NEEDED Q47 SEE ATT. UL REPAIRS

Task performed:

Parts

Quantity



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

C-Inspection	101331605QUINT COOLANT RES CAP	2
2. Adj load minder for tip load.	1229F4634SKIT RING/LOCK WASHER	2
3. Rem ext cyl for rebuild.	15W40BSYN OIL BULK QTS	40
4. Started rear brakes	33063FUEL FILTER ONAN	1
5. Rem seat belts	51064OIL FILTER ONAN	1
6. Replc hold opens	91388906 VALVE KIT 2.5 IN AKRON	1
7. Finished replc rear brakes/drums	C10FILTER Q47	1
8. Svc T-case	CA7230WA10116 AIR FILTER 46893 WIX	1
9. Replc PTO seal	KIT9081BRAKE HARDWARE KIT	2
10. R/R trans cooler lines	16302RETAINER CLIP	6
11. Rem PS fittings	EAA-8350-60UGSS6557UP STRUT-LIFT	1
12. Replc hyd filter	EAA-8350-90UGSS6558UK STRUT-LIFT	5
13. Reinstalled rebuilt cyl	1654-8FERRULE .718	4
14. Adj all aerial cables	605-2HOSE END-FEMALE	3
15. Adj waterway relief	1893BULB	1
16. Chk wtrway swivel	434WDLAMP	1
17. Lube side of aerial stablizr	50-24WIPER BLADE - KME	2
18. Lube ladder sections	3202099SEAL WITH RACE QUINT	2
19. CInd/lube wtrway	401581GASKET AXLE FL80 R002435	2
20. Chkd torq turntblc bolts	3219F4972-TDIAMOND TREATED BRAKE DRUM QUINT	2
21. R/R ft trash line valve	FT4471BD-TDIAMOND TREATED BRAKE REAR SHOES	4
22. Installed/adj new SCBA hldrs	349415HOSE AND FITTING	1
23. Lube pump pnl slideout step	47913MARKER LIGHT LED NEWER QUINTS	1
24. Wire dead wires	854003-012SEAT BELT 3 POINT QUINTS	2
25. Rep lts compt	98032R 41032-3 RED REFLECTOR OVAL REFLECTOR	1
26. Rem mrkr lt asy	B480AREFLECT-AMBER	1
27. Install S/S plug cab door	6819634283068-1963428-30 LENS CLR	1
28. R/R cab dash A/C	7020228R/S WINDSHIELD QUINT AND S/O	1
29. R/R (2) body reflectors	83631HYD CLY REPAIR	2
30. Rem lddr cntrl pnl rear	91378905 VALVE KIT 2 IN AKRON	1
31. R/R wpr blades	KR-CCLCATHODE COMPARTMENT LIGHT	2
32. Reinstall hdlr	P1147GFUEL FILTER 33120 WIX DELCO TP916	1
33. R/R cross lay nets	PH47 51758 L/F PH725 OIL FILTERL	1
34. Help w/cab lift elec cntrls	PH7405 51971 OIL FILTER WIX	2
35. Help w/jumpline vlv	PS683033442 FUEL FILTER	1
36. Mix/fill w/wshr fluid reservoir	S775COUPLER	1
37. Chk wiring steer column	S777COUPLING NIPPLE	1
38. Chk wiring both air guages	TG-GSK-ASEAL KIT PTO	1
39. Quality cntrl chk		
40. Sec tool hldrs in L-1 compt		
41. Replc ft seat belts		
42. Chkd trans codes		
43. Monitor did not mov left/right, lube		
44. Sec coat hooks		
45. Sec door hndls/cab		
46. T-shoot/rep cab lift sys		
47. Tightened lines to eng cooler		
48. Replc coolant resv cap.		
49. Replc heat sensors		
50. Rebuilt #4 discharge vlv.		
51. Replc LF/rear A/C filters		
52. Filled wtr tank & ran pump		



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V28618

In Date: 12/28/2009

Meter Reading: 27,055.00

Close Date: 01/12/2010

Problem?

RAM FAN STALLS AND RUNS ROUGH

Task performed:

1. Ram fan stalls; replcd failed plug & clnd carb (will have Regan repair.
2. Ram fan feet worn; replcd feet.
3. Pull start not retracting at times; needs a new part-spring binding; remnt pull starter; still acts up sometimes. j

Parts

Quantity

BPR6ESSPARK PLUG 7131

1

Workorder: V27724

In Date: 11/17/2009

Meter Reading: 26,250.00

Close Date: 01/13/2010

Problem?

chain saw oil cap inop Q47

Task performed:

- Replcd cap on chain saw & adj carb. j

Parts

Quantity

NO PARTS USED

Workorder: V27893

In Date: 11/24/2009

Meter Reading: 26,554.00

Close Date: 01/13/2010

Problem?

repair coolant leak Q47

Task performed:

1. Press tested for coolant leak & rep leaks.
2. Rear A/C warm; cln roof mntd condensor fans & tested. j

Parts

Quantity

NO PARTS USED

Workorder: V28310

In Date: 12/13/2009

Meter Reading: 2,388.00

Close Date: 01/15/2010

Problem?

Driver compartment door gas shock mount (aluminum) broke. q47

Task performed:

- Rep drivers compt door piston. j

Parts

Quantity

101305001BRACKET LEFT DH0008-5

1

101305002DH0007-5 BRACKET RIGHT

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V28370

In Date: 12/15/2009
Close Date: 01/15/2010

Meter Reading: 2,388.00

Problem?

Overhead panel containing electronics is leaking water and Officer side windshield wiper stopped working. Q47

Task performed:

Parts

Quantity

Resealed top roof. j

NO PARTS USED

Workorder: V28434

In Date: 12/17/2009
Close Date: 01/15/2010

Meter Reading: 26,554.00

Problem?

REPAIR AIR LEAK Q47

Task performed:

Parts

Quantity

Traced out air leaks & rep. j

NO PARTS USED

Workorder: V29229

In Date: 01/19/2010
Close Date: 02/11/2010

Meter Reading: 27,812.00

Problem?

on call no power to tp of ladder q47

Task performed:

Parts

Quantity

Fnd bad connection at relay board. j

NO PARTS USED

Workorder: V28822

In Date: 01/05/2010
Close Date: 02/22/2010

Meter Reading: 2,439.00

Problem?

Hex bolt stuck in tread surface of front driver side tire. Unknown depth. Not losing air. Q47

Task performed:

Parts

Quantity

Rem bolt frm tire & chkd tire for losing air & chkd ok. j

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V28901

In Date: 01/07/2010
Close Date: 02/22/2010

Meter Reading: 2,439.00

Problem?

federal Q siren malfunctioning

Task performed:

tested unit & tested ok. j

Parts

Quantity

NO PARTS USED

Workorder: V29688

In Date: 02/03/2010
Close Date: 03/01/2010

Meter Reading: 28,341.00

Problem?

A/C NOT WORKING PROPERLY BLOWING HOT AIR. q47

Task performed:

Travel to Stn47. Chk A/C on Q47 low on freon. j

Parts

Quantity

NO PARTS USED

Workorder: V30065

In Date: 02/19/2010
Close Date: 03/18/2010

Meter Reading: 29,064.00

Problem?

generator wont start q 47 on call

Task performed:

Gen not starting; rep fuel line that was kinked. j

Parts

Quantity

NO PARTS USED

Workorder: V29304

In Date: 01/20/2010
Close Date: 03/19/2010

Meter Reading: 2,502.00

Problem?

speaker at end of aerial ladder is not working. thankyou Q47

Task performed:

Rep speaker at tip of ladder that was not working. j

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V29404

In Date: 01/25/2010
Close Date: 03/19/2010

Meter Reading: 27,945.00

Problem?

bulb burnt out on large quarts flood light located just behind cab on officer side q47

Task performed:

Air leak at officers seat; rep air line that was leaking.

Parts

Quantity

NO PARTS USED

Workorder: V29566

In Date: 01/31/2010
Close Date: 03/19/2010

Meter Reading: 25,219.00

Problem?

quartz bulb in flood light located behind cab on officer side burnt out Q47

Task performed:

Rep 110 spotlight that was out. j

Parts

Quantity

NO PARTS USED

Workorder: V29769

In Date: 02/06/2010
Close Date: 03/19/2010

Meter Reading: 28,400.00

Problem?

driver side low beam headlight out on Q47

Task performed:

Rem light bezel & installed new headlight. j

Parts

Quantity

NO PARTS USED

Workorder: V29928

In Date: 02/12/2010
Close Date: 03/19/2010

Meter Reading: 29,755.00

Problem?

Right Rear discharge gauge not functioning. Q47

Task performed:

Tested gauge & fnd no problem with gauge. j

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V30368

In Date: 03/02/2010
Close Date: 03/26/2010

Meter Reading: 29,458.00

Problem?

the quartz flood light in front of truck over drivers windshield is burnt out or not working. there is also one burnt out on officer side i back of cab that was reported in past but not fixed Q47

Task performed:

Replcd button on vista screen. j

Parts

Quantity

OK00-1957-00KEY PAD 4 POSITION

2

OK00-1958-00KEY PAD 7 POSITION

1

Workorder: V30303

In Date: 02/28/2010
Close Date: 03/29/2010

Meter Reading: 29,458.00

Problem?

Driver side front scene light is out. Officer side telescope scene light is out. Q47

Task performed:

Replcd bulbs in lites & tsted. j

Parts

Quantity

NO PARTS USED

Workorder: V27620

In Date: 11/12/2009
Close Date: 04/14/2010

Meter Reading: 26,250.00

Problem?

Drivers air seat inop Q47

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V30509

In Date: 03/06/2010
Close Date: 04/21/2010

Meter Reading: 29,679.00

Problem?

Aerial "up down" toggle at tip of ladder is broke. //// Speaker at tip not working. /// Officer intake Vent is loose. //// Driver compartment hinge broken //// Medic compartment door hinge broken //// Q47 Thanks

Task performed:

Mounted all loose equipment. j

Parts

Quantity

5269LPVM-5 SM MOUNT

10

55021-07SWITCH

1

8126482-2106 TOGGLE GUARD

1

J254HALOGEN BULB 1000 WATT WPB

2

LPVM-7LG MOUNT

2

Q1500T3/CL-1BULB QUARTZ 120V

2



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V30566

In Date: 03/08/2010
Close Date: 04/21/2010

Meter Reading: 29,755.00

Problem?

flood light over cab on driver side is out. was previousl reported on MARCH 2 Sta47

Task performed:

Replc 110 lith5 & tested. j

Parts	Quantity
05-17223-000CAP RADIATOR 10 LB	1
435 VALVE CAP	2
K080590AC BELT WPB	2
K100540USE K100540HD BELT WPB	1
R950012REGENERATION VALVE WABCO	1
S690AIR CHUCK	1
S777COUPLING NIPPLE	1
UMVS254411STRAP 46 IN	1
WAT61403STRAINER 6 IN	1

Workorder: V30599

In Date: 03/09/2010
Close Date: 04/21/2010

Meter Reading: 29,924.00

Problem?

TANK FILL LEVER WILL NOT CLOSE COMPLETELY. THANKS. Q 47

Task performed:

Readj tank fill linkage. j

Parts	Quantity
NO PARTS USED	

Workorder: V30600

In Date: 03/09/2010
Close Date: 04/21/2010

Meter Reading: 29,924.00

Problem?

Spoke to Tommy about mounting tool hooks and straps for misc equipment and unsecured extinguishers, etc. Would like to schedule Tommy for Friday March 12th if it's okay and possible. Thanks in advance!! STa 47

Task performed:

Mounted loose equipment.

Parts	Quantity
NO PARTS USED	



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V30609

In Date: 03/10/2010 Meter Reading: 29,924.00
Close Date: 04/21/2010

Problem?

q47 tank fill valve jammed,will not close

Task performed:

Rep tank to pump valve that was not closing. j

Parts

Quantity

NO PARTS USED

Workorder: V30696

In Date: 03/12/2010 Meter Reading: 29,924.00
Close Date: 04/21/2010

Problem?

POSSIBLE SHORT BETWEEN WINDSHIELD WIPER AND ENGINE SHUTOFF. Q47

Task performed:

FNP w/wipe switch. j

Parts

Quantity

NO PARTS USED

Workorder: V30372

In Date: 03/02/2010 Meter Reading: 29,458.00
Close Date: 04/22/2010

Problem?

repair tire- looses air L/R inner tire Q47(outside agency-boulevard tire)

Task performed:

Repair tire Q57 - Boulevard j

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD TIRE

Workorder: V30819

In Date: 03/17/2010 Meter Reading: 30,121.00
Close Date: 05/01/2010

Problem?

both quartz flood lights over fron windshield on driver and officer side are out.Q47

Task performed:

replcd bulb in L/side lite & rep wire. j

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V30897

In Date: 03/20/2010
Close Date: 05/01/2010

Meter Reading: 30,438.00

Problem?

BOTH QUARTZ FLOOD LIGHTS OVER CAB ON FRONT OF QUINT ARE BURNT OUT OR BROKEN Q47 2nd request

Task performed:

All lites have been rep. j

Parts

Quantity

NO PARTS USED

Workorder: V30900

In Date: 03/20/2010
Close Date: 05/01/2010

Meter Reading: 30,438.00

Problem?

AIRCONDITIONING BLOWING WARM AIR Q47 or R47?

Task performed:

Recharged A/C on cab for rescue. j

Parts

Quantity

NO PARTS USED

Workorder: V30924

In Date: 03/22/2010
Close Date: 05/01/2010

Meter Reading: 30,438.00

Problem?

lightbox charger at FF seat needs replacement, not charging unless it sits just right. Often the light dies out unless you shake it in the box charger base.q47

Task performed:

Tested lite for charging & tested ok. j

Parts

Quantity

NO PARTS USED

Workorder: V30930

In Date: 03/22/2010
Close Date: 05/01/2010

Meter Reading: 30,438.00

Problem?

speaker at the tip of quints' ladder is not working. We can hear at the turn table, but the person at the tip cannot here the turn table operator. Q47

Task performed:

Tested intercom & rep connection 7 tested ok. j

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V30935

In Date: 03/22/2010

Meter Reading: 30,438.00

Close Date: 05/01/2010

Problem?

front quartz flood lights out Q47

Task performed:

Replc bulb in quartz lite. j

Parts

Quantity

2220-10SLIDE 10 IN

2

HLD39917DC23-5011 50 # HOLD-OPEN RESCUE

2

J254HALOGEN BULB 1000 WATT WPB

2

Q1500T3/CL-1BULB QUARTZ 120V

4

Workorder: V31286

In Date: 04/05/2010

Meter Reading: 30,848.00

Close Date: 05/01/2010

Problem?

Front AC blowing hot air. Q47

Task performed:

recharged sys & tested. j

Parts

Quantity

NO PARTS USED

Workorder: V31382

In Date: 04/09/2010

Meter Reading: 31,011.00

Close Date: 05/01/2010

Problem?

Standing at the controls for the aerial ladder we can hear people at the tip of the ladder, but they can't hear the person at the controls, when pushing in the button q47

Task performed:

Chkd opn of intercom & tested ok. j

Parts

Quantity

0332002156USE 380830 RELAY 12V 75A RLY5491

1

Workorder: V31469

In Date: 04/12/2010

Meter Reading: 31,083.00

Close Date: 05/01/2010

Problem?

a/c out. blows hot air. summers coming. q47

Task performed:

Replc ___ switch & rep condensor fans. j

Parts

Quantity

RD546400P11-2630 SWITCH BINARY

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V31582

In Date: 04/16/2010

Meter Reading: 31,083.00

Close Date: 05/01/2010

Problem?

repair fuse panel

Task performed:

Parts

Quantity

Rep fuse panel that was falling off. j

NO PARTS USED

Workorder: V31855

In Date: 04/28/2010

Meter Reading: 29,064.00

Close Date: 05/04/2010

Problem?

door ajar alarm staying on Q47 (on call)

Task performed:

Parts

Quantity

Traced problem; fnd wtr inside all connectors; clnd/tested. j

NO PARTS USED

Workorder: V31991

In Date: 05/04/2010

Meter Reading: 31,522.00

Close Date: 05/17/2010

Problem?

Check body damage to left rear of truck for possible in house repair.

Task performed:

Parts

Quantity

Reset sideok tkj weld up brkn beam; rem SCBA tube & E11 outlet; problem is that safety pin brkt is hitting body side & got stuck under beam when going out; rem pin holder; rem pin on top of outrigger; paint repairs. j

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V31987

In Date: 05/04/2010

Meter Reading: 31,522.00

Close Date: 05/19/2010

Problem?

Check body damage to Q47.

Task performed:

Parts

Quantity

Call dispatch, they called Stn47; they said the quint was damaged by pin on stabilizer; it ____ inner fender out by driver; said it wld not be a problem to driver he did not want to use ladder so I called DC4.

NO PARTS USED

Chuck Lupo said he wld go look & let me know if I needed to come to Stn47; when I talked to him again he said they cld use for eng & I did not need to come over; I called dispatch & let them know.

Workorder: V32069

In Date: 05/07/2010

Meter Reading: 31,522.00

Close Date: 05/20/2010

Problem?

Aerial master would not articulate LEFT and RIGHT from turn table. Would from tip. I applied force by hand while operated from turntable to free jam. Motion sounds like bad bearing. May seize again once dry. q47

Task performed:

Parts

Quantity

1. Monitor having troble moving extreme left/right; rem cvr for bearing & tried spraying WBO into bearing aggr. stail sluggish.

NO PARTS USED

2. Monitor tip cracked - need to order new tip.

3. Went to stn47 to get off waterway monitor - not at stn.

j

Workorder: V32258

In Date: 05/18/2010

Meter Reading: 31,522.00

Close Date: 05/28/2010

Problem?

REPAIR WIPER Q47

Task performed:

Parts

Quantity

Rem R/side wiper motor, swtch brkt & shaft to new motor; reinstall new wiper motor. j

7605-7441299809 MOTOR WIPER RIGHT SIDE

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V30919

In Date: 03/21/2010
Close Date: 06/04/2010

Meter Reading: 30,438.00

Problem?

The left side Rubberized Rung Tread Grip tore off one of the rungs on the fly section of the aerial during a training exercise. An appliance dropped down while the sections were extending. Property Report filed#P10-048 Q47

Task performed:

1. Install handle on rear of handle.
2. Rear LED light brkn; replcd light. j

Parts	Quantity
39008USE 39045 KIT	1
752-0011RUNG COVER 8.5 KIT	1
774-0344RUNG CLIP	1
FREIGHTSHIPPING CHARGES	25
L31HRFNBEACIN SUPER LED	1

Workorder: V31918

In Date: 05/02/2010
Close Date: 06/04/2010

Meter Reading: 31,522.00

Problem?

Outrigger bent frame on the driver side. Q47

Task performed:

- C/O - outrigger will need to come to shop. j

Parts	Quantity
NO PARTS USED	

Workorder: V32863

In Date: 06/14/2010
Close Date: 06/21/2010

Meter Reading: 32,970.00

Problem?

ON CALL DOOR OPEN LT ON Q47

Task performed:

- Door open light on; rep left rear step switch. j

Parts	Quantity
NO PARTS USED	

Workorder: V32865

In Date: 06/14/2010
Close Date: 06/21/2010

Meter Reading: 32,970.00

Problem?

ON CALL A/C 10-7 Q47

Task performed:

- Recharge A/C & tested. j

Parts	Quantity
NO PARTS USED	



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V32472

In Date: 05/27/2010
Close Date: 06/28/2010

Meter Reading: 31,522.00

Problem?

Q47 OVERHEATED AFTER LONG DAY OF TRAINING. QUINT IS FINE NOW. q47

Task performed:

Road tested & chk temp; tested ok. j

Parts

NO PARTS USED

Quantity

Workorder: V32689

In Date: 06/07/2010
Close Date: 06/28/2010

Meter Reading: 32,970.00

Problem?

On call not charging Q47

Task performed:

Replcd alternator that was not charging. j

Parts

A0014949PA4949PA/4962 320 AMP UPGRADE SADDLE MC

1

Quantity

Workorder: V32727

In Date: 06/08/2010
Close Date: 06/28/2010

Meter Reading: 32,970.00

Problem?

AC is blowing hot Q47

Task performed:

1. Coolant leak; replc cap & brass fittings.
2. A/C inop; recharged A/C. j

Parts

F6DZ-8100-A9C3Z8101B RADIATOR CAP 10238 STANT

1

Quantity

Workorder: V33212

In Date: 06/29/2010
Close Date: 07/01/2010

Meter Reading: 32,970.00

Problem?

on call q 47 door alarm on

Task performed:

Disconnected switch; will order new one. j

Parts

NO PARTS USED

Quantity



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V33466

In Date: 07/12/2010 Meter Reading: 32,970.00
Close Date: 07/19/2010

Problem?

OJN CALL TIRE LOW ON AIR Q 47

Task performed:

Parts

Quantity

Tire valve extensions leaking; tried to tighten; had to take off. j

NO PARTS USED

Workorder: V32856

In Date: 06/13/2010 Meter Reading: 32,970.00
Close Date: 07/20/2010

Problem?

Spreaders plastic piece that operates the spreaders is stripped. We have to pull back the plastic cover and grip it on the metal to turn it to work. thx. Also, right telescope light is still out. thx. Q47

Task performed:

Parts

Quantity

Cabv A/C inop; recharged sys. j

NO PARTS USED

Workorder: V33676

In Date: 07/20/2010 Meter Reading: 32,970.00
Close Date: 07/20/2010

Problem?

need tire hose extensions (parts only) Q47

Task performed:

Parts

Quantity

Parts only j

AMH-1AMH-1 VALVE EXTENSION

1

Workorder: V32870

In Date: 06/14/2010 Meter Reading: 32,970.00
Close Date: 07/21/2010

Problem?

A/C is not working properly. it's hot in the truck q47

Task performed:

Parts

Quantity

Recharged A/C & rep condensor fans. j

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V33477

In Date: 07/12/2010
Close Date: 07/22/2010

Meter Reading: 32,970.00

Problem?

RUBBER CLAMP THAT SECURES AXE TO TIP OF LADDER ON Q47 BROKE OFF. AXE NOT SECURED PROPERLY. Q47

Task performed:

Get parts at shop; drive to Stn47; Q47 installed axe lock on tip of ladder; completed ok. j

Parts

Quantity

5269LPVM-5 SM MOUNT
LPVM-7LG MOUNT

1
1

Workorder: V33347

In Date: 07/06/2010
Close Date: 07/28/2010

Meter Reading: 32,970.00

Problem?

tire tread worn very low on outer rear tire officer side of Q47. It is a Bridgestone 12.00R24

Task performed:

Went to 47; chkd rear tires on Q47; (3) out of (4) worn to wear bars; report to Ehrke needs (4) tires

Parts

Quantity

NO PARTS USED

Workorder: V33435

In Date: 07/09/2010
Close Date: 08/02/2010

Meter Reading: 32,970.00

Problem?

LAST SHIFT Q47 HAD 4 NEW REAR TIRES PUT ON IT. THE NEW VALVE STEMS ARE MUCH TO SHORT AND CAN NOT CHECK PRESSURE.

Task performed:

Call Boulevard, spoke w/Ron; he will get the extensions put on. j

Parts

Quantity

NO PARTS USED

Workorder: V33448

In Date: 07/10/2010
Close Date: 08/09/2010

Meter Reading: 32,970.00

Problem?

there are three reflectors on the rear bottom of turntable - the right cover is broken. thank you - 47 Q47

Task performed:

Rep on WO 33623. j

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V33656

In Date: 07/19/2010 Meter Reading: 32,970.00

Close Date: 08/09/2010

Problem?

Q47 IS READY FOR PICK UP AT ST47 FOR PM. WE NOTICED THAT CLEAR COLD WATER WAS LEAKING EXCESSIVELY FROM THE UNDERCARRIAGE WHEN WE WERE SWAPPING OUT TONIGHT.

Task performed:	Parts	Quantity
Condensation frm A/C in rear of cab. j	NO PARTS USED	

Workorder: V31020

In Date: 03/24/2010 Meter Reading: 30,438.00

Close Date: 08/11/2010

Problem?

Several pieces of electrical cords need repairs: broken threads, outlets set too far in to connect. One D light has broken handle an frame. Need one more black hook to hang one more extension cord.

Task performed:	Parts	Quantity
C/O; need plug from W. Chambers. j	NO PARTS USED	

Chkd equipments - all items in place; none unreolvsd.
ja

Workorder: V32585

In Date: 06/01/2010 Meter Reading: 31,522.00

Close Date: 08/12/2010

Problem?

1. Right rear step sensor malfunction. Keeps beeping even when step is up. Old issue but never been fixed. 2. We need better / faster window wipers for Quint 47. They are to slow. Not safe in heavy pouring rain. Q47

Task performed:	Parts	Quantity
1. Air leak; traced & rep.	NO PARTS USED	

2. Rep door open sensor on step that had bad grnd.
ja

Workorder: V33350

In Date: 07/06/2010 Meter Reading: 32,970.00

Close Date: 08/13/2010

Problem?

replace rear tires q47 boulevard

Task performed:	Parts	Quantity
Replc rear tires Q47 - Boulevard ja	NO PARTS USED	

Vendor?: BOULEVARD TIRE



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V33152

In Date: 06/25/2010
Close Date: 08/17/2010

Meter Reading: 32,970.00

Problem?

Q47 lighting system is malfunctioning. Head lights are defaulting in the off position and rear lights shut off while driving to call. Also Screen is missing from one intake from trimese to water tower. Q47

Task performed:

Chkd sys & all teted ok. ja

Parts

NO PARTS USED

Quantity

Workorder: V33189

In Date: 06/28/2010
Close Date: 08/17/2010

Meter Reading: 32,970.00

Problem?

Closing stabilizer bar broke off door. Q47

Task performed:

Installed new brkt for door open spring. ja

Parts

HLD39917DC23-5011 50 # HOLD-OPEN RESCUE

Quantity

1

Workorder: V33202

In Date: 06/28/2010
Close Date: 08/17/2010

Meter Reading: 32,970.00

Problem?

Door alarm inside cab goes off without a door being open. Q41

Task performed:

Fnd bad sensor; rem/installed new one. ja

Parts

NBG818GM60A0360000161 PROXIMIITY SWITCH

Quantity

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V33623

In Date: 07/19/2010

Meter Reading: 34,363.00

Close Date: 09/01/2010

Problem?

C inspection and repairs q47

Task performed:

Parts

Quantity



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

C-inspection	0769027STRAINER 2.5 IN	1
2. Rear marker lite out; install new bulb	101443028101443030 HORN PLATE	1
3. Wndshld spray tip brkn-install new	15W40BSYN OIL BULK QTS	40
4. Telescopic light blown; replc w/new	FREIGHTSHIPPING CHARGES	13
5. R/marker light holder damage; rep	P1147GFUEL FILTER 33120 WIX DELCO TP916	1
6. L/rear, R/frnt, R/rear door panel msng screws; correct fault	PH7405 51971 OIL FILTER WIX	2
7. Driver window cracked/door lock loose, handrail loose; secure/fasten	PS683033442 FUEL FILTER	1
8. R-1 loose tray, R-5 loose tool holder; secure	SWT54915SWIT-251240 SW ROCKER SPST ON/OFF GREE	1
9. Attic ladder heat sensor expired; rem sticker; install new	16-3443CAP-BLUE R134 NEW #5574	2
10. Grease spring shackle	23920-9213UTILITY PUMP	1
11. L/side aerial flip down setp sencor out of adjustment; adj	33063FUEL FILTER ONAN	1
12. R-2 compt door hold open damage; install new	51064OIL FILTER ONAN	1
13. license plate lite 10-7; isntall new bulb.	35200-RLIGHT MARKER LED RED	1
14. Turntable LED lens brkn; install new	35200-YLIGHT MARKER LEDAMBER	1
15. L&R side marker light; rewire/install bulbs; reassem side moldings	5004049GOV CHK VALVE KIT M2	1
16. Elect failure compt lite node; dia fault	5008414CARTRIDGE DC100	1
17. Elect failure fault node 7; low output; contact mfrf for node download specs L-4 compt	K022105PURGE VALVE AD-IP-IS	1
18. Frnt A/c cool; evac freon-chk/leak; fitting leaks; replc bac 0-ring.	5582-10 82-2111 GROTE ON-OFF WEATHERPROOF	2
19. work on compt lite compt light problem	67BULB 12 VOLT	1
20. Rear A/C fan speed 10-7; fnd loose switch connection at panel; A/C filter clogged-install new	KR-CCLCATHODE COMPARTMENT LIGHT	1
21. Condensor fans cable chaffed & msng hold down bolts; rep cables, sec/replc msng bolts	6819634283068-1963428-30 LENS CLR	1
22. A/C charging port-chk for leak; none fnd	HLD374211 IN HOLD-OPEN 30LB	1
23. Svc btrys & test	98032R 41032-3 RED REFLECTOR OVAL REFLECTOR	1
24. Fix cab lift plug wire	HA49102C2-32-15 LATCH NON LOCKING	1
25. Rep air line; replc fitting at compressor	PVG-KITORING KIT	1
26. Svc gen		
27. Auto lube svc		
28. Exh pipe wrap torn & clmp loose; rem old wrap/tighten exh clmp		
29. Svc air dryer		
30. Rem bolts frm PTO & seal thrds; tighten bolts		
31. Trans fluid on retarder; cln/inspect gskt/nut/bolt		
32. install protection hose/clmp on frnt jump line		
33. Work on compt lighting failure		
34. L-4 fault-incorrect wiring; correct		
35. L/rear aerial step rail loose-sec.		
36. Assist w/ foam fill sys		
37. Dia foam fill pump failure; no pulling vac to fill sys		
38. R/R steer column		
39. Asst w/ dia foam fill pump		
40. Chk trans code to 703; inactive		
41. Install msng tri-mess strainer		
42. Air PSI; dia fault; replc air gov		
43. Per Ehrke, diss steering column		
44. Aired pump; chk/leaks; fnd bad fitting; replc, perform		



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

- dry vac; test ok
- 45. Fill wtr tank; adj pump packing shaft bad
- 46. Cab lift stopped wrkng; elect ok; spread pin for better connection
- 47. Burnt fuse panel lite bars; rep/splic wires
- 48. Assist-burnt fuse panel
- 49. Put steer colum pieces back tog
- 50. Ign swtch brkn; install new
- 51. Cln ladder rung
- 52. dia cab lift lite
- 53. Jump start veh/change btrys
- 54. Dia intermittant horn
- 55. 110V out
- 56. Install msng helmet hook
- 57. Primer pump leaking-valve sticking
- 58. Dia hyd w/lifting ladder
- 59. Adj/calibrate loadminder to specs
- 60. Install horn/steering wheel parts
- 61. Reverse wires/remote cntrl of monitor
- 62. Dia cab lift problem
- 63. Apply splicing tape to ladder platform railing
- 64. Jump start uni
- 65. Drain foam pump
- 66. Cabinet latch jaming-install new latch
- 67. Adfj pump packing
- 68. Outrigger alarm going off
- 69. Low volt alarm going off
- 70. Switch up/don monitor installed backwards-correct js

Workorder: V33449

In Date: 07/10/2010 **Meter Reading:** 32,970.00
Close Date: 09/02/2010

Problem?

The new rear tires does not feel "comfortable" to ride at high speeds such as code 3. Also, the left wheel (rim) appears to be on backwards. Missing valve stems. Front tires balding as well.

Task performed:

- 1. Valve stems are on unit; all stems are secure; left rims are ok.
- 2. Frnt tires are good; this appearance is due to wear pattern associated to weight distribution & turning. js

<u>Parts</u>	<u>Quantity</u>
440-5 VALVE EXT.	2



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V34084

In Date: 08/06/2010 Meter Reading: 32,970.00

Close Date: 09/10/2010

Problem?

replace rear springs q 47 total truck

Task performed:

Replc rear springs Q47 - Total Truck j

Parts

NO PARTS USED

Quantity

Vendor?: TOTAL TRUCK

Workorder: V32455

In Date: 05/26/2010 Meter Reading: 31,522.00

Close Date: 09/15/2010

Problem?

Aerial master would not articulate LEFT and RIGHT from turn table. Would from tip. I applied force by hand while operated from turntable to free jam. Motion sounds like bad bearing. May seize again once dry. q47

Task performed:

1. Diss monitor.
 2. Work on remote control L&R backwards; look for wiring diagram.
 3. Cln/inspect monitor parts & order parts.
 4. Research elect diagram papeer for rep of platform turntable control wiring.
 5. Reassemble monitor; install on truck & test ok.
 6. Assist in installation & testing of monitor.
 7. Test monitor under press - ok.
 8. Reverse fob/stream switch on platform control area.
- j

Parts

104209FLANGE KIT
117823FLANGE BASE

Quantity

1
1

Workorder: V32255

In Date: 05/18/2010 Meter Reading: 31,522.00

Close Date: 10/04/2010

Problem?

ON CALL WIPERS 10-7 Q47

Task performed:

Wiper inop; chkd power to motor; good voltage; motor faulty. j

Parts

NO PARTS USED

Quantity



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V33179

In Date: 06/27/2010

Meter Reading: 32,970.00

Close Date: 10/04/2010

Problem?

ff head piece is having problems, when plugged in, it sounds like wind is blowing through the head piece q47

Task performed:

reported to radio shop 06/28

Parts

Quantity

NO PARTS USED

Workorder: V35251

In Date: 09/28/2010

Meter Reading: 32,970.00

Close Date: 10/18/2010

Problem?

replace front tires boulevard

Task performed:

Replc frnt tires - Boulevard j

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD TIRE

Workorder: V34945

In Date: 09/14/2010

Meter Reading: 32,970.00

Close Date: 10/20/2010

Problem?

defroster inop Q47

Task performed:

1. Chk defroster & fnd FNP w/sys.
2. installed new wiper motor. j

Parts

Quantity

5TSMACMOUNT 500 TIR SER CHROME 4

7605-7441299809 MOTOR WIPER RIGHT SIDE 1

WL2000WLA200-A00 WATER TANKVISION OLD FERR # 35: 1

WLA290-A00REMOTE LIGHT DRIVER FRS 1

Workorder: V34989

In Date: 09/21/2010

Meter Reading: 32,970.00

Close Date: 10/20/2010

Problem?

The water tank level indicators are all not working. The large LEDs on both sides of the truck are off. the one on the pump panel flashes the top half then the bottom half Q47

Task performed:

1. Recliabrated water level guages.
2. Adj ladder cables that were loose. j

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V35074

In Date: 09/20/2010

Meter Reading: 32,970.00

Close Date: 10/20/2010

Problem?

discharge "4" handle came off during operations. We have the handle. , thank you. Q47

Task performed:

Parts

Quantity

Reinstalled and tested. j

NO PARTS USED

Workorder: V35080

In Date: 09/21/2010

Meter Reading: 32,970.00

Close Date: 10/20/2010

Problem?

steering wheel horn cover loose, "popped" out. Q47

Task performed:

Parts

Quantity

1. Reinstalled horn button.
2. Chk A/C & fnd unit blowing cold. j

NO PARTS USED

Workorder: V34707

In Date: 09/02/2010

Meter Reading: 32,970.00

Close Date: 10/21/2010

Problem?

cotter pin missing from discharge #2 on Q47. Handle found on bay floor this morning by C shift. I'll look for a small nail to use temporary.

Task performed:

Parts

Quantity

1. reinstalled handle and tested. jab

NO PARTS USED

Workorder: V35364

In Date: 10/04/2010

Meter Reading: 32,970.00

Close Date: 10/25/2010

Problem?

ON CALL BELTS SQUEEL Q47

Task performed:

Parts

Quantity

1. check belts for squeel, found belts loose, adjusted belts. jab

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V35371

In Date: 10/04/2010 Meter Reading: 32,970.00

Close Date: 10/25/2010

Problem?

ON CALL LADDER MAKING NOISE Q47

Task performed:

Parts

Quantity

1. road call, check ladder for noise, checked and adjusted cables, tested ok. jab

NO PARTS USED

Workorder: V35567

In Date: 10/12/2010 Meter Reading: 32,970.00

Close Date: 10/25/2010

Problem?

Ceck out overheat alarm.

Task performed:

Parts

Quantity

1. road call, travel to station 47,check coolant level,oil&trans fluid levels, check belt and fan clutch operation, check for debris in radiator, all check ok. hook up laptop to check gauges in truck versus laptop, check ok. took truck for test drive, truck checks normal in highway and city traffic, check with retarder on, in city traffic , truck reached 225 trans temp, 222 coolant temp, 240 retarder temp, temp alarm sounded , called supervisor about problem, he was aware of problem, keep truck in service, will advise fdda of bad sensor. jab

NO PARTS USED

Workorder: V35779

In Date: 10/19/2010 Meter Reading: 32,970.00

Close Date: 11/09/2010

Problem?

*

Task performed:

Parts

Quantity

Replc alt & road tested. j

A0014949PA4949PA/4962 320 AMP UPGRADE SADDLE MC

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V35950

In Date: 10/27/2010

Meter Reading: 32,970.00

Close Date: 11/17/2010

Problem?

perform ladder certification test (outside agency-Mistras Group Inc.)

Task performed:

Parts

Quantity

Perform ladder certification test - Mistras Group j

NO PARTS USED

Vendor?: MISTRAS GROUP

Workorder: V35745

In Date: 10/19/2010

Meter Reading: 32,970.00

Close Date: 12/07/2010

Problem?

Q47 marker light.

Task performed:

Parts

Quantity

1. Marker lite shorted; rem lite asy; no part on truck.
2. Rep all melted wires in headliner.
3. Installed new marker light & tested.
4. Remntd tools in L-1 compt.
5. Adj rear door latch. j

47913MARKER LIGHT LED NEWER QUINTS

1

Workorder: V36213

In Date: 11/05/2010

Meter Reading: 36,688.00

Close Date: 12/08/2010

Problem?

Tank fill valve is problematic. Won't fully close / seems loose Q47

Task performed:

Parts

Quantity

1. Air valve leaking; replc gov & road rtested.
2. Readj tank fill valve linkage. j

5004049GOV CHK VALVE KIT M2

1

Workorder: V36294

In Date: 11/08/2010

Meter Reading: 36,816.00

Close Date: 12/08/2010

Problem?

rear brake leak. guage pulsates low. q47

Task performed:

Parts

Quantity

Road tested truck; FNP w/brakes. j

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V34873

In Date: 09/10/2010
Close Date: 12/22/2010

Meter Reading: 32,970.00

Problem?

can not close recerculation pump valve on Q47 all the way allowing foam to get in tank.

Task performed:

(1) CAN'T COMPLETELY CLOSE OFF TANK FILL VALVE CAUSING FOAM TO ENTER WATER TANK WHEN FLOWING FOAM ON Q47.

READJUSTED TANK FILL VALVE HANDLE AND TESTED OK. J.W.

Parts

Quantity

NO PARTS USED

Workorder: V35815

In Date: 10/20/2010
Close Date: 12/22/2010

Meter Reading: 32,970.00

Problem?

telescope lights out, both of them.Q47

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V36178

In Date: 11/04/2010
Close Date: 12/22/2010

Meter Reading: 36,679.00

Problem?

repair ladder report from inspection Q47

Task performed:

Parts

Quantity

PL-11005 WATERWAY RELIEF VALVE

1

Workorder: V36251

In Date: 11/07/2010
Close Date: 12/22/2010

Meter Reading: 36,769.00

Problem?

left tele light is out Q47

Task performed:

Parts

Quantity

(1) TRAVELED TO ST47 TO REPAIR A TELESCOPIC LIGHT ON Q47. PART FOR LIGHT ON ORDER.

J.W.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V35308

In Date: 10/01/2010
Close Date: 12/29/2010

Meter Reading: 32,970.00

Problem?

Make portable crosslay for Q47

Task performed:

(1) FABRICATED HOSE BED PROPS FOR Q47.
J.W.

Parts

NO PARTS USED

Quantity

Workorder: V37188

In Date: 12/15/2010
Close Date: 12/30/2010

Meter Reading: 37,887.00

Problem?

Q47 CAB DOOR OPEN FLASHING RED LIGHT, AUDIBLE AND CAB LIGHTS WILL NOT GO OFF EVEN WHEN ALL DOORS ARE CLEARLY SHUT.

Task performed:

(1) TRAVELED TO ST47 TO REPAIR DOOR ALARM ON Q47 THAT WON'T TURN OFF WHILE DOORS ARE CLOSED. TESTED ALL SWITCHES THAT WERE OK. WASN'T ABLE TO REPAIR AT THIS TIME. REMOVED RED WARNING LIGHT UNTILL REPAIRS ARE DONE.
(2) TRAVELED BACK TO ST47 AND OTHER MECHANIC(TOMMY) SHOULD WHERE THE DOOR RELAYS ARE LOCATED ON Q47. FOUND FAULTY RELAY. INSTALLED A NEW ONE. RECONNECTED THE THE RED WARNING LIGHT. OK NOW. J.W.

Parts

52-624SWITCH DOOR

Quantity

3

Workorder: V37468

In Date: 12/28/2010
Close Date: 12/30/2010

Meter Reading: 38,637.00

Problem?

Air Leak, no air horn. Q47

Task performed:

- adjust air horns
- Traced out air leak; fnd frnt suction valve leaking; R/R
- Rep rear compt door spring. j

Parts

15W40QSYN OIL QT

ALA00350-50 EXTENDED LIFE COOLANT GAL

Quantity

12

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V36729

In Date: 11/30/2010

Meter Reading: 37,509.00

Close Date: 01/03/2011

Problem?

BOX LIGHT NOT WORKING. LOCATED IN THE COMPUTER ROOM AT STATION 47.

Task performed:

Parts

Quantity

(1) TRAVELED TO ST-47 TO REPAIR BOX LIGHT CHARGER LOCATED IN THE COMPUTER ROOM OF THE STATION. CHECKED OUT AND REPAIRED, OK.

NO PARTS USED

(2) REPAIRED REAR STEP LATCH THAT WAS FALLING OFF VEHICLE.

J.W.

Workorder: V36890

In Date: 12/05/2010

Meter Reading: 37,803.00

Close Date: 01/07/2011

Problem?

IS already out of service because it has a bad collector ring. The truck also will not engage PTO. This was noticed while trying to raise ladder to get exhaust fan out from underneath. Q47

Task performed:

Parts

Quantity

Chk PTO wiring switches, etc; fnd open connector on press switch plug. j

NO PARTS USED

Workorder: V36957

In Date: 12/07/2010

Meter Reading: 37,803.00

Close Date: 01/07/2011

Problem?

on call monitor 10-7 q47

Task performed:

Parts

Quantity

FF advised manual controls inop on monitor; swap into spare. j

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V36852

In Date: 12/03/2010

Meter Reading: 37,716.00

Close Date: 01/10/2011

Problem?

can not switch ladder from rescue mode to water mode and can not work master stream nozzle at end of ladder with controls on turn table. Q47

Task performed:

1. Pull panes etc.; cC/O fuses, brkrs, relays etc., wiring; rep wiring to upper ladder controls.
2. Q&A Q47 - flow meter at upper aerial controls inop & intercom inop.
3. Q&A ladder wtr flow control frm tip & platform operates normal; flow at aerial platform panel 10-7 & intercom at platform not hearing from tip.
4. Q47 PTO/outriggers not working properly; t-shoot diverter switch; called ___; fnd cradle switch was shorting diverter valve.
5. Rep bed light. j

Parts

Quantity

091-84-022DIODE 6 AMP

3

1156BULB

1

EL-10366MICRO SWITCH XCKL1041

1

FREIGHTSHIPPING CHARGES

58

Workorder: V37229

In Date: 12/17/2010

Meter Reading: 38,025.00

Close Date: 01/11/2011

Problem?

Telescope lights not working again. On going problem for 2 years. Generator wont start from in the cabs Q47

Task performed:

Waiting for parts; ordered 10/20/10. j

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V37076

In Date: 12/10/2010

Meter Reading: 37,716.00

Close Date: 01/12/2011

Problem?

cab tilt innop, replace electrical air guages in dash with mechanical Q47

Task performed:

Parts

Quantity

(1) TRAVELED TO ST-47 TO REPAIR CAB TILT MEC. TALKED TO TOMMY ABOUT AIR GAUGE CONNECTION TO TEST SYSTEM. HE SAID THE ONLY PLACE TO HOOK UP IS AT THE FOOT VALVE ON Q47.

NO PARTS USED

(1) REMOVED ELECTRIC GAUGES AND REPLACED WITH MECHANICAL GAUGES. WIRED LIGHTS, RUNAIR LINES, MADE FITTINGS TO TAP INTO THE AIR LINE.

(2) TROUBLE SHOOT CAB TILT PROBLEM. FOUND LOOSE PLUG IN FRAME.

(3) TROUBLE SHOOT PROBLEM WITH DIVERTER VALVE. BAD LADDER BED SWITCH. J.W.

Workorder: V37386

In Date: 12/23/2010

Meter Reading: 38,360.00

Close Date: 02/07/2011

Problem?

1. federal q (button on capt panel) not working. 2. radio button (capt side) needs repair. 3. We have an air leak. You can hear it for several minutes after you shut the truck off. Q47 thank you for your work.

Task performed:

Parts

Quantity

1. Rep federal Q button that had bad grnd.

NO PARTS USED

2. Chkd for air leak; fnd no leaks. j

Workorder: V37470

In Date: 12/28/2010

Meter Reading: 38,637.00

Close Date: 02/07/2011

Problem?

FED Q ON OFFICER SIDE "PUSHED THRU" Q47

Task performed:

Parts

Quantity

Rep horn botton that fell in dash. j

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V37471

In Date: 12/28/2010 Meter Reading: 38,637.00

Close Date: 02/07/2011

Problem?

LIGHTS (WHITE / RED) ABOVE OUR HEADS (DRIVER & OFFICER) - THE WHITES ARE NOT WORKING Q47

Task performed:

Parts

Quantity

- | | |
|---|---------------|
| 1. Rep overhead light in cab; fnd bad switch. | NO PARTS USED |
| 2. Ladder cables making noise; adj ladder cables. j | |

Workorder: V37508

In Date: 12/30/2010 Meter Reading: 38,637.00

Close Date: 02/07/2011

Problem?

when pulling out of the station at full throttle the truck only revs about 1/3 of its capacity and crawls for about 100 yards, then the turbo spools up and the truck roars. I noticed the air tanks were listing 90-100 psi q47

Task performed:

Parts

Quantity

- | | |
|--|---------------|
| 1. Road tested truck & FNP with unit. | NO PARTS USED |
| 2. Rep left rear door latch that was brkn. j | |

Workorder: V38487

In Date: 02/14/2011 Meter Reading: 41,270.00

Close Date: 02/24/2011

Problem?

Top lightbulb on tank water level is out on pump panel indicator. Large red,yellow,green, blue LED display on cab is working properly.q47

Task performed:

Parts

Quantity

- | | |
|---|---------------|
| Adj all ladder cables & greased ladder. j | NO PARTS USED |
|---|---------------|

Workorder: V37821

In Date: 01/15/2011 Meter Reading: 39,596.00

Close Date: 02/25/2011

Problem?

need tires real soon. low tread mostly on right side. Q47 Also, L5 door hinge broke. Thank you for your work. - 47

Task performed:

Parts

Quantity

- | | |
|---|---------------|
| 1. installed new door hinge in L-5 | NO PARTS USED |
| 2. Will have all rear tires replaced. j | |



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V38105

In Date: 01/27/2011

Meter Reading: 41,013.00

Close Date: 02/25/2011

Problem?

24v dewalt battery is damaged...will need to be replaced....this is needed for the stryker stretcher as well as the recipricating saw on Q47..

Task performed:

dropped off new btry. j

Parts

NO PARTS USED

Quantity

Workorder: V38132

In Date: 01/28/2011

Meter Reading: 41,013.00

Close Date: 02/25/2011

Problem?

officers side head lamp out. I swapped the high beam with the low beam so I had two working lowbeams.Q47

Task performed:

replcd headlight & adj lights. j

Parts

H4651USE CV TYPE SEALED BEAM

H4656USE CV TYPE HEAD LIGHT

2

2

Workorder: V38689

In Date: 02/22/2011

Meter Reading: 41,817.00

Close Date: 02/25/2011

Problem?

ON CALL Q 47 OVERHEATING

Task performed:

Eng overheats on T-pike/Glades; fan inop; brought back to stn; manually locked up _____. j

Parts

NO PARTS USED

Quantity

Workorder: V38885

In Date: 03/01/2011

Meter Reading: 41,817.00

Close Date: 03/03/2011

Problem?

ON CALL Q 47 OVERHEATING (2/24/11)

Task performed:

Overheated on last call of the evening; chkd to see if belts were twisted or thrown; belts good; capt decided to stay in it for the night. j

Parts

NO PARTS USED

Quantity



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V38149

In Date: 01/30/2011

Meter Reading: 40,435.00

Close Date: 03/08/2011

Problem?

Door stop (hold open) on medical compartment door failed. q47

Task performed:

Replcd door hold open spring. j

Parts

Quantity

101305001BRACKET LEFT DH0008-5

1

101305002DH0007-5 BRACKET RIGHT

1

HLD39917DC23-5011 50 # HOLD-OPEN RESCUE

1

Workorder: V38150

In Date: 01/30/2011

Meter Reading: 40,435.00

Close Date: 03/08/2011

Problem?

Tires on the truck are done. needs new tires! right side rears are the worst. q47 Replace all 4 rear tires (outside agency-boulevard tire)

Task performed:

Replc (4) reat tires - Boulevard j

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD

Workorder: V38574

In Date: 02/16/2011

Meter Reading: 41,501.00

Close Date: 03/09/2011

Problem?

Chief Blake has approved and request i IBEM the following. 1 master intake valve for Q47 and wrenches for storz hose including mounting bracket on officer side. the MIV will need to be charged by 5 inch hose for LDH

Task performed:

Installed spanners 7 valve on truck. j

Parts

Quantity

NO PARTS USED

Workorder: V37270

In Date: 12/20/2010

Meter Reading: 38,168.00

Close Date: 03/10/2011

Problem?

Both mid-mount telescoping lights are burned out. Power button on radio on officer side is missing. Air brake leak. q47

Task performed:

waiting for parts 12/20/10

Parts

Quantity

NO PARTS USED

Remov light to send out for repair. j



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V38753

In Date: 02/24/2011

Meter Reading: 41,955.00

Close Date: 03/22/2011

Problem?

OVERHEATING Q 47

Task performed:

1. Eng poverheats - fan clutch worn; rep fan locked up & ordere new one.
2. Rep coolant & air intake leaks; topped off coolant. j (3/3/11)
3. Fnd fan not locking up & belts off; replc belts. j (3/22/11)

Parts

Quantity

2500902250-0902 CLAMP EXHAUST

1

9435BELT

3

HE50067HE50067 REGULATOR AIR HOR

1

Workorder: V39333

In Date: 03/21/2011

Meter Reading: 42,342.00

Close Date: 03/25/2011

Problem?

repair seat Q47 (outside agency-central auto trim)

Task performed:

- Repair seat q47 - Central Auto j

Parts

Quantity

NO PARTS USED

Vendor?: CENTRAL AUTO

Workorder: V38786

In Date: 02/25/2011

Meter Reading: 42,176.00

Close Date: 03/28/2011

Problem?

can we get tommy to mount our new Stortz 5" to NST 6" adaptor to the outer panel near the officer's side hosewell? See Driver Resch or Mcglynn for details. Thanks for all you guys do! Q47

Task performed:

1. Installed new brkt for stortz.
2. Readj tank to pump linkage. j

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V39008

In Date: 03/07/2011

Meter Reading: 42,702.00

Close Date: 04/01/2011

Problem?

C INSPECTION AND REPAIRS AS NEEDED Q 47

Task performed:

Parts

Quantity



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

C-Inspection	106-0530-25FIRECOM BOX	2
2. Svc all (6) btrys.	15W40BSYN OIL BULK QTS	40
3. Chk aerial overload guage for accuracy-bad; recalibrate gauge.	29526898 29548988 TRANS FILTER ALLISON	1
4. Adj ladder slide pads.	35200-RLIGHT MARKER LED RED	2
5. Replcd coolant reservoir.	P1147GFUEL FILTER 33120 WIX DELCO TP916	1
6. R5 & L5 compt lt damage; rem/install new lt asy.	PH47 51758 L/F PH725 OIL FILTERL	1
7. P/S svc.	PH7405 51971 OIL FILTER WIX	2
8. Grnd ladder 14',24',35' heat stickers expire; install new.	PS683033442 FUEL FILTER	1
9. L/R cab lift cyl leaking; assisted w/removal.	FG87904MFG3937557S FILTER P/S NEW STYLE	1
10. Rem left/right cab cyl.	360000052IGN ROCKER SWITCH	1
11. Replc alt belt.	360090031ACTUATOR HARD AMBER WINDOW	1
12. Rem fan/clutch asy - order correct parts.	820001-009GASKET P/S	1
13. Cab lift cntrl inop.	839009-003P/S PUMP 07 QUINTS	1
14. L5 door holdopen brkt loose.	371104371104 SWITCH ROCKER MOM.	1
15. R4 door striker loose.	SWT54915SWIT-251240 SW ROCKER SPST ON/OFF GREE	1
16. Replc L/rear mrkr light.	434WDLAMP	2
17. Replc L/rear center tailboard mrkr lt; rep connection at feed wire.	5001XXENON STROBE	2
18. Rep connection for L/center mrkr lt.	829008-001COOLANT TANK RESERVOIR QUINT	1
19. Replc msng R/rear hub cap nut/tightened.	9435BELT	3
20. Glue loadminder label back on.	FREIGHTSHIPPING CHARGES	345
21. Tighten door latch bolts.	K080570BELT	1
22. Grind cab lift cyl end for clearance w/cab.	KR-CCLCATHODE COMPARTMENT LIGHT	2
23. Install pulley/fan asy, fan belts & adj.	600000003NODE HERCULES V-MUX	1
24. Wire fan, heat shrink connections; protect w/wire loom & secure; retighten fan belts.	827009-002CAB LIFT CYL	2
25. Grind down other cab lift cyl for clearance.	829017-004FAN CLUTCH	1
26. Install cab lift cyl/hyd lines.	9420BELT	1
27. Dia problem with L&R outrigger cntrl panel lighting.	CA7230WA10116 AIR FILTER 46893 WIX	1
28. Rem frt pass seat for rep.	FG-Q59278P/S GASKET	1
29. T-case svc.		
30. Svc trans.		
31. Rem fuel filtr hsng/A/C compressor.		
32. Svc rear axle.		
33. Tighten rear A/C stch cvr.		
34. Chk computer codes-erase inactive codes.		
35. Cln out frt A/C drain hose.		
36. Replc o-ring on P/S line; bleed sys.		
37. Replc ign swtch; ordered PTO swtch.		
38. Adj squirter noszzles/time wiper arms.		
39. install steering pump fittings.		
40. Degrease motor.		
41. Refab/weld up frnt bumper.		
42. Assist John V. in frame weld rep.		
43. Test drive veh; adj fluid leversl for hot.		
44. Put ladder in raised pos & grease pinion gear.		
45. Chk frt end w/veh on jacks for loosensss.		
46. Ordered frt wheel hub caps.		
47.Replc ign/PTO swtch.		
48. Install pass frt seat.		
49. Svc auto lube.		
50. Rem loose turntable stantion.		



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

- 51. Replc msng grease fitting frm wtrwayshutoff valve.
- 52. Cvr L-rear door acces hole cvr.
- 53. Reinstall hub caps.
- 54. Repos ladder rung cvr holders.
- 55. Insulate A/C lines w/tape.
- 56. Tighten SCBA brkts.
- 57. Reinspect PTO trans/hyd pump.
- 58. Test eng/fan coming on.
- 59. Dia code P0703.
- 60. Repl strobe bulbs.
- 61. Chk ladder oveerload strobes.
- 62. Dia en fan inop.
- 63. Dia PTo swtch inop.
- 64. Dia gen-no start.
- 65. Install L&R telelight fix.
- 66. Intercom inop.
- 67. Chk/assist eng fan\68. Fnd PTO wont engage.
- 69. R/R both nite fighter lts.
- 70. Rem brkn cap chain.
- 71. Glue/secure rubber opr lid bumpers. j4/1/11
- 72. Replc pipe plug on air tank w/drain valve.
- 73. Dia air builb up.
- 74. Wash pump area of debris.
- 75. Replc pump alt/fan belt. j4/18/11

Workorder: V38904

In Date: 03/02/2011 **Meter Reading:** 42,342.00
Close Date: 04/04/2011

Problem?

remote control for aerial is not working. we put new battery in, still not working. thanks. q47

Task performed:

Fnd loose antenna on remote; tightened antenna; replc btry w/new; test remote - ok. j

Parts _____ Quantity

PM27JPM27JUG NEW NUMBER DIESEL EXHAUST FLUID : 1

Workorder: V39428

In Date: 03/24/2011 **Meter Reading:** 42,493.00
Close Date: 04/05/2011

Problem?

replace front tires

Task performed:

Replace front tires - Elpex j

Parts _____ Quantity

NO PARTS USED

Vendor?: EXPEX



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V37973

In Date: 01/21/2011
Close Date: 04/06/2011

Meter Reading: 39,914.00

Problem?

Q47 Hydraulic Spreader: The tray hook does not fit properly. The Spreader Throttle Coupling is stripped & difficult to operate under conditions. tommy knows about both issues.

Task performed:

Readj Hurst brkts. j

Parts

Quantity

NO PARTS USED

Workorder: V40275

In Date: 04/29/2011
Close Date: 05/03/2011

Meter Reading: 43,766.00

Problem?

Mount marker poles on quint 57, Sta 47.

Task performed:

Mnt marker poles; drill holes/secure; add locking nuts.
j

Parts

Quantity

NO PARTS USED

Workorder: V40101

In Date: 04/23/2011
Close Date: 05/09/2011

Meter Reading: 43,579.00

Problem?

mount for the piercing nozzle broken q47

Task performed:

Remounted nozzle in rear compt. j

Parts

Quantity

NO PARTS USED

Workorder: V40107

In Date: 04/24/2011
Close Date: 05/09/2011

Meter Reading: 43,730.00

Problem?

piercing nozzle "Loop Bracket" broke off and is sitting on Cpts Desk. Needs pot mettle welded back on? Also the nozzle is missing the hammer head portion to it. Q47

Task performed:

Replc brkt in rear compt. j

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V39886

In Date: 04/13/2011 Meter Reading: 43,163.00

Close Date: 05/13/2011

Problem?

front left light frame is loose, missing a screw. q47

Task performed:

Rep cover over light. j

Parts

Quantity

NO PARTS USED

Workorder: V39721

In Date: 05/16/2011 Meter Reading: 44,413.00

Close Date: 05/20/2011

Problem?

ON CALL DOOR OPEN ALRM ON Q47

Task performed:

Door open switches; all operating normal; vista control pad malfunction; unit if svc. j

Parts

Quantity

NO PARTS USED

Workorder: V40106

In Date: 04/24/2011 Meter Reading: 43,730.00

Close Date: 05/31/2011

Problem?

LED Bumper Guides are in Cpt's office and ready for install to front bumpers of R47 &Q47.

Task performed:

Installed bumper poles. j

Parts

Quantity

NO PARTS USED

Workorder: V39470

In Date: 03/27/2011 Meter Reading: 42,493.00

Close Date: 06/01/2011

Problem?

repair trans fla detroit

Task performed:

Repair trans - Fla Detroit j

Parts

Quantity

NO PARTS USED

Vendor?: FLORIDA DETROIT



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V40105

In Date: 04/24/2011
Close Date: 06/02/2011

Meter Reading: 43,730.00

Problem?

st47 hosecart is ready for pickup for wheel modification and reinforcements on angle brackets (see Tommy) for info. q47

Task performed:

- 1. Replcd light bulbs in 110 light
- 2. Replcd wipers. j

Parts

Quantity

91-20WIPER BLADE 20 IN

4

Q1000T3CLHALOGEN LIGHT 120V/1000W

4

Workorder: V40490

In Date: 05/09/2011
Close Date: 06/09/2011

Meter Reading: 44,186.00

Problem?

Take 100 foot sect of 5inch and cut it into 1-50 ft, 2-25 ft section. It will need 4 storz connections. Thank You q47

Task performed:

- 1. Cab A/C inop; rep condensor fans that were out.
- 2. Cut hose to length & installed ends. j

Parts

Quantity

5582-10 82-2111 GROTE ON-OFF WEATHERPROOF

2

71R755011-2624 TRINARY SWITCH A/C 1560

1

8126482-2106 TOGGLE GUARD

2

ICC5RLLED CLEARANCE LIGHT RED

1

Workorder: V40677

In Date: 05/17/2011
Close Date: 06/09/2011

Meter Reading: 44,413.00

Problem?

back up camera in cab of Q47 not working. Screen black

Task performed:

- Rep backup camera that was not working. j

Parts

Quantity

NO PARTS USED

Workorder: V40725

In Date: 05/19/2011
Close Date: 06/09/2011

Meter Reading: 44,549.00

Problem?

electrical problem on platform controls, Sta 47.

Task performed:

- Smoke frm turn table; fnd shorted wires; rep/tested. j

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V41469

In Date: 06/20/2011 Meter Reading: 45,597.00
Close Date: 06/24/2011

Problem?
replace batteries not changeed on call check for bad ecm

Task performed:

1. Dia for bad ECM; fnd ECM bad; vendor repair.
2. Assist in raising ladder/cab; ECM inop - vendor repair.
3. Replcd L/side btrys; R/side replcd by S.O.C. tech. j

Parts	Quantity
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	6
HP-31DBATTERY 950CCA HP-31D	6

Workorder: V41500

In Date: 06/21/2011 Meter Reading: 45,645.00
Close Date: 06/24/2011

Problem?
Q47 was inoperable.

Task performed:

Boynton Beach Blvd overpass, just west of turnpike.

FF explained Q47 died on them while driving; chkd volt - low; alt looked brand new; btrys failed load test; R/R one ____ of btry lost ECM power; won't start; looked for blown ECM fuse - all good; unplugged harness at ECM; truck started; suspect ECM or harness problem. j

Parts	Quantity
NO PARTS USED	

Workorder: V41572

In Date: 06/24/2011 Meter Reading: 45,729.00
Close Date: 06/27/2011

Problem?
Repair Hurst hose.

Task performed:

Drilled/tapped brkn screws in quick disconnect on Hurst tool hoses. j

Parts	Quantity
NO PARTS USED	



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V41643

In Date: 06/28/2011
Close Date: 07/05/2011

Meter Reading: 45,786.00

Problem?

Will not shut off.

Task performed:

TRAVEL TO STATION
COULD NOT DUPLICATE
NO SHUT OFF FAULT

Parts

Quantity

NO PARTS USED

DOOR OPEN ALARM
DISABLE WARNING LIGHT
DEFERRED REPAIR AK

Workorder: V41420

In Date: 06/17/2011
Close Date: 07/11/2011

Meter Reading: 45,597.00

Problem?

need 2 cycle oil for vent saw and K12 Q47

Task performed:

Rep saw & cld carb. j

Parts

Quantity

NO PARTS USED

Workorder: V41559

In Date: 06/23/2011
Close Date: 07/19/2011

Meter Reading: 45,675.00

Problem?

hing broke L5 (gas fan, lights compartment). thanks. Sta 47.

Task performed:

REPAIRED COMPARTMENT DOOR HINGE AK

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V41690

In Date: 06/30/2011

Meter Reading: 45,786.00

Close Date: 07/19/2011

Problem?

Saw/ cut poles, Sta 47.

Task performed:

Parts

Quantity

REMOVED LIGHT POLES FROM TRUCK AND CUT TO FIT AND WIRED

NO PARTS USED

REPAIRED SIDE OUT STEP THAT WAS DAMAGED BY POLE. AK

Workorder: V41720

In Date: 06/30/2011

Meter Reading: 45,906.00

Close Date: 07/22/2011

Problem?

There is a leak underneath the dash on the officer's side of cabin. Captain reports the leak being near some wires and possibly allowing water to hit wires. Sta 47.

Task performed:

Parts

Quantity

Rem dash panel; fnd no leaks. j

NO PARTS USED

Workorder: V37623

In Date: 01/04/2011

Meter Reading: 38,997.00

Close Date: 07/28/2011

Problem?

A/C 10-7 Q47

Task performed:

Parts

Quantity

close per mike 7-28-11

851001-009A/C BRACKET

1

ref to wo 39008 c inspection 3-8-11

Workorder: V40342

In Date: 05/02/2011

Meter Reading: 43,942.00

Close Date: 08/02/2011

Problem?

MOUNT TIRE ON WHEEL Q47

Task performed:

Parts

Quantity

Mount tire on wheel Q47 - Boulevard j

NO PARTS USED

Vendor?: BOULEVARD



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V41761

In Date: 07/02/2011

Meter Reading: 45,906.00

Close Date: 08/08/2011

Problem?

light on the ladder tip on officers side is out Q47

Task performed:

repaired broken wire in light

Parts

NO PARTS USED

Quantity

Workorder: V41043

In Date: 06/02/2011

Meter Reading: 45,006.00

Close Date: 08/12/2011

Problem?

Repair hose cart prop.

Task performed:

C/O cart; ordered new wheels for cart; start replacing wheels; mk fit new mnts; weld up cart per Doug. j

Parts

NO PARTS USED

Quantity

Workorder: V41376

In Date: 06/20/2011

Meter Reading: 45,597.00

Close Date: 08/17/2011

Problem?

check engine light on, ecm.

Task performed:

Chk eng light on ECM - Fla Detroit Diesel j

Parts

R90PFILTER FUEL 33231

Quantity

1

Vendor?: FLA DETROIT DIESEL

Workorder: V42262

In Date: 07/25/2011

Meter Reading: 46,717.00

Close Date: 08/25/2011

Problem?

Time for rear tires all four getting thin. Getting intresting to drive in the rain! Sta 47.

Task performed:

Chkd tires; will replc tires. j

Parts

NO PARTS USED

Quantity



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V41612

In Date: 06/26/2011

Meter Reading: 45,786.00

Close Date: 09/06/2011

Problem?

right aerial tip spot light out. not sure if reported yet. Q 47

Task performed:

repaired

Parts

NO PARTS USED

Quantity

Workorder: V42561

In Date: 08/04/2011

Meter Reading: 47,041.00

Close Date: 09/12/2011

Problem?

Orange Hose "quick connect" is NOT connecting. Hurst hose, Sta 47.

Task performed:

installed new connection and dropped off at station

Parts

128R119COUPLER GOLD

3530016HOSE HURST 16 ORANGE

Quantity

1

1

Workorder: V42710

In Date: 08/10/2011

Meter Reading: 47,320.00

Close Date: 09/12/2011

Problem?

Gas Fan is missing a rubber "leg". it broke off. thanks. Sta 47.

Task performed:

repaired gas fan and tested

Parts

NO PARTS USED

Quantity

Workorder: V42768

In Date: 08/12/2011

Meter Reading: 47,421.00

Close Date: 09/16/2011

Problem?

Replace 4 rear tires.

Task performed:

Replace (4) rear tires - Boulevard j

Parts

NO PARTS USED

Quantity

Vendor?: BOULEVARD



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V43196

In Date: 08/31/2011
Close Date: 09/19/2011

Meter Reading: 47,940.00

Problem?

Driver seat is torn Q47

Task performed:

will repair at b

Parts

Quantity

NO PARTS USED

Workorder: V43382

In Date: 09/01/2011
Close Date: 09/19/2011

Meter Reading: 47,979.00

Problem?

Q47 feels like the transmission is slipping or not getting fuel or power while driving. Occuring multiple times a shift, Sta 47.

Task performed:

traced out probelm connected detr-- de--

Parts

Quantity

NO PARTS USED

Workorder: V43409

In Date: 09/04/2011
Close Date: 09/19/2011

Meter Reading: 48,123.00

Problem?

need rubber shoe to PPV Fan ASAP.Fan spins around when running causing a safety hazar ddue to the shoe missing. Should probably replace both so fan is level due to even wear. we can mount it if you deliver Q47

Task performed:

installed new rubber pads on ppv all ok at this time

Parts

Quantity

FZ51368FEET RUBBER RAM-FAN

2

Workorder: V43504

In Date: 09/07/2011
Close Date: 09/19/2011

Meter Reading: 48,193.00

Problem?

fs47 tic not charging unit or spare battery Q47

Task performed:

installed new tic charger unit, all work ok at this time

Parts

Quantity

NO PARTS USED

light out on ladder, driver error lights work on gen



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V42261

In Date: 07/25/2011

Meter Reading: 46,717.00

Close Date: 09/21/2011

Problem?

Both tele lights out, sta 47.

Task performed:

repaired both tele lights that were out

Parts

Quantity

50R03ZCRLIGHT LED RED TIR 6

1

87499RY48 RELAY

2

J254HALOGEN BULB 1000 WATT WPB

2

X-OP251-12BRACKET OPA RIGHT

1

X-OP250-12MOUNT FOR OPA810 LEFT

1

Workorder: V43744

In Date: 09/18/2011

Meter Reading: 48,505.00

Close Date: 09/23/2011

Problem?

light box chargers are not charging (both), Sta 47.

Task performed:

repaired chargers and tested

Parts

Quantity

NO PARTS USED

readjusted ladder lables

Workorder: V43385

In Date: 09/02/2011

Meter Reading: 47,979.00

Close Date: 09/29/2011

Problem?

Transmission slipping and losing power while driving.

Task performed:

detroit desiel

Parts

Quantity

NO PARTS USED

Vendor?: DETROIT DIESEL

Workorder: V43902

In Date: 09/24/2011

Meter Reading: 48,725.00

Close Date: 10/14/2011

Problem?

The officer seat headset connection will not allow the microphone to be keyed. We tried moving the headsets around but no headsets will allow the mic to be keyed when plugged into the officer seat firecom. Gave to radio shop

Task performed:

GAVE TO RADIO SHOP TO COMPLETE

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V43936

In Date: 09/26/2011

Meter Reading: 48,725.00

Close Date: 10/14/2011

Problem?

leaking water from roof inside cab above windshield on officer side and near center by fan. fairly steady drip water must be getting in somehow from rain, Sta 47.

Task performed:

RESEALED ROOF AD INSIDE OF WINDOW

Parts

NO PARTS USED

Quantity

Workorder: V44011

In Date: 09/29/2011

Meter Reading: 49,007.00

Close Date: 10/14/2011

Problem?

Parts only.

Task performed:

INSTALLED BROKEN LIGHT BRACKET

Parts

UMVS254411STRAP 46 IN

Quantity

4

Workorder: V44039

In Date: 09/29/2011

Meter Reading: 49,047.00

Close Date: 10/14/2011

Problem?

New Genisix equipment has no mounts! Needs to be secured in compartments in vehicle. (Spoke with Tommy), Sta 47.

Task performed:

THEY ARE ON ORDER

Parts

NO PARTS USED

Quantity

Workorder: V44244

In Date: 10/09/2011

Meter Reading: 49,357.00

Close Date: 10/14/2011

Problem?

o2 sensor is not initializing, but other gasses work fine. properly charge, zero out, and bumped tested Q57

Task performed:

TESTED MONITOR AND TESTED OK

Parts

NO PARTS USED

Quantity



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V42610

In Date: 08/06/2011

Meter Reading: 47,114.00

Close Date: 10/21/2011

Problem?

The left and right side scene lights that are controlled by the on board generator, are not working. Q 47

Task performed:

repaired connections in light

Parts

Quantity

J254HALOGEN BULB 1000 WATT WPB

4

Q500T3CLBULB HALOGEN 120V 500WATT 4 11/16 LONG

3

Workorder: V44130

In Date: 10/04/2011

Meter Reading: 49,973.00

Close Date: 10/21/2011

Problem?

remote is not working properly, Sta 47.

Task performed:

installed new battery and tested ok

Parts

Quantity

NO PARTS USED

Workorder: V43648

In Date: 09/13/2011

Meter Reading: 48,281.00

Close Date: 10/28/2011

Problem?

UL TEST UNIT Q 47

Task performed:

UL test unit Q47 - Mistras j

Parts

Quantity

NO PARTS USED

Vendor?: MISTRAS

Workorder: V44418

In Date: 10/16/2011

Meter Reading:

Close Date: 10/28/2011

Problem?

Right Front Spot light out. Left Telescope Light out. Right side aerial light has cracked glass. Driver seat torn. Thank You. Q47

Task performed:

rep all lighting on truck. j

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V44509

In Date: 10/19/2011
Close Date: 10/28/2011

Meter Reading: 49,689.00

Problem?

Door alarm going off.

Task performed:

Traced out problem; fnd switch out of adjustment;
readj/tested. j

Parts

Quantity

NO PARTS USED

Workorder: V44626

In Date: 10/24/2011
Close Date: 11/07/2011

Meter Reading: 49,689.00

Problem?

brakes Repair.

Task performed:

CHECKED BRAKES AND CHECKED OK

Parts

Quantity

NO PARTS USED

Workorder: V44787

In Date: 10/31/2011
Close Date: 11/07/2011

Meter Reading: 50,075.00

Problem?

Transmission leak, sta 47.

Task performed:

Fnd fitting leaking & rep; will need to rep hoses. j

Parts

Quantity

NO PARTS USED

Workorder: V44808

In Date: 10/31/2011
Close Date: 11/08/2011

Meter Reading: 50,075.00

Problem?

service call install tire q47

Task performed:

Service call install tire Q47 - tiresoles j

Parts

Quantity

NO PARTS USED

Vendor?: TIRESOLES



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V44450

In Date: 10/18/2011

Meter Reading: 49,584.00

Close Date: 11/09/2011

Problem?

Repairs for UL test on the ladder.

Task performed:

1. Went to Stn47; chk trans cooler hose & mov clamp to stop rubbing on bell hsng.
2. Chk Chelsea pump on side of trans; fnd bolts loose; tighten bolts to shop leak.
3. Chk all (4) magnetic sensor for jack & tighten gthem.
4. Cln/grease under sides of stabilizer.
5. Charged waterway to see if relief valve wld work; it did not so readj the relief valve so it wld work at 240 PSI & order new one.
6. Assist w/relief valve.
7. Chk guage & fnd bad so order new gauge.
8. Sand down weld frm paint over it to see if it was crqacked; no crack fnd; cln up & repaint; use under cut in welding - ok.
9. Cln/grease main rail on ladder.
10. Chk bottom base section cradle pad & tighten screw
11. Chk waterway swivel above the hydro swivel; grease it/mov ladder up/down & rotate swivel to get grease all the way arnd.
12. Cln/lube waterway with ATF1.
13. Chk intercom sys; fnd spkr bad at end of ladder; need to order parts.
14. Assist w/intercom.
15. Chk handheld remote; fnd bad btry.
16. R/R rear waterway gauge; new gauge was too tight so I had to grind the hole a little to mk it fit.
17. R/R both intercome box, (1) at pump panel & (1) at turntable & order hand free for ladder tip. j

Parts

Quantity

91523934GAUGE 0-600 PSI

1

PL-11005 WATERWAY RELIEF VALVE

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V44855

In Date: 11/01/2011

Meter Reading: 50,075.00

Close Date: 11/10/2011

Problem?

not charging speaker inop trans lines Q 47

Task performed:

- Assist in ladder spkr replacement.
- 2. Raise ladder/cab; chk charging sys; fnd alt not putting out; rem belt, cables & alt; R/R alt - swapped pulley; ran eng - chk ok.
- 3. Chk trans line for leaks; clnd lines; ran & fnd both lines leaking; rem clamps/lines.
- 4. Install/chk ladder TIP spkr.
- 5. Assist w/chkng charging sys & alt - Hines.
- 6. R/R trans cooler; go to Mako. j

Parts

Quantity

A0014949PA4949PA/4962 320 AMP UPGRADE SADDLE MC

1

Workorder: V44347

In Date: 10/12/2011

Meter Reading:

Close Date: 11/14/2011

Problem?

foam coming out of the seat. q 47

Task performed:

Will have seat rep at B. j

Parts

Quantity

NO PARTS USED

Workorder: V44888

In Date: 11/01/2011

Meter Reading: 50,075.00

Close Date: 11/15/2011

Problem?

OFFICER SEAT BELT NOT WORKING PROPERLY. TENSION RECOILER BROKE NOT PULLING SEAT BELT TENSION. Q47

Task performed:

- 1. Replc seat belt.
- 2. Rep driver side window regulator. j

Parts

Quantity

854003-012SEAT BELT 3 POINT QUINTS

1

Workorder: V45110

In Date: 11/11/2011

Meter Reading:

Close Date: 11/16/2011

Problem?

Exposed wires coming from DO's headset in truck. Give to radio shop

Task performed:

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V45055

In Date: 11/08/2011

Meter Reading:

Close Date: 11/23/2011

Problem?

discharge # 2 (purple) unattached inside "real loose) Q47

Task performed:

repaired linkage for valve

Parts

Quantity

NO PARTS USED

Workorder: V45397

In Date: 11/23/2011

Meter Reading: 50,771.00

Close Date: 12/01/2011

Problem?

Replace command module.

Task performed:

DIAGNOSE AND INSTALL COMMAND MODULE AND PROGRAM.

Parts

Quantity

NO PARTS USED

Workorder: V45340

In Date: 11/21/2011

Meter Reading:

Close Date: 12/02/2011

Problem?

burning smeel coming from cab, Sta 47.

Task performed:

found marker lights burning

Parts

Quantity

ICC5ALLED CLEARANCE LIGHT AMBER

7

ICC5RLLED CLEARANCE LIGHT RED

1

Workorder: V45564

In Date: 12/01/2011

Meter Reading: 51,043.00

Close Date: 12/06/2011

Problem?

REPLACE REAR TIRES Q 47 TIRESOLES

Task performed:

REPLACE REAR TIRES Q 47 TIRESOLES.

Parts

Quantity

NO PARTS USED

Vendor?: TIRESOLES



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V45109

In Date: 11/11/2011

Meter Reading:

Close Date: 12/08/2011

Problem?

The locking device that holds the wheel chock in the wheel chock holder is not functioning properly. The wheel chock can be pulled out with moving the lock out of the way.

Task performed:

Parts

Quantity

REPLACE BOTH WHEEL CHOCK HOLDERS.

NO PARTS USED

Workorder: V45174

In Date: 11/14/2011

Meter Reading:

Close Date: 12/08/2011

Problem?

left front scene light is out. Q47

Task performed:

Parts

Quantity

INSTALL WATERWAY RELIEF VALVE.

NO PARTS USED

Workorder: V45108

In Date: 11/11/2011

Meter Reading:

Close Date: 12/12/2011

Problem?

One lock that holds the wheel chocks in holder does not keep the wheel chock from coming out of holder.E47

Task performed:

Parts

Quantity

repaired atch on wheel chock holder

NO PARTS USED

Workorder: V45431

In Date: 11/26/2011

Meter Reading:

Close Date: 12/12/2011

Problem?

No. 2 Discharge gauge needle does not move when increasing presure. thx. Q47

Task performed:

Parts

Quantity

tested pump and found no problem with gauge

PM27JPM27JUG NEW NUMBER DIESEL EXHAUST FLUID :

2

repaired rear comp taht would not open



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V45484

In Date: 11/29/2011

Close Date: 12/15/2011

Meter Reading: 51,097.00

Problem?

C INSPECTION Q 47

Task performed:

Parts

Quantity



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

C INSPECTION X 4 DAYS	101781007BUSHING CAB TILT	2
ASSIST WITH C INSPECTION SHEEDY	200-2450-00NC SWITCH OK TO PUMP	1
ASSIST WITH C INSPECTION MCWHITE	29526898 29548988 TRANS FILTER ALLISON	1
SERVICE AIR DRYER HAD TO REMOVE BRAKET TO SERVICE	3202099SEAL WITH RACE QUINT	2
REPAIRED COMPARTMENT DOORS, SHOCKS AND SPRINGS	33063FUEL FILTER ONAN	1
ASS---WITH TIRE ON REAR	5008414CARTRIDGE DC100	1
REMOVE SEAT AND INSTALL SPARE SEAT	51064OIL FILTER ONAN	1
REMOVE SPARE SEAT AND INSTALL NEW SEAT	68-3963453-30LENS CLEAR FOR STRIP LIGHT	1
SERVICE T CASE AND TRANS	827007-001PIN CAB TILT FERRARA	2
START REAR BRAKES FOUND SHOE BAD BUT DRUM WERE HEAT--- AND MIKE SAID TO REUSE THEM BUT ---SEAL WERE LOUD SO REPLACE SEAL CLEAN AND INSPECT BEARING BRAKE SHOE AND NEW TIRES	E-600013-3052 NUT	4
ASSIST WITH REAR BRAKES	FT4471BDQUINT REAR BRAKE SHOES	4
R&R GREESE --IN TOP OF KING PIN	HLD374211 IN HOLD-OPEN 30LB	2
TILL WATER TANK AND TEST DRIVE	KIT9081BRAKE HARDWARE KIT	2
SERVICE TRANS AND T CASE	Q1500T3/CLLB-M15 240 V BULB	1
TOR U BOLTS	PS683033442 FUEL FILTER	1
ASSIST WITH U BOLTS	401581GASKET AXLE FL80 R002435	2
REAPAIR WIRING TO COMMAND MODULE	EAA-8350-60UGSS6557UP STRUT-LIFT	1
R&R BULB IN LEFT FRONT SCENE LIGHT	S260291008LENS AMBER	1
MAKE ACCESS TO GEN AIR GILER AND SERVICE GEN	P1147GFUEL FILTER 33120 WIX DELCO TP916	1
ASSIST WITH GEN	PH47 51758 L/F PH725 OIL FILTERL	1
ORDER TRANS COOLER AND CAB TILTPINS AND BUSHING	PH7405 51971 OIL FILTER WIX	2



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V45728

In Date: 12/08/2011

Meter Reading:

Close Date: 12/16/2011

Problem?

check engine light stays on and the alarm sounding. Sta 47

Task performed:

Parts

Quantity

WORKED ON UNIT AT STATION - NEED TO SEND TO SHOP.

NO PARTS USED

Workorder: V45789

In Date: 12/12/2011

Meter Reading: 51,203.00

Close Date: 12/16/2011

Problem?

Q47 door open light on

Task performed:

Parts

Quantity

TRACED OUT PROBLEM AND FOUND LIGHT POLE WAS UP AND MAKING LIGHT TO STAY ON.

NO PARTS USED

Workorder: V45736

In Date: 12/08/2011

Meter Reading: 51,043.00

Close Date: 12/27/2011

Problem?

foot throttle.

Task performed:

Parts

Quantity

REPLACED FOOT THROTTLE.

350000054THROTTLE PEDAL

1

Workorder: V45771

In Date: 12/09/2011

Meter Reading:

Close Date: 01/03/2012

Problem?

Spot light out, rear officer side. Q47

Task performed:

Parts

Quantity

repaired ground wire for spot light

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V45898

In Date: 12/15/2011

Meter Reading:

Close Date: 01/03/2012

Problem?

battery charge on the truck is broken. need a new piece to plug into on q47

Task performed:

found breaker blown in station

Parts

Quantity

L1261F33585XE FUEL FILTER WIX

1

PH8942FILTER OIL 57182 LFP3729

1

S3225PFUEL FILTER 33630 LFF5849

1

Workorder: V45927

In Date: 12/18/2011

Meter Reading:

Close Date: 01/03/2012

Problem?

SHORELINE POWERCORD WILL NOT PLUG INTO TRUCK ADAPTER. NOT CIRCUIT BREAKER THERE IS POWER TO COR BUT IT WILL NOT ATTACH TO TRUCK, Sta 47

Task performed:

replaced pulg and auto eject

Parts

Quantity

NO PARTS USED

Workorder: V45932

In Date: 12/19/2011

Meter Reading:

51,636.00

Close Date: 01/04/2012

Problem?

Primer inop.

Task performed:

FOUND BAD CONNECTION ON SOLENOID.

Parts

Quantity

NO PARTS USED

Workorder: V46360

In Date: 01/06/2012

Meter Reading:

52,067.00

Close Date: 01/06/2012

Problem?

Oncall Transmission inop.

Task performed:

DRIVE FROM PALMS WEST TO STA. 47 SCAN COMPUTER TEST FOR TRANSMISSION CODE. DRIVE TO STA 42 THEN DRIVE TO SHOP FOR SPARE ENGINE.

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V46356

In Date: 01/05/2012 Meter Reading: 52,067.00

Close Date: 01/10/2012

Problem?

wont move at pike rd and southern

Task performed:

TRAVEL TO SCENE AT PIKE ROAD. START VEHICLE AND FOLLOW BACK TO SHOP. FOUND TRANS. 5 QUARTS LOW ON TRANS FLUID AND CODE PO843. ADD FLUID AND ERASE CODE. TEST DRIVE (OK)

Parts

NO PARTS USED

Quantity

Workorder: V45987

In Date: 12/20/2011 Meter Reading: 51,669.00

Close Date: 01/13/2012

Problem?

Q47 shoreline plug on truck is broke, possible causing a short...need repair asap, Sta 47

Task performed:

1. STATION NEEDS OIL. DROPPED OFF OIL AND INSTALLED IN RESCUE.
2. AUTO EJECT - REPLACED COVER AND TESTED UNIT/ REPAIRED WIRES.

Parts

0915520120AUTO EJECT 20 AERO OTL3925
15W40QSYN OIL QT

Quantity

1
12

Workorder: V45991

In Date: 12/20/2011 Meter Reading: 51,669.00

Close Date: 01/13/2012

Problem?

Driver side telescoping light not working. Q47

Task performed:

REPLACED BULB IN LIGHT.

Parts

NO PARTS USED

Quantity

Workorder: V46185

In Date: 12/30/2011 Meter Reading: 51,998.00

Close Date: 01/13/2012

Problem?

Officer side, rear spot light out. Q47

Task performed:

1. AIR LEAK TRACED OUT AIR LEAKS.
2. REPLACED BULB IN LIGHT.

Parts

NO PARTS USED

Quantity



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V46407

In Date: 01/08/2012
Close Date: 01/13/2012

Meter Reading: 4,634.00

Problem?

front light out also left side telescope out. left side is a on going problem for three years. a light bulb lasts maybe 2 shifts, Sta 47

Task performed:

REPAIRED LIGHT AND TESTED.

Parts

NO PARTS USED

Quantity

Workorder: V46695

In Date: 01/19/2012
Close Date: 01/19/2012

Meter Reading: 52,619.00

Problem?

assist allison tech with repairs

Task performed:

ASSIST TRANSMISSION GUY WITH REMOVAL AND
INSTALLATION OF VALVE BODY TEST DRIVE.

Parts

NO PARTS USED

Quantity

Workorder: V46325

In Date: 01/05/2012
Close Date: 01/23/2012

Meter Reading: 52,067.00

Problem?

Install Genesis tool brackets.

Task performed:

INSTALLED ALL BRACKETS WERE NEEDED.

Parts

NO PARTS USED

Quantity

Workorder: V46846

In Date: 01/25/2012
Close Date: 01/25/2012

Meter Reading: 52,863.00

Problem?

PARTS ONLY Q 47

Task performed:

NO LABOR PARTS ONLY

Parts

106-0530-10FIRECOM BOX LADDER END

Quantity

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V46575

In Date: 01/14/2012

Meter Reading: 52,598.00

Close Date: 01/27/2012

Problem?

Quint 47 Aerial Nozzle Up/Dwn Motor is sticking and not moving nozzle at all.

Task performed:

TRACED OUT PROBLEM WITH NOZZLE AND FOUND
BROKEN WIRE ON LADDER REPAIRED.

Parts

NO PARTS USED

Quantity

Workorder: V46590

In Date: 01/15/2012

Meter Reading: 52,598.00

Close Date: 01/27/2012

Problem?

large side mirror on officer side of cab has broken glass in it. It struck object last night. frame appears undamaged but glass is shattered effecting visability Q 47

Task performed:

INSTALLED NEW MIRROR ON PASS SIDE.

Parts

708212VELVAC HEATED MIRROR

GRO716SGRO716S MIRROR S/S

Quantity

1

1

Workorder: V46654

In Date: 01/18/2012

Meter Reading: 52,619.00

Close Date: 01/27/2012

Problem?

Back driver side panel whic hcovers the controls for the driver side outrigger swings open and wont stay shut. Sta 47

Task performed:

REPLACED REAR DOORS FOR CONTROLS FOR
JACKS.

Parts

DOR4011AD0010-0 DOOR SCBA COMPT.

Quantity

1

Workorder: V47081

In Date: 02/03/2012

Meter Reading:

Close Date: 02/07/2012

Problem?

Chrome hub cover on officers side rear wheel missing a lug(1 of 2) that hold the cover on the hub.Sta 47

Task performed:

1. travel to sta-47, found 1 nut that holds chrome wheel cover on missing and the other loose, remove center hub cover and tighten nut holdind wheel cover on, advised Steve Rines that we needed 1 nut to hold the hub on. travel back to s/shop

Parts

6256RJN6256RJN NUT-OUTER/RIGHT

H1422TSX STUD

Quantity

2

2



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V46363

In Date: 01/06/2012
Close Date: 02/10/2012

Meter Reading: 52,067.00

Problem?

TRANS REPAIR Q 47

Task performed:

TRANS REPAIR Q 47.

Parts

NO PARTS USED

Quantity

Vendor?: FLORIDA DETROIT DIES

Workorder: V47254

In Date: 02/12/2012
Close Date: 02/28/2012

Meter Reading: 53,380.00

Problem?

drivers side, switch that makes stabilizer go in and out working intermittently. switch has to be toggled in order to make it work. Q

Task performed:

1. REPLACED SWITCH FOR REAR JACK AND TESTED.
2. REPAIRED COOLANT LEAK AND TESTED.

Parts

330000119MICRO SWITCH OUTRIGER

1

Quantity

Workorder: V47535

In Date: 02/23/2012
Close Date: 03/06/2012

Meter Reading: 53,759.00

Problem?

Aerial light OIC side and PBC placard on the ariel damaged on call # 12-18206. Property Damage reports P-12-052 and P-12-053 Sta 47

Task performed:

REINSTALLED SIGN AND REPAIRED BRACKETS.

Parts

NO PARTS USED

Quantity

Workorder: V43835

In Date: 09/21/2011
Close Date: 03/09/2012

Meter Reading: 48,658.00

Problem?

f/f headset is broken, Sta 47.

Task performed:

filled out by mechanics shop and turned over to radio shop.

Parts

NO PARTS USED

Quantity



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V47655

In Date: 03/01/2012

Meter Reading: 54,091.00

Close Date: 03/13/2012

Problem?

Repair ripped off sign plate.

Task performed:

REINSTALLED SIGN PLATE AND REPAIRED.

Parts

NO PARTS USED

Quantity

Workorder: V47819

In Date: 03/08/2012

Meter Reading: 54,365.00

Close Date: 03/16/2012

Problem?

nail found in front officer's tire of Q47. no air leadage after 12hrs of notice, Sta 47

Task performed:

CHECKED TIRE, CHECKED OK.

Parts

NO PARTS USED

Quantity

Workorder: V48139

In Date: 03/22/2012

Meter Reading:

Close Date: 03/26/2012

Problem?

water is leaking at the officers feet- coming from under the dash

Task performed:

1. travel to sta-47, check for water leaking on officer side floor, found a/c drain leaking, clean out drain line and recheck draining ok now. travel back to s/shop

Parts

NO PARTS USED

Quantity

Workorder: V48020

In Date: 03/16/2012

Meter Reading: 54,623.00

Close Date: 04/02/2012

Problem?

per B/C Blake we are requesting that the Genesis power unit compartment have a slid out tray. It is the compartment closest to the cab on the officers side.

Task performed:

1. RELOCATED ALL HURST TOOLS TO R-4 COMPARTMENT.
2. REPLACED QUARTZ LIGHTS THAT WERE DAMAGED BY TREE.

Parts

OPA570SCENE LIGHT

Quantity

2



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V48182

In Date: 03/26/2012

Meter Reading: 54,904.00

Close Date: 04/05/2012

Problem?

rear scene light officers side is out. Brow light officers side is very dim, about to go out, Sta 47

Task performed:

- R/R SCENE LIGHT R&R BULB AND FRONT OF LIGHT ASSY R&R BULB INTO FRONT ASSY REINSTALL AND MAKE CORRECTIONS.
- L/F BROW LIGHT DIM - SOMEONE PUT 240V BULB WHERE 120V BULB GOES ALSO NO BULB IN R/F BROW LIGHT R&R LENS R&R BULBS AND CLEAN REFLECTORS IN BOTH BROW LIGHTS.

Parts

Quantity

4435HEADLIGHT

1

Q1000T3CLHALOGEN LIGHT 120V/1000W

2

Workorder: V48272

In Date: 03/28/2012

Meter Reading: 55,009.00

Close Date: 04/05/2012

Problem?

aerial remote not working Q47

Task performed:

DIAGNOSE AERIAL REMOTE CONTROL. R&R BATTERY IN REMOTE. CHECK P/C BOARD, FUSES AND ANTENNA AND SWITCH ON TURNTABLE CONTROL STATION.

Parts

Quantity

NO PARTS USED

Workorder: V48317

In Date: 03/31/2012

Meter Reading: 55,093.00

Close Date: 04/05/2012

Problem?

light box chargers- next to FF on drivers side- light does not stay in charger due to busted tab. charger on center console, drivers side not working. Q47

Task performed:

R&R LITE BOX CHARGER AT L/R CAB LOCATION. TEST CHARGERS ON CENTER CONSOLE - BOTH HAVE GROUND AND 12V PUT HAND LIGHT IN EACH BASE AND CHARGER INDICATORS LIGHT UP - NO PROBLEM FOUND.

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V48354

In Date: 04/02/2012

Meter Reading: 55,093.00

Close Date: 04/05/2012

Problem?

ON CALL OIL LEAK Q47

Task performed:

FOUND POWER STEERING 2 QUARTS LOW FILL TO PROPER LEVEL. COULD NOT FIND LEAK. ENGINE OIL LEAKING FROM TURBO RETURN LINE - TIGHTEN LINE AS SECURE AS POSSIBLE STILL LEAKING ADD 2.2 GALLONS OF OIL TOOK OPERATOR TO SHOP FOR SWAP OUT. ASKED ME TO TAKE DRIVER TO SPARE ENGINE - 10132040 MILES 85149 HOURS 3258.

Parts

NO PARTS USED

Quantity

Workorder: V48356

In Date: 04/02/2012

Meter Reading: 55,093.00

Close Date: 04/05/2012

Problem?

OIL LEAK Q47

Task performed:

1. TURBO CHARGER OIL LEAK - R&R BURBO OIL DRAIN BUBE REPLACE GASKET AND O-RINGS.
2. P/S LEAK R&R PRESSURE HOSE MAKE NEW HOSE ASSY.

Parts

08929285T DRAIN

Quantity

1

Workorder: V48458

In Date: 04/05/2012

Meter Reading: 55,172.00

Close Date: 04/05/2012

Problem?

BROW LIGHT BROKEN Q 47

Task performed:

1. travel to sta-47, check driver side brow light brackets broken, travel to s/shop for electrical cord, driver cut cord to close to lamp and removed lamp, travel back to sta-47
2. remove broken brackets, take apart lamp and rewire lamp, install new brackets and lamp, run gen. and check brow lights all ok
3. travel back to s/shop

Parts

X-OP250-12MOUNT FOR OPA810 LEFT

X-OP251-12BRACKET OPA RIGHT

Quantity

1

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V49156

In Date: 05/07/2012

Meter Reading: 56,114.00

Close Date: 05/10/2012

Problem?

OIL LEAK Q 47

Task performed:

1. REMOVE AIR CLEANER VGT SOLENOID AND TURBO OIL RETURN TUBE AND ADAPTER AND ORDER PARTS.
2. INSTALL TURBO OIL RETURN TUBE AND ADAPTOR. VGT SOLENOID AND AIR CLEANER. DEGREASE ENGINE AND TEST DRIVE RECHECK LEAKS OK AT THIS TIME.

Parts	Quantity
23532171FLANGE OIL TUBE	1
23532326O RING OIL TUBE	2
8929285GASKET OIL RETURN LINE	1

Workorder: V48439

In Date: 04/04/2012

Meter Reading: 55,093.00

Close Date: 05/11/2012

Problem?

a number of the light are broken on the truck including one of the front scene lights where the bracket is broke and a light inside driver side compasrtment 4 is hanging, Q47

Task performed:

1. REPLACED LIGHTS ON TIP THAT WERE BROKEN
2. REMOUNTED HURST TOOLS AND UNIT.

Parts	Quantity
NO PARTS USED	

Workorder: V49316

In Date: 05/13/2012

Meter Reading:

Close Date: 05/14/2012

Problem?

VHF radio not working properly q47

Task performed:

REPORTED TO RADIO SHOP 05/14

Parts	Quantity
NO PARTS USED	

Workorder: V49608

In Date: 05/24/2012

Meter Reading: 56,764.00

Close Date: 05/30/2012

Problem?

CHECK LADDER CABLES Q 47

Task performed:

CHECKED LADDER CABLES.

Parts	Quantity
NO PARTS USED	



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V49833

In Date: 06/02/2012 Meter Reading: 57,236.00

Close Date: 06/05/2012

Problem?

the terminal that the drivers headset plugs into does not work. the one behind it, for the FF , has static and works intermittently. It is not the headset, checked it on other side of quint and on the rescue Gave to radio shop

Task performed:

RADIO SHOP WILL REPAIR

Parts

NO PARTS USED

Quantity

Workorder: V49937

In Date: 06/06/2012 Meter Reading: 57,236.00

Close Date: 06/07/2012

Problem?

VHF RADIO DOES NOT WORK q 47

Task performed:

REPORTED TO RADIO SHOP 6/6/12

Parts

NO PARTS USED

Quantity

Workorder: V49941

In Date: 06/06/2012 Meter Reading: 57,236.00

Close Date: 06/13/2012

Problem?

REPLACE REAR TIRES

Task performed:

REPLACE REAR TIRES

Parts

NO PARTS USED

Quantity

Vendor?: BOULEVARD TIRE CENTE

Workorder: V49652

In Date: 05/26/2012 Meter Reading: 56,977.00

Close Date: 06/15/2012

Problem?

Q47 WATER TANK LEVEL DISPLAYS NOT WORKING. THE COLOR BAR LIGHTS ARE COMPLETELY OUT AND THE SMALLER LOWER GAUGE IS INACCURATE READING HALF TANK OR LOWER WHEN TANK IS COMPLETELY FULL Q47

Task performed:

1. RECALABRATED WATER LEVEL GAUGES AND TESTED.
2. NOT CHARGING, REPLACED BATTERY AND CHECKED VOLTAGE - FOUND VOLTAGE DROP AT DASH - REPAIRED BAD CONNECTION.
3. BROW LIGHTS OUT - REPLACED BULBS AND TESTED.

Parts

A0014949PA4949PA/4962 320 AMP UPGRADE SADDLE MC
 BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER BATTERY
 HP-31D BATTERY 950CCA HP-31D
 Q1500T3/CL-1 BULB QUARTZ 120V

Quantity

1
6
6
3



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V49476

In Date: 05/18/2012
Close Date: 06/18/2012

Meter Reading: 56,621.00

Problem?

officer side rear outside tire is very worn. Also officers side front tire has approx 1/4" of tread left. Q47

Task performed:

1. REPLACE ALL FOUR TIRES IN REAR (TIRES REPLACED 6-12-12)
2. HANDLE FOR PUMP PANEL LEFT INTAKE REPLACED WITH NEW ONE.

Parts

91-22WIPER BLADE

Quantity

2

Workorder: V50119

In Date: 06/13/2012
Close Date: 06/25/2012

Meter Reading: 57,534.00

Problem?

Front eyebrow light out on officers side. Q47

Task performed:

1. REPAIRED REAR WHEEL COVERS.
2. REPLACED BULBS IN BROW LIGHT.

Parts

ACX-84534LUG NUT COVER PK10

Quantity

10

Workorder: V50143

In Date: 06/14/2012
Close Date: 07/13/2012

Meter Reading: 89,529.00

Problem?

Brow lights not working, bulbs were just changed 3 days ago by Tommy.

Task performed:

SENT TO SHOP FOR REPAIR.

Parts

NO PARTS USED

Quantity

Workorder: V50860

In Date: 07/14/2012
Close Date: 07/25/2012

Meter Reading: 58,103.00

Problem?

Pump PTO is having trouble switching on. Had to turn the truck and battery off 3 times for it to work. Q47

Task performed:

1. TESTED PTO SWITCH AND OPERATION AND ALL TESTED OK.
2. REPAIRED WATER LEVEL GAUGE RECALABRATED.

Parts

NO PARTS USED

Quantity



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V50861

In Date: 07/14/2012
Close Date: 07/25/2012

Meter Reading: 58,103.00

Problem?

Monitor nozzle on end of stick will not go up when the nozzle is in the in-line position. Will only go up when the nozzle is tilted left or right. Q 47

Task performed:

RAN LADDER AND TESTED MONITOR FOUND NO PROBLEM WITH UNIT.

Parts

NO PARTS USED

Quantity

Workorder: V51021

In Date: 07/20/2012
Close Date: 08/06/2012

Meter Reading: 58,233.00

Problem?

brow lights not working. officer side missing glass cover and bulb. Q47

Task performed:

1. REPLACED LENS ON BROW LIGHT ON CAB.
2. TRACED OUT PROBLEM WITH LADDER LIGHTS, FOUND BAD CONNECTION ON RELAY.

Parts

4246107LENS WILL BURT 1
 4246108GASKET WIL BURT 1
 J254HALOGEN BULB 1000 WATT WPB 2
 Q1500T3/CL-1BULB QUARTZ 120V 3
 Q1500T3/CLLB-M15 240 V BULB 3

Quantity

Workorder: V51289

In Date: 08/01/2012
Close Date: 08/09/2012

Meter Reading: 58,233.00

Problem?

replace front tires

Task performed:

REPLACE FRONT TIRES.

Parts

NO PARTS USED

Quantity

Vendor?: ELPEX

Workorder: V51751

In Date: 08/20/2012
Close Date: 09/13/2012

Meter Reading:

Problem?

the air compressor leak compensator has gone off a couple of times today. The air breaks are working but it did activate twice Q 47

Task performed:

1. CHK OUT COMPRESSOR FOUND NO PROB W/ UNIT.

Parts

NO PARTS USED

Quantity



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V50788

In Date: 07/30/2012

Meter Reading: 57,910.00

Close Date: 09/14/2012

Problem?

check to see if 25 hour check sheet and monthly inspection sheet have been placed neat aerial hour meter/controls. Also see if 20 ft pike pole has been installed. Report back to Lehan

Task performed:

Parts

Quantity

CHK SHEET IS INSTALLED ON TRUCK AND PIKE POLE.

NO PARTS USED

Workorder: V51693

In Date: 08/17/2012

Meter Reading:

Close Date: 09/17/2012

Problem?

Aerial ladder/aerial outriggers warning light and audible alarm constantly alarming on interior of cab. No signs of ladder/outrigger problems Q47

Task performed:

Parts

Quantity

TRUCK WENT THREW WATER IN RAIN STORM-SHORTED EVERYTHING OUT CLEANED AND DRIED CONNECTIONS ROAD TESTED ALL LIGHTS ARE NOW OUT.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V50285

In Date: 06/21/2012

Close Date: 09/18/2012

Meter Reading: 57,592.00

Problem?

C INSPECTION Q 47

Task performed:

Parts

Quantity



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

1. RECVER SYST REMOVE SWACTOR VALVE REPLACE SWACTOR VALVE AND VACC SYST AND RECHG SYST A/C WORKS GOOD AND NO LEAKS.
2. TROUBLESHOOT W/ CABLIFT WHEN TO NODE FOUND PIN X PUT 12V ON PIN AND CAN LIFT WORKED.
3. R&R LATCH LADDER.
4. CUT OFF 20' PIPE POLES TWO 16' FOUND DAMAGED.
5. C INSP
6. C INSP
7. C-INSP
- 8 C- INSP
- 9 C-INSP
10. C INSP
11. C- INSP
- 12 REMOVE A/C COMPRESSOR AND BASKET TO REPAIR BASKET.
13. REPAIRED A/C BASKET INSTALL TRUCK FOUND COMPRESS BAD PART ROOM HAD COMPRESS BUT I HAD TO CHARGE THE END W/ HOSE CONNECTOR.
14. ASSIST JERRY W/ BRACKET REPAIR-WELD UP BRACKET.
15. CHK OUT CAB TILT FOUND ONLY VALVE 5.8 VOLT AT TRIGGER WIRE ON SOLINOD.
16. INSTALLED COMPRESSOR AND VACC SYST AND CHANGED SYST RAN A/C PRESSURE WERE GOOD REMOVE AC MACHNE AND SWADER VALVE LOCKED.
- 17.CHKD DIP STICK FOR POWER STEERING FOUND NUT MISING.
18. PUT AC MACHINE ON TO SEE IF AC WAS LOW AND CLEAN HOSES THAT LOOKED LIKE THEY WERE LEAKING.
19. CHKD EXHAUST FOR LEAKS BEFORE STARTED TRACK UNDER WRAP EXHAUST . FOUUND LEAK AT CLAMP REMOVE CLAMP AND REPLACE.
20. PAINT FUEL CAP.
21. REMOVE WIPER BLADES TO TAKE TO PART ROOM.
22. FOUND FUEL LEAK IN REAR OF HEAD A FANEL FITTING WAS LOOSE BUT YOU HAVE TO REMOVE BOTH WIRE TO TIGHTEN IS SO I TOOK BOTH OFF CLEAN THE TREADS AND REPLACED.
23. FOUND AC ONE LB LOW SO I REMOVED LINE FOUND COMPRESS TO FILL PART AND SENT TO MAKE.
24. INSTALL ASS # ON WINDSHEILD.
25. FOUND STAD MISSING TO HOLD WHEEL COVER ON REPLACED STUD NUT AND COVER.
26. GOT HOSE BAKE FRM MAKO INSTALL HOSE INSTALL DRYER VACC SYST LEAK TEST PASS.
27. FOUND SYST DID NOT HOLD VACC OVER NIGHT SO I CHARGED W/ 1/2 LB FREON AND PUT

010102WRAP 2 IN WIDE	2
091-9COMPRESSOR 12 VOLT	1
1250E473PLUG DRAIN REAR END FREIGHTLINER	1
16-31438915 VALVE CORE A/C 3544706C1	2
20S-500EXHAUST CLAMP 33225 5 IN	1
3202099SEAL WITH RACE QUINT	1
401581GASKET AXLE FL80 R002435	1
8201L17-3428 ESTER OIL E7	1
PS683033442 FUEL FILTER	1
14714-1-5COOLER NEW QUINTS	1
160012-2012A EXPANSION VALVE 71R8301	2
3945207BOLT ADJ A/C COMP	1
923182-2151 SWITCH MOMENTARY 24-372	1
19570 AMP RELAY	2
2258Y1273BRAKE SPRING- SUIT CASE STYLE	2
3687DRUM 3687X	2
KSR4034715QPSHOE KIT	2
310-1089AXEL WEAR RING	1
35200-RLIGHT MARKER LED RED	2
35200-YLIGHT MARKER LEDAMBER	1
371007110RUBBER LATCH	1
60351STEPWELL LIGHT	1
6256RJN6256RJN NUT-OUTER/RIGHT	1
406-0612LATCH CUMMINS-ONAN	1
414369HOSE & FITTING ASSY	1
440-5 VALVE EXT.	2
834020-002TRANS DIPSTICK TUBE	1
FG-Q59278P/S GASKET	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
H1422TSX STUD	1
5638G03-6540G COMPRESSOR HEAD	2
576403-3470 COMPRESSOR A/C 5720	1
74R258607-2613A RED DOT DRIER 7127	2
570703-3418 COMPRESSOR 4666	1
68-3963453-30LENS CLEAR FOR STRIP LIGHT	2
839012-004P/S DIP STICK	1
TH2QUIC-MOUNT TOOL HOLDER	2
A53275T1216SLACK ADJ	1
A53275U1217SLACK ADJ	1
AH0001CAST DOOR HINGE	6
OPP-503SLENS FOR OPA570	1
XMGSOP235-OPSGASKET FOR OPA570	1
P1147GFUEL FILTER 33120 WIX DELCO TP916	1
PH7405 51971 OIL FILTER WIX	4



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

- NITROGEN CHK ALL JOINTS.
- 28. ASSIST JERRY WITH AC SYST.
- 29. HELP TIRE MAN W/ JACK UP AND WHEEL COVERS.
- 30. R&R 3 MARKERS LIGHT AND TAG LIGHT ASS.
- 31. INSTALL NEW COMPRESSOR UT HAD TO CHARGE BACK ON THE COMPRESSOR ONE HOSE FITTING AND VACC SYST FOR ONE HR.
- 32. PUT TIRE AND WHEEL COVER ON FRT AXLE AND ADJ BRAKES.
- 33. CHARGE AC AND CHK SYST.
- 34. PICK UP TRACK PUT PLUG IN REAR.
- 35. CLEAN UP AROUND TRANS AND PTO TO FIND LEAK FOUND LOOSE LOCK NUT.
- 36. CHK STEP LIGHTER ON PASSENGER SIDE BOTH NEED LENS R&R LENS.
- 37. CHK PUMP PACKINGS, ADJUST AND INSTALL.
- 38. CK COMPT DOOR ALARM LIGHT FOUND LIGHT UNPLUG SO FISH WIRE OUT AND REPLUG.
- 39. CHK ON BOARD COMPRESSOR FOUND MOTOR BAD R&R COMPRESS.
- 40. ADJ LATCH ON CENTER LID IN CAB.
- 41. TIGHTEN SCREW SIGN ON LADDER.
- 42. JACKED REAR Q47 AND PULL ALL TIRES PULL AXLE AND HUB AND DRUM ON DRIVER SIDE.
- 43. ASSECT TIRES SEAL AND BRAKES.
- 44. TEST DRIVE TO CHK WHEEL AND SEAL.
- 45. CHK UNDER LADDER FOR OIL LEAK FOUND LOOSE FITTING, TIGHTEN FITTING.
- 46. ASSIST W/ LEAK REPAIR.
- 47. COOL LINE LEAKING SO I REPLACED FOR COOLERS TO SPLICE ABOUT 2 OF LINE.
- 48. R&R HINGES ON DOOR FOR STABILIZER CONTROL.
- 49. PUT CABLES AND AX ON LADDER FOR HELP TO HOLD IN PLACE.
- 50. R&R LENSE ON CASE.
- 51. CHK WINDSHIELD WASHER FOUND LOOSE BROKEN AND BENT NEED ADJUSTMENT.
- 52. TEST DROVE AND FOUND DRIVERSIDE AC QUITE NOT WORKING.
- 53. AIR IN FRT TIRES 130 PSI DROPPED IT TO 120.
- 54. NO FUSE OR RELAY PROBLEM IN FAN.
- 55. R&R FAN MOTOR IN DRIVERSIDE AC.
- 56. TEST DRIVE / ADJ BRAKES.
- 57. PUT NEW SLACE ADJ ON AND TEST DROVE.
- 58. TOOK TIRES AND DRUMS OFF FOUND ALOT OF CRACKS IN BREAK SHOE.
- 59. INSTALL FRT BRAKE ADJ AND INSTALL AND TEST DROVE.
- 60. FOUND A/C FILTER IN BACK DIRT SO R&R AC FILTER.
- 61. STARTED WIRE BUMPER LLIGHTS.
- 62. FINISH WIRE BUMPER LGHT.



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

63. R&R TRANS COOLER.

Workorder: V52152

In Date: 09/04/2012 Meter Reading:
Close Date: 09/20/2012

Problem?

Vent saw won't start. Cleaned plug, still won't start. Q47

Task performed:

REPAIRED SAW TESTED AND RAN OK. ADJ QUARTZ LIGHT SWITCH THAT WERE TURNING ON LIGHT.

Parts _____ Quantity

NO PARTS USED

Workorder: V52075

In Date: 08/31/2012 Meter Reading:
Close Date: 09/21/2012

Problem?

telescoping light on officers side is out. brow light still out Q47

Task performed:

DOOR OPEN LIGHT ON-REPAIRED BAD CONNECTION, AIR LEAK REPAIRED LEAK AT PUMP SHIFTER.

Parts _____ Quantity

NO PARTS USED

Workorder: V50356

In Date: 06/24/2012 Meter Reading:
Close Date: 09/24/2012

Problem?

brow lights not working, bulbs burn out in a couple of days. please replace. glass for officers side brow light broken Q47

Task performed:

FOUND BAD WIRE.

Parts _____ Quantity

NO PARTS USED

Workorder: V50363

In Date: 06/24/2012 Meter Reading:
Close Date: 09/24/2012

Problem?

rear hub cap on officers side missing a lug

Task performed:

WITH REPAIR WAIT FOR NEXT B INSPECTION.

Parts _____ Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V52076

In Date: 08/31/2012

Meter Reading:

Close Date: 09/24/2012

Problem?

master stream nozzle will not go up and down, Able to go side to side and from fog to straight. Q47

Task performed:

Parts

Quantity

DISASSEMBLED MOTOR AND CLEANED AND GREASED UNIT REASSEMBLED AND TESTED.

NO PARTS USED

Workorder: V52039

In Date: 08/30/2012

Meter Reading:

Close Date: 09/25/2012

Problem?

PROTECTIVE CAGE ON ONE OF THE CIRCLE D LIGHTS IS BROKEN. NOT PROTECTING BULB. Q47

Task performed:

Parts

Quantity

REPAIRED LIGHT AND REWIRED UNIT.

NO PARTS USED

Workorder: V52620

In Date: 09/25/2012

Meter Reading:

Close Date: 09/26/2012

Problem?

The electric plug in to keep the batteries at full charge continues to blow out the MDT. this was addressed when q47 was delivered for PM a couple of months ago. When the truck came back, it was not fixed.

Task performed:

Parts

Quantity

TURNT OVER TO STEVE LEE RADIO SHOP.

NO PARTS USED

Workorder: V51871

In Date: 08/25/2012

Meter Reading:

Close Date: 10/01/2012

Problem?

replaced bulb 8/20 driver side brow light. 8/24 light burned out again. please fix this problem, this has been an ongoing problem as it is not being fixed.

Task performed:

Parts

Quantity

DOOR OPEN ALARM AND LADDER NOT IN BED LIGHT ON- REPAIRED LIGHTS THAT WERE ON DUE TO WATER. UNIT NOT CHARGING REMOVED AND REPLACED ALTERNATOR.

A0014949PA4949PA/4962 320 AMP UPGRADE SADDLE MC

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V52619

In Date: 09/25/2012

Meter Reading:

Close Date: 10/16/2012

Problem?

Check charging system. Q47

Task performed:

REPLACED ALTERNATOR AND RAN NEW GROUND. POWER STEERING BOX LEAK, REPAIRED LEAK AND ROAD TESTED.

Parts

4962PAUSE 4949PA UPGRADE ALT. 320A LEECE

Quantity

1

Workorder: V52639

In Date: 09/26/2012

Meter Reading: 59,533.00

Close Date: 10/16/2012

Problem?

DOOR OPEN WARNING ON

Task performed:

FOUND QUARTZ LIGHT SWITCH WAS NO GOOD REMOVED AND REPLACED.

Parts

NO PARTS USED

Quantity

Workorder: V52718

In Date: 09/29/2012

Meter Reading:

Close Date: 10/16/2012

Problem?

tank fill recirculator valve failed. Q 47

Task performed:

REMOVED TANK TILL VALVE AND INSTALLED NEW ONE. PRIMER INOP-REMOVED AND INSTALLED NEW PRIMER.

Parts

538028052VALVE PRIMER PUMP W/HARDWARE

91368904 VALVE KIT 1 1/2 IN

Quantity

1

1

Workorder: V51707

In Date: 08/19/2012

Meter Reading: 58,484.00

Close Date: 10/26/2012

Problem?

driver side brow light out again Q 47

Task performed:

INSTALLED NEW QUARTZ LIGHTS AND WIRED AND TESTED.

Parts

J254HALOGEN BULB 1000 WATT WPB

OPA810-M10-02BROW LIGHT

PR338324070 WIX FILTER WATER

Quantity

4

2

1



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V52891

In Date: 10/05/2012
Close Date: 10/29/2012

Meter Reading: 59,796.00

Problem?

the left stabilizer light will not turn green. need to hit aerial override to engage ladder suspect left stabilizer sensor defective Q 47

Task performed:

1. RAN JACKS AND ADJUSTED ALL SWITCHES ON JACKS ALL TESTED GOOD.
2. ADJUSTED LADDER CABLES AND RAN LADDER AND GREASED.

Parts

NO PARTS USED

Quantity

Workorder: V53639

In Date: 11/08/2012
Close Date: 11/09/2012

Meter Reading: 60,666.00

Problem?

PARTS ONLY NO LABOR

Task performed:

PARTS ONLY NO LABOR.

Parts

5269LPVM-5 SM MOUNT

Quantity

8

Workorder: V53348

In Date: 10/28/2012
Close Date: 11/13/2012

Meter Reading: 60,375.00

Problem?

make repairs from ul test

Task performed:

1. MADE REPAIR TO WATERWAY SWIVAL AND TESTED.
2. REPAIRED ELECTRICAL CONNECTION AT END OF LADDER.
3. ADJUSTED RELIEF VALVE AND TESTED.

Parts

NO PARTS USED

Quantity

Workorder: V54229

In Date: 12/05/2012
Close Date: 12/07/2012

Meter Reading: 61,650.00

Problem?

Scene light out and Ram fan inop

Task performed:

INSTALL SCENE LIGHTS AND SWAY CUT RAN FAN.

Parts

4435HEADLIGHT
J254HALOGEN BULB 1000 WATT WPB

Quantity

1
4



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V53337

In Date: 10/27/2012

Meter Reading:

Close Date: 12/14/2012

Problem?

remote for aerial nozzle does not work. also if nozzle is all the way in the up position the nozzle gets stuck and has to be freed by using the allen key to crank the motor. Q 47

Task performed:

Parts

Quantity

READJUSTED STOP ON MONITOR AND CLEANED UNIT AND TESTED.

35780011AKRON MOTOR GEAR AND CONN NOZZLE

1

Workorder: V53562

In Date: 11/06/2012

Meter Reading:

Close Date: 12/14/2012

Problem?

officers side telescoping light out again

Task performed:

Parts

Quantity

REPAIRED SHORT IN WIRE.

NO PARTS USED

Workorder: V53815

In Date: 11/16/2012

Meter Reading:

Close Date: 12/14/2012

Problem?

Q47 will not switch from rescue mode to water mode from turn table.

Task performed:

Parts

Quantity

REPLACED CONNECTION ON MOTOR AND TESTED.

NO PARTS USED

Workorder: V53935

In Date: 11/21/2012

Meter Reading:

Close Date: 12/14/2012

Problem?

Ram Fan is not working properly. possible carb problem. This was put in ibem 2 weeks ago and still no one has come to fix it. Q47

Task performed:

Parts

Quantity

CLEAN CARB AND REPLACED FUEL.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V54017

In Date: 11/27/2012

Meter Reading:

Close Date: 01/03/2013

Problem?

Q47 would not transfer over to water tower mode. several attempts with no success

Task performed:

REPLACED MOTOR AND TESTED.

Parts

EL-12524ACTUATOR MOTOR

Quantity

1

Workorder: V54347

In Date: 12/10/2012

Meter Reading:

Close Date: 01/03/2013

Problem?

both the front and rear AC are blowing hot air.Q47

Task performed:

RECHARGED A/C UNIT AND REPAIRED LEAK.

Parts

NO PARTS USED

Quantity

Workorder: V54444

In Date: 12/14/2012

Meter Reading:

Close Date: 01/03/2013

Problem?

drivers side scene light out Q47

Task performed:

REPAIRED LIGHT ON DRIVERS SIDE. REPLACED MONATOR MOTOR, AND TESTED.

Parts

NO PARTS USED

Quantity

Workorder: V54445

In Date: 12/14/2012

Meter Reading:

Close Date: 01/03/2013

Problem?

officers side rear wheels need to be replaced soon. They are bridgestone 12.00r24 Q47

Task performed:

WILL REPLACED REAR TIRES.

Parts

NO PARTS USED

Quantity



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V54815

In Date: 01/04/2013
Close Date: 01/04/2013

Meter Reading: 62,723.00

Problem?

cab lock leaking hyd. fluid

Task performed:

REPLACE CAB LOCK LEAKING REPLACED R/S CAB LOCK. CLEANED ALL OIL TOP OFF RESEVOIR TESTED OK. TOP OFF COOLANT AND OIL.

Parts

Quantity

15W40BSYN OIL BULK QTS

2

827011-001CAB LIFT LOCK

1

ALA00350-50 EXTENDED LIFE COOLANT GAL

1

Workorder: V54928

In Date: 01/08/2013
Close Date: 01/08/2013

Meter Reading: 62,871.00

Problem?

pump gov. will not stay set, Q-47

Task performed:

1. Q-47 came to s/shop officer stated that the pump pressure gov. would not stay at preset settings, would go to settings then go to idle, start unit check gov. out worked ok, pump unit gov. stayed at preset setting's, hook up laptop and check for codes none found. will monitor.

Parts

Quantity

NO PARTS USED

Workorder: V54745

In Date: 01/02/2013
Close Date: 01/10/2013

Meter Reading: 62,670.00

Problem?

REPLACE REAR TIRES

Task performed:

REPAIR REAR TIRES.

Parts

Quantity

1100/1200R24/25TIRE TUBE

4

Vendor?: ELPEX

Workorder: V54544

In Date: 12/20/2012
Close Date: 01/14/2013

Meter Reading:

Problem?

jake brake not working, transmission retarder is working. Jake brake indicator stating that it is activated, but no red box comes on the display after accelerator is let up

Task performed:

ROAD TESTED TO CHECK BRAKES AND TESTED OK. AIR LEAK REPAIRED AIR LEAKS AND RETESTED.

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V54617

In Date: 12/26/2012
Close Date: 01/14/2013

Meter Reading: 62,455.00

Problem?

pump master inop

Task performed:

REMOVED AND REPLACED UNIT AND RECALBRATED UNIT.

Parts

NO PARTS USED

Quantity

Workorder: V55018

In Date: 01/12/2013
Close Date: 01/14/2013

Meter Reading:

Problem?

while driving the "check engine" light comes on and audible alarm sounds for several seconds, then shuts off. At the same time th "pro driver" screen (officer side) shows "Fuel Temperature Circuit High" and shuts off.

Task performed:

CHECK ENGINE LIGHT ON, FUEK TEMP SENSOR VOLTAGE HIGH. CHECKED CONNECTOR WILL ORDER NEW SENSOR.

Parts

23527830SENDER FUEL TEMP 60 SERIES
3157TAIL LIGHT BULBS
89073-7EJG120V-750WC BULB

Quantity

1
1
1

Workorder: V55201

In Date: 01/22/2013
Close Date: 01/23/2013

Meter Reading: 63,281.00

Problem?

On Call door open warning Q 47

Task performed:

ELECTRICAL PROBLEM DOOR ALARM ON/WATER IN CONNECTORS/CLEANED Y CONNECTORS TESTED OK

Parts

NO PARTS USED

Quantity

Workorder: V54948

In Date: 01/09/2013
Close Date: 01/25/2013

Meter Reading: 62,871.00

Problem?

replace comand master q47

Task performed:

REMOVED AND REPLACED COMAND MATER AND REPROGRAMMED.

Parts

111085COMMAND MASTER CLASS 1

Quantity

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V55330

In Date: 01/27/2013

Meter Reading:

Close Date: 01/29/2013

Problem?

officer's seat leaking air, after truck has been sitting for an hour or so, officers seat will be bottomed out Q 47

Task performed:

Parts

Quantity

REMOVED OFFICER SEAT REPAIRED AIR LINE AND REINSTALLED.

NO PARTS USED

Workorder: V54834

In Date: 01/04/2013

Meter Reading:

Close Date: 02/01/2013

Problem?

need Genesis mineral oil for Q47

Task performed:

Parts

Quantity

DROPPED OFF OIL AND REPAIR LEAK.

L0767-057GENESIS HYD FLUID

1

Workorder: V55087

In Date: 01/15/2013

Meter Reading: 63,119.00

Close Date: 02/07/2013

Problem?

Q47 FRONT SEATBELT OFFICER SIDE HAS A HOLE TORN IN THE MIDDLE OF IT. WHILE TRYING TO GET OUT OF TRUCK STRUCTURE FIRE I WAS STUCK IN SEAT CAUSE CLIP ON JACKET WENT INTO HOLE AND GOT TANGLED.

Task performed:

Parts

Quantity

INSTALLED NEW SEAT BELT IN OFFICERS SIDE.

1156BULB

10

854003-012SEAT BELT 3 POINT QUINTS

1

Workorder: V55159

In Date: 01/21/2013

Meter Reading: 63,281.00

Close Date: 02/07/2013

Problem?

Q47 OFFICER SIDE HEAD LIGHT OUT ON LOW BEAM AND DRIVER SIDE HIGH BEAM LIGHT IS OUT.

Task performed:

Parts

Quantity

1. REPLACED THREE HEADLIGHTS AND REPAIRED WIRE.

H4651USE CV TYPE SEALED BEAM

2

2. CHECKED LADDER CABLES AND ADJUSTED.

H4656USE CV TYPE HEAD LIGHT

2



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V55176

In Date: 01/20/2013

Meter Reading: 63,281.00

Close Date: 02/07/2013

Problem?

tic charger inop in cab

Task performed:

Parts

Quantity

1. REPAIRED TIC-CHARGER AND TESTED.
2. AIR LEAK - REPAIRED AIR LEAK AT AIR SEAT.

NO PARTS USED

Workorder: V55785

In Date: 02/15/2013

Meter Reading: 64,216.00

Close Date: 02/15/2013

Problem?

Door open warning on Q-47

Task performed:

Parts

Quantity

DOOR OPEN LIGHT ON REPAIRED AND TESTED.

NO PARTS USED

Workorder: V55829

In Date: 02/19/2013

Meter Reading: 64,327.00

Close Date: 02/19/2013

Problem?

Air leak Q-47

Task performed:

Parts

Quantity

AIR LEAK REPAIRED AIR LEAK AT MAIN TANK.

NO PARTS USED

Workorder: V55017

In Date: 01/12/2013

Meter Reading: 63,025.00

Close Date: 02/22/2013

Problem?

Scene light o the driver side (behind front door) cab out. Officer side "deck light" (rear of truck behind the turn table) very dim, appears to be a bad bulb?

Task performed:

Parts

Quantity

REPLACED BULBS.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V55022

In Date: 01/13/2013

Meter Reading: 63,025.00

Close Date: 02/22/2013

Problem?

Q47 WAS STUCK IN GEAR 1 AND COULD NOT BE PUT IN NEUTRAL. TRUCK WAS SHUT DOWN AND TURNED BACK ON 5 MINUTES LATER AND SEEMS TO BE WORKING FINE NOW.

Task performed:

ROAD TESTED NO PROBLEM AND FOUND CODES ORDERED PART.

Parts

NO PARTS USED

Quantity

Workorder: V55033

In Date: 01/14/2013

Meter Reading: 63,025.00

Close Date: 02/22/2013

Problem?

could not switch to neutral after driving. had to shut off the quint and restart.

Task performed:

1. MONITOR NOT WORKING IN UP POSITION - REMOVED MOTOR AND INSTALLED NEW ONE AND TESTED.
2. TRACED OUT PROBLEM WITH TRANS FOUND BAD SENDER ON TRANS - REMOVED AND REPLACED.

Parts

29543435SPEED SENSOR

821002-900SHIFTER PUSH BUTTON QUINTS

1

1

Quantity

Workorder: V55842

In Date: 02/19/2013

Meter Reading: 64,327.00

Close Date: 03/15/2013

Problem?

first compartment on driver side, hydraulic closer detached. needs repair. low voltage and low oil pressure alarm going off. Q-47

Task performed:

FOUND BAD CONNECTION ON BATTERIES FOR ALL ALARMS.

Parts

NO PARTS USED

Quantity

Workorder: V55880

In Date: 02/20/2013

Meter Reading: 64,327.00

Close Date: 03/15/2013

Problem?

Officer side brow light out. Also, the piston for keeping the door open on the first compartment door behind the pump panel (generator compartment) is off Q-47

Task performed:

REMOVED LIGHT AND REPAIRED WIRES.

Parts

60-9118OIL PRESSURE GAUGE PIERCE

1

Quantity



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V55958

In Date: 02/23/2013

Meter Reading: 64,529.00

Close Date: 03/15/2013

Problem?

A/C blowing hot air, only able to select temp in "auto" mode, when in "A/C" mode unit advises "climate control off". Q 47

Task performed:

Parts

Quantity

1. TESTED A/C FOUND UNIT WORKING.
2. CHECKED LADDER CABLES AND ADJUSTED.

NO PARTS USED

Workorder: V56034

In Date: 02/27/2013

Meter Reading: 64,593.00

Close Date: 03/15/2013

Problem?

BOTH TAIL LIGHT ARE OUT ON Q47. BRAKE LIGHTS WORK BUT NO REAR TAIL LIGHTS Q47

Task performed:

Parts

Quantity

FOUND BAD CONNECTION ON RELAY.

NO PARTS USED

Workorder: V56129

In Date: 03/04/2013

Meter Reading: 64,751.00

Close Date: 03/22/2013

Problem?

driver side "brow" light (halogen light mounted to cab) out. Bulb appears burned out Q47

Task performed:

Parts

Quantity

1. REPLACED BULB IN LIGHTS, REMOVED LIGHT FROM TRUCK AND REPAIRED.
2. DOOR OPEN ALARM REPAIRED BAD CONNECTION.

NO PARTS USED

Workorder: V56650

In Date: 03/26/2013

Meter Reading: 99,999,999.00

Close Date: 03/27/2013

Problem?

Brakes wont release. Shop notified. Q47

Task performed:

Parts

Quantity

1. REMOVED OLD BRAKE CHAMBERS AND WAITING FOR PART, AND INSTALLING NEW BRAKE CHAMBERS.
2. WENT TO TOTAL TRUCK FOR PARTS - WENT ST 47 - ASSIST IN REPLACING REAR BRAKE CHAMBERS - RETURN TO SHOP.

5004049GOV CHK VALVE KIT M2

1

GC3636TYPE 36 COMBO CHAMBER

2



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V52587

In Date: 09/24/2012

Meter Reading: 59,453.00

Close Date: 04/04/2013

Problem?

ON CALL WIPER FELL OFF Q 47

Task performed:

Parts

Quantity

1. CONTACTED CAPT HE ABLE TO MOVE

50-24WIPER BLADE - KME

2

Workorder: V53011

In Date: 10/11/2012

Meter Reading:

Close Date: 04/04/2013

Problem?

There is nother wrong with the Quint. It is running great and everything works fine. You guys are doing a great job!

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V55442

In Date: 01/31/2013

Meter Reading: 63,659.00

Close Date: 04/04/2013

Problem?

transmission getting stuck in gear

Task performed:

Parts

Quantity

1. travel to sta-47, help tommy, hook up laptop, found code for turbine sensor inop, tom will replace part. travel back to s/shop

29543435SPEED SENSOR

1

Workorder: V55172

In Date: 01/20/2013

Meter Reading: 63,281.00

Close Date: 04/05/2013

Problem?

nozzle on ladder stuck in fog position, not able to change to straight stream.

Task performed:

Parts

Quantity

REPAIRED NOZZLE AND TESTED.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V55908

In Date: 02/21/2013

Meter Reading: 64,431.00

Close Date: 04/05/2013

Problem?

fog nozzle on aerial cannot open or close. Q-47

Task performed:

REPLACED MOTOR IN NOZZLE.

Parts

Quantity

50770028MOTOR ASSEMBLY 12V FOG

1

Workorder: V56759

In Date: 04/01/2013

Meter Reading: 65,774.00

Close Date: 04/05/2013

Problem?

Air leak Front a/c inop Q-47

Task performed:

1. FIND SOURCE OF AIR LEAK. R&R GOVERNOR AND REPLACE O-RING AT FITTING TO DRYER AND TEST OK.

2. DIAGNOSE A/C SYSTEMS AND CACUATE AND RECHARGE REAR A/C SYSTEM FRONT SYSTEM EMPTY. FIND LEAKS RECRIMP HOSES AND R&R COMP FITTING O-RINGS. RECHARGE ANOTHER LEAK NEEDS HOSE BETWEEN COMP AND TEE FITTINGS.

Parts

Quantity

NO PARTS USED

Workorder: V46788

In Date: 01/23/2012

Meter Reading: 52,818.00

Close Date: 04/08/2013

Problem?

Replace broken trans dipstick

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V48071

In Date: 03/20/2012

Meter Reading:

Close Date: 04/08/2013

Problem?

Interior door alarm sounding,all doors closed. Q47

Task performed:

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V48316

In Date: 03/31/2012

Meter Reading:

Close Date: 04/08/2013

Problem?

lel sensor on scout 4 gas monitor failed Q47

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V48809

In Date: 04/22/2012

Meter Reading:

Close Date: 04/08/2013

Problem?

AERIAL NOZZLE WILL INTERMITTENTLY STICK IN POSITIONS MAKING IT IMPOSSIBLE TO MOVE WITH CONTROLS. DO NOT HAPPEN ALL THE TIME. Q47

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V50144

In Date: 06/14/2012

Meter Reading:

Close Date: 04/08/2013

Problem?

Per B/C 4 the ladder needs its 25 hour inspection.

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V53567

In Date: 11/06/2012

Meter Reading:

Close Date: 04/08/2013

Problem?

RAM fan is not running at full power. appears to be a carb problem

Task performed:

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V49866

In Date: 06/04/2012

Meter Reading:

Close Date: 04/09/2013

Problem?

TIRES ARE WORN IN NEED OF REPLACEMENT ESPECIALLY OUTSIDE RIGHT REAR

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V56215

In Date: 03/07/2013

Meter Reading: 64,915.00

Close Date: 04/10/2013

Problem?

Spot light Driver side rear is out.

Task performed:

Parts

Quantity

REPAIRED SPOT LIGHT AND TESTED.

NO PARTS USED

Workorder: V56322

In Date: 03/11/2013

Meter Reading: 65,071.00

Close Date: 04/10/2013

Problem?

left driver side scene light not working Q47

Task performed:

Parts

Quantity

REPAIRED BAD GROUND WIRE FOR SCENE LIGHT.

NO PARTS USED

Workorder: V57079

In Date: 04/16/2013

Meter Reading: 66,319.00

Close Date: 04/19/2013

Problem?

R/R/O flat

Task performed:

Parts

Quantity

R/R/O FLAT.

NO PARTS USED

Vendor?: ELPEX



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V56789

In Date: 04/02/2013

Meter Reading: 65,825.00

Close Date: 04/26/2013

Problem?

pull chord broken Q47

Task performed:

REPAIRED PULL CORD.

Parts

Quantity

NO PARTS USED

Workorder: V57067

In Date: 04/15/2013

Meter Reading:

Close Date: 04/29/2013

Problem?

AC not working in the cab. Q-47

Task performed:

1. FOUND BOTH HOSE FROM COMPRESSOR BAD AND BAD COMPRESSOR TOOK HOSES OFF AND WHEN TO MAKE TO GET HOSE MADE R&R COMPRESSOR FLASHED SYSTEM PUT NEW HOSES ON NEW DRYER CHARGED SYSTEM 3.5 BT 1 LB TO GET PRESSURE UP.

2,. ASSIST JERRY WITH ABOVE.

Parts

Quantity

435101HOSE & FITTING ASSY

1

570703-3418 COMPRESSOR 4666

1

74R258607-2613A RED DOT DRIER 7127

1

Workorder: V57096

In Date: 04/17/2013

Meter Reading:

Close Date: 04/29/2013

Problem?

vent saw wont start. no spark plugs here. Q47

Task performed:

SENT TO SHOP.

Parts

Quantity

NO PARTS USED

Workorder: V57268

In Date: 04/25/2013

Meter Reading:

Close Date: 04/29/2013

Problem?

hand held aerial remote control does not work, need a new one. Also left scene light out. Need 1000w bulbs for brow lights Q47

Task performed:

WILL NEED TO SEND OUT FOR REPAIRS.

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V56733

In Date: 03/31/2013
Close Date: 05/01/2013

Meter Reading: 65,743.00

Problem?

A/C in front cab blowing hot on all settings and at all temps. Attempted shutting down/ restarting system several times with no change. Q-47

Task performed:

A/C IN FRONT CAB BLOWING HOT ON ALL SETTINGS AND AT ALL TEMPS. ATTEMPTED SHUTTING DOWN/RESTARTING SYSTEM SEVERAL TIMES WITH NO CHANGE. Q-47.

Parts

Quantity

NO PARTS USED

Workorder: V57432

In Date: 05/02/2013
Close Date: 05/03/2013

Meter Reading:

Problem?

air horn spontaneously comes on and won't go off. q47

Task performed:

DISCONNECTED AIR HORN AT THIS TIME.

Parts

Quantity

NO PARTS USED

Workorder: V57659

In Date: 05/11/2013
Close Date: 05/13/2013

Meter Reading:

Problem?

There was what appeared to be a transmission fluid leak. I checked the trucks trani fluid level after letting it warm up for 15 minute and the trani fluis is very low. Q47

Task performed:

TRASSMISSION LEAK/ HRDRAULIC LINE LOOSE/ TIGHTENED URC CLEANED AREA TESTED OK.

Parts

Quantity

NO PARTS USED

Workorder: V57677

In Date: 05/13/2013
Close Date: 05/13/2013

Meter Reading: 67,111.00

Problem?

Coolant leak

Task performed:

COOLANT LEAK/ LOWER RADIATOR HOSE BURST/ REPAIRED LEAK NEEDS TO COME IN O REPLACE OTHER HOSE.

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V57307

In Date: 04/27/2013

Meter Reading:

Close Date: 05/16/2013

Problem?

lens on driver side brow light cracked. Q47

Task performed:

Parts

Quantity

1. AIR LEAKS GOING OFF-REPAIRED BAD CONNECTION.
2. REPAIRED LEFT REAR DOOR THAT WAS NOT CLOSING.

NO PARTS USED

Workorder: V57678

In Date: 05/13/2013

Meter Reading: 67,111.00

Close Date: 05/17/2013

Problem?

Lights flashing on and off Q47

Task performed:

Parts

Quantity

1. REPLACED PUSH BOTTON ON VISTA SCREEN.
2. AIR LEAK REPAIRED LEAK.

NO PARTS USED

Workorder: V57744

In Date: 05/15/2013

Meter Reading: 67,169.00

Close Date: 05/22/2013

Problem?

Replace lower radiator hose Q47

Task performed:

Parts

Quantity

1. DRAINED COOLANT REPLACED TWO LOWER RAD HOSES (LEAKING/WORN). ALSO REPLACED CLAMPS . REFILLED COOLING SYSTEM PRESSURE TESTED AND ROAD TESTED.
2. CHECKED FRT END ALIGNMENT SET TOE AIRED UP ALL TIRES.

NO PARTS USED

Workorder: V57369

In Date: 04/30/2013

Meter Reading:

Close Date: 05/24/2013

Problem?

Door open lights come on when all doors are closed. q 47

Task performed:

Parts

Quantity

REPAIRED ON 57678.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V57854

In Date: 05/20/2013

Meter Reading:

Close Date: 05/31/2013

Problem?

ladder alarm raised wont go off and the truck will not turn off unless the battery is shut off.

Task performed:

Parts

Quantity

1. LADDER ALARMS GOING OFF AND DOOR ALARMS GOING OFF-DRIED ALL CONNECTORS.

NO PARTS USED

Workorder: V58218

In Date: 06/05/2013

Meter Reading: 67,867.00

Close Date: 06/21/2013

Problem?

Flowmeter on stick not working. Reads zero at all times q 47

Task performed:

Parts

Quantity

1. OPERATED FLOW METER AND FOUND UNIT WORKING AT THIS TIME.

NO PARTS USED

2. RECHARGED A/C AND TESTED.

Workorder: V58458

In Date: 06/16/2013

Meter Reading: 68,198.00

Close Date: 06/24/2013

Problem?

The light sensor showing the master stream nozzle being in either Water Tower or Rescue mode is stuck in Rescue Mode. The nozzle will still transition between the two but the light stays on Rescue mode. q47

Task performed:

Parts

Quantity

REPLACED REAR LENS FOR BACK UP LIGHT.

NO PARTS USED

Workorder: V58543

In Date: 06/19/2013

Meter Reading: 68,248.00

Close Date: 06/24/2013

Problem?

repair a/c q47

Task performed:

Parts

Quantity

WORK DONE ON TICKET 58592.

BH13003993 BLOWER MOTOR +SQUIRREL CAGE ASSY.

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V58592

In Date: 06/19/2013

Meter Reading: 68,248.00

Close Date: 07/02/2013

Problem?

change lock arm on ladder and replace a/c blower motor

Task performed:

1. REPLACED BROKEN ARM FOR LOCK OUT MECHANISM ON LADDER FOR NOZZLE SLED ASSEMBLY.

2. REPLACED BLOWER MOTOR ASSEMBLY IN RIGHT SIDE A/C CONDENSER UNIT. HAD TO R&R ENTIRE ASSEMBLY TO ACCESS BLOWER MOTOR AND FANS. ALSO R EPLACED FAN SPEED RESISTER BLOWER MOTOR NOW WORKS NORMALLY.

3. ladder tip nozzle will not go from fog to straight stream, remove motor and time gears, reinstall motor, ol

4. driver side wiper blade making noise, found wiper going over to far and was very loose, remove wiper and adjust stop, tighten both wiper blades.

Parts

Quantity

123411-0806 RESISTOR BLOWER MTR A/C

1

Workorder: V58870

In Date: 07/05/2013

Meter Reading: 68,938.00

Close Date: 07/05/2013

Problem?

Ladder inop Q47

Task performed:

LADDER STUCKIN UP POSITION/SHORT IN CONTROL CIRCUIT/TROUBLE SHOOT CONTROL CIRCUIT FOUND PANEL POWER WIRE TRIPPING BREAKER TRAVEL TO SHOP TO GET SPARE FOUND A PROBLEM WITH SPARE, 47 STAYED IN Q47 WILL USE AS AN ENGINE WILL ORDER PART IN THE MORNING.

Parts

Quantity

NO PARTS USED

Workorder: V59149

In Date: 07/16/2013

Meter Reading: 68,938.00

Close Date: 07/19/2013

Problem?

it looks like a front left gear leak Q 47

Task performed:

OIL SEAL LEAK - REPAIRED FRONT HUB LEAK AND CLEANED ALL OIL OFF OF TIRE, ROAD TESTED.

Parts

Quantity

01-0269606-D0LIGHT BALLEST MINI BAR

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V58749

In Date: 06/28/2013

Meter Reading: 68,641.00

Close Date: 08/19/2013

Problem?

all 3 water tank level lights are not working

Task performed:

1. FOUND BREAKER TRIPPING ON PANEL PWR BREAKER CALLED TECH LINE AND GOT WIRE PRINTS AND FOUND WIRE 179 PUMP DES WAS SHORT TO GROUND SO WE ?????? WIRE OUT AND FOUND A SCREW IN WIRE UPON THE TURNTABLE REPAIRED WIRE AND FOUND DIODE BAD ON TURNTABLE AND ?????? BACK IN PANEL R&R ?????? AND SYSTEM WORKED.
2. PUT ALL PANEL BACK TOGETHER AND INSTALL REMOTE CONTROL BOX.

Parts

Quantity

091-84-022DIODE 6 AMP	1
333090021 DIODE MODULE	1
XE-WLPT1-SOCTANK SENSOR FOR TANK VISION	1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V58954

In Date: 07/09/2013

Close Date: 08/19/2013

Meter Reading: 68,938.00

Problem?

C inspection Q47

Task performed:

Parts

Quantity



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

1. C-INSPECTION.
2. CHECK INTAKE SCREEN FOUND NO IN RIGHT SIDE INTAKE AND INTAKE SCREEN ON FRONT BUMPER WAS BAD R&R BOTH SCREENS.
3. SERVICE T-CASE.
4. SERVICE AIR DRYER.
5. R&R CAP ON RADIATOR OVER FULL AND R&R CAP ON RADIATOR.
6. BATTERY FAILED LOAD TEST SO I R&R ALL SIX BATTERY.
7. CHECK SHORE LINE CHARGE FOUND FUSE MISSING INSTALL NEW FUSE AND CHARGED WORKS.
8. STARTED REAR BRAKES R&R DRUM, SHOE, HOOD SEAL AND ADJUST BRAKE AND TEST DRIVE BRAKE WORK GOOD.
9. REMOVE TRANS. COOLER LINE AND SEND TO MAKO INSTALL TRANS LINE AND MOVE COOLER.
10. CLEANED UP TRANS AND PTO TO FIND LEAK RAN TRUCK AND FOUND PTO LEAK ON TOP FRONT . TOOK DRIVE SHAFT OUT AND PTO OFF FOUND A BOLT MISSING ON TOP FRONT ORDER NEW GASKET SET AND BOLT INSTALL NEW GASKET ON SEALING OF PTO AND NEW BOLT.
11. START LOOK AT STEP ON PASSENGER SIDE FOUND WIRE CUT GO I LOOK WIRE DIAGRAM TOOK DRIVER SIDE WIRE DOWN TO SEE HOW IT WAS WIRED SO PUT PASSENGER AIDE TOGETHER LIKE THAT AND MAKE IT WORK.
12. GOT WITH STEVE PUT COMPUTER ON CHECK TRANS AND EGINE CODE ALL WERE NO ACTIVE OLD CODE SO WE CLEAN THEM AND WILL CHECK AFTER TEST DRIVE DID TEST DRIVE AND CHECKED CODE NO CODE FOUND INTRANS OR ENGINE.
13. R&R
14. R&R SCENE LIGHT ON DRIVER SIDE, R&R LEN ON FRONT DRIVER SIDE TIP LIGHT AND R&R CENTER MARKER LIGHT.
15. CHECK WATERWAY AND RESCURE FOUND MOTOR WAS WORKING, BOTH PER OK, SWITCH WERE GOOD FOUND AT SWITCH ON TURNTABLE WIRED WRONG WIRED IT RIGHT AND IT WORKS GOOD.
16. TRY TO REMOVE SENSOR FROM WATERWAY BUT BROKEN SENSOR SO REMOVE FLANGE AND PUSH IT OUT LOOK IN PARTS ROOM FOR SENSOR AND DID NOT FIND ONE.
17. GOT ED IN PART AND FOUND FLOW SENSOR AND REMOVE FLOW SENSOR FOR PUMP PANEL TO MAKE SHORE THE WHEEL WOULD WORK GOT BOTH SENSER WORKING SO I GOT SCOTT TO HELP AND WE CALIBRATED BOTH FLOW METER FOUND PUMP PANEL GAUGE THE LAST NUMBER DID NOT READ ALL THE NUMBER SO CHECK WITH ED W. IN

02028345000REFLECTOR	1
029-0511-00-0ANODE ONLY	1
0401590000O-RING SEAL	2
22-40868-000WASHER CAP WPB-FREIGHTLINER	1
329071-19XGSKT KIT	1
4246107LENS WILL BURT	1
4246108GASKET WIL BURT	1
5004049GOV CHK VALVE KIT M2	1
68118358130600 SER OPTIC CLEAR	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	6
H35SN12BULB	1
HP-31DBATTERY 950CCA HP-31D	6
ICC5ALLED CLEARANCE LIGHT AMBER	1
K022105PURGE VALVE AD-IP-IS	1
P1147GFUEL FILTER 33120 WIX DELCO TP916	1
PH47 51758 L/F PH725 OIL FILTERL	1
PH7405 51971 OIL FILTER WIX	2
PS683033442 FUEL FILTER	1
S775COUPLER	1
05-17223-000CAP RADIATOR 10 LB	1
0714021GASKET 2 1/2"	1
0769027STRAINER 2.5 IN	1
WAT61403STRAINER 6 IN	1
0714024GASKET 4 IN	1
REDG6S14023 GASKET 6 IN	1
111602SPS PANEL	1
1261A/C RELAY	1
23920-9213UTILITY PUMP	1
1250E473PLUG DRAIN REAR END FREIGHTLINER	1
140-2897AIR FILTER ONAN 49697	1
33063FUEL FILTER ONAN	1
51064OIL FILTER ONAN	1
A0924LADDER OUT OF SERVICE STICKER	6
20X2040WHEEL STUD	20
443838HOSED AND FITTING	1
839012-004P/S DIP STICK	1
FREIGHTSHIPPING CHARGES	1
3202099SEAL WITH RACE QUINT	2
401581GASKET AXLE FL80 R002435	2
3219F4972BRAKE DRUM QUINT	2
KIT9081BRAKE HARDWARE KIT	2
445093HOSE AND FITTING	1
5008414CARTRIDGE DC100	1
8201L17-3428 ESTER OIL E7	1
827009-002CAB LIFT CYL	1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

PARTS TO SET PRISE.

18. ASSIST WITH CALIBRATION.

19. CHECK ALL VALVE AND DRAINS OPEN ALL OUT LET AND CLOSED ALL INLETS AND DID VACUUM TEST ON PUMP AND IT PASSED.

20. TIGHTEN UP BOLT IN FRONT BUMPER AND HAD TO REMOVE 3 BOLT BECAUSE OF BAD TREADS.

21. REMOVE STICKER OFF BOTH DOORS.

22. CHECK FOR AIDECKS FOUND TWO FITTING ON THE FIRST AIR TANK R&R BOTH CHECKED AGAIN FOUND AIR LEAK ON WATER WAY VALVE TOOK WATER WAY VALVE APART FOUND ONE BOLTS AND BAD O-RING COULD NOT GET AN O-RING TO FIT SO I CUT ONE AND MADE IT FIT PUT IT TOGETHER FOUND OTHER FITTING LEAKING ND CHECK VALVE ON DRYER LEAK.

23. INSTALLED DIP STICK IN POWER STEERING.

24. CHECK AIR FOUND NO AIR STARTED TRUCK AND BUILT UP AIR AND FOUND A LEAK AT THE GOVERNOR TIGHTEN UP A PLUG, STOP THAT LEDS AND CHECKED THE REST OF TRUCK FOUND AIR LEAK AT COMPRESSER BEHIND DRIVER SEAT R&R FITTING AND STOP LEAK.

25. FOUND AIR LEAK AT TURBO SOLINOID R&R FITTINGS AND STOP LEAK.

26. INSTALLED CAB LIFT CYCLINDER ON PASSENGER SIDE TOOK HOSE OF CYCLINDER AND SEND TO MAKO TO MAKE A NEW HOSE.

27. CHECK FOAM PUMP FOUND MOTOR BAD R&R MOTOR ON FOAM PUMP.

E-600013-3052 NUT

1

FT4471BDQUINT REAR BRAKE SHOES

4

MF15PSENSOR PADDLEWHEEL

1

Workorder: V59873

In Date: 08/17/2013

Meter Reading: 69,190.00

Close Date: 08/19/2013

Problem?

air horn going off by itself. Tommy was here and thinks it was due to exposed wires under officers feet getting wet from a/c condensation on floor Q47

Task performed:

TRACED OUT PROBLEM FOUND BAD CONNECTION ON OFFICERS SIDE OF TRUCK THAT WAS SHORTING OUT WIRE.

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V59867

In Date: 08/17/2013
Close Date: 08/30/2013

Meter Reading: 69,190.00

Problem?

wiper on drivers side only clears half the windshield. Very difficult to see during heavy rain Q47

Task performed:

INSTALLED NEW WIPER ARMS ON FRONT.

Parts

857001001WIPER KIT SPEC OPPTS

Quantity

1

Workorder: V59868

In Date: 08/17/2013
Close Date: 08/30/2013

Meter Reading: 69,190.00

Problem?

2.5" intake on driver side leaking Q47

Task performed:

ADJUSTED VALVE LINKAGE AND TESTED.

Parts

NO PARTS USED

Quantity

Workorder: V59874

In Date: 08/17/2013
Close Date: 08/30/2013

Meter Reading: 69,190.00

Problem?

we are requesting new 2.5" plugs for side intakes Q 47

Task performed:

DROPPED OFF NEW INTAKE PLUGS.

Parts

NO PARTS USED

Quantity

Workorder: V60400

In Date: 09/09/2013
Close Date: 09/10/2013

Meter Reading: 69,766.00

Problem?

Replace starter

Task performed:

BAD STARTER - REPLACE STARTER MOTOR AND TEST FOR OPERATION IS WORKING NICE NOW.

Parts

NO PARTS USED

Quantity



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V59936

In Date: 08/20/2013
Close Date: 09/13/2013

Meter Reading: 69,218.00

Problem?

Ladder remote was sent out to be repaired and came back 8/16. Still does not work, was not tested at PM Q47

Task performed:

REMOTE INOP REPLACED BATTERIES AND TESTED UNIT AND TESTED OK.

Parts

NO PARTS USED

Quantity

Workorder: V60171

In Date: 08/29/2013
Close Date: 09/16/2013

Meter Reading: 69,441.00

Problem?

left scene light defaults to the on position and right does not.

Task performed:

CHECKED OPERATION OF LIGHT AND TESTED OK.

Parts

NO PARTS USED

Quantity

Workorder: V60391

In Date: 09/09/2013
Close Date: 09/16/2013

Meter Reading: 69,766.00

Problem?

Q47 won't start. Battery switch is on, Batterys appear charged, all the gauges activate. Turn the ignition switch on and push start and all that is heard is a "click" from the battery auto eject.

Task performed:

NO START FOUND BAD STARTER UNIT WAS SENT TO SHOP.

Parts

19939826356 QUINT 42MT STARTER

1

Quantity

Workorder: V60545

In Date: 09/17/2013
Close Date: 09/23/2013

Meter Reading: 70,120.00

Problem?

door not latching

Task performed:

DROVE TO STATION, TRACE OUT PROBLEM WITH DOOR READJUSTED DOOR LATCH AND TESTED.

Parts

NO PARTS USED

Quantity



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V60771

In Date: 09/25/2013

Meter Reading: 70,320.00

Close Date: 09/30/2013

Problem?

Power steering leak

Task performed:

- CHECK POWER STEERING FOUND BOTH HOSES FROM RESEVOR LEAKING SO I REMOVE THEM AND SEND TO MAKO AND FOUND O-RING ON FITTING ON DRIVE SIDE STEERING BOX LEAK R&R O-RING AND SERVICE FILTER.
- FOUND HOSE FOR CAB LIFT CYCLIND LEAKING SO REMOVE AND SEND TO MAKO.
- R&R OIL PRESSURE SENDER.
- INSTALL CAB LIFT CYLINDER HOSE.
- GOT HOSE FROM MAKO AND INSTALLED THEM FILL POWER STEERING UP RAN ENGINE AND RECHECK FLUID TEST AND CHECK ALL FLUIDS.

Parts

Quantity

448848HOSE & FITTING ASSY	1
FG-Q59278P/S GASKET	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
TRANSYNDALLISON TRANS FLUID GAL	1

Workorder: V60860

In Date: 09/30/2013

Meter Reading:

Close Date: 09/30/2013

Problem?

The PPV fan & the hydraulic power unit have gas in the oil reservoirs.

Task performed:

- Quint was sent to s/shop per Tommy to drain the engine oil and refill with new oil for both units, was told they had gas in the oil from not shutting off gas.

Parts

Quantity

2525 NAPA SPARK PLUGS CHAMPION RV17YV NGK 6630	4
BPR6ESSPARK PLUG 7131	4

Workorder: V60422

In Date: 09/10/2013

Meter Reading: 69,820.00

Close Date: 10/01/2013

Problem?

the air hose that is used for tire filling, air tools is leaking from collar. fittings on ends are new, the leak is coming from the crimped collar. requesting a new hose

Task performed:

MADE UP NEW AIR LINE AND INSTALLED ON TRUCK

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V60429

In Date: 09/10/2013
Close Date: 10/01/2013

Meter Reading: 69,886.00

Problem?

scene lights on cab in between doors default to the on position. have to be turned off manually

Task performed:

1. TESTED LIGHTS, THEY WILL HAVE TO TURN OFF MANUALLY FOR NOW UNTIL WE GET PROGRAM FROM ??????
2. AIR LEAK TRACED OUT AIR LEAKS AND REPAIRED.

Parts

NO PARTS USED

Quantity

Workorder: V60233

In Date: 09/03/2013
Close Date: 10/10/2013

Meter Reading:

Problem?

Officer side halogen "tip" light out, bulb obviously burnt out need replacement bulb. Roof ladder, on driver side of big ladder, head inspection sticker expired.

Task performed:

REPLACED OIL PRESSURE SWITCH-THAT WAS BROKEN.

Parts

23527828SENSOR OIL PRESSURE DETROIT

Quantity

1

Workorder: V60392

In Date: 09/09/2013
Close Date: 10/10/2013

Meter Reading:

Problem?

drivers side scene light burnt out

Task performed:

REPLACED ALL BULBS IN LIGHTS WERE NEEDED.

Parts

89073-7EJG120V-750WC BULB

Q1000T3CLHALOGEN LIGHT 120V/1000W

Quantity

4

4

Workorder: V60628

In Date: 09/19/2013
Close Date: 10/10/2013

Meter Reading: 70,202.00

Problem?

Repair flat tire

Task performed:

REPAIR FLAT TIRE.

Parts

NO PARTS USED

Quantity

Vendor?: ELPEX



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V60673

In Date: 09/22/2013
Close Date: 10/10/2013

Meter Reading: 70,309.00

Problem?

yellow fluid is leaking from under cab. cannot find location from underneath and cab will not tilt up. Q47

Task performed:

CHECKED LEAK FOUND ALL POWER STEERING LINES NEED TO BE REPLACED SWAPED UNIT OUT AND WILL SEND TO SHOP.

Parts

NO PARTS USED

Quantity

Workorder: V60852

In Date: 09/28/2013
Close Date: 10/10/2013

Meter Reading:

Problem?

genesis power unit is leaking mineral oil where the gasket is that attaches the resevoir to the rest of the unit

Task performed:

POWER UNIT UNIT LEAKING- REPAIRED CASKET, BUT WILL MONITOR LEAK.

Parts

NO PARTS USED

Quantity

Workorder: V58779

In Date: 06/29/2013
Close Date: 10/18/2013

Meter Reading: 70,293.00

Problem?

All tank water level gages not working Q47

Task performed:

REPAIRED ON 7/10/13 ON WORK ORDER V58749.

Parts

740-1032LOCKING ARN LH SMEAL
FREIGHTSHIPPING CHARGES

Quantity

1

45

Workorder: V58790

In Date: 06/30/2013
Close Date: 10/18/2013

Meter Reading: 70,293.00

Problem?

remote needs to be replaced, has not worked for some time Q47

Task performed:

REPAIRED ON WORK ORDER V58954

Parts

NO PARTS USED

Quantity



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V58822

In Date: 07/02/2013
Close Date: 10/18/2013

Meter Reading: 70,293.00

Problem?

Cab lift is not working, appears to be "trying" to lift the cab but the locks seem to not be releasing. Just can't check the oil and other fluid levels. q47

Task performed:

REPAIRED ON WORK ORDER V58954

Parts	Quantity
333090021 DIODE MODULE	1
DS-913REPAIR CONTROL REMOTE	1
FREIGHTSHIPPING CHARGES	45
L PLACARDLARGE SIDE PLACARD	2
S PLACARDFRONT AND BACK PLACARD	1

Workorder: V58852

In Date: 07/04/2013
Close Date: 10/18/2013

Meter Reading: 70,293.00

Problem?

engine oil leaking on to floor. unknown where it is coming from, not able to tilt the cab

Task performed:

REPAIRED ON WORK ORDER V58954

Parts	Quantity
NO PARTS USED	

Workorder: V61342

In Date: 10/17/2013
Close Date: 10/22/2013

Meter Reading: 70,970.00

Problem?

door alarm

Task performed:

DOOR ALARM GOING OFF REPAIRED BAD CONNECTION AND TESTED.

Parts	Quantity
NO PARTS USED	

Workorder: V61343

In Date: 10/17/2013
Close Date: 10/22/2013

Meter Reading: 70,970.00

Problem?

coolant leak

Task performed:

COOLANT LEAK - TRACED OUT LEAK FOUND LOWER HOSE LEAKING - REPAIRED HOSE AND ROAD TESTED.

Parts	Quantity
NO PARTS USED	

ALSO, TWO NEW TIRES INSTALLED ON FRONT.



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V61566

In Date: 10/28/2013

Meter Reading: 71,387.00

Close Date: 10/30/2013

Problem?

Genesis power unit making loud noise

Task performed:

Parts

Quantity

GENESIS POWER UNIT MAKING LOUD NOISE/
SHROUD FOR PULL START HITTING FAN/ REPAIRED
UNIT AND REARRANGED COMPARTMENT NOISES.

NO PARTS USED

Workorder: V61018

In Date: 10/05/2013

Meter Reading:

Close Date: 11/01/2013

Problem?

request to add a 12V charging port for the rear/firefighter back area of quint cab to charge trip tix hand held. Also, the current 12V in the officer seat does not charge trip tix while truck is off.

Task performed:

Parts

Quantity

INSTALLED 12 VOLT CHARGE AND MOUNT TRIP TIX

NO PARTS USED

Workorder: V62138

In Date: 11/19/2013

Meter Reading: 72,154.00

Close Date: 11/20/2013

Problem?

door alarm in cab going off

Task performed:

Parts

Quantity

FOUND ALARM GOING OFF FOR QUARTZ LIGHT
REPAIRED SWITCH AND TESTED.

NO PARTS USED

Workorder: V61017

In Date: 10/05/2013

Meter Reading:

Close Date: 11/25/2013

Problem?

door "hold open" bar on the driver compartment door (2nd back from the pump panel) broken. Genesis power unit still leaking hydraulic (mineral oil) fluid

Task performed:

Parts

Quantity

- CHECKED GENS TOOL UNIT STILL HAS LEAK WILL HAVE UNIT REPAIRED.
- SCENE LIGHT INOP- REPLACED BULBS- AND REPAIRED WIRING THAT SHORTED OUT.

Q1000T3CLHALOGEN LIGHT 120V/1000W

4



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V61880

In Date: 11/07/2013

Meter Reading:

Close Date: 11/25/2013

Problem?

Handle on the front of the MDC broke off (one side). MDC still functioning properly, handle mount just cracked and broke off.

Task performed:

Parts

Quantity

DC-WILL HANDLE REPAIRS.

NO PARTS USED

Workorder: V62068

In Date: 11/16/2013

Meter Reading:

Close Date: 11/25/2013

Problem?

GENESIS POWER UNIT THAT WAS SERVICED 11/13 MAKES AN ABNORMAL WINDING SOUND WHILE ON LOW IDLE. ASSET # 10186756 WOULD NOT BE ACCEPTED BY ABOVE BUT IS THE NUMBER Q47

Task performed:

Parts

Quantity

RAN UNIT AND FOUND NO NOISE TESTED OK.

NO PARTS USED

Workorder: V62069

In Date: 11/16/2013

Meter Reading:

Close Date: 11/25/2013

Problem?

ALL 4 TIRES ON THE REAR OF Q47 ARE WORN DOWN IN NEED OF REPLACEMENT Q47

Task performed:

Parts

Quantity

CHECKED ALL FOUR TIRES AND WILL MONITOR TIRE FOR REPLACEMENT.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V62195

In Date: 11/21/2013

Meter Reading:

Close Date: 11/25/2013

Problem?

red fluid leaking from under front of Quint. It seems to be coming from under a hose that is covered with a blue sleeve that has two hose clamps on it

Task performed:

Parts

Quantity

1. WENT TO STA 47 TO LOOK AT COOLANT LEAK. TIGHTENED CLAMP ON HOSE TO TRANS COOLER. OTHER CLAMP AS CUTTING HOSE. NEEDS TO COME TO THIS SHOP IN THE MORNING TO HAVE HOSE REPLACED.

NO PARTS USED

2. STEVE SHOWN ME THE BAD HOSE SO I REPLACED HOSE AND MOVE COOLER AND PIPE TO MAKE A BETTER FIT FILL UP WITH COOLANT AND AND PRESSURE TESTED SYSTEM AND DROVE TO SET OT TILTED CAB AND TOP OFF COOLANT.

Workorder: V62311

In Date: 11/27/2013

Meter Reading:

Close Date: 11/27/2013

Problem?

mdt not powered by the truck, will not work

Task performed:

Parts

Quantity

forwarded to radio shop

NO PARTS USED

Workorder: V62581

In Date: 12/09/2013

Meter Reading: 72,996.00

Close Date: 12/13/2013

Problem?

ON CALL COOLANT LEAK Q47

Task performed:

Parts

Quantity

REPAIRED HOSE CLAMP AND PRESSURE TESTED SYSTEM.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V61685

In Date: 11/22/2013

Meter Reading:

Close Date: 12/17/2013

Problem?

Replace battery charger

Task performed:

Parts

Quantity

INSTALLED NEW CHARGER AND REWIRED UNIT
READJUSTED AIR PUMP AND TESTED.

0913912CHARGER 2000

1

Workorder: V62043

In Date: 11/15/2013

Meter Reading:

Close Date: 12/17/2013

Problem?

primer motor is not working

Task performed:

Parts

Quantity

REPAIRED BAD CONNECTION ON PRIMER.

NO PARTS USED

Workorder: V62237

In Date: 11/24/2013

Meter Reading:

Close Date: 12/17/2013

Problem?

map light is broken Q 47

Task performed:

Parts

Quantity

1. REPLACED MAP LIGHT AND TESTED.

ART20EXTGENESIS HOSE

1

Workorder: V62238

In Date: 11/24/2013

Meter Reading:

Close Date: 12/17/2013

Problem?

outside rear tires are becoming very worn Q47

Task performed:

Parts

Quantity

LEFT SIDE CAB LOCK LEAKING- REMOVED AND
REPLACED LOCK.

827011-001CAB LIFT LOCK

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V62352

In Date: 11/30/2013

Meter Reading:

Close Date: 12/17/2013

Problem?

Genesis Power Unit STILL leaking "hydraulic" fluid out of the reservoir. Q 47

Task performed:

Parts

Quantity

PICKED UP UNIT AND WILL HAVE REPAIRED.

NO PARTS USED

Workorder: V62353

In Date: 11/30/2013

Meter Reading:

Close Date: 12/17/2013

Problem?

Tread wear on rear tires getting low, possibly need replaced Q 47

Task performed:

Parts

Quantity

1. TIRES WILL BE REPLACED.

NO PARTS USED

2. AIR LEAK REPAIRED AT DRIVERS SEAT.

Workorder: V62419

In Date: 12/02/2013

Meter Reading:

Close Date: 12/17/2013

Problem?

Per Tommy, need additional "Genesis" supply hose on Q47 to operate spare tools.

Task performed:

Parts

Quantity

DROPPED OFF NEW HOSE AND CONNECTED FITTINGS ON UNIT.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V61299

In Date: 10/17/2013

Meter Reading: 70,970.00

Close Date: 12/19/2013

Problem?

UL TEST REPAIRS Q47

Task performed:

Parts

Quantity

1. RECALABRATED GUAGE AT TURN TABLE WILL MONITOR CALABRATION.
2. READJUSTED ALL LADDER CABLES AND RAN LADDER CABLES AND RAN LADDER.
3. RESEALED ALL CABLE HOLES IN LADDER.
4. WATER WAY SEALS NEED TOBE REPLACED ONLY LEAKING SMALL AMOUNT OF WATER AT THIS TIME.
5. OVERLOAD ALARM SYSTEM INOP- REPAIRED BAD GROUND WIRE AND TESTED LIGHT.
6. TESTED PRESSURE RELIEF VALVE AND DID OPEN AT 27.5 ADJUSTED SET SCREW AND RETESTED.
7. GREASED TURN TABLE AND 90 DEGREE ELBOW AND RAN LADDER-/ GRAESE OUTRIGGERS.
8. CRACKS IN BRACKET- LADDER CRACKS WERE REPAIRED- BY OUTSIDE VENDER.

NO PARTS USED

Workorder: V62647

In Date: 12/11/2013

Meter Reading: 73,107.00

Close Date: 12/23/2013

Problem?

Replace rear tires

Task performed:

Parts

Quantity

REPLACE REAR TIRES.

NO PARTS USED

Vendor?: ELPEX

Workorder: V62539

In Date: 12/06/2013

Meter Reading:

Close Date: 12/31/2013

Problem?

WATERWAY PIPE IS LEAKING AT FITTING BETWEEN BASE OF LADDER AND FIRST FLY Q47

Task performed:

Parts

Quantity

1. READJUSTED WATERWAY- LEAK IS NOT AS BAD WILL MONITOR.
2. COOLANT LEAK- REPAIRED LEAK AT HOSE CLAMP.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V62540

In Date: 12/06/2013

Meter Reading:

Close Date: 12/31/2013

Problem?

LADDER MAKING LOUD SQUEEKING NOISE AFTER IT HAS BEEN FULLY EXTENDED, RIGHT BEFORE IT IS BEDDED. Q47

Task performed:

Parts

Quantity

TRACED OUT PROBLEM WITH LADDER FOUND SOLENOID WAS MAKING NOISE ON HYDRAULIC VALVE- SWAPPED OUT SOLENIOD AND TESTED.

NO PARTS USED

Workorder: V57581

In Date: 05/08/2013

Meter Reading:

Close Date: 01/06/2014

Problem?

a reminder that the quint needs its 25 hour ladder inspection

Task performed:

Parts

Quantity

REPAIRED ON V7854.

NO PARTS USED

Workorder: V58853

In Date: 07/04/2013

Meter Reading:

Close Date: 01/06/2014

Problem?

water tank level lights not working. all three out, 2 rainbow lights and the one on the pump panel

Task performed:

Parts

Quantity

REPAIRED ON V59954.

NO PARTS USED

Workorder: V59872

In Date: 08/17/2013

Meter Reading:

Close Date: 01/06/2014

Problem?

rear 2.5" discharge fills with water after running pump. if we don't empty it after running pump the line fills with water under pressure and leaks under rear of truck

Task performed:

Parts

Quantity

REPAIRED ON V59868.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V60053

In Date: 01/01/1900
Close Date: 01/06/2014

Meter Reading: 69,333.00

Problem?

QUINT 47-MAX GPM 1476-FAILED CAPACITY TEST.

Task performed:

TO BE RPAIRED AT P.M.

Parts

Quantity

NO PARTS USED

Workorder: V60741

In Date: 09/24/2013
Close Date: 01/07/2014

Meter Reading:

Problem?

Genesis Power Unit (asset# 10186756) leaking hydraulic fluid (mineral oil) from the main seal connecting the reservoir to the gas motor.

Task performed:

POWER UNIT LEAKING, SEAL NAD. SEAL UNIT TO RESCUE SYSTEM.

Parts

Quantity

NO PARTS USED

Workorder: V61147

In Date: 10/10/2013
Close Date: 01/24/2014

Meter Reading: 70,800.00

Problem?

Headlights default to off and scene lights default to on when starting engine

Task performed:

VERIFIED COMPLAINT. WORK COMPLETED ON ANOTHER WORK ORDER.

Parts

Quantity

NO PARTS USED

Workorder: V61273

In Date: 10/15/2013
Close Date: 01/24/2014

Meter Reading: 72,996.00

Problem?

Power steering fluid leaking from the fitting just below the reservoir. Fluid level in reservoir steadily declining, however very slight leak and fluid level still well above "add" mark.

Task performed:

VERIFIED COMPLAINT / WORK COMPLETED ON ANOTHER WORK ORDER.

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V61684

In Date: 10/31/2013

Meter Reading:

Close Date: 01/24/2014

Problem?

right scene light is out and the lens needs to be replaced

Task performed:

Parts

Quantity

1. drill holes in spacers for tripex so it does not flop in holder

NO PARTS USED

Workorder: V62985

In Date: 12/27/2013

Meter Reading: 73,899.00

Close Date: 01/24/2014

Problem?

spare genesis power unit is leaking hydraulic fluid Q 47

Task performed:

Parts

Quantity

CLEANED OFF UNIT TO CHECK LEAK - REPAIRED LEAK WILL MONITOR.

NO PARTS USED

Workorder: V63152

In Date: 01/06/2014

Meter Reading: 74,240.00

Close Date: 01/24/2014

Problem?

after the rain, the sensors for the ladder raise and back door are sounding and light in the cab are flashing, not able to stop the sound. ladder sensors have butt splices near the sensor which are exposed to the rain.

Task performed:

Parts

Quantity

REPAIRED ALL CONNECTORS THAT ARE WET AND TESTED SYSTEM.

NO PARTS USED

Workorder: V63802

In Date: 01/29/2014

Meter Reading: 75,334.00

Close Date: 02/03/2014

Problem?

Tail lights inop

Task performed:

Parts

Quantity

RESET V-MUX CHECKED WIRING OK- RETURNED TO SERVICE.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V63202

In Date: 01/07/2014

Meter Reading:

Close Date: 02/06/2014

Problem?

Spare Genesis power unit leaking "hydraulic" fluid. Used up all spare hydraulic fluid in the station and reservoir on unit is only to minimum full level. Will continue to need additional fluid.

Task performed:

1. TIRES TO REPAIR UNIT, BUT NEED TO SEND SPARE TO STATION.
2. REPAIRED COOLANT LEAK AT BOTTOM HOSE, REPAIRED CLAMPS.

Parts

Quantity

L0767-057GENESIS HYD FLUID

1

Workorder: V63235

In Date: 01/08/2014

Meter Reading:

Close Date: 02/06/2014

Problem?

need more genesis mineral oil. Unit is leaking badly q47

Task performed:

CHECKED FOR LEAK, REPAIRED FILL CAP AND FILLED UNIT WITH OIL.

Parts

Quantity

NO PARTS USED

Workorder: V64027

In Date: 02/06/2014

Meter Reading: 75,656.00

Close Date: 02/11/2014

Problem?

check auto eject

Task performed:

CHK AUTO EJECT- CHK AUTO EJECT OPERATION- EJECTS CORD WHEN CRANKING JUST BEFORE START UP CHK OK.

Parts

Quantity

NO PARTS USED

Workorder: V63730

In Date: 01/26/2014

Meter Reading:

Close Date: 02/12/2014

Problem?

used spare genesis power unit,spreaders, cutters. Unit does not provide any cutting power, unable to cut a seat back support

Task performed:

SWAPTED OUT UNIT WITH HURST POWER UNIT.

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V64099

In Date: 02/10/2014

Meter Reading: 75,828.00

Close Date: 02/12/2014

Problem?

hydraulic leak.

Task performed:

Parts

Quantity

REPAIRED FITTING ON PTO PUMP THAT WAS LEAKING RAN SYSTEM AND RECHARGED FOR LEAKS.

NO PARTS USED

Workorder: V64357

In Date: 02/19/2014

Meter Reading: 76,241.00

Close Date: 02/20/2014

Problem?

Genius tool oil

Task performed:

Parts

Quantity

PARTS ONLY.

22855316CONNECTOR

1

L0767-057GENESIS HYD FLUID

2

Workorder: V64396

In Date: 02/20/2014

Meter Reading: 76,248.00

Close Date: 02/21/2014

Problem?

Repair tire and replace tube Q47

Task performed:

Parts

Quantity

REPAIR TIRE AND REPLACE TUBE Q47.

NO PARTS USED

Vendor?: ELPEX

Workorder: V61251

In Date: 10/14/2013

Meter Reading:

Close Date: 02/27/2014

Problem?

Front Right Tire has wire showing through tire

Task performed:

Parts

Quantity

FRONT RIGHT TIRE HAS WIRE CHOWING THROUGH TIRE.

NO PARTS USED

Vendor?: BOULEVARD TIRE



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V64313

In Date: 02/18/2014

Meter Reading: 76,178.00

Close Date: 03/04/2014

Problem?

jack inop

Task performed:

FOUND ENG BRAKE INOP- DOWN LOAD NODE 2 AND 2- TEST DROVE NO CHARGE- FOUND INPUTS CHK OK- OUTPUT GROUNDS INOP- CALLED WELDON- LEFT MESSAGE- TEMP REPAIRED YOKE BRAKE TEST DROVE CHK OK.

Parts

Quantity

47153582-2116 TOGGLE SW ON/OFF

1

Workorder: V62753

In Date: 12/16/2013

Meter Reading:

Close Date: 03/05/2014

Problem?

Aerial ladder squeals noticeably upon lowering from a raised position. q47

Task performed:

1. ADJUSTED REAR DOOR THAT WAS NOT CLOSING
2. INSTALLED BATTERY CHARGER AND TESTED.

Parts

Quantity

0913912CHARGER 2000

1

FREIGHTSHIPPING CHARGES

2

HT-10189PRESSURE REDUCING VLV

1

HY-1009212V COIL

1

Workorder: V63610

In Date: 01/22/2014

Meter Reading:

Close Date: 03/05/2014

Problem?

Oil dipstick "T" handle snapped off, Need replacement. Dipstick still covers and seals the opening, just difficult to lock and unlock check oil. q47

Task performed:

1. REPAIRED HOLDER FOR TRIPIX THAT WAS BROKEN.
2. INSTALLED AND RAN NEW WIRES FOR BATTERY CHARGER.

Parts

Quantity

23532155OIL DIPSTICK ASSBLY

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V63796

In Date: 01/28/2014

Meter Reading:

Close Date: 03/05/2014

Problem?

this request has already been repaired !!! Q47 taillights and brites were out. Q47

Task performed:

Parts

Quantity

CHECKED ALL LIGHTS AND CONNECTION ALL TESTED OK AT THIS TIME.

NO PARTS USED

Workorder: V63965

In Date: 02/04/2014

Meter Reading:

Close Date: 03/05/2014

Problem?

q47 on board battery charger blows fuse and interrupts laptop when plugged in.needs replacement.

Task performed:

Parts

Quantity

REMOVED AND INSTALLED NEW CHARGER.

NO PARTS USED

Workorder: V64088

In Date: 02/09/2014

Meter Reading:

Close Date: 03/05/2014

Problem?

makes a thud under the officers floor board when braking. can actually feel whetever it is hit the floorboard.

Task performed:

Parts

Quantity

ROAD TESTED TRUCK AND READJUSTED BRAKES AND TESTED OK.

NO PARTS USED

Workorder: V63731

In Date: 01/26/2014

Meter Reading:

Close Date: 03/12/2014

Problem?

DOOR AJAR ALARM AND LIGHT ACTIVATED(CONSTANT) AND NO DOORS ARE OPEN

Task performed:

Parts

Quantity

TRACED OUT PROBLEM WITH DOOR AJAR LIGHT FOUND BAD CONNECTION.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V64430

In Date: 02/21/2014

Meter Reading: 76,268.00

Close Date: 03/19/2014

Problem?

Mount SCUBA equipment in Q47

Task performed:

REMOVED CABNET AND INSTALLED DIVE BOTLE HOLDERS.

Parts

ULLH-EZOAIR BRACKETS

Quantity

4

Workorder: V64532

In Date: 02/25/2014

Meter Reading:

Close Date: 03/19/2014

Problem?

auto eject for shore line not working Q47

Task performed:

REPLACED AUTO EJECT PLUG AND TESTED.

Parts

091-20WP-120AUTO EJECT

Quantity

1

Workorder: V64533

In Date: 02/25/2014

Meter Reading:

Close Date: 03/19/2014

Problem?

St47 is requesting 8) 1000W halaogen bulbs for brow lights and scene lights Q47

Task performed:

REPLACED FOUR HALOGEN LIGHTS THAT WERE OUT.

Parts

NO PARTS USED

Quantity

Workorder: V62993

In Date: 12/28/2013

Meter Reading:

Close Date: 03/20/2014

Problem?

The back up genesis unit is spraying fluid out of the male coupling end when it is not connected to a tool. It still will power a tool, b less efficiency due to fluid issue

Task performed:

REPAIRED BY TORCHIA ON ANOTHER ORDER.

Parts

NO PARTS USED

Quantity



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V65131

In Date: 03/23/2014
Close Date: 03/24/2014

Meter Reading: 77,341.00

Problem?

light broke off ladder q47

Task performed:

CHECKED LIGHT FOR DAMAGE, WILL NEED TO REPLACE LIGHT ALSO WILL NEED TO REPLACE LADDER/RESCUE MODE BRACKET DO TO IT GOT HUNG UP ON LADDER.

Parts

NO PARTS USED

Quantity

Workorder: V62042

In Date: 11/15/2013
Close Date: 03/26/2014

Meter Reading:

Problem?

outside rear tires on both sides are becoming very worn

Task performed:

REPAIRED ON WORK ORDER #62238.

Parts

NO PARTS USED

Quantity

Workorder: V65379

In Date: 04/01/2014
Close Date: 04/01/2014

Meter Reading: 77,621.00

Problem?

nozzle at ladder tip will not open, Q-47

Task performed:

1. travel to sta-47, work with wayne from conam testing to get the nozzle to work, travel back to s/shop

Parts

NO PARTS USED

Quantity

Workorder: V64852

In Date: 03/11/2014
Close Date: 04/08/2014

Meter Reading: 76,915.00

Problem?

quartz lights inop

Task performed:

REMOVED AND REPLACED BULB.

Parts

377R054FEET - HURST TOOL	1
EG-3500OIL CAP HONDA	1
Q1000T3CLHALOGEN LIGHT 120V/1000W	7

Quantity



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V65710

In Date: 04/15/2014

Meter Reading: 78,148.00

Close Date: 04/15/2014

Problem?

Low voltage alarm

Task performed:

LOW VOLTAGE ALARM, ALTERNATOR BAD.
REPLACED ALTERNATOR TRAVEL TO FIRE SCENE,
GET BACK TO STATION TO CCOMPLETE REPAIRS,

Parts

Quantity

A0014949PA4949PA/4962 320 AMP UPGRADE SADDLE MC

1

Workorder: V65126

In Date: 03/22/2014

Meter Reading:

Close Date: 04/17/2014

Problem?

Q47 needs new wiper blades.

Task performed:

REPLACED WIPER BLADES.

Parts

Quantity

X-OP250-12MOUNT FOR OPA810 LEFT

1

X-OP251-12BRACKET OPA RIGHT

1

Workorder: V65182

In Date: 03/24/2014

Meter Reading:

Close Date: 04/17/2014

Problem?

Cover for the drivers side telescope light is broken . Light is still intact and working.

Task performed:

REMOVED AND REPLACED GLASS ON LIGHT.

Parts

Quantity

NO PARTS USED

Workorder: V65865

In Date: 04/22/2014

Meter Reading: 78,309.00

Close Date: 04/24/2014

Problem?

ON CALL UNIT OVERHEATING Q 47

Task performed:

REPLACE FAN BELTS.

Parts

Quantity

9435BELT

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V65449

In Date: 04/04/2014
Close Date: 04/25/2014

Meter Reading: 77,682.00

Problem?

no 110 to ladder

Task performed:

1. REPAIRED CONNECTION AT BOTTOM OF LADDER FOR 110 VOLTS.
2. REMOUNTED HURST TOOL IN REAR.

Parts

NO PARTS USED

Quantity

Workorder: V65524

In Date: 04/07/2014
Close Date: 05/09/2014

Meter Reading: 77,892.00

Problem?

Repair monitor

Task performed:

1. REPAIRED HEAD LIGHT.
2. GREASED MONITOR WILL NEED TO ORDER PARTS FOR MONITOR.

Parts

H4656USE CV TYPE HEAD LIGHT

Quantity

1

Workorder: V65679

In Date: 04/13/2014
Close Date: 05/09/2014

Meter Reading:

Problem?

Loud squeeling noise from the engine when truck is at high RPM and under a load. Possibly a loose belt ??? Everything runs fine and it only seems to happen when driving (intial take off from a stop light) Q47

Task performed:

READJUST BELTS AND ROAD TESTED.

Parts

K080570BELT

K080590AC BELT WPB

Quantity

1

1

Workorder: V65756

In Date: 04/16/2014
Close Date: 05/09/2014

Meter Reading:

Problem?

Hydraulic fluid leaking from the rear of the quint while operating the stabilizers/ladder. Leaking directly under the "control panel" in the rear of the quint

Task performed:

TRACED OUT LEAK AND FOUND FITTING ON HIGH PRESSURE BLOCK LEAKING/REPAIRED.

Parts

NO PARTS USED

Quantity



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V65866

In Date: 04/22/2014

Meter Reading: 78,309.00

Close Date: 05/09/2014

Problem?

A/C 10-7 Q 47

Task performed:

1. REPLACED A/C BELTS AND TESTED.
2. COOLANT LEAK REPLACED HOSE CLAMP AND ROAD TESTED.
3. CHECK ENGINE LIGHT ON- EGR VALVE STUCK WILL NEED TO SWAP OUT.

Parts	Quantity
9420BELT	1
9435BELT	1
ALA00350-50 EXTENDED LIFE COOLANT GAL	6

Workorder: V66245

In Date: 05/05/2014

Meter Reading: 78,436.00

Close Date: 05/13/2014

Problem?

repair egr fault

Task performed:

repair egr fault

Parts	Quantity
NO PARTS USED	

Vendor?: FLORIDA DETROIT

Workorder: V66324

In Date: 05/08/2014

Meter Reading: 78,436.00

Close Date: 05/13/2014

Problem?

genesis oil

Task performed:

LD DELIVERED.

Parts	Quantity
110527AIR DRAIN VALVE	1
L0767-057GENESIS HYD FLUID	1

Workorder: V66459

In Date: 05/13/2014

Meter Reading: 78,436.00

Close Date: 05/21/2014

Problem?

R/R/O flat

Task performed:

R/R/O flat

Parts	Quantity
NO PARTS USED	

Vendor?: ELPEX



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V65398

In Date: 04/02/2014

Meter Reading:

Close Date: 06/10/2014

Problem?

Nozzle stuck pointing down, would not move while under pressure. Q47

Task performed:

Parts

Quantity

grease nozzle and tested ran unit up down and side to side tested ok.

NO PARTS USED

Workorder: V66417

In Date: 05/12/2014

Meter Reading:

Close Date: 06/10/2014

Problem?

Cutiing blades on Genesis cutters are chipped and need replacing. Cutters asset # is 10186845

Task performed:

Parts

Quantity

willl order new blades and install when parts come in.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V65929

In Date: 04/23/2014

Meter Reading:

Close Date: 06/11/2014

Problem?

crosslay #1 discharge gauge is not working properly. Pumped at 300 psi during hose testing, would not go over 150psi

Task performed:

Parts

Quantity



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Began Changing out sliding waterway cradle on the end of the ladder.

Continued changing cradle. Removed cradle from ladder and began Drilling all holes.

Continued changing out cradle: Continued drilling holes for waterway and mounts. Also painted drilled areas.

Finished prep work on cradle and began reassembly. Assist in slide cradle replacement.

Continued/ Completed changing out nozzle slice cradle tested release locking mechanism. All worked well.

Replaced laddle nozzle center section as per tommy t. Also removed motor and gear assemble for nozzle stream Adjustment, clean and lubed and reassessmbled. (seized)

Installed new brow light on Drivers side of cab (broken) Also moved passenger light over on bracket to avoid contact with ladder nozzle sliding cradle.

Repaired hydraulic fluid leak at rear of truck. Remoed hydraulic fitting from valve. Replaced o-ring. Reinstalled fitting and tested hydraulics. No further sign of leak.

Replaced numerous ladder rung rubber covers.

Checked out Vista Scheen inop. Removed dash panel and found scheen unplugged. Secured plug and reinstalled dash.

Connected truck to hydrant to flow water and check for leaks and operation. found nozzle leaking at up and down joint. Turn nozzle down.

Completed tear down and cleaning of nozzle, nozzle motor and gear case. Ordered parts for reassembly.

Repaired 2 marker lights on cab roof. Cut out faulty power and ground connection and replaced with heat shrink connections.

Began reassembly of ladder nozzle.

Continued / Completed Reassembly of nozzle.

Connected truck to hydrant and flow water through nozzle. Nozzle worked normally but still had leak at up and down pipe pivot point. Began 2nd disassembly.

Began Reassembly again with propper o-rings.

Drove to station 23 to fuel truck (empty)

Continued to assemble nozzle. Tested nozzle assembly and found elbows. Cleaned and prepped all parts for reassembly.

Continued reassembly nozzle assembly. Completed installation. Pumped water with truck. No further leaks at nozzle assembly.

Trouble shot door alarm going off constantly.

067877AKRON NOZZEL KIT	1
0679383578 STREAM MASTER KIT	1
109342PKG BEARINGS 50	1
FRT 66081FREIGHT CHARGE	1
6122500061225000 PLUG	1
51600001BAFFLE ASSY 1250G AKRON	1
OPA810-M10-02BROW LIGHT	1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V65385

In Date: 04/02/2014

Meter Reading: 77,633.00

Close Date: 06/16/2014

Problem?

MAKE REPAIRS FROM UL TEST

Task performed:

- 1) ladder repairs to tip done at shop.
- 2) rung cover has been replaced.
- 3) recalabrated ladder over load light.
- 4) nozzle porblem has been repaired nozzle has been rebiulded and tested.

Parts

Quantity

740-1031PINN FRAME

1

740-1032LOCKING ARN LH SMEAL

1

740-1075LOCKING ARM RH SMEAL

1

740-2342LEVER PINN

1

752-0011RUNG COVER 8.5 KIT

4

774-0344RUNG CLIP

4

FREIGHTSHIPPING CHARGES

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V66657

In Date: 05/21/2014

Meter Reading: 78,436.00

Close Date: 06/18/2014

Problem?

B inspection Q47

Task performed:

- 1) ser. trans,
- 2) ser, t. case.
- 3) R&R batteries.
- 4) trouble shooting electrical problem found bad ground wires in wrong place
reprgram all nodes and replaced node 6 to fix eng, high idle and jake brake
and door ajar light and right left scene on cab.
- 5) assect with elec, troubleshooting .
- 6) assect.
- 7) ck, clean turn sigal light on left side found bad bulb
R&R light asem, had to remove trim to replace light.
- 8) R&R water level gauge on left side because LED light wires rip out.
- 9) R&R water way relief valve.
- 10) WORK ON pm LIST REPAIRED COOLANT leaks on lower radiator hoses.
- 11) work on PM list repairs.
- 12) work on PM list repairs, replaced L2 compartment door springs & stopers.
- 13) B ser, rebiuld water values after vac, test.

Parts

Quantity

02028345000REFLECTOR	1
15W40BSYN OIL BULK QTS	36
29526898 29548988 TRANS FILTER ALLISON	1
5008414CARTRIDGE DC100	1
68118358130600 SER OPTIC CLEAR	1
75W90GEAR OIL SYN QT	5
84-1041RELAY CONNECTOR	1
91378905 VALVE KIT 2 IN AKRON	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	6
CA7230WA10116 AIR FILTER 46893 WIX	1
H35SN12BULB	1
HP-31DBATTERY 950CCA HP-31D	6
K022105PURGE VALVE AD-IP-IS	1
P1147GFUEL FILTER 33120 WIX DELCO TP916	1
PH47 51758 L/F PH725 OIL FILTERL	1
PH7405 51971 OIL FILTER WIX	2
PL-11005 WATERWAY RELIEF VALVE	1
35200-YLIGHT MARKER LEDAMBER	1
94862PIGTAIL LED MARKER LIGHTS	1
HLD374211 IN HOLD-OPEN 30LB	1
52-624SWITCH DOOR	5
91398907 VALVE KIT 3 IN AKRON	2
91388906 VALVE KIT 2.5 IN AKRON	1
A0924LADDER OUT OF SERVICE STICKER	8
PS683033442 FUEL FILTER	1
TRANSYNDALLISON TRANS FLUID GAL	6
VF445F11FSO140A RELAY A/C DIODE SUP	1

Workorder: V66934

In Date: 06/03/2014

Meter Reading: 78,805.00

Close Date: 06/18/2014

Problem?

A/C inop

Task performed:

a/c inop low freon add freon found leal on schrader value on high side repaired leak.

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V67235

In Date: 06/16/2014

Meter Reading:

Close Date: 06/20/2014

Problem?

DRIVER SIDE OUTER REAR TIRE LOW ON AIR 60 LBS UNABLE TO FILL WITH OUR COMPRESSOR.

Task performed:

Parts

Quantity

DRIVER SIDE OUTER REAR TIRE LOW ON AIR 60 LBS UNABLE TO FILL WITH OUR COMPRESSOR.

NO PARTS USED

Vendor?: ELPEX

Workorder: V66889

In Date: 05/31/2014

Meter Reading:

Close Date: 06/23/2014

Problem?

Officer's side brow light is out.

Task performed:

Parts

Quantity

offices side quartz light out replaced

NO PARTS USED

Workorder: V66899

In Date: 05/31/2014

Meter Reading:

Close Date: 06/23/2014

Problem?

brow light on officer side out, telelight on driver side out, green "cab lift" (officer side pump panel) light on (can't get it to turn off).

Task performed:

Parts

Quantity

replaced bulb and repaired connections.

NO PARTS USED

Workorder: V66909

In Date: 06/01/2014

Meter Reading:

Close Date: 06/23/2014

Problem?

driver side telescoping light out along with officers side brow light. 47 is requesting 10 1000w bulbs be sent to 47

Task performed:

Parts

Quantity

driver quartz light out replaced
alarms going off in cab found door open alarm going off repaired

J254HALOGEN BULB 1000 WATT WPB

4



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V66970

In Date: 06/04/2014

Meter Reading:

Close Date: 06/23/2014

Problem?

driver low beam headlite out. q47

Task performed:

Parts

Quantity

repaired connections no back of head lights plug and test ok.

NO PARTS USED

repaired air leak at main tank.

Workorder: V67426

In Date: 06/24/2014

Meter Reading: 79,632.00

Close Date: 06/26/2014

Problem?

L/R/O flat

Task performed:

Parts

Quantity

NO PARTS USED

Vendor?: ELPEX TIRES

Workorder: V67429

In Date: 06/24/2014

Meter Reading: 79,632.00

Close Date: 06/26/2014

Problem?

L/R/I flat

Task performed:

Parts

Quantity

NO PARTS USED

Vendor?: ELPEX TIRES

Workorder: V67497

In Date: 06/27/2014

Meter Reading: 79,666.00

Close Date: 06/30/2014

Problem?

Coolant leak

Task performed:

Parts

Quantity

went to sta 47 raised ladder to raise cab found lower hose blown R&R hoses fill with coolant ck. for leaks ck, ok.

ALA00350-50 EXTENDED LIFE COOLANT GAL

3



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V67170

In Date: 06/12/2014

Meter Reading:

Close Date: 07/03/2014

Problem?

Front tires seem to have some excessive wear, especially on the inside portion of the tread. Genisis Cutters need new "blades". Several "chips" out of current ones

Task performed:

1. REMOVED AND REPLACED BLADES ON GENISIS TOOL.
2. OIL LEAK REPAIRED LEAK AT DRAIN PLUG.
3. REPLACED FRONT TIRES.

Parts

NO PARTS USED

Quantity

Workorder: V67339

In Date: 06/19/2014

Meter Reading:

Close Date: 07/03/2014

Problem?

Master discharge gauge is leaking fluid, quarter low now.

Task performed:

REMOVED AND INSTALLED NEW MASTER GUAGE.

Parts

5921SPARK PLUG REPLACES BM6A
 91583953GAUGE COMPOUND LIQUID FILLED
 BPM8YSPRK PLUG BLOWER

Quantity

3
1
1

Workorder: V67512

In Date: 06/27/2014

Meter Reading:

Close Date: 07/07/2014

Problem?

Check engine, stop engine, and low coolant light come on, on the dash each time the truck is started and then go off after several minutes. Coolant level seems OK.

Task performed:

TRAVEL TO ST-47 CHECKING

Parts

ALA00350-50 EXTENDED LIFE COOLANT GAL
 TRANSYND-GGAL CONTAINER TRANS FLUID

Quantity

2
1

Workorder: V65930

In Date: 04/23/2014

Meter Reading:

Close Date: 07/08/2014

Problem?

light just behind officers window(small 4 X 6") not working and lens is oxidized. requesting a replacement

Task performed:

repaired on C SER,AT SHOP V66657 TICKET

Parts

NO PARTS USED

Quantity



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V65931

In Date: 04/23/2014

Meter Reading:

Close Date: 07/08/2014

Problem?

R Rear Discharge valve not closing all the way. We leave the bleeder open because the pipe gets charged with water during check out in the am

Task performed:

Parts

Quantity

REPAIRED AT TIME OF C SER, AT SHOP V66657

NO PARTS USED

Workorder: V67775

In Date: 07/08/2014

Meter Reading: 80,063.00

Close Date: 07/10/2014

Problem?

Q47 not going into pump gear

Task performed:

Parts

Quantity

Traced out problem and found bad connection on pump switch. Repaired and tested.

NO PARTS USED

Workorder: V64225

In Date: 02/14/2014

Meter Reading: 75,995.00

Close Date: 07/17/2014

Problem?

Jake brake inop

Task performed:

Parts

Quantity

repairs done on ticket 64313 at shop.

600000003NODE HERCULES V-MUX

1

Workorder: V65399

In Date: 04/02/2014

Meter Reading:

Close Date: 07/17/2014

Problem?

Flowmeter on aerial needs to be calibrated. At 250psi discharge pressure the meter indicates only 704 gpm on a good hydrant. Does not seem correct

Task performed:

Parts

Quantity

pressure relief valve open up at 260psi tested ok.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V67110

In Date: 06/10/2014

Meter Reading:

Close Date: 07/21/2014

Problem?

Left strobe light above wheel wel 10-07, Right front brow light 10-07

Task performed:

Parts

Quantity

repaired bad connection in rear strobes
traced out problem with genertor not starting found bad connection.

NO PARTS USED

Workorder: V67868

In Date: 07/13/2014

Meter Reading:

Close Date: 07/21/2014

Problem?

A/C in cab not blowing cold, possibly due to "short curcit" alarm on vista screen?????

Task performed:

Parts

Quantity

Found short circuit message on vesta screen.Related to front A/C compressor. Brought to shop and replaced A/C comp. Ran system. All ok. Brought back to staion.

570703-3418 COMPRESSOR 4666

1

Workorder: V67274

In Date: 06/17/2014

Meter Reading:

Close Date: 07/22/2014

Problem?

driver side rear (outter tire) still slowly leaking air... at 35 psi this morning, elpex out yesterday, checked and filled tire to 120psi. Elpex tech advised possibly valve stem extension?????

Task performed:

Parts

Quantity

REPAIRED BY TIRE SOLES

NO PARTS USED

Vendor?: TIRE SOLES

Workorder: V67085

In Date: 06/09/2014

Meter Reading:

Close Date: 07/23/2014

Problem?

Left rear inside tire is flat.

Task performed:

Parts

Quantity

tire repaired on jun 16 ticket v76235 complete.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V67415

In Date: 06/24/2014

Meter Reading:

Close Date: 07/25/2014

Problem?

TIC base not charging TIC unit, replaced battery this morning with spare from base in truck and TIC would not turn on. Spare batt. charger on base seems to be working properly.

Task performed:

Parts

Quantity

CK, TIC CHARGER AND REPAIRED CONNECTION.

NO PARTS USED

Workorder: V67878

In Date: 07/13/2014

Meter Reading:

Close Date: 07/25/2014

Problem?

power steering fluid leaking from reservoir, found when cab was raised. Q47

Task performed:

Parts

Quantity

REPAIRED LEAK AT TANK WILL MONATOR LEAK.

NO PARTS USED

Workorder: V68112

In Date: 07/23/2014

Meter Reading:

Close Date: 08/05/2014

Problem?

officers side rear outside tire is very worn and may need to be replaced soon. drivers side outside rear tire also becoming worn, not as much as other side Q47

Task performed:

Parts

Quantity

ck, tires and will monator tires at this time.

NO PARTS USED

Workorder: V68453

In Date: 08/06/2014

Meter Reading: 81,254.00

Close Date: 08/07/2014

Problem?

Check front suspension

Task performed:

Parts

Quantity

TRAVEL TO STA,47 CK, OUT FRONT END FOR CRACKING NOISE OK, STRAIGHT AXEL.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V68476

In Date: 08/07/2014

Meter Reading:

Close Date: 08/07/2014

Problem?

low voltage alarm keeps activating, truck had been charging and charger indicated a full battery. Q47

Task performed:

Went to 47. Raised ladder and cab found alternator not charging. Removed batteries cables , alternator cables , belt and alternator. Remove and replace alternator. Reassembled. Check charging system. Checked ok. Lowered cab and ladder, parked truck.

Parts

Quantity

A0014949PA4949PA/4962 320 AMP UPGRADE SADDLE MC

1

Workorder: V68381

In Date: 08/04/2014

Meter Reading:

Close Date: 08/08/2014

Problem?

tip light glass lens was broken by a overhanging tree branch. light is fine, just glass needs to be replaced.

Task performed:

Went to 47. Found left light glass cracked. Disassembled and removed broken glass. Replaced lense. Checked ok.

Parts

Quantity

J254HALOGEN BULB 1000 WATT WPB

2

Workorder: V68710

In Date: 08/15/2014

Meter Reading:

Close Date: 08/22/2014

Problem?

OUTSIDE REAR TIRES ARE VERY WORN, OFFICERS SIDE OUTSIDE REAR TIRE NEEDS TO BE REPLACED VERY SOON q47

Task performed:

CK, REAR TIRES AND NEEDS TO BE REPLACED.

Parts

Quantity

NO PARTS USED

Workorder: V68966

In Date: 08/26/2014

Meter Reading: 81,876.00

Close Date: 08/28/2014

Problem?

Replace rear tires

Task performed:

Replace rear tires.

Parts

Quantity

NO PARTS USED

Vendor?: ELPEX



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V68911

In Date: 08/23/2014
Close Date: 08/29/2014

Meter Reading: 81,816.00

Problem?

coolant leak

Task performed:

Repaired coolant leak and pressure. Tested system.

Parts

NO PARTS USED

Quantity

Workorder: V68891

In Date: 08/23/2014
Close Date: 09/08/2014

Meter Reading:

Problem?

--A/C in cab blowing hot air --Door hold open piston on officer side rear compartment broken

Task performed:

INSTALLED LED SPOT LIGHTS AND WIRESD LIGHTS
A/C INOP, REPAIRED BAD GROUND ON
COMPRESSOR.
DOOR HOLD OPEN PISTON BROKEN R&R PISTON.

Parts

ALA00350-50 EXTENDED LIFE COOLANT GAL
ELSS-XLAC-BLLED BROW LITE 120V

Quantity

6
2

Workorder: V68300

In Date: 07/31/2014
Close Date: 09/10/2014

Meter Reading: 80,940.00

Problem?

coolant leak

Task performed:

1. travel to scene where truck broke down bring coolant
and assist tommy with repairs, travel back to s/shop

Parts

NO PARTS USED

Quantity

Workorder: V69134

In Date: 09/03/2014
Close Date: 09/19/2014

Meter Reading: 82,114.00

Problem?

cab a/c

Task performed:

recharged system and repaired leak at compressor

Parts

NO PARTS USED

Quantity



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V69095

In Date: 09/01/2014

Meter Reading:

Close Date: 09/23/2014

Problem?

Emergency light outside of drivers door not functioning.

Task performed:

1. replace l/side led lite
2. remove and repair driver side mirror
3. check driver side windshield wiper, order new motor, will install when in

Parts	Quantity
60R00FRR600 SERIES RED LED W/O FLANGE	1
857001001WIPER KIT SPEC OPPTS	1

Workorder: V69630

In Date: 09/23/2014

Meter Reading: 82,828.00

Close Date: 09/24/2014

Problem?

Replace rear tires

Task performed:

Replace rear tires

Parts	Quantity
NO PARTS USED	

Vendor?: ELPEX

Workorder: V69287

In Date: 09/11/2014

Meter Reading: 82,409.00

Close Date: 09/29/2014

Problem?

coolant leak

Task performed:

REPAIRED COOLANT LEAK AT TOP HOSE.

Parts	Quantity
NO PARTS USED	

Workorder: V69375

In Date: 09/14/2014

Meter Reading:

Close Date: 09/29/2014

Problem?

EMERGENCY LIGHT JUST ABOVE DRIVERS SIDE FRONT WHEEL IS NOT WORKING. HAD JUST BEEN REPLACED AT SOUTH SHOP 1 WEEK AGO Q47

Task performed:

REPAIRED BAD GROUND ON LIGHT

Parts	Quantity
NO PARTS USED	



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V69480

In Date: 09/18/2014
Close Date: 10/10/2014

Meter Reading: 82,586.00

Problem?

handlights on q47 are old and no longer bright in fire conditions. FF Q47 position handlight harness/craddle is broken and handlight does not stay in craddle to be charged any longer. Requesting new LED handlights

Task performed:

Parts

Quantity

1. Repaired air leaks.

NO PARTS USED

2. Repaired coolant leak at top of radiator.

Workorder: V69729

In Date: 09/26/2014
Close Date: 10/29/2014

Meter Reading: 83,017.00

Problem?

ladder pipe leaking between 2nd and 3rd fly Q47

Task performed:

Parts

Quantity

1. Checked for leak on water way, found small leak- Will monitor.

NO PARTS USED

2. Traced out air leak (found) and repaired.

3. Repaired left rear cab door that was hard to close and open.

Workorder: V69452

In Date: 09/17/2014
Close Date: 10/30/2014

Meter Reading: 82,586.00

Problem?

orange strobe light on the ladder(overload warning light) is not working. Officers side Q47

Task performed:

Parts

Quantity

1. Repaired connection in yellow light and repaired wires

NO PARTS USED

2. Repaired air leak at drivers seat and tested



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V70128

In Date: 10/14/2014
Close Date: 10/31/2014

Meter Reading: 83,515.00

Problem?

Ladder does not stay in position, slowly drops when fully extended. dropped 1 foot in 30 minutes. Ladder also making loud sound when bedding

Task performed:

Set up ladder made a mark on cylinder to check drift- Drift was in spec. check leak on rear of track. Found o-ring bad on stablizer valve back, remove and replace o-ring and stop leak.

Parts	Quantity
046-0040-000GASKET CAP PLATE	1
115-0670-00-0CAP PLATE	1
FRT V66885FREIGHT CHARGE	1
HY10172VALVE NEEDLE	1
HY10382SV3 CARTRIDGE SMEAL	2

Workorder: V70582

In Date: 10/30/2014
Close Date: 11/03/2014

Meter Reading: 84,225.00

Problem?

weigh vehicle

Task performed:

1. Weighed truck on all four wheels and gave figures to E. Ehrke.

Parts	Quantity
NO PARTS USED	

Workorder: V70479

In Date: 10/27/2014
Close Date: 11/10/2014

Meter Reading: 84,047.00

Problem?

coolant leak

Task performed:

Truck broke down-Found blown coolant hose, replaced hose clamp and top off coolant.

Parts	Quantity
101305009SS0001 CPI SHELF BRACKET ONE HOLE 2005 I	6
89S203468BB0667STRUT	1
ALA00350-50 EXTENDED LIFE COOLANT GAL	12
FHLP-6TANK CLIP	4
OPA570SCENE LIGHT	1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V70499

In Date: 10/28/2014

Meter Reading: 84,152.00

Close Date: 11/10/2014

Problem?

replace scene lights with LED's

Task performed:

Replaced cab light with LED light

Parts

Quantity

ELSS-XLACLED LIGHT ONLY 120V

2

Workorder: V70711

In Date: 11/04/2014

Meter Reading:

Close Date: 11/18/2014

Problem?

Q47 is leaking engine oil, unknown where it is coming from. Q47

Task performed:

Traced out oil leak, found leak at oil pan gasket-will have repaired at B.

Parts

Quantity

NO PARTS USED

Workorder: V71095

In Date: 11/20/2014

Meter Reading: 84,983.00

Close Date: 11/21/2014

Problem?

Repair ram fan

Task performed:

Replace pull cord-remove cord cover install new cord and handle.

Parts

Quantity

31-907STARTER GRIP

1

Workorder: V71365

In Date: 12/03/2014

Meter Reading: 85,426.00

Close Date: 12/04/2014

Problem?

remove front suction

Task performed:

1. Remove front dischagre pipe-install cap plate on pump seal air hoses to pipe valve, replace hydraulic calender ladder-check valves.
2. Assisted removing front suction
3. Pick up all remove parts set scales to check unit for weight
4. Weight truck-adsuted driver door, adsuted captains door and found bolt missing, had to remove door panel to put bolt in latch.

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V71425

In Date: 12/05/2014

Meter Reading: 85,513.00

Close Date: 12/05/2014

Problem?

Air leak

Task performed:

Parts

Quantity

Drive to station, found air heat on lines to front discharge valve lines cap of lines. Seperate from each other-test it's good now

NO PARTS USED

Workorder: V69079

In Date: 08/31/2014

Meter Reading:

Close Date: 12/18/2014

Problem?

Driver side TeleLight out. Q47

Task performed:

Parts

Quantity

Close ticket-no work done replaced lights with LED's on ticket #70499

NO PARTS USED

Workorder: V71421

In Date: 12/04/2014

Meter Reading:

Close Date: 12/22/2014

Problem?

WATER AND OIL ARE LEAKING FROM UNDER THE TRUCK

Task performed:

Parts

Quantity

1. Adjusted pump packing and ran pump
2. Oil leak in form oil pan gasket will ahve replaced at shop

NO PARTS USED

Workorder: V71804

In Date: 12/22/2014

Meter Reading: 86,167.00

Close Date: 12/29/2014

Problem?

air leak

Task performed:

Parts

Quantity

Repaired air line that was leaking at rear tank.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V71332

In Date: 12/02/2014

Meter Reading: 85,354.00

Close Date: 01/05/2015

Problem?

not charging, Q-47

Task performed:

check charging system, replace alternator, when changing pully noticed that alt. shaft was keyed and pully was not, also alt. shaft was not tapered, advised john murry and asked to look into matter.

Parts

Quantity

A0014949PA4949PA/4962 320 AMP UPGRADE SADDLE MC

1

ALA00350-50 EXTENDED LIFE COOLANT GAL

2

Workorder: V70537

In Date: 10/29/2014

Meter Reading:

Close Date: 01/06/2015

Problem?

Noticed upon start up the "Check Coolant" light came on. Light went off after one to two min. of running. Tommy replaced coolant line and all coolant day before yesterday, possibly just needs top off of coolant.

Task performed:

Completed on WO# 70479

Parts

Quantity

NO PARTS USED

Workorder: V71610

In Date: 12/12/2014

Meter Reading: 85,765.00

Close Date: 01/06/2015

Problem?

Rear officer side (inside) tire's valve stem extension not allowing air in or out, needs replcement (per Tommy). Requires a one piec 8 1/2" valve stem extension. Tire has air in it, just can't check pressure or adjust p

Task performed:

Repaired valve stem and check air

Parts

Quantity

440-33-11/16 VALVE EXT

6

440-5 VALVE EXT.

2

Workorder: V71773

In Date: 12/20/2014

Meter Reading: 86,085.00

Close Date: 01/09/2015

Problem?

window in back, behind driver is not operating. During a drive the window slid to the completely down position and would not roll u the glass is intact.

Task performed:

Repaired window regulator and tested

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V71794

In Date: 12/21/2014
Close Date: 01/09/2015

Meter Reading: 86,138.00

Problem?

Cabinet door in center rear of cab missing two of three nut and bolt sets holding the door to the hinge. Door nearly falling off the hinge. Q47

Task performed:

1. Repaired door on cabinet that was falling off
2. Replaced headlight and repaired wiring

Parts	Quantity
H4651USE CV TYPE SEALED BEAM	1
H4656USE CV TYPE HEAD LIGHT	1

Workorder: V71828

In Date: 12/22/2014
Close Date: 01/09/2015

Meter Reading: 86,271.00

Problem?

Driver side rear FF door latch not working from the inside. FF unable to open the door from the inside to exit. Door does open from the outside. Q47

Task performed:

Repaired door linkage and tested

Parts	Quantity
NO PARTS USED	

Workorder: V71923

In Date: 12/29/2014
Close Date: 01/09/2015

Meter Reading: 86,489.00

Problem?

FF window on driver side will not roll up. Q47

Task performed:

Removed door panel and installed new window regulato

Parts	Quantity
70-01-016WINDOW REG LEFT HAND SPEC OPS QUINTS	1

Workorder: V72201

In Date: 01/11/2015
Close Date: 01/16/2015

Meter Reading:

Problem?

There is a moderate water leak coming from around the center of the cab of Q47. Water flown day before, possibly the aux engine cooler line.

Task performed:

Repaired water leak at pump cooler.

Parts	Quantity
NO PARTS USED	



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V71966

In Date: 12/31/2014

Meter Reading:

Close Date: 01/20/2015

Problem?

oil and water leaking from under cab of vehicle. Q47

Task performed:

1. Adjusted pump packing and ran pump.
2. Oil leak will repair at B-Inspection.

Parts

NO PARTS USED

Quantity

Workorder: V71967

In Date: 12/31/2014

Meter Reading:

Close Date: 01/28/2015

Problem?

master intake gauge is leaking oil and has lost 1/3 of the fluid Q47

Task performed:

Removed and replaced gauge.

Parts

91583953GAUGE COMPOUND LIQUID FILLED

Quantity

1

Workorder: V72200

In Date: 01/11/2015

Meter Reading:

Close Date: 01/28/2015

Problem?

The orange light on the end of the stick is missing the plastic housing. There is an orange light on each side of the end of the stick & 1 is missing

Task performed:

Removed and replaced light and tested system.

Parts

470S-1280-ASTROBE

Quantity

1

Workorder: V72241

In Date: 01/12/2015

Meter Reading:

Close Date: 01/28/2015

Problem?

a/c on officers side not working at all

Task performed:

Removed blower motor. Installed new blower motor and rewired.

Parts

BH13003993 BLOWER MOTOR +SQUIRREL CAGE ASSY.

Quantity

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V72242

In Date: 01/12/2015

Meter Reading:

Close Date: 01/28/2015

Problem?

aerial master switch not lighting up when engaged

Task performed:

1. Repaired ground wire on switch and tested.
2. Mounted tools in L1 compartment.

Parts

Quantity

SWT54915SWIT-251240 SW ROCKER SPST ON/OFF GREE

1

Workorder: V72453

In Date: 01/20/2015

Meter Reading:

Close Date: 02/05/2015

Problem?

"47" placard on driverside rear, bracket coming lose. Need double face tape to re-attach

Task performed:

Repaired placard and number plate.

Parts

Quantity

NO PARTS USED

Workorder: V72653

In Date: 01/27/2015

Meter Reading:

Close Date: 02/11/2015

Problem?

hose bed cover dry rotted and ripped, velchro and fasteners are no good that hold the cover down.

Task performed:

Will send hose bed out for repair.

Parts

Quantity

NO PARTS USED

Workorder: V72654

In Date: 01/27/2015

Meter Reading:

Close Date: 02/11/2015

Problem?

Need 2 stroke engine oil and ethanol treatment. also need something to preserve the fuel like sta-bil

Task performed:

Dropped off oil at station.

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V72867

In Date: 02/04/2015

Meter Reading:

Close Date: 02/20/2015

Problem?

Air horn out of tune. Won't blow very loud and sounds like it has to "building up" pressure to get any sound at all out Q47

Task performed:

Parts

Quantity

Readjusted air horns.

NO PARTS USED

Workorder: V72876

In Date: 02/04/2015

Meter Reading:

Close Date: 02/26/2015

Problem?

Command Master computer will not allow me to throttle up or down, all push buttons illuminated and no functions working

Task performed:

Parts

Quantity

Removed command master, installed and reprogramed.

NO PARTS USED

Workorder: V73082

In Date: 02/11/2015

Meter Reading:

Close Date: 03/11/2015

Problem?

outside rear tires will need to be replaced soon

Task performed:

Parts

Quantity

replace rear tires

NO PARTS USED

Vendor?: ELPEX

Workorder: V72573

In Date: 01/24/2015

Meter Reading:

Close Date: 03/16/2015

Problem?

genesis brake cutter has the jaws damaged and need to be replaced. the unit works fine, just the cutting surface needs to be fixed Q47

Task performed:

Parts

Quantity

1. Replaced bulb in celing light and repaired connections.

921LIGHT BULB

10



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V74480

In Date: 04/07/2015
Close Date: 04/07/2015

Meter Reading: 88,360.00

Problem?

officer seat belt broken

Task performed:

repaired on w/o#74481

Parts

Quantity

854003-012SEAT BELT 3 POINT QUINTS

1

Workorder: V74481

In Date: 04/07/2015
Close Date: 04/07/2015

Meter Reading: 88,360.00

Problem?

officer seat belt inop, Q-47

Task performed:

officer seat belt jammed, remove scba officer seat,
replace seat belt harness and buckle

Parts

Quantity

NO PARTS USED

***part charged out to w/o#74480

Workorder: V74545

In Date: 04/09/2015
Close Date: 04/09/2015

Meter Reading: 88,507.00

Problem?

Rear tire replaced by Tiresoles

Task performed:

Tires installed by tiresoles

Parts

Quantity

1100/1200R24/25TIRE TUBE

4

138655715 12R241200R24 TIRE

2

Workorder: V74738

In Date: 04/17/2015
Close Date: 04/17/2015

Meter Reading:

Problem?

Rubber band that holds the spreaders in the bracket is broken in two. Please replace with new rubber band to secure the spreader when possible. Thank you.

Task performed:

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V74527

In Date: 04/09/2015

Meter Reading:

Close Date: 04/22/2015

Problem?

"ABS" idiot light on dash comes on and off periodically while driving...Also the TIC base seems to not be charging the TIC itself (spare TIC battery seems to be charging OK)

Task performed:

1. Readjusted ABS sensor and road tested.
2. Repaired tic charger and tested.

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: V73215

In Date: 02/17/2015

Close Date: 05/21/2015

Meter Reading: 88,269.00

Problem?

C inspection Q47

Task performed:

Parts

Quantity



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

1. Remove water way to replace seal, found chip in rear seal housing. R&R housing and seal and O-ring. Cleaned up waterway and installed on ladder, found monitor broken.
2. Took monitor apart and order parts. Got new parts and put monitor back together and back on truck and test it.
3. Check lift cylinder, found cylinder leaking at ramseal and leaking down the line so I R&R both lift cylinder and send to be rebuilt. Install cylinders.
4. Assect with cylinders
5. R&R wiper blades.
6. Remove left rear jump seat cushier and send it to be repaired. Got new seat cushion and installed it.
7. Check windshield washer, pump plug up, clean up screen pump blow all hose out and replaced on spray nozzle.
8. R&R siren head, send old one to be repaired.
9. Start taking swivel apart on water way. Got it apart and cleaned up, found balls and O-ring put one side back together lube one side finish swivel.
10. Check foam system found motor on pump bad. R&R pump but valve would drop foam on ground, took pump and valve assemble out and found valve work, so got to check wiring , found switch was bad. R&R switch, foam work good.
11. Check right side pump panel light, found wire broken in panel, had to remove panels and rewire light assembly.
12. Check compartment light. R&R light assembly in R-2 moved screw in R-4 and R&R light assembly in L-5.
13. Check fed. Q brqke found coin on, brake was burned up. R&R brake assembly.
14. Make cove for intake hole in bumper.
15. Try ladder down to go TTP to replace springs.
16. Made shim to go under cab locks to hold cab off exhaust.
17. Clean up wheels and painted the wheels order lug covers.
18. Welding work, cut out broken spots in monitor that need welded, sand down and clean out get ready to weld up. Weld up, grind down welds, sent to machine shop for refacing.
19. Test on monitor to see if it fits before sending machine to shop, after testing to see if fit ok. Remove get ready to finish up work.
20. C-Inspection.
21. Engine oil leaking badly. Remove all necessary components to gain access for removal of pan wash off all oil residues and wash out oil pan. Order pan gasket. Reinstall seal and pan. Reconnect all removed components.
22. Transmission leaking oil badly. Found hydraulic cooler line fittings leaking. Disconnect all lines and remove fitting. Find new fitting O-rings and replace fitting

01-06635060-C90PSC0CDCR STRIP LIGHT STEADY WHITE	6
0106837849C8COMP LIGHT WHITE LED 200	2
082-2007-00-0GREASE ZERK W/CHECK VLV	1
117823FLANGE BASE	1
15W40BSYN OIL BULK QTS	36
546-00011-000HALE GREEN INDICATOR	1
64-2911PLUG 4WAY REMOTE CAB LIFT PIERCE	1
744337PLUG AKRON	20
757020ORING AKRON	2
757041757041 O-RING	2
757042ORING AKRON	2
757056O-RING BUNA	2
757068ORING SREAM MASTER 3579 4-1/2	1
757076ORING STREAM MASTER 3579 4-3/4	2
757077ORING STREAM MASTER 3579 5"	1
757295ORING AKRON	1
757312O-RING BUNA	2
757313ORING AKRON	2
757446ORING	1
765100SCREW AKRON	2
ACX-84534LUG NUT COVER PK10	20
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	6
E-600013-3052 NUT	1
FG-Q59278P/S GASKET	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
HP-31DBATTERY 950CCA HP-31D	6
P1147GFUEL FILTER 33120 WIX DELCO TP916	1
111602SPS PANEL	1
23920-9213UTILITY PUMP	1
30-230FH3683 STRAP-RATCHET TYPE	2
194BULB	10
310-1089AXEL WEAR RING	2
2021810008312 NOZZLES WINDSHIELD WASHERS	1
7001-40ESEAL 4 IN	1
23522281BOLT KIT WITH INSULATOR AND SPACER	10
29526898 29548988 TRANS FILTER ALLISON	1
5008414CARTRIDGE DC100	1
K022105PURGE VALVE AD-IP-IS	1
23539104GASKET OIL PAN 60 SERIES BLACK	1
3202099SEAL WITH RACE QUINT	2
401581GASKET AXLE FL80 R002435	2
FT4471BDQUINT REAR BRAKE SHOES	4
KIT9081BRAKE HARDWARE KIT	2
33063FUEL FILTER ONAN	1
51064OIL FILTER ONAN	1



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

and lines, wash off oil residue from drive line and frame.
23. Finish draining remainder of transmission fluid as at least half drained out with above repair. Finish transmission service.

24. Service transfer case.

25. PTO has oil leak. Oil line fitting leaking, remove line, oil line has reassemble fitting. Get new line and reinstall fittings. Reinstall line and refill, clean off oil residue from frame and wiring harness, etc.

26. Service air dryer.

27. Failed battery load, test, replace all six batteries.

28. Battery charger seems to be only putting out half its capacity. Check out charger and found that it was wired wrong. Set up output wiring so full output of charger can be obtained, also monitor display wiring wrong- repair.

29. Cab lift-inop. Have manually jump terminals to lift or lower cab. Check out wiring found main power lead wire to side remove, dead, also activations panel, it was on saying power was there, hooked up laptop to check out node. Found power from node was ok. Trace back wiring and found splices and wires hooked up wrong. Cut out all splices and rerun wiring and making proper connections for both remote and activation light to operate properly. Rested now all work ok.

Vendor?: CENTRAL AUTO

C10FILTER Q47	1
470S-1280-ASTROBE	1
50-24WIPER BLADE - KME	2
70002629109041 BEARING 025 IN 50 PK	2
740-WWS75WATERWAY SEAL KIT	1
AMH-1AMH-1 VALVE EXTENSION	1
FRT V27865FREIGHT CHARGE	1
HY-10174VELOCITY FUSE	2
HY-10359REDUCER	2
PH47 51758 L/F PH725 OIL FILTERL	1
PH7405 51971 OIL FILTER WIX	2
PR-10061FLANG 4 IN WATERWAY SEAL	1
PS683033442 FUEL FILTER	1
S775COUPLER	2
S777COUPLING NIPPLE	4
TRANSYNDALLISON TRANS FLUID GAL	11
Z8280B003A02BRAKE SOL. FED. Q SIREN 12V	1

Workorder: V73081

In Date: 02/11/2015

Meter Reading:

Close Date: 06/30/2015

Problem?

ladder tip light on officers side is stripped and will not lock in the upright position.

Task performed:

Parts _____ Quantity

NO PARTS USED

Workorder: V74574

In Date: 04/10/2015

Meter Reading:

Close Date: 07/07/2015

Problem?

Halyard snapped while raising the ladder. Ladder was at full extension (35ft), and came crashing down, shock loading both fly sections. Ladder needs to be professionally inspected and tested and halyard replaced. q47

Task performed:

Parts _____ Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10172453

FERRARA QUINT AERIAL

Workorder: **V74597**

In Date: 04/11/2015

Meter Reading:

Close Date: 07/07/2015

Problem?

Tank water leaking from the Pump/Engine cooler, 1/2" or 3/8" poly line going to the top of the engine. Seems like the brass fitting just needs to be tightened, need to remove hose from fitting to do it (not sure how) Q47

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: **V76094**

In Date: 07/07/2015

Meter Reading:

Close Date: 09/08/2015

Problem?

Tank water leaking from the engine cooler line (from pump to engine).

Task performed:

Parts

Quantity

NO PARTS USED



Palm Beach County Fire Rescue Fleet Maintenance Asset History

Asset: (10172453) 2007 - FERRARA HD77 Spare Ladder 1

10172453

10192795-2015-1

Date Opened: 4-15-2015 Date Finished 4-15-2015 Meter 1 Reading: 88,507

TASKS PERFORMED

NO PARTS USED

FIRE PUMP
AIR SYSTEM

CSHOP-2015-1147

Comments: L47 ONE LADDER SPOT INOP 1 B/U SPOT INOP

Date Opened: 6-12-2015 Date Finished 7-23-2015 Meter 1 Reading: 90,100

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
QUARTZ LIGHT
EMERGENCY EQUIPMENT
HVAC SYSTEM

CSHOP-2015-126

Comments: RUBBER THAT HOLDS SPREADER BROKEN L47 ONE OF THE PORTABLE EXTENSION CORD LIGHTS IS NOT WORKING

Date Opened: 4-17-2015 Date Finished 5-12-2015 Meter 1 Reading: 89,368

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM
AIR SYSTEM
EMERGENCY EQUIPMENT
HVAC SYSTEM

CSHOP-2015-1526

Comments: CHECK FRONT TIRES LOW COOLANT NONE IN STATION L47

Date Opened: 7-2-2015 Date Finished 7-17-2015 Meter 1 Reading: 90,000

TASKS PERFORMED

Q PARTS

FIRE APPARATUS 3 BULB; EJG120V-750WC BULB
COOLING SYSTEM 2 FLUID; 50-50 EXTENDED LIFE COOLANT GAL
TIRES & WHEELS

Asset Work Order History 10172453

CSHOP-2015-1626

Comments: **L47 WATER LEAKING FROM PUMP AREA, POSSIBLE PUMP/ENGINE COOLER**
Date Opened: 7-7-2015 Date Finished 8-5-2015 Meter 1 Reading: 93,000

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE APPARATUS

CSHOP-2015-1724

Comments: **L47 DRIVER SIDE QUARTZ LITE OUT, PASS SIDE QUARTZ DIM SLOW LEAK FROM ENGINE COOLER HAS BEEN REPAIRED SEVERAL TIMES IN THE PAST SCREECHING NOISE WHEN RETRACTING LADDER**
Date Opened: 7-13-2015 Date Finished 7-24-2015 Meter 1 Reading: 90,100

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE APPARATUS

CSHOP-2015-2018

Comments: **LOW VOLTAGE**
Date Opened: 7-29-2015 Date Finished 7-29-2015 Meter 1 Reading: 92,670

TASKS PERFORMED

Q PARTS

ALTERNATOR-GENERATOR

1 MOUNT; 4949PA/4962 320 AMP UPGRADE SADDLE MOUNT
1 9IP; 3925852 PULLEY

CSHOP-2015-2048

Comments: **WIPER ARM CAME APART L47**
Date Opened: 7-31-2015 Date Finished 8-3-2015 Meter 1 Reading: 92,918

WINDSHIELD WIPER INOP.

TASKS PERFORMED

Q PARTS

WIPER ARM

2 WIPER; WIPER BLADE - KME
1 9IP; WIPER KIT SPEC OPSS

CSHOP-2015-2117

Comments: **COOLANT LEAK L47 A/C SHUTS OFF WHILE DRIVING**
Date Opened: 8-4-2015 Date Finished 8-17-2015 Meter 1 Reading: 93,000

TASKS PERFORMED

NO PARTS USED

WAIT TIME TO BE CHARGED TO WORK ORDER
TRAVEL TO BE CHARGED TO WORK ORDER
FIRE APPARATUS
HOSES-LINES & FITTINGS
COOLING SYSTEM
HVAC SYSTEM

Asset Work Order History 10172453

CSHOP-2015-2268

Comments: **THROTTLE PROBLEM L47**

Date Opened: 8-11-2015 Date Finished 8-11-2015 Meter 1 Reading: 93,000

TASKS PERFORMED

NO PARTS USED

FIRE PUMP

CSHOP-2015-2561

Comments: **DOOR OPEN ALARM L47**

Date Opened: 8-26-2015 Date Finished 9-25-2015 Meter 1 Reading: 94,310

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
DIAGNOSE ELECTRICAL
CAB-INTERIOR ACCESSORIES
HVAC SYSTEM

CSHOP-2015-2667

Comments: **DRIVER AND OFFICER AIR SEAT PROBLEM LOSES AIR PRESSUR THEN WORKS AFTER A MINUTE OR TWO L47
DRIVERS SIDE OUTRIGGER SEEMS TO BE SINKING DOWN FROM STOWED POSITION ALARM STARTS SOUNDING
IN CAB**

Date Opened: 9-2-2015 Date Finished 9-25-2015 Meter 1 Reading: 94,410

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
HYDRAULIC CYLINDER EXTENSION
AIR SYSTEM

CSHOP-2015-2673

Comments: **REPAIRS FROM UL TEST**

Date Opened: 9-2-2015 Date Finished 10-6-2015 Meter 1 Reading: 94,420

ELECT LINE GOING INTO MAIN RAILS--PUTTY NEEDS REPLACEMENT

TASKS PERFORMED

NO PARTS USED

CRADLE AERIAL LADDER
WATERWAY AERIAL LADDER
HYDRAULIC CYLINDER EXTENSION
EGRESS TIP AERIAL LADDER FLY
AERIAL LADDER EQUIPMENT
UL AERIAL TESTING
FIRE APPARATUS

CSHOP-2015-2739

Comments: **ON-CALL L47 NOISE HEARD WHEN DRIVING**

Date Opened: 9-8-2015 Date Finished 9-8-2015 Meter 1 Reading: 94,243

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

Asset Work Order History 10172453

CSHOP-2015-2809

Comments: **REAR END BROKE**

Date Opened: 9-9-2015

Date Finished 9-15-2015

Meter 1 Reading: 94,310

TASKS PERFORMED

NO PARTS USED

REAR AXLE

VENDOR? WESTWAY TOWING

CSHOP-2015-288

Comments: **L47 RIGHT SIDE FRONT DOOR WINDOW OFF TRACK AND DOOR DOES NOT OPEN FROM INSIDE**

Date Opened: 4-27-2015

Date Finished 5-1-2015

Meter 1 Reading: 89,268

TASKS PERFORMED

NO PARTS USED

DOOR

CSHOP-2015-3043

Comments: **B INSPECTION L47**

Date Opened: 9-22-2015

Date Finished 9-29-2015

Meter 1 Reading: 94,410

TASKS PERFORMED

Q PARTS

PM SERVICE B

10 FLUID; SYN OIL BULK QTS
2 FILTER; 51971 OIL FILTER WIX
1 FILTER; 33442 FUEL FILTER
1 FILTER; FUEL FILTER 33120 WIX DELCO TP916

CSHOP-2015-3044

Comments: **REPAIRS FROM B INSPECTION**

Date Opened: 9-22-2015

Date Finished 9-29-2015

Meter 1 Reading: 94,411

RT/ REAR HUB SEAL SHOWING SLITE OIL SEEPAGE

TASKS PERFORMED

Q PARTS

HYDRAULIC CYLINDER EXTENSION
DOOR-PANEL HINGE
CAB
ENGINE AND ACCESSORIES
PARK-CLEARANCE LIGHTS
LIGHTING SYSTEM
TRANSMISSION
REAR HUB SEAL-GASKET

4 VALVE; PILOT CHECK VALVE
1 LIGHT; LIGHT MARKER LED RED
1 NEWPART; HOSE & FITTINGS

Asset Work Order History 10172453

CSHOP-2015-3289

Comments: **Q 47**

Date Opened: 10-7-2015 Date Finished 10-28-2015 Meter 1 Reading: 95,121

TASKS PERFORMED

NO PARTS USED

INSTRUMENTS-GAUGES-METERS
HVAC SYSTEM

Service Requests:

10/07/2015 ALARMS / 17: INSUFFICIENT LUBRICANT / REPAIR
LOADMINDER ON LADDER 47 IS NOT CALIBRATED. WHEN IN PTO AND AERIAL MASTER ON, THERE IS A RED LIGHT THAT CYCLES THROUGH THE WEIGHT LIMITS ON THE LOAD MINDER.

CSHOP-2015-3373

Comments: **L47**

Date Opened: 10-13-2015 Date Finished 10-28-2015 Meter 1 Reading: 95,163

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
ELECTRICAL
REAR TIRES
BODY EXTERIOR
HVAC SYSTEM

Service Requests:

10/10/2015 TIRES / 19: LOOSE / REPAIR
RIGHT REAR TIRE IS AT WEAR BAR, NEEDS 4 NEW REAR TIRES PER TOMMY THE MECHANIC

10/12/2015 DOOR / 19: LOOSE / REPAIR
LADDER 47 DRIVER SIDE REAR PASSENGER DOOR HANDLE NOT WORKING. DOOR MECHANISM HAS BROKEN OFF COMPLETELY FROM THE HANDLE IN THE INSIDE DOOR PANNEL. REAR FIREFIGHTER IS UNABLE TO OPEN DOOR AND EXIT. (DOOR HANDLE HAS BEEN TEMPORARY FIXED WITH ZIP TIE)

CSHOP-2015-3398

Comments: **L47 SEAT BELT INOP**

Date Opened: 10-13-2015 Date Finished 10-28-2015 Meter 1 Reading: 95,163

TASKS PERFORMED

Q PARTS

CAB-INTERIOR ACCESSORIES

1 BELT; SEAT BELT 3 POINT QUINTS

CSHOP-2015-3413

Comments: **HOSE BAD ON GENNISIS TOOL Q47**

Date Opened: 10-14-2015 Date Finished 10-28-2015 Meter 1 Reading: 95,163

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
EMERGENCY EQUIPMENT
CAB-INTERIOR ACCESSORIES

Asset Work Order History 10172453

CSHOP-2015-3734

Comments: **L47 TUBE FROM TIRE CHANGE**

Date Opened: 11-2-2015 Date Finished 11-2-2015 Meter 1 Reading: 95,387

TASKS PERFORMED

NO PARTS USED

REAR TIRES

VENDOR? ELPEX TIRE TIRESOLES

CSHOP-2015-3787

Comments: **OFFICERS SEAT BELT L47**

Date Opened: 11-4-2015 Date Finished 12-4-2015 Meter 1 Reading: 96,635

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
AERIAL EQUIPMENT FIRE APPARATUS
SEAT BELTS
HVAC SYSTEM

1 ACCUTATOR PART
1 NONSTOCK; FREIGHT CHARGE
1 BELT; SEAT BELT 3 POINT QUINTS

CSHOP-2015-3813

Comments: **L47**

Date Opened: 11-6-2015 Date Finished 11-6-2015 Meter 1 Reading: 95,560

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE FIGHTING EQUIPMENT
CAB-INTERIOR ACCESSORIES

1 SWITCH; TURN SIGNAL SWITCH

Service Requests:

11/06/2015 LIGHTS / 19: LOOSE / REPAIR
TOP LEFT FRONT QUARTZ LIGHT STOPPED WORKING, ALSO WINDSHIELD WIFER COMPLETELY OUT, NOT WORKING
OR HAVE ANY POWER TO IT

CSHOP-2015-3912

Date Opened: 11-12-2015 Date Finished 12-15-2015 Meter 1 Reading: 97,226

TASKS PERFORMED

NO PARTS USED

EMERGENCY EQUIPMENT

Service Requests:

11/10/2015 SERVICE REQUEST / 18: LEAKING / REPAIR
THE "LOADMINDER" GAGE IS NOT WORKING ON THE LADDER TURNTABLE. ALSO, THE INTERCOM ON THE LADDER IS
NOT WORKING PROPERLY (THE FIREFIGHTER ON THE TIP CANNOT HEAR THE FIREFIGHTER ON THE TURNTABLE,
EVEN WHEN THE PUSH TO TALK BUTTON IS PUSHED)

Asset Work Order History 10172453

CSHOP-2015-3974

Comments: **L47 OUTRIGGER ISSUE**

Date Opened: 11-16-2015 Date Finished 1-13-2016 Meter 1 Reading: 98,528

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
HYDRAULIC CYLINDER EXTENSION
FIRE APPARATUS
HYDRAULIC SYSTEM
AIR SYSTEM
CAB-INTERIOR ACCESSORIES
HVAC SYSTEM

1 CAP; HONDA FUEL CAP
1 VALVE; ARO A212SS-12D VALVE
1 NEWPART; SNUBBER
4 VALVE; PILOT CHECK VALVE

Service Requests:

-
- 11/14/2015 SERVICE REQUEST / 10: BENT / REPAIR
OUTRIGGER ON DRIVERS SIDE OCCASIONALLY SLIDES DOWN CAUSING THE OUTRIGGER DEPLOYED SENSOR TO SOUND IN THE CAB. THE OUTRIGGER HAS TO BE DEPLOYED AND STOWED TO FIX THE PROBLEM
- 11/16/2015 ALARMS / 19: LOOSE / REPAIR
AERIAL OUTRIGGER ALARM, INDICATING AN OUTRIGGER IS NOT FULLY RETRACTED AND STORED AWAY, WAS GOING OFF YESTERDAY. TRIED TO DEPLOY OUTRIGGERS AND THEN RETRACT ALL THE WAY BACK IN TO GET IT TO STOP, ALARM STILL WAS GOING OFF. LADDER WAS ALSO DEPLOYED AND THEN BEDDED TO TRY TO GET IT TO STOP. HAS BEEN AN ONGOING ISSUE FOR L47. SHUTTING THE TRUCK AND BATTERY OFF EVENTUALLY GOT IT TO STOP.
- 12/12/2015 AIR RIDE / 18: LEAKING / REPAIR
(NO GOOD SYMPTOM CODE) DRIVER'S SIDE OUTRIGGER HAS A LEAK. WHEN DEPLOYED TODAY, WAS SET 1" ABOVE SAFETY PIN, AND AN HR LATER THE OUTRIGGER HAD SUNKEN DOWN TO RESTING ON THE PIN, UNABLE TO REMOVE THE PIN WITHOUT RAISING THE OUTRIGGER. THERE HAS BEEN A PERSISTENT LEAK WHERE THE "OUTRIGGER DEPLOYED" WARNING LIGHT IN THE CAB WILL GO ON, THIS ALSO OCCURED.
- 12/14/2015 ALARMS / 19: LOOSE / REPAIR
COMPARTMENT SENSOR CONTINUALLY SOUNDING FOR OFFICER SIDE REAR COMPARTMENT.
-

CSHOP-2015-4638

Date Opened: 12-24-2015 Date Finished 12-24-2015 Meter 1 Reading: 97,674

TASKS PERFORMED

NO PARTS USED

CAB-INTERIOR ACCESSORIES

CSHOP-2015-4639

Date Opened: 12-27-2015 Date Finished 12-31-2015 Meter 1 Reading: 97,964

TASKS PERFORMED

Q PARTS

SEAT BELTS

1 BELT; SEAT BELT 3 POINT QUINTS

CSHOP-2015-583

Date Opened: 5-12-2015 Date Finished 5-20-2015 Meter 1 Reading: 89,468

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE PUMP CONTROLS
RELIEF VALVE FIRE PUMP
FIRE PUMP
DIAGNOSE ELECTRICAL
DOOR HANDLES INSIDE-OUTSIDE

3 BULB; LB-M15 240 V BULB

Asset Work Order History 10172453

CSHOP-2015-635

Comments: **L47 ARM FOR WATER AND RESCUE MODE BROKEN ON OFFICER SIDE FOR LADDER**

Date Opened: 5-14-2015 Date Finished 5-19-2015 Meter 1 Reading: 89,368

TASKS PERFORMED

Q PARTS

EMERGENCY EQUIPMENT

1 FERRARA; LOCKING ARM RH SMEAL
1 FERRARA; LOCKING ARN LH SMEAL

CSHOP-2015-727

Comments: **L47 PUMP CONTROL INOP**

Date Opened: 5-20-2015 Date Finished 5-27-2015 Meter 1 Reading: 89,568

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FOAM SYSTEM
PUMP PANEL
FIRE APPARATUS
DOOR ALARM OR OTHER WARNING
HVAC SYSTEM

CSHOP-2015-817

Comments: **Q47 LOADMINDER INOP AND INTERCOM MIC ON LADDER INOP**

Date Opened: 5-26-2015 Date Finished 6-16-2015 Meter 1 Reading: 89,870

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
EQUIPMENT MOUNTING BRACKETS
FIRE APPARATUS

1 PIERCE; FIRECOM BOX LADDER END
1 CLASS 1; LOADMINDER LMS KIT

CSHOP-2015-890

Comments: **L47 WHILE BEDDING THE LADDER, HYDRAULICS IS MAKING A LOUD GRINDING SOUND AND NOW THERE IS A SLIGHT BURNT SMELL. ALSO THE CAPTAINS SIDE FLOOD LIGHT AT THE LADDER BASE IS BURNED OUT DRIVERS SIDE TELESCOPING LIGHT NOT WORKING, PASS SIDE BASE OF AERIAL NOT WORKING, ONE CIRCLE D LIGHT**

Date Opened: 6-1-2015 Date Finished 6-8-2015 Meter 1 Reading: 89,770

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AERIAL EQUIPMENT FIRE APPARATUS

Asset Work Order History 10172453

CSHOP-2016-102

Comments: L47

Date Opened: 1-8-2016

Date Finished

1-22-2016

Meter 1 Reading:

98,924

TASKS PERFORMED

NO PARTS USED

DIAGNOSE ELECTRICAL
EMERGENCY EQUIPMENT

Service Requests:

-
- 01/08/2016 SERVICE REQUEST / 19: LOOSE / REPAIR
SHORELINE AUTOEJECT IS NOT WORKING PROPERLY. WILL NOT AUTOEJECT WHEN TRUCK IS TURNED ON.
- 01/13/2016 OIL / 19: LOOSE / REPAIR
TRUCK HAS AN ENGINE OIL LEAK
- 01/18/2016 ALARMS / 19: LOOSE / REPAIR
AN AUDIBLE ALARM KEEPS SOUNDING, AND A LIGHT IN THE FRONT SEAT ROOF KEEPS BLINKING YELLOW. THE INFORMATION ON THE CAB COMPUTER SAYS THAT IT IS THE AERIAL OUTRIGGERS. LADDER 47 STOPPED AND MADE SURE THE THE OUTRIGGERS WERE ALL THE WAY UP AND RETRACTED. THE AUDIBLE ALARM CONTINUES TO ACTIVATE.
-

CSHOP-2016-1475

Comments: T47 PART ONLY ADDED GENESIS FLUID AND VELCRO STRAP

Date Opened: 3-29-2016

Date Finished

4-28-2016

Meter 1 Reading:

100,878

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE FIGHTING EQUIPMENT
TOWING HITCH
COOLING SYSTEM
CAB-INTERIOR ACCESSORIES

1	HURST; GENESIS HYD FLUID
1	STRAP; STRAP
1	STRAP; STRAP
1	9IP; WINDOW REG RH INFERNO

Service Requests:

-
- 03/28/2016 SERVICE REQUEST / 19: LOOSE / REPAIR
FLASHLIGHT CHARGERS NOT CHARGING FLASHLIGHTS IN REAR COMPARTMENT, TWO CHARGING MOUNTS NOT WORKING.
-

CSHOP-2016-1741

Comments: L47

Date Opened: 4-12-2016

Date Finished

4-12-2016

Meter 1 Reading:

100,748

TASKS PERFORMED

Q PARTS

DOOR GLASS

1	9IP; WINDOW REG RH INFERNO
---	----------------------------

Service Requests:

-
- 04/12/2016 WINDOW / 10: BENT / EXCHANGE - NEW
OFFICERS SIDE WINDOW WILL NOT ROLL UP ON LADDER 47.
-

Asset Work Order History 10172453

CSHOP-2016-187

Comments: **REPAIR REAR END**

Date Opened: 1-14-2016

Date Finished

1-26-2016

Meter 1 Reading:

99,102

TASKS PERFORMED

NO PARTS USED

DIFFERENTIAL

VENDOR?

TOTAL TRUCK PARTS INC

CSHOP-2016-2094

Date Opened: 5-2-2016

Date Finished

5-12-2016

Meter 1 Reading:

100,878

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM

HVAC SYSTEM

CSHOP-2016-2200

Comments: **L47**

Date Opened: 5-6-2016

Date Finished

5-21-2016

Meter 1 Reading:

100,878

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER

FIRE APPARATUS

ELECTRICAL

EMERGENCY EQUIPMENT

1

9IP; PERKO SWITCH

Service Requests:

05/06/2016

SERVICE REQUEST / 19: LOOSE / REPAIR

MASTER STREAM FOG NOZZLE NOT ABLE TO ADJUST FROM STRAIGHT STREAM TO FOG PATTERN, AND VICE VERSA.

05/06/2016

SERVICE REQUEST / 19: LOOSE / Q

SPEAKER AT TURN TABLE NOT ABLE TO TRANSMIT VOICE FROM DRIVER TO FIREFIGHTER AT THE TIP OF THE LADDER. DRIVER AT THE TURNTABLE CAN HEAR THE FIREFIGHTERS VOICE AT THE TIP OF THE LADDER BUT CANNOT COMMUNICATE BACK.

05/06/2016

SERVICE REQUEST / 18: LEAKING / A

BATTERY SWITCH VERY DIFFICULT TO TURN ON AND OFF, APPEARS LADDER 47 NEED A NEW SWITCH.

CSHOP-2016-2467

Comments: **ON-CALL L47**

Date Opened: 5-23-2016

Date Finished

5-23-2016

Meter 1 Reading:

102,266

TASKS PERFORMED

Q PARTS

TURNTABLE AERIAL LADDER

1

LAMP; LB-M12 240V 1000W HALOGEN LAMP

Asset Work Order History 10172453

CSHOP-2016-2697

Date Opened: 6-6-2016 Date Finished 8-23-2016 Meter 1 Reading: 102,860

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
COOLING SYSTEM
DIAGNOSE ELECTRICAL
HVAC SYSTEM

3 A/C; FREON LB

CSHOP-2016-2765

Date Opened: 6-9-2016 Date Finished 6-9-2016 Meter 1 Reading: 102,830

TASKS PERFORMED

NO PARTS USED

DIAGNOSE ELECTRICAL

CSHOP-2016-2812

Comments: **L47**

Date Opened: 6-13-2016 Date Finished 8-23-2016 Meter 1 Reading: 104,742

TASKS PERFORMED

Q PARTS

AERIAL LADDER EQUIPMENT
TURNTABLE CONTROL CONSOLE AER
AERIAL EQUIPMENT PEDESTAL FIR
AERIAL EQUIPMENT FIRE APPARATUS
INTERCOM SYSTEM - EMERGENCY V
DISCHARGE GAUGE
SIDE COMPARTMENT BODY
WIPER BLADES
COOLING SYSTEM
QUARTZ LIGHT
LIGHTING SYSTEM
BATTERY
ALTERNATOR-GENERATOR
TRANSFER CASE
TIRE
REAR SPRING
AIR SYSTEM
DOOR ALARM OR OTHER WARNING
HVAC SYSTEM

40 DECAL; LADDER OUT OF SERVICE STICKER
1 SOLENOID; 24071 SOLENOID
1 9IP; LENS WILL BURT
1 GASKET; GASKET WIL BURT
2 GAUGE; GAUGE 0-600 PSI
2 9IP; 11 IN HOLD-OPEN 30LB
-1 WIPER; WIPER BLADES ANCO 24
1 WIPER; WIPER BLADES ANCO 24
2 WIPER; WIPER BLADE - KME
1 9IP; LENS WILL BURT
1 GASKET; GASKET WIL BURT
6 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY
6 BATTERY; BATTERY 950CCA HP-31D
1 BELT; BELT
3 BELT; BELT
1 BELT; BELT E-ONE
8 GEAR; GEAR OIL SYN QT
1 BRAKE; CARTRIDGE DC100
1 VALVE; PURGE VALVE AD-IP-IS
1 ALARM; BACKUP ALARM ECCO 107 DEC
3 A/C; FREON LB

Service Requests:

06/12/2016 ACCIDENT / 12: BROKEN / DRIVERS SIDE POLE LAMP LENS BROKEN. REMOVED A LENS FROM A
DRIVER SIDE TELESCOPIC GLASS LENS BROKE ACCIDENTALLY WHILE LOWERING SCENE LIGHT.

Asset Work Order History 10172453

CSHOP-2016-3063

Comments: **ON-CALL L47 ALARM GOING OFF**

Date Opened: 6-27-2016 Date Finished 6-27-2016 Meter 1 Reading: 103,675

TASKS PERFORMED

NO PARTS USED

ANTIFREEZE

CSHOP-2016-3115

Comments: **Q47**

Date Opened: 6-29-2016 Date Finished 7-12-2016 Meter 1 Reading: 102,830

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM
HVAC SYSTEM

3 A/C; FREON LB

Service Requests:

06/28/2016 BRAKES / 19: LOOSE / S
THERE IS AN UNIDENTIFIED AIR LEAK, UNABLE TO LOCATE IT. HOWEVER, WHEN THE TRUCK IS NOT RUN FOR APPROX 4-5 HRS BOTH AIR TANKS ARE COMPLETELY EMPTY, MUST IDLE IN THE BAY FOR APPROX 45 SECONDS FOR ENOUGH AIR TO BUILD UP TO RESPOND TO A CALL

06/28/2016 LIGHTS / 19: LOOSE / W
DRIVER SIDE TELESCOPING LIGHT GLASS WAS BROKEN WEEKS AGO AND NEEDS TO BE REPLACED. LIGHT STILL TURNS ON AND FUNCTIONS.

Asset Work Order History 10172453

CSHOP-2016-3170

Comments: CHECK WITH L47 POSSIBLE GENESIS RAM LEAK AND PROBLEM WITH AIR BAG CONNECTOR. WRITTEN UP BY BIDWELL CRANAGE UNKNOWN LOCATION THANKS

Date Opened: 7-1-2016 Date Finished 8-26-2016 Meter 1 Reading: 102,860

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM 3 A/C; FREON LB
EMERGENCY EQUIPMENT
DOOR
HVAC SYSTEM

Service Requests:

-
- 07/16/2016 A/C / 19: LOOSE / REPAIR
A/C IS GETTING WARMER AND WARMER BY THE DAY. BLOWING LUKE WARM AIR AT THIS POINT.
 - 07/16/2016 BRAKES / 19: LOOSE / S
AIR BRAKE TAKES A FEW MINUTES TO DISENGAUGE ONCE TRUCK SITS FOR A WHILE
 - 07/17/2016 TIRES / 19: LOOSE / REPAIR
OFFICERS SIDE FRONT TIRE HAS CRACKS, AND WEAR INDICATOR SHOWS TREAD IS LOW, WEAR INDICATOR ON DRIVERS SIDE FRONT SHOWS LOW TREAD AS WELL.
 - 07/17/2016 AIR RIDE / 19: LOOSE / REPAIR
AIR LEAK, VEHICLE HAS BEEN TO SHOP A COUPLE WEEKS AGO FOR SAME PROBLEM, BUT IT WAS NOT RESOLVED. LADDER 47 STILL HAS A BAD AIR LEAK.
 - 07/17/2016 DOOR / 19: LOOSE / S
FIREFIGHTERS DOOR IN REAR WILL NOT OPEN FROM THE INSIDE.
 - 07/17/2016 SERVICE REQUEST / 19: LOOSE / REPAIR
TELESCOPIC LIGHT ON THE DRIVERS SIDE HAS HAD A BROKEN GLASS LENSE COVER FOR APPROX. 1 MONTH, THIS HAS BEEN PUT IN THE SYSTEM BUT HAS NOT BEEN REPAIRED.
-

CSHOP-2016-3196

Comments: ON-CALL L47 AIR LEAK

Date Opened: 7-5-2016 Date Finished 7-6-2016 Meter 1 Reading: 103,889

TASKS PERFORMED

Q PARTS

GEAR BOX FIRE PUMP
AIR SYSTEM 1 PUMP; VPS SHIFT KIT 2 PIECE

Service Requests:

-
- 07/04/2016 BRAKES / 12: BROKEN / AIR SYSTEM QUICK CONNECT AND AIR LINE RUBBING IN BOLT
WENT IN FOR BRAKE SERVICE TWO DAYS AGO. ISSUE WAS NOT FIXED. BRAKES STILL HAVE AIR LEAK. AIR TANK EMPTIES LESS THAN 2HRS AFTER SHUTTING THE TRUCK OFF.
-

Asset Work Order History 10172453

CSHOP-2016-3369

Comments: **L47 COMING HERE AFTER 13:00 TUES**

Date Opened: 7-12-2016 Date Finished: 7-13-2016 Meter 1 Reading: 102,830

TASKS PERFORMED

Q PARTS

AIR SYSTEM

1 DRAIN; DRAIN COCK
1 VALVE; DASH VALVE

Service Requests:

07/12/2016 AIR RIDE / 18: LEAKING / REPAIR
UNIDENTIFIED AIR LEAK THAT HAS BEEN PERSISTENT FOR WEEKS AND IS ONLY GETTING WORSE. TRUCK DOES NOT RUN FOR APPROX 3 HOURS AND THE AIR IS AT ZERO. MUST IDLE IN THE BAYS FOR THE AIR PRESSURE TO BUILD UP AND PUMPING STATION FULL OF DIESEL EXHAUST

CSHOP-2016-3469

Comments: **L47**

Date Opened: 7-19-2016 Date Finished: 8-29-2016 Meter 1 Reading: 102,865

TASKS PERFORMED

Q PARTS

ANTIFREEZE
BELT
REAR TIRES

1 NEWPART; TUBE EGR
1 GASKET; EGR GASKET
1 NEWPART; GASKET EGR VALVE
1 PUMP; WATER PUMP 60 SERIES EGR
5 FLUID; COOLANT ANTIFREEZE GAL
1 NEWPART; ORING ACC DRIVE
1 NEWPART; HOSE COOLING
1 CAP; CAP RADIATOR 10 LB
1 NEWPART; HOSE
1 NEWPART; HOSE & FITTING
1 NEWPART; HOSE
1 BELT; BELT E-ONE
1 BELT; BELT
3 BELT; BELT

Service Requests:

07/15/2016 DOOR / 11: BINDS/STICKS / REPAIR
CAB DOOR, DRIVER SIDE REAR WHERE THE FF SITS IS NOT ABLE TO OPEN FROM INSIDE THE CAB, BUT IS ABLE TO BE OPENED FROM THE OUTSIDE. ONGING ISSUE WITH THESE DOORS

07/15/2016 AIR RIDE / 18: LEAKING / REPAIR
UNIDENTIFIABLE AIR LEAK. WAS AT THE SHOP 7/12 FOR REPAIRS, DID NOT NOTICE ANY IMPROVEMENT AFTER REPAIRS WERE DONE ON 7/12, BOTH AIR TANKS EMPTY AFTER APPROX 4-5 HOURS OF SITTING IDLE

CSHOP-2016-3495

Date Opened: 7-21-2016 Date Finished: 7-21-2016 Meter 1 Reading: 104,742

TASKS PERFORMED

Q PARTS

AIR SYSTEM
SEAT BELTS

1 BELT; SEAT BELT 3 POINT QUINTS

Service Requests:

07/20/2016 HAZARD / 12: BROKEN / OFFICER'S SEATBELT RETRACTOR BROKEN DUE TO CONTACT WITH TH
OFFICERS SIDE SEAT BELT RETENTIONER DOES NOT WORK

Asset Work Order History 10172453

CSHOP-2016-350

Comments: **QUINT 47 DOOR ALARM**

Date Opened: 1-25-2016 Date Finished 2-2-2016 Meter 1 Reading: 99,439

TASKS PERFORMED

NO PARTS USED

CAB-INTERIOR ACCESSORIES

Service Requests:

01/22/2016 SERVICE REQUEST / 19: LOOSE / REPAIR
DOOR ALARM INDICATING THAT THERE IS A OPEN DOOR WILL NOT SHUT OFF. ALL DOORS ARE SECURED AND NOT OPEN.

CSHOP-2016-3527

Date Opened: 7-23-2016 Date Finished 7-28-2016 Meter 1 Reading: 102,860

TASKS PERFORMED

Q PARTS

WHEEL STUD 1 9IP; AMH-1 VALVE EXTENSION
REAR TIRES
AIR SYSTEM

Service Requests:

07/22/2016 SERVICE REQUEST / 12: BROKEN / REPAIR
FEDERAL Q IS NOT WORKING ON L47.

07/26/2016 TIRES / 12: BROKEN / REPAIR
NEED REAR TIRES ON LADDER 47, TREAD INDICATOR VERY LOW, WORSE ON OFFICERS SIDE.

CSHOP-2016-3546

Date Opened: 7-25-2016 Date Finished 7-25-2016 Meter 1 Reading: 102,830

TASKS PERFORMED

NO PARTS USED

FRONT TIRES

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2016-3594

Date Opened: 7-28-2016 Date Finished 7-28-2016 Meter 1 Reading: 102,860

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER 1 STUD; WHEEL STUD
COOLING SYSTEM 1 9IP; 13-3052 NUT
WHEEL STUD 1 9IP; SEAL WITH RACE QUINT
1 GASKET; GASKET AXLE FL80 R002435

Asset Work Order History 10172453

CSHOP-2016-3655

Date Opened: 8-1-2016 Date Finished 8-1-2016 Meter 1 Reading: 102,860

TASKS PERFORMED

NO PARTS USED

REAR TIRES

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2016-3755

Comments: **C-INSPECTION L47**

Date Opened: 8-2-2016 Date Finished 8-29-2016 Meter 1 Reading: 102,862

TASKS PERFORMED

Q PARTS

PM SERVICE C AERIAL

- 1 FILTER; FUEL FILTER ONAN
- 1 FILTER; OIL FILTER ONAN
- 2 FILTER; 51971 OIL FILTER WIX
- 2 9IP; GASKET 2 1/2"
- 1 FILTER; FUEL FILTER 33120 WIX DELCO TP916
- 1 FILTER; 33442 FUEL FILTER
- 1 FILTER; AIR FILTER ONAN 49697
- 2 GASKET; 14023 GASKET 6 IN
- 1 FILTER; 51758 L/F PH725 OIL FILTERL

CSHOP-2016-4193

Date Opened: 8-25-2016 Date Finished 9-2-2016 Meter 1 Reading: 102,865

TASKS PERFORMED

Q PARTS

AIR SYSTEM
HVAC SYSTEM

- 1 NEWPART; RKN28300

Service Requests:

08/24/2016 AIR RIDE / 19: LOOSE / REPAIR
AIR LEAK STILL NOT FIXED, TRUCK TAKES OVER 5 MINUTES IF NOT MORE TO GET OUT TO DRIVE. SLOWING RESPONSE TIMES

CSHOP-2016-4357

Date Opened: 9-6-2016 Date Finished 9-19-2016 Meter 1 Reading: 105,778

TASKS PERFORMED

Q PARTS

SOLENOID
AIR SYSTEM
DOOR
BODY EXTERIOR

- 1 SOLENOID; STARTER SOLENOID EONE
- 1 9IP; FRONT GRILL ASSBLY
- 1 DRAIN; DRAIN COCK
- 1 BRAKE; BRAKE VALVE E-6 NEW
- 1 BRAKE; BRAKE VALVE E-6 NEW

Service Requests:

09/06/2016 SERVICE REQUEST / 12: BROKEN / REPAIR
DRAGER 4 GAS MONITOR NOT HOLDING A CHARGE, EITHER BATTERY IS BAD OR CHARGING BASE NOT WORKING

09/06/2016 DOOR / 19: LOOSE / EXCHANGE - NEW
VEHICLE DOORS, DRIVER SIDE PASSENGER DOOR WILL NOT OPEN FROM THE INTERIOR, CAN ONLY BE OPENED FROM THE EXTERIOR.

Asset Work Order History 10172453

CSHOP-2016-4428

Date Opened: 9-12-2016 Date Finished 9-12-2016 Meter 1 Reading: 105,778

TASKS PERFORMED

NO PARTS USED

FUEL SYSTEM

CSHOP-2016-4514

Date Opened: 9-16-2016 Date Finished 9-16-2016 Meter 1 Reading: 105,778

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

CSHOP-2016-4562

Comments: **EPU FOR L47**

Date Opened: 9-19-2016 Date Finished 1-6-2017 Meter 1 Reading: 105,778

TASKS PERFORMED

Q PARTS

AERIAL EQUIPMENT FIRE APPARATUS
FIRE PUMP

1 **NEWPART; PUMP EMERGENCY SMEAL LADDER**

CSHOP-2016-4982

Date Opened: 10-19-2016 Date Finished 10-19-2016 Meter 1 Reading: 105,778

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM

CSHOP-2016-4985

Date Opened: 10-19-2016 Date Finished 10-19-2016 Meter 1 Reading: 105,778

TASKS PERFORMED

NO PARTS USED

FIRE APPARATUS

CSHOP-2016-5016

Comments: **L47**

Date Opened: 10-21-2016 Date Finished 10-23-2016 Meter 1 Reading: 105,778

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM

Service Requests:

10/20/2016 SERVICE REQUEST / 19: LOOSE / REPAIR
LADDER 47 LOW ON COOLANT, RED LIGHT COMING ON, AND THEIR IS NO COOLANT AT THE STATION

Asset Work Order History 10172453

CSHOP-2016-5240

Date Opened: 11-7-2016 Date Finished 11-22-2016 Meter 1 Reading: 105,778

TASKS PERFORMED

Q PARTS

HOSES-LINES & FITTINGS
HYDRAULIC SYSTEM
COOLING SYSTEM
LIGHTING SYSTEM
AIR SYSTEM
CAB-INTERIOR ACCESSORIES
HVAC SYSTEM

1 BLOWER; BLOWER MOTOR

Service Requests:

- 11/06/2016 A/C / 19: LOOSE / REPAIR
A/C ISSUE, L47 A/C NOT WORKING PROPERLY
 - 11/06/2016 AIR RIDE / 19: LOOSE / REPAIR
AIR LEAK IN THE SYSTEM AGAIN, WILL NOT BUILD UP AIR PRESSURE UNTIL ENGINE IS REVVED UP.
 - 11/07/2016 LIGHTS / 19: LOOSE / REPAIR
DRIVER SIDE HEADLIGHT IS OUT. DONT HAVE AN EXTRA LOW BEAM HEADLIGHT IN STATION OR WOULD REPLACE IT MYSELF
 - 11/07/2016 A/C / 19: LOOSE / REPAIR
OFFICER SIDE AC NOT BLOWING ANY AIR AT ALL. DRIVER SIDE AND REAR SEATS AC IS BLOWING
 - 11/21/2016 ENGINE / 19: LOOSE / REPAIR
CHECK ENGINE LIGHT CAME ON WHILE DRIVING TO A CALL.
-

CSHOP-2016-5462

Date Opened: 11-22-2016 Date Finished 11-22-2016 Meter 1 Reading: 105,778

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

Service Requests:

- 11/22/2016 ENGINE / 19: LOOSE / REPAIR
TRUCK STALLED ON B SHIFT ON A CALL AROUND MIDNIGHT THEN STALLED AGAIN DURING MORNING TRUCK CHECKOUT THIS MORNING.
-

CSHOP-2016-5620

Date Opened: 12-1-2016 Date Finished 12-1-2016 Meter 1 Reading: 105,778

TASKS PERFORMED

NO PARTS USED

FIRE APPARATUS
INSTRUMENTS-GAUGES-METERS

CSHOP-2016-5973

Date Opened: 12-26-2016 Date Finished 12-26-2016 Meter 1 Reading: 105,778

TASKS PERFORMED

NO PARTS USED

FIRE APPARATUS
COOLING SYSTEM

Asset Work Order History 10172453

CSHOP-2016-6069

Comments: **L47 GAS SHOCKS FOR SIDE DOOR ARE BROKEN CANT GET EQUIPMENT OUT WITHOUT 2 PEOPLE.**

Date Opened: 12-28-2016 Date Finished 12-29-2016 Meter 1 Reading: 105,778

TASKS PERFORMED

Q PARTS

BODY EXTERIOR
HVAC SYSTEM

2 STRUT; STRUT

Service Requests:

12/28/2016 SERVICE REQUEST / 19: LOOSE / REPAIR
GAS SHOCKS TO HOLD UP SIDE DOOR ARE BOTH BROKEN, NO WAY TO REMOVE EQUIPMENT FROM THAT COMPARTMENT WITHOUT 2 PEOPLE. ALL EQUIPMENT IN THAT COMPARTMENT IS HEAVY. RIGHT SIDE OF TRUCK 1 COMPARTMENT FROM REAR OF TRUCK.

CSHOP-2016-612

Comments: **L47 NO START**

Date Opened: 2-8-2016 Date Finished 2-8-2016 Meter 1 Reading: 99,681

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
STARTER RELAY-SOLENOID
STARTER
BATTERY
DIAGNOSE ELECTRICAL

Asset Work Order History 10172453

CSHOP-2016-650

Comments: **L47 NO START?**

Date Opened: 2-9-2016

Date Finished

3-23-2016

Meter 1 Reading:

99,935

RETURN AIR FILTER LOUVER BROKEN

TASKS PERFORMED

	Q	PARTS
AERIAL LADDER EQUIPMENT	1	9IP; STROBE
FIRE PUMP PLUMBING	1	9IP; R002436 GASKET-REAR AXLE
TANK SUCTION VALVE FIRE PUMP	1	SEAL; SEAL
HYD PUMP-PTO	1	SEAL; SEAL
CYLINDER	4	CHAIN; BEADED CHAIN W/CONN 12
WIPER BLADES	1	NEWPART; 4 IN SER KIT
FUEL TANK	1	VALVE; 8904 VALVE KIT 1 1/2 IN
FILTER	1	VALVE; 8915 VALVE 1 1/2
FUEL SYSTEM	1	PUMP; TRUNNION THREAD
SYSTEM TEST	1	PUMP; TRUNNION THREAD
OIL PAN-GASKET	1	VALVE; 8907 VALVE KIT 3 IN AKRON
MOTOR MOUNTS	1	VALVE; 8906 VALVE KIT 2.5 IN AKRON
FAULT CODE	2	PUMP; TRUNNION
PARK-CLEARANCE LIGHTS	1	PUMP; TRUNNION
CRANKING SYSTEM	1	PUMP; TRUNNION
FLUID	1	ORING; ORING CHELSEA PTO
DEF FLUID	1	NEWPART; PTO SWITCH
REAR BRAKE PADS-SHOES	1	SOLENOID; SOLENOID COVER CHELSEA PTO
AIR DRIER	1	NEWPART; LIFT CYLINDER
AIR SYSTEM	1	NEWPART; LIFT CYLINDER
WINDSHIELD	2	WIPER; WIPER BLADE - KME
SEAT BELTS	2	TUBE; O RING OIL TUBE
SEAT FRONT	2	TUBE; O RING OIL TUBE
A/C FILTER	1	GASKET; GASKET OIL RETURN LINE
	1	GASKET; GASKET OIL RETURN LINE
	1	FLANGE; FLANGE OIL TUBE
	1	EXHAUST; WRAP 2 IN WIDE
	2	NEWPART; INSULATOR FRONT MOTOR MOUNT
	1	CLAMP; EXHAUST CLAMP 33225 5 IN
	2	MOUNT; ISOLATOR MOUNT QUINT
	1	9IP; LED CLEARANCE LIGHT AMBER
	1	STARTER; 6356 QUINT 42MT STARTER
	5	GEAR; GEAR OIL SYN QT
	20	GEAR; GEAR OIL SYN QT
	4	BRAKE; QUINT REAR BRAKE SHOES
	2	BRAKE; BRAKE HARDWARE KIT
	1	9IP; SEAL QUINT
	20	STUD; WHEEL STUD
	1	9IP; 13-3052 NUT
	2	9IP; SEAL WITH RACE QUINT
	2	GASKET; GASKET AXLE FL80 R002435
	1	ADJUSTER; SLACK ADJUSTER WAB-409-10615
	1	ADJUSTER; SLACK ADJUSTER WAB-409-10615
	1	9IP; AMH-1 VALVE EXTENSION
	2	BRAKE; BRAKE DRUM QUINT
	1	BRAKE; CARTRIDGE DC100
	1	VALVE; PURGE VALVE AD-IP-IS
	1	DRAIN; QUICK DRAIN
	2	WIPER; WIPER BLADE
	1	BELT; SEAT BELT 3 POINT QUINTS
	2	NEWPART; A/C COVER BLACK

Asset Work Order History 10172453

CSHOP-2016-659

Comments: **L47 C INSPECTION**

Date Opened: 2-9-2016

Date Finished

3-3-2016

Meter 1 Reading:

99,700

TASKS PERFORMED

Q PARTS

PM SERVICE C

1 FILTER; FUEL FILTER 33120 WIX DELCO TP916
1 FILTER; 33442 FUEL FILTER
1 FLUID; ALLISON TRANS FLUID GAL
1 FILTER; WA10116 AIR 46893
1 FILTER; 51758 L/F PH725 OIL FILTERL
-1 9IP; FILTER Q47
1 9IP; FILTER Q47
1 STRAINER; STRAINER 2.5 IN
2 FILTER; 51971 OIL FILTER WIX
34 FLUID; SYN OIL BULK QTS
1 FILTER; OIL FILTER ONAN
1 FILTER; FUEL FILTER ONAN

CSHOP-2017-1198

Date Opened: 2-27-2017

Date Finished

3-15-2017

Meter 1 Reading:

112,113

C-SER.

TASKS PERFORMED

Q PARTS

PM SERVICE B

3 9OC; SYN 15W40
38 9OC; SYN 15W40
1 FILTER; OIL FILTER ONAN
2 FIL; NAPAGOLD OIL FILTER
1 FILTER; 33442 FUEL FILTER
1 FILTER; FUEL FILTER 33120 WIX DELCO TP916
1 FILTER; FUEL FILTER ONAN

CSHOP-2017-133

Date Opened: 1-6-2017

Date Finished

1-6-2017

Meter 1 Reading:

105,778

TASKS PERFORMED

NO PARTS USED

UL AERIAL TESTING

VENDOR? MISTRAS GROUP INC

CSHOP-2017-189

Date Opened: 1-9-2017

Date Finished

1-9-2017

Meter 1 Reading:

105,778

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM

Asset Work Order History 10172453

CSHOP-2017-23

Comments: **L-47 ELECTRICAL PROBLEM CALL OUT**

Date Opened: 1-3-2017 Date Finished 1-3-2017 Meter 1 Reading: 105,778

TASKS PERFORMED

NO PARTS USED

ELECTRICAL

CSHOP-2017-2643

Date Opened: 5-5-2017 Date Finished 5-5-2017 Meter 1 Reading: 105,778

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM
DIAGNOSE ELECTRICAL

CSHOP-2017-2685

Date Opened: 5-8-2017 Date Finished 5-9-2017 Meter 1 Reading: 105,778

TASKS PERFORMED

Q PARTS

FIRE APPARATUS
WIPERS-WASHER

2 WIPER; WIPER BLADE - KME

Service Requests:

05/06/2017 W/S WIPER / 17: INSUFFICIENT LUBRICANT / REPAIR
WIPERS BAD BOTH SIDES

05/08/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
THE WATER TANK ON LADDER 47 HAS A CONSTANT LEAK FROM THE UNDERSIDE OF THE TANK.

CSHOP-2017-2809

Date Opened: 5-12-2017 Date Finished 5-15-2017 Meter 1 Reading: 105,778

TASKS PERFORMED

NO PARTS USED

COMMERCIAL WORK - OUTSIDE AGENCY

VENDOR? DAN CALLAGHAN ENTERPRISES

Service Requests:

05/12/2017 TIRES / 18: LEAKING / REPAIR
DRIVER OUTSIDE REAR AIR LEAK. HAS BEEN FILLED TWICE AND STILL HAS A SLOW LEAK. GOOD YEAR G288 MSA
12.00 R24

Asset Work Order History 10172453

CSHOP-2017-296

Comments: **L47 AERIAL MASTER SWITCH INDICATOR NOT WORKING**

Date Opened: 1-13-2017 Date Finished 3-21-2017 Meter 1 Reading: 105,778

TASKS PERFORMED

Q PARTS

FIRE PUMP 1 **NONSTOCK; FREIGHT CHARGE**
INSTRUMENTS-GAUGES-METERS 4 **MOUNT; LPVM-5 SM MOUNT**
HVAC SYSTEM 1 **2FR; 2FR**

Service Requests:

01/13/2017 **ELECTRICAL / 19: LOOSE / REPAIR**
"AERIAL MASTER" SWITCH INSIDE THE CAB OF THE LADDER IS NOT LIGHTING UP WHEN IT IS TURNED ON. THE POWER WORKS, THERE IS NO ISSUES THERE, JUST NEEDS A NEW SWITCH

CSHOP-2017-3038

Date Opened: 5-23-2017 Date Finished 6-2-2017 Meter 1 Reading: 113,797

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER 1 **9IP; LOCKING ARM RH SMEAL**
FIRE APPARATUS 1 **FERRARA; LOCKING ARN LH SMEAL**

CSHOP-2017-3069

Date Opened: 5-24-2017 Date Finished 5-25-2017 Meter 1 Reading: 106,000

TASKS PERFORMED

NO PARTS USED

ENGINE COOLANT TEMPERATURE SE

CSHOP-2017-3283

Comments: **CHECK COOLANT**

Date Opened: 6-5-2017 Date Finished 6-5-2017 Meter 1 Reading: 106,000

TASKS PERFORMED

NO PARTS USED

ENGINE COOLANT TEMPERATURE SE

CSHOP-2017-3325

Comments: **ALREADY REPLACED NEW GLASS ORDERED 6-7-17**

Date Opened: 6-6-2017 Date Finished 10-26-2017 Meter 1 Reading: 115,720

TASKS PERFORMED

Q PARTS

WINDSHIELD 1 **9AP; WINDSHIELD RH**

VENDOR? SAFELITE FULLFILLMENT GLASS

Service Requests:

06/05/2017 **WINDOW / 12: BROKEN / EXCHANGE - NEW**
FRONT OFFICERS SIDE WINDSHIELD CRACKED

Asset Work Order History 10172453

CSHOP-2017-3382

Date Opened: 6-8-2017 Date Finished 6-14-2017 Meter 1 Reading: 106,000

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE APPARATUS
HVAC SYSTEM

CSHOP-2017-3602

Date Opened: 6-19-2017 Date Finished 8-3-2017 Meter 1 Reading: 114,105

TASKS PERFORMED

Q PARTS

INTERCOM SYSTEM - EMERGENCY V	1	TEM; TAPE
FIRE APPARATUS	2	MMM; ELECTRICAL TAPE
EGR VALVE	1	MMM; MARINE ADH SEAL WHITE
RADIATOR	1	5AB; 5AB
HVAC SYSTEM	3	2DD; STUD
	1	9IP; BELT
	2	2DD; CLAMP
	1	2DD; GASKET
	1	2DD; BELLOW
	1	2DD; EGR VALVE ASM
	3	2DD; NUT
	1	TEM; EXPANSION VALVE
	1	NONSTOCK; FREIGHT CHARGE
	-1	2TP; AC COMPRESSOR U4664
	1	2TP; AC COMPRESSOR U4664
	1	9IP; ATF DETRAN 3
	1	2TP; A/C COMPRESSOR
	1	9HY; HOSE MADE
	1	TEM; FILTER DRIER
	1	FIL; NAPAGOLD FUEL FILTER
	1	9IP; CAP RADIATOR 10 LB

Service Requests:

06/17/2017 SERVICE REQUEST / 12: BROKEN / REPAIR
SHORE LINE AUTO EJECT RECEPTACLE IS NOT WORKING ON L47

CSHOP-2017-435

Date Opened: 1-19-2017 Date Finished 6-5-2017 Meter 1 Reading: 105,778

UL REPAIRS

TASKS PERFORMED

Q PARTS

CRADLE AERIAL LADDER	1	5EF; WATER WAY SEAL KIT
WATERWAY AERIAL LADDER	1	9AP; 9AP
HYDRAULIC CYLINDER EXTENSION	1	NEWPART; FUSE HOLDER
INTERCOM SYSTEM - EMERGENCY V	1	NONSTOCK; FREIGHT CHARGE
EQUIPMENT MOUNTING BRACKETS	1	5FF; MASTER INTERCOM
UL AERIAL TESTING	1	5FF; MASTER INTERCOM
	1	5FF; SLAVE INTERCOM

Asset Work Order History 10172453

CSHOP-2017-4750

Date Opened: 8-14-2017 Date Finished 8-17-2017 Meter 1 Reading: 114,105

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
CAB & BODY MOUNT
REPAIR FROM PM - DECALS/CLEANLINESS

6 MAC; NON-CHLOR BRAKE CLNR
2 5SC; CAB LATCH LOCK

CSHOP-2017-4954

Date Opened: 8-23-2017 Date Finished 8-23-2017 Meter 1 Reading: 114,105

TASKS PERFORMED

NO PARTS USED

COMMERCIAL WORK - OUTSIDE AGENCY

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2017-5015

Date Opened: 8-25-2017 Date Finished 8-28-2017 Meter 1 Reading: 115,720

TASKS PERFORMED

Q PARTS

AIR SYSTEM

1 9IP; VALVE AIR CONTROL

CSHOP-2017-5016

Comments: **LADDER WARNING STAYS ON**

Date Opened: 8-25-2017 Date Finished 8-28-2017 Meter 1 Reading: 115,472

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
INSTRUMENTS-GAUGES-METERS

Service Requests:

08/25/2017 ALARMS / 38: SHORTED / TRAVEL TO STATION 29. SPOKE WITH LADDER DRIVER. LADDER/ OUTF
ALARM SIGNALS

Asset Work Order History 10172453

CSHOP-2017-5224

Date Opened: 9-6-2017

Date Finished

11-30-2017

Meter 1 Reading:

115,617

TASKS PERFORMED

Q PARTS

BATTERY	6	1AD; BATTERY 31 SERIES
TRANSMISSION	-1	BRG; WB/CUP
REPAIR FROM PM - WHEEL SEALS	2	BRG; WB/CUP
WHEEL BEARINGS	1	9HD; OIL SEAL
BRAKE CHAMBER	2	9HD; OIL SEAL
BRAKES	1	NONSTOCK; FREIGHT CHARGE
AIR SYSTEM	1	NONSTOCK; FREIGHT CHARGE
	-1	9HD; AXLE SEAL
	2	9HD; AXLE SEAL
	1	9IP; GASKET AXLE FL80 R002435
	2	9IP; GASKET AXLE FL80 R002435
	2	MBI; HARDWARE KIT
	-1	9AP; BEARING
	2	9AP; BEARING
	1	FPG; GASKET MATERIAL
	-1	TWD; CUP
	2	TWD; CUP
	1	BK; FORM-A GASKET SEALANT
	5	9IP; 13-3052 NUT
	2	9HD; BEARING RACE CUP
	2	9HD; BEARING CUP
	12	MAC; NON-CHLOR BRAKE CLNR
	-1	9AP; BEARING
	2	9AP; BEARING
	2	9HD; BRAKE CHAMBER
	2	NTH; ADAPTER
	2	9HD; SLACK ADJ
	1	NONSTOCK; FREIGHT CHARGE
	12	2TP; WHEEL STUD
	4	MBI; REMAN/BS
	2	9HD; BRAKE DRUM
	10	9IP; WHEEL STUD
	20	9OC; GEAR OIL BULK
	-20	9OC; GEAR OIL BULK
	10	GEAR; GEAR OIL SYN QT
	10	GEAR; GEAR OIL SYN QT
	1	2IH; SEAL, DIPSTICK-ALLISON
	1	NCB; BLASTER PENETRANT

CSHOP-2017-5227

Date Opened: 9-6-2017

Date Finished

9-6-2017

Meter 1 Reading:

115,720

TASKS PERFORMED

NO PARTS USED

REAR TIRES

VENDOR? ELPEX TIRE TIRESOLES

Asset Work Order History 10172453

CSHOP-2017-616

Comments: **L47 TELESCOPING LIGHT BULB IS OUT.**

Date Opened: 1-30-2017 Date Finished: 2-24-2017 Meter 1 Reading: 105,778

TASKS PERFORMED

Q PARTS

COOLING SYSTEM
DIAGNOSE ELECTRICAL

1 9IP; CAP RADIATOR 10 LB
1 BULB; LB-M15 240 V BULB
1 BULB; LB-M15 240 V BULB
1 BULB; LB-M15 240 V BULB
2 DOOR; MAGNETS ROM DOORS

Service Requests:

01/29/2017 BODY / 19: LOOSE / REPAIR
LEFT TELESCOPING LIGHT BULB IS BROKEN.

CSHOP-2017-660

Date Opened: 1-31-2017 Date Finished: 1-31-2017 Meter 1 Reading: 105,778

TASKS PERFORMED

NO PARTS USED

DIAGNOSE ELECTRICAL

Service Requests:

01/31/2017 ALARMS / 19: LOOSE / REPAIR
ALARM SIGNALS. OPEN DOOR ALARM FOR REAR OF THE TRUCK GOING OFF. ALL DOORS ARE CLOSED.

CSHOP-2017-7183

Date Opened: 12-17-2017 Date Finished: 1-28-2018 Meter 1 Reading: 116,817

TASKS PERFORMED

Q PARTS

AIR SYSTEM

1 TWD; BENDIX

CSHOP-2017-7216

Date Opened: 12-18-2017 Date Finished: 12-20-2017 Meter 1 Reading: 116,012

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

Service Requests:

12/18/2017 BRAKES / 18: LEAKING / REPAIR
BRAKE ISSUES- AIR LEAK , NOT ABLE TO RELEASE BRAKES OR RAISE DRIVERS SEAT. AIR LEAKS OUT COMPLETELY
IN 1.5 HOURS AND TAKES 5 MIN TO FILL AIR TANK.

12/18/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
SERVICE REQUEST- OFFICER SIDE REAR VIEW MIRROR REMOTE NOT WORKING

Asset Work Order History 10172453

CSHOP-2017-737

Comments: **LADDER 47**

Date Opened: 2-6-2017

Date Finished

3-21-2017

Meter 1 Reading:

105,778

TASKS PERFORMED

Q PARTS

FIRE APPARATUS
EMERGENCY EQUIPMENT

2 6AK; C236 NXTGEN INSERT CUTTERS

Service Requests:

02/03/2017 SERVICE REQUEST / 19: LOOSE / REPAIR
SERVICE REQUEST- OFFICERS SIDE PISTON INTAKE VALVE LEAKING

02/05/2017 SERVICE REQUEST / 19: LOOSE / REPAIR
SERVICE REQUEST. GENESIS CUTTERS YELLOW REPLACEABLE BLADES ARE CHIPPED AND NEED TO BE
REPLACED ON BOTH SIDES.

Asset Work Order History 10172453

CSHOP-2017-822

Comments: **L47**

Date Opened: 4-27-2017

Date Finished

6-5-2017

Meter 1 Reading:

106,000

CONDENSER FAN INOP.

TASKS PERFORMED

	Q	PARTS
PUMP PANEL	1	5TN; GUAGE 2.5 0-600
CAB TILT PUMP	1	5TN; GUAGE 2.5 0-600
SYSTEM TEST	2	GAUGE; GAUGE 0-600 PSI
TURN SIGNAL LIGHTS	1	GAUGE; GAUGE COMPOUND LIQUID FILLED
SWITCH-ELECTRICAL	1	LIT; LED MDL 33 M C GMT KT
OIL COOLER-HEAT EXCHANGER	1	9HY; 9HY
FILTER	1	9IP; WASHER CAP WPB-FREIGHTLINER
DIPSTICK AND TUBE	1	SWITCH; TURN SIGNAL SWITCH
SUSPENSION	1	5EF; ROCKER SWITCH COVER RED
REAR BRAKE PADS-SHOES	1	5EF; ON/OFF ROCKER SWITCH 6P
AIR DRIER	1	NW; SWITCH
CAB STEP	1	NONSTOCK; FREIGHT CHARGE
A/C CONDENSER FAN	1	2DD; TRANSMISSION OIL COOLER
	14	9OC; BULK TRANS SYN
	40	FLUID; COOLANT ANTIFREEZE GAL
	40	9OC; COOLANT
	40	9OC; COOLANT
	40	9OC; COOLANT
	1	9IP; 29548988 TRANS FILTER ALLISON
	1	9AP; TRANS DIPSTICK
	2	9IP; R002436 GASKET-REAR AXLE
	4	BRAKE; QUINT REAR BRAKE SHOES
	14	FLUID; ALLISON TRANS FLUID GAL
	2	TWD; HD PLUS
	1	5FF; STEEL RIM
	2	2TP; 2TP
	-10	9IP; WHEEL STUD
	20	9IP; WHEEL STUD
	2	9IP; SEAL WITH RACE QUINT
	2	2TP; AXEL GASKET
	1	STRAP; 3683 STRAP-RATCHET TYPE
	1	NONSTOCK; FREIGHT CHARGE
	1	FIL; NAPAGOLD AIR FILTER
	2	SVP; CNDSRFAN

Service Requests:

02/08/2017

SERVICE REQUEST / 18: LEAKING / REPAIRED

SERVICE REQUEST..... REAR AXLE LEAKING FLUID OUT OF THE DRIVER SIDE COVER AT THE REAR WHEEL.

02/12/2017

SERVICE REQUEST / 12: BROKEN / REPAIR

SERVICE REQUEST. REAR DIFFERENTIAL LEAKING FROM DRIVER SIDE AXLE COVER NEEDS TO BE FIXED. ENGINE OIL LEVEL IS LOW AND NEEDS OIL. ENGINE COOLANT LEVEL IS LOW AND NEEDS COOLANT

Asset Work Order History 10172453

CSHOP-2017-857

Comments: **L47 LOW ON OIL NONE AT STATION**

Date Opened: 2-10-2017 Date Finished 2-13-2017 Meter 1 Reading: 112,080

TASKS PERFORMED

NO PARTS USED

FIRE APPARATUS

Service Requests:

02/10/2017 ENGINE / 19: LOOSE / REPAIR
OIL IS LOW AND THERE IS NO OIL AT STATION 47

CSHOP-2017-880

Date Opened: 2-12-2017 Date Finished 2-16-2017 Meter 1 Reading: 105,778

OIL LEAKING FROM DIFF. & NEED MOTOR & COOLANT

TASKS PERFORMED

Q PARTS

REAR HUB SEAL-GASKET

12 9IP; MOTOR OIL
6 PAF; ANTIFRZ

Service Requests:

02/12/2017 BRAKES / 17: INSUFFICIENT LUBRICANT / LUBRICATE

CSHOP-2018-105

Date Opened: 1-5-2018 Date Finished 2-14-2018 Meter 1 Reading: 117,236

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
COOLING SYSTEM
VENDOR TIRE REPAIR/CHANGE
AIR SYSTEM
BODY EXTERIOR

1 9AP; ARM
1 9AP; ARM, LOCKING PINN RH

Service Requests:

01/05/2018 SERVICE REQUEST / 18: LEAKING / REPAIR
OFFICER SIDE RESCUE/WATER TOWER BRACKET IS CRACKED AT THE WELD.

Asset Work Order History 10172453

CSHOP-2018-11

Comments: **SPARE LADDER AT 57**

Date Opened: 1-2-2018

Date Finished

1-2-2018

Meter 1 Reading:

116,279

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM
INSTRUMENTS-GAUGES-METERS
HVAC SYSTEM

Service Requests:

01/02/2018

AIR RIDE / 18: LEAKING / REPAIR

AIR RIDE ISSUE. AIR LEAK CAUSING RESPOND DELAYS.

CSHOP-2018-1340

Date Opened: 3-6-2018

Date Finished

3-20-2018

Meter 1 Reading:

118,047

TASKS PERFORMED

Q PARTS

PM SERVICE C AERIAL

1	FIL; NAPAGOLD OIL FILTER
1	FIL; NAPAGOLD OIL FILTER
1	FIL; NAPAGOLD OIL FILTER
40	9IP; 15W40 MOTOR OIL NON SYN
3	9IP; 15W40 MOTOR OIL NON SYN
1	FIL; NAPAGOLD FUEL FILTER
1	FIL; NAPAGOLD FUEL FILTER

Asset Work Order History 10172453

CSHOP-2018-1553

Date Opened: 3-16-2018

Date Finished

6-14-2018

Meter 1 Reading:

118,570

TASKS PERFORMED

	Q	PARTS
WATERWAY AERIAL LADDER	1	9AP; REBUILD CYLINDER
HYDRAULIC CYLINDER EXTENSION	2	9OC; BULK TRANS SYN
FIRE PUMP PLUMBING	1	9IP; GASKET 2 1/2"
FIRE PUMP	1	5AB; 2.5 BALL KIT COMPOSITE
HOSE STORAGE BOX BODY	1	1DB; PUMP
STEP	1	NONSTOCK; FREIGHT CHARGE
HYD PUMP-PTO	1	9AP; -30-0 GAUGE
FILTER	1	FIL; NAPA TRANS FILTER
HYDRAULIC SYSTEM	4	9OC; GEAR OIL BULK
REPAIR FROM PM - TRANSFER CASE	1	5SC; ZM PACKING KIT
VACUUM PUMP	38	9AP; HEAT SENSOR LADDER LABELS
REPAIR FROM PM - GROUND LADDERS	1	9AP; AUX BOOSTER COOLER
AIR FILTER	1	9AP; SOLENOILD
COOLING SYSTEM	1	NONSTOCK; FREIGHT CHARGE
REPAIR FROM PM - TILT CAB	1	2FL; CAP
ENGINE AND ACCESSORIES	1	9IP; WA10116 AIR 46893
HANDLIGHT	2	9AP; JW SPEAKER LOW BEAM
HEADLIGHTS HIGH BEAM	2	9AP; JW SPEAKER HIGH BEAM
HEADLIGHTS LOW BEAM	1	5EF; PROXIMITY SWITCH
LIGHTING SYSTEM	1	9IP; BULB
REPAIR FROM PM - POWER STEERING	4	LIT; LED M C LAMP
DIAGNOSE ELECTRICAL	1	9IP; CATHODE LIGHT WATERPROOF
FAULT CODE	1	FIL; NAPA HYDRAULIC FILTER
REAR SPRING	4	9OC; BULK TRANS SYN
TILT & RAISE-LOWER MECHANISM	12	9AP; BRAKE CLEANER
HOSES-LINES & FITTINGS (AIR &	1	FIL; NAPAGOLD AIR FILTER
REPAIR FROM PM - DECALS/CLEANLINESS	4	9IP; ALLISON TRANS FLUID GAL
REPAIR FROM PM - TRANSMISSION	-4	9OC; BULK TRANS SYN
AIR DRIER	51	9OC; BULK TRANS SYN
AIR SYSTEM	1	TWD; E-6VALVE BRAKE
BACK-UP ALARM	1	9IP; DC23-5011 50 # HOLD-OPEN RESCUE
DOOR	3	9XX; 134A 10194654
SUN VISOR	2	BK; PTEX ULTRA BLACK 30Z
SEAT FRONT	1	TEM; EXPANSION VALVE
BLOWER MOTOR	1	5EF; BLOWER MOTOR
HOSE-LINES & FITTINGS	1	TEM; FILTER DRIER
BELT(S)- A-C COMPRESSOR	1	5EF; ROCKER SWITCH BLOWER MOTOR
A/C HOSES/FITTINGS	1	5EF; COVER, SWITCH, BLOWER 360000040
	1	NONSTOCK; FREIGHT CHARGE
	1	9HY; AC HOSE WO#1553

Service Requests:

03/16/2018

SERVICE REQUEST / 12: BROKEN / REPAIR ELECTRICAL FAULT

Asset Work Order History 10172453

CSHOP-2018-2183

Date Opened: 4-19-2018 Date Finished 6-19-2018 Meter 1 Reading: 118,570

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
LADDER RACK BODY

Service Requests:

04/19/2018 SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW
WATER WAY TO RESCUE MODE LEVER IS BROKE ON RIGHT SIDE OF LADDER.

CSHOP-2018-272

Comments: **TRK 57**
Date Opened: 1-12-2018 Date Finished 1-12-2018 Meter 1 Reading: 116,435

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE APPARATUS
DIAGNOSE ELECTRICAL

Service Requests:

01/11/2018 MIRROR / 18: LEAKING / REPAIR
MIRROR ISSUE- OFFICERS SIDE POWER MIRROR NOT WORKING

01/11/2018 SERVICE REQUEST / 18: LEAKING / REPAIR
HYDRAULIC FLUID LEAKING UNDER BASE OF LADDER WHERE MOTOR THAT SPINS THE TURNTABLE IS LOCATED.
LADDER WILL NOT ROTATE LEFT AND HYDRAULIC CONTROL THAT ROTATES THE LADDER HAS NO RESISTANCE.

CSHOP-2018-2837

Comments: **TRK 35**
Date Opened: 5-22-2018 Date Finished 6-5-2018 Meter 1 Reading: 118,570

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
COOLING SYSTEM

6 NBH; SIL SDI COOLANT HOSE
-10 9OC; COOLANT
10 9OC; COOLANT
10 FLUID; COOLANT ANTIFREEZE GAL

Service Requests:

05/22/2018 RADIATOR / 12: BROKEN / EXCHANGE - NEW
RADIATOR LEAKING COOLANT FLOWING OUT ON FLOOR.

05/22/2018 A/C / 18: LEAKING / REPAIR REPAIRS WILL BE DONE AT TIME OF SERVICE AND THEY GET BACK I
A/C ISSUE AC LEAKING WATER ON OFFICER SIDE NEXT TO FEET.

Asset Work Order History 10172453

CSHOP-2018-2866

Date Opened: 5-23-2018 Date Finished 6-7-2018 Meter 1 Reading: 118,570

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM

Service Requests:

05/23/2018 LIGHTS / 18: LEAKING / REPAIR
VEHICLE LIGHTS NOT WORKING, DRIVER SIDE SCENE LIGHT NOT WORKING.

CSHOP-2018-3019

Comments: **AT ST-35**

Date Opened: 6-1-2018 Date Finished 6-1-2018 Meter 1 Reading: 119,712

TASKS PERFORMED

Q PARTS

COMPUTER CONTROLS

1 9AP; VISTA

Service Requests:

05/31/2018 SERVICE REQUEST / 38: SHORTED / REPLACED VISTA SCREEN AND REPROGRAMMED
VEHICLE CENTER CONSOLE TO OPERATE ALL SYSTEMS IS SEIZING UP OR GOING BLANK. HAVE TO SHUT DOWN
TRUCK AND RESTART TO GET BACK IN OPERATION. TRUCK SHOULD BE GOING TO SHOP IN AM FOR RADIOS.

CSHOP-2018-3279

Comments: **TRK29**

Date Opened: 6-12-2018 Date Finished 6-22-2018 Meter 1 Reading: 118,570

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM
DIAGNOSE ELECTRICAL
HVAC SYSTEM

1 9IP; HALOGEN LIGHT 120V/1000W

Service Requests:

06/12/2018 LIGHTS / 18: LEAKING / REPAIR
VEHICLE LIGHTS NOT WORKING, RIGHT SIDE TELESCOPE LIGHT NOT WORKING

CSHOP-2018-3367

Date Opened: 6-15-2018 Date Finished 7-10-2018 Meter 1 Reading: 118,570

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES
CHARGING SYSTEM
BRAKES

1 5SC; DONALDSON FILTER
1 MBI; VALVE

Asset Work Order History 10172453

CSHOP-2018-3434

Date Opened: 6-19-2018 Date Finished 6-19-2018 Meter 1 Reading: 118,570

TASKS PERFORMED

NO PARTS USED

CAB-INTERIOR ACCESSORIES
HVAC SYSTEM

Service Requests:

06/18/2018 SERVICE REQUEST / 18: LEAKING / REPAIR
ELECTRICAL ISSUE. WIND SHIED WIPERS WILL NOT TURN OFF.

CSHOP-2018-356

Date Opened: 1-17-2018 Date Finished 2-28-2018 Meter 1 Reading: 117,522

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
WIPERS-WASHER
AIR SYSTEM
BODY EXTERIOR

2 1AN; WIPER BLADES
1 NONSTOCK; FREIGHT CHARGE
2 5EF; PROXIMITY SWITCH

Service Requests:

01/16/2018 DOOR / 18: LEAKING / REPAIR
VEHICLE DOORS OIC COMPARTMENT 4 SENSOR CONTINUE TO BE ON.

01/16/2018 W/S WIPER / 18: LEAKING / REPAIR
WIPERS BAD BOTH OFFICER AND DRIVER

01/16/2018 BRAKES / 18: LEAKING / REPAIR
AIR SYSTEM HAS A LEAK. AT THIS TIME HAVING TO HOOK COMPRESSOR TO AIR LINE IN ORDER TO MAINTAIN
PRESSURE IN THE SYSTEM.

CSHOP-2018-3644

Date Opened: 6-28-2018 Date Finished 6-28-2018 Meter 1 Reading: 118,570

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM

CSHOP-2018-3699

Date Opened: 7-2-2018 Date Finished 7-2-2018 Meter 1 Reading: 118,570

TASKS PERFORMED

NO PARTS USED

REPAIR FROM PM - OUTRIGGERS

Service Requests:

06/30/2018 SERVICE REQUEST / 11: BINDS/STICKS / REPAIR
THE OUT-RIGGERS ARE NOT WORKING PROPERLY UNLESS THE HIGH IDLE IS ENGAGED.

Asset Work Order History 10172453

CSHOP-2018-3741

Comments: **OUTRIGGERS INOP AT ST47**

Date Opened: 7-3-2018

Date Finished

9-14-2018

Meter 1 Reading:

120,813

TASKS PERFORMED

AERIAL LADDER EQUIPMENT
CAB TILT PUMP
WIPER MOTOR
ENGINE AND ACCESSORIES
OIL COOLER-HEAT EXCHANGER
POWER STEERING PUMP
FUEL GAUGE

Q PARTS

1 5EF; PTO ASM
-1 5EF; PTO ASM
1 5EF; PTO ASM
1 9AP; OIL ABSORBENT MAT
1 TWD; C-1COCK DRAIN
12 9AP; BRAKE CLEAN
1 9AP; SWITCH, PTO
1 BK; PTEX ULTRA GREY 3OZ
4 2DD; AMP TERMINAL
6 2DD; AMP TERMINAL
1 FRT
30 BK; KNIFE
1 2DD; TURBO DRAIN TUBE
12 9AP; BRAKE CLEAN
1 NCB; DEGREASER MULTI PURP
1 FIL; NAPA TRANS FILTER
1 9HY; FITTING
1 9HY; HOSE MADE
1 FIL; NAPA HYDRAULIC FILTER
12 9AP; BRAKE CLEAN
1 5EF; FUEL SENDING UNIT
1 9IP; 301-104 FUEL GAUGE

CSHOP-2018-5371

Comments: **TRK57**

Date Opened: 9-20-2018

Date Finished

10-15-2018

Meter 1 Reading:

118,570

TASKS PERFORMED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE APPARATUS
HVAC SYSTEM

Q PARTS

1 BK; CURCUIT TESTER
1 NONSTOCK; FREIGHT CHARGE
1 5EF; WATERWAY ACUATOR 12V

Service Requests:

09/19/2018

SERVICE REQUEST / 18: LEAKING / REPAIR

TYPE PROBLEM INTO DESCRIPTION LADDER IN RESCUE MODE, WILL NOT TRANSFER INTO WATERWAY.

CSHOP-2018-5499

Date Opened: 9-26-2018

Date Finished

9-26-2018

Meter 1 Reading:

118,570

TASKS PERFORMED

SUSPENSION

NO PARTS USED

Asset Work Order History 10172453

CSHOP-2018-5545

Date Opened: 9-28-2018 Date Finished 10-1-2018 Meter 1 Reading: 118,570

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE APPARATUS

Service Requests:

09/28/2018 HAZARD / 18: LEAKING / REPAIR
HAZARDOUS ISSUE- DISCHARGE 2 VALVE IS BROKE

CSHOP-2018-5597

Date Opened: 10-1-2018 Date Finished 10-1-2018 Meter 1 Reading: 118,570

TASKS PERFORMED

NO PARTS USED

TIRES ALL

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2018-5625

Comments: **AIR HORN SOUNDING**

Date Opened: 10-2-2018 Date Finished 10-2-2018 Meter 1 Reading: 118,570

TASKS PERFORMED

NO PARTS USED

AIR HORN

CSHOP-2018-5680

Date Opened: 10-8-2018 Date Finished 10-10-2018 Meter 1 Reading: 118,570

TASKS PERFORMED

NO PARTS USED

FIRE APPARATUS

CSHOP-2018-5853

Comments: **SPARE LADDER AT 57**

Date Opened: 10-16-2018 Date Finished 10-16-2018 Meter 1 Reading: 118,570

TASKS PERFORMED

NO PARTS USED

AIR HORN

Service Requests:

10/16/2018 SERVICE REQUEST / 18: LEAKING / REPAIR
AIR HORN SOUND STICKS WHEN BUTTON IS PRESSED ON DRIVER OR OFFICER SIDE, WILL NOT SHUT OFF
BLASTING HORN.

Asset Work Order History 10172453

CSHOP-2018-6194

Date Opened: 10-31-2018 Date Finished 2-14-2019 Meter 1 Reading: 123,377

TASKS PERFORMED

Q PARTS

FIRE PUMP	1	5SC; ZM PACKING KIT
FIRE APPARATUS	1	FRT
COOLING SYSTEM	1	9AP; CORNER LEDS
ENGINE AND ACCESSORIES	2	5FR; LIGHT HEAD
QUARTZ LIGHT	2	5FR; LIGHT HEAD
ELECTRICAL	1	5EF; BRACKET
SUSPENSION	2	NS; GAS GRANDE 65 HD SHOC
STEERING	1	5EF; STEERING COULMN
	12	9AP; BRAKE CLEAN

CSHOP-2018-7125

Comments: **L15**

Date Opened: 12-17-2018 Date Finished 12-21-2018 Meter 1 Reading: 122,345

TASKS PERFORMED

NO PARTS USED

AUTO-EJECT
TIRE
AIR SYSTEM

Service Requests:

-
- | | |
|------------|--|
| 12/16/2018 | AIR RIDE / 13: CHIPPED / REPAIR
AIR RIDE ISSUE. L15 SPARE LEAK CAUSING A DELAY IN RESPONSE TIME. |
| 12/21/2018 | TIRES / 17: INSUFFICIENT LUBRICANT / REPAIR
RIGHT REAR TIRES LEAKING AGAIN. WAS CHECKED LAST SHIFT AND HAD 30PSI FILLED TO 120 PSI AND NOW BACK AT 40PSI HAS A LEAK |
| 12/21/2018 | ALARMS / 12: BROKEN / REPAIR
FUSE BLOWN FOR ON BOARD SHORELINE CHARGER. CURRENTLY INOP |
-

CSHOP-2018-7271

Date Opened: 12-26-2018 Date Finished 1-4-2019 Meter 1 Reading: 122,789

TASKS PERFORMED

NO PARTS USED

LIGHTING SYSTEM

Service Requests:

-
- | | |
|------------|---|
| 12/22/2018 | LIGHTS / 18: LEAKING / REPAIR
VEHICLE LIGHTS NOT WORKING- SPARE L15 DRIVER SIDE SCENE LIGHT IS OUT |
| 12/31/2018 | LIGHTS / 12: BROKEN / REPAIR
VEHICLE LIGHTS NOT WORKING. DRIVER SIDE SCENE LIGHT IS OUT. |
-

Asset Work Order History 10172453

CSHOP-2018-7322

Date Opened: 12-26-2018 Date Finished 12-26-2018 Meter 1 Reading: 122,545

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2019-11

Date Opened: 1-2-2019 Date Finished 1-3-2019 Meter 1 Reading: 122,712

TASKS PERFORMED

NO PARTS USED

ABS COMPUTER CONTROLS

Service Requests:

01/01/2019 BRAKES / 18: LEAKING / REPAIR
BRAKE ISSUES- ABS LIGHT CAME ON TEMPORARILY THEN HAS GONE OFF

CSHOP-2019-1161

Comments: **PLEASE DO NOT CLOSE THIS WORK ORDER WE HAVE PARTS ORDERED ON THIS**

Date Opened: 3-4-2019 Date Finished 4-23-2019 Meter 1 Reading: 123,377

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
COOLING SYSTEM

CSHOP-2019-12

Date Opened: 1-2-2019 Date Finished 1-3-2019 Meter 1 Reading: 122,712

TASKS PERFORMED

Q PARTS

AUTO-EJECT

1 6KU; AUTO EJECT

Service Requests:

01/01/2019 SERVICE REQUEST / 12: BROKEN / REPAIR
SHORELINE EJECTOR DOES NOT APPEAR TO BE EJECTING.

CSHOP-2019-13

Comments: **COOLANT LEAK SPARE LADDER AT ST15**

Date Opened: 1-2-2019 Date Finished 1-3-2019 Meter 1 Reading: 122,712

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
ENGINE COOLANT TEMPERATURE SE
QUARTZ LIGHT

1 BK; RADIATOR CAPS
1 9IP; HALOGEN BULB 1000 WATT WPB
1 9IP; HALOGEN BULB 1000 WATT WPB

Service Requests:

01/01/2019 LIGHTS / 12: BROKEN / REPAIR
VEHICLE LIGHTS NOT WORKING- OFFICER SIDE TELE LIGHT IS OUT THAT RUNS ON THE GENERATOR

Asset Work Order History 10172453

CSHOP-2019-1430

Date Opened: 3-18-2019 Date Finished 3-18-2019 Meter 1 Reading: 124,510

EVAPORATOR DRAIN PLUGGED UP

TASKS PERFORMED

NO PARTS USED

QUALITY CHECK-REPAIRS
WIPER BLADES
DIP STICK TUBE
EVAPORATOR-EVAPORATOR MOTOR

CSHOP-2019-1488

Comments: **SPARE LADDER AT 35**

Date Opened: 3-20-2019 Date Finished 4-12-2019 Meter 1 Reading: 125,012

TASKS PERFORMED

Q PARTS

COOLING SYSTEM
SIREN

1 5EF; STARTERSOLENOIDEONE
1 9IP; NODE HERCULES V-MUX
-1 9IP; NODE HERCULES V-MUX
1 BK; ATC FUSEHOLDER-CARD

Service Requests:

03/20/2019 SERVICE REQUEST / 12: BROKEN / REPAIR
THE FEDERAL Q SIREN STOPPED WORKING

CSHOP-2019-151

Date Opened: 1-9-2019 Date Finished 2-5-2019 Meter 1 Reading: 123,034

TASKS PERFORMED

Q PARTS

PM SERVICE C AERIAL

1 FIL; NAPAGOLD OIL FILTER
1 9AP; COME ALONG
1 FIL; NAPAGOLD FUEL FILTER
40 4PC; 15W40 PREMIUM BLUE OIL
2 NCB; GOJO SCRUB WIPES 72CT
12 9AP; BRAKE CLEAN
1 9AP; METAL TREATMENT
2 FIL; NAPAGOLD OIL FILTER
2 BK; SPRAYER
-1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPAGOLD FUEL FILTER
1 BK; FITTING
3 8HD; PAINT BRUSH 1IN
1 FIL; NAPAGOLD FUEL FILTER

CSHOP-2019-1553

Comments: **DIESEL LEAK**

Date Opened: 3-25-2019 Date Finished 3-25-2019 Meter 1 Reading: 123,377

TASKS PERFORMED

Q PARTS

FUEL SYSTEM

1 FIL; NAPAGOLD FUEL FILTER

Asset Work Order History 10172453

CSHOP-2019-164

Date Opened: 1-10-2019

Date Finished

2-14-2019

Meter 1 Reading:

123,377

BRACKET BROKE EAR OFF COMPRESSOR

TASKS PERFORMED

PIVOT AERIAL LADDER
AERIAL LADDER EQUIPMENT
INTERCOM SYSTEM - EMERGENCY V
DISCHARGE GAUGE
SIDE COMPARTMENT BODY
WIPER BLADES
BY-PASS HOSES
SPOT LIGHTS
PARK-CLEARANCE LIGHTS
BELT
FLUID
RESERVOIR
FRONT BRAKE PADS-SHOES
AIR DRIER
AIR SYSTEM
STEPS
A/C HOSES/FITTINGS

Q PARTS

1	TWD; DCK/BUMP
2	LUC; LUCAS RED-TACKY GRS
3	5TN; GUAGE 2.5 0-600
1	BK; ATC FUSEHOLDER-CARD
3	5EF; PROXIMITY SWITCH
1	5EF; PROXIMITY SWITCH
1	9IP; 11 IN HOLD-OPEN 30LB
2	1AN; WIPER BLADE
1	9HY; HOSE ELBOW 2.25"
1	NBH; RAD/HOSE
2	9IP; 0120152006 CLAMP
1	LIT; BULB, WHELEN H27SN12
2	1WL; BACKUP LIGHT
1	9LL; BUMPER POLE LIGHTS
1	BK; BLK LIQ ELEC TAPE
1	NBH; SERPENTINE BELT
3	NBH; V-BELT
1	NBH; V-BELT
1	FIL; NAPA HYDRAULIC FILTER
3	9OC; BULK TRANS SYN
5	4PC; GEAR OIL-SYN BULK (DELO)
2	MBI; REMAN GRIPPER KIT
12	9AP; BRAKE CLEAN
1	FIL; NAPAGOLD AIR FILTER
1	TWD; PURGE VALVE ASSY KIT
1	9AP; HORNBLASTER SOLENOID
1	9AP; HORNBLASTER SOLENOID
1	9IP; PSC0CDCR STRIP LIGHT STEADY WHITE
1	SVP; COMPRSOR
4	9XX; AC FREON 10174676
1	TEM; FILTER DRIER

CSHOP-2019-1676

Date Opened: 4-1-2019

Date Finished

4-23-2019

Meter 1 Reading:

125,012

TASKS PERFORMED

UL REPAIRS

Q PARTS

1	2DD; HOSE
1	5TN; GUAGE 2.5 0-600
1	8AM; PERMATEX THREAD LOCKER
2	9AP; ARM, LOCKING PINN RH
2	2DD; THERMOSTAT KIT

Asset Work Order History 10172453

CSHOP-2019-2399

Date Opened: 5-7-2019 Date Finished 5-10-2019 Meter 1 Reading: 123,400

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
COOLING SYSTEM

CSHOP-2019-2424

Comments: **SAFELITE WILL REPLACE 5-9-19 USED OUR GLASS FROM STOCK ORDERED NEW TO REPLACE IT 5-9-19**

Date Opened: 5-8-2019 Date Finished 6-12-2019 Meter 1 Reading: 0

TASKS PERFORMED

Q PARTS

WINDSHIELD

1 9AP; WINDSHIELD

VENDOR? SAFELITE FULLFILLMENT GLASS

Service Requests:

05/08/2019 WINDOW / 14: CRACKED / EXCHANGE - NEW
WINDOW/GLASS CRACKED OFFICER SIDE

CSHOP-2019-2447

Comments: **AT ST29**

Date Opened: 5-9-2019 Date Finished 5-10-2019 Meter 1 Reading: 123,400

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
SIREN

Service Requests:

05/09/2019 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / INSPECT
FEDERAL Q NOT WORKING ALL THE TIME

CSHOP-2019-249

Date Opened: 1-14-2019 Date Finished 1-14-2019 Meter 1 Reading: 122,824

TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR? DAN CALLAGHAN ENTERPRISES

Asset Work Order History 10172453

CSHOP-2019-2672

Comments: **SPARE LADDER AT TRAINING**

Date Opened: 5-24-2019 Date Finished 7-10-2019 Meter 1 Reading: 123,400

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
RADIO

Service Requests:

05/23/2019 RADIO / 49: CAN NOT DUPLICATE CONCERN / INSPECT
COMMUNICATION SYSTEM ON LADDER IS NOT WORKING PROPERLY. VOLUME CONTROL IS BROKEN

CSHOP-2019-3052

Date Opened: 6-12-2019 Date Finished 10-31-2019 Meter 1 Reading: 125,521

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS	1	9IP; WATERWAYRELIEFVALVE
WATERWAY AERIAL LADDER	1	5EF; RELIFE VALVE
COMPARTMENT LIGHT BODY	3	5EF; SWITCH DOOR PROXIMITY
CAB TILT PUMP	1	5EF; REGULATOR
ENGINE AND ACCESSORIES	1	5EF; REGULATOR
TRANSMISSION	2	9HC; TAPE
WINDOW REGULATOR	2	BK; SPRAYER
INTERIOR TRIM-MOLDINGS-UPHOLS	3	9XX; AC FREON 10174676
DASH CONTROLS	1	BK; PTEX ULTRA BLACK 30Z
HVAC SYSTEM	1	9IP; BEZEL AC
	1	2TK; BLOWER

CSHOP-2019-3978

Date Opened: 7-31-2019 Date Finished 5-2-2020 Meter 1 Reading: 129,158

TASKS PERFORMED

Q PARTS

TIRES & WHEELS	1	5EF; 3PC WHEEL STEEL 24X8 5 10 HOLE
----------------	---	-------------------------------------

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2019-4206

Date Opened: 8-11-2019 Date Finished 11-7-2019 Meter 1 Reading: 127,339

TRAN. OVER HEATING

TASKS PERFORMED

NO PARTS USED

OIL COOLER-HEAT EXCHANGER

Service Requests:

08/10/2019 TRANSMISSION / 27: OVERHEATED / INSPECT
WHILE ON A CALL GOT A HIGH TRANSMISSION TEMP WARNING.

Asset Work Order History 10172453

CSHOP-2019-4326

Comments: **SPARE LADDER AR ST35**

Date Opened: 8-16-2019 Date Finished 8-17-2019 Meter 1 Reading: 123,400

TASKS PERFORMED

NO PARTS USED

LIGHTING SYSTEM
AIR SYSTEM

Service Requests:

08/16/2019 LIGHTS / 18: LEAKING / REPAIR
OFFICER SIDE TELESCOPING SCENE LIGHT BURNT OUT.

08/16/2019 SERVICE REQUEST / 18: LEAKING / REPAIR
AIR LEAK FOUND UNDER THE CAB JUST BEHIND THE TRANSMISSION, BLUE AIRLINE, LEAKING AT COMPRESSION FITTING.

CSHOP-2019-4598

Date Opened: 8-28-2019 Date Finished 9-12-2019 Meter 1 Reading: 123,400

TASKS PERFORMED

Q PARTS

ELECTRICAL

1 1AD; 65 SERIES BATTERY

Service Requests:

08/28/2019 SERVICE REQUEST / 18: LEAKING / REPAIR
JOYSTICK ON TURN TABLE IS INTERMITTENT WHEN YOU TRY TO GO FROM FOG TO STRAIGHT STREAM ON THE STICK

CSHOP-2019-4639

Comments: **COOLANT HOSE**

Date Opened: 8-30-2019 Date Finished 9-30-2019 Meter 1 Reading: 123,400

TASKS PERFORMED

Q PARTS

COOLING SYSTEM

3 NBH; SIL SDI COOLANT HOSE

CSHOP-2019-4682

Date Opened: 9-4-2019 Date Finished 10-16-2019 Meter 1 Reading: 123,400

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
COOLING SYSTEM

1 5EF; FAN CLUTCH SER 10213616
1 2FL; RAD CAP 10LB

Service Requests:

08/31/2019 SERVICE REQUEST / 18: LEAKING / REPAIR
THE AERIAL MASTER STREAM NOZZLE WILL NOT TURN LEFT OR RIGHT, THE MOTOR LOCKED UP, UNABLE TO MOVE IT MANUALLY.

Asset Work Order History 10172453

CSHOP-2019-4881

Comments: **SPARE LADDER AT 35**

Date Opened: 9-16-2019

Date Finished 9-18-2019

Meter 1 Reading: 123,400

TASKS PERFORMED

Q PARTS

ELECTRICAL
EMERGENCY EQUIPMENT

1 2PR; STARTER SOLENOID EONE

Service Requests:

09/16/2019 SERVICE REQUEST / 18: LEAKING / REPAIR
AUTO EJECT DOES NOT WORK ON SHORELINE.

09/16/2019 SERVICE REQUEST / 18: LEAKING / REPAIR
FEDERAL Q SIREN WORKS INTERMITTENTLY

CSHOP-2019-5152

Comments: **AIR LEAK**

Date Opened: 9-30-2019

Date Finished 10-3-2019

Meter 1 Reading: 123,400

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

Service Requests:

09/30/2019 SERVICE REQUEST / 18: LEAKING / REPAIR
AIR LEAK IN THE DASH OF THE SPARE LADDER TRUCK.

CSHOP-2019-5159

Comments: **SPARE AT 35**

Date Opened: 10-1-2019

Date Finished 11-7-2019

Meter 1 Reading: 127,339

OUTRIGGERS LEAKING

TASKS PERFORMED

NO PARTS USED

OUTRIGGERS/STABILIZERS

Service Requests:

10/01/2019 HAZARD / 18: LEAKING / CLEAN
HAZARDOUS ISSUE RIGHT STABILIZER ARM LEAKING FL

CSHOP-2019-6109

Date Opened: 11-21-2019

Date Finished 12-19-2019

Meter 1 Reading: 127,392

BAD BATTERIES

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
EGRESS TIP AERIAL LADDER FLY
AERIAL LADDER EQUIPMENT
BATTERY

4 9HW; HINGES BLUM 1 3 8
1 5AB; MOTOR MONITOR CONTROL
1 5FF; ARM LOCKING RH
6 1AD; BATTERY GROUP 31

Asset Work Order History 10172453

CSHOP-2019-6328

Date Opened: 12-6-2019 Date Finished 12-6-2019 Meter 1 Reading: 123,400

TASKS PERFORMED

Q PARTS

REPAIR FROM PM - DECALS/CLEANLINESS

2 9PB; LARGE PLACARD
1 9PB; SMALL PLACARD

CSHOP-2019-6425

Comments: **SPARE LADDER AT 57**

Date Opened: 12-11-2019 Date Finished 1-31-2020 Meter 1 Reading: 129,101

TASKS PERFORMED

Q PARTS

COOLING SYSTEM
ELECTRICAL
CAB-INTERIOR ACCESSORIES

2 PAF; ANTIFRZ
1 5GI; SOCKET TRAILER

Service Requests:

12/11/2019 SERVICE REQUEST / 12: BROKEN / INSPECT
CAB LIFT RECEPTACLE PRONG BROKEN OFF INSIDE. UNABLE TO CONNECT CAB LIFT CONTROLLER AND CAN NOT LIFT CAB.

CSHOP-2019-6432

Date Opened: 12-11-2019 Date Finished 12-17-2019 Meter 1 Reading: 123,401

TASKS PERFORMED

NO PARTS USED

EMERGENCY EQUIPMENT

Service Requests:

12/11/2019 W/S WIPER / 18: LEAKING / REPAIR
WIPERS WONT TURN OFF HAVE TO PULL FUSE TO HAVE THEM STOP

CSHOP-2019-6469

Comments: **AIR LEAK**

Date Opened: 12-14-2019 Date Finished 12-15-2019 Meter 1 Reading: 123,401

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM

CSHOP-2019-647

Date Opened: 2-1-2019 Date Finished 2-14-2019 Meter 1 Reading: 123,377

TASKS PERFORMED

Q PARTS

WIPER BLADES

2 1AN; WIPER BLADE
1 2FL; SWITCH
1 NONSTOCK; FREIGHT CHARGE

Asset Work Order History 10172453

CSHOP-2019-6494

Date Opened: 12-16-2019 Date Finished 2-26-2020 Meter 1 Reading: 127,784

AIR LEAK

TASKS PERFORMED

Q PARTS

OUTRIGGERS/STABILIZERS	2	9HY; OUTRIGGER CYLINDER
AERIAL LADDER EQUIPMENT	1	5FF; PIN UPPER CYLINDER
TURNTABLE AERIAL LADDER	1	9AP; HAND SOAP PUM TOTAL TRK
REPAIR FROM PM - TILT CAB	12	1CH; BRAKE CLEANER MOPAR
REAR TIRES	2	9HY; LIFT CYLINDER
AIR SYSTEM	9	9HD; FITTINGS DOT AIR LINE
	1	2BE; AIR DRYER AD IS

CSHOP-2019-657

Date Opened: 2-2-2019 Date Finished 2-21-2019 Meter 1 Reading: 123,377

TASKS PERFORMED

Q PARTS

FIRE APPARATUS	1	9AP; DETAIL
AIR SYSTEM		
HVAC SYSTEM		

Service Requests:

02/02/2019 A/C / 18: LEAKING / REPAIR

CSHOP-2019-846

Date Opened: 2-12-2019 Date Finished 2-19-2019 Meter 1 Reading: 123,377

TASKS PERFORMED

NO PARTS USED

TIRE

CSHOP-2019-948

Comments: **SPARE AT ST47**

Date Opened: 2-19-2019 Date Finished 3-5-2019 Meter 1 Reading: 123,377

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM
EMERGENCY EQUIPMENT

Service Requests:

02/18/2019 SERVICE REQUEST / 18: LEAKING / REPAIR
JACK DOWN WARNING INDICATOR INTERMITTENTLY GOING ON AND OFF, JACKS ARE PROPERLY STOWED.

Asset Work Order History 10172453

CSHOP-2020-1021

Date Opened: 2-21-2020 Date Finished 3-12-2020 Meter 1 Reading: 129,158

TASKS PERFORMED

PM SERVICE C AERIAL

Q PARTS

1 FIL; NAPAGOLD OIL FILTER
1 FIL; NAPAGOLD FUEL FILTER
3 4PC; 15W40 PREMIUM BLUE OIL
1 FIL; WIX OIL FILTER

CSHOP-2020-1155

Date Opened: 2-27-2020 Date Finished 3-10-2020 Meter 1 Reading: 129,131

2 GAUGES ON DASH LIGHT ARE OUT

TASKS PERFORMED

REPAIR FROM PM - TURNTABLE CONTROLS
REPAIR FROM PM - FOAM SYS
REPAIR FROM PM - FIRE PUMP SYS
PARK-CLEARANCE LIGHTS
AUTO-EJECT
REPAIR FROM PM - REAR SUSPENSION
REPAIR FROM PM - ENGINE
REPAIR FROM PM - WINDSHIELD
SEAT FRONT
CAB FANS
CAB-INTERIOR ACCESSORIES
INSTRUMENT CLUSTER

Q PARTS

1 1WL; LIGHT 18 LED STRIP
1 9HY; REBUILD KIT FOAM VALVE
1 PTX; PERMATEX
1 9AP; SORBENT PAD
1 9HY; MAKO FITTINGS
1 9IP; SEAL
2 9EM; 9EM
-1 5AB; 5AB
1 5AB; 5AB
1 5AB; TRUNNION
1 5AB; 1 5 BALL KIT
1 5AB; 3 3 5 BALL KIT COMPOSITE
2 5AB; TRUNNION3INVLAVE
1 LIT; LED M C LAMP
1 6KU; 6KU
-1 6KU; AUTO EJECT W STD YEL CVR
1 6KU; AUTO EJECT W STD YEL CVR
20 4PC; GEAR OIL SYN BULK DELO
30 4PC; 15W40 PREMIUM BLUE OIL
1 1AN; WIPER BLADE
1 FIL; NAPAGOLD FUEL FILTER
2 FIL; NAPAGOLD OIL FILTER
2 1AN; WIPER BLADE
2 5SC; WIPER NOZZLE
2 MBI; DASH FAN
1 5FS; LIGHT INTERIOR WARNING

CSHOP-2020-1398

Comments: **DECIDED TO WAIT TO NEXT P/M TO REPLACE TOTAL SYST. REWIRE.**

Date Opened: 3-9-2020 Date Finished 4-8-2020 Meter 1 Reading: 129,158

TASKS PERFORMED

FIRE PUMP

Q PARTS

1 5HP; 5HP
1 5HP; 5HP
1 5CS; CAPTAIN GOV KIT
1 9IP; 9IP

Asset Work Order History 10172453

CSHOP-2020-1456

Date Opened: 3-12-2020 Date Finished 4-8-2020 Meter 1 Reading: 129,158

TASKS PERFORMED

NO PARTS USED

FIRE PUMP PLUMBING

Service Requests:

03/12/2020 SERVICE REQUEST / 12: BROKEN / REPAIR
TYPE PROBLEM INTO DESCRIPTION: WATERWAY DRAIN LINKAGE BROKEN BUT IT CAN BE OPEN AND CLOSED STILL BY HAND UNDER TRUCK.

CSHOP-2020-1462

Comments: **PART ORDERED FOR STOCK**

Date Opened: 3-12-2020 Date Finished 3-31-2020 Meter 1 Reading: 0

TASKS PERFORMED

Q PARTS

EGRESS TIP AERIAL LADDER FLY

1 9HD; PB FE ORDER

CSHOP-2020-1502

Date Opened: 3-15-2020 Date Finished 4-10-2020 Meter 1 Reading: 129,158

TASKS PERFORMED

Q PARTS

CRADLE AERIAL LADDER

1 5EF; 5EF
1 5EF; HANDLE PUSH PULL
1 5EF; 5EF
1 5EF; 5EF
1 5EF; 5EF

CSHOP-2020-1766

Comments: **SPARE LADDER AT ST35 WILL REPLACE DURING NEXT PM**

Date Opened: 3-31-2020 Date Finished 6-1-2020 Meter 1 Reading: 129,909

ALARM GOING OFF IN CAB

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
WATERWAY AERIAL LADDER
AERIAL LADDER EQUIPMENT
DOOR ALARM OR OTHER WARNING

1 5AB; 1 5 VALVE SUB ASS SS BALL
1 5FS; INTERCOM ATKINSON DYNAMICS
1 6WL; LIGHT CLR LED PUMP PNL
1 5PF; SWITCH DOOR DPST NC MOM
1 5EF; MICRO SWITCH PROXIMITY LADDER CRADLE

Service Requests:

03/28/2020 SERVICE REQUEST / 12: BROKEN / INSPECT
AERIAL SPEAKERS ARE NOT WORKING

Asset Work Order History 10172453

CSHOP-2020-1866

Comments: **SPARE LADDER AT 35**

Date Opened: 4-7-2020

Date Finished

4-21-2020

Meter 1 Reading:

129,158

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
CHARGING SYSTEM
AIR HORN

1 1AD; ALTERNATOR 320A
1 NTE; VAC PUMP OIL 32 OZ
1 SL; SL

Service Requests:

04/05/2020

ALARMS / 12: BROKEN / REPAIR
ALARM SIGNALS- AIR HORN NOT WORKING

CSHOP-2020-2407

Comments: **SPARE LADDER AT 47**

Date Opened: 5-6-2020

Date Finished

5-14-2020

Meter 1 Reading:

129,158

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM
DIAGNOSE ELECTRICAL
EMERGENCY EQUIPMENT

Service Requests:

05/05/2020

SERVICE REQUEST / 18: LEAKING / REPAIR
LOW VOLTAGE ALARM ON DRIVER DASHBOARD. SHOWING VOLT RANGE 13.1-13.5. LADDER IS LOCATED AT 47

CSHOP-2020-2585

Date Opened: 5-15-2020

Date Finished

5-21-2020

Meter 1 Reading:

129,158

TASKS PERFORMED

NO PARTS USED

HYDRAULIC SYSTEM

CSHOP-2020-353

Comments: **SPARE LADDER AT 57 CHECK FOR TREE HIT ON TIP OF LADDER**

Date Opened: 1-22-2020

Date Finished

2-26-2020

Meter 1 Reading:

129,101

TASKS PERFORMED

Q PARTS

LADDER INSPECTION
LIGHTING SYSTEM

1 5EF; LADDER TIP
1 8AM; 8AM
1 9IP; HALOGEN BULB 1000 WATT WPB

Service Requests:

01/20/2020

LIGHTS / 12: BROKEN / EXCHANGE - NEW
OFFICERS SIDE TELESCOPING LIGHT DOES NOT WORK, HAS BROKEN BULB.

Asset Work Order History 10172453

CSHOP-2020-404

Date Opened: 1-24-2020 Date Finished 1-24-2020 Meter 1 Reading: 128,911

TASKS PERFORMED

Q PARTS

SHORELINE CHARGER

1 6KU; AUTO EJECT W STD YEL CVR
1 6KU; AC2000 12V PLC TEN 8

Service Requests:

01/24/2020 SERVICE REQUEST / 12: BROKEN / REPAIRED
SHORELINE CONNECTION FOR LADDER 57 IS NOT WORKING AND LADDER IN UNABLE TO CHARGE

CSHOP-2020-4060

Date Opened: 8-7-2020 Date Finished 8-9-2020 Meter 1 Reading: 129,158

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM
AIR SYSTEM

CSHOP-2020-4073

Date Opened: 8-8-2020 Date Finished 8-8-2020 Meter 1 Reading: 129,158

TASKS PERFORMED

NO PARTS USED

FIRE APPARATUS

CSHOP-2020-4099

Date Opened: 8-9-2020 Date Finished 8-9-2020 Meter 1 Reading: 129,158

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM

CSHOP-2020-4183

Date Opened: 8-13-2020 Date Finished 9-6-2020 Meter 1 Reading: 129,500

TASKS PERFORMED

Q PARTS

AIR SYSTEM

8 8HD; PLUNGER FUEL

CSHOP-2020-4286

Date Opened: 8-19-2020 Date Finished 8-20-2020 Meter 1 Reading: 129,500

TASKS PERFORMED

NO PARTS USED

AERIAL EQUIPMENT PEDESTAL FIR

Service Requests:

08/18/2020 BODY / 12: BROKEN / INSPECT
THE RAILS ON THE TURNTABLE ARE BEND DOWN ON THE OFFICER SIDE OF THE TURNTABLE AND THE REAR RAIL IS BENT DOWN SLIGHTLY. JERRY AT THE SOUTH SHOP INSPECTED THE DAMAGE.

Asset Work Order History 10172453

CSHOP-2020-4327

Date Opened: 8-20-2020 Date Finished 9-29-2020 Meter 1 Reading: 129,550

UL REPAIR #5(C) AERIAL SPOTLIGHTS INOP.

TASKS PERFORMED

NO PARTS USED

HYDRAULIC CYLINDER EXTENSION
EGRESS TIP AERIAL LADDER FLY
AERIAL LADDER EQUIPMENT
SWIVEL AERIAL LADDER
INTERCOM SYSTEM - EMERGENCY V
MOTOR
SPOT LIGHTS

CSHOP-2020-4355

Date Opened: 8-21-2020 Date Finished 9-3-2020 Meter 1 Reading: 129,500

TASKS PERFORMED

NO PARTS USED

ELECTRICAL
AIR SYSTEM
EMERGENCY EQUIPMENT

CSHOP-2020-4511

Date Opened: 8-31-2020 Date Finished 9-23-2020 Meter 1 Reading: 129,550

TASKS PERFORMED

NO PARTS USED

DOOR ALARM OR OTHER WARNING

Service Requests:

08/30/2020 ENGINE / 49: CAN NOT DUPLICATE CONCERN / INSPECT
ENGINE

CSHOP-2020-4641

Date Opened: 9-6-2020 Date Finished 9-6-2020 Meter 1 Reading: 129,500

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM

CSHOP-2020-4670

Date Opened: 9-8-2020 Date Finished 9-18-2020 Meter 1 Reading: 129,500

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

Service Requests:

09/05/2020 TIRES / 18: LEAKING / EXCHANGE - NEW
BOTH FRONT TIRE WEARING ON THE OUTSIDE EDGE. PLEASE INSPECT AND CHANGE IF NEEDED. THANK YOU.

Asset Work Order History 10172453

CSHOP-2020-4827

Date Opened: 9-15-2020 Date Finished 9-22-2020 Meter 1 Reading: 129,500

TASKS PERFORMED

Q PARTS

COOLING SYSTEM
AIR SYSTEM

2 2DD; THERMOSTAT KIT

CSHOP-2020-4921

Date Opened: 9-19-2020 Date Finished 9-23-2020 Meter 1 Reading: 129,550

TASKS PERFORMED

NO PARTS USED

DOOR HANDLES INSIDE-OUTSIDE

CSHOP-2020-4959

Date Opened: 9-21-2020 Date Finished 11-24-2020 Meter 1 Reading: 134,226

NEED REAR BRAKES

TASKS PERFORMED

Q PARTS

WATERWAY AERIAL LADDER
FILTER
WIPERS-WASHER
REAR BRAKE PADS-SHOES

1 5EF; REBUID KIT SWIVEL
1 5EF; FILTER HYD SPIN ON
1 9IP; ETN 8907K645 SWITCH WIPER
2 2IH; SHOES MERRITOR
1 9HD; AMH 1 VALVE EXTENSION
2 NTL; AXL GSKT
2 9HD; BRAKE DRUM
20 5EF; WHEEL STUD REAR
1 9HD; BRUSH PAINT 1
2 TWD; RING LOCK WASHR
20 5EF; 5EF
1 2TP; BEARING
1 TWD; CUP
2 TWD; OIL SEAL

Service Requests:

09/21/2020 W/S WIPER / 12: BROKEN / EXCHANGE - NEW
WINDSHIELD WIPERS WILL NOT TURN OFF

CSHOP-2020-5042

Date Opened: 9-25-2020 Date Finished 10-22-2020 Meter 1 Reading: 129,550

TASKS PERFORMED

Q PARTS

EMERGENCY EQUIPMENT

-2 1AN; WIPER BLADE 24 IN
2 1AN; WIPER BLADE 24 IN
2 1AN; 1AN

Asset Work Order History 10172453

CSHOP-2020-5054

Date Opened: 9-28-2020 Date Finished 10-2-2020 Meter 1 Reading: 129,550

TASKS PERFORMED

NO PARTS USED

FIRE APPARATUS
AIR SYSTEM

Service Requests:

09/27/2020 ALARMS / 18: LEAKING / REPAIR
SPARE LADDER AT STATION 47 HAS LOW VOLTAGE ALARMS GOING OFF 12.2VOLTS

CSHOP-2020-5245

Date Opened: 10-6-2020 Date Finished 10-6-2020 Meter 1 Reading: 129,550

TASKS PERFORMED

NO PARTS USED

BODY EXTERIOR

Service Requests:

10/05/2020 ALARMS / 18: LEAKING / REPAIR
LOW VOLTAGE ALARMS ON DIGITAL COMPUTER BUT ANALOG GAUGE READS NORMAL. MECH TOMMY AWARE. WILL
HAVE TO ORDER NEW DASH COMPUTER.

CSHOP-2020-5411

Date Opened: 10-14-2020 Date Finished 10-14-2020 Meter 1 Reading: 129,550

TASKS PERFORMED

NO PARTS USED

FIRE APPARATUS

CSHOP-2020-5419

Date Opened: 10-14-2020 Date Finished 10-16-2020 Meter 1 Reading: 134,120

TASKS PERFORMED

Q PARTS

CAB TILT PUMP
HVAC SYSTEM

1 SVP; SVP

CSHOP-2020-6106

Date Opened: 11-20-2020 Date Finished 12-8-2020 Meter 1 Reading: 0

TASKS PERFORMED

Q PARTS

STEERING

12 CRC; BRAKLEEN 20OZ
1 5EF; POWER STEERING PUMP

CSHOP-2020-6250

Date Opened: 12-1-2020 Date Finished 12-1-2020 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

Asset Work Order History 10172453

CSHOP-2020-6273

Comments: **POSSIBLE COOLANT LEAK**

Date Opened: 12-2-2020 Date Finished 12-14-2020 Meter 1 Reading: 0

TASKS PERFORMED

Q PARTS

COOLING SYSTEM

2 2IH; 50 50 COOLANT FLEETGUARD
1 BK; RADIATOR CAP
1 2IH; TRANSYND

CSHOP-2020-6463

Date Opened: 12-10-2020 Date Finished 12-18-2020 Meter 1 Reading: 0

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
AUTO-EJECT

2 6KU; AUTO EJECT

Service Requests:

12/09/2020 SERVICE REQUEST / 12: BROKEN / REPAIR
THE SHORELINE PLUG IS NOT EJECTING. (AT STATION 15)

CSHOP-2020-6546

Date Opened: 12-16-2020 Date Finished 2-16-2021 Meter 1 Reading: 0

TASKS PERFORMED

Q PARTS

SMALL ENGINE REPAIR
FIRE FIGHTING EQUIPMENT
REPAIR FROM PM - DECALS/CLEANLINESS

1 5AB; NOZZLE MOTOR 12V ASM
1 FREIGHT
1 9HD; GRAPHICS TRUCK

Service Requests:

12/11/2020 SERVICE REQUEST / 12: BROKEN / REPAIR
SPARE LAD15 OIL LEAK COMING FROM BY FIRE PUMP, WATER LEVEL LIGHT INDICATOR NOT WORKING, SHORE LINE
AUTO INJECTOR NOT WORKING

12/15/2020 SERVICE REQUEST / 12: BROKEN / REPAIR
TYPE PROBLEM INTO DESCRIPTION

12/15/2020 ENGINE / 12: BROKEN / REPAIR
GENERATOR NOT WORKING

12/17/2020 SERVICE REQUEST / 12: BROKEN / OVERHAUL
MASTER STREAM WILL NOT GO INTO FOG PATTERN. ALSO, ON BOARD GENERATOR WILL START BUT NOT STAY ON.

Asset Work Order History 10172453

CSHOP-2020-6706

Date Opened: 12-23-2020 Date Finished 1-5-2021 Meter 1 Reading: 130,000

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER	4	NOL; NAPA QT 15W40 CJ4
SMALL ENGINE REPAIR	1	2IH; 2IH
COOLING SYSTEM	1	2IH; 50 50 COOLANT FLEETGUARD
AIR SYSTEM		

Service Requests:

12/23/2020 ENGINE / 12: BROKEN / REPAIR
ENGINE - GENERATOR DOES NOT START. THIS CONTROLS MAJORITY OF TRUCKS SCENE LIGHTING.

CSHOP-2020-6872

Comments: **FAN CLUTCH THAT WAS ON ORDER IS UNAVAILABLE, CURRENT UNIT WAS TAKEN APART, CLEANED AND REBUILT AND UNIT NOW OPERATING NORMAL**

Date Opened: 12-31-2020 Date Finished 6-11-2021 Meter 1 Reading: 134,883

TASKS PERFORMED

Q PARTS

EXHAUST MANIFOLD	1	FIL; NAPAGOLDAIRFILTER
REPAIR FROM PM - GENERATOR	-1	FIL; NAPAGOLD AIR FILTER
FAN CLUTCH	1	FIL; NAPAGOLD AIR FILTER
COOLING SYSTEM	2	2DD; THERMOSTAT KIT
DIAGNOSE ELECTRICAL	3	2FL; GASKET EXHAUST MANIFOLD
TRANSMISSION	1	BRG; ALTERNATOR BEARING
POWER STEERING PUMP	1	FREIGHT
	1	5EF; CURRENT SENSOR
	1	FREIGHT
	1	2DD; FILTER KIT TRANS SUMP 4
	1	BK; RADIATOR CAP

CSHOP-2021-2148

Date Opened: 4-21-2021 Date Finished 4-23-2021 Meter 1 Reading: 134,936

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS	1	9IP; HALOGEN BULB 1000 WATT WPB
QUARTZ LIGHT		
DOOR		
HVAC SYSTEM		

CSHOP-2021-2253

Date Opened: 4-26-2021 Date Finished 5-26-2021 Meter 1 Reading: 136,595

TASKS PERFORMED

NO PARTS USED

PM SERVICE C AERIAL

Asset Work Order History 10172453

CSHOP-2021-2265

Date Opened: 4-26-2021 Date Finished 4-28-2021 Meter 1 Reading: 134,936

TASKS PERFORMED

Q PARTS

COOLING SYSTEM
EMERGENCY EQUIPMENT

1 TWD; VELVAC

CSHOP-2021-2303

Date Opened: 4-27-2021 Date Finished 4-27-2021 Meter 1 Reading: 134,936

TASKS PERFORMED

Q PARTS

SIDE COMPARTMENT BODY

2 4AH; GAS SPRING 20 65 LB

Service Requests:

04/27/2021 SERVICE REQUEST / 17: INSUFFICIENT LUBRICANT / EXCHANGE - NEW
SPARE L47 NEEDS 2 HYDRAULIC DOOR STRUTS FOR COMPARTMENT L4. WE WILL GO TO SHOP 42 TODAY PER JOHN AT C-SHOP.

CSHOP-2021-2415

Comments: **SPARE LADDER AT 47**

Date Opened: 5-3-2021 Date Finished 5-4-2021 Meter 1 Reading: 134,936

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM
EMERGENCY EQUIPMENT

Service Requests:

04/30/2021 SERVICE REQUEST / 18: LEAKING / REPAIR
L47 SPARE. THE MASTER STREAM NOZZLE IS STUCK IN THE STRAIGHT STREAM POSITION, YOU CANNOT CYCLE THE NOZZLE TO A FOG

CSHOP-2021-2544

Date Opened: 5-7-2021 Date Finished 5-7-2021 Meter 1 Reading: 134,936

TASKS PERFORMED

Q PARTS

HVAC SYSTEM

8 9XX; 10177987 AC RECYCLER

Service Requests:

05/06/2021 A/C / 16: GLAZED / REPAIR
A/C ISSUE...SPARE LADDER AT 47 FRONT AC NOT WORKING. SHOP 42 FOUND ZERO FREON. NEED TO RETURN ON 5/7 TO CONTINUE REPAIRS.

Asset Work Order History 10172453

CSHOP-2021-2594

Comments: **CAN YOU CHECK THE REAR TIRES ON THIS WHEN YOU GOT THERE? THE TIRES WILL BE REPLACED TOMORROW. JUST WANT TO CONFIRM THEY ARE NOT NEEDED RIGHT AWAY.**

Date Opened: 5-11-2021 Date Finished 5-18-2021 Meter 1 Reading: 134,936

TASKS PERFORMED

Q PARTS

COOLING SYSTEM	1	FREIGHT
AIR SYSTEM	1	5EO; LEFT REAR WINDOW REGULATOR
CAB-INTERIOR ACCESSORIES		
INSTRUMENTS-GAUGES-METERS		

Service Requests:

05/08/2021 TIRES / 18: LEAKING / REPAIR
BAD TIRES, 5/8/21 OFFICER SIDE OUTSIDE REAR TIRE AND WHEEL WAS REPLACED, THE REMAINING REAR 3 TIRES
NEED TO BE REPLACED DUE TO WEAR

CSHOP-2021-2902

Date Opened: 5-26-2021 Date Finished 5-26-2021 Meter 1 Reading: 134,936

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

Asset Work Order History 10172453

CSHOP-2021-2908

Date Opened: 5-26-2021

Date Finished

7-7-2021

Meter 1 Reading:

136,595

TASKS PERFORMED

Q PARTS

WATERWAY AERIAL LADDER	2	NCB; CHK THRTL BDY CLNR BERRYMAN
HYD PUMP-PTO	8	4PC; 15W40 PREMIUM BLUE OIL
REPAIR FROM PM - GENERATOR	1	FIL; NAPAGOLD OIL FILTER
OIL	1	TEM; FILTER DRIER
SHORELINE CHARGER	1	FIL; NAPAGOLD FUEL FILTER
TRANSFER CASE	1	9HC; HOSE CUSTOM MAKO
OIL PAN-GASKET	2	FIL; NAPAGOLD OIL FILTER
TRANSMISSION	1	9OC; OIL DETROIT SERIES60 42 QTS2
REPAIR FROM PM - AERIAL	1	FIL; NAPAGOLD FUEL FILTER
STEERING	1	9AP; OIL SAMPLE TEST KIT PETRO CANADA
BRAKES	1	FIL; NAPAGOLD FUEL FILTER
COMPRESSOR	1	6KU; AC2000 12V PLC TEN 8
	1	5HP; BEARING COVER GASKET
	1	NOS; NAPA OIL SEAL
	1	PTX; PERMATEX
	3	2DD; KIT, INSERT
	3	2DD; 2DD
	1	2DD; FILTER KIT TRANS SUMP 4
	1	2DD; GASKET
	2	8HD; BRUSH PAINT 2
	2	UJS; UJOINT
	2	9AP; JOINT U
	1	TWD; PURGE VALVE ASSY KIT
	1	FIL; NAPAGOLD AIR FILTER
	1	NBH; V BELT
	1	TWD; TRINSWI
	1	TEM; NEW COMPRESSOR
	1	SVP; COMPRSOR
	1	BK; PAG 46 W UV DYE 8OZ
	1	TEM; FILTER DRIER

CSHOP-2021-3590

Comments: **CALLAGHAN TIRE INVOICE**

Date Opened: 6-29-2021

Date Finished

6-29-2021

Meter 1 Reading:

0

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2021-3612

Comments: **CALLAGHAN TIRE INVOICE**

Date Opened: 6-29-2021

Date Finished

6-29-2021

Meter 1 Reading:

0

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

Asset Work Order History 10172453

CSHOP-2021-4049

Comments: **DOOR ALARM**

Date Opened: 7-20-2021 Date Finished 7-20-2021 Meter 1 Reading: 136,780

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
DOOR ALARM OR OTHER WARNING

Service Requests:

07/19/2021 ALARMS / 49: CAN NOT DUPLICATE CONCERN / INSPECT
SPARE LADDER AT STATION 29 HAS OPEN DOOR ALARM SOUNDING. ALL DOORS WERE OPEN AND CLOSED AND
ALARM CONTINUED TO SOUND.

CSHOP-2021-4050

Comments: **DISCHARGE VALVE SPARE LADDER AT 29**

Date Opened: 7-20-2021 Date Finished 7-20-2021 Meter 1 Reading: 136,780

TASKS PERFORMED

NO PARTS USED

DISCHARGE GAUGE

Service Requests:

07/19/2021 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / INSPECT
DISCHARGE 3 WILL NOT CLOSE. IT IS LEAKING AND IS UNDER PRESSURE EVEN WITH THE HANDLE BEING FULLY
PUSHED IN.

CSHOP-2021-4115

Comments: **AC ISSUE**

Date Opened: 7-23-2021 Date Finished 7-26-2021 Meter 1 Reading: 137,040

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
HVAC SYSTEM

Service Requests:

07/22/2021 A/C / 15: FOREIGN MATERIAL / CLEAN
A/C ISSUE

CSHOP-2021-4123

Comments: **PUMP SHIFT FELL OFF**

Date Opened: 7-23-2021 Date Finished 7-23-2021 Meter 1 Reading: 136,984

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE PUMP CONTROLS

1 TWD; WILLIAM

Service Requests:

07/23/2021 SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW
ROAD TO PUMP TRANSFER SWITCH FELL OFF.

Asset Work Order History 10172453

CSHOP-2021-4225

Comments: **CALLAGHAN TIRE INVOICE**

Date Opened: 7-28-2021 Date Finished 7-28-2021 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2021-4283

Comments: **ON CALL REPAIR LOW POWER**

Date Opened: 7-31-2021 Date Finished 8-2-2021 Meter 1 Reading: 137,148

TASKS PERFORMED

NO PARTS USED

SWAP UNIT INTO SPARE

CSHOP-2021-4336

Date Opened: 8-3-2021 Date Finished 8-24-2021 Meter 1 Reading: 137,182

TASKS PERFORMED

Q PARTS

TURBOCHARGER

1 FITTING, TURBO
1 VPOD
4 STUD
4 2DD; NUT
2 2DD; ORING
1 2DD; GASKET
1 GASKET
1 TURBO

CSHOP-2021-4661

Date Opened: 8-17-2021 Date Finished 8-20-2021 Meter 1 Reading: 137,182

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
DIPSTICK AND TUBE
HVAC SYSTEM

1 9HC; BLOWER ASSY DBL W SEAL 12V
1 GRO; GRO
17 9XX; AC FREON 10199801
1 ECH; RELAY

CSHOP-2021-5798

Date Opened: 10-15-2021 Date Finished 10-16-2021 Meter 1 Reading: 137,182

TASKS PERFORMED

NO PARTS USED

BODY EXTERIOR

Asset Work Order History 10172453

CSHOP-2021-5819

Comments: **PTO**

Date Opened: 10-18-2021 Date Finished 10-19-2021 Meter 1 Reading: 137,182

TASKS PERFORMED

NO PARTS USED

DIAGNOSE ELECTRICAL

Service Requests:

10/16/2021 SERVICE REQUEST / 18: LEAKING / REPAIR
PTO IN CAB FOR AERIAL LADDER IS WORKING INTERMITTENTLY AND NOT ALLOWING PTO TO ENGAGE LADDER.
REAR DRIVER SIDE SIDE DOES NOT OPEN FROM OUTSIDE, ONLY INSIDE.

CSHOP-2021-5913

Comments: **HYDRAULIC LEAK AT ST47**

Date Opened: 10-21-2021 Date Finished 10-21-2021 Meter 1 Reading: 137,182

TASKS PERFORMED

NO PARTS USED

HYDRAULIC SYSTEM

CSHOP-2021-5980

Comments: **HYDRAULIC LEAK FROM LADDER ELECTRIC PUMP AREA**

Date Opened: 10-26-2021 Date Finished 11-19-2021 Meter 1 Reading: 137,575

TASKS PERFORMED

Q PARTS

AERIAL EQUIPMENT FIRE APPARATUS

1 8AM; POWERSEAL DC CONTACTOR 12V
1 5EF; PUMP EMERGENCY
1 FREIGHT
1 FREIGHT

CSHOP-2021-6042

Comments: **ANNUAL AERIAL UL TEST**

Date Opened: 10-28-2021 Date Finished 5-3-2022 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

UL AERIAL TESTING

VENDOR? DIVERSIFIED INSPECTIONS/ITL INC

CSHOP-2021-899

Comments: **10172453 HYDRO HOSES TO PUMP/TANK NEED TO BE REPLACED AND CHECK GENERATOR PER VASKO**

Date Opened: 2-16-2021 Date Finished 3-19-2021 Meter 1 Reading: 130,000

TASKS PERFORMED

Q PARTS

PRIMING PUMP FIRE PUMP

1 5HP; EPS PRIMER PUMP

Asset Work Order History 10172453

CSHOP-2022-1161

Date Opened: 2-28-2022 Date Finished 3-2-2022 Meter 1 Reading: 137,582

TASKS PERFORMED

NO PARTS USED

BODY EXTERIOR

CSHOP-2022-2521

Date Opened: 5-10-2022 Date Finished 5-24-2022 Meter 1 Reading: 137,675

TASKS PERFORMED

Q PARTS

FUEL SYSTEM
HVAC SYSTEM

1 FIL; NAPAGOLD FUEL FILTER
1 8HY; CUSTOM HOSES
1 8HY; FITTING
2 SVP; CNDSRFAN
-1 SVP; CNDSRFAN
2 1AD; OIL PAG W DYE
1 2RD; LIQUID LINE REFRIGERANT SOLENOID VALVE
1 TEM; NEW COMPRESSOR
1 FREIGHT
1 FREIGHT
1 6ZA; STRAP
1 9AP; A C CLUTCH CYCLE THERMOSTAT SWITCH
-1 6ZA; STRAP 25 44
1 6ZA; STRAP 25 44
1 8GR; COOLING FAN 12IN

CSHOP-2022-3048

Date Opened: 6-6-2022 Date Finished 6-7-2022 Meter 1 Reading: 137,675

TASKS PERFORMED

NO PARTS USED

STEERING WHEEL

-1 5SC; STEERING WHEEL 18
1 5SC; STEERING WHEEL 18

CSHOP-2022-3124

Comments: **PLEASE REPAIR: PUMP HEATER VALVE NT WORKING VALVE # 3 LEAKING FLOW METER AND PSI GAUGE NOT WORKING IN AERIAL**

Date Opened: 6-8-2022 Date Finished 6-9-2022 Meter 1 Reading: 137,675

TASKS PERFORMED

Q PARTS

FIRE PUMP
DISCHARGE GAUGE
INSTRUMENTS-GAUGES-METERS

1 FREIGHT
1 5SC; BUZZERALARM
1 BK; ATC FUSEHOLDER CARD
1 LMP; LAMP
1 GRO; SWITCH

Asset Work Order History 10172453

CSHOP-2022-3215

Date Opened: 6-13-2022 Date Finished 6-18-2022 Meter 1 Reading: 137,891

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS

24 1WL; CODE 3 MEGA THIN 12 LED
2 NHF; PREM AW 32 HYD FL 5G
1 FREIGHT

CSHOP-2022-3262

Comments: **L15 VOLTAGE ISSUE AND AUTO EJECT NOT EJECTING**

Date Opened: 6-14-2022 Date Finished 6-15-2022 Meter 1 Reading: 137,810

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
CHARGING SYSTEM
AUTO-EJECT
SIREN

1 6KU; AUTO EJECT

Service Requests:

06/13/2022 SERVICE REQUEST / 15: FOREIGN MATERIAL / REPAIR
KUSSMAUL AUTO EJECT CHARGES OK, BUT NOT EJECTING, I ACCIDENTALLY ENTERED THIS FOR OUR REGULAR L15 10203962 PLEASE CORRECT.

06/13/2022 SERVICE REQUEST / 12: BROKEN / REPAIR
POSSIBLY LOW VOLTAGE PROBLEM. NOTICING VOLTAGE RUNNING BETWEEN 12.5-13.5 ALSO NOTICING A BEEPING ALARM THAT I THINK IS FOR THE VOLTAGE. I ACCIDENTALLY ENTERED THIS FOR OUR REGULAR L15 UNDER 10203962 PLEASE CORRECT.

CSHOP-2022-3330

Date Opened: 6-18-2022 Date Finished 6-18-2022 Meter 1 Reading: 137,891

TASKS PERFORMED

NO PARTS USED

WIPER MOTOR

CSHOP-2022-3339

Date Opened: 6-20-2022 Date Finished 6-21-2022 Meter 1 Reading: 137,891

TASKS PERFORMED

NO PARTS USED

ELECTRICAL

Service Requests:

06/20/2022 SERVICE REQUEST / 38: SHORTED / INSPECT
TYPE PROBLEM INTO DESCRIPTION- MULTIPLE ALARMS AND OUT RIGGER ALARM GOING OFF WHILE OUTRIGGER IS TUCKED IN

Asset Work Order History 10172453

CSHOP-2022-3470

Comments: **ALARMS**

Date Opened: 6-27-2022

Date Finished

9-1-2022

Meter 1 Reading:

137,892

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FAULT CODE

Service Requests:

06/21/2022

ALARMS / 16: GLAZED / LUBRICATE

ALL ALARM SIGNALS STILL ACTIVATED THIS MORNING, EXERCISED AERIAL WITH NO CHANGE.

CSHOP-2022-3505

Comments: **LIGHTS**

Date Opened: 6-29-2022

Date Finished

7-8-2022

Meter 1 Reading:

137,892

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
BACK-UP ALARM

1 BK; BACK UP ALARM

Service Requests:

06/28/2022

SERVICE REQUEST / 12: BROKEN / REPAIR

REVERSE WARNING ALARM NOT WORKING ON SPARE LADDER

CSHOP-2022-3506

Comments: **ALARMS SPARE LADDER AT 15**

Date Opened: 6-29-2022

Date Finished

6-29-2022

Meter 1 Reading:

137,891

TASKS PERFORMED

NO PARTS USED

SIREN

Service Requests:

06/28/2022

SERVICE REQUEST / 12: BROKEN / REPAIR

FEDERAL Q NOT WORKING

06/28/2022

LIGHTS / 12: BROKEN / REPAIR

VEHICLE LIGHTS NOT WORKING- REAR SCENE FISH EYE LIGHTS NOT WORKING

CSHOP-2022-3562

Date Opened: 7-2-2022

Date Finished

7-2-2022

Meter 1 Reading:

137,891

TASKS PERFORMED

NO PARTS USED

TIRE

Service Requests:

07/02/2022

SERVICE REQUEST / 18: LEAKING / REPLACED TIRE

DRIVER SIDE OUTSIDE REAR TIRE HAD SLOW AIR LEAK

Asset Work Order History 10172453

CSHOP-2022-4682

Comments: **CALLAGHAN TIRE**

Date Opened: 8-31-2022

Date Finished

8-31-2022

Meter 1 Reading:

0

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2022-564

Comments: **SPARE LADDER MT HAND LIGHTS**

Date Opened: 1-31-2022

Date Finished

2-2-2022

Meter 1 Reading:

137,582

TASKS PERFORMED

NO PARTS USED

FAULT CODE
SPOT LIGHTS
HANDLIGHT
BATTERY
DOOR ALARM OR OTHER WARNING

CSHOP-2022-610

Date Opened: 2-2-2022

Date Finished

7-11-2022

Meter 1 Reading:

137,892

MAY NEED BATTERIES

TASKS PERFORMED

Q PARTS

BATTERY

2	1AD; 1000 CCA 31 SERIES BATTERY
4	1AD; 1000 CCA 31 SERIES BATTERY

Service Requests:

02/01/2022 SERVICE REQUEST / 20: LUBE/OIL SOAKED / LUBRICATE
LADDER APPEARS TO NEED SOME GREASE ON THE RAILS

02/01/2022 SERVICE REQUEST / 17: INSUFFICIENT LUBRICANT / LUBRICATE
AERIAL MAKING NOISES WHILE OPERATING. SENT STEVEN REINES A SHORT VIDEO (ATTEMPTED TO ATTACH BELOW

02/01/2022 SERVICE REQUEST / 11: BINDS/STICKS / ADJUST
AERIAL DEGREE LEVEL AT BASE STICKS AND DOSE NOT WORK WELL

02/01/2022 ALARMS / 38: SHORTED / EXCHANGE - NEW
ALARM SIGNALS- WHILE ACTIVATING EMERGENCY LIGHTS THERE IS A LOW VOLTAGE ALARM AND E-MASTER DIGITAL
SCREEN SHOWS 12.5V WHILE DASH SHOWS 14V. ALSO THE SCREEN ON THE E-MASTER DIGITAL SCREEN IS
DIFFICULT TO SEE AND FADING OUT.

CSHOP-2022-6343

Comments: **139472**

Date Opened: 12-6-2022

Date Finished

1-4-2023

Meter 1 Reading:

139,472

BOOM ANGLE BUBBLE INOP.

TASKS PERFORMED

Q PARTS

WATERWAY AERIAL LADDER
AERIAL LADDER EQUIPMENT

1	8GR; LUBRICANT GREASE
1	5EO; INCLINOMETER 120D
1	FREIGHT

Asset Work Order History 10172453

CSHOP-2022-824

Date Opened: 2-11-2022 Date Finished 2-12-2022 Meter 1 Reading: 137,582

TASKS PERFORMED

NO PARTS USED

FIRE APPARATUS

RADIO-2017-874

Date Opened: 12-27-2017 Date Finished 12-28-2017 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

RADIO

Service Requests:

12/23/2017 SERVICE REQUEST / /
SERVICE REQUEST FOR THE OFFICER HEAD SET. MICROPHONE DOES NOT READ, AND OFFICER UNABLE TO GIVE CLEAR COMMUNICATIONS. ERS 18035

RADIO-2018-349

Comments: REPLACING 3 FIRECOM HEADSETS ON SPARE LADDER PARTS REQUEST 3X UH-51 HEADSETS REPLACED ALL 3 HEADSETS. REMOVED THE BRAND NEW MIC XE500 HEADS BECAUSE THEY ALL HAVE OLD FIRMWARE. PUT THE ORIGINAL HEADS FROM THE UNITS WITH UPDATED FIRMWARE ON THE NEW CORDS AND TESTED THEM ON THE

Date Opened: 4-20-2018 Date Finished 4-20-2018 Meter 1 Reading: 0

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
MOBILE RELATED

3 9ES; HEADSET, WIRED, FIRECOM (CONTROL COMM)

Service Requests:

04/19/2018 RADIO / /
THE CREW AT ST 15 IS CURRENTLY IN THE SPARE LADDER AND THE HEADSETS FOR RADIO COMMUNICATIONS ARE FALLING APART LITERALLY. WE NEED THREE NEW HEAD SETS FOR THE TRUCK.

RADIO-2018-584

Comments: REMOVAL OF 10141616, INSTALL OF 10205557 INTO SL1 - 10172453

Date Opened: 6-4-2018 Date Finished 6-4-2018 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

MOBILE RELATED

Service Requests:

06/04/2018 RADIO / /
REMOVAL & INSTALL OF MOBILE RADIO INTO PBC SPARE LADDER 1

Asset Work Order History 10172453

RADIO-2019-159

Date Opened: 3-1-2019 Date Finished 3-4-2019 Meter 1 Reading: 0

TASKS PERFORMED

Q PARTS

RADIO

2 9ES; HEADSET MODULE SINGLE

Service Requests:

02/28/2019 RADIO / /
RADIO ISSUES.....SPARE LADDER TRUCK AT STATION 47 NEEDS (3) FIRECOM HEADSETS FOR THE FRONT CAB. HEADSETS DID NOT COME WITH THE LADDER DURING SWAP OUT. RANDY ALI WAS NOTIFIED 2/28 OF REQUEST. REQUEST HM-10 (2EA). 107-0407-10 REPLACED 3 FIRECOM HEADSETS.

RADIO-2020-1094

Date Opened: 12-28-2020 Date Finished 12-28-2020 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

INSTRUMENTS-GAUGES-METERS

Service Requests:

12/23/2020 RADIO / /
RADIO ISSUES- THESE ARE FIRECOM WIRED HEADSETS. DRIVER NOT ABLE TO HEAR HIMSELF AND FF HEADSET NOT ABLE TO HEAR HIM SPEAK AT ALL.

RADIO-2021-426

Comments: **CHECKED OUT OK**

Date Opened: 5-4-2021 Date Finished 5-4-2021 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

MOBILE RELATED

Service Requests:

05/03/2021 RADIO / /
RADIO ISSUES.....L47 OIC PORTABLE RADIO VOLUME KNOB ON MAIN UNIT IS INTERMITTENT WITH VOLUME ADJUSTMENTS. VOLUME DEFAULTS TO MINIMUM LEVELS AND UNABLE TO HEAR.

RADIO-2022-484

Comments: **REPLACED HM-10 JACK BOX.**

Date Opened: 6-30-2022 Date Finished 6-29-2022 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
INTERCOM SYSTEM - EMERGENCY V

Service Requests:

06/28/2022 RADIO / /
RADIO ISSUES- HEAD PHONE JACK FOR FF SEAT ON DRIVER SIDE IS NOT WORKING. HEADPHONES APPEAR TO WORK ON OTHER JACKS BUT NOT THE FF'S SEAT (SPARE L1 RUNNING AS L15)

Asset Work Order History 10172453

SSHOP-2019-434

Date Opened: 12-25-2019 Date Finished 12-27-2019 Meter 1 Reading: 123,401

TASKS PERFORMED

Q PARTS

FAN
ENGINE AND ACCESSORIES

1 5HO; FAN CLUTCH REPL 5SC 10049733
3 NBH; V-BELT

Service Requests:

12/25/2019 ENGINE / /
FAN BELT GOT BURNED OUT, AND POSSIBLE DAMAGE TO THE PULLEY.

SSHOP-2019-44

Date Opened: 2-19-2019 Date Finished 2-19-2019 Meter 1 Reading: 123,377

TASKS PERFORMED

NO PARTS USED

ENGINE COOLANT TEMPERATURE SE

SSHOP-2019-46

Date Opened: 2-19-2019 Date Finished 2-19-2019 Meter 1 Reading: 123,377

TASKS PERFORMED

NO PARTS USED

FIRE APPARATUS

SSHOP-2019-48

Date Opened: 2-19-2019 Date Finished 3-19-2019 Meter 1 Reading: 123,377

TASKS PERFORMED

Q PARTS

FIRE PUMP
DEF FLUID
WINDOW REGULATOR

8 NAF; BLUE DEF 2.5 GAL

SSHOP-2020-130

Date Opened: 4-28-2020 Date Finished 5-8-2020 Meter 1 Reading: 129,158

TASKS PERFORMED

Q PARTS

CHARGING SYSTEM
AIR SYSTEM

1 5HP; KIT VPS KPS PWR SHIFT AMP CNTRL
10 9IP; GEAR OIL SYN QT
1 5HP; 5HP
-10 9OC; DELO SYN GL5 GEAR OIL QTS
10 9OC; DELO SYN GL5 GEAR OIL QTS

SSHOP-2020-150

Date Opened: 5-22-2020 Date Finished 5-26-2020 Meter 1 Reading: 129,158

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

Asset Work Order History 10172453

SSHOP-2020-163

Date Opened: 5-26-2020 Date Finished 6-2-2020 Meter 1 Reading: 129,158

TASKS PERFORMED

Q PARTS

FIRE PUMP

1 PAF; ANTIFRZ

SSHOP-2020-172

Date Opened: 6-3-2020 Date Finished 7-22-2020 Meter 1 Reading: 129,158

TASKS PERFORMED

Q PARTS

OUTRIGGERS/STABILIZERS
DOOR PANEL
DOOR ALARM OR OTHER WARNING
HVAC SYSTEM

1 9AP; SENSOR HARSH DUTY
-4 9XX; 10177987 AC RECYCLER
4 9XX; 10177987 AC RECYCLER
4 9IP; FREON LB

SSHOP-2020-253

Date Opened: 7-28-2020 Date Finished 7-29-2020 Meter 1 Reading: 129,158

TASKS PERFORMED

NO PARTS USED

INTERCOM SYSTEM - EMERGENCY V

SSHOP-2020-280

Date Opened: 8-18-2020 Date Finished 8-27-2020 Meter 1 Reading: 129,500

TASKS PERFORMED

Q PARTS

TURNTABLE AERIAL LADDER

1 9EM; TURNTABLE RAILS PB IRON
3 DC; BLK CT

SSHOP-2020-303

Comments: **A/C AND FANS**

Date Opened: 9-2-2020 Date Finished 9-10-2020 Meter 1 Reading: 129,500

TASKS PERFORMED

Q PARTS

COMPRESSOR

2 MBI; DASH FAN

SSHOP-2020-317

Date Opened: 9-16-2020 Date Finished 9-18-2020 Meter 1 Reading: 129,500

TASKS PERFORMED

Q PARTS

THERMOSTAT

2 9IP; T3248 SIGHT GLASS
4 PAF; ANTIFRZ

Asset Work Order History 10172453

SSHOP-2021-173

Date Opened: 5-5-2021 Date Finished 5-21-2021 Meter 1 Reading: 134,936

TASKS PERFORMED

Q PARTS

AIR SYSTEM

1 TWD; BENDIX D 2 GOV
1 9HD; GAUGE MECHANICAL AIR PRESS
1 9HD; GAUGE MECHANICAL AIR PRESS

SSHOP-2021-194

Comments: **CALLED OUT FOR BURNING SMELL**

Date Opened: 5-20-2021 Date Finished 6-2-2021 Meter 1 Reading: 134,936

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
HYD PUMP-PTO
COMPRESSOR

SSHOP-2022-1046

Comments: **ANNUAL AERIAL UL TEST**

Date Opened: 12-6-2022 Date Finished 1-5-2023 Meter 1 Reading: 139,470

TASKS PERFORMED

NO PARTS USED

UL AERIAL TESTING

VENDOR? DIVERSIFIED INSPECTIONS/ITL INC
