

MAKO BREATHING AIR COMPRESSOR

Workorder: V011

In Date: 10/03/2005

Close Date: 10/14/2005

Meter Reading:

Problem?
am/fm radio inoperative I A 34

am/fm radio	inoperative L	A 34		
Task performed:			Parts	Quantity
			ALP1160941CIRCUIT BREAKER S/O	1
Workorder:	V012			
In Date: Close Date: Problem?	10/03/2005 10/14/2005	Meter Reading:		
	ot work LA34			
Task perform	ned:		Parts	Quantity
			NO PARTS USED	
Workorder:	V376			
In Date: Close Date: Problem?	10/31/2005 11/02/2005	Meter Reading:		
	ON, DOOR A	JAR LITE ON, (DRIVER F	REMOVED RELAY DURING STORM) AL-34	
Task perform	ned:		Parts	Quantity
			NO PARTS USED	
Workorder:	V323			
In Date: Close Date: Problem?	10/27/2005 11/07/2005	Meter Reading:		
	extreemely hard	d to start when cold		
Task perform	ned:		Parts	Quantity
			24353GLOW PLUG NS	4



MAKO BREATHING AIR COMPRESSOR

Workorder: V634

In Date: 11/18/2005 **Close Date:**

12/06/2005

Meter Reading:

Meter Reading:

Problem?

check all brakes- left rear worn extensively more than other wheels truck went 3,724 miles since brake job (airlight 34)

Task performed:	Parts	Quantity
	15016KIT15016 PIN KIT	2
	1654-8FERRULE .718	2
	3218K167ROTOR-BRAKE	2
	401581GASKET AXLE FL80 R002435	2
	R00781R01078 SWITCH ROM ROLL UP DOOR	1
	S2R7017173USE KIT15625PM BRAKE PAD	2
	380003ASEAL	2

Workorder: V1823

In Date: 03/13/2006

Close Date: 03/27/2006

Problem?

SIREN INOP, AL-34

Task performed: **Parts** Quantity NO PARTS USED



MAKO BREATHING AIR COMPRESSOR

Workorder: V2044

In Date: 03/30/2006 Close Date:

04/05/2006

Meter Reading:

61,984.00

Problem?

B INSPECTION, SEE ATTACHED SHEET, LA-34

Task performed:	Parts	Quantity
See B Inspection pre-printed form	102267016 RAD CAP 16LB SUPTHEN	1
	194BULB	10
	33472FUEL FILTER FOR DIESEL ENG LISTER	1
	6809880678STUD DZ	2
	6809940145CLIP	2
	751-1062051335 OIL FILTER	1
	A1712756000HOOD CABLE	2
	FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
	G3FUEL FILTER 33033	1
	H27SN12BULB	1
	HPH6349AOIL FILTER 51748	1
	PH8AOIL FILTER WIX 51515	1
	PR338324070 WIX FILTER WATER	1
	Q1500T3/CLLB-M15 240 V BULB	1
Vandar2: TCI	R90PFILTER FUEL 33231	1

Vendor?:

Workorder: V1163

In Date: 01/10/2006 Close Date:

04/06/2006

Problem?

door alarm stays on (Relay has been removed to silence alarm AIRLIGHT34

Meter Reading:

Task performed:	Parts	Quantity
	K040345BELT	1

Workorder: V2220

In Date: 04/13/2006 Meter Reading:

Close Date: 04/18/2006

Problem?

COMPRESSOR ENGINE CLUTCH BROKEN, LA-34

Task performed: **Parts** Quantity



MAKO BREATHING AIR COMPRESSOR

Workorder: V2377

04/25/2006 In Date: Close Date:

04/27/2006

Meter Reading:

Problem?

REPAIR CLUTCH FOR BREATHING AIR COMPRESSOR ENGINE

Task performed:			Parts	Quantity
			NO PARTS USED	
Vorkorder:	V2202			
n Date: Close Date: Problem?	04/11/2006 05/03/2006	Meter Reading:		
	t for breathing	air compressor (united cor	mpressor)	
Task perforr	ned:		Parts	Quantity
			AX78AX78 BELT	1
			FREIGHTSHIPPING CHARGES	1
			UMVS111611STRAP	1
			UMVS162511STRAP	2
Vorkorder:	V356			
In Date: Close Date: Problem?	10/31/2005 05/11/2006	Meter Reading:		
	TING ON AIR	HOSE BROKE AL-34		
Task perform	med:		Parts	Quantity
			NO PARTS USED	
Workorder:	V786			
In Date:	12/05/2005	Meter Reading:		

Close Date:

05/11/2006

Problem?

SIREN 10-7 LA34

Task performed: **Parts** Quantity



MAKO BREATHING AIR COMPRESSOR

Workorder: V2598

05/12/2006 In Date:

Close Date: 05/23/2006

Problem?

protivo girlight 24

Meter Reading:

a/c innoper	ative airiight 34	+		
Task perfori	med:		Parts	Quantity
			22-43249-0001513 SW PRES.A/C	1
			716907-0610A DRYER	1
			A22451940011499 SWITCH A/C HIGH PRESSURE NC	1
Workorder:	V3166			
In Date: Close Date: Problem?	06/27/2006 06/29/2006	Meter Reading:		
engine war	ning light on w	hen started truck this am. will be	at shop approx 10:30am AL 34	
Task perfori	med:		Parts	Quantity
			NO PARTS USED	
Workorder:	V3134			
In Date: Close Date: Problem?	06/25/2006 06/30/2006	Meter Reading:		
electical pig	g tail w/wrong r which pig tales)		n), missing 1 of same pig tales, also missing 4 other pig t	ales (sorry ha
Task perfori	med:		Parts	Quantity
			NO PARTS USED	
Workorder:	V3577			
In Date: Close Date: Problem?	07/21/2006 07/25/2006	Meter Reading:		
	side emergend	y light at end of bar is out LA 34		
Task perfori	med:		Parts	Quantity
-			02036141700GTURBO TUBE	



MAKO BREATHING AIR COMPRESSOR

Workorder: V3647

In Date: 07/26/2006 Close Date:

07/28/2006

Meter Reading:

Problem?

REPAIR DOOR OPEN CIRCUT, REAIR EXHAUST BRAKE AL 34

Task performed: **Parts** Quantity

6809881078DZ STUD

1

Workorder: V3209

06/28/2006 In Date: Meter Reading:

Close Date: 09/13/2006

Problem?

change out female recepticals on both electrical receptical boxes, 6 total AL 34

Task performed: **Parts** Quantity



MAKO BREATHING AIR COMPRESSOR

Workorder: V4034

In Date: 08/21/2006 Meter Reading:

Close Date: 09/15/2006

Problem?

B INSPECTION AND REPAIRS AS NEEDED A L 34

Task performed:	Parts	Quantity
	107796DRYER KIT AD9 -NEW	1
	1194GAUGE PRESSURE 0-160 PSI	1
	1654-8FERRULE .718	7
	3020030200 FUEL FILTER	1
	33472FUEL FILTER FOR DIESEL ENG LISTER	1
	366-07188366-07188 AIR FLT 42135	1
	4ZM08MINITURE REGULATOR	1
	52-24WIPER BLADES ANCO 24	2
	751-1062051335 OIL FILTER	1
	CA8193AIR FILTER 46744 WIX	1
	5005037KIT MAINT. AD-9	1
	9510BELT	1
	A0516003000CLUTCH-FAN BRACKET NEW # A05-16003-0(1
	FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
	FZ-K190-1MOTOR MOUNT RAM FAN GF165	1
	G3FUEL FILTER 33033	1
	HPH6349AOIL FILTER 51748	1
	K040345BELT	1
	K080680BELT SAME AS 3281981 CUMMINS	1
	PH8AOIL FILTER WIX 51515	1
	PR338324070 WIX FILTER WATER	1
	R90PFILTER FUEL 33231	1
	S2R7017173USE KIT15625PM BRAKE PAD	2
	S602CARD MALE CONN. 3/8 IN HOSE	3
	S638-1GAUGE AIR 1/4 FEM X 1/4 MALE	1
	S775COUPLER	3
	S777COUPLING NIPPLE	3
	S778COUPLING	2
	SWT54917SW ROCKER DPDT ON-ON RED	1

68,961.00



MAKO BREATHING AIR COMPRESSOR

Workorder: V4454

In Date: 09/14/2006 Close Date:

09/21/2006

Meter Reading:

Problem?

ABS LIGHT CAME ON AFTER LEAVING STA 28 IN LATE AFTERNOON

Task performed: **Parts** Quantity

1. TRAVELED TO STN 28 HOOKED UP LAP TOP FOUND INACTIVE CODES STORED. CLEAR CODES ROAD TEST UNIT RECHECK NO PROBLEMS FOUND

NO PARTS USED

Workorder: V4419

In Date: 09/13/2006 Meter Reading: 69,525.00

Close Date: 09/22/2006

Problem?

REPAIR EXHAUST SYSTEM RP30

Task performed: **Parts** Quantity 1. TRAVELED TO STN 34 TO INSTALL NEW EXHAUST 2 35103HANGAR EXHAUST SYSTEM HANGER. 35775CLAMP 5 IN 1

Workorder: V4418

09/13/2006 In Date: Meter Reading:

Close Date: 09/25/2006

Problem?

COMPARTMENT AJAR LIGHT ON CHECKED ALL COMPARTMENT S. D/O GREER PULLED RELAY AND LEFT IN CAB. LA34

Task performed: **Parts** Quantity

1. TRAVEL TO TRAINING SITE CHECK DOOR ADJAR

LT NPF AT THIS TIME

NO PARTS USED

35799FLAT CLAMP 4 IN

Workorder: V4349

In Date: 09/09/2006 Meter Reading:

Close Date: 09/26/2006

Problem?

ABS LIGHT CAME ON UPON RETURNING TO STA. 34 AL34

Task performed: **Parts** Quantity

1. anti lock It on code Ift rear sensor clear code road test NO PARTS USED



MAKO BREATHING AIR COMPRESSOR

Workorder: V4508

In Date: 09/19/2006 Meter Reading:

Close Date: 09/26/2006

Problem?

ANTI LOCK LIGHT ON AFTER 4 DAYS LA 34

Task performed: **Parts** Quantity

NO PARTS USED

1. TRAVELED TO STN 34 FOUND L REAR SENDER GROUNDED, SHORTED. OPEN, CHECK WIRES CLEAN PLUG ON COMPUTER AND SENDER NEEDS

NEW SENDER.

Workorder: V4644

In Date: 09/28/2006 Meter Reading:

Close Date: 10/05/2006

Problem?

master circuit breaker on westerbeke generator broke again. last time it was super glued, part order through granger a while back should be in stock. little plastic lever found but pin that goes between the two not foun LA34

Task performed: **Parts** Quantity

 TRAVELED TO STN 34. LEVER ON BREAKER FOUND BROKEN. REMOVE COVER R/R BREAKER.

APL11-6094-1CURCIT BREAKER AIR LIGHT TRUCK

V4195 Workorder:

In Date: 08/31/2006 Meter Reading: 52,927.00

Close Date: 10/10/2006

Problem?

replace lift pump on site south east power

Task performed: **Parts** Quantity

1. REPLACE LIFT PUMP ON SITE SOUTH EAST

POWER.

NO PARTS USED

Workorder: V4890

In Date: 10/13/2006 Meter Reading:

Close Date: 10/15/2006

Problem?

Articulating boom lights got stuck in the up possition this morning. We managed to get it down. LA34 will stop by the shop this morning, see ya then.

Task performed: Quantity **Parts**

1. Tested light tower could not duplicate problem. NO PARTS USED



MAKO BREATHING AIR COMPRESSOR

Workorder: V4737

In Date: 10/04/2006

Close Date: 10/25/2006

Problem?

FUEL SHUT OFF INOP, LA-34

Task performed: Parts Quantity

NO PARTS USED

70,106.00

72,256.00

1. REMOVE SHUT OFF LEVER, STRAIGHTEND AND THEN MODIFY TO MAKE STRONGER REINSTALL AND

Meter Reading:

Meter Reading:

RESET LINKAGE

Workorder: V5153

In Date: 10/30/2006

Close Date: 11/01/2006

Problem?

exhaust brake 10-7 la 34

Task performed: Parts Quantity

NO PARTS USED

1. TEST FLAPPER VALVE- AIR SOLINOID ECT. CHECK WIPING- FOUND WIRES TO DASH SWITCH PULLED OFF BACK OF SWITCH -REPAIR AND

REINSTALL DASH COVER.

Workorder: V5202

In Date: 11/01/2006 Meter Reading: 72,391.00

Close Date: 11/07/2006

Problem?

B INSPECTION AND REPAIRS NEEDED LA 34

Task performed:

- 1. "B" inspection
- 2.replace steering box
- 3. replace left rear wheel sencer
- 4. tighten strob bracket
- 5. TRAN SERVICE
- 6.replace marker bulb
- 7.replace strob bulb

Parts	Quantity
14-7014HGR-1 HELMET HOOK	2
23-12080-150BOLT BUMPER	2
380003ASEAL	1
401581GASKET AXLE FL80 R002435	1
500T3QCL500T3QCL BULB	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
G3FUEL FILTER 33033	1
HPH6349AOIL FILTER 51748	1
PH8AOIL FILTER WIX 51515	1
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1
RGTTAS65052ASTEERING GEAR BOX FRTLNR. ENG.	1
S4410325140R955342 SENSOR REAR ABS 4410328140	1
VML-S1414FILTER P/S	1



MAKO BREATHING AIR COMPRESSOR

Workorder: V5143

10/30/2006 In Date: Close Date:

11/14/2006

Meter Reading: 72,256.00

Problem?

ON CALL NO BRAKE LTS LA34

ON CALL N	IO BRAKE LTS	LA34		
Task perforn	ned:		Parts	Quantity
replace brake light switch			FSC17492134NC SW PARK BK SPADE TYPE CONNECTOR	2
Workorder:	V5331			
In Date: Close Date: Problem?	11/09/2006 11/14/2006	Meter Reading: 7	72,367.00	
CHECK AN	ID REPAIR A/C	CLUTCH LA34		
Task perforn	med:		Parts	Quantity
1. reshim a/c clutch			1004BULB	1
Workorder:	V4556			
In Date: Close Date: Problem? ABS light ca	09/22/2006 11/15/2006 ame on. LA34	Meter Reading:		
Task perforn	ned:		Parts	Quantity
	OF L/R WHEEL	4. PUT LAP TOP ON & SENCER, REPAIR ON "B	NO LAKTO GOLD	
Workorder:	V5405			
In Date: Close Date:	11/15/2006 11/20/2006	Meter Reading: 7	72,367.00	

Close Date: 11/20/2006

Problem?

CHECK ENG LT ON LA34

Task performed: **Parts** Quantity

1. CHECK ENGIN LIGHT ON NO PARTS USED



MAKO BREATHING AIR COMPRESSOR

Workorder: V5444

In Date: 11/18/2006 Close Date:

12/01/2006

Meter Reading:

4,002.20

Problem?

one areal boom light is out, and LA34 is missing one electrical extention cord box (there use to be 2 now there is 1).

Task performed:	Parts	Quantity
1. TRAVELED TO STN 34. LIGHT TOWER BULB OUT.	0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
REPLACED BULB.	02-0463748-50CORNER LED 4500 USE 01-263814-50	1
	194BULB	10
	322502BULB PATIENT GH22	1
	75907SWITCH - BATTERY -MASTER	1
	ESX120105112STARTER RELAY ESX-120-105112	1
	HLD374211 IN HOLD-OPEN 30LB	1
	HLD3999GSS1715UV 30LB STRUT GAS	1
	Q1500T3/CLLB-M15 240 V BULB	2

Workorder: **V5278**

In Date: 11/06/2006 12/04/2006 Close Date:

Meter Reading: 3,980.00

Problem?

roof mounted tower needs one bulb. bulb is 1500 watt appleton. truck may be at shop in am. AL34

Task performed:	Parts	Quantity
1. replace broken bulb	H6054USE CV TYPE SEALED BEAM	1
	Q1500T3/CLLB-M15 240 V BULB	1

Workorder: V5651

In Date: 12/02/2006 Close Date:

12/13/2006

Meter Reading:

Problem?

Check engine light came on. LA-34

Task performed:	Parts		
•			
4 Diameter Andrew and Harris and Alexander Build			

 Diagnose starting problem and check engine light. NO PARTS USED



MAKO BREATHING AIR COMPRESSOR

Workorder: V2786

05/29/2006 In Date: Close Date:

12/14/2006

Meter Reading:

Problem?

		comp leaking bad un cle asset number.	der pressure. may need to be rebuilt. sent this	to vehicle repair, system would n
Task performed:			Parts	Quantity
			NO PARTS USED	
Norkorder:	V3208			
In Date: Close Date: Problem?	06/28/2006 12/14/2006	Meter Reading:		
engine oil le	eakAL 34			
Task perforr	med:		Parts	Quantity
			NO PARTS USED	
Norkorder:	V5846			
In Date: Close Date: Problem?	12/18/2006 12/22/2006	Meter Reading:		
	E LIGHT LEN'S	MISSING LA 34		
Task perforr	med:		Parts	Quantity
1. Drive to sta	ation no problem	found.	NO PARTS USED	
Norkorder:	V5960			
In Date: Close Date: Problem?	12/26/2006 01/04/2007	Meter Reading:	4,093.50	
	VER WILL NOT	FULLY EXTEND TO	FULL HEIGHT .SCENE LIGHT ON LEFT FRO	NT NOT WORKING LA34
Task perforr	ned:		Parts	Quantity
Word order c	anceled by drive	er	NO DARTS LISED	



MAKO BREATHING AIR COMPRESSOR

Workorder: V6545

In Date: 01/31/2007

Close Date: 01/31/2007

Meter Reading:

77,482.00

Problem?

ON CALL AWNING WONT CLOSE LA34

Task performed: Parts Quantity

NO PARTS USED

Workorder: V6108

In Date: 01/04/2007 Meter Reading:

Close Date: 02/01/2007

Problem?

CANAPY ON TRUCK BLEW OFF, BRACKET NEEDS REPAIR-IN REAR OF TRUCK

Task performed: Parts Quantity

1. Check out canopy R001022CRANK ASSEMBLY

R00213MOUNTING KIT

1

1

Workorder: V6480

In Date: 01/26/2007 Meter Reading: 4,184.20

Close Date: 02/01/2007

Problem?

Halogen light on front driver side is out. Station 34 is out of Synthetic motor oil. LA34 will be at shop this morning to get awning

fixed.

Task performed: Parts Quantity

R&R awning brackets and side crank assy. Seal gap

between body and awning

NO PARTS USED

Workorder: V6623

In Date: 02/05/2007 Meter Reading: 77,747.00

Close Date: 02/12/2007

Problem?

Replace wipers LA34

Task performed: Parts Quantity

R&R wiper blades 31-24WIPER BLADES 2



MAKO BREATHING AIR COMPRESSOR

Workorder: V6697

In Date: 02/10/2007 Meter Reading:

Close Date: 02/21/2007

Problem?

backup camera 10-7. wire fell out of the bottom of the main unit. pins are bent slightly and plastic end of cable may be broke.

78,033.00

LA-34

Task performed: Parts Quantity

1. repair cable on camera NO PARTS USED

Workorder: V6900

In Date: 02/22/2007 Meter Reading:

Close Date: 03/07/2007

Problem?

MAP LIGHT BROKE AT BASE. NEEDS REPLACEMENT PLEASE. THANKS CIOFF. LA 34

Task performed: Parts Quantity

Remove dash. Remove map light. Drill hole for wires and install gromet. Splice wires and heat shrink. Install dash panals and parking brake knob.

87141USE LED MAP LIGHT 24""

1

Workorder: V6993

In Date: 02/28/2007 Meter Reading: 79,584.00

Close Date: 03/07/2007

Problem?

belts on breathing air compressor came off (al34)

Task performed: Parts Quantity

R&R belts on compressor AX78AX78 BELT 2

Workorder: V6970

In Date: 02/27/2007 Meter Reading: 4,260.70

Close Date: 03/14/2007

Problem?

BELT'S ON COMPRESSOR CAME OFF BROKE 3 BLADES Ia34

Task performed: Parts Quantity



MAKO BREATHING AIR COMPRESSOR

Workorder: V7329

In Date: 03/22/2007

Close Date: 03/26/2007

Meter Reading: 80,770.00

Problem?

repair portable halogen It la34

Task performed:	Parts	Quantity
Repaired halogen light	KR-1-2ACQUARTZ LIGHT	1

Workorder: V7468

In Date: 04/02/2007 Meter Reading: 81,432.00

Close Date: 04/10/2007

Problem?

b inspection and repairs as needed la34

Task po	erformed:
---------	-----------

- 1. B Inspection
- 2. B Inspection
- 3. R&R front brake pads
- 4. Passenger door mirror loose. Remove tighten and reinstall
- 5. R&R roof marker light
- 6. Coolent filter shut off stuck. Remove housing and rebuilt valve
- 7. Left door window track rusted away. R&R assembly
- 8. Check engine light on. Code 434. Diagnose problem
- 9. Diagnose check engine light. Test all wiring, connectors, and computer
- 10. R&R seat for repair
- 11. R&R 110v Quartz light
- 12. Panal light shorted found wire pinched and repaired

Parts	Quantity
33472FUEL FILTER FOR DIESEL ENG LISTER	1
366-07188366-07188 AIR FLT 42135	1
3818885O-RING WATER SHUT OFF	2
3937367GASKET 4942874	1
39437394940547 SHAFT SHUT-OFF VALVE	1
3943740SHAFT SHUT-OFF VALVE	1
39438574989614 SEAL O-RING SHUT-OFF VALVE	1
39444543977737 SCREW SHUTOFF VALVE	1
3VX400BELT	1
4025130FUEL PRESS SENSOR	1
500T3QCL500T3QCL BULB	1
6737200054673-720-00-54 SEAL WINDOW	2
6806870307A/C VENT DASH COVER 18-35571-000	1
6807200253GUIDE METAL	1
6808300074VENT A/C LH	1
6809870055SEAL CAB WINDOW	1
751-1062051335 OIL FILTER	1
A1834388003MOLD R/H	1
A33222T2308USE KIT195020 BRAKE PADS FL80	1
CA8193AIR FILTER 46744 WIX	1
EXO3AH00015SPLUG RAD. DRAIN	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
G3FUEL FILTER 33033	1
HPH6349AOIL FILTER 51748	1
PH8AOIL FILTER WIX 51515	1
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1



MAKO BREATHING AIR COMPRESSOR

Workorder: V7510

In Date: 04/03/2007

04/12/2007 Close Date:

Problem?

repair seat la 34 central auto trim

Task performed: Quantity **Parts**

81,432.00

Repair seat LA34 Central Auto Trim NO PARTS USED

Meter Reading:

Vendor?: CENTRAL AUTO TRIM

Workorder: V7382

In Date: 03/26/2007 81,041.00 Meter Reading:

04/18/2007 Close Date:

Problem?

replace front tires callaghan ent la34

Task performed: **Parts** Quantity

Replaced front tires LA34 Callaghan Ent NO PARTS USED

Vendor?: CALLAGHAN ENT

Workorder: V8097

In Date: 05/04/2007 82,259.00 Meter Reading:

Close Date: 05/15/2007

Problem?

three rear lenses need replacement (grote # 9020)

Task performed: **Parts** Quantity

Give to F.F. Green 3 134RLENS

Workorder: V8466

In Date: 05/29/2007 Meter Reading: 84,009.00

06/05/2007 Close Date:

Problem?

check engine It on la34

Task performed: **Parts** Quantity

1. Engine code - put lap top on & found 1 time - Clear &

monitor



MAKO BREATHING AIR COMPRESSOR

Workorder: V7743

In Date: 04/16/2007

06/19/2007 Close Date:

repair ecm cummins power south la34

Meter Reading:

Task performed: Quantity **Parts**

81,548.00

84,720.00

84,960.00

NO PARTS USED

Vendor?: POWER SOUTH

Workorder: V8864

In Date: 06/15/2007 Meter Reading:

06/29/2007 Close Date:

Problem?

Problem?

engine bucked several times AL34

Task performed: **Parts** Quantity

1. Engine bucks when driving/ road tested found inactive

eng speed sensor code/ replace speed sensor

4921597OUTBOARD SPEED SENSOR

1

Workorder: V8967

In Date: 06/22/2007 Meter Reading:

Close Date: 07/14/2007

Problem?

need straps for securing toll box AL34

Task performed: **Parts** Quantity

CYBS24268011CYBS-2426-80-11 STRAP

2

Workorder: V9269

In Date: 07/11/2007 Meter Reading: 85,791.00

Close Date: 07/18/2007

Problem?

check engine light came on AL34 (code 115)

Task performed:	Parts	Quantity
1. CHECKED OUT ENGINE LIGHT. FOUND CODE 115	3408430NXSENSOR SPEED USE 4921597	1
(ENGINE SPEED SENSOR). TROUBLE SHOT.	4025130FUEL PRESS SENSOR	1
ERASED CODE. TRUCK HAD TO LEAVE.	4921597OUTBOARD SPEED SENSOR	1
2. REPLACED BOTH ENGINE SPEED SENSORS.		



MAKO BREATHING AIR COMPRESSOR

Workorder: V9443

In Date: 07/19/2007

Close Date: 07/24/2007

Vendor?: POWER SOUTH

Problem?

check engine came back on (X1), runs fine. did not miss or pop like last week. la34

Meter Reading:

Task performed: **Parts** Quantity Chkd codes 121; code 3 counts; rem both sensors & NO PARTS USED chkd ok; reinstalled sensors; Ed E. said we will send truck Cummins Workorder: V9392 In Date: 07/18/2007 Meter Reading: 4,585.00 Close Date: 07/25/2007 Problem? MARKER LIGHT IS LOCATED ON THE UPPER LEFTSIDE FACING THE TAIL BOARD LA34 Task performed: **Parts** Quantity No problem found NO PARTS USED Workorder: V9509 In Date: 07/24/2007 Meter Reading: Close Date: 07/30/2007 **Problem?** LA34 DRIVER J.KEY STATES THE LIGHT TOWER IS STUCK IN THE UP POSITION. UNABLE TO BRING TOWER DOWN. Task performed: **Parts** Quantity Rem electric cover & rep connection on relay NO PARTS USED Workorder: V9583 In Date: 07/27/2007 Meter Reading: 86,625.00 **Close Date:** 08/10/2007 **Problem?** repair engine at cummins power south la 34 Task performed: **Parts** Quantity



MAKO BREATHING AIR COMPRESSOR

Workorder: V9908

In Date: 08/14/2007 Close Date:

08/28/2007

Meter Reading:

Meter Reading:

88,051.00

88,511.00

Problem?

whining noise coming from engine on deacceleration AL34

Task performed: **Parts** Quantity

test drive truck & no abnormal noise to be alarmed

now-will monitor

Problem?

NO PARTS USED

Workorder: V10149

In Date: 08/27/2007

Close Date: 09/12/2007

repair fan hub assembly la34

Parts Quantity Task performed:

1, Replace fan hub bearing assy-Levy 9510BELT 2. Assist with fan hub-Vasko

1 K080680BELT SAME AS 3281981 CUMMINS

Workorder: V10148

In Date: 08/27/2007 88,511.00 Meter Reading:

Close Date: 09/18/2007

Problem?

tow unit from turnpike and boynton to cs al34

Task performed: **Parts** Quantity

Tow unit from turnpike/Boy nto n to CS - Sisters Towing NO PARTS USED

Vendor?: SISTERS TOWING



MAKO BREATHING AIR COMPRESSOR

Workorder: V10263

09/05/2007 In Date: Close Date:

09/25/2007

Meter Reading:

88,996.30

Problem?

B INSPECTION AND REPAIRS AS NEEDED LA34 CRACK IN REAR ROTOR

Task performed:	Parts	Quantity
Task performed: 1. R/R L/R quarts light in body. 2. Install steel brackets in rear shelf. 3. B INSPECTION	3218K167ROTOR-BRAKE	2
	380003ASEAL	2
3. B INSPECTION	401581GASKET AXLE FL80 R002435	2
	500T3QCL500T3QCL BULB	1
	6256RJN6256RJN NUT-OUTER/RIGHT	1
	A-1779-WGREASE ROCKWELL A-1779-W-283	1
	CA8193AIR FILTER 46744 WIX	1
	FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
	G3FUEL FILTER 33033	1
	HPH6349AOIL FILTER 51748	1
	PH8AOIL FILTER WIX 51515	1
	PR338324070 WIX FILTER WATER	1
	R90PFILTER FUEL 33231	1
	S2R7017173USE KIT15625PM BRAKE PAD	2
	S4410325140R955342 SENSOR REAR ABS 4410328140	2

89,557.00

Workorder: V10578

In Date: 09/20/2007 Close Date:

09/27/2007

Problem?

caliper hanging up AL34

Task performed:

1. DRIVE TO STATION, LEFT REAR HANGING UP, DRIVING TO SHOP FOR REPAIRS.

Meter Reading:

2. R/R BOTH CANS, SLACKADJUSTERS, AND QUICK RELEASE VALVES- ADJUSTAND TEST DRIVE.

Parts	Quantity
MA15445NT3030 STD CHAMBER 30/30	2
R802462SLACK ADJ	1
R802463SLACK ADJUSTER	1
R802491SLACK ADJ.	1
S1144REG/FILTER	4



MAKO BREATHING AIR COMPRESSOR

Workorder: V10264

In Date: 09/05/2007 Close Date:

09/28/2007

Meter Reading:

88,996.00

89,828.00

Problem?

REPLACE REAR TIRES AT SHOP CALLAGHAN ENT LA34

Task performed: **Parts** Quantity

REPLACEMENT TIRES NO PARTS USED

Meter Reading:

Vendor?: CALLAGHAN TIRE

Workorder: V10657

In Date: 09/25/2007 Meter Reading:

Close Date: 10/02/2007

Problem?

check engine light on AL34

Task performed: **Parts** Quantity

1. INSTALL LAP-TOP TO LOCATE PROBLEM, HAD 1

HIT OF 268- WILL MONITOR

NO PARTS USED

Workorder: V10782

In Date: 10/02/2007

Close Date: 10/03/2007

Problem?

2 requests, driver seat slide acting up, wont slide at times and small light over fill station broke, appears to be a map light on a flexable cable. al34

Task performed: **Parts** Quantity

1. REPLACED LIGHT ASSEMBLY AT FILL STATION

COMPARTMENT

2. LUBED SEAT ADJUSTER MECHANISM

Workorder: V10794

In Date: 10/02/2007 Meter Reading: 4.738.00

Close Date: 10/04/2007

Problem?

2 problems, mech removed door ajar relay on 10/2/07, system 10-7. need light bulb in light tower, bulbs are 220 volts, top left bulk out if you are looking at the bulbs. thanks, cioff LA34

Task performed: Quantity **Parts**

1. TROUBLE SHOOT AND REPAIR DOOR ADJAR

LIGHT

2. TROUBLE SHOOT AND REPAIR DOOR ADJAR LIGHT, STAYING ON ALL THE TIME

5269LPVM-5 SM MOUNT

87141USE LED MAP LIGHT 24""

4

1



MAKO BREATHING AIR COMPRESSOR

Workorder: V11004

In Date: 10/13/2007

Close Date: 10/22/2007

Meter Reading: 4,770.00

Problem?

One of the electrical gang boxs is not working, also 1 bulb on light tower is still burned out since beginning of Oct. LA34

Task performed: Parts Quantity

1. replace bulb, check operation of tower Q1500T3/CLLB-M15 240 V BULB

2

Workorder: V11149

In Date: 10/20/2007 Meter Reading: 4,791.60

Close Date: 10/25/2007

Problem?

amber light on light tower out. LA-34

Task performed: Parts Quantity

1. diagnose amber light. found operator error. no NO PARTS USED

problem found.

Workorder: V11323

In Date: 10/30/2007 Meter Reading: 4,821.00

Close Date: 10/30/2007

Problem?

radiator fan guard is loose on compressor motor la34

Task performed: Parts Quantity

1. install tie wrap on shroud temp repair defer to pm NO PARTS USED

Workorder: V11325

In Date: 10/30/2007 Meter Reading: 4,821.00

Close Date: 10/30/2007

Problem?

clear lights on light bar dont work and headlights do not flash la34

Task performed: Parts Quantity

1. check unit driver did not have unit in gear with p brake

off npf



MAKO BREATHING AIR COMPRESSOR

Workorder: V11283

In Date: 10/27/2007 Close Date:

11/21/2007

Problem?

Meter Reading:

compartment ajar alarm sounding, turned on masterlight switch and compartment lights and it stopped.went in left rear and right re and then the ajar system no longer sounded Task performed: Quantity **Parts** Chkd unit; cld not make problem reoccur j NO PARTS USED Workorder: V11688 In Date: 11/20/2007 Meter Reading: **Close Date:** 11/28/2007 **Problem?** air leak in brake system, orange needle on guage loses 50-60psi over an 8-9hr period, truck is involved in a massive training excerise at the old shop over the next two weeks, when driving air stays up. la34 Task performed: Quantity **Parts** Air leak-several leaks @ air feed for seal; replc air NO PARTS USED couplers as needed Workorder: V11736 In Date: 11/24/2007 Meter Reading: Close Date: 11/30/2007 **Problem?** door open alarm LA34 Task performed: **Parts** Quantity Drive to Sta. Found senser bad, test OK. NO PARTS USED Workorder: V12092 In Date: 12/16/2007 Meter Reading: 4,943.00 Close Date: 12/18/2007

Problem?

front compartment door on pass side very hard to roll up or down. when up door is angled 3 inches side to side. on call mech enroute on 12-16 AL-34

Task performed: **Parts** Quantity

R-1 door inop; tensioner pin came apart; installed new

pins & reassembled



MAKO BREATHING AIR COMPRESSOR

Workorder: V12395

In Date: 01/07/2008 Close Date:

01/08/2008

Meter Reading:

95,296.00

Problem?

ON CALL FUEL LEAK LA34	
Task performed:	Parts Quantity
Fnd fuel in inj pump; cln/dry off; start/chk for leak; no leak fnd. j	NO PARTS USED
Workorder: V12439	
In Date: 01/08/2008 Meter Reading: 95, Close Date: 01/08/2008 Problem? repair fuel system cummins power south	673.00
Task performed:	Parts Quantity
Repair fuel system - Cummins Power j	NO PARTS USED
Vendor?: CUMMINS	
Workorder: V11689	
In Date: 11/20/2007 Meter Reading: Close Date: 01/15/2008 Problem?	
can a canvas cover be made with snaps to cover the eleusing air comp. during heavy rain at a training site. trying	ectrical generator? had to use a rain coat to cover while doors were oper g to protect it from shorting out. la34
Task performed:	Parts Quantity
	NO PARTS USED

In Date: 12/21/2007 Meter Reading: 4,950.00

Close Date: 01/16/2008

Problem?

air leak at air clutch on diesel engine for scba comp. air felt like it was coming from air gap on clutch when key powered on and diesel not running. AL-34

Task performed: **Parts** Quantity

Chkd air leak; fnd non; compressor clutch will be reuilt

son on schedule. j



MAKO BREATHING AIR COMPRESSOR

Workorder: V12191

In Date: 12/21/2007

Close Date: 01/16/2008

21/2007 Meter Reading:

95,000.00

Problem?

breathing air compressor clutch leaking air AL34

Task performed: Parts Quantity

Check out air leaks finally got chlutch to leak.

NO PARTS USED

Workorder: V13152

In Date: 02/09/2008 Meter Reading: 5,053.70

Close Date: 02/15/2008

Problem?

Gauge lights not working on siren controls and emergency light switches.LA 24

Task performed: Parts Quantity

repair Door latch for door alarm in rear of truck.

NO PARTS USED

Workorder: V13663

In Date: 03/03/2008 Meter Reading: 5,113.40

Close Date: 03/05/2008

Problem?

station 24 needs 15w-40 syn. oil, can la24 pickup on tuesday 3-4-08. thanks

Task performed: Parts Quantity

1. Parts only, no labor NO PARTS USED

Workorder: V14435

In Date: 04/13/2008 Meter Reading:

Close Date: 04/14/2008

Problem?

OIL FILTER BRACKET ON AIR COMPRESSOR ENGINE HAS BROKEN OFF, OIL FILTER IS HANGING BY HOSES. LA34

Task performed: Parts Quantity

1. REMOVE BROKEN FUEL FILTER BRAKET, WELD

GRIND, PAINT, REINSTALL.



MAKO BREATHING AIR COMPRESSOR

Workorder: V14227

In Date: 04/01/2008 Close Date:

04/18/2008

Meter Reading:

100,119.00

Problem?

replace front tires at shop la 34

Task performed: **Parts** Quantity

Replace front ties at shop LA34 - Callaghan NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V14652

In Date: 04/24/2008 5,267.00 Meter Reading:

05/09/2008 Close Date:

Problem?

compartment lights (2) L1 don't work (side wall of compartment, not scba panel). map light (left side) compartment L2 don't work. windshield washer no workie. thanks, Cioff L/A-24

Task performed:	Parts	Quantity
1. Drive to Stn34; replc bulbs; fix grnds on map light-ok;	1142BULB	10
bad grnd; test ok. Lehan	4020362171 GRO LAMP DOME 4 IN	2
Traced wiring for compt lights; fnd bad compt door	87141USE LED MAP LIGHT 24""	1
relay; R/R relay; replc map light & (2) other compt	A2254926000WASHER PUMP W/GROMMET	1
lights.	R134AFREON LB	3
2. Replc washer pump. Levy j		

Workorder: V14840

In Date: 05/03/2008 Meter Reading:

Close Date: 05/12/2008

Problem?

Left rear stop light out. LA24

Task performed: Quantity **Parts**

Checked lights - ok j NO PARTS USED

Workorder: V14906

In Date: 05/06/2008 Meter Reading:

Close Date: 05/21/2008

Problem?

LEFT HOSE REEL HOSE DAMAGED, NEEDS TO BE REPLACED. la24

Task performed: **Parts** Quantity

1. Remove hose, send to Mako NO PARTS USED



MAKO BREATHING AIR COMPRESSOR

Workorder: V15232

In Date: 05/21/2008 Close Date:

06/18/2008

Meter Reading:

53,334.00

Problem?

diesel motor on electrical generator has been smoking ALOT when running. Used 1/2 guart over two hrs yesterday. Can a oil additive (engine restorer) help. It does work. Thanks Cioff. la 34

Task performed: Quantity **Parts**

rings in engine 10-7. change oil to thicker grade.

problem still exists.

NO PARTS USED

Workorder: V15252

In Date: 05/21/2008 06/18/2008

Meter Reading:

103,155.00

Close Date: **Problem?**

B inspection and repairs as needed la24

Task performed:	Parts	Quantity
1. b inspection.	15W40BSYN OIL BULK QTS	24
1. b inspection.	33472FUEL FILTER FOR DIESEL ENG LISTER	1
	39428AIR FILTER WESTERBEKE	1
	FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
	G3FUEL FILTER 33033	1
	PH8AOIL FILTER WIX 51515	1
	PR338324070 WIX FILTER WATER	1
	R90PFILTER FUEL 33231	1
	RB6DRPRB6PRP RED ROTATING BEACON	1
	HPH6349AOIL FILTER 51748	1
	751-1062051335 OIL FILTER	1

Workorder: V15739

In Date: 06/13/2008

07/10/2008

Meter Reading:

Close Date: Problem?

> REAR ROLL UP DOOR SENSOR DOES NOT WORK TO SWITCH ON COMPARTMENT LIGHT OR DOOR OPEN ALARM FOR **BOTH REAR COMPARMENTS. AL 24**

таsк perтormed:		Quantity
Chk comp door switches, multiple switches seem bad; needs more diagnosis.	AX78AX78 BELT	2

2. Reinstall compressor belt; order new belt for unit Twin

3. Rem old belts; new Twin V belt too wide; install new V-belts; reorder new Twin V.



MAKO BREATHING AIR COMPRESSOR

Quantity

106,073.00

Parts

Workorder: V16406

In Date: 07/17/2008 Meter Reading:

Close Date: 07/21/2008

Problem?

Task performed:

make plate to cap off exhaust in r 1 comp la24

j	BUSI. NO PARTS USED	
Workorder: V16884		
In Date: 08/06/2008		
Problem? Give to scba shop. Pressure regulator extremely have recheck. Cioff A/L-24	ard to turn, just replaced with a rebulit unit two week	s ago. United needs to
Task performed:	Parts	Quantity
GAVE W/O TO REX, MYRON MADE REPAIR PRESSURE REGULATOR	TO NO PARTS USED	
Workorder: V16793		
In Date: 08/03/2008 Meter Reading: Close Date: 08/28/2008 Problem? Rain gutter over L1 (front top left side) hanging out	ut(loose). need oversized bolts to fix(tighten). thanks	Cijoff A/I -24
ram gatter ever 21 (nont top left side) hanging ed	integration, meet eversized bond to including include	OIOII7VE 24
Task performed:	Parts	Quantity
Rep rain gutter; isntalled new bolts.	NO PARTS USED	
Workorder: V17257		
In Date: 08/22/2008 Meter Reading: Close Date: 08/28/2008 Problem?		
There is a loose strip abouve the roll up doors on t	he driver side a few feet, the screws are stripped.AL	. 24
Task performed:	Parts	Quantity
Rem generator to send out for repair. j	NO PARTS USED	



MAKO BREATHING AIR COMPRESSOR

Workorder: V16179

In Date: 07/06/2008

Close Date: 09/02/2008

Meter Reading:

5,463.80

Problem?

LEFT/REAR YELLOW BEACON IS OUT. COMPARTMENT OPEN ALARM ON LR AND RR DOORS DOES NOT WORK. Ia 34

Task performed: 1. Assist generator removal.	Parts	Quantity 1 1 1 1
2. Rem clutch & shaft asy from air compressor & took shaft & new clutch to machine shop; installed hub/shaft asy & R/R belts.3. Rem wiring & hoses for gen removal; rem gen for re	807650FAN CLUTCH AIR AND LIGHT 87499RY48 RELAY PH8AOIL FILTER WIX 51515	
build; diss gen; fnd cyl hoses very bad; honed/cyl - NG; block done. 4. New gen eng arrived; rem gen from old eng; had to rem all internal wires to case; installed gen on new motor & wired; Installed gen in truck & installed oil filters; started gen; eng runs good; no electric al power; chk all poss issues with; could not find problem; called for a pro with generators. j		
Workorder: V17489		
In Date: 09/03/2008 Meter Reading: 108,80 Close Date: 09/29/2008 Problem? install generator la 34	00.00	
Task performed:	Parts	Quantity
	NO PARTS USED	
Workorder: V17433		
In Date: 09/01/2008 Meter Reading: 5,57 Close Date: 09/30/2008 Problem? 5,57	73.00	
yellow rear beacon and r/lower clearance light is out. L/A-2	24	
Task performed:	Parts	Quantity
Rep rear yellow rotator light; C/O R/R lower marker-ok; replc R/F air horn bracket. j	GRV1720244770R1 HORN SUPPORT BRKT	1



MAKO BREATHING AIR COMPRESSOR

Workorder: V18134

In Date: 10/06/2008 Close Date: 10/09/2008

Meter Reading:

Problem?

electrical gen quit last night on fire scene. mech called to scene. unit wont even crank. Carl tested and starter has dead short keep popping 20 amp reset breaker on side of unit, call me if needed 3735378 cioff LA24

popping 20	amp reset bre	aker on side of unit. call me if	needed 3735378 cioff LA24	
Task performed: 1. check out Gen no start, found bad starter on Gen, Gen out of service.			Parts	Quantity
		found bad starter on Gen,	NO PARTS USED	
(R.T.)				
Workorder:	V14154			
In Date: Close Date: Problem?	03/28/2008 10/17/2008	Meter Reading: 5,	197.00	
	ire wearing une	even and pulling to the right. la	1 34	
Task perfor	med:		Parts	Quantity
new tires ins	talled (4)		NO PARTS USED	
Workorder:	V14835			
In Date: Close Date: Problem?	05/02/2008 10/20/2008	Meter Reading:		
	warning buzze	r doesnt go off when all doors	are closed. pulled relay out of fuse box to shut down system	. LA24
Task perfor	med:		Parts	Quantity
			NO PARTS USED	



MAKO BREATHING AIR COMPRESSOR

Workorder: V18154

In Date: 10/06/2008 Meter Reading:

Close Date: 10/22/2008

111,078.00

Problem?

C INSPECTION AND REPAIRS AS NEEDED LA 24

Task performed: Parts Quantity



MAKO BREATHING AIR COMPRESSOR

1/10/2023

1. Road test + "C"	inspection, servi	ice generator	engine.
Service air compre	essor engine.		

- 2. Remove starter from on board Diesel generator.
- 3. Remove battery cables start testing of batteries as per "low voltage " Elec system performance test.
- 4. Bad battery fail load test- remove + reinstall (2) new batteries.
- 5. Compressor engine coolant.
- 6. Low voltage performance test.
- 7. Water filter housing (coolant) leaking-remove clean surface. Install new gasket + secure (T) to specs 18 ft. lbs. torque. coolant service.
- 8. Air dryer service.
- 9. Laptop had problem reading ECU. spent time (W) E. Erke/E. Orlando fixing problem. laptop working now.
- 10. Rear brake, rotor pad disassemble for replacement. Inspect, clean, +install new parts. Reassemble brake+adjust brake travel.
- 11. Front + rear sensor ABS fault-Diagnose fault, clean, inspect, check cabeling ohmes as per manual+adjust air
- 12. Install starter in generator + test run-(OK).
- 13. Front wheel hub + tire only-clean wheel_hub assembly.
- 14. Swap into on call truck, fuel + check stock.
- 15. Generator exhaust + air comporessor exhaust piping-cut ,disassemble.
- 16. Mud flap missing-cut=install new mud flap.
- 17. L-rear reflector missing. clean area = install new
- 18. Wind Shield wiper blades-install new wiper blades.
- 19. Dome light out-found blown bulb+corroded ground. clean ground connection+replace bulb.
- 20. Clean work areaa. Oil+dirt on floor. Check+start unit in yard for weekend on call.
- 21. L-2+L-3 light out-replace one bulb+found one wire chafed, spliced wire+reconnect.
- 22. Power steering system service.
- 23. Battery charge indicator inop-diagnose found ground connection corroded+green indicator bulb blown. Replaceed indicator assembly+clean ground connection
- 24. Bumper breakaway nut missing+bent -remove damaged bolts+install new ones.
- 25. Cables+wires hanging along frame rail-secure all wires+cables along frame rail.
- 26. Cutting+fitting exaust system piping.
- 27. Fabricate complete new exhaust system for Ger set.
- 28. Wrong caliper issued in manufactures box-remove caliper+reinstall correct one, also readjust slack adjuster 29. R&R A/C+engine belts.
- 30. Fast adapt transmission+road test.
- 31. Fast adapt transmission+road test.

032-0116549297 BATTERY INDICATOR	
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	
1156BULB	1
227871USE 800372 CK VALV	1
23-12080-150BOLT BUMPER	
800405PURGE VALVE KIT	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	2
HP-31DBATTERY 950CCA HP-31D	
R90PFILTER FUEL 33231	
15W40BSYN OIL BULK QTS	
33472FUEL FILTER FOR DIESEL ENG LISTER	
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	
G3FUEL FILTER 33033	
HPH6349AOIL FILTER 51748	
PH8AOIL FILTER WIX 51515	
PR338324070 WIX FILTER WATER	
284358GOVERNOR D-2	
3937367GASKET 4942874	
3218K167ROTOR-BRAKE	
380003ASEAL	
A13263M1157CALIPER ASSY ENGREAR L/H	
35103HANGAR EXHAUST	
401581GASKET AXLE FL80 R002435	
52-24WIPER BLADES ANCO 24	•
98003RREFLECTOR RED 40132 GROTE	
M2T50381STARTER	
751-1062051335 OIL FILTER	
9510BELT	
A23263M1157CALIPER ASSY ENG REAR R/H	
R802462SLACK ADJ	
R802463SLACK ADJUSTER	
B2420LP-SMUD FLAP 24 X 24	
DNEPG110286DNEPG110314 AIR CLEANER ASSY	
K080680BELT SAME AS 3281981 CUMMINS	
VML-S1414FILTER P/S	
VML-T1264GASKET P/S COVER	
VML-T1279WASHER P/S	
S2R7017173USE KIT15625PM BRAKE PAD	



FREIGHTLINER FL60 AIR AND LIGHT

Workorder: V18513

In Date: 10/22/2008 Close Date:

10/29/2008

Meter Reading:

Problem?

STARTER ON GENERATOR IS STAYING ENGAGED WHILE RUNNING. la 24

Task performed: 1. Dia why starter stays engaged when funning; diss remote start panel & changed relay on main start panel. 2. Assisted with above mentioned diagnostics.			Parts		
		NO PARTS USED			
Workorder:	V18718				
In Date: Close Date: Problem? coolant leal	10/30/2008 11/05/2008	Meter Reading:	111,4	80.00	
Task perforr	ned:			Parts	Quantity
valve, retrur	n on rad, low	ipper hose, T-state, ver hose on oil c oir; tighte; test ok.		NO PARTS USED	
Workorder:	V18941				
In Date: Close Date: Problem? compressor	11/08/2008 11/18/2008 auto run malfu	Meter Reading:	ŕ	ving difficulty starting, have to open a bank to start.	LA24
Task perforr	ned:			Parts	Quantity
C/O no problem with unitper driver 11/10/08 j		NO PARTS USED			
Workorder:	V18782				
•	11/01/2008 11/19/2008 enerator doesnt d works fine. LA	•	e if prehe	at is working, no power to glow plugs. had to pull fue	el sol. in to get starte
Task perforr	ned:			Parts	Quantity
C/O generato	or starting sys.	j			



MAKO BREATHING AIR COMPRESSOR

Workorder: V18997

11/11/2008 In Date: Close Date:

11/19/2008

Meter Reading:

Problem?

Task performed:

Vendor?: CALLAGHAN

Repair flat at Stn24 LA24 - Callaghan

light tower has one light out on passenger side on the t	50tt0111,EA24	
Task performed:	Parts	Quantity
 Quartz light out; fnd wrong voltage; bulb in asy; installed 1500 watt at 240 volts. L-rear rotator asy leaking; rem/install new rotator asy & rewire. warning lights out; blwon bulb; install new stroble bull 4. Grounding pro blem w/lights; locate fault on frame, cln & sec connection; replce blown bulbs. 		
Norkorder: V19064 In Date: 11/13/2008 Meter Reading: Close Date: 11/20/2008 Problem? upper rear beacon light out la24		
Task performed:	Parts	Quantity
Fnd grnd wire bad; rework; test ok. j	NO PARTS USED	
Workorder: V19187		
In Date: 11/19/2008 Meter Reading: 113 Close Date: 11/25/2008 Problem? repair volt meter on generator	3,085.00	
Task performed:	Parts	Quantity
Rep guages; ckt to be powered while unit on; replc voltage guage & chk charging sys. j	82862PVOLTAGE GAUGE USE EL38002	1
Norkorder: V19254		
In Date: 11/21/2008 Meter Reading: 113 Close Date: 12/09/2008 Problem? REPAIR FLAT AT STA 24 LA24	3,328.00	

Parts

NO PARTS USED

Quantity



MAKO BREATHING AIR COMPRESSOR

Workorder: V19255

In Date: 11/21/2008 Close Date:

12/09/2008

Meter Reading: 113,328.00

Problem?

REPLACE 3 REAR TIRES AT SHOP LA 24

Task performed: **Parts** Quantity

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V19391

In Date: 11/29/2008 Meter Reading: 113,939.00

Close Date: 12/10/2008

Problem?

The passenger side electrical hose reel chain fell off the track. AL-24

Task performed: **Parts** Quantity

1. Electric hose reel chain & shroud; rem brkn shroud & reinstall chain & adj tension, then secure.

NO PARTS USED

2. Light tripod ladders loose; rem/sec; reinstall. j

Workorder: V19549

In Date: 12/05/2008 Meter Reading:

Close Date: 12/10/2008

Problem?

please give to rex. guage above pressure pressure reg loose in hole. must have be taken loose to replace reg other day. united

forgot to tighten. LA-24

Task performed: **Parts** Quantity

GAVE WORK ORDER TO REX 12/05/2008. NO PARTS USED

Air regulator replaced and resecured by United

Compressor Inc.

Checked over by Myron Nash.

V19493 Workorder:

In Date: 12/03/2008 Meter Reading: 113,939.00

Close Date: 12/11/2008

Problem?

check brakes la 24

Task performed: **Parts** Quantity

Chk brakes sys; adjustment; Il sys within normal mfr. specs; no wear or damage; advise drive to keep monitoring brakes. j



MAKO BREATHING AIR COMPRESSOR

Workorder: V19644

In Date: 12/09/2008 Close Date:

12/12/2008

Meter Reading:

Problem?

ONE OF THE CABLES STOPPING THE HOOD FROM OPENING TOO FAR IS BROKEN. la 24

Task performed: **Parts** Quantity REPLACED BROKEN HOOD STRAP. 1 A1712756000HOOD CABLE

Workorder: V19808

In Date: 12/17/2008 Meter Reading: 5,824.00

Close Date: 12/17/2008

Problem?

Eddie, st 24 needs case of syn oil. used last 3 yesterday, thanks Cioff

Task performed: Quantity **Parts**

15W40QSYN OIL QT

12

Workorder: V19548

In Date: 12/05/2008 Meter Reading:

Close Date: 01/02/2009

Problem?

when light tower is fully extended up, it slowly leaks down in height over 30 mins, will not stay up. LA-24

Task performed:	Parts	Quantity
1. Light tower drops down on its own; intermittent control	01046301700S30HACP STROBE CLEAR	1
swtch problem; replcd swtch.	SWT54913SW ROCKER SPST ON-OFF RED	1

2. Gen wont start sometimes; weak fuel solenoid; replcd solenoid; adj shutdown. j

Workorder: V19898

In Date: 12/22/2008 Meter Reading: 115,157.00

01/02/2009 Close Date:

Problem?

refill radiator. j

ON CALL LA24 BELT CAME OFF

Task performed:	Parts	Quantity
drive to Stn24; chk veh; drive to C/S for fan belt; return	K040345BELT	1
to Stn24: R/R fan helt on eng that drives air compressor:		



MAKO BREATHING AIR COMPRESSOR

Workorder: V20271

In Date: 01/09/2009

Close Date: 01/12/2009

Meter Reading:

5,876.10

Problem?

valve handle "To Bank 4" is not turning properly. The handle feels like it is stripped. LA 24

Task performed: Parts Quantity

contacted Rex Taylor in scba for repair NO PARTS USED

Workorder: V19925

In Date: 12/23/2008 Meter Reading: 5,824.00

Close Date: 01/13/2009

Problem?

right front fender side marker light out . LA24

Task performed: Parts Quantity

Replcd RF & R-rear marker bulbs; replcd RF lens. j NO PARTS USED

Workorder: V18783

In Date: 11/01/2008

Close Date: 01/30/2009

Problem?

please give to rex or ed. Co needs to be calibrated on scba compressor.

Meter Reading:

Task performed: Parts Quantity

REPAIRED BY MAKO

NO PARTS USED

Workorder: V20394

In Date: 01/15/2009 Meter Reading: 116,548.80

Close Date: 02/12/2009

Problem?

repair eng on air compressor la 24

Task performed: Parts Quantity

1- Clean compressor air check and repaired fuil leaks.

NO PARTS USED



MAKO BREATHING AIR COMPRESSOR

Workorder: V20770

In Date: 02/01/2009 Close Date:

02/12/2009

Meter Reading:

Problem?

Task performed:

further repairs needed.

Replaced purification Filters (1503, and 1803). No

COMPRESSOR LOW OIL SWITCH KEEPS TRIGGERING EVEN THOUGH OIL LEVEL IS FULL. AL-24

Task performed: Quantity **Parts** 1- Work with Rex, replaced sender, test ok. NO PARTS USED Workorder: V20517 In Date: 01/22/2009 Meter Reading: Close Date: 02/18/2009 **Problem?** Alt belt on air comp diesel eng. replaced about three weeks ago. need to be adjusted, squells bad for five seconds on start up. **AL-24** Task performed: Quantity **Parts** Drive to Stn; rem fan cover around alt & adj belts; test; 1 366-07188366-07188 AIR FLT 42135 installed hsng; replc air filter on unit. Workorder: V21036 In Date: 02/10/2009 Meter Reading: Close Date: 02/20/2009 **Problem?** BACK-UP CAMERA HAS POWER BUT PICTURE IS BLANK. la24 Task performed: **Parts** Quantity Chk camera; NPF at this time. NO PARTS USED Workorder: \$3122 In Date: 02/24/2009 Meter Reading: Close Date: 02/24/2009 Problem? Replace filters on L/A-24 breathing air compressor.

Parts

NO PARTS USED

Quantity



MAKO BREATHING AIR COMPRESSOR

Workorder: V17959

In Date: 09/26/2008 Close Date:

03/02/2009

03/02/2009

Meter Reading:

110,190.00

Problem?

requesting 1 cs of oil for R24/E24/LA24... LA24 will pick-up @ shop on 9/26...

Task performed: Quantity **Parts** 12

15W40QSYN OIL QT

ALA00350-50 EXTENDED LIFE COOLANT GAL

Workorder: V18056

In Date: 10/01/2008

Meter Reading:

5,642.10

Close Date: Problem?

FOUND PUDDLE OF COOLANT UNDER TRUCK, PASSENGER SIDE OF ENGINE BLOCK WET. la24

Task performed: **Parts** Quantity 1 05-17223-000CAP RADIATOR 10 LB 1

Workorder: V18809

In Date: 11/03/2008 Meter Reading:

Close Date: 03/02/2009

Problem?

YELLOW BEACON ON TOP L/REAR IS OUT. LIGHT SPINS BUT BULB IS OUT. LA24

Task performed: **Parts** Quantity

NO PARTS USED

Workorder: V19013

In Date: 11/12/2008 Meter Reading:

Close Date: 03/02/2009

Problem?

R/SIDE FRONT RED HALOGEN FLASHER IS OUT. LA24

Task performed: **Parts** Quantity 1 H50SN12BULB

> J254HALOGEN BULB 1000 WATT WPB Q1500T3/CL-1BULB QUARTZ 120V RB6PAPRB6PAP ROTATING BEACON AMBER 1

S30HACSTROBE BULB **TURBO64STROBE TUBE**



MAKO BREATHING AIR COMPRESSOR

Workorder: V21118

In Date: 02/15/2009 Close Date:

03/12/2009

Meter Reading:

Problem?

L4 compartment lights dont come on when door is open, also when door is open door ajar not working on that door. LA24

Task performed: Quantity **Parts**

Fnd light inop; T-shoot bad door swtch; drilled/rem swtch asy; rem door truck/wres; T-shoot wiring & replcd swtch;

reassembled; ck opn; ck ok.

NO PARTS USED

Workorder: V21523

In Date: 03/04/2009 Meter Reading:

Close Date: 03/12/2009

Problem?

While truck in for b maintance, check for fuel leak on engine around accumulator.la 24

Task performed: **Parts** Quantity

Ck for fuel leak; clnd/dried eng; ran eng; cld not find fuel leaking; poss fuel left from previous fuel leak repair.



1/10/2023

Palm Beach County Fire Rescue **Fleet Maintenance Asset History** 10125552

MAKO BREATHING AIR COMPRESSOR

Workorder: V20580

In Date: 01/25/2009

03/16/2009 Close Date:

117.679.00 Meter Reading:

Problem?

B INSPECTION AND REPAIRS AS NEEDED LA 24

Task performed:

- 1. B-Inspection; R/R generator oil/filter; R/R air comp eng oil/filter.
- 2. Assist with B-Service Meenaghan
- 3. Ck for coolant leak; pressurize sys; fnd leaks; drained coolant; rem air comp lines; replcd rubber seal rings; reinstalled lines & all wires; rep steamer & top rod hose; filled sys; ck for leaks; ck ok.
- 4. Load test btry; rem all cables-load test; btry bad; reinstalled all cables for air comp repair; techs to finish their jobs; rem cables & holddown; R/R (2) btry; reinstalled all parts.
- 5. Fnd starter loose; rem starter; torqued nose cone; mount bolts; c Ind bell hsng adaptor/starter bolts; reinstalled starter; ck opn; ck ok.
- 6. Ck for P/S leak; clnd & dried box; rear truck; fnd slightly; ok to run.
- 7. Ck for oil leaks; fnd majority of leak is blow-by.
- 8. R/R wiper blades.
- 9. Rep rear tank rack in rear compt; grnd out; weld mount saddle to rack; drilled, tapped, counter sunk & mnted saddle to rack; ck ok. i

Parts	Quantity
15W40BSYN OIL BULK QTS	34
33472FUEL FILTER FOR DIESEL ENG LISTER	1
39428AIR FILTER WESTERBEKE	1
52-24WIPER BLADES ANCO 24	2
751-1062051335 OIL FILTER	1
91513AMBER LENS	2
CA8193AIR FILTER 46744 WIX	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
G3FUEL FILTER 33033	1
HPH6349AOIL FILTER 51748	1
PH8AOIL FILTER WIX 51515	1
PR338324070 WIX FILTER WATER	1
R00781R01078 SWITCH ROM ROLL UP DOOR	1
R90PFILTER FUEL 33231	1
S1003-A3103015 SEAL	4
HP-31DBATTERY 950CCA HP-31D	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	2

Workorder: V22146

In Date: 03/27/2009 Meter Reading: 120,856.00

Close Date: 04/01/2009

Problem?

drip rail on left side above compartments coming off LA34

Task performed: Quantity **Parts**

Rem worn out drip rail screws; cln/retap hoes; install new screws; sec with locktite.

NO PARTS USED

Workorder: V22247

In Date: 04/01/2009 Meter Reading:

Close Date: 04/16/2009

Problem?

on the scba compressor diesel motor, the starter motor sometimes only throws into the flywheel but does not spin. (heavy click) asts like a bad set of contacts(gear reduction starters)mainly acts up first time daily LA24

Task performed: Quantity

t-SHOOT STARTER PROB LEM; GET NUMBERS & ORDER PART. J

228000-1880STARTER AIR/LIGHT

1



MAKO BREATHING AIR COMPRESSOR

Workorder: V22470

04/11/2009 In Date:

04/23/2009 Close Date:

Problem?

Problem?

LA24

Task performed:

1. Installed starter relay to try & remedy start up clicking.

2. Replcd relay for fuel shut off solenoid.

Meter Reading:

ABS warning light is on la24		
Task performed:	Parts	Quantity
ABS lite coming on; reset ABS sensor - all wheels j	ok. NO PARTS USED	
Workorder: V22572		
In Date: 04/15/2009 Meter Reading: Close Date: 04/24/2009 Problem? replace wiper blades la 24	122,222.00	
Task performed:	Parts	Quantity
Replc wiper blades. j	52-24WIPER BLADES ANCO 24	2
Workorder: V22257		
In Date: 04/01/2009 Meter Reading: Close Date: 05/12/2009 Problem?	121,256.00	
breathing air compressor starter is intermittant LA3	34	
Task performed:	Parts	Quantity
	NO PARTS USED	
Workorder: V23166		
In Date: 05/08/2009 Meter Reading: Close Date: 05/27/2009		

HAVE TO ROTATE KEY FOR COMPRESSOR BACK AND FORTH TO MAKE STARTER ENGAGE. MAKES CLICKING NOISE.

Parts

NO PARTS USED

Quantity

6,111.20



1/10/2023

Palm Beach County Fire Rescue **Fleet Maintenance Asset History**

10125552

MAKO BREATHING AIR COMPRESSOR

Workorder: V23713

In Date: 06/01/2009

06/20/2009 Close Date:

Meter Reading:

125.036.00

Problem?

C INSPECTION AND REPAIRS AS NEEDED LA 24

Task performed:

Road test & C-Inspection

- 2. Complete C-Inspection including gen svc & compressor svc.
- 3. Dia gen hard start, fuel line restriction; rem section of hose & install new line.
- 4. Dia light tower light inop; fnd weak brkr; parts on
- 5. Tag light out; fnd blown bulb; rem/install new bulb.
- 6. R/rear brake light inop; rem asy; fnd bulb blown; install new bulb.
- 7. Dia compressor eng failure; fnd bad fuel solenoid; parts on order; for parts.
- 8. Replcd bad worn windshield wiperblade & all fluid rservoirs.
- 9. Fuel leak at pump asy; cln area; fnd loose fitting at fuel pump; secure/operate eng to normal temp; no leaks at this time.
- 10. Starter bolts loose; cln area/inspect/secure loose starter bolts.
- 11. Exh pipe msng support u-clamp; install replacement clamp & secure.
- 8. Cln up shop work are & eqmpt.
- 9. Compressor eng fuel skirt off solenoid; install correct hard start on compressor eng; operate en; all functions operating normal.
- 10. Light tower light inop; fnd loose grnd cable at control box; correct fault.
- 11. light tower will not stay extended; dia sys; fnd safety SW LS5 inop; not holding press; parts on order.
- 12. Light tower box cover screw holes worn out; retap & install new holddown screws.

Parts	Quantity
01046139100EBULB STOP/TAIL	1
15W40BSYN OIL BULK QTS	24
33472FUEL FILTER FOR DIESEL ENG LISTER	1
35799FLAT CLAMP 4 IN	1
366-07188366-07188 AIR FLT 42135	1
366-07197750-14310 SOLENOID FUEL SHUTOFF KIT	1
52-24WIPER BLADES ANCO 24	2
67BULB 12 VOLT	1
751-1062051335 OIL FILTER	1
CA8193AIR FILTER 46744 WIX	1
FREIGHTSHIPPING CHARGES	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
G3FUEL FILTER 33033	1
HPH6349AOIL FILTER 51748	1
PH8AOIL FILTER WIX 51515	1
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1

Workorder: V24352

In Date: 06/25/2009 Meter Reading: 126,066.00

Close Date: 06/30/2009

Problem?

door ajar warning stays on al24

Task performed: **Parts** Quantity

Ck connectors/connections; fnd switch not working on door; rep magnet in handle; ck opn; ck ok.



MAKO BREATHING AIR COMPRESSOR

Workorder: V23445

In Date: 05/21/2009 Close Date:

07/02/2009

124,262.00 Meter Reading:

Problem?

requesting 1 case of motor oil for st24's 3 trucks...LA24 will pick up from shop on 5/21/09...

Task performed: **Parts** Quantity

PARTS ONLY NO LABOR NO PARTS USED

Workorder: V25151

In Date: 07/29/2009 126,066.00 Meter Reading:

Close Date: 08/10/2009

Problem?

dead batt. at scba shop at HQ

Task performed: Quantity **Parts**

126,442.00

Go to HQ; get spare air night light working; help get

SCBA shop up/running.

NO PARTS USED

Workorder: V27342

In Date: 11/02/2009 Meter Reading:

Close Date: 11/02/2009

Problem?

charge out of part not done on earlier wo and was back when it was BAT 3 nb

Task performed: **Parts** Quantity

MC4059TRANS COOLER

1

Workorder: V27345

In Date: 11/02/2009 Meter Reading: 126,442.00

Close Date: 11/02/2009

Problem?

charge out of part not done on earlier wo and was back when it was BAT 3 nb

Task performed: **Parts** Quantity

757-14981STARTER RELAY



MAKO BREATHING AIR COMPRESSOR

Workorder: V27347

In Date: 11/02/2009 Close Date:

11/02/2009

Meter Reading: 126,442.00

Problem?

charge out of part not done on earlier wo and was back when it was BAT 3 nb

Task performed: **Parts** Quantity

901284SWITCH NUMATECK

1

Workorder: V23774

In Date: 06/03/2009

12/01/2009

Meter Reading:

6,240.00

Close Date: Problem?

> starter on air compressor diesel still acting up. had to on/off many times (over 20) to get motor started last night, starter only clicks when key is turned but lights on panel dim alot like heavy draw or bad connection la24

Task performed: Quantity **Parts**

1. Dia compressor starting problem.

2. Compressor failure to start problem; solenoid for fuel working intermittent; parts on order.

NO PARTS USED

Workorder: V29817

In Date: 02/08/2010 Close Date:

03/09/2010

Meter Reading:

126,442.00

Problem?

REPAIR WIRING TO CLUTCH

Task performed: **Parts** Quantity

NO PARTS USED

1. Mov harness to attach to solenoid.

2. T-shoot compressor eng-no start; fnd no power getting to shut off solenoid; after locating schematic, fnd wires incorrectly installed on compressor.

3. Worked w/other tech on dia compressor; no power;

fnd loose wire.

Workorder: V30142

In Date: 02/22/2010 Meter Reading: 126,442.00

Close Date: 03/17/2010

Problem?

A/C 10-7 LA 24

Task performed: Quantity

1. A/C sys low on charge; leaked chk sys; no signs of leakage anywhere; held vac; charged/ran sys; all ok.

2. Coolant hose leaking; drained coolant; replcd hose/clamps; test sys for leaks; all ok. j

05-22029-001UPPER RAD HOSE M2



MAKO BREATHING AIR COMPRESSOR

Workorder: V29907

In Date: 02/11/2010

Close Date: 03/18/2010

Meter Reading: 126

126,442.00

Problem?

A INSPECTION AND REPAIRS AS NEEDED

Task perform	med:		Parts	Quantity
A-Inspection	j		NO PARTS USED	
Workorder:	V30000			
In Date: Close Date: Problem? battery dea	02/16/2010 03/18/2010	Meter Reading:	126,442.00	
Task perfori	med:		Parts	Quantity
Jump start ve	eh & charge btr	/s. j	NO PARTS USED	
Workorder:	V30179			
In Date: Close Date: Problem?	02/23/2010 03/18/2010	Meter Reading:	127,416.00	
Door adjar	lt on la 24			
Task perfori	med:		Parts	Quantity
Chkd door aj	ar ckt. j		NO PARTS USED	
Workorder:	V24163			
In Date: Close Date: Problem?	06/17/2009 03/22/2010	Meter Reading:	125,538.00	
repair air le	eak in tower la24	1		
Task perfori	med:		Parts	Quantity

15W40QSYN OIL QT

516TIRE INFLATOR

38

1



MAKO BREATHING AIR COMPRESSOR

Workorder: V30227

In Date: 02/25/2010

Close Date: 03/22/2010

C/O coolant leak; get new clamp. j

Meter Reading: 127,

127,416.00

Problem?

ABS LIGHT CAME ON. BRAKES FEEL NORMAL. la24

Task performed: 1. Chk ABS codes; fnd L/rear sensor frequency herased inactive code & test drive (ok). 2. replcd drivers air bag for seat. 3. Chk problem w/door ajar lite; NPF at this time compt light & alarm inop; to be rep later per Mike Id. Travel to HQ; no problem w/door ajar at this time rear compt swtch & adj handle/latch tighten; road travel back to shop.	BOS622208400BOS6222084001 KIT ; L-2 replc	Quantity 1 AIR 1
Workorder: V30340 In Date: 03/01/2010 Close Date: 03/25/2010 Problem? Air leak in seat Alight Meter Reading:	127,710.00	
Task performed: Air seat leak - replc seat valve. j	Parts BOS62221360026222207-001 W AIF	Quantity R SEAT 1
Workorder: V30496 In Date: 03/05/2010 Close Date: 03/25/2010 Problem? coolant leak air light 24	128,192.00	
Task performed:	Parts	Quantity



MAKO BREATHING AIR COMPRESSOR

Workorder: V30531

In Date: 03/08/2010

04/02/2010 Close Date:

Problem?

rad leaking air light Sta24

Meter Reading: 128,192.00

Task performed:	Parts	Quantity
1. REM RADIATOR.	01-20152-004CLAMP	1
2. REPLC TRANS COOLER.	05-16062-004HOSE ELB	2
3. REM FAN. 4. INSTALL FAN CLUTCH.	05-16281-000HOSE ELB	1
5. INSTALL RADIATOR.	23-12201-200HOSE CLAMP	2
6. REPLC FRNT GRILL. 7. TIGHTEN ALL CLAMPS, REROUGHT HOSES. 8. INSTALL NEW BADIATOR HOSE TO CLAMPS	23-12201-225HOSE CLAMP	8
	354496FITTING	1
8. INSTALL NEW RADIATOR HOSE TO CLAMPS. 9. REPLACE FAN. J	473514139234FAN ASSBLY AIR LIGHT	1
O. INC. LANCE ITAL.	6808880023GRILLE FRTLNR. A17-14766-000	1
	A0516058001F10 RESCUE C RADIATOR	1
	HTS388SPRING HOSE CLAMP	1
	6809880678STUD DZ	1
	FREIGHTSHIPPING CHARGES	25

Workorder: V30907

In Date: 03/21/2010

Close Date: 04/09/2010

Problem?

radiator fluid found on bay floor in morning, looked underneath, found fluid. topped off radiator reserve. LA24

129,050.00

Task performed: Quantity **Parts**

Press tested cooling sys; fnd loose hose clamps; tightened all clamps; chkd compt repair on new truck; FF

swapped back into new truck. j

NO PARTS USED

Workorder: V28372

In Date: 12/15/2009 Meter Reading: 126,442.00

Close Date: 04/14/2010

Problem?

REPLACE TRANS COOLER OLD LA

Task performed: **Parts** Quantity

repaired on wo 30531 NO PARTS USED

Meter Reading:



MAKO BREATHING AIR COMPRESSOR

Workorder: V28847

In Date: 01/06/2010

Close Date: 04/22/2010

Meter Reading: 126,

126,442.00

Problem?

RESEAL ENG FOR COMPRESSOR

Task performed:		Parts	Quantity
Reseal eng for compressor Cummins	j	NO PARTS USED	
Vendor?: CUMMINS			

Workorder: S3971

In Date: 02/22/2010 Meter Reading:

Close Date: 05/04/2010

Problem?

SCBA DIESEL MOTOR HAS PROBLEM FIXED BEFORE. FUEL SOLINOID BOUNCES/SURGES. BOSCH RELAY INSTALLED INSTEAD OF TIMER LAST YEAR. RELAY WITH BUTTON ON THE SIDE HAS A PLASTIC TIE STRAP OVER THE BUTTON TO KEEP TRUCK IN SERVICE

Task performed: Parts Quantity

Check fuel solinoid & timer relay. Channel innovation rebuilt breathing air compressor and had to return and repair Bounce/Surge of fuel solinoin and timer relay. Repairs made and covered under Compressor rebuild. Unit now running properly.

NO PARTS USED

Workorder: V31919

In Date: 05/02/2010 Meter Reading: 129,428.00

Close Date: 06/04/2010

Problem?

Elbow to fill hose adaptor is boken. Two other fill hoses are still in service. A/L34

Task performed: Parts Quantity

Rep brkn air line in L-1 compt. j NO PARTS USED

Workorder: V31920

In Date: 05/02/2010 Meter Reading: 129,428.00

Close Date: 06/04/2010

Problem?

Shoulder on control valve on bottle fill whip broken. Needs new control valve. A/L34

Task performed: Parts Quantity

Installed new valve on whip hose. j NO PARTS USED



MAKO BREATHING AIR COMPRESSOR

Workorder: V32887

06/14/2010 In Date:

06/21/2010 Close Date:

Meter Reading:

129,428.00

129,428.00

Problem?

door alarm stays on (Old air/light)

Task performed:	Parts	Quantity
Start t-shoot compt open ckt; needed truck. j	091-84-022DIODE 6 AMP	2
	14-7014HGR-1 HELMET HOOK	1
	R00781R01078 SWITCH ROM ROLL UP DOOR	3
Workorder: V32939		

In Date: 06/16/2010

Close Date: 06/21/2010

Problem?

compressor wont run

Task performed:	Parts	Quantity
1. Rep comptlight ckt & assist John w/compressor repair.	4020362171 GRO LAMP DOME 4 IN	1
2. C/O compressor no start; C/O sys not getting signal frm door switch relay; chk wiring switches, etc; per Mike L. jump relay for now; Bill already looked at trkc &		
ordered parts. j		

Workorder: V32953

In Date: 06/16/2010 Meter Reading: 129,466.00

06/22/2010 **Close Date:**

Problem?

la24 tower light has one bulb out. the other three are working. la 24

Meter Reading:

Task performed:		Parts	Quantity
Parts only - no labor.	j	Q1500T3/CLLB-M15 240 V BULB	1

Workorder: V26774

In Date: 10/08/2009 126,442.00 Meter Reading:

Close Date: 07/13/2010

Problem?

tower light out LA24

Task performed:	Parts	Quantity
Verified job. j	Q1500T3/CLLB-M15 240 V BULB	1
Fnd light - rep. j		



MAKO BREATHING AIR COMPRESSOR

Workorder: V30034

In Date: 02/17/2010

Close Date: 07/13/2010

Meter Reading:

126,442.00

Problem?

SPARE L/A TRUCK AIR CONDITIONING IS BLOWING WARM AND IS MAKING A HIGH PITCH NOISE. LA24

Task perfo	rmed:			Parts	Quantity
Verified job.	. j			NO PARTS USED	
Workorder	: V33204				
In Date: Close Date: Problem?	06/28/2010 07/20/2010	Meter Reading:	129,42	8.00	
	n stays on (Old a	ir/light)			
Task perfo	rmed:			Parts	Quantity
not working to work on v 2. R/R defe move relay lite rep; rep 3. Rep air of door open s 4. Reassen	; had to rem all s weh. ective door switch hitting rollup door PVC storage tub compressor door sys/compt lites. nble/test opn of	s on veh; re compt L helves/storage tubes i ches; R/R defective of the L-1; cont door opn nes - not securedbolts msng; cont rep all compt lites; , doo ilt into door open sw	frm L-2 diodes; //compt o/dia of	R00011MAGNETS ROM DOORS	1
Workorder	: V33417				
In Date: Close Date: Problem? Spare Lig	07/08/2010 08/02/2010 ht and Air truck h	Meter Reading: as air leak and banks	129,70	7.00 eyond 5000 psi. Audible air leak can be heard.	Air light sta 34
Task perfo	rmed:			Parts	Quantity
Contacted F	Rocky at SCBA fo	or repair. j		NO PARTS USED	



MAKO BREATHING AIR COMPRESSOR

Workorder: V34855

In Date: 09/09/2010

Close Date: 09/27/2010

Meter Reading: 129,707.00

Problem?

reserve light and air truck has leaking blue air tank on compressor and banks are still leaking down.

Task performed: Parts Quantity

Contacted SCBA shop for repair. j NO PARTS USED

Workorder: V34892

In Date: 09/12/2010 Meter Reading: 129,707.00

Close Date: 09/27/2010

Problem?

reserve light and air vehicle has air leak and compressor cannot fill on board cascade bottles.

Task performed: Parts Quantity

Contacted SCBA shop for repair. j NO PARTS USED

Workorder: S4917

In Date: 08/15/2010 Meter Reading:

Close Date: 10/07/2010

Problem?

Replaced one fill whip knob on LA24 spare at staion 34. (#one fill hose)

Task performed: Parts Quantity

Replaced (1) stripped out valve knob. no further repairs

needed.



1/10/2023

Palm Beach County Fire Rescue **Fleet Maintenance Asset History** 10125552

MAKO BREATHING AIR COMPRESSOR

Workorder: V35234

In Date: 09/28/2010

10/15/2010 Close Date:

Meter Reading:

129,730.00

Problem?

C INSPECTION SPARE LT AND AIR

Task performed:	Parts	Quantit
1. c inspection	1046250300BULB	3
2. service differential	107796DRYER KIT AD9 -NEW	1
3. service air dryer	107800VALVE CHECK AD9	1
4. inspect for trans leak, non leak found added 1 quart		34
of oil	15W40BSYN OIL BULK QTS	1
5. night scan loose, tighten all mounting screws, checks	800405PURGE VALVE KIT	1
ok. 5. night scan will not telescope, inspected night scan	FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
and found air leak, repair air leak, test ok.	HPH6349AOIL FILTER 51748	1
7. check for inop strobe on night scan, check all fuses	PR338324070 WIX FILTER WATER	1
and relays 7 connections, everything checks good,r&r	R90PFILTER FUEL 33231	1
strobe becans , still has bad connection, seg defered.	VML-S1414FILTER P/S	1
8. 2 lights out on night scan, found loose connection,	VML-T1264GASKET P/S COVER	1
secure connection.	SPRGW2612WASHER NOZZLE W/RELIEF	2
9. r&r fuel caps and paint caps.		1
10. windshield washers inop, found clogged lines and	7605-666764-0023 SWITCH FOOT SIREN	1
cracked nozzles, replace lines and nozzles, tst ok.	EC6550ASTROBE LIGHT AMBER	
11. marker lamp inop, right front marker light ground	G3FUEL FILTER 33033	1
bad, clean and reinstall, tailboard marker inop, r&r bulb ,	PH8AOIL FILTER WIX 51515	1
all lights test ok. 12. lights in console switch inop, inspect, and found bad	SPR-W58-1TEE PLASTIC	1
switch, no parts instock		
13. service steering		
14. left rear brake light out, found bad bulb, r&r bulb,		
test ok.		
15. fuel pump damp, inspected and clean for leaks, no		
eaks found.		
16. compressor door loose, r&r bolts, test ok.		
17. abs light on, inspect and found air gap code, adjust		
sensor , test ok.		
18 air horn inon diagnose and found had foot switch		

Workorder: V35207

r&r foot switch, test ok.

In Date: 09/27/2010 Meter Reading: 129,707.00 Close Date: 10/18/2010

Problem?

WONT START LAAT 34

Quantity Task performed: **Parts**

1. jump start and load test batterys



MAKO BREATHING AIR COMPRESSOR

Workorder: V34522

In Date: 08/26/2010 Close Date:

10/20/2010

Meter Reading:

129,707,00

Problem?

wont start spare It air at 34

Task performed: **Parts** Quantity

Recharged btrys & tested. İ NO PARTS USED

Workorder: V35729

In Date: 10/18/2010 Meter Reading: 129,707.00

Close Date: 10/27/2010

Problem?

THERE ARE TWO LIGHTS IN THE LIGHT TOWER THAT ARE OUT. SAL24

Task performed: Quantity **Parts**

Night scan light - light out; rem blown bulbs (2) & install

new bulbs.

Q1500T3/CLLB-M15 240 V BULB

3

Workorder: V36414

11/13/2010 In Date: Meter Reading: 130,225.00

Close Date: 11/30/2010

Problem?

right rear brake light out. bulb is whelan design, looks like a 1157 with a short wire harness. AIRLIGHT 24

Task performed: **Parts** Quantity

(1) TRAVELED TO ST24 TO REPAIR RIGHT REAR BRAKE LIGHT ON THE AIR AND LIGHT TRUCK. FOUND BAD BULB. REPLACED WITH NEW ON. (2) A/C ALSO WASN'T COOLING VERY WELL.

CHECKED OUT SYSTEM AND ADDED SOME FREON. CHECKED FOR LEAK BUT NONE FOUND. COOLING

OK NOW. J.W.

01046139100EBULB STOP/TAIL

1

Workorder: V36569

In Date: 11/18/2010 Meter Reading: 130,635.00

Close Date: 12/22/2010

Problem?

repair fuel system la24 cumins power south

Task performed: **Parts** Quantity



MAKO BREATHING AIR COMPRESSOR

Workorder: V37007

In Date: 12/08/2010 01/07/2011 Close Date:

Meter Reading:

132,086.00

Problem?

check engine It on sla 24

Task performed: Quantity **Parts**

Replcd eng position sensors & cleared codes. i 4921597OUTBOARD SPEED SENSOR 3

1

V37424 Workorder:

In Date: 12/27/2010

Meter Reading: 01/10/2011

132,086.00

Close Date: Problem?

COOLANT LEAK SLAAT 34

Task performed: Quantity **Parts**

1. Replc radiator - leaking.

2. Fab new hood spring mnt for radiator - previously cut off.

- 3. Rewired rad fan connector brkn.
- 4. installed new left side fender well mnts in hood stripped.
- 5. Extensive road test; chkd ovr rad for leaks; no leaks at this time. i
- 6. Travel to Stn34; chk cooling sys; fnd rad leaking on bommom tank; tried to tightene up tank - no luck; send to shop.

A0516058000RADIATOR B SERIES

Workorder: V38812

In Date: 02/28/2011 Meter Reading: 133,130.00

Close Date: 03/03/2011

Problem?

CHECK ENGINE LT ON

Task performed: Quantity **Parts**

C/O code; fnd codes for both eng pos sensors; replc both sensors, erased codes; went for extensive road

test; rechkd codes, fnd none.



MAKO BREATHING AIR COMPRESSOR

Workorder: V38013

In Date: 01/24/2011

Close Date: 03/08/2011

Meter Reading: 13

132,086.00

Problem?

shelf in passenger side rear compartment broke/bent so34

Task performed: Parts Quantity

Rep brkn shelf in rear side compt. j

Workorder: V39157

In Date: 03/14/2011 Meter Reading: 133,130.00

Close Date: 03/22/2011 Problem?

A inspection

Task performed: Parts Quantity

Completed on W.O. 39145 j NO PARTS USED

Workorder: V39145

In Date: 03/14/2011 Meter Reading: 133,367.00

Close Date: 03/29/2011

Problem?A inspection

Task performed: Parts Quantity

52-24WIPER BLADES ANCO 24

2

A-Inspection & road test.

- 2. Center rear marker 10-7; fnd bad grnd connection; correct fault. R/frnt marker 10-7; blown bulb; install new bulb.
- 3. Heater hose shaffing; reroute & install protective rubber sleeve on hose.
- 4. Windshield wiperblade damaged; rem & install new wiper blade. j



MAKO BREATHING AIR COMPRESSOR

Workorder: V41137

In Date: 06/06/2011 Close Date:

06/07/2011

Meter Reading:

133,872.00

Problem?

(L2) ROLL-UP DOOR IS JAMMED, WILL NOT ROLL UP. THIS IS FOR ACCESS TO THE FILL-STATION. Sta 24.

Task perfor	med:	Parts	Quantity
 Chkd L-2 compt door stuck shut; pried door open; Secured side rail screws; lube/adj door/slides. Mntd eqmpt in R-3 compt; (fire exts, cooler, air pack). Freed up jammed docking stn. j 		FHLP-6TANK CLIP KD-UN-5-SFUSE 6-SF BRACKET UMVS162511STRAP UMVS254411STRAP 46 IN	2 1 2 1
Workorder:	V40857		_
	06/13/2011 A BACK WALL DIVIDER MADE FOR TOP SH	83.30 ELF IN L2 COMPARTMENT ABOVE FILL STAT IV BULBS IN THE LIGHT TOWER IS OUT. Sta (
Task perfor	med:	Parts	Quantity
Made a meta	al back wall for compt shelf.	NO PARTS USED	
Workorder:	V41198		
In Date: Close Date: Problem? LIGHT OU	06/08/2011 Meter Reading: 134,1 06/13/2011 T IN LIGHT TOWER	07.00	
Task perfor	med:	Parts	Quantity
	oulb out; raise tower, rem blown bulb; isntall erate & lower tower.	Q1500T3/CLLB-M15 240 V BULB	1
Workorder:	S6887		
In Date: Close Date:	06/08/2011 Meter Reading: 07/18/2011		

Close Date: 07/18/2011

Problem?

bulb out on light tower. 220v bulb. OLD WORK ORDER. IT HAS BEEN FIXED.

Task performed: **Parts** Quantity

Light tower was repaired by Vehical appratus tech's. NO PARTS USED



MAKO BREATHING AIR COMPRESSOR

Quantity

Workorder: S6972

In Date: 08/05/2011

Close Date: 08/05/2011

Problem?

Fill whip valve broken.

Task performed:

Parts

R/R broken fill whip valve with new valve.

NO PARTS USED

Meter Reading:

Workorder: V40625

In Date: 05/15/2011 Meter Reading: 133,130.00

Close Date: 08/05/2011

Problem?

The backup camera is not working on the backup LA vehicle. No picture comes up on the screen. SPARE LA

Task performed: Parts Quantity

sent to shop for repair

NO PARTS USED



MAKO BREATHING AIR COMPRESSOR

Workorder: V42565

In Date: 08/04/2011

Close Date: 08/17/2011

Meter Reading: 134,400.00

Problem?

B INSPECTION AND REPAIRS AS NEEDED SLA

Task performed:	Parts	Quantity
B INSPECTION ON LA34	01046139100EBULB STOP/TAIL	1
CEDVICE OILAND FILTED ALL	134RLENS	1
SERVICE OIL AND FILTER ALL SERVICE AIR COMPRESSOR MOTOR ALL	15W40BSYN OIL BULK QTS	10
CERTIFICATION RESIDENCE TO THE PROPERTY OF THE	33472FUEL FILTER FOR DIESEL ENG LISTER	1
R&R BOTH MARKER LIGHT OF FRONT FENDER	389054HOSE & FITTINGS	1
R&R RIGHT SIDE REAR STROBE LIGHT OUT R&R BUMPER LIGHT OUT LENSE CRACK REPLACE	751-1062051335 OIL FILTER	1
R&R BUMPER LIGHT OUT LENSE CRACK REPLACE	FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
LUBE BOTH DOOR HINGES AND STRICKER PLATE	G3FUEL FILTER 33033	1
LOCKS	HPH6349AOIL FILTER 51748	1
R&R LIGHT ON IGNT BATTERY ON SWITCH OUT	PH8AOIL FILTER WIX 51515	1
R&R BOTH TRANS COOLER - LEAKING FLUID	R90PFILTER FUEL 33231	1
CHECK AND ADJUST ALL TIRE PRESSURE	RAIRK30880N122WSKL4000 SENSOR WATER IN FUEL	1
R&R START BATTERY ALL BAD ON CHEKOUT BUFF OFF LIGHT - INSEPTION	TURBO64STROBE TUBE	1
REPAIR WIRES TO CHARGER AND REPLACE FUSE CHARGING AT THIS TIME		
CHECK ON SHELF WORK ALL READY DONE CHECK AND REPAIR LIGHT ON TOWER WIRING		

Workorder: V43683

QA INSPECTION

In Date: 09/14/2011 Meter Reading: 134,423.00

Close Date: 09/15/2011

Problem?

multiple problems, 1)tower light will not return to parked postion unless someone gets on the roof and pushes as down switch is h 2)tower light has 1 bulb out (220 bulb) 3)rear step pivot broke on left side of step. la24

Task performed:	Parts	Quantity
cleaned and lubed light tower mechanism (seized)	Q1500T3/CLLB-M15 240 V BULB	1
replaced 240v light bulb in tower		
repaired fold out step on tail board (bolt missing/bent)		



MAKO BREATHING AIR COMPRESSOR

Workorder: V44173

In Date: 10/05/2011

Close Date: 10/14/2011

Meter Reading: 134,832.00

Problem?

The bottle fill regulator is leaking air. sta 34.

Task performed: Parts Quantity

REPALCE LIGHT THAT WAS BROKEN IN REAR OF

TRUCK

01-0263814-50USE 01-026B807-50 CORNER LED 4500 LIG

- 1

REPAIRED AIR LEAK IN REGULATOR

Workorder: V41220

In Date: 06/09/2011 Close Date: 11/02/2011

Meter Reading: 134,271.00

Close Date: Problem?

CHECK ENGINE LIGHT IS ON AND STAYED ON, Sta 24.

Task performed: Parts Quantity

ref to wo 42565 inspection NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue **Fleet Maintenance Asset History** 10125552

MAKO BREATHING AIR COMPRESSOR

52-24WIPER BLADES ANCO 24

SWT54915SWIT-251240 SW ROCKER SPST ON/OFF GREE

Quantity 2

1

Parts

Workorder: V44952

In Date: 11/04/2011

11/15/2011 Close Date:

Problem? A inspection.

135.184.00 Meter Reading:

Task performed:

A INSPECTION, CHECK GEN MOTOR, COMPRESSOR MOTOR, AND VEHICLE ENGINE

ADD TRANS FLUID

DIAGNOSE PROBLEM WITH NO START ON GENERATOR AND COMPRESSOR MOTOR, GEN FUEL SHUT OFF, SOLENOID STICKS AND COMPRESSOR A CO CALIBRATION PROBLEM

CAULK TOP OF AWNING AFTER FILLING LARGE GAP WITH WEATHER STRIP

DIAGNOSE COMPRESSOR COMPT. MAP LIGHT INOP. CHECKED POWER AND GROUND OK, REPLACED **BULB AND MISING SCREW**

REMOVED CONSOL PANEL AND REMOVED MODULAR SWITCH HOUSING, REPLACED REAR LIGHT BAR SWITCH

REPAIR WIRE TERMINAL TO OIL PRESSURE SWITCH

REINSTALL COMPRESSOR DOOR AND PIN TOP HINGE

CHECK TOE ANGLE OK, CHECK FRT END

REPAIR LOOSE CONNECTIONS AT BULB FOR ROOF CLEARANCE LIGHT

REPLACE WIPER BLADES

Workorder: V45070

In Date: 11/09/2011 Meter Reading: 134,942.50

Close Date: 11/30/2011

Problem?

REPLACE TIRES CALLAGHAN

Task performed: **Parts** Quantity

Replace tires - Callaghan.bp NO PARTS USED

Vendor?: CALLAGHAN TIRE



MAKO BREATHING AIR COMPRESSOR

Workorder: V45870

In Date: 12/14/2011 12/15/2011

Close Date:

Problem?

repair a/c la 24

135,259.50 Meter Reading:

Task performed: Quantity **Parts**

CHARGE A/C AND CHECK FOR LEAKS. NO PARTS USED

Workorder: V45914

In Date: 12/19/2011 135,500.00 Meter Reading:

Close Date: 12/19/2011

Problem?

Bottle tube brackets not bolted down.

Task performed: Quantity **Parts**

BOLTED BOTTLE **TUBE RACKS** INTO NO PARTS USED

COMPARTMENTS.

Workorder: V46996

In Date: 02/01/2012 Meter Reading: 64,270.00

Close Date: 02/28/2012

Problem?

High co alarm and cascade conpressor shut down while trying to fill bottles, sta 34

Task performed: **Parts** Quantity

RAN COMPRESSOR AND CHECKED OPERATION AND

ALL TESTED OK.

NO PARTS USED

Workorder: V45069

In Date: 11/09/2011 Meter Reading: 134,942.50

Close Date: 03/12/2012

Problem?

ALIGNMENT CALLAGHAN

Task performed: **Parts** Quantity



MAKO BREATHING AIR COMPRESSOR

Workorder: V48108

In Date: 03/21/2012

Close Date: 04/02/2012

Meter Reading:

35,599.00

Problem?

Audible and visual door alarm continues to go off when brake is off, all doors are shut and truck is in drive. Sta 34

Task performed: Parts Quantity

REPAIRED AND ADJUSTED SWITCH ON DOOR. NO PARTS USED

Workorder: \$7652

In Date: 05/08/2012 Meter Reading:

Close Date: 05/08/2012

Problem?

Breathing air compressor filters due for replacement.

Task performed: Parts Quantity

Replaced breathing air filters (1) 1803, (1) 1503.

Compressor running properly.



MAKO BREATHING AIR COMPRESSOR

135,626.70

Parts

Workorder: V48985

In Date: 04/30/2012 Close Date: 05/14/2012

Meter Reading:

Problem?

C INSPECTION LA HQ

Task performed:

Quantity



MAKO BREATHING AIR COMPRESSOR

1	1/	ı۸	ハ	ი23

1.	C-Inspect	tion.	2.	C-Inspectio	n.	3.	Service
gen	erator. 4.	Servic	e Co	ompressor.	5. Re	pair	RRI Tire
leak	c and LRI	tire le	ak.	Air all tires	s to m	nanı	ıfactures
spe	cs, tighten	valve s	tem	nuts, replace	ed valv	e ex	kt for LRI
tire.	File dow	n stem	to c	orrect size.	6. R	epla	ce wiper
blad	des. 7. Re	ebuild d	l rye	r.			

- 8. Replaced compressor discharge hose. Hose too short. Cut all tire straps, repositioned fitting at dryer, R&R clamps. Connect hose, protect hose and tie strap back up. 9. Diagnose problem with a uto eject. Found corrosion in auto eject. 10. Install new auto eject. Drill out frozen bolt. Cut out and clean body of silicone. Splice wires. Replaced broken cover. Test operation of auto eject (ok)
- 11. Replaced L Frt door weather strip. 12. Replaced R frt door weather strip.
- 13. Replaced roof clearance bulb. 14. Replaced LF door trim. R&R panel.
- 15. Replaced RF door trim. R&R panel. 16. Diagnose problem with light tower strobe in/op remove cover for wiring. Replaced bad wiring splice and heat shrink connections. Order parts. 17. Remove tower light frame and broken len pieces. Order new frame and lens. 18. Diagnose problem with tower going into stowed position. Found sensor out of position. Re-position sensor. All fasterners on cover frozen. Cut off fasteners to remove cover.
- 19. Diagnose problem with tower not retracting. Found vehicle air must be close to 100% in order for solenoids to dump air
- 20. R-2 compt light in/op. Remove light fixture no wire connector on light. Fish wire connector out of inner panel. Test light ok. Wiring not correct. Hot on ground lead. Check wires at relay not problem. Somewhere in harness.
- 21. Replaced bulb L Frt marker. 22. Replaced cracked marker lens and bulb (LR).
- 23. Tighten tool brackets. 24. Straighten out bent diamond plate rear compt.
- 25. Remove rear air brake hose (checking). Found checking not hose but paint. Re-install hose. No hose in parts. 26. Reposition brake hoses rubbing on diff.
- 27. Remove front switch panel and removed switch for rear lights. LED out. No switch in parts dept. Install switch back in panel and install panel.
- 28. Diagnose camera in/op. Remove camera cable and trace to center consol. Remove consol cover. Checked power and ground. Trace blue wire to electrical panel. Trigger for reverse/500 tryed camera II imput no good. call tech support. Monitor internal relay bad. Disconnect trigger. Reinstall panel and consol cover. Switch camera for reg view and not mirror view at camera.
- 29. Piercer not rotating. Remove piercer found piece

107796DRYER KIT AD9 -NEW	
107800VALVE CHECK AD9	1
15W40BSYN OIL BULK QTS	30
800405PURGE VALVE KIT	1
A1211593054HOSE DISCHG	1
A1834388002MOLD L/H	1
A1834388003MOLD R/H	1
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1
UMVS162511STRAP	6
15W40QSYN OIL QT	5
33472FUEL FILTER FOR DIESEL ENG LISTER	1
3934044 3938160 OIL PAN C GASKET	1
751-1062051335 OIL FILTER	1
EC6550ASTROBE LIGHT AMBER	1
G3FUEL FILTER 33033	1
HPH6349AOIL FILTER 51748	1
PH8AOIL FILTER WIX 51515	1
366-07188366-07188 AIR FLT 42135	1
40896474309418 PUMP-WATER ISC REBUILT	1
440-5 VALVE EXT.	1
6806970098SEAL DOOR	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
EL360081760611 SOLENOID AIR HORN	1
Q1500T3/CLLB-M15 240 V BULB	4



MAKO BREATHING AIR COMPRESSOR

1/10/2023

of reflector jamming gear train. Removed pierce bench test (ok) Splice wiring and reinstall test ok.

- 30. Mount brackets in rear compt. for air packs.
- 31. Diagnose air leaks. Repair leaks at various fittings found air horn solenoid body cracked. No solenoid in stock. Replaced solenoid with different version adapt to fit splice wiring test ok. Adjust gov to 120 PSI.
- 32. Re-wire door open and compt lights. Relay wired backwards. Time with e-one tech support.
- 33. Diagnose coolant leak found bad water pump. Drain coolant, remove belt, remove water pump.
- 34. Install water pump, belt, and fill with coolant. 35. Degrease motor.
- 36. Test drive vehicle and check for oil leaks. Tighten oil pan bolts and vehicle air compressor. Run vehicle on high idle during lunch. Bring in and put on lift. Oil pan leak rear of motor.
- 37. Diagnose siren in/op found bad power unit remove consol cover and replaced siren, test ok.
- 38. Drain oil, remove oil pan, clean gaskets and oil pan. Install pan with new gasket. Apply sealer at machine surfaces torque bolts.
- 39. Fill oil pan with oil saved in buckets when drained. Run vehicle and check for leaks. Ok.
- 40. Install new strobe on light tower. Splice wires. Diagnose problem with wiring. Found wire from box to board inside tube bad. Re-wire to by pass bad wire cut off bolts for strobe cover. Install missing bolts.



MAKO BREATHING AIR COMPRESSOR

Workorder: V48853

In Date: 04/24/2012 Close Date:

05/15/2012

Meter Reading:

135.626.70

Problem?

roll up open door light stays on while driving

Task performed:

- TRAVEL TO ST 34 CHECK OUT SWITCHES ON TRUCK FOUND BOTH REAR SIDE DOORS SWITCHES NOT RESPONDING NEED WIRE DIG. FOR SYST CAN AND LOCATE WIRES.
- 2. REPLACE BROKEN MAKO KNOB ON FILL.
- 3. REAR COMPARTMENT LIGHT NOT ON. REMOVE LIGHT - FOUND WIRE CONNECTOR MISSING. TRYED TO FISH OUT CONNECTOR BUT TOO FAR IN RECESS. DRILL LARGE HOLE ON BOTTOM OF COMPARTMENT - COULD NOT GET TO CONNECTOR, DRILL ACCESS HOLE HIGHER. FISH CONNECTOR UP THROUGH FIXTURE HOLE AND CONNECT TO LIGHT (NO GOOD) TEST BULB (OK). CHECK SWITCH ON ROM DOOR COULD NOT GET IT TO WORK. REMOVE SIDE DOOR TRACK AND DRILL OUT PAP RIVETS. INSTALL NEW SWITCH POP RIVIT NEW SWITCH TO TRACK. HOLES IN TRACK TOO LARGE TO MAKE POP RIVETS GRAB. DRILL OUT POP RIVITS AND INSTALL BACK-UP WASHES. RE-POP RIVIT SWITCH. PROTECT WIRES WITH ELECTRICAL TAPE AND FEED INTO TRACK SPLICE WIRES AND INSTALL TRACK TO BODY. CUT LARGE PLATES TO COVER ACCESS HOLES TEST OK.

Parts Quantity

1875627DOOR HANDLE LOCKING

Workorder: V49727

In Date: 05/30/2012 Meter Reading:

Close Date: 06/01/2012

Problem?

COwarning light sensor activates on the air compressor of truck when trying to run compressor to fill SCBA bottles. Needs service vehicle located at station 34.

135,974.00

Task performed: **Parts** Quantity

CONTACTED SCBA SHOP FOR REPAIR. NO PARTS USED



MAKO BREATHING AIR COMPRESSOR

Workorder: V49971

In Date: 06/07/2012

06/13/2012 Close Date:

Problem?

CHECK ENG LT ON

136,260.30 Meter Reading:

Task performed:

CHECKED TRUCKS VOLTAGE FROM ALTERNATOR TO BATTERYS HOOKED UP LAP TOP READ CODES

CHECKED OK.

NO PARTS USED

Parts

Workorder: V49658

In Date: 05/27/2012

Close Date: 06/18/2012

Problem?

Asset number is assigned to Spare AL341-CO sensor faulting, compressor deadlined. AT 34

Meter Reading:

Task performed:

Parts

Parts

135,974.00

136,373.40

Quantity

Quantity

RAN COMPRESSURE FOR 25 MINUTES AND ALL

TESTED GOOD.

NO PARTS USED

Workorder: V50236

In Date: 06/19/2012

Close Date: 06/22/2012

Problem?

check eng It on

Task performed:

Meter Reading:

TRAVEL TO 19 CHECKED ENGINE CODES CODE 121 PRESENT BUT NOT ACTIVE REMOVED TIMING SENSOR AND WAITED FOR SHOP TO BEING REPLACEMENTS. INSTALLED AND RAN TRUCK OK. COULD NOT CLEAR CODES.

4921597OUTBOARD SPEED SENSOR

Quantity 2



MAKO BREATHING AIR COMPRESSOR

Workorder: V50764

In Date: 07/11/2012 07/12/2012 Close Date:

Problem?

a/c blowing warm

136,373.40 Meter Reading:

Task performed:

CHECKED OUT A/C: FOUND NO FREON IN SYSTEM. FILLED SYSTEM WITH NITROGEN AND LEAK CHECKED. FOUND ACCESSIVE LEAK AT COMPRESSOR. REPLACED COMPRESSOR AND DRYER. VACCUMED AND RECHARGED SYSTEM.

Parts Quantity 1 532703-0602 COMPRESSOR U4735 4471 1 716907-0610A DRYER

Workorder: V51580

In Date: 08/14/2012

Close Date:

09/17/2012

A/C IS NOW WORKING NORMALLY.

DISCONNECT REAR DOOR ALARM

Task performed:

Problem?

Parts

Quantity

DISCONNECTED REAR DOOR ALARM/INTERMITT

FAULT/ DISCONNECTED ALARM.

NO PARTS USED

Workorder: V52421

In Date: 09/17/2012 Close Date:

09/19/2012

Meter Reading:

Meter Reading:

136,939.80

136,939.80

Problem?

ON CALL COMP. WONT START LA 34

Task performed:

Parts

Quantity

CHK OUT ONE RELAY NUT ACTIVITY NEW TO COMPT TO SHOP ONN MON. TO BE LOOKED AT BY

COMPRESSOR WORKER, O.O.S.

NO PARTS USED

Workorder: V52413

In Date: 09/16/2012

Meter Reading:

Close Date: 09/25/2012

Problem?

broken relay wire connection for compressor, needs new connector per on-call mechanic who diagnosed problem on 9/16, LA341 may be at HQ if after 8 AM.

Task performed:

Parts

Quantity

REPAIRED AT SHOP.



MAKO BREATHING AIR COMPRESSOR

Workorder: V54901

In Date: 01/07/2013 Close Date: 02/07/2013

Task performed:

Meter Reading:

Problem? Left rear marker light burned out. LA 341		
Task performed:	Parts	Quantity
REPAIRED GROUND WIRE FOR MARKER LIGHTS THAT WERE OUT.	NO PARTS USED	
Workorder: V55743		
In Date: 02/12/2013 Meter Reading: Close Date: 03/05/2013 Problem?		
motor oil is needed for the aperatus H-Q		
Task performed:	Parts	Quantity
DROPPED OFF OIL.	NO PARTS USED	
Workorder: V55866		
In Date: 02/19/2013 Meter Reading: Close Date: 04/04/2013 Problem?		
Locks to be installed on roll up doors. Ed Woodland state	d locks were received. Thanks	
Task performed:	Parts	Quantity
1. INSTALL L-1 COMPARTMENT DOOR LOCK.	R00178 S812-0134RAIL ASSY BOTTOM LOCKING ROM	2
2. INSTALL L2, L3, R1, COMPARTMENT DOOR LOCKS.	R00178 S812-0137RAIL ASSY BOTTOM LOCKING ROM	1
3. INSTALL R2, R3, R4, COMPARTMENT LOCKS.	R00178 S812-0140RAIL ASSY BOTTOM LOCKING ROM	2
	R00178-S812-0137RAIL ASSY BOTTOM LOCKING ROM	2
Workorder: V48555		
Close Date: 04/08/2013 Problem?	99.00	
ROLL UP DOOR SWITCH INOP, RR TURN SIGNAL INC	OP, BACK UP MONITOR INOP, TOWER LIGHT NEED A C	LEAR LENS

Parts

NO PARTS USED

Quantity



MAKO BREATHING AIR COMPRESSOR

Workorder: V50804

07/12/2012 In Date:

04/15/2013 Close Date:

Problem?

REPLACE LIGHT

Meter Reading: 136,373.40

Meter Reading:

Task performed:	Parts	Quantity
	903367LIGHT HEAD	1
	EC6501FTFLASH TUBE ECCO	1
	ECR6050LALENS LOW PROFILE AMBER ECCO	1
	Q1500T3/CLLB-M15 240 V BULB	1

137,501.70

Workorder: V56532

In Date: 03/20/2013

Close Date: 04/15/2013

Problem?

B inspection on Light and air

13. REPLACE TOP L/R CLEARANCE LIGHT.

Task performed:	Parts	Quantity
1. B-INSPECTION.	107796DRYER KIT AD9 -NEW	1
2. FINISH B INSPECTION.	107800VALVE CHECK AD9	1
3. REPLACE R/S REAR PADS FOUND L/S R ROTER CRACKED. REMOVE ROTER AND REPLACE ROTOR	15016KIT15016 PIN KIT	2
AND INNER SEAL.	29526898 29548988 TRANS FILTER ALLISON	1
4. FINISH REAR BRAKE JOB REPLACE R/S ROTOR	3218K167ROTOR-BRAKE	2
AND INNER SEAL.	380003ASEAL	2
5. REMOVE AIR DRYER AND REBUILD REINSTALL.	401581GASKET AXLE FL80 R002435	2
6. REPAIR REAR WIRING HARNESS AND SECURE HARNESS FROM RUBBING ON FRAME.	52-24WIPER BLADES ANCO 24	2
7. REPLACE 3 MARKER LIGHTS ON REAR BUMPER	800405PURGE VALVE KIT	1
AND REPAIR WIRING.	KIT15625PMAXEL SET	1
8. DIAGNOSE FAULTY REAR BRAKE CHAMBER	MA15445NT3030 STD CHAMBER 30/30	2
REPLACE BOTH BRAKE CHAMBERS AND SET REAR BRAKE ADJUSTMENT.	33472FUEL FILTER FOR DIESEL ENG LISTER	1
9. DIAGNOSE ABS LILGHT AND RESET ABS SENSOR	FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
DEPTH AND TEST DRIVE.	HPH6349AOIL FILTER 51748	1
10. TIGHTEN LOWER RADIATOR HOSE CLAMP	R90PFILTER FUEL 33231	1
PRESSURE TEST COOLING SYSTEM.	440-5 VALVE EXT.	2
11. RECHECK BRAKE ADJUSTMENT.	E-600013-3052 NUT	2
12. CLEAN OIL PAN AND TIGHTEN PAN BOLTS.	_ 0000.0 000	_

46792LIGHT MARKER

3



MAKO BREATHING AIR COMPRESSOR

Workorder: \$8447

In Date: 01/01/1900

Close Date: 08/07/2013

Problem?

Calibration and Zero gas issued - LA341.

Task performed: Parts Quantity

Issue calibration and zero gas.

NO PARTS USED

Meter Reading:

Workorder: \$8483

In Date: 09/06/2013 Meter Reading:

Close Date: 09/06/2013

Problem?

20 PPM Calibration gas installed - LA341.

Task performed: Parts Quantity

Replaced 20 PPM calibration gas on LA341.

NO PARTS USED

Workorder: S8518

In Date: 10/02/2013 Meter Reading:

Close Date: 10/02/2013

Problem?

Gauges replaced - LA341 compressor unit.

Task performed: Parts Quantity

Replace gauges - LA341 compressor unit.

NO PARTS USED

Workorder: V62014

In Date: 11/14/2013 Meter Reading: 137,881.70

Close Date: 11/27/2013

Problem?

REPLACE STARTERON COMPRESSOR

CHARGE BATTERIES AND RETEST-OK.

Task performed:	Parts	Quantity
1. DIAGNOSE NO START ON A BOARD AIR	228000-1880STARTER AIR/LIGHT	1
COMPRESSOR.	33472FUEL FILTER FOR DIESEL ENG LISTER	1
2. INSPECT FRT AND REAR BRAKE LININGS.	366-07188366-07188 AIR FLT 42135	1
3. R&R STARTER ON COMPRESSOR ENGINE-		4
WOULD NOT START- DIAGNOSE BATTERIES LOW-	751-1062051335 OIL FILTER	ı



MAKO BREATHING AIR COMPRESSOR

Workorder: V63785

In Date: 01/28/2014 Close Date:

01/31/2014

Meter Reading:

138,278.20

Problem?

glass broke on one of lights on mast

Task performed: **Parts** Quantity

REPLACED BROKEN PIECE OF GLASS. 900854REPL LENS 1500W 1

Workorder: V64115

In Date: 02/10/2014

Meter Reading:

Close Date: 02/11/2014

Problem?

Generator no working, Check engine light comes on while driving.

Task performed: **Parts** Quantity

CHK GENERATOR FOR NOT STARTING- TRACED WIRING- REPAIRED WIRING @ STARTER- FOUND REMOVE STARTING PANEL ON DRIVER SIDE TRIPS BREAKER NEEDS FURTHER REPAIR.

NO PARTS USED

Workorder: V63995

In Date: 02/05/2014 Meter Reading: 138,374.80

Close Date: 02/25/2014

Problem?

air comp no start, c/e light

Task performed: **Parts** Quantity

TRACED OUT PROBLEM WITH COMPRESSOR NOT

STARING FOUND BAD CONECTION.



MAKO BREATHING AIR COMPRESSOR

Workorder: V65166

In Date: 03/24/2014 Close Date: 04/15/2014

Meter Reading: 138,969.00

Problem?

C INSPECTION LIGHT AIR

Task performed: Parts Quantity



1/10/2023

(BURNT).

(BURNT).

REINSTALLED LIGHT.

REAR LIGHT BAR. (BROKEN).

NEW BRAKES (BROKEN).

19. REPLACED BODY MARKER LIGHT ASSEMBLY ON

20. CHECKED OUT LEFT REAR ROTATOR INOP. DISASSEMBLED LIGHT AND FOUND BAD GROUND. CLEAN GROUND BOLT AND SURFACE AND

21. REPLACED SWITCH IN CENTER CONSOLE FOR

22. REPLACED BROKEN SWITCH FOR TOWER

23. TROUBLESHOOT GENERATOR SHUTTING DOWN DURING OPERATIONAGAIN, TRACED PROBLEM TO FAULTY COOLANT SHUTDOWN SWITCH. REMOVED SWITCH AND ORDERED NEW. ALSO ORDERED

24. REPLACED TWO 240 LIGHT BULBS IN TOWER

25. RETAPPED AND REINSTALLED WIRES LOOMS AFTER MENTIONED TROUBLESHOOT PROCESS.
26. LIGHT TOWER ON ROOF OF BODY WOULD NOT STOW PROPERLY ADJUST RACK AND LUBED.

RIGHT, FRT, TOP OF BODY. (CORRODED).

POWER ON OFF IN L-1 COMPARTMENT.

Palm Beach County Fire Rescue Fleet Maintenance Asset History 10125552

MAKO BREATHING AIR COMPRESSOR

1. PERFORM C SERVICE.	064615900006-46159-001 SWITCH WIPER
2. CONTINUED/COMPLETED C SERVICE. 3. TROUBLESHOOT WIRING PROBLEM ON	103385NDRAIN COCK
GENERATION FOUND GENERATOR FOUND	107796DRYER KIT AD9 -NEW
GENERATOR ENGINE WOULD NOT START OR	107800VALVE CHECK AD9
SHUTDOWN PROPERLY.	1156BULB
4. CONTINUED WIRING TROUBLESHOOT FINALLY	194BULB
TRACED PROBLEM FAULTY WIRING FOR THE	33472FUEL FILTER FOR DIESEL ENG LISTER
SHUTDOWN SOLENOID AND THE ALTERNATIVE WIRING. REWIRE ENTIRE CIRCUIT, ALSO REPAIRED	39550TEMP SENSOR
NUMEROUS CHAFTED AND BROKEN WIRES AND	42709BREAKER 60AMP
REPLACED STARTER RELAY.	46793-346793 AMBER MARKER LIGHT
5. SERVICE DIESEL ENGINE FOR GENERATOR.	52-24WIPER BLADES ANCO 24
6. SERVICED AIR COMPRESSOR DIESEL ENGINE.	751-1062051335 OIL FILTER
7. REPAIRED AIR COMPRESSORCAGE DOOR (FALLING OFF).	800405PURGE VALVE KIT
8. PAINTED BOTH FUEL CAPS.	9510BELT
9. SERVICED AIR BRAKE DRYER.	CA8193AIR FILTER 46744 WIX
10. REPAIRED AIR LEAKS. REPLACED PULL CORD	FS1022FILTER FUEL WIX 33422 PS8689 FRAM
DRAINS WITH PECOCKS. REMOVED AUTO DRAIN	G3FUEL FILTER 33033
AND CAPPED. 11. DISASSEMBLED DASH AND REPLACE	HPH6349AOIL FILTER 51748
11. DISASSEMBLED DASH AND REPLACE NUMEROUS DASH IGHTS. (BURNT OUT).	K080680BELT SAME AS 3281981 CUMMINS
12. REPLACED WIPER BLADES.	
13. REPLACED WINDSHIELD WIPER/WASHER	PH8AOIL FILTER WIX 51515
SWITCH 10 REPAIR WASHERS INOP.	PR338324070 WIX FILTER WATER
14. REPLACED BELTS.	Q1500T3/CLLB-M15 240 V BULB
15. REPLACED AIR FILTER.16. CHECK LOW ALTERNATOR OUTPUT CONERN.	R90PFILTER FUEL 33231
CHECKED ALT, FOUND ALT CHARGING NORMALLY.	VF445F11FSO140A RELAY A/C DIODE SUP
17. SERVICED P/S.	VML-S1414FILTER P/S
18. REPLACED LEFT FRT. TURN SIGNAL BULB	VML-T1264GASKET P/S COVER

VML-T1279WASHER P/S



MAKO BREATHING AIR COMPRESSOR

REMOVED COVERS AND STRAIGHTENED LUBED AND ADJUSTED LIFTED MECHANISM. TOWER NOW OPERATES SMOOTHLY.

27. INSTALLED TEMP SHUTDOWN SENSOR IN GENERATOR RAN GENERATOR UP TO RUNNING TEMP. ENGINE RAN NORMALLY NO SIGN OF SHUTDOWN. NOW WORKING ON MASTER BRAKES.
28. INSTALLED NEW MAIN BREAKER FOR GENERATOR. STARTER GENERATOR AND TESTED ALL SYSTEMS. ALL WORKING NORMAL.

Workorder: V61982

In Date: 11/13/2013

Close Date: 04/17/2014

Problem?

SCBA compressor issue - Channel Innovations stated issue with compressor starter.

Task performed: Parts Quantity

REPAIRED ON ANOTHER WORK ORDER V62014. NO PARTS USED

Meter Reading:

Workorder: V62184

In Date: 11/21/2013 Meter Reading:

Close Date: 04/17/2014

Problem? A/c inop

Task performed: Parts Quantity

REPAIRED ON V63995. ABPN8330101701-0604 3924 BLOWER A/C BOA 852050000

137,881.70

Workorder: V64584

In Date: 02/27/2014

Close Date: 04/29/2014

Problem?

check engine light comes on goes off comes on goes off all gauges water, oil, trans., and air all have good readings

Task performed: Parts Quantity

REPAIRED ON C-INSPECTION V65166.

NO PARTS USED

Meter Reading:



MAKO BREATHING AIR COMPRESSOR

Workorder: S8844

In Date: 06/05/2014 Close Date:

06/05/2014

Meter Reading:

Problem?

LA24 - CO sensor inoperable

Task performed: Quantity **Parts**

Replace sensor, hose whip. NO PARTS USED

Workorder: V68502

08/07/2014 In Date: 82,475.00 Meter Reading:

Close Date: 08/07/2014

Problem?

Canopy top left gear getting more stripped. Having problems retracting unit.

Task performed: Quantity **Parts**

NO PARTS USED

Needs an a/c compressor,

This vehicle will go to surplus will not do repairs

Vendor?: AL PACKER

Workorder: V69403

In Date: 09/15/2014 Meter Reading: 140,102.60

Close Date: 09/17/2014

Problem?

Replace awning

Task performed: **Parts** Quantity

Remove old awning, clean up silicone and start installing new brackets for awning. (truckwent on a call) finish

installing awning.



MAKO BREATHING AIR COMPRESSOR

Workorder: V71160

In Date: 11/24/2014 Close Date:

12/15/2014

Meter Reading:

Problem?

Starter on air compressor does not engage all the time. It clicks clicks and then it will engage.

Task performed:

- 1. Battery failed load test-replace batteries. Note: these batteies are under cab body and have no slide out battery tray-very difficult to get to cables-after battery removal, clean all cable and wire ends as the looked like were never done(REFER TO w/o 71359 FOR CHARGED **OUT PARTS)**
- 2. Alternator output would not hold load from AC and emergency lighting-replace alternator(REFER TO w/o 71359 FOR CHARGED OUT PARTS)
- 3. Belt tensioner making noise and was light on tension-replace belt tensioner
- 4. Battery compartment door latches broken-no latches available-found two old latches around shop disassemble and make two useable latches-install in door and adjust to fit ..
- 5. Check out problem with starter-trace wiring back from starter to ignition switch-pull down control panel to gain acess to ignition switch wiring-found problem at connection of compund switch-repair also tightened switch in panel

Parts

Quantity



MAKO BREATHING AIR COMPRESSOR

Workorder: V71359

In Date: 12/04/2014 Meter

12/15/2014

Meter Reading: 140,708.30

Close Date: Problem?

inital shift from N to D is hard, check for harding shifting while driving

Task performed:

- 1. Road test and perform a fast adapt program with Steve.R our shop foreman on passenger side with computer while i drove-now shifts ok but noticed a slight vibration/shutter when under acceleration.
- 2. Both center support bearings worn out-disconnect and remove all three section of drive shaft-pull apart center bearings from shafts and press on new ones-reassemble drive shaft and reinstall in vehicle-also check U-joints while apart-all seems ok.
- 3. Check engine light on-on dash and engine has codes-replace both cam sensors in back side of engine front cover between cover and air compressor.
- 4. Brake assemblies-check out all componets-make parts list and give to parts dept. wash up all reusable parts and components-start reassembly with new part available-knock out all studs from left side to install new rotor-press back in studs-assemble hub caliper etc on left side only-finish brake job on right side.

Parts	Quantity
05-17223-000CAP RADIATOR 10 LB	1
23-12080-150BOLT BUMPER	2
3218N1366BRAKE ROTOR	2
370001ASEAL 35066	2
39768315259022 GROOVED TENSIONER OLD#3936213	1
4867JB320 UPGRADE ALTERNATOR	1
4921597OUTBOARD SPEED SENSOR	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	2
CHR1612340-4024 HUB COVER - FRONT AXLE 2004 RESC	2
FRT V68040FREIGHT CHARGE	1
H6054USE CV TYPE SEALED BEAM	1
HP-31DBATTERY 950CCA HP-31D	2
KIT195020PAD KIT FRONT FL80 PUMPER	1
5003323CENTER BEARING	2

Workorder: V71489

In Date: 12/08/2014 Meter Reading:

Close Date: 12/15/2014

Problem?

Needs new rear tires. Compressor filter needs changed. Very slow to fill banks. Transmission very rough shifting gears.

Task performed: Parts Quantity

1. Remove all rear tires for replacement-Steve.R shop foreman look at tires and said don't replace at this time-reinstall all rear tires/with simulators. For trans rough shifting-see W/O 71359



MAKO BREATHING AIR COMPRESSOR

1/10/2023

Workorder: V72543

In Date: 01/22/2015

06/03/2015

Meter Reading:

Close Date: Problem?

B-inspection Towerlight 3-lights out and doesn't pan L-R oil leak?

Task performed:

- 1. B- Inspection.
- 2. Unit not breaking. Lossen slack adjuster, brake can and clevis pin. Check strocke and adjust. Reassemble as to specs. Adjust brake and road test.
- 3. Work lights.
- 4. Tower lights inop- Disassemble. Remove bulbs and install new bulbs and reassemble.
- 5. Generator/ air compressor compartment only- clean and degrease compartment.
- 6. Air leak overnight. Replace air purge valve on air tank. Replace quick connect coupler on air lines and drain valve.
- 7. Light tower re-fabricated hole down broken. Re-fabricate all mounts and make new bracket to fit drill and tap holes. Weld up brackets to fit.
- 8. Light tower support frame wels all broken. Fabricate support anle inop. Cut, drill, tap and reassemble. Install on door. Secure with extra support anchor bolt hold.
- 9. Change oil and filter in breathing air compressor. Clean up unit after.
- 10. Change oil filter and fuel filter on gen. Clean up unit also.
- 11. Replace light assemble on right side quart light.
- Remove light from side of truck and repair and replace.
- 12. Do repair on Willburt light. No pan right or left, check, found pin sheired of replace.
- 13. Breathing air compressor exhaust pipe clamp missing, install and secure new clamp.
- 14. Right side lower body marker inop. Bulb socket loose and corroded. Remove bulb, clean socket ajust spring clip tension, install bulb.
- 15. Will-Burt light not paning left or right. Assist in repair of sheared pin. remove and support tower upper section. Install new pin and reassemble.
- 16. B-Service on unit.

Parts	Quantity
33472FUEL FILTER FOR DIESEL ENG LISTER	1
35408 CLAMP	1
751-1062051335 OIL FILTER	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
G3FUEL FILTER 33033	1
HPH6349AOIL FILTER 51748	1
LB-S72240V 750 W BULB	1
PH8AOIL FILTER WIX 51515	1
Q1500T3/CLLB-M15 240 V BULB	5
R90PFILTER FUEL 33231	1



Asset: (10125552) 1999 - EONE FL60 Air Light

10125552

CSHOP-2015-2400

Comments: BATTERIES DEAD

Date Opened: 8-19-2015 Date Finished 8-19-2015 Meter 1 Reading: 141,036

TASKS PERFORMED NO PARTS USED

BATTERY

CSHOP-2015-3572

Comments: AIR AND LIGHT AT HQ

Date Opened: 10-23-2015 Date Finished 11-13-2015 Meter 1 Reading: 141,048

TASKS PERFORMED NO PARTS USED

ENGINE AND ACCESSORIES

Service Requests:

10/23/2015 OIL / 16: GLAZED / REPAIR

THE LOW OIL LIGHT IS ON FOR THE COMPRESSOR DIESEL MOTOR.

CSHOP-2015-404

Comments: B INSPECTION COMPLETED ON IBEM WORK ORDER 72543

Date Opened: 5-7-2015 Date Finished 5-7-2015 Meter 1 Reading: 140,958

TASKS PERFORMED NO PARTS USED

PM SERVICE B

CSHOP-2015-4077

Comments: L/A GEN WON`T RUN

Date Opened: 11-20-2015 Date Finished 11-25-2015 Meter 1 Reading: 141,071

TASKS PERFORMED NO PARTS USED

CRANKING SYSTEM

CSHOP-2015-52

Comments: REAR TIRES ARE GETTING LOW LEFT REAR TIRES AT 5/32AND AND 6/32 RIGHT SIDE AT 6/32 AND 4/32 NOTE

PLEASE UPDATE HOURS ON TRUCK HOUR ARE 7332

Date Opened: 4-15-2015 Date Finished 4-29-2015 Meter 1 Reading: 140,958

TASKS PERFORMED NO PARTS USED

A INSPECTION

CSHOP-2015-733

Comments: L/A 34 DEAD BATTERIES.

> Date Opened: 5-20-2015 Date Finished 6-2-2015 Meter 1 Reading: 140,970

TASKS PERFORMED NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

BATTERY

DIAGNOSE ELECTRICAL

CSHOP-2015-85

HOLDING ON PARTS OUT OF COUNTRY ORDER EDDIE KNOW ABOUT PARTS.WATER PUMP IS OFF OF ENGINE Comments:

RADIATOR NEED SENT OUT TO BE CK,

Date Opened: 4-16-2015 Date Finished 5-6-2015 140,958 Meter 1 Reading:

TASKS PERFORMED Q **PARTS**

COOLING SYSTEM

NONSTOCK; FREIGHT CHARGE

WATER PUMP LISTER PETTER

FLUID; COOLANT ANTIFREEZE GAL 2

1 **GASKET THERMOSTAT LISTER PETTER**

BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY

2 ORING LISTER PETTER

HOSE

CSHOP-2016-1320

SCBA SHOP Comments:

> Date Opened: 3-18-2016 4-4-2016 Date Finished Meter 1 Reading: 141,093

TASKS PERFORMED

Q **PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER

BATTERY

2 BATTERY; BATTERY 950CCA HP-31D

2

Service Requests:

03/18/2016

STARTER / 19: LOOSE / REPAIR

BATTERIES WON'T HOLD CHARGE CONTACT MYRON 561-616-6967

CSHOP-2016-2624

C-INSPECTION AIR AND LIGHT Comments:

Date Opened: 6-1-2016 Date Finished 6-15-2016 Meter 1 Reading: 141,142 Q

TASKS PERFORMED

PM SERVICE C

10 MOTOR; 15W40 MOTOR OIL NON SYN

FILTER; 33442 FUEL FILTER 1

1 FILTER; FILTER FUEL 33231

1 FILTER; 51335 OIL FILTER

25 FLUID; SYN OIL BULK QTS

FILTER; OIL FILTER WIX 51515

LENS; 9029W LENS

PARTS

FILTER: FUEL FILTER FOR DIESEL ENG LISTER

1 FILTER; FUEL FILTER 33033

FILTER: 24070 WIX FILTER WATER

FILTER; OIL FILTER 51748

CSHOP-2016-2669

REPAIRS FROM PM AWAITING OIL PRESSURE SWITCH AND AIR FILTER FOR GEN Comments:

> Date Opened: 6-3-2016 Date Finished 1-6-2017 Meter 1 Reading: 141,197

TASKS PERFORMED

WIPER BLADES

ENGINE AND ACCESSORIES INSTRUMENT PANEL LIGHTS PARK-CLEARANCE LIGHTS

LIGHTING SYSTEM

VOLT METER TIRES ALL **REAR TIRES**

AIR SYSTEM

BACK UP CAMERA-MONITOR DOOR ALARM OR OTHER WARNING

HEATING AND VENTILATION

PARTS Q

2 WIPER; WIPER BLADES ANCO 24

NEWPART; SWITCH OIL PRESSURE WESTERBEKE

FILTER; 366-07188 AIR FLT 42135

NEWPART; FILTER AIR

9IP; TAILBOARD LIGHT

SWITCH: R01078 SWITCH ROM ROLL UP DOOR

5TN; TEST

CSHOP-2016-4974

Date Opened: 10-18-2016 Date Finished 10-20-2016 141,197 Meter 1 Reading:

TASKS PERFORMED NO PARTS USED

COMPRESSOR CLUTCH

CSHOP-2017-1406

AIR / LIGHT C-INSPECTION Comments:

> Date Opened: 3-7-2017 4-10-2017 141,288 Date Finished Meter 1 Reading:

TASKS PERFORMED PARTS O

PM SERVICE C FIL; FUEL WATER SEPARATOR 1

> 1 5EF; 5EF

> > 1 9IP; FILTER FUEL 33231

CSHOP-2017-1407

Comments: PM FOLLOW UPS GENERATOR LEAKING OIL

> Date Opened: 3-7-2017 Date Finished 4-13-2017 Meter 1 Reading: 141,272 Q

TASKS PERFORMED

REPAIR FROM PM - GENERATOR

1 2FL; SWITCH, NORMAL OPEN LIGHTING SYSTEM 2FL; SWITCH, NORMAL OPEN -1 **TRANSMISSION**

FIL; NAPA TRANS FILTER AIR SYSTEM

BK; SWITCH 1 **INSTRUMENTS-GAUGES-METERS**

20 90C; BULK TRANS SYN

> 1 5EF; VALVE

PARTS

CSHOP-2017-4411

Date Opened: 7-31-2017 Date Finished 8-15-2017 Meter 1 Reading: 141,272

TASKS PERFORMED Q PARTS

STARTER 1 1AD; STARTER (AIR COMPRESSOR)

CSHOP-2017-4972

Comments: REPLACE AIR COMPRESSOR STARTER

TASKS PERFORMED NO PARTS USED

STARTER

CSHOP-2018-4127

Comments: HOSE CRIMP FROM MAKO

Date Opened: 7-23-2018 Date Finished 8-14-2018 Meter 1 Reading: 141,709

TASKS PERFORMED Q PARTS

AIR SYSTEM 1 9HY; HOSE

CSHOP-2018-5455

TASKS PERFORMED Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER

FIRE APPARATUS

DIAGNOSE ELECTRICAL

4 9AP; 1000W 240V

CSHOP-2019-142

Date Opened: 1-8-2019 Date Finished 1-11-2019 Meter 1 Reading: 141,781

TASKS PERFORMED Q PARTS

GROUND LIGHT BODY

100 BEL; BULK BATTERY CABLE

CSHOP-2019-230

Date Opened: 1-14-2019 Date Finished 3-12-2019 Meter 1 Reading: 141,857

TASKS PERFORMED Q PARTS

PM SERVICE B 1 FIL; NAPAGOLD OIL FILTER

24 9OC; 15W40 OIL VAL DRUM S SHOP

1 FIL; FUEL WATER SEPARATOR

1 FIL; NAPAGOLD FUEL FILTER

CSHOP-2019-250

Date Opened: 1-14-2019 Date Finished 3-15-2019 Meter 1 Reading: 141,888

TASKS PERFORMED Q PARTS

SCBA BRACKETS
PONY PUMP MOTOR
WIPERS-WASHER

REPAIR FROM PM - POWER STEERING

FILTER

AIR SYSTEM

STROBE LIGHTS

1 9HY; CUSTOM HOSE

1 FIL; NAPAGOLD FUEL FILTER

12 9AP; BRAKE CLEAN

5 4PC; 15W40 PB OIL DRM/QT

1 CRC; CLEANRCARB 200Z

11 CRC; CLEANRCARB 20OZ

1 FIL; NAPAGOLD FUEL FILTER

2 1AN; WIPER BLADES

1 FIL; NAPAGOLD AIR FILTER

1 FIL; NAPAGOLD FUEL FILTER

1 FIL; WIX OIL FILTER

1 TWD; AD-9KIT

1 TWD; AD-9KIT MINOR

CSHOP-2019-5004

Comments: BURNING SMELL IN CAB AT TRAINING

Date Opened: 9-23-2019 Date Finished 12-10-2019 Meter 1 Reading: 142,090

TASKS PERFORMED NO PARTS USED

ELECTRICAL

CSHOP-2020-1083

Date Opened: 2-24-2020 Date Finished 2-25-2020 Meter 1 Reading: 142,091

TASKS PERFORMED NO PARTS USED

DIAGNOSE ELECTRICAL

Service Requests:

02/24/2020 ENGINE / 18: LEAKING / REPAIR

ENGINE

CSHOP-2020-1490

Date Opened: 3-13-2020 Date Finished 3-23-2020 Meter 1 Reading: 142,116

TASKS PERFORMED Q PARTS

PM SERVICE C 1 FIL; NAPAGOLD FUEL FILTER

1 FIL; FUEL WATER SEPARATOR

CSHOP-2020-2348

TASKS PERFORMED Q PARTS

ENGINE AND ACCESSORIES

1 1AD; STARTER AIR COMPRESSOR

DIAGNOSE ELECTRICAL

1 PTX; PERMATEX

VENDOR TIRE REPAIR/CHANGE

1 FIL; NAPAGOLD FUEL FILTER

1 9HD; PUMP FUEL LIFT

CSHOP-2020-4720

Date Opened: 9-10-2020 Date Finished 9-28-2020 Meter 1 Reading: 142,151

TASKS PERFORMED Q PARTS

FUEL SYSTEM

2 NCB; DEGREASER MULTI PURP

ALTERNATOR-GENERATOR
SHORELINE CHARGER
12 1AD; BRAKE CLEAN
1 ECH; RELAY AR462

EMERGENCY EQUIPMENT 1 8AM; DELAY TIME CONTROL

1 6KU; AC2000 12V PLC TEN 8

Service Requests:

09/08/2020 ENGINE / 18: LEAKING / REPAIR

DIESEL MOTOR FOR COMPRESSOR WILL NOT STAY RUNNING; CONTACT MYRON AT SCBA SHOP FOR MORE INFO

CSHOP-2020-553

Date Opened: 2-3-2020 Date Finished 4-8-2020 Meter 1 Reading: 142,116

TASKS PERFORMED Q PARTS

PARK-CLEARANCE LIGHTS

1 LIT; MARKER L

CRANKING SYSTEM

1 LIT; MARKERL

DOOR ALARM OR OTHER WARNING

1 6HR; MOTOR BOOSTER REEL

CSHOP-2020-5837

Date Opened: 11-5-2020 Date Finished 11-5-2020 Meter 1 Reading: 142,151

TASKS PERFORMED Q PARTS

AIR SYSTEM 18 9HY; FITTINGS WHIP HOSE

Service Requests:

11/05/2020 SERVICE REQUEST / 18: LEAKING / REPAIR

REPLACEMENT FILL WHIP HOSES FOR FILL STATION MADE AT MAKO HOSE AND RUBBER; RECEIPTS WERE GIVEN TO

JEFF AT NAPA

CSHOP-2020-5980

Date Opened: 11-13-2020 Date Finished 11-15-2020 Meter 1 Reading: 142,151

TASKS PERFORMED NO PARTS USED

ELECTRICAL

CSHOP-2021-1530

Date Opened: 3-22-2021 Date Finished 3-22-2021 Meter 1 Reading: 142,300

TASKS PERFORMED Q PARTS

PM SERVICE B 2 1AN; 24 WIPER BLADE

4 NOL; NAPA QT 15W40 CJ4

CSHOP-2021-1532

Comments: LUBE,OIL,FILTERS FRONT & REAR LIGHT BARS INOP LEFT LOWER TURN BEHIND DRIVERS STEP OUT RT REAR

TURN SIGNAL OUT SIREN INOP-POSSIBLY DISABLED CK ENG OIL LEAK ON DRIVERS SIDE P/S LEAK REPLACE ENG

BELT & TENSIONER

TASKS PERFORMED Q PARTS

FUEL SYSTEM
OIL FILTER
OIL FILTER
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; FUEL WATER SEPARATOR
1 FIL; NAPAGOLD OIL FILTER
SIREN

HVAC SYSTEM 25 4PC; 15W40 PREMIUM BLUE OIL

CSHOP-2021-5049

Date Opened: 9-7-2021 Date Finished 9-7-2021 Meter 1 Reading: 142,300

TASKS PERFORMED NO PARTS USED

ELECTRICAL

CSHOP-2021-5185

Comments: RADIATOR LEAK

Date Opened: 9-15-2021 Date Finished 9-15-2021 Meter 1 Reading: 142,300

TASKS PERFORMED NO PARTS USED

COOLING SYSTEM

Service Requests:

09/14/2021 RADIATOR / 18: LEAKING / REPAIR

RADIATOR LEAKING ON GENERATOR UPPER LEFT CORNER HAS A HAIR LINE CRACK

CSHOP-2021-5214

Comments:

AIR GAUGE

TASKS PERFORMED

OIL LEAK ON COMPRESSOR

TASKS PERFORMED	Q	PARTS
RADIATOR		
QUARTZ LIGHT	1	9HC; GASKET THERMOSTAT
COMPRESSOR	1	9HC; GASKET WATER PUMP
	1	9HC; PUMP WATER FRESH 9HC; HOSE LOWER
	1	NBH; SUPER HC IND V BELT
	1	9HC; THERMOSTAT 180F
	1	9HC; HOSE PUMP
	1	9HC; HOSE UPPER
	1	FREIGHT
	1	9RR; CLEAN REPAIR RADIATOR
	2	NAF; 1GAL RTU ANTIFREEZE
	1	9AM; 500W 120V HALOGEN TUBE 118MM
Comments: ISSUED FILL VALVE KNOBS AND CAPS TO Date Opened: 9-16-2015 Date Finished	9-16	-2015 Meter 1 Reading: 141,048
	9-16 Q	-2015 Meter 1 Reading: 141,048 PARTS
Comments: ISSUED FILL VALVE KNOBS AND CAPS TO Date Opened: 9-16-2015 Date Finished TASKS PERFORMED	9-16	-2015 Meter 1 Reading: 141,048
Comments: ISSUED FILL VALVE KNOBS AND CAPS TO Date Opened: 9-16-2015 Date Finished TASKS PERFORMED	9-16 Q 38	-2015 Meter 1 Reading: 141,048 PARTS COMPRESSOR; HAND WHEEL CAP
Comments: ISSUED FILL VALVE KNOBS AND CAPS TO Date Opened: 9-16-2015 Date Finished TASKS PERFORMED EMERGENCY EQUIPMENT	9-16 Q 38 38	PARTS COMPRESSOR; HAND WHEEL CAP COMPRESSOR; HAND WHEEL
Comments: ISSUED FILL VALVE KNOBS AND CAPS TO Date Opened: 9-16-2015 Date Finished TASKS PERFORMED EMERGENCY EQUIPMENT Service Requests: 09/16/2015 SCBA-COMPRESSOR / / ISSUE FILL VALVE KNOBS AND CAPS TO TRAIN	9-16 Q 38 38 38	PARTS COMPRESSOR; HAND WHEEL CAP COMPRESSOR; HAND WHEEL
Comments: ISSUED FILL VALVE KNOBS AND CAPS TO Date Opened: 9-16-2015 Date Finished TASKS PERFORMED EMERGENCY EQUIPMENT Service Requests: 09/16/2015 SCBA-COMPRESSOR / / ISSUE FILL VALVE KNOBS AND CAPS TO TRAIN	9-16 Q 38 38 38 IIING AND I	PARTS COMPRESSOR; HAND WHEEL CAP COMPRESSOR; HAND WHEEL
Comments: ISSUED FILL VALVE KNOBS AND CAPS TO Date Opened: 9-16-2015 Date Finished TASKS PERFORMED EMERGENCY EQUIPMENT Service Requests: 09/16/2015 SCBA-COMPRESSOR / / ISSUE FILL VALVE KNOBS AND CAPS TO TRAIN SCBA-2017-223 Comments: ISSUE ADAPTERS TO CREATE FILL WHIP	9-16 Q 38 38 38 IIING AND I	PARTS COMPRESSOR; HAND WHEEL CAP COMPRESSOR; HAND WHEEL A-341.
Comments: ISSUED FILL VALVE KNOBS AND CAPS TO Date Opened: 9-16-2015 Date Finished TASKS PERFORMED EMERGENCY EQUIPMENT Service Requests: 09/16/2015 SCBA-COMPRESSOR / / ISSUE FILL VALVE KNOBS AND CAPS TO TRAIN SCBA-2017-223 Comments: ISSUE ADAPTERS TO CREATE FILL WHIP Date Opened: 3-22-2017 Date Finished	9-16 Q 38 38 38 IIING AND I	PARTS COMPRESSOR; HAND WHEEL CAP COMPRESSOR; HAND WHEEL A-341. CRO'D CYLINDERS -2017 Meter 1 Reading: 141,272

10-4-2017

Q

1

PARTS

Meter 1 Reading:

COMPRESSOR; GAUGE 0-10000

141,272

REPLACED GAUGE ON COMPRESSOR FILL PANEL

Date Finished

Date Opened: 10-4-2017

SCBA-2018-489

Comments: REPLACED CO SENSOR/ ADDED 20PPM/ ZERO AIR CO GAS

Date Opened: 6-15-2018 Date Finished 6-15-2018 Meter 1 Reading: 141,608

TASKS PERFORMED Q PARTS

AIR SYSTEM 1 COMPRESSOR; CALIBRATION GAS - ZERO AIR

1 COMPRESSOR; CALIBRATION GAS 20 PPM

1 COMPRESSOR; C/O MONITOR SENSOR CELL MAKO

SCBA-2019-1048

Comments: ADDED ZERO GAS ON COMPRESSOR

TASKS PERFORMED Q PARTS

AIR SYSTEM 1 COMPRESSOR; CALIBRATION GAS - ZERO AIR

SCBA-2019-1049

Comments: ADDED 20PPM GAS FOR COMPRESSOR

Date Opened: 12-2-2019 Date Finished 12-2-2019 Meter 1 Reading: 142,053

TASKS PERFORMED Q PARTS

AIR SYSTEM 1 COMPRESSOR; CALIBRATION GAS 20 PPM

SCBA-2019-16

Comments: INSTALLED 415 REG BODY & KNOB

Date Opened: 1-8-2019 Date Finished 1-17-2019 Meter 1 Reading: 141,781

TASKS PERFORMED Q PARTS

AIR SYSTEM 1 COMPRESSOR; REGULATOR KNOB (COMPRESSOR)

1 COMPRESSOR; REGULATOR CAP 6000 PSI

SCBA-2019-542

Comments: INSTALLED TOGGLE VALVE/ RETRACTABLE PLUNGER FOR FILL STATION DOOR HANDLE

Date Opened: 6-14-2019 Date Finished 6-14-2019 Meter 1 Reading: 141,900

TASKS PERFORMED Q PARTS

AIR SYSTEM 1 COMPRESSOR; TOGGLE VALVE; MAKO FILL STATION

1 COMPRESSOR; PLUNGER ASSY

SCBA-2019-796

Comments: LIGHT/AIR 341

Date Opened: 9-18-2019 Date Finished 9-18-2019 Meter 1 Reading: 141,990

TASKS PERFORMED Q PARTS

AIR SYSTEM 1 COMPRESSOR; TOGGLE VALVE; MAKO FILL STATION

1 COMPRESSOR; REGULATOR, 3500 IN 400 OUT WITH

GAUGES AND RELIEF VALVE

SCBA-2020-778

Comments: INSTALLED BLEEDER

Date Opened: 8-19-2020 Date Finished 8-19-2020 Meter 1 Reading: 142,151

TASKS PERFORMED Q PARTS

AIR SYSTEM 1 COMPRESSOR; BLEEDER

SCBA-2021-106

Comments: GAUGE & RELIEF VALVE

TASKS PERFORMED Q PARTS

AIR SYSTEM 1 COMPRESSOR; L/P SAFETY RELIEF VALVE

1 COMPRESSOR; 200 PSI GAUGE, LIQUID FILLED, LINE

MOUNT

SSHOP-2015-44

Comments: LIGHT AND AIR TRUCK WONT START AT HQ

Date Opened: 5-20-2015 Date Finished 5-21-2015 Meter 1 Reading: 140,960

TASKS PERFORMED NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

BATTERY

SSHOP-2021-144

Date Opened: 4-7-2021 Date Finished 6-8-2021 Meter 1 Reading: 142,300

TASKS PERFORMED Q PARTS

SUPPLIES 1 9HC; FITTINGS MAKO

SSHOP-2021-145

Date Opened: 4-7-2021 Date Finished 4-9-2021 Meter 1 Reading: 142,300

TASKS PERFORMED Q PARTS

MIRRORS 1 GRO; CONVEX MIRROR