



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142546

* FREIGHLINER TANKER TRUCK

Workorder: V502

In Date: 11/07/2005
Close Date: 11/15/2005

Meter Reading: 19,324.00

Problem?

R/REAR SCENE LIGHT, AND BACK UP LIGHT INOP, T-21

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V555

In Date: 11/14/2005
Close Date: 11/15/2005

Meter Reading:

Problem?

pump cooler control knob broken off and is in cab T21

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V829

In Date: 12/07/2005
Close Date: 12/15/2005

Meter Reading:

Problem?

R/SIDE TOP FRONT SCENE LITE MISSING LENS COVER, BACK UP CAMERA INOP, NEED CHROME HUB CAPS, FRONT A REAR, T-21

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V924

In Date: 12/14/2005
Close Date: 12/19/2005

Meter Reading:

Problem?

R/REAR HIGH SIDE MARKER LIGHT BROKEN OFF, T-21

Task performed:

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

* FREIGHLINER TANKER TRUCK

Workorder: V1319

In Date: 01/27/2006

Meter Reading:

Close Date: 01/31/2006

Problem?

SIREN SPEAKERS ARE MOUNTED UPSIDE DOWN T21

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V677

In Date: 11/23/2005

Meter Reading: 20,483.00

Close Date: 02/10/2006

Problem?

SIRENS ARE MOUNTED UPSIDE DOWN AND FILL WITH WATER, T-21

Task performed:

Parts

Quantity

30276RLIGHT KIT STANTION KIT 10276R LED 47222 GRO 2

6811813493LENS CLEAR 68-1181349-3 1

Workorder: V1341

In Date: 01/30/2006

Meter Reading:

Close Date: 02/13/2006

Problem?

NEED HEADLIGHT, L/SIDE T-21

Task performed:

Parts

Quantity

H4651USE CV TYPE SEALED BEAM 1

H4656USE CV TYPE HEAD LIGHT 1

Workorder: V1780

In Date: 03/08/2006

Meter Reading:

Close Date: 03/20/2006

Problem?

L/REAR SCENE LIGHT INOP, T-21

Task performed:

Parts

Quantity

6811813493LENS CLEAR 68-1181349-3 1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

* FREIGHLINER TANKER TRUCK

Workorder: V1517

In Date: 02/15/2006

Meter Reading:

Close Date: 03/28/2006

Problem?

R/REAR WARNING LIGHT INOP, T-21

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V2436

In Date: 05/01/2006

Meter Reading:

Close Date: 05/04/2006

Problem?

HEADLIGHTS NEED ADJ, MARKER LIGHT INOP, T-21

Task performed:

Parts

Quantity

B-1102SPACER LENS

1

B-1103A1131 LENS (AMBER)

2

Workorder: V2747

In Date: 05/25/2006

Meter Reading:

Close Date: 06/05/2006

Problem?

WOOD GRAIN DASH COMMING OFF, T-21

Task performed:

Parts

Quantity

291525END STANCHION

1

Workorder: V2981

In Date: 06/14/2006

Meter Reading:

Close Date: 06/27/2006

Problem?

GRAB RAIL FELL OFF, T- 21

Task performed:

Parts

Quantity

101260001291686 GRAB RAIL FT

8



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V3104

In Date: 06/22/2006

Meter Reading:

Close Date: 06/30/2006

Problem?

REPAIR RRI TIRE T-21 (CALLAGHAN)

Task performed:

Parts

Quantity

NO PARTS USED

Vendor?: VC-15214

Workorder: V3744

In Date: 08/02/2006

Meter Reading:

Close Date: 08/08/2006

Problem?

low beam passanger head light out. t21

Task performed:

Parts

Quantity

H4656USE CV TYPE HEAD LIGHT

2

Workorder: V3795

In Date: 08/06/2006

Meter Reading:

Close Date: 08/11/2006

Problem?

missing 1 wheel chock T21

Task performed:

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

* FREIGHLINER TANKER TRUCK

Workorder: V3956

In Date: 08/16/2006

Meter Reading: 24,107.00

Close Date: 08/31/2006

Problem?

B INSPECTION AND REPAIRS AS NESS T21

Task performed:

NEW BACK UP CAMERA ORDERED INSTALL WHEN PART ARIVES

Parts	Quantity
05-17223-000CAP RADIATOR 10 LB	1
210661-1XBEARING KIT	1
2P/50BELT	1
301-506GAUGE FUEL BRUSH USE 301-105	1
35200-RLIGHT MARKER LED RED	2
5008414CARTRIDGE DC100	1
54-15 31-15 WIPER BLADE	2
6140261402 SCREEN SUCTION 5"	2
91388906 VALVE KIT 2.5 IN AKRON	1
91513AMBER LENS	1
9530BELT	3
A0631087000CABLE BATT. POS.	1
A0631088000CABLE BATT. NEG.	1
CV320HXL CAMERA SYSTEM W/50 CABLE	1
CVM600MONITOR 6 IN	1
HP-31DBATTERY 950CCA HP-31D	4
MISC PARTMISC PART	1
PH7405 51971 OIL FILTER WIX	2
60R00FRR600 SERIES RED LED W/O FLANGE	4
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
CA3990AIR FILTER 46883	1
P1147GFUEL FILTER 33120 WIX DELCO TP916	1
BPR6ESSPARK PLUG 7131	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1

Workorder: V3983

In Date: 08/17/2006

Meter Reading:

Close Date: 09/08/2006

Problem?

REPLACE FRONT TIRES AT SHOP CALLAGHAN ENT

Task performed:

Parts	Quantity
NO PARTS USED	

Vendor?: VC-15214



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V4262

In Date: 09/05/2006
Close Date: 09/25/2006

Meter Reading: 24,123.00

Problem?

AIR HOSE/AIR CHUCK NEED REPLACING, T-21

Task performed:

1. TRAVELED TO STN 21 FOUND OUT WHAT FITTING ARE ON TRUCK FOR HOSE CONNECTION.
2. ROLL OUT 30' HOSE- CRIMP ENDS AND "MAKE UP HOSE".
3. TRAVELED TO STN 21 DROP OFF HOSE AND CHUCK.

Parts

Quantity

1654-8FERRULE .718	1
605-2HOSE END-FEMALE	1
S506USE 501 GAUGE AIR	1
S777COUPLING NIPPLE	2

Workorder: V5230

In Date: 11/03/2006
Close Date: 11/03/2006

Meter Reading: 24,804.00

Problem?

COMP OPEN WARNING LT GOING OFF WHILE DRIVING T21

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V5231

In Date: 11/03/2006
Close Date: 11/08/2006

Meter Reading: 24,804.00

Problem?

COMP WARNING LT GOING OFF WHILE DRIVING

Task performed:

1. REPLACE REAR DOOR SWITCHES
2. REPAIR SHORTS IN REAR DOOR SWITCHES
3. REPAIR SHORTS IN REAR DOOR SWITCH HARNESS

Parts

Quantity

52-624SWITCH DOOR	4
-------------------	---

Workorder: V5384

In Date: 11/14/2006
Close Date: 11/20/2006

Meter Reading: 15,090.00

Problem?

Amber warning light on drivers side cab roof light bar OOS. T21

Task performed:

1. replace bulb in front light bar

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

* FREIGHLINER TANKER TRUCK

Workorder: V5549

In Date: 11/27/2006

Meter Reading: 24,804.00

Close Date: 12/07/2006

Problem?

REPLACE BAD NODE T21

Task performed:

1. TRAVELED TO STN 21. INSTALLED NODE, TEST/OK.

Parts

104434PDM MODULE

Quantity

1

Workorder: V5772

In Date: 12/11/2006

Meter Reading: 25,543.00

Close Date: 12/13/2006

Problem?

BRAKE LIGHTS ON DRIVER SIDE INOP, T-21

Task performed:

1. On call no tail lights shorted node.
2. Drive to station R&R node and checked wiring.
3. Drive to station traced and repaired wiring to node.

Parts

NO PARTS USED

Quantity

Workorder: V6107

In Date: 01/04/2007

Meter Reading: 1,179.00

Close Date: 01/30/2007

Problem?

severe frontend hop at 40 mph r21

Task performed:

1. TRAVELED TO STN 21. TEST DROVE AND CHECKED FRONT END SHOCK BAD.
2. DRIVE TO STA INSTALLED SHOCKS FOR FRONT TEST DRIVE OK.

Parts

1012032002FRONT SHOCKS TANKER 21

Quantity

2

Workorder: V7437

In Date: 03/30/2007

Meter Reading: 1,663.50

Close Date: 04/06/2007

Problem?

tender 21 needs new rear tires

Task performed:

Drivr to station. Checked tires needs 4 rear tires. Called Ed about tires

Parts

NO PARTS USED

Quantity



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V7466

In Date: 04/02/2007 Meter Reading: 27,738.00
Close Date: 04/18/2007

Problem?

replace 4 tires on rear-most axle (outside agency-callaghan tire)

Task performed:

Replaced 4 tires on rear most axle Callaghan Ent

Parts

NO PARTS USED

Quantity

Vendor?: CALLAGHAN ENT

Workorder: V7735

In Date: 04/16/2007 Meter Reading: 28,047.00
Close Date: 04/23/2007

Problem?

air leak in cab T21

Task performed:

Air leaking from park brake switch; replaced switch
Order air valve from parts room; truck came in on
4/19/07 for repairs @ shop.

Parts

FSC17492134NC SW PARK BK SPADE TYPE CONNECTOR

1

Quantity

Workorder: V7741

In Date: 04/16/2007 Meter Reading: 1,702.00
Close Date: 04/30/2007

Problem?

LEFT HANDLIGHT CHARGER IN DRIVER COMPARTMENT DOES NOT SEEM TO BE CHARGING PROPERLY. t21

Task performed:

At shop

Parts

NO PARTS USED

Quantity

Workorder: V9296

In Date: 07/13/2007 Meter Reading: 1,819.00
Close Date: 07/19/2007

Problem?

Belts may need to be tightened under the hood. Belts screech intermittently while driving. R21

Task performed:

1. DRIVE TO STA. TIGHTEN BOTH A/C BELTS.
TEST-OK.

Parts

NO PARTS USED

Quantity



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V9525

In Date: 07/24/2007

Meter Reading: 1,823.00

Close Date: 07/30/2007

Problem?

warning light turns on and off on the center computer console. Voltage meter reading 11 while tender is in operation. T21

Task performed:

1. DRIVE TO STA. BELT LOOSE. ADJUSTED. CHECK VOLTS- 14.2. TEST- OK.

Parts

Quantity

1141BULB

10

39437933943793 LINK ADJ A/C COMP

1

3945207BOLT ADJ A/C COMP

1

Workorder: V9632

In Date: 07/30/2007

Meter Reading: 1,840.00

Close Date: 08/07/2007

Problem?

clamp that holds radiator hose up is broken. t21

Task performed:

installed clamps on rad hose

Parts

Quantity

NO PARTS USED

Workorder: V9691

In Date: 08/02/2007

Meter Reading: 30,685.00

Close Date: 08/08/2007

Problem?

OUTLET COVER BROKEN SIDE OF BATTERY BOX T21

Task performed:

replace cover on side-tested ok

Parts

Quantity

091-3YWCOVER KUSSMAUL AUTO EJECT

1

Workorder: V9746

In Date: 08/07/2007

Meter Reading: 30,685.00

Close Date: 08/08/2007

Problem?

repair comp door t21

Task performed:

mount bracket for rear door

Parts

Quantity

16301BALL STUD

1



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V9806

In Date: 08/09/2007

Meter Reading: 30,993.00

Close Date: 08/14/2007

Problem?

repair float pump t21

Task performed:

Parts

Quantity

Repair float pump - Regan's Small Eng

NO PARTS USED

Vendor?: REGANS SM ENG

Workorder: V9872

In Date: 08/13/2007

Meter Reading: 30,993.00

Close Date: 09/12/2007

Problem?

flat repair t 21

Task performed:

Parts

Quantity

Flat repair - Callaghan

NO PARTS USED

Vendor?: CALLAGHAN



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142546

* FREIGHTLINER TANKER TRUCK

Workorder: V11602

In Date: 11/14/2007

Meter Reading: 33,080.00

Close Date: 12/03/2007

Problem?

B inspection and repairs as needed t21

Task performed:

- B-Inspection
 - 11/20/07 5.0 hrs
 - 11/21/07 3.0 hrs Total 8.0 hrs
- 2. Physical - Hope Clinic
- 3. Trans svc; filter/fluid
- 4. Coolant svc
- 5.. Replcd (2) swtch c vrs; (ripped/Tom)
- 6. Replc rubber button cvr for air horn on pump panel
- 7. Batry failed load test; R/R & cln term; replc holdwn & cln rails frm sand
- 8. Exh band clmp brkn; R/R/ w/new clamp
- 9. Drive Shft han ger bearing brokn; ness to R/R D-shaft & replc bearing
- 10. Svc P.S, filter/fluid
- 11. Rebuilt primer pump valve
- 12. Replc pump ovrheaet light lenses (2)
- 13. Exh bank clmp brkn; ness to R/R/ w/new clamp
- Handlight wont charge; ness to trace power supply & replc fuse holder
- 14. Pressure cln eng comp
- 15. Fab upper rad & cooler hose support w/clamps
- 16. Alt & A/C belt R/R & tighten fan belts
- 17. R-F siren drvr inop; ness to R/R on frnt bumper
- 18. Adj Right Rear door opn light swtch & test drive j

Parts

Quantity

02036273300 TURBO94 CORNERLINEAR REFLECTOR	1
20S-500EXHAUST CLAMP 33225 5 IN	1
210661-1XBEARING KIT	1
25-358SWITCH COVER	1
29526898 29548988 TRANS FILTER ALLISON	1
2P/50BELT	1
8126482-2106 TOGGLE GUARD	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
CA3990AIR FILTER 46883	1
FG83284DFG/HF6238 PS/HDY FILTER	1
HP-31DBATTERY 950CCA HP-31D	4
P1147GFUEL FILTER 33120 WIX DELCO TP916	1
PH7405 51971 OIL FILTER WIX	2
PVG-KITORING KIT	1
S260291006M2359 LENS RED	2
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
SD-210RXSIREN DRIVER SMALL	1

Workorder: V6868

In Date: 02/21/2007

Meter Reading: 26,727.00

Close Date: 12/10/2007

Problem?

REPLACE SEVERAL HOSE GASKETS T21

Task performed:

Parts

Quantity

0714021GASKET 2 1/2"	6
0714025GASKET 4.5 IN	4
071704214035 GASKET 1 1/2	10
REDG6S14023 GASKET 6 IN	4



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V11842

In Date: 11/30/2007

Meter Reading: 1,979.00

Close Date: 12/18/2007

Problem?

missing rescue rope with bag T21

Task performed:

Parts

Quantity

1. Contacted Batt Chief

NO PARTS USED

Workorder: V12220

In Date: 12/26/2007

Meter Reading: 33,284.00

Close Date: 12/26/2007

Problem?

driver states parking brake came on while pulling out T21

Task performed:

Parts

Quantity

Drive to Stn21; chk truck for air leaks; chk brake adjustment, smoke, application, air guage 5-10PSI per application; test drive; ret to svc; NPF. j

NO PARTS USED

Workorder: V7694

In Date: 04/13/2007

Meter Reading: 1,702.00

Close Date: 01/14/2008

Problem?

AIR LEAK WHEN THE PARKING BRAKE IS RELEASED. ALSO, LIGHT IN CAB ALONG DRIVER SIDE A AND B POST HANGIN DOWN.

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V12423

In Date: 01/07/2008

Meter Reading: 1,991.10

Close Date: 01/24/2008

Problem?

2/step lights in rear out. T21

Task performed:

Parts

Quantity

1. Drive to Sta. R/R step light, test OK.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

* FREIGHLINER TANKER TRUCK

Workorder: V12515

In Date: 01/11/2008

Meter Reading:

Close Date: 01/24/2008

Problem?

PLASTIC LINE TO GUAGES CRACKED AND LEAKING T21

Task performed:

Parts

Quantity

- 1. Replace plug in tank fill.

NO PARTS USED

Workorder: V12604

In Date: 01/15/2008

Meter Reading: 34,158.00

Close Date: 01/31/2008

Problem?

float a pump/loose throttle cable t21

Task performed:

Parts

Quantity

- 1. Drive to Stn21
- 2. Tighten throttle cable j

NO PARTS USED

Workorder: V199

In Date: 02/05/2008

Meter Reading: 34,530.00

Close Date: 02/07/2008

Problem?

SEVICE GENERATOR, A INSPECTION, CHECK BATTERY ON FRONT OF TRAILER

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V13322

In Date: 02/18/2008

Meter Reading:

Close Date: 02/19/2008

Problem?

hose bed cover needs to be replaced. need cover for 2.5 floto pump in left rear comp. vents in all comp. allow dust in. open door alarm not working on R/SIDE. T21

Task performed:

Parts

Quantity

- 1. Remove vent plates to all 4 compartments, turn plates upright to vent properly. (Modify all 4 plates to match existing screw holes in body frame)

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V13218

In Date: 02/13/2008

Meter Reading:

Close Date: 02/21/2008

Problem?

r-side drain leaking approx. 5 gal./ min. t21

Task performed:

Parts

Quantity

1. Check truck, tank leaking on passenger side in front approximately 1/2 way up.

NO PARTS USED

Workorder: V13374

In Date: 02/20/2008

Meter Reading: 34,530.00

Close Date: 02/22/2008

Problem?

remove hose and bed for tank repair

Task performed:

Parts

Quantity

1. Remove hose and stack

1A. Remove hose and stack

2. Remove hose bed for access to repair water tank, Empty tank

2A. Remove hose bed for access to repair water tank, Empty tank

3. Assist tank repair tech with repositioning tank and removing water at bottom of tank, fill tank and test

4. Install hose bed and warning light protectors. Replace warning light lens

4A. Install hose bed and warning light protectors. Replace warning light lens

6811813493LENS CLEAR 68-1181349-3

1

Workorder: V13637

In Date: 03/03/2008

Meter Reading: 34,643.00

Close Date: 03/03/2008

Problem?

ON CALL T21 NO PUMP AND LIGHTING FUNCTIONS WORKING

Task performed:

Parts

Quantity

Travel to Stn21; chk electrical problem; locate/rep poor conn on PDM in pump panel; resecure PDM in rear of pump panel; replce bad converter in conn cable; fnd water in PDM & cleanout water & reseal unit.

DT043PP007DEUTSCH RECEPTACLE

1

j



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

* FREIGHTLINER TANKER TRUCK

Workorder: V13595

In Date: 02/29/2008

Meter Reading: 34,643.00

Close Date: 03/06/2008

Problem?

MOUNT NOZZEL HOLDERS T21

Task performed:

Parts

Quantity

1. Drive to station, installed 4 brackets to L-1 compartment to hold nozzel on T21

NO PARTS USED

Workorder: V13898

In Date: 03/14/2008

Meter Reading: 34,908.00

Close Date: 03/26/2008

Problem?

replace rear tires t21 4 caps

Task performed:

Parts

Quantity

Replace rear tires T21, 4 caps. Callaghan j

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V13219

In Date: 02/13/2008

Meter Reading:

Close Date: 04/07/2008

Problem?

need to get measured for a hose bed tarp.also i need a cover for my 2.5 floto pump. i retire 6/30/08 guys, how bout some crome hub caps/nut covers for old faithful. all help appreciated. thanks ron j.

Task performed:

Parts

Quantity

1. repaired on b inspection

NO PARTS USED

Workorder: V13370

In Date: 02/20/2008

Meter Reading: 34,530.00

Close Date: 06/17/2008

Problem?

replace hose bed cover t21 central auto trim

Task performed:

Parts

Quantity

Replace hose bed cover T21 - Central Auto Trim

NO PARTS USED

j

Vendor?: CENTRAL AUTO TRIM



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

* FREIGHLINER TANKER TRUCK

Workorder: V15933

In Date: 06/23/2008

Meter Reading: 36,718.00

Close Date: 07/11/2008

Problem?

LEFT REAR FENDERWELL INSIDE ABOVE THE TIRES HAS CRACKED AROUND THE EXISTING SHEETMETAL SCREWS AS IS VERY LOOSE AND HANGING. NEEDS MORE SCREWS IN NEW AREA. T21

Task performed:

drive to Stn; installed screw; test ok. j

Parts

NO PARTS USED

Quantity

Workorder: V17388

In Date: 08/29/2008

Meter Reading:

Close Date: 09/23/2008

Problem?

interior cab "deck gun not stowed" light keeps coming on and now stays on. T21

Task performed:

Check at station; could not repair at station; had to bring to shop & repair. j

Parts

NO PARTS USED

Quantity

Workorder: V17521

In Date: 09/05/2008

Meter Reading: 37,814.70

Close Date: 09/29/2008

Problem?

repair electrical problem t21

Task performed:

1. Traced & rep connector problems & water intrusion at nodes & 3-way connections at rear of truck & in pump hose.
2. Traced electrical problem to faulty connection at node.

Parts

DT043PP007DEUTSCH RECEPTACLE

Quantity

1

Workorder: V17485

In Date: 09/03/2008

Meter Reading: 37,814.70

Close Date: 09/30/2008

Problem?

spare battery charger for the on board tic doesn't charge. missing terminal. also the emergency light on the right side of the engine between the front and rear door , only half the lights are blinking. t21

Task performed:

R & R TIC Charger, need replacement from shop.

Parts

50R03ZRRLIGHT 500 TIR LED

Quantity

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

* FREIGHLINER TANKER TRUCK

Workorder: V17628

In Date: 09/10/2008

Meter Reading:

Close Date: 09/30/2008

Problem?

CLEARANCE LITE UPPER RIGHT REAR OUT. T21

Task performed:

Drive to stn; installed light; test ok. j

Parts

Quantity

372000084MARKER LIGHT

1

Workorder: V18261

In Date: 10/10/2008

Meter Reading:

Close Date: 10/14/2008

Problem?

STROBE LIGHT LEFT CONER OF LIGHT BAR OUT.INNER FINDER LEFT REAR LOSE . MISSING SCREWS AND BROKEN METAL. t21

Task performed:

1-Drive to sta, R/R trouble light drill tap screw in fender well. test ok.

Parts

Quantity

NO PARTS USED

Workorder: V18395

In Date: 10/17/2008

Meter Reading:

Close Date: 10/24/2008

Problem?

left light marker blown bulb t21

Task performed:

1. Drive to Stn; chk tires; called Ed to have replaced; need lens for marker.

2. Drive to Stn; replcd light and lens; test ok. j

Parts

Quantity

B-1103A1131 LENS (AMBER)

2



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

* FREIGHTLINER TANKER TRUCK

Workorder: V18520

In Date: 10/22/2008

Meter Reading: 38,389.30

Close Date: 12/04/2008

Problem?

C INSPECTION AND REPAIRS AS NEEDED T21

Task performed:

1. C-Inspection
2. Svc T-Case
3. Svc rear axles.
4. Rebuilt air dryer & svc filter.
5. Lube/ajd linkage on L1 doors; lube all compt doors.
6. Replcd both frt signals on hood; melted side light.
7. Rem/ordered charge air cooler hose; installed new hose.
8. Rem LR wheels & sec inner fended well.
9. Replc all body holdopens; rep deck gun up light.
10. Lube all valve handles & assist w/valve rebuilding; revac; tested; passes.
11. Replc master drain valve.
12. Meetings w/Tim & Chf Southard.
13. T-shoot & dia compt lights & door ajar ckt; installed new Class 1 module & remnted; chkd sys.
14. Rem trans cooler measure for new cooler; installed cooler.
15. Performed NFPA electrical sys test & make repairs. cind cable connections; replcd alt; replcd solenoid for hose reel; replc btry swtch.
16. Replcd btry swtch; had to enlarge mntng hole to fit swtch.
17. Cind/sec all btry cables.
18. Replc alt.
19. Replcd hose reel solenoid.
20. Rem oil pan & replc gskt.
21. Chk frnt excessive play in frnt _____; not enough to remove hubs.
22. Replcd rad cap & test cooling sys.
23. Cind/tightened loose oil fill hose.
24. Rebuilt primer control valve.
25. Rebuilt (3) Akron valves that were leaking.
26. T-shoot rear compt lights.
27. Assisted w/NFPA electrical sys chk.(Reines) j

Parts

Quantity

Parts	Quantity
01-27041-000AIR COOLER HOSE	1
05-17223-000CAP RADIATOR 10 LB	1
104961MASTER DRAIN VALVE	1
2352227923539104 OIL PAN GASKETERIES 60	1
2P/50BELT	1
5008414CARTRIDGE DC100	1
52-624SWITCH DOOR	2
6808200020LIGHT ASSY. TURN SIGNAL	2
BPR6ESSPARK PLUG 7131	2
CA3990AIR FILTER 46883	1
EAA-8350-30UGSS1783UQ STRUT-LIFT	6
EXO3AH00015SPLUG RAD. DRAIN	1
FREIGHTSHIPPING CHARGES	1
P1147GFUEL FILTER 33120 WIX DELCO TP916	1
PH7405 51971 OIL FILTER WIX	1
R950013TURBO CUT OFF VLV KIT	1
R950014PURGE VALVE WABCO AIR DRYER	1
SS598STARTER SOLENOID FORD TYPE	1
15W40BSYN OIL BULK QTS	40
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
16302RETAINER CLIP	6
75908SWITCH BATTERY MASTER 300A	1
91388906 VALVE KIT 2.5 IN AKRON	3
9530BELT	3



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

* **FREIGHLINER TANKER TRUCK**

Workorder: V19428

In Date: 12/01/2008

Meter Reading:

Close Date: 01/02/2009

Problem?

check engine light stays on T-21

Task performed:

1. Drive to Stn; chk eng code; coolant low pressure; chk eng-fnd reservoir leaking; take apart; order parts.
 2. Drive to Stn; installed new reservoir; test drive & pressure chk; fnd leak at trans cooler; repair; test ok.
- j

Parts

Quantity

A05-23574-000SURG TANK TANKER

1

ALA00350-50 EXTENDED LIFE COOLANT GAL

4

Workorder: V19622

In Date: 12/09/2008

Meter Reading: 38,811.70

Close Date: 01/02/2009

Problem?

repair electrical problem and deck gun valve t21

Task performed:

1. Pump not working; fnd electrical short in wiring; replcd connector splitter; rem wiring harness; diss/replc pin connectors; reinstalled wiring; ck opn; ck ok.
 2. Deck gun valve leaking; rem linkage, deck gun stand, pipe asy, rusted flange bolts & valve; rebuilt valve; replcd flange bolts; reinstalled all parts; ran; ck for leaks; ck ok.
- j

Parts

Quantity

91398907 VALVE KIT 3 IN AKRON

1

DT043PP007DEUTSCH RECEPTACLE

1

Workorder: V18390

In Date: 10/17/2008

Meter Reading: 38,389.30

Close Date: 01/13/2009

Problem?

lace tires on forward rear axle t21

Task performed:

Lace tires on forward rear axle T21 - Callaghan j

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

* FREIGHLINER TANKER TRUCK

Workorder: V20551

In Date: 01/23/2009

Meter Reading:

Close Date: 02/10/2009

Problem?

strobe light on light bar [right coner facing to the back and side]out . fan blade rubbing shroud on radiator. j.g. T21

Task performed:

replc corner strobe in light bar.

2. Adj fan shouud so fan stop rubbing. j

Parts

Quantity

02036273300 TURBO94 CORNERLINEAR REFLECTOR

1

Workorder: V20596

In Date: 01/26/2009

Meter Reading:

Close Date: 02/11/2009

Problem?

NEED HEAD LIGHT BULB FOR TENDER .WHICH HAS A FOUR BULB CONFIGERATION. t21

Task performed:

1- Drive to sta. replace head light test ok.

Parts

Quantity

H4656USE CV TYPE HEAD LIGHT

2

Workorder: V20847

In Date: 02/03/2009

Meter Reading: 39,491.00

Close Date: 02/12/2009

Problem?

deck gun valve leaking t 21

Task performed:

1- Drive to sta. reboild deck gun valve. test ok.

Parts

Quantity

91398907 VALVE KIT 3 IN AKRON

1

Workorder: V20346

In Date: 01/14/2009

Meter Reading: 39,103.00

Close Date: 02/18/2009

Problem?

REPLACE TRANS COOLER T21

Task performed:

R/R trans cooler; drained coolant & refilled; added ATF; adj belts also. j

Parts

Quantity

801846510367-1-5 TRANS COOLER

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V21242

In Date: 02/20/2009

Meter Reading: 39,731.90

Close Date: 02/28/2009

Problem?

O.K. to pump light won't come on T21

Task performed:

drive to Stn; pump transfer case swtch; test ok. j

Parts

NO PARTS USED

Quantity

Workorder: V21915

In Date: 03/18/2009

Meter Reading: 40,209.00

Close Date: 03/23/2009

Problem?

foam fill pump 10-7 t21

Task performed:

1. C/O foam fill pump; fill is ok; pump is locked up; cln up pump from old foam; flush out; reinstall unit; test; fill up foam sys; R/R tri-lock in deck gun well foam and installed fog nozzle.

2. Assist on foam pump repair & tank fill - Meenaghan j

Parts

373-2.5E-Z LOK BRACKET

1

Quantity

Workorder: V22801

In Date: 04/25/2009

Meter Reading: 40,933.90

Close Date: 05/04/2009

Problem?

pedal for air horn on tender 21 is inoperable.

Task performed:

drive to Stn; fnd bad grnd at swtch; rep; test ok. j

Parts

NO PARTS USED

Quantity

Workorder: V24399

In Date: 06/27/2009

Meter Reading: 2,514.40

Close Date: 07/16/2009

Problem?

seal on dump discharge leaks T21

Task performed:

Drive to Stn; rework seal; test ok. j

Parts

NO PARTS USED

Quantity



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142546

* **FREIGHLINER TANKER TRUCK**

Workorder: V24633

In Date: 07/08/2009

Meter Reading: 42,022.00

Close Date: 07/22/2009

Problem?

B INSPECTION AND REPAIRS AS NEEDED T21

Task performed:

- B-Inspection
- 2. Replcd all (4) btrys & jumper cables; clnd all term ends; R/R R-side cab step to access frame connections & clnd all.
- 3. Took oil sample for oil analysis.
- 4. Svc T-case.
- 5. Replc btry charger cover & reinstalled cab stp asy on dri ver's side of truck.
- 6. Replcd brake shoes; drums & hardware on rear, rear, drive axle.
- 7. Replcd wiper blades.
- 8. Painted fuel tank cap.
- 9. Replcd cab roof marker light bulb.
- 10. Replcd flag stickers (faded)
- 11. T-shoot no charge condition; replcd alt; adj eng idle to 650 RPMs for optimum alt output; also traced volt dorps to console; read out in cab;e load tested btrys & chkd for volt drop in btry switch.
- 12. Cln shop & floor after PM svc.
- 13. Tracked down & installed dome lights in cab.
- 14. Reattached under hood insulation (falling off).
- 15. T-shoot water leak at rear drain chute. clnd drain chute door & flange & ordered new door.
- 16. Seal/installed rear chute asy; filled tank; ck for leaks; ck ok.
- 17. Assist install rear water chute. j

Parts

Quantity

091-3YWCOVER KUSSMAUL AUTO EJECT	1
15W40BSYN OIL BULK QTS	40
211-2BULB	2
3576REAR BRAKE DRUMS	2
54-15 31-15 WIPER BLADE	2
680-10LAMERICAN FLAG W UV CLEAR LEFT	1
680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
A0631087000CABLE BATT. POS.	1
AB4515Q685REXP4515Q BRAKE SHOES	4
FREIGHTSHIPPING CHARGES	1
P1147GFUEL FILTER 33120 WIX DELCO TP916	1
PH7405 51971 OIL FILTER WIX	2
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
T21DUMP VALVE SEAL	1
HP-31DBATTERY 950CCA HP-31D	4
4867JB320 UPGRADE ALTERNATOR	1
A0631088000CABLE BATT. NEG.	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4

Workorder: V24801

In Date: 07/15/2009

Meter Reading: 42,022.00

Close Date: 07/30/2009

Problem?

replace tires rear axle t21 callaghan

Task performed:

Replace tires rear axle t21 - Callaghan j

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V24968

In Date: 07/22/2009

Meter Reading: 42,022.00

Close Date: 08/05/2009

Problem?

TAG LIGHT OUT T-21

Task performed:

drive to Stn; bad ground wire; rework; tested ok. j

Parts

NO PARTS USED

Quantity

Workorder: V25516

In Date: 08/13/2009

Meter Reading: 42,373.50

Close Date: 08/17/2009

Problem?

check front tires t21

Task performed:

drive to Stn; order tires for truck; talk w/Ed O. about Elpex, i.e. replcd tires. j

Parts

NO PARTS USED

Quantity

Workorder: V25529

In Date: 08/14/2009

Meter Reading: 42,373.50

Close Date: 08/26/2009

Problem?

REPLACE FRONT TIRES, T-21 ELPEX

Task performed:

replace fro nt tires T21 - Tiresoles j

Parts

NO PARTS USED

Quantity

Vendor?: TIRESOLES

Workorder: V26131

In Date: 09/09/2009

Meter Reading: 42,501.00

Close Date: 09/15/2009

Problem?

2 lenses cracked T-21

Task performed:

drive to stn; replaced lens with DNI parts. j

Parts

6811802645S68-1180264-5S LENS RED

6811813495LENS-RED 68-1181349-5

901000RUSTROBE 900 RED

TURBO5TUBE - STROBE

Quantity

1

1

1

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V27343

In Date: 11/02/2009

Meter Reading: 38,389.30

Close Date: 11/02/2009

Problem?

one part not charged on original wo 18520 nb

Task performed:

Parts

Quantity

104434PDM MODULE

1

Workorder: V26640

In Date: 10/02/2009

Meter Reading:

Close Date: 11/05/2009

Problem?

scene light len's missing on light on left side at rear. T21

Task performed:

Parts

Quantity

Drive to Stn; replcd lens; test ok. j

6811813493LENS CLEAR 68-1181349-3

5

6811813635S68-1181363-5S LENS RED 64 SERIES

3

Workorder: V25123

In Date: 07/28/2009

Meter Reading: 42,022.00

Close Date: 12/03/2009

Problem?

rear dump leaking (parts only) T21

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V29379

In Date: 01/24/2010

Meter Reading:

Close Date: 02/08/2010

Problem?

#2 discharge leaking at first set of bolts going towards pump. Will make it almost impossible to draft. T21

Task performed:

Parts

Quantity

Went to Stn21; fnd #2 discharge leaking & damaged; went to shop w/truck; rem discharge pipe valve & pump flange; did not have new parts; rem parts frm SBE3; rebuilt valve; assembled parts on tank; ran/ck for leaks; ck ok; let DC3 chief in shop look for keys & nozzle. return home. j

91388906 VALVE KIT 2.5 IN AKRON

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

* **FREIGHLINER TANKER TRUCK**

Workorder: V30182

In Date: 02/23/2010

Meter Reading: 44,554.00

Close Date: 02/23/2010

Problem?

replace bulb parts only t21

Task performed:

Cln connection in light & put back together. j

Parts

Quantity

1156BULB

1

Workorder: V30680

In Date: 03/12/2010

Meter Reading: 44,942.80

Close Date: 03/17/2010

Problem?

Door ajar light on T21 is constantly alarming

Task performed:

1. WENT TO STA 21 FOUND ALARM GOING OFF CLEANED AND DRIED CONNECTIONS AT COMMUNICATION CABLES IN PUMP PANEL R&R CAB DOOR SWITCHES REMOVE PANEL RT REAR COMPT. FOUND DOOR SWITCH WITH SOCKET SHORTED R&R SOCKET CHECK OPERATION NPF

Parts

Quantity

52-624SWITCH DOOR

1

Workorder: V29976

In Date: 02/15/2010

Meter Reading: 44,417.70

Close Date: 03/18/2010

Problem?

light on right side of the truck above steamer is out.(right light) T21

Task performed:

Fnd right pump panel light out; R/R bulb; ck ok. j

Parts

Quantity

NO PARTS USED

Workorder: V30736

In Date: 03/15/2010

Meter Reading: 45,008.00

Close Date: 03/19/2010

Problem?

T21 door ajar light stuck on

Task performed:

1. went to 21 found alarm going off cleaned and dried connections at power modual and also in pump panel recheck npf
2.installed new air pack brakets on truck had to cut off bolts

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

* FREIGHLINER TANKER TRUCK

Workorder: V29977

In Date: 02/15/2010

Meter Reading: 44,417.70

Close Date: 03/22/2010

Problem?

Black foam strip on portable tank door is peeling off.T21

Task performed:

1. Need flat foam; rem old foam frm ladder compr; replc seal; ck ok.
2. Fnd lenses brkn; R/R rt/tail, L/frnt bumper & rt/frt bumper lenses; ck ok. j

Parts

68118358150600 SER OPTIC RED

Quantity

3

Workorder: V30333

In Date: 03/01/2010

Meter Reading: 44,732.50

Close Date: 03/24/2010

Problem?

door ajar light intermittently comes on and off. jg T21

Task performed:

- Went to Stn21; all trcks on a brush fire; fnd door ajar alarm & lite on all the time; ck; clnd/dried "Y" connectors & clnd/dried connections at nodes; ck opn; ck ok. j

Parts

NO PARTS USED

Quantity

Workorder: V30505

In Date: 03/06/2010

Meter Reading: 44,825.00

Close Date: 04/20/2010

Problem?

Check valves leaks, rear discharge and deck gun. unable to pass dry vaccum test.T21

Task performed:

- Ck for door ajar going off; R/R (3) door switches on L-1 & R-1 compt; ck opn; ck ok. j

Parts

52-624SWITCH DOOR

Quantity

3

Workorder: V32508

In Date: 05/28/2010

Meter Reading: 45,349.00

Close Date: 06/11/2010

Problem?

low voltage reading on the pump panel display. (LOW) charging and running at 12 volts T21

Task performed:

- Went to 21 from turnpike & PGA Blvd; fnd alt not charging; load test btry; btry ok; R/R alt fan & chk ok. j

Parts

4867JB320 UPGRADE ALTERNATOR

Quantity

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V29392

In Date: 01/25/2010

Meter Reading: 44,025.60

Close Date: 07/08/2010

Problem?

parts only for on call repair t21

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V33596

In Date: 07/17/2010

Meter Reading: 46,366.00

Close Date: 07/23/2010

Problem?

drivers side rear veiw mirror broken T21

Task performed:

Parts

Quantity

R/R L/side driver's mirror; brkn off, got new one installed. j

16093MIRROR

1

Workorder: V30839

In Date: 03/18/2010

Meter Reading: 45,096.10

Close Date: 08/04/2010

Problem?

B INSPECTION AND REPAIRS AS NEEDED T21

Task performed:

Parts

Quantity

1. Help with B-Inspection - Flerx
2. B-Inspection
3. R/R master drain valve asy.
4. Get btry tray to slide out; cln/lube trayu/slides.
5. Start t-shoot pump; R/R deck gun, right rear discharge & recirc valves.
6. Tighten/adj comp doors.
7. Rem/rebuild both crosslay valves.
8. Rem drive shaft primer motor & cvr plate to get to tank to pump valve; rem valve & install new one; reinstall cvr, primer motor & drive shaft.
9. Rem/rebuild #1 discharge valve.
10. T-shoot compt door alarm going off; poss module getting wet; install rubber cvr over module.
11. Cut off 5' of dry rotted hose reel hose & reinstall fitting & nozzle.
12. Chk for air leaks; replc (2) quick connect fittings on air tank. ja

0773275TRUNION BALL 3 IN

1

104961MASTER DRAIN VALVE

1

8126482-2106 TOGGLE GUARD

1

91368904 VALVE KIT 1 1/2 IN

1

91398907 VALVE KIT 3 IN AKRON

2

CA3990AIR FILTER 46883

1

S153BLOW GUN

1

S777COUPLING NIPPLE

1

S3226FL02FUEL FILTER 33813 L/F # LFF5851

1

P1147GFUEL FILTER 33120 WIX DELCO TP916

1

PH7405 51971 OIL FILTER WIX

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V33828

In Date: 07/27/2010
Close Date: 08/11/2010

Meter Reading: 46,366.00

Problem?

Master intake gauge is not working correctly. Shows 37-42psi when it could be 0 while just in Tank to pump mode. Probably needs to be calibrated, I guess? Master discharge gauge appears to be working good. T21

Task performed:

Went to 21; mov truck; ran pump; fnd intake press wrong; drained pump; R/R suction transducer; ran/ck opn; ck ok. ja

Parts

Quantity

FP4000PT-1TRANSDUCER DISCHARGE DIG. MASTER PU

1

Workorder: V35094

In Date: 09/21/2010
Close Date: 10/05/2010

Meter Reading: 46,996.00

Problem?

NUMBER 3 DISCHARGE APPEARS TO BE BLOCKED WHEN BACK FLUSHING THROUGH THAT DISCHARGE. NUMBER 3 DISCHARGES CORRECTLY WHEN USED AS A DISCHARGE T21

Task performed:

Went to 21; ck #3 discharge - is a foam discharge; ck ok. j

Parts

Quantity

NO PARTS USED

Workorder: V32507

In Date: 05/28/2010
Close Date: 10/19/2010

Meter Reading: 45,349.00

Problem?

Driver door sticks when you try to open the door from the inside. It locked closed twice and I was unable to open the door. t21

Task performed:

Completed j

Parts

Quantity

NO PARTS USED

Workorder: V35920

In Date: 10/26/2010
Close Date: 11/03/2010

Meter Reading: 47,200.00

Problem?

repair loose panel on rear of unit t21

Task performed:

Rattling noise - loose panel L-5; replc msng & stripped screws. j

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

* FREIGHLINER TANKER TRUCK

Workorder: V32749

In Date: 06/08/2010
Close Date: 11/08/2010

Meter Reading: 45,872.00

Problem?

mount #plates T21

Task performed:

Went to 21; installed plate mnts; installed numbers on plates. j

Parts

NO PARTS USED

Quantity

Workorder: V33311

In Date: 07/03/2010
Close Date: 11/08/2010

Meter Reading: 46,211.90

Problem?

Hose adapter holder on rear tail board broken T21

Task performed:

Went to Stn21; replc brkn E-Z locks. j

Parts

NO PARTS USED

Quantity

Workorder: V36234

In Date: 11/06/2010
Close Date: 12/01/2010

Meter Reading: 47,507.40

Problem?

light in leftside of light bar next to white light's.out light on top row driver's side out.jg T21

Task performed:

Travel to stn; strobe inop front light bar; replc bulb. j

Parts

7ELTUBE7ELTUBE LINEAR STROBE REF

Quantity

1

Workorder: V36432

In Date: 11/15/2010
Close Date: 12/07/2010

Meter Reading: 47,646.20

Problem?

fill cap for top of water tank missing. T21

Task performed:

1. Travel to stn; Wtr tank cvr msng; will order new one; needs to get info on tank.
2. L/R spot inop replc bulb. j

Parts

44364436 BULB

Quantity

1



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142546

* **FREIGHTLINER TANKER TRUCK**

Workorder: V36709

In Date: 11/29/2010

Meter Reading: 47,691.90

Close Date: 12/21/2010

Problem?

C INSPECTION AND REPAIRS AS NEEDED T21

Task performed:

Parts

Quantity



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142546

* FREIGHLINER TANKER TRUCK

- (1) "C" INSPECTION AND REPAIRS AS NEEDED ON T21.
- (1) "C" INSPECTION.
- (2) SERVICED & TESTED BATTERIES. CLEANED CABLES & BATTERY COMPARTMENT.
- (3) AIR ALL 10 TIRES TO PROPER PSI.
- (4) SECURE LOOSE HOSE & COVERING R SIDE OF MOTOR.
- (5) SERVICE T-CASE.
- (6) COOLANT SERVICED.
- (7) SERVICE DRYER. REMOVED FROZEN BOLTS FROM FRAME. REPLACED TURBO & PURGE VALVES. CHECKED FOR LEAKS,NOTED PURGE VALVE LEAKING. DRAIN AIR PRESSURE,REMOVED & REINSTALLED PURGE VALVE, CHECKED FOR LEAKS. NO LEAKS DETECTED.
- (8) PROTECT AIR LINESRUBBING ON THE FRAME.
- (9) REPLACED ALT BELT.
- (10) TRANSMISSION SERVICE.
- (11) REPLACED FAN BELT.
- (12) REPAIRED GROUND CONNECTION FOR PUMP PANEL LIGHT.
- (13) DIAGNOSED R-3 COMPT LIGHT 10-7 FROM 1ST DOOR. FOUND A BAD SWITCH. REPLACED SWITCH & LENS.
- (14) REMOVED DASH PANEL & REPOSITIONED RETARTER SWITCH.
- (15) SECURE LEFT FRT MARKER LIGHT POLE. ADJ HEIGHT.
- (16) REPLACED FOAM FILL PLUG CABLE WITH WRONG CABLE SIZE, WRONG CRIMP SIZE & NO CRIMP TOOL.
- (17) REMOVED NAIL FROM RF & CHECKED FOR LEAKS. OK.
- (18) REPLACED BRAKES ON 1ST REAR AXLE.
- (19) TIGHTENED LOOSE MUD FLAP FRAME BOLTS.
- (20) TIGHTENED LOOSE BRACKET BOLTS UNDER P/S RESERVOIR.
- (21) TORQUED ALL U BOLTS.
- (22) DIAGNOSED AIR LEAK IN UPS. REBUILTUPS & REPLACED FITTINGS.
- (23) DIAGNOSED PROBLEM WITH PURGE VALVE CYCLING. MAKE UP TEST GUAGE SET. FOUND BAD GOVERNOR. REPLACED WITH NEW ONE.
- (24) FILL AUTO GREASE SYSTEM. REPAIR BROKEN LINE,RT FRT. CYCLE & BLEED SYSTEM. PROTECT & SECURE LINES.
- (25) P/S SERVICE.
- (26) GLUED ENGINE HOOD INSULATION TO CAB & MAKE UP LARGE PLASTIC BLOCKS TO ADD WITH NYLON PIN FASTENERS.
- (27) REBUILT INTAKE VALVE.
- (28)CONNECTED LAPTOP & CHECKED TRANS,ABS& ENGINE CODES. ERASED LOW COOLANT CODE

1094KIT-AIR HORN-GROVER	1
15W40BSYN OIL BULK QTS	40
284358GOVERNOR D-2	1
29526898 29548988 TRANS FILTER ALLISON	1
52-624SWITCH DOOR	1
91581CLEAR LENS	1
P1147GFUEL FILTER 33120 WIX DELCO TP916	1
PH7405 51971 OIL FILTER WIX	2
R950013TURBO CUT OFF VLV KIT	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
XG840-KITEXTENDA GUN SWITCH	2
2P/50BELT	1
FG83284DFG/HF6238 PS/HDY FILTER	1
3576REAR BRAKE DRUMS	2
9530BELT	3
AB4515Q685REXP4515Q BRAKE SHOES	4
E-2769MKT4515QB BRAKE KIT	2
5008414CARTRIDGE DC100	1
R950014PURGE VALVE WABCO AIR DRYER	1
5460370530VPS SHIFT KIT 546-0370-53-0	1
91388906 VALVE KIT 2.5 IN AKRON	1
RTBASSYREAR TAIL BRD OUT 91 IN	1



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142546

* **FREIGHLINER TANKER TRUCK**

FROM DOING COOLANT SERVICE.

(29) REPLACED FLASHLIGHT CHARGERS. INSTALLED NEW TYPE . DRILLED NEW HOLES. EXTENDED WIRING, HEAT SHRINK & INSTALLED THROUGH THE GROMMET. REPLACED BLOWN FUSE. TESTED OK.

(30) TIGHTENEE R-2 SHOCK BOLT,L1 SHOCK BOLT, LUBED ALL LATCHES. TIGHTENED HOSE CLAMP BOLTS. DRILLED OUT & THREADED SIDE PANEL TOOL HOLDER & INSTALLED BOLT. TIGHTENED PINCH BAR BOLTS,DRILLED & THREADED L-2 STRIKER BOLT. TIGHTENEDHYDRANT WRENCH HOLDER.

(31) REPLACED EXTENDER - GUN SENSOR & ADJ. SPLICED WIRES, PROTECT & HEAT SHRINK.

(32) INSTALLED ASSET # ON WINDSHIELD.

(33) INSTALLED NEW TAIL BOARD. DRILLED HOLES FOR BOLTS & WIRE HARNESS CLAMPS. THREAD CLAMP BOLTS ,CONNECT ELECTRICAL & HEAT SHRINK CONNECTION. TESTED OK.

(34) CALIBRATED FOAM SYSTEM TO SPECS.

(35) TESTED AIR HORNS-RIGHT SIDE 10-7 WITH FROZEN ADJUSTMENT SCREW. REMOVED HORN & FREE UP FROZEN PARTS. PARTS DEPT CLOSED. NO PARTS.

(35) REASSEMBLED AIR HORN. REPLACED BRASS FITTING. CUT HARNESS TIE STRAP TO GAIN TUBE LENGTH. SECURE/ PROTECT TUBING. ADJ HORN FOR SOUND QUALITY.

(36) PERFORM NFPA BRAKE TEST AT 20MPH. VEHICLE STOPPED IN 15FT WELL WITHIN THE 35FT MAX LIMITS.

(37) INSTALLED A PLUG IN THE DECK GUN GAUGE PORT UNTIL NEW GAUGE COMES IN.
J.W.

Workorder: V37179

In Date: 12/15/2010 **Meter Reading:** 47,691.90
Close Date: 12/29/2010

Problem?

REPLACE DECK GUN GAUGE T21

Task performed:

(1) AT SHOP, REPLACE BROKEN DECK GUN GAUGE ON T21 WITH A NEW ONE THAT HAD BEEN ON ORDER. OK. J.W.

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V37445

In Date: 12/28/2010

Meter Reading: 48,173.00

Close Date: 01/05/2011

Problem?

Right front diamond plate and bumper damage. Need to check for front intake damage. None noted on inspection. T21

Task performed:

Parts

Quantity

(1) TRAVELED TO ST-21 TO CHECK OUT REPAIR NEEDED TO T21. R/F FRONT RIGHT BUMPER. DIAMOND PLATE DAMAGE/ BUMPER. WILL REPAIR ON NEXT TIME T21 IS IN THE SHOP. J.W.

NO PARTS USED

Workorder: V37503

In Date: 12/29/2010

Meter Reading: 48,248.00

Close Date: 02/04/2011

Problem?

need tank lid for water tank t21

Task performed:

Parts

Quantity

Travel to stn; Water tank lid msng; will replc when in for svc. j

NO PARTS USED

Workorder: V38638

In Date: 02/19/2011

Meter Reading: 49,226.20

Close Date: 02/23/2011

Problem?

Emergency Flasher on passenger side just above the 2 rear axles is not flashing it just stays solid red. T21

Task performed:

Parts

Quantity

1. Travel to Stn21 & replc LED light betwn tandems.
2. Assist - Murray. j

60R00FRR600 SERIES RED LED W/O FLANGE

1

Workorder: V37502

In Date: 12/29/2010

Meter Reading: 48,248.00

Close Date: 03/08/2011

Problem?

air leak plz fix t21

Task performed:

Parts

Quantity

(1) TRAVELED TO ST-21 TO REPAIR AIR LEAK ON T21. DIAGNOSED THE LEAK IN THE DASH. REPLACED AIR FITTING. OK. J.W.

223-485V91-8301 85 PSI CLOSED 67 OPEN PREEURE PF

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

* FREIGHLINER TANKER TRUCK

Workorder: V39129

In Date: 03/11/2011

Meter Reading: 49,848.50

Close Date: 03/22/2011

Problem?

left side 21/2 intake no.3 discharge leaking during vacuum test. fanbelts squelling at shift points

Task performed:

Travel to 21; adj belts & chkd valves. j

Parts

Quantity

NO PARTS USED

Workorder: V39209

In Date: 03/15/2011

Meter Reading: 49,909.00

Close Date: 03/25/2011

Problem?

replace tire tiresoles

Task performed:

Replace tire - Tiresoles j

Parts

Quantity

NO PARTS USED

Vendor?: ELPEX

Workorder: V39810

In Date: 04/09/2011

Meter Reading: 50,745.30

Close Date: 04/14/2011

Problem?

T21 Driver's side rear outside dual tire wearing uneven. Light on front light bumper pole out. T21

Task performed:

Bumper pole light bulb 10-7; rem/install new bulb.

Parts

Quantity

NO PARTS USED

600 series LED 60R00FRR 06837195ROB lite asy
needed R/side frnt bumper.

Strainer needs bolt to secure onto asy.

Tires R/R left I-4, O-4

F/R left I8, O8

R/R right I3, O__

R/F right I9, O7



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V39831

In Date: 04/11/2011 Meter Reading: 50,745.30
Close Date: 04/21/2011

Problem?

strode light on right front bumper not working. T21

Task performed:

Replc LED on RF bumper. j

Parts	Quantity
60R00FRR600 SERIES RED LED W/O FLANGE	1

Workorder: V40340

In Date: 05/02/2011 Meter Reading: 51,334.80
Close Date: 05/10/2011

Problem?

Door ajar buzzer on at all times. Checked and rechecked doors. Buzzer still on. No problem with buzzer at truck check this morning.Sta 21.

Task performed:

Travel to Stn21; reconnected buzzer for door alarm; rem all switches; chk harnesses; fnd shorted wire in tank compt; rep wire ok. j

Parts	Quantity
52-624SWITCH DOOR	3

Workorder: V40352

In Date: 05/02/2011 Meter Reading: 51,334.80
Close Date: 05/13/2011

Problem?

Buzzer started again. mech came out after hours. Unable to locate problem. Disconnect buzzer until mech return in the morning. T21

Task performed:

Travel to Stn21; chkd all switches - ok; must have short in wiring; Disconnet buzzard light; travel home. j

Parts	Quantity
NO PARTS USED	

Workorder: V40347

In Date: 05/02/2011 Meter Reading: 51,334.80
Close Date: 05/18/2011

Problem?

REPLACE REAR TIRES AT 21 T 21 TIRESOLES

Task performed:

Replace rear tires at 21, T21 - Elpex j

Parts	Quantity
NO PARTS USED	

Vendor?: ELPEX



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

* FREIGHLINER TANKER TRUCK

Workorder: V40726

In Date: 05/19/2011

Close Date: 05/23/2011

Meter Reading: 51,483.00

Problem?

replace headlight.

Task performed:

L/headlight burnt - replcd. j

Parts

H4656USE CV TYPE HEAD LIGHT

Quantity

1

Workorder: V40757

In Date: 05/20/2011

Close Date: 05/25/2011

Meter Reading: 51,483.00

Problem?

primer leaking water. Sta 21.

Task performed:

Replc o-ring kit in primer handle. j

Parts

PVG-KITORING KIT

Quantity

1

Workorder: V40802

In Date: 05/23/2011

Close Date: 05/25/2011

Meter Reading: 51,804.00

Problem?

leaking water behind pump panel, Sta 21.

Task performed:

Travel to 21; secured wtr line at primer handle. j

Parts

NO PARTS USED

Quantity

Workorder: V40325

In Date: 05/02/2011

Close Date: 05/27/2011

Meter Reading: 51,334.80

Problem?

REPLACE TIRE T21

Task performed:

Replace tire T21 - Tiresoles j

Parts

NO PARTS USED

Quantity

Vendor?: TIRESOLE



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V40878

In Date: 05/26/2011

Meter Reading: 51,949.90

Close Date: 06/01/2011

Problem?

primer pump leaking T21

Task performed:

See repair order W.O. 40948

j

Parts

Quantity

NO PARTS USED

Workorder: V40948

In Date: 05/29/2011

Meter Reading: 51,989.00

Close Date: 06/01/2011

Problem?

Constent leaking underneath the pump T21

Task performed:

Rebuild primer valve.

j

Parts

Quantity

PVG-KITORING KIT

1

Workorder: V41087

In Date: 06/03/2011

Meter Reading: 52,074.00

Close Date: 06/07/2011

Problem?

gover inop t21

Task performed:

Installed new gov in pump panel electronic pump cntrl unit; drill/tap holes.

j

Parts

Quantity

E23519655FIRE COMMAND Q29

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

* **FREIGHLINER TANKER TRUCK**

Workorder: **V41501**

In Date: 06/21/2011

Meter Reading: 52,465.00

Close Date: 06/24/2011

Problem?

lights flickering on pump panel, control panel for pump wont program, scene lights fashing.

Task performed:

1. T-shoot work light/pump panel lights; fnd faulty connections, corroded switch & bad relay; replc all (3) toggle switches for pump panel & scene lights; rewired switches; replc relay & rewired grnd for relay; all lights now working normally.
2. T-shoot command master: cind/sealed all related connectors at panel; reprogram press/RPM presets in cntrl panel.
3. Fnd wtr leak lid msg; rem lid frm another trk; installed lid. j

Parts

Quantity

5582-10 82-2111 GROTE ON-OFF WEATHERPROOF

3

8126482-2106 TOGGLE GUARD

3

87499RY48 RELAY

1

H35SN12BULB

1

Workorder: **V41534**

In Date: 06/22/2011

Meter Reading: 52,542.80

Close Date: 06/30/2011

Problem?

2 trilock brackets broken; 1 rear tailboard, 1 top deckgun, Sta 21.

Task performed:

Travel to 21; installed new trilocks for brkn ones. j

Parts

Quantity

NO PARTS USED

Workorder: **V41603**

In Date: 06/25/2011

Meter Reading: 52,542.80

Close Date: 06/30/2011

Problem?

broken wire found on left side front bumper siren. T 21

Task performed:

Travel to 21; rep brkn wire to siren speaker. j

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V42109

In Date: 07/19/2011
Close Date: 07/20/2011

Meter Reading: 52,978.00

Problem?

Replace tank lid.

Task performed:

REPAIRED TANK LID AK

Parts

Quantity

824-0004TANK LID 12X12

1

Workorder: V42251

In Date: 07/24/2011
Close Date: 07/29/2011

Meter Reading: 53,213.30

Problem?

fan belts slipping.red lens that cover bulb on pump over heat broken T 21

Task performed:

1. Adj fan belts.
 2. Travel to 21; replcd brkn lens on overheat warning.
- j

Parts

Quantity

S260291006M2359 LENS RED

2

Workorder: V42418

In Date: 07/31/2011
Close Date: 08/03/2011

Meter Reading: 22,809.00

Problem?

pry bar holder need to be replace. Left side below pike poles. T21

Task performed:

TRAVEL TO 21 REPAIRED PRY BAR HOLDER AK

Parts

Quantity

NO PARTS USED

Workorder: V42353

In Date: 07/27/2011
Close Date: 08/08/2011

Meter Reading: 53,213.30

Problem?

need cable for tank shute .need a hose for foam tank drain .need a bracket inside the compartment toward front where folding tan is storedto keep tank from getting hungup .need tri lock x2 for mounting auxzilary tank T21

Task performed:

- travel to 21 install ehat cable
- installed angle iron for water tank comp
- installed foam tank drain hose
- truck had call will finish later

Parts

Quantity

UMVS056511STRAP

1

UMVS111611STRAP

1

- travel to 21 install 2 1/2" tri locks of equipment to -- mounted



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V42120

In Date: 07/19/2011

Meter Reading: 53,012.10

Close Date: 08/24/2011

Problem?

T21 UIP missing, needs replaced

Task performed:

told driver to see his dc or capt

Parts

NO PARTS USED

Quantity

Workorder: V42969

In Date: 08/22/2011

Meter Reading: 53,829.80

Close Date: 08/24/2011

Problem?

two small aprx 3" * 1" red reflectors missing from rear bumper t21

Task performed:

travel to 21 replaced reflectors on rear of trauck

Parts

98032R 41032-3 RED REFLECTOR OVAL REFLECTOR

3

Quantity

Workorder: V43571

In Date: 09/10/2011

Meter Reading: 54,228.70

Close Date: 09/14/2011

Problem?

Brake leak notice this morning. Took more than 1 min to fill. Loud noise when brakes are pushed during stopping. It holds the air when pushed, but has loud noise. T21

Task performed:

travel to 21 found air switches leaking replaced switches ok

Parts

FSC17491907NO SWITCH LOW AIR PRESSURE

1

FSC17492134NC SW PARK BK SPADE TYPE CONNECTOR

1

Quantity



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

* FREIGHLINER TANKER TRUCK

Workorder: V43152

In Date: 08/29/2011

Meter Reading: 53,986.00

Close Date: 09/16/2011

Problem?

B INSPECTION AND REPAIRS T 21

Task performed:

B INSPECTION/SERVICE

B SERVICE

DOOR AJAR GOING OFF. HAD TO UNHOOK BUZZER TO BRING TO SHOP. RESET ALL DOOR SWITCHES. CLEANED, DRIED AND LUBED ALL CONNECTORS. CK OK

CK AC NOT COOLING. RECOVER FREAN. R&R O RINGS REMOVED PANELS. CLEANED BLOWER AND E--VAC AND CHARGE A/C . CK OK

ENG LTS INOP. REPAIR POWER WIRE. R&R 2 LTS. CK OK

REINSTALLED DRAIN HOSES AND TIED UP WIRES AT FRT. RT. BUMPER

DASH LIS OUT. REMOVED DASH PANEL. R&R BULBS. CK OK

CK FOR COOLANT LEAKS. PRESS TEST. CK --TORQUE CLAMPS. TOPPED OFF TANK CK OK

DELIVER TRUCK TO STATION

R&R RIGHT SIDE CENTER ANDLEFT SIDE MIDDLE LIGHT BAR STROBE LIGHTS

TIGHTEN ENGINE BELTS

SERVICE BOTH DIFFERENTIALS

Parts

Quantity

1141BULB	4
120257100C2030-7110-30 CLEAR DOME STEP	3
7ELTUBE7ELTUBE LINEAR STROBE REF	2
CA3990AIR FILTER 46883	1
P1147GFUEL FILTER 33120 WIX DELCO TP916	1
PH7405 51971 OIL FILTER WIX	2
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1

Workorder: V43858

In Date: 09/22/2011

Meter Reading: 54,411.70

Close Date: 09/23/2011

Problem?

steering column loose T-42

Task performed:

1.check steering column for looseness, found bolts on sides loose. tighten bolts

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V43988

In Date: 09/28/2011

Meter Reading: 54,450.00

Close Date: 10/03/2011

Problem?

float a pump P700-1843 throttle cable not working correctly. where throttle cable hooks to carb linkage, it is not connected proper Sta 21.

Task performed:

Parts

Quantity

travel to 21 checked float pump found cable for throttle broken will re/as cable none on truck

VCGTX35CABLE THROTTLE 35 FOOT

1

travel to 21 r&r throttle cable on float pump

Workorder: V44446

In Date: 10/17/2011

Meter Reading:

Close Date: 10/20/2011

Problem?

tri lock found not holding gate valve T21

Task performed:

Parts

Quantity

travel to 21 replaced trilock in l1 ompartment

NO PARTS USED

Workorder: V44573

In Date: 10/20/2011

Meter Reading:

Close Date: 10/24/2011

Problem?

compartment and deck gun alarm in cab activates and will not turn off, all comp. and deck gun checked and ok t 21

Task performed:

Parts

Quantity

Went to 21; reset all door switches, cld/dried connectors at modules; ck connections to deckgun; mov gun; ck alarms, chk ok. j

NO PARTS USED

Workorder: V44064

In Date: 10/01/2011

Meter Reading: 54,450.00

Close Date: 11/21/2011

Problem?

air brake leak gauge for the over heat pump is broken T21

Task performed:

Parts

Quantity

1. Travel to 21; chkd for air leak - none fnd.
2. Travel to Stn21; C/O air leaks; fnd on pump panel; rep fittings; rech ok.
3. C/O pump over heat sys wiring, etc; fnd bad sensor; R/R pump sensor. j

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V45357

In Date: 11/22/2011

Meter Reading:

Close Date: 11/30/2011

Problem?

air tanks found at morning check below 20 psi both tanks, sta 21

Task performed:

Parts

Quantity

Repaired air leak at valves; Resealed fittings.bp

NO PARTS USED

Workorder: V46062

In Date: 12/24/2011

Meter Reading: 55,742.00

Close Date: 01/04/2012

Problem?

Parking brake switch leaking when brake is disengaged. I heard a pop when I was driving. When the emergency brake is on the leak stops. Jin "Doc" Fortnash, Sta 21

Task performed:

Parts

Quantity

REPLACED SENSER FOR BRAKE SWITCH, ALSO TRACE OUT 2ND AIR LEAK AND REPAIRED.

FSC17492134NC SW PARK BK SPADE TYPE CONNECTOR

1

Workorder: V47517

In Date: 02/23/2012

Meter Reading: 56,835.30

Close Date: 02/29/2012

Problem?

water tank level indicator not operating, Sta 21

Task performed:

Parts

Quantity

REMOVED PUMP PANEL ON DRIVER SIDE OF TRUCK FOUND HOT WIRE PULLED OUT OF PLUG CORRECTED CHECKED OK.

NO PARTS USED

Workorder: V48412

In Date: 04/04/2012

Meter Reading: 57,997.30

Close Date: 04/10/2012

Problem?

Repair primer

Task performed:

Parts

Quantity

REPLACED PRIMMER

501-3090-00PRIMER PUMP MOTOR

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V48295

In Date: 03/29/2012
Close Date: 04/24/2012

Meter Reading: 57,881.20

Problem?

driver's door inside panel coming off, also scene light cover missing passinger side rear T21

Task performed:

INSTALLED NEW LENS; CORRECTED DOOR PANEL.

Parts

NO PARTS USED

Quantity

Workorder: V48669

In Date: 04/14/2012
Close Date: 04/30/2012

Meter Reading: 58,324.20

Problem?

speedometer light out (night time)

Task performed:

REMOVED FROM DASH INSTALLED NEW BULB.
REINSTALLED DASH CLUSTER.

Parts

NO PARTS USED

Quantity

Workorder: V48922

In Date: 04/26/2012
Close Date: 05/01/2012

Meter Reading: 58,486.80

Problem?

REPLACE REAR TIRES T21

Task performed:

REPLACE REAR TIRES T21

Parts

NO PARTS USED

Quantity

Vendor?: ELPEX

Workorder: V48868

In Date: 04/24/2012
Close Date: 05/17/2012

Meter Reading: 58,359.50

Problem?

Green pump indicator light on the pump shifter is out. t21

Task performed:

COMPLETED ON TICKET #V49270.

Parts

1893BULB

Quantity

10



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V49268

In Date: 05/11/2012 Meter Reading: 58,646.80
Close Date: 05/17/2012

Problem?

door sticks and panel is coming off at the top

Task performed:

TRAVEL TO 21 ADJUSTED DOOR AND SECURED DOOR PANEL.

Parts

NO PARTS USED

Quantity

Workorder: V49270

In Date: 05/11/2012 Meter Reading: 58,646.80
Close Date: 05/17/2012

Problem?

pump shift light is out at the shifter. the pump shift works but light is out.

Task performed:

REPLACED PUMP SHIFT LIGHT.

Parts

NO PARTS USED

Quantity

Workorder: V49637

In Date: 05/26/2012 Meter Reading: 58,941.10
Close Date: 06/04/2012

Problem?

The right and left scene light clear cover is cracked. T 21

Task performed:

REPLACED BROKEN LENS ON TANKER

Parts

6811813493LENS CLEAR 68-1181349-3

Quantity

2

Workorder: V49787

In Date: 06/01/2012 Meter Reading: 58,941.10
Close Date: 06/06/2012

Problem?

Box light will not hold a charge. When in charger the red charging light is consistantly on.

Task performed:

TRAVEL TO 21 REPLACED 1 HAD LIGHT WITH REPAIRED UNIT. REPLACED AND REMOUNTED 2 HAND LIGHT BASES.

Parts

NO PARTS USED

Quantity



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142546

* FREIGHLINER TANKER TRUCK

Workorder: V48891

In Date: 04/25/2012

Meter Reading: 58,359.50

Close Date: 06/27/2012

Problem?

DOOR AJAR LIGHT WILL NOT GO OFF. CHECKED ALL DOORS NUMEROUS TIMES AND WERE UNABLE TO SHUT LIGHT / BUZZER OFF

Task performed:

1. TROUBLESHOOT ELECTRICAL PROBLEM WITH DOOR OPEN ALARM GOING OFF. CHECK ALL DOOR SWITCH, ADJUST ALL HOOK UP WIRES TO LIGHT AND BUZZER, FOUND BAD CLASS 1 MOD WATER INTRUTION BAD, WATER IN PLUGS, REPAIR ORDER PARTS DAY OUT.

2. REINSTALLED NEW PDM UNDER TRUCK AFTER RESETING DIP SWITCH AND PROGRAM OF PDM, MAKE COVER TO FIT OVER PDM TO STOP WATER INTRUTION, CHECK OK.

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142546

* **FREIGHLINER TANKER TRUCK**

Workorder: V49903

In Date: 06/05/2012

Meter Reading: 59,022.00

Close Date: 06/27/2012

Problem?

C INSPECTION T 21

Task performed:

1. C INSPECTION
2. SERVICE DRYER, REMOVE FROM TRUCK CLEAN OUT AND REBUILD REINSTALLED. ALSO INSTALLED NEW DRY AIR FILTER.
3. SERVICE T-CASE, WATER IN CASE, CLEAN OUT REFILL CHECK OK.
4. REPLACE ALL BATTERY OUT OF DATE BY YEARS. INSTALLED ALL 4 OF THEM TEST OK.
5. INSTALLED PUMP ANODES, NO ANODES IN PUMP REPLACE WITH NEW UNIT IN SIDE OF PUMP INSPECT ALL SCREEN ALSO OK.
6. REPLACE BOTH REAR MARKER BED LIGHTS ON BOTTOM OF TRUCK, WIRES VERY SHORT TO CONNECT REPAIR, TEST WORKING OK. REPLACE TAG LIGHT ALSO.
7. REBUILD PRIME VALVE VERY HARD TO MOVE NOT WORKING VERY WELL, REPAIR RETEST WORKING GOOD.
8. REBUILD TANK TO PUMP VALVE, REMOVE PANEL TO GET TO VALVE REMOVE AND REBUILD VALVE AFTER REPAIR 22" START STOP 21" GOOD.
9. REPAIR STRAPS TO WATER SHOOT ON REAR OF TRUCK MAKE REPAIR TO CABLES.
10. REDO PLACKER, REMOVE OLD NUMBER CLEAN PUT RED TAP AND THEN NUMBER BOTH SIDE.
11. REPAIR INNER FENDER OF LEFT REAR TIRE ALL SCREW MISSING AND STRIP OUT, REWORK HOLES, INSTALLED NEW SCREW AND WASHER.
12. REPLACE EMERGENCY LIGHT COVER, BROKEN HAD TWO LIGHT COVER, SCREW BROKE OFF, HAD TO DRIVE OUT AND TAP HOLE FOR NEW SCREW.
13. START TO REPLACE DRIVER DOOR LEDGES, REMOVE OLD ONE, SCREW BROKEN OFF IN PANEL DRILL OUT AND TAP HOLES, ORDER PARTS FOR LEDGES, BE HER IN A.M.
14. TRANSFER OVER ALL PARTS TO NEW LEDGES INSTALLED BACK ON DRIVER DOOR, INSTALL NEW SCREW TO FIT HOLES AND REPLACE MISSING SCREW IN PANEL THAT WERE MISSING TO FRONT.
15. R&R DRIVER SEAT TO HAVE REWORK, RIP, REINSTALL SEAT TO TRUCK.
16. SERVICE FLOATER PUMP OIL FILTER PLUG REPAIR CHOCK CABLE NOT WORK, WOULD NOT START.
17. Q.A. INSPECTION.

Parts

Quantity

104529ES KEY PDM	1
17211ZF5V01FILTER AIR	1
35200-RLIGHT MARKER LED RED	2
5008414CARTRIDGE DC100	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
BPR6ESSPARK PLUG 7131	1
CA3990AIR FILTER 46883	1
DS-13721-1-513748-1-5 TRANS COOLER	1
HP-31DBATTERY 950CCA HP-31D	4
PVG-KITORING KIT	1
R950013TURBO CUT OFF VLV KIT	1
R950014PURGE VALVE WABCO AIR DRYER	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
529008000529-0080-10-0 1 1/4 ANODE KIT	1
68318358750600 NON OPTIC RED LENS	4
91388906 VALVE KIT 2.5 IN AKRON	1
A18-21720-004DOOR SILL	1
P1147GFUEL FILTER 33120 WIX DELCO TP916	1
PH7405 51971 OIL FILTER WIX	2



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142546

* FREIGHLINER TANKER TRUCK

Workorder: V50158

In Date: 06/15/2012 Meter Reading: 59,022.00
Close Date: 06/27/2012

Problem?

westcoast mirrors need to be replace. Both sides.

Task performed:

NO PROBLEM FOUND WITH MIRROR, STEVE R.
LOOK AT ALSO OK.

Parts

NO PARTS USED

Quantity

Workorder: V50157

In Date: 06/15/2012 Meter Reading: 59,022.00
Close Date: 06/28/2012

Problem?

truck baffles no working truck dances around at 40 mph

Task performed:

OPEN WATER TANK COVER LOOK OK IN FROM TOP,
OPEN WATER SHOOT ON REAR OF TRUCK LOOK
INSIDE ALL BOFFLES LOOK GOOD, HAD STEVE R.
LOOK ALSO OK. DRIVE TRUCK WITH NO WATER IN
TANK DRIVE OK. DRIVE TRUCK WITH TANK FULL OF
WATER DRIVE OK. ALL TIRES VERY LOW ON P/M
CHECKOUT, AIR TO PROPER AIR.

Parts

NO PARTS USED

Quantity

Workorder: V49695

In Date: 05/29/2012 Meter Reading: 58,941.10
Close Date: 07/03/2012

Problem?

selector knobs broken, need replaced for a/c and lights

Task performed:

INSTALLED NEW KNOBS ON DASH

Parts

71R4040KNOB

Quantity

2



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V51075

In Date: 07/24/2012

Meter Reading: 59,022.00

Close Date: 07/27/2012

Problem?

tranny shifting very bad. very hard banging between 2nd. and third gears. t21

Task performed:

Parts

Quantity

1. TRAVEL TO 21 TEST DRIVE TENDER TRANS SLIPS RETURN GEARS AND BANGS GOING INTO GEAR. WILL HAVE TO BE LOOKED AT BY ALLISON.
2. TRAVEL TO 21 CHECKED TRANS TRANS OK. T-CASE NOT SHIFTING FO?? OR SHAFT BENT NOT ALLOWING T-CASE TO MOVE.

NO PARTS USED

Workorder: V52109

In Date: 09/03/2012

Meter Reading:

Close Date: 09/12/2012

Problem?

air banks leak down faster than in past, may delay response... E21

Task performed:

Parts

Quantity

1. TRAVEL TO 21 CHK FOR OIL LEAKS AND REPAIRED. TESTED OK.

NO PARTS USED

Workorder: V52150

In Date: 09/04/2012

Meter Reading:

Close Date: 09/13/2012

Problem?

The cable holding the last section of the water spout on has disconnected on both sides of the spout. Cables needs to be recrimped. t 21

Task performed:

Parts

Quantity

1. TRVL TO 21 REPLACED BOTH CABLES ON SHOOT TO PREVENT SHOOT FRM SLIDING OFF.

NO PARTS USED

Workorder: V51532

In Date: 08/11/2012

Meter Reading:

Close Date: 09/17/2012

Problem?

The front tires are worn down into the ware indicators T21

Task performed:

Parts

Quantity

- CHKD FT TIRES HAVE TIME LFT OK WILL MONITOR.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

* FREIGHLINER TANKER TRUCK

Workorder: V52151

In Date: 09/04/2012

Meter Reading:

Close Date: 09/20/2012

Problem?

The valve/handle at the rear of the tender that opens to dump the water will not stay open while the water is dumping. t 21

Task performed:

Parts

Quantity

REPAIRES MADE TO DUMP TANK SO TANK TO STAY OPEN.

NO PARTS USED

Workorder: V52297

In Date: 09/10/2012

Meter Reading: 59,751.70

Close Date: 09/21/2012

Problem?

repair cage on portable tank

Task performed:

Parts

Quantity

TRVL TO HQ HILL CHK OUT TANK FRAME FOUND METAL ON CAR TO USE TRAINING GUY WELDED UP PLATE.

NO PARTS USED

Workorder: V52564

In Date: 09/22/2012

Meter Reading:

Close Date: 09/26/2012

Problem?

The chainsaw on the tender will not start. The pull start cord will not engage the motor when pulled. The plastic arm that is suppos to engage the knob just skips over it. T21

Task performed:

Parts

Quantity

TRAVEL TO 21 TO PICKUP BROKEN SAW.

NO PARTS USED

Workorder: V52248

In Date: 09/07/2012

Meter Reading:

Close Date: 10/01/2012

Problem?

The 2 cable that holds the last section of the water shoot together on the rear dump have both come loose. Both cables are not connected. T21

Task performed:

Parts

Quantity

REPLACED CABLES TO REAR SHOOT.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V53036

In Date: 10/12/2012
Close Date: 10/16/2012

Meter Reading: 60,143.10

Problem?

Rightside (Passenger) headlight out. Bright light works but regular driving light is out. T21

Task performed:

TRAVEL TO 21 R&R HEADLIGHT.

Parts

H4656USE CV TYPE HEAD LIGHT

Quantity

1

Workorder: V53103

In Date: 10/15/2012
Close Date: 10/24/2012

Meter Reading: 60,178.90

Problem?

foat a pump starting pull cord is broken T21

Task performed:

TRAVEL TO ST 21 R&R PULL CORD HAD TO PULL UNIT OFF FLOAT TO GET OFF COVER GET STARTEI

Parts

16957-ZE1-812HONDA FUEL GROMET

Quantity

2

Workorder: V53818

In Date: 11/16/2012
Close Date: 11/20/2012

Meter Reading:

Problem?

LEFT SIDE (FRONT) SCENE LIGHT OUT

Task performed:

CHECK OUT LIGHT R/R BULB AND REPAIR PLUG.

Parts

NO PARTS USED

Quantity

Workorder: V53884

In Date: 11/19/2012
Close Date: 11/20/2012

Meter Reading:

Problem?

The air system on the truck will not build pressure and it leaks. Even with the truck in high idle the truck will only build pressure to 50psi and then stop. Engage the brake and it almost completely depletes the air. t21

Task performed:

TRAVEL TO ST 21 CHECK OUT AIR SYSTEM REBUILD PURGE VAVLE.

Parts

R950014PURGE VALVE WABCO AIR DRYER

Quantity

1



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142546

* **FREIGHLINER TANKER TRUCK**

Workorder: V54183

In Date: 12/04/2012

Meter Reading:

Close Date: 12/10/2012

Problem?

1- need foam pick up hose. 2- Guages and labels for crosslays 1&2 are reversed and need to be changed. T21

Task performed:

1. TRAVEL TO 21 OICKED UP FITTING FOR FOAM PICKUP TO MAKE HOSE.
2. REPLACED GAUGES AND HANDLES FOR CROSSLAYS.
3. REPLACED LED ON GRILL.

Parts

Quantity

60R00FRR600 SERIES RED LED W/O FLANGE

1

Workorder: V54206

In Date: 12/04/2012

Meter Reading:

Close Date: 12/10/2012

Problem?

air horn does not work T21

Task performed:

CHECKED AIR HOW AND ADJUSTED.

Parts

Quantity

NO PARTS USED

Workorder: V54610

In Date: 12/25/2012

Meter Reading: 61,370.50

Close Date: 12/27/2012

Problem?

front suction drain leaks under normal (non pumping) operation. E21

Task performed:

TRAVEL TO 21 REPLACED DRAW VALVE ON FRONT SUCTION.

Parts

Quantity

34BVVALVE DRAIN CLASS1

1

Workorder: V54967

In Date: 01/10/2013

Meter Reading:

Close Date: 01/16/2013

Problem?

Have to buildup air pressure everytime truck start up, after truck sat in bay for awhile. Pressure drop to 50 psi.

Task performed:

CHECKED AND REPAIRED AIR LEAKS.

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

* FREIGHLINER TANKER TRUCK

Workorder: V55074

In Date: 01/15/2013

Meter Reading: 3,672.20

Close Date: 01/28/2013

Problem?

urb mirror mounted on passenger cab door 1 appliance bracket mounted on right side diamond plate 2 appliance brackets, (1 replaced), back tailboard mallet mounted on door halligan bar mounted 2 appliance brackets mounted on ceiling of DO compartment T21

Task performed:

1. MOUNTED 2 BRACKETS ON BODY AND 1 HAMMER BRACKET IN L1 COMPARTMENT.
2. TRAVEL TO 21 INSTALLED TOOL LADDERS MOVED FIRE EXTINGUISHER. MOUNTED HOSE AND GATE VALVE ON BUMPER MOUNTED NOZZLES AND FITTING TOOL.

Parts	Quantity
5269LPVM-5 SM MOUNT	4

Workorder: V55148

In Date: 01/18/2013

Meter Reading:

Close Date: 01/28/2013

Problem?

right front scene light 10-7. Also quick note for mechanic to mount 3 appliance clips and 2 strap brackets to secure equipment to diamond plate. T-21

Task performed:

REPAIRED SCENE LIGHT.

Parts	Quantity
NO PARTS USED	

Workorder: V55273

In Date: 01/24/2013

Meter Reading:

Close Date: 01/28/2013

Problem?

would like to get the SCBA bracket mounted to door

Task performed:

TRAVEL TO 21 MOUNTED SCBA BRACKET TO DOOF

Parts	Quantity
NO PARTS USED	

Workorder: V55568

In Date: 02/05/2013

Meter Reading:

Close Date: 02/08/2013

Problem?

pump panel lights. one om driver side. two on passenger side burnt out. also cab light driver side out. E21

Task performed:

TRAVEL TO 21 REPAIRED ALL LIGHTS.

Parts	Quantity
NO PARTS USED	



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V56290

In Date: 03/10/2013

Meter Reading: 62,844.60

Close Date: 03/12/2013

Problem?

3 appliance clamps, (to diamond plate) do not have 3 prongs to hold appliances securely. they are located on; the right front bumper, mid-right diamond plate, and right rear tail board.

Task performed:

Parts

Quantity

REPLACED 3 BROKEN CLAMPS.

NO PARTS USED

Workorder: V48101

In Date: 03/21/2012

Meter Reading:

Close Date: 04/08/2013

Problem?

small holes in dump tank need patched

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V48907

In Date: 04/26/2012

Meter Reading: 58,486.80

Close Date: 04/08/2013

Problem?

door ajar issue

Task performed:

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

* **FREIGHLINER TANKER TRUCK**

Workorder: V56502

In Date: 03/19/2013

Close Date: 04/17/2013

Meter Reading: 62,939.00

Problem?

B inspection T21

Task performed:

Parts

Quantity



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142546

* FREIGHTLINER TANKER TRUCK

1. B-INSPECTION.
2. BATTERY TESTING - BATTERIES WERE TO LOW ON CHARGE TO TEST - HOOK UP JUMPS TO ALL POSTS AND CHARGE BATTERIES FULLY AND THEN TEST - SERVICE BATTERY SLIDE TRAY.
3. R&R LEAKS - CHECK ALL VISABLE AIR CONNECTIONS NO LEAK FOUND.
4. VOGEL TRUCK AUTO LUBE SYSTEM INOP. FOLLOW MANUFACTORY INSTRUCTIONS DIAGNOSE ENTIRE SYSTEM BLEED SYSTEM CHECK PSI, CHECK REJECT??? CHECK VOLTAGE, ALL CHECK GOOD PUMP NOT MOVING GREASE, REMOVE SYSTEM AS PER FOREMAN - PUT IN MANUAL GREASE FITTINGS.
5. RIGHT AIR HORN BROKE OFF - REMOVE PIECES - INSTALL AND ADJUST NEW HORN.
6. 3 ENGINE BELTS AND A/C - ALTERNATOR BELTS SERVICE.
7. LEFT BUMPER POLE LIGHT INOP - REMOVE BLOWN BULB AND INSTALL NEW BULB, REPLACE DAMAGE LENSE.
8. RIGHT MIRROR TURN SIGNAL, 3 PUMP PANEL LIGHT AND ASSEMBLY L/REAR WING MARKER LIGHT INOP AND CORRODED HOUSING ASSEMBLY. REMOVE AND INSTALL NEW PARTS.
9. REPAIR THREADS ON VOGEL LUBE 4 PORT MANIFOLD.
10. CAB DOME AND MAP LIGHT MOUNT BROKEN - REMOVE FROM ROOF PARTS NOT AVAILABLE - REPAIR AND REINSTALL ASSEMBLY.
11. PUMP MASTER INTAKE VALVE WARNING LIGHT INOP - REMOVE BLOWN BULBS - CLEAN SOCKET WITH ELECTRICAL CONTACT SOLUTION AND INSTALL NEW BULBS.
12. PUMP OVER HEAT LIGHT TEST SWITCH MISSING - OPEN PUMP PANEL REMOVE FIRE COMMAND PANEL TO GAIN ACCESS TO SWITCH - REMOVE SWITCH AND INSTALL NEW ONE. REASSEMBLE.
13. #1 DISCHARGE GAUGE LOOSE - CRAWL INTO PUMP COMPARTMENT TO SECURE LOOSE GAUGE - SECURE GAUGE.
14. CAB DOOR DECAL SIGN OFF BY S. REINES. FOR REPAIR AT LATER DATE.
15. CLASS 1 LEAK AT TRANSFER CASE, POWER STEERING RETURN LINE - CLEAN ALL AREA AND OBSERVE AS PER FORMAN S.R.
16. WINDSHIELD WIPER BLADE AND FLUID.
17. PRESSURE WASH ENGINE COMPARTMENT OF ALL EXCESS GREASE AND DIRT.
18. Q. & A.
19. Q/A PRIMER PUMP INOP - DIAGNOSE FAULT INTERMITTING FAILURE FOUND SOLENOID INTERMITTING FAILURE - REMOVE AND INSTALL NEW SOLENOID.

1141BULB	3
120257100C2030-7110-30 CLEAR DOME STEP	3
2000071102000072100 SOLENOID HALE PRIMER	1
22-27156-000GASKET FUEL SENDER	1
2P/50BELT	1
372000084MARKER LIGHT	2
52165216 WIPER	2
923182-2151 SWITCH MOMENTARY 24-372	1
9530BELT	3
B-1103A1131 LENS (AMBER)	1
CB031/4X2-1/2 BELTING	10
HRN6681HORN AIR 24" GROVER P/N-1510	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
91523934GAUGE 0-600 PSI	1
P1147GFUEL FILTER 33120 WIX DELCO TP916	1
PH7405 51971 OIL FILTER WIX	2



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

20. REAR STEP LIGHT INOP - LIGHT ASSEMBLY RUSTED AND SCREW BROKE OFF IN STEP MOUNT - REPLACE ASSEMBLY AND RETAP HOLD DOWN HOLES.

21. R-1 COMPARTMENT STRUT LOOSE AND BRACKETS MOUNT BROKEN - REPLACE BRACKET MOUNT FROM FABRICATED MEDAL DRILL AND TAP NEW SUPPORT HOLES, MOUNT STRUTS.

Workorder: V54746

In Date: 01/02/2013
Close Date: 04/18/2013

Meter Reading:

Problem?

Nader pin on top in the middle of compartment holding double doors closed broke off. T21

Task performed:

Parts	Quantity
657843STRIKER EGS-FM-E500-106-ZN MT EONE	1

Workorder: V54866

In Date: 01/06/2013
Close Date: 04/18/2013

Meter Reading:

Problem?

pager/beeper needs servicing/replaced. does not display all characters on page out. can you please forward this to communications for us.

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V57049

In Date: 04/15/2013
Close Date: 04/18/2013

Meter Reading: 62,939.00

Problem?

right rear discharge slow leak when pump is in gear. fills blitz line with 1 gallon of water when valve is fully closed.

Task performed:

TRAVEL TO 21 REBUILT RR DISCHARGE VALVE. LEAKING

Parts	Quantity
91398907 VALVE KIT 3 IN AKRON	1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V57050

In Date: 04/15/2013
Close Date: 04/18/2013

Meter Reading: 62,939.00

Problem?

front LDH 20' section small hole/leak 12" away from front 6" steamer side, (truck side)

Task performed:

1. INFORMED DRIVER TO CONTACT HIS DISTRICT CHIEF FOR NEW LDH HOSE.
2. DRIVER COMPLAINED OF AIR LEAK. REBUILD VPS SHIFTER FOR T-CASE.

Parts

5460370530VPS SHIFT KIT 546-0370-53-0

Quantity

1

Workorder: V50310

In Date: 06/21/2012
Close Date: 04/19/2013

Meter Reading: 59,022.00

Problem?

REPAIR CHASSIS

Task performed:

REPAIR CHASSIS.

Parts

NO PARTS USED

Quantity

Vendor?: TOTAL TRUCK PARTS

Workorder: V57334

In Date: 04/29/2013
Close Date: 05/01/2013

Meter Reading: 63,289.80

Problem?

Flat LRI Tanker21

Task performed:

FLAT LRI TANKER 21.

Parts

292850BRIDGESTONE 12R22.5 TIRE

Quantity

1

Vendor?: BOULEVARD TIRE CENTE

Workorder: V57528

In Date: 05/06/2013
Close Date: 05/07/2013

Meter Reading:

Problem?

Left front scene light out.

Task performed:

TRAVEL TO 21 REPLACED BULB IN R/F SCENE LIGHT.

Parts

H35SN12BULB

Quantity

2



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V57844

In Date: 05/20/2013

Meter Reading:

Close Date: 05/29/2013

Problem?

Foam guage reading empty yet tank is full. T21

Task performed:

- CHECK OUT FOAM SYST NEEDS NEW GUAGE WILL ORDER.
- R&R GUAGE IN PUMP PANEL MAKE NEW GUAGE FIT IN HOLE REPROGRAM GUAGE.

Parts

Quantity

WL2600WLA260-A00 FOAM TANK VISION OLD FERR # 352

1

Workorder: V57909

In Date: 05/22/2013

Meter Reading:

Close Date: 05/29/2013

Problem?

water leak on deck gun ball valve T21

Task performed:

- TRAVEL TO 21 R&R DECK GUN VALVE AND REBUILD UNIT.

Parts

Quantity

91398907 VALVE KIT 3 IN AKRON

1

Workorder: V57735

In Date: 05/14/2013

Meter Reading:

Close Date: 05/31/2013

Problem?

Map light falling down.

Task performed:

- CHECKED MAP LIGHT FOUND NO PROBLEM.

Parts

Quantity

NO PARTS USED

Workorder: V57987

In Date: 05/27/2013

Meter Reading:

Close Date: 05/31/2013

Problem?

driver side high-beam 10/7

Task performed:

- TRAVEL TO 21 R&R HIGH BEAM.

Parts

Quantity

H4651USE CV TYPE SEALED BEAM

1

H6054USE CV TYPE SEALED BEAM

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V58331

In Date: 06/11/2013

Meter Reading: 63,983.50

Close Date: 07/03/2013

Problem?

Water leaking from right steamer/front LDH connection junction t21

Task performed:

Parts

Quantity

1. TRAVEL TO 21 FOUND FRONT SUCTION LINE AT PADDLE VALVE LEAKING AT VICTALIC CONNECTION WILL BEING TO SHOP FOR REPAIRS.

NO PARTS USED

2. ADJUSTED HANDLE FOR RIGHT INTAKE TO MAKE EASIER TO MAKE EASIER TO OPEN.

3. DOME LIGHT FELL DOWN REPLACED SCREWS AND REATTCHED SERVICED ENN

Workorder: V59051

In Date: 07/12/2013

Meter Reading: 64,402.40

Close Date: 07/17/2013

Problem?

Replace front tires

Task performed:

Parts

Quantity

REPLACE FRONT TIRES.

NO PARTS USED

Vendor?: BOULEVARD TIRE CENTE

Workorder: V59085

In Date: 07/15/2013

Meter Reading: 64,402.40

Close Date: 07/18/2013

Problem?

foam pickup tube missing nipple, need a new one. T21 .

Task performed:

Parts

Quantity

FABRICATED FOAM PICK UP HOSE AND ASSEMBLED - DIAGNOSED ELECTRICAL ISSUE CHECKED ALTERNATOR AND MULTIPLEX.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V59119

In Date: 07/16/2013

Meter Reading: 64,402.40

Close Date: 07/18/2013

Problem?

UNIT WILL NOT GO INTO 4TH GEAR LOCK UP T 21

Task performed:

REPLACED SWITCH ON TRANS. SYSTEM STILL NOT WORKING FOLLOWED WORING TO POWER DISTRIBUTION MODULE FOUND POWER LIGHT OFF ON MODULE. REMOVED CORODED WIRES FROM POWER SWITCH AND CLEANED. PUT THEM BACK ON CHECKED AND CLEANED GROUND WIRES NO GO MODULE ROD. SENT TO SHOP NO PARTS IN STOCK.

Parts

NO PARTS USED

Quantity

Workorder: V59304

In Date: 07/23/2013

Meter Reading: 64,402.40

Close Date: 08/07/2013

Problem?

no 4th gear and repair water leaks

Task performed:

CHANGED CLASS 1 MODULE IN PUMP PANEL - STARTED REPAIRING WATER LEAK IN PUMP AREA.

Parts

007-3490-00-012 BOLT FLANG 5 IN VIC

1

5V7001-5 SEAL PUMP

1

627505PDM 104369

1

91388906 VALVE KIT 2.5 IN AKRON

1

91398907 VALVE KIT 3 IN AKRON

1

Workorder: V59706

In Date: 08/09/2013

Meter Reading: 64,592.00

Close Date: 08/19/2013

Problem?

Left rear turn signal does not function.

Task performed:

1. TRAVEL TO 21 CHECKED LR SIGNAL LIGHT NO POWER TO LIGHT TRACED WIRE BACK FOUND NO POWER COMING FROM NODE ORDERED PARTS.

Parts

1046250300BULB

1

350000034PDM 80 UMS

1

FREIGHTSHIPPING CHARGES

85

2. TRAVEL TO 21 REPLACED CLASS 1 MODULE AND TESTED OK.

H50TL12BULB

1



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142546

* **FREIGHLINER TANKER TRUCK**

Workorder: V59750

In Date: 08/12/2013

Meter Reading: 64,592.00

Close Date: 08/19/2013

Problem?

pressure governor not working. found during pump testing.

Task performed:

1. PRESSURE GOVERNOR DOES NOT RELIEVE RAISES PRESSURE BUT DOES NOT RELIEVE WHEN YOU CLOSE DISCHARGE WILL GET BOOKS TO REPAIR.
2. GOT NUMBERS OFF SENSOR TO ORDER PARTS.
3. TRAVEL TO 21 REPLACED SENSOR FOR PRESSURE GOVERNOR AND TESTED OK.

Parts

Quantity

23520795DISCHARG TRNDUCR

1

Workorder: V60058

In Date: 08/27/2013

Meter Reading: 64,896.00

Close Date: 08/28/2013

Problem?

ENGINE 53-DIGITAL GAUGE ON PUMP PANEL-LED LIGHTS OUT ON VOLTAGE.

Task performed:

TRAVEL TO 21 CHECKED DIGITAL DISPLAY FOUND NO PROBLEM WORKS FINE.

Parts

Quantity

NO PARTS USED

Workorder: V60261

In Date: 09/04/2013

Meter Reading: 65,054.00

Close Date: 09/05/2013

Problem?

Replace alternator

Task performed:

TRAVEL TO ST 21 DRIVER COMPLAINS OF BELT SQUEEL. CHECKED BELTS FOUND ALTERNATOR BASE BROKEN. REPLACED ALTERNATOR AND ADJUSTED BELTS TESTED OK.

Parts

Quantity

4867JB320 UPGRADE ALTERNATOR

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

* FREIGHLINER TANKER TRUCK

Workorder: V60368

In Date: 09/08/2013

Meter Reading: 65,137.00

Close Date: 09/12/2013

Problem?

emergency flasher not operating drivers side T21

Task performed:

Parts

Quantity

DRIVER COMPLAINT EMERGENCY LIGHT LEFT MID BODY OUT. CHECKED ALL LIGHTS ALL WORKING PROPERLY NOW NO PROBLEM FOUND.

NO PARTS USED

Workorder: V60462

In Date: 09/12/2013

Meter Reading: 65,137.00

Close Date: 09/19/2013

Problem?

Compartment door inop

Task performed:

Parts

Quantity

L-2 DOOR WILL NOT CLOSE FOUND LATCH AND HANDLE WORN, REPLACE LATCH AND HANDLE ASSEMBLY, ADJUSTEDLINKAGE,.

HA24015LATCH

1

LTC594211657-16 LATCH L/H MEDIC MASTER

1

Workorder: V61181

In Date: 10/11/2013

Meter Reading: 65,589.00

Close Date: 10/18/2013

Problem?

driver compt. door will not open on right side

Task performed:

Parts

Quantity

TRAVEL TO 21 DRIVER COMPLAINT COMPACTMENT DOOR INOP ADJUSTED DOOR LATCH A ND SRIKER OK.

NO PARTS USED

Workorder: V61463

In Date: 10/22/2013

Meter Reading: 65,675.30

Close Date: 10/24/2013

Problem?

tank to fill valve feels sloppy, like its getting ready to break

Task performed:

Parts

Quantity

TRAVEL TO 21 DRIVER COMPLAINT TANK FILL HANDLE LOOSE OPEN PUMP PANEL AND SECURED LOOSE BOLTS ON TANK FILL VALVE.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

* FREIGHLINER TANKER TRUCK

Workorder: V61481

In Date: 10/24/2013
Close Date: 10/24/2013

Meter Reading: 65,733.50

Problem?

L1 comp will not open

Task performed:

DRIVER COMPLAINT L-1 WILL NOT OPEN FOUND INNER HANDLE ON SECOND DOOR FALLING OUT AND INSTALLED BACKWARDS REINSTALLED PROPERLY AND REDRILLED HOLES FOR NEW SCREWS TESTED AND USED DOOR LATCH OK.

Parts

NO PARTS USED

Quantity

Workorder: V61487

In Date: 10/24/2013
Close Date: 10/30/2013

Meter Reading:

Problem?

Light bar, left rear corner strobe out. T21

Task performed:

TRAVEL TO 21 DRIVER COMPLAINT COVER STROBE OUT R&R CORNER STROBE.

Parts

02036273300 TURBO94 CORNERLINEAR REFLECTOR

1

Quantity

Workorder: V60059

In Date: 01/01/1900
Close Date: 12/06/2013

Meter Reading: 64,896.00

Problem?

TENDER 21- PRESSURE GOVERNOR HAD NO CHAGE AT 150PSI.

Task performed:

REPAIRED ON WORK ORDER 59750

Parts

NO PARTS USED

Quantity

Workorder: V62622

In Date: 12/10/2013
Close Date: 12/13/2013

Meter Reading:

Problem?

front left low beam not working, looked for replacement bulb at station, could not find one

Task performed:

DRIVERCOMPLAINT LOW BEAM LIGHT OUT R&R LOW BEAM.

Parts

H4656USE CV TYPE HEAD LIGHT

2

Quantity



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142546

* FREIGHTLINER TANKER TRUCK

Workorder: V64345

In Date: 02/19/2014

Meter Reading: 66,823.00

Close Date: 02/20/2014

Problem?

Replace Front tandum tires Elpex Tire

Task performed:

REPLACE FRONT TANDUM TIRES ELPEX TIRE.

Parts

NO PARTS USED

Quantity

Vendor?: ELPEX



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V63031

In Date: 12/30/2013

Meter Reading: 66,792.00

Close Date: 02/26/2014

Problem?

T21 C inspection

Task performed:

1. CONTINUE LOOKING FOR WIG WAG, FOUND BURNED IN CONSOLE.
2. TROUBLESHOOT DECK GUN WARNING ADJUST SENSORS.
3. TROUBLESHOOT CITY HORN INOP, REPAIR PINCHED WIRES.
4. REPAIR AIR LEAKS.
5. REPAIR ALL COMP AND PUMP PANEL LIGHTS.
6. TIGHTEN ALT BELT REPLACE JAM NUT.
7. REPAIR ALL COMP DOOR SHOCKS AND MOUNTING BRACKETS.
8. STATION WANTS WIG WAGS DISABLED START TO CHECK WIRING TO DISCONNECT WIG WAGS.
9. R&R TIE ROD ENDS ADJUST TOE.
10. TROUBLESHOOT FOAM SYS INOP.
11. CONTINUE TROUBLESHOOT FOAM SYS FOUND TALK FOAM VALVE NOT OPEN ALL THE WAY.
12. TIGHTEN AND RESECURE ALL COMP TOOL HOLERS AND BRACKETS.
13. REMOVE POWER STEERING LINE.
14. DRUM POWER STEERING SYS, CLEAN UNDER TRUCK.
15. INSTALL NEW POWER STEERING LINE, BLEED SYST.
16. R&R FRONT SHOCKS.
17. C-INSP.
18. C-INSP.
19. REPLACE JERK FITTINGS AND CLEAN CROSSES ON U-JOINTS.
20. SERVICE DRYER COULD NOT REMOVE FILTERS, REMOVE DRYER ASSEMBLY FROM FRAME, REMOVE FILTER, INSIDE OF HOUSING RUSTED AND PUT ORDER NEW IN HOUSING.
21. RESECURE FRONT BUMPER LIGHTS REPLACE LENSES.
22. ADJUST AIR HORNS.
23. TIGHTEN OIL PAN BOLTS.

Parts

Quantity

0100030000SCREEN 6 IN	2
029-0511-00-0ANODE ONLY	1
05-18833-000HOSE COOLER TANKER ELB 90 3.0X2.5 ID	2
120257100C2030-7110-30 CLEAR DOME STEP	2
15W40BSYN OIL BULK QTS	36
194BULB	10
565103SHOCK	2
B-1103A1131 LENS (AMBER)	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
E-6856TIE ROD END 310-396	1
E-6857TIE ROD END T21 310-395	1
FREIGHTSHIPPING CHARGES	1
HP-31DBATTERY 950CCA HP-31D	4
R955205AIR DRYER	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
62201BACK-UPLIGHT	2
91581CLEAR LENS	1
CA3990AIR FILTER 46883	1
FG83284DFG/HF6238 PS/HDY FILTER	1
P1147GFUEL FILTER 33120 WIX DELCO TP916	1
PH7405 51971 OIL FILTER WIX	2



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

* FREIGHTLINER TANKER TRUCK

Workorder: V64555

In Date: 02/26/2014

Meter Reading: 66,875.10

Close Date: 02/27/2014

Problem?

Tire repair at station T21 Boulevard Tire

Task performed:

Parts

Quantity

TIRE REPAIR AT STATION T21 BOULEVARD TIRE.

NO PARTS USED

Vendor?: BOULEVARD TIRE

Workorder: V65251

In Date: 03/27/2014

Meter Reading:

Close Date: 03/31/2014

Problem?

primer pump not working

Task performed:

Parts

Quantity

DRIVER COMPLAINT PRIMER INOP R&R PRIMER MOTOR AND SOLENOID.

2000071102000072100 SOLENOID HALE PRIMER

1

501-3090-00PRIMER PUMP MOTOR

1

Workorder: V65620

In Date: 04/10/2014

Meter Reading: 67,839.50

Close Date: 04/14/2014

Problem?

air leak at park brake valve

Task performed:

Parts

Quantity

CHECK FOR AIR LEAKS LEAKS FOUND. AIR CONTROL. SWITCH LEAKING REPLACE SWITCH TEST FOR OPERATION IS GOOD NOW.

FSC17492134NC SW PARK BK SPADE TYPE CONNECTOR

1

Workorder: V66358

In Date: 05/09/2014

Meter Reading:

Close Date: 05/13/2014

Problem?

Foam system not working. Need new deck gun. Old deck gun will not secure to mount.

Task performed:

Parts

Quantity

TRAVEL TO 21 DRIVER COMPLAINT DECK GUN POPPED OFF UNDER PRESSURE. TOOK SPARE MONITOR AND REPLACED.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

* **FREIGHLINER TANKER TRUCK**

Workorder: V66800

In Date: 05/28/2014

Meter Reading:

Close Date: 06/10/2014

Problem?

After engaging parking break, it is taking some time for the truck to reconize it is in park, wont go into pump untill it reconizes it. Also pump fill and recirculate vave not closing all the way.

Task performed:

Driver Complaint parking brake taking time to engage. tested unit could not duplicate problem.
Driver domplaint water leak in tank found prior tank fill pipe loose stripped leaking swapped out truck

Parts

NO PARTS USED

Quantity

Workorder: V65274

In Date: 03/28/2014

Meter Reading:

Close Date: 06/17/2014

Problem?

Primer was replaced yesterday but not working today.

Task performed:

repaired primer.

Parts

2000071102000072100 SOLENOID HALE PRIMER

Quantity

1

Workorder: V66976

In Date: 06/04/2014

Meter Reading:

68,830.00

Close Date: 06/19/2014

Problem?

tank leak

Task performed:

- 1) removed direct tank fill value and piping found tank buck cracked cut dismond plate at rear of truck and piping support to gain access for repair.
- 2) fabricated new support for piping and cut new diamond plate overlay for access cover installed.
- 3) filled tank ck, for leaks after repairs.

Parts

NO PARTS USED

Quantity

Workorder: V67770

In Date: 07/08/2014

Meter Reading:

69,138.00

Close Date: 07/09/2014

Problem?

door ajar

Task performed:

CLEANED OUT WET TERMINALS.

Parts

NO PARTS USED

Quantity



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V68487

In Date: 08/07/2014
Close Date: 08/11/2014

Meter Reading:

Problem?

Parking brake light not working. Rob knows about it.

Task performed:

travel to sta,21 replaced sw, in dash for brake light display on multi plex screen replaced push button for hose reel. repaired loose ground to marker light.

Parts

Quantity

76072-15-DC76072-15-DC SWITCH SW76072
923182-2151 SWITCH MOMENTARY 24-372

1
1

Workorder: V69497

In Date: 09/19/2014
Close Date: 09/19/2014

Meter Reading: 70,112.80

Problem?

Air tires

Task performed:

air all tires on truck.

Parts

Quantity

NO PARTS USED

Workorder: V69641

In Date: 09/24/2014
Close Date: 09/24/2014

Meter Reading: 70,186.00

Problem?

Repair L/R/I

Task performed:

Repair L/R/I

Parts

Quantity

NO PARTS USED

Vendor?: ELPEX

Workorder: V69565

In Date: 09/21/2014
Close Date: 09/29/2014

Meter Reading: 70,159.90

Problem?

Discharge guage loose in pump panel, getting reading to fall out. Bolt missing from drafting strainer. T21

Task performed:

Travel to 21. Repaired discharge gauge. Replaced bolt.

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V69793

In Date: 09/30/2014

Meter Reading: 70,224.00

Close Date: 10/14/2014

Problem?

Voltage drop during primer operation Belts squealing during primer operation Failed dry vacuum test. Lost 20Hg

Task performed:

Parts

Quantity

1. Adjust alternator belt.

NO PARTS USED

2. Drain pump and perform dry vac. test 22.5". No drop.
Passes dry vac.

3. Install missing bolt from strainer.

Workorder: V70560

In Date: 10/29/2014

Meter Reading: 70,879.60

Close Date: 10/29/2014

Problem?

Electrical issues & pump shift problem

Task performed:

Parts

Quantity

1. Travel to station 21. could not duplicate issues with electrical. Checked bus line connections. Found connections in rear of vehicle wet from leaking tank. Dried out all connections. One connector missing gasket and electrical separator. None on service truck. Diagnose pump shift problem - Found air leak and no building air. Diagnose problem - Found air escaping from ABS valves. Diagnose problem - Found 3 brake chambers leaking internally - OOS. Wrap electrical connector with no gasket with glove and tie strap to keep water out.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V70562

In Date: 10/29/2014

Meter Reading: 70,879.60

Close Date: 11/20/2014

Problem?

Brakes wont release

Task performed:

1. Diagnose brake system-air wont build w/park br off and service brakes applying. Diagnose air system found leaking air chambers bypassing internally. No parts in stock-ordered-start disassembly.
2. Continue with above rear brake job, had to order adapters for service brake hose to air chamber connections on one axle.
3. Diassemble body access panels until able to find source of water tank leak. Get tank serial # and give to foreman to call tank mfr.
4. Find and repair elec system connector assy on communication circuit. Repair broken wire-Repair connector term seperator and secure wiring harness.
5. Finish replacing 4 brake chambers-set up and adjusted all rear brakes
6. Assist Ken in rmeoving hose bed for tank repair
7. Remove hose, remove decking on top of tank.
8. Assist Ken in installing hose bed after tank repair.
9. Assist K. Flerx in rmeoving hose bed from vehicle
10. Assist K. Flerx in reinstalling hose bed back in vehicle
11. Reinstall hose bed decking and trim plates after water tank repair. Fill tank and check for leaks.
12. Install new brakes and drums on rear axle #2. Adjusted and road test

Parts

Quantity

90013CLEVIS SLACK ADJ

4

K022884NT3030ELS-80 LONG CHAMBER 30/30

4



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

*** FREIGHTLINER TANKER TRUCK**

Workorder: V70611

In Date: 10/31/2014

Meter Reading: 70,879.60

Close Date: 11/20/2014

Problem?

B inspection T21

Task performed:

1. "B" inspection
2. Finish B inspection
3. Adjust air pressure on all 10 tires
4. R/R drivers air seat air control asy.
5. P/S leak-R/R hose between reservoir and pump. Had to R/R fuel filter and hedder to access drain P/S reservoir. R/R lid to get broken pieces of dipstick assy out of was parts. Reinstall lube and band assy.
6. Refill power steering reservoir and isntall new dipstick assy.
7. Diagnose vehicle horn not working-found open circuit in steering column slip ring assy. ordered parts.
8. Diagnose trans fault code 6412-trans retarder not working.
9. R/R lens, R/R bulb r/f turn signal
10. Straighten bracket for R/R mudflap
11. Diagnose vehicle air leaks-won't hold air overnight.
12. Service pump trans.
13. Continue diagnosis and repair of trans retarder not working(trouble code 6412) repair wiring at trans retarder modulator assy. road test vehicle-ok. Erase trouble code.
14. Continue air leak diagnosis- R/R air fitting at front suction water valve
15. Repair air horns on vehicle overhaul r/s horn assy and tune both.
16. Diagnose why foam system does not work
17. Reassemble steering column with new slip ring and attaching parts for horn circuit-test horn, OK .

Parts

Quantity

1094KIT-AIR HORN-GROVER	1
23530682SEAL	2
3576REAR BRAKE DRUMS	2
451672CABLE CITY HORN	1
AB4515Q685REXP4515Q BRAKE SHOES	4
BOS6222136002622207-001 W AIR SEAT	1
E-2769MKT4515QB BRAKE KIT	2
FRT 65376FREIGHT CHARGE	1
L2643655P/S HOSE 3/4	4
NMC Q56636DIPSTICK POWER STEERING	1
P1147GFUEL FILTER 33120 WIX DELCO TP916	1
PH7405 51971 OIL FILTER WIX	2
RGT 020168SCREW	1
RGT 031087TERMINAL	1
RGT 065068CONTACT HORN	1
RGT 451670-0300CABLE HORN	1
RGT 453096CONTACT HORN	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1

Workorder: V71707

In Date: 12/17/2014

Meter Reading: 71,525.00

Close Date: 12/18/2014

Problem?

Huge air leak behind dash. seems to stop when put in pump.

Task performed:

Travel to 21, traced air leak to control switch-replaced control switch-ok.

Parts

Quantity

15W40BSYN OIL BULK QTS	23
538-0180-00SHIFT CONTROL VALVE PUMP ROAD	1
75W90GEAR OIL SYN QT	4



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142546

* **FREIGHLINER TANKER TRUCK**

Workorder: V72445

In Date: 01/19/2015

Meter Reading:

Close Date: 01/22/2015

Problem?

no throttle response. Per on call tech, Lou, Pump engage switch needed. Tech got it working but still needs switch. T21

Task performed:

1. Drive to station. Check unit and found no codes. Check for connection on throttle. Found sensor on transmission case sending signal like pump was on. Relocate harness to second sensor - is good now. We need to get 2 new sensors.

Parts

Quantity

200-2450-00NC SWITCH OK TO PUMP

2

Workorder: V72539

In Date: 01/22/2015

Meter Reading:

Close Date: 01/26/2015

Problem?

replace t-case switches

Task performed:

Travel to ST 21. Replaced T case switches.

Parts

Quantity

NO PARTS USED

Workorder: V72866

In Date: 02/04/2015

Meter Reading:

Close Date: 02/13/2015

Problem?

Left rear warning light not working (above tail light) T21

Task performed:

Travel to ST 21. Replaced LED light on rear left. Traced and repaired broken ground wire to left tailboard. OK.

Parts

Quantity

60R00FRR600 SERIES RED LED W/O FLANGE

1

Workorder: V73124

In Date: 02/13/2015

Meter Reading:

72,223.10

Close Date: 02/20/2015

Problem?

air leak

Task performed:

Travel to ST 21. Replaced leaking air switch in dash.

Parts

Quantity

FSC17492134NC SW PARK BK SPADE TYPE CONNECTOR

1



1/10/2023

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142546

*** FREIGHLINER TANKER TRUCK**

Workorder: V73388

In Date: 02/24/2015

Meter Reading:

Close Date: 02/27/2015

Problem?

Left bumper marker light out. All ready fix by Levy. T21

Task performed:

Parts

Quantity

Replaced blown marker light.

194BULB

10

Workorder: V74361

In Date: 04/01/2015

Meter Reading:

Close Date: 05/04/2015

Problem?

Rob Levy replaced equipememnt mount on tailboard. T21

Task performed:

Parts

Quantity

1. Installed equipment mounts on tail board.

NO PARTS USED

Workorder: V74654

In Date: 04/14/2015

Meter Reading:

Close Date: 07/07/2015

Problem?

USE FOR ANOTHER JOB

Task performed:

Parts

Quantity

NO PARTS USED



Palm Beach County Fire Rescue

Fleet Maintenance Asset History

Asset: (10142546) 2003 - FERRARA FLD120SD Tender St3

10142546

CSHOP-2015-1358

Comments: **FLAT DRAFTING STRAINER MISSING PIVOT BOLT. LOOKS LIKE 1/2" BOLT AND WASHERS WITH LOCKTIGHT NEEDED T21**

Date Opened: 6-24-2015 Date Finished: 6-25-2015 Meter 1 Reading: 73,331

TASKS PERFORMED

NO PARTS USED

FIRE FIGHTING EQUIPMENT

CSHOP-2015-2092

Comments: **RIGHT LOW BEAM OUT TANKER 21**

Date Opened: 8-3-2015 Date Finished: 8-5-2015 Meter 1 Reading: 73,331

TASKS PERFORMED

Q PARTS

HEADLIGHTS LOW BEAM

1 LAMP; HEAD LAMP LOW BEAM CRYSTAL VISION

CSHOP-2015-2308

Comments: **CHECK ENGINE LIGHT AND WARNING TRIPPED T21**

Date Opened: 8-13-2015 Date Finished: 8-14-2015 Meter 1 Reading: 73,331

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
ENGINE AND ACCESSORIES

CSHOP-2015-2349

Comments: **WATER LEAK T21**

Date Opened: 8-17-2015 Date Finished: 8-20-2015 Meter 1 Reading: 73,331

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
ENGINE COOLANT TEMPERATURE SE

1 TANK; SURG TANK TANKER

CSHOP-2015-2535

Comments: **T21 C INSPECTION**

Date Opened: 8-25-2015 Date Finished: 9-21-2015 Meter 1 Reading: 75,575

TASKS PERFORMED

Q PARTS

PM SERVICE C

1 9IP; SPARK PLUG 7131
1 FILTER; FUEL FILTER 33813 L/F # LFF5851
1 9IP; AIR FILTER 46883
2 FILTER; 51971 OIL FILTER WIX
1 FILTER; FUEL FILTER 33120 WIX DELCO TP916

Asset Work Order History 10142546

CSHOP-2015-2536

Comments: **T21 REPAIRS FROM INSPECTION**

Date Opened: 8-25-2015

Date Finished

9-21-2015

Meter 1 Reading:

75,575

TASKS PERFORMED

FOAM SYSTEM
FIRE FIGHTING EQUIPMENT
FIRE APPARATUS
WIPER BLADES
FUEL TANK
EXHAUST SYSTEM
FAN BELT
COOLING SYSTEM
ENGINE AND ACCESSORIES
LIGHTING SYSTEM
ALTERNATOR-GENERATOR
DIAGNOSE ELECTRICAL
TRANSFER CASE
RETARDER
TRANSMISSION
RESERVOIR
AIR SYSTEM
EMERGENCY EQUIPMENT

Q PARTS

1 MOTOR; 108494-00 MOTOR ELECT HALE FOAM PUMP
-1 CABLE; 6 PIN CABLE HALE CONTROL
1 CABLE; 6 PIN CABLE HALE CONTROL
1 9IP; SENSOR HALE HPF FOAM FLOW
1 VALVE; CHECK VALVE INJECTOR HALE FOAM SYS.
1 PUMP; 546-3240-00-0 FOAM PUMP SENSOR KIT
1 CONTROL; FM CONTROL UNIT RETROFIT KIT
1 9IP; DISTRIBUTION BOX
1 9IP; PUMP HALE FOR FOAMMASTER
1 VALVE; 8904 VALVE KIT 1 1/2 IN
1 CABLE; 4 PIN CABLE FLOW SENSOR HALE FOAM SYS.
1 9IP; HALE CAFTEC TRANSORB ASSY. FOAM SYS
1 9IP; FILTER AIR
1 VALVE; MASTER DRAIN VALVE
2 WIPER; 5216 WIPER
2 CLAMP; EXHAUST CLAMP 33225 5 IN
3 9IP; 5 IN STAINLESS FLEX
1 CLAMP; CLAMP 5 IN
1 BELT; BELT
3 BELT; BELT
1 BULB; BULB
2 LIGHT; CLEAR BACKUP 600 SERIES
2 9IP; AMBER LENS
1 REFLECTOR; REFLECT-AMBER
1 SWITCH; EXTENDA GUN SWITCH
1 LIGHT; LIGHT MARKER LEDAMBER
1 9IP; ACCUM.KIT
1 SEAL; SEAL TRANS REAR
1 9IP; 29552377 VALVE ASSY.ACCUM
1 GASKET POWER STEERING TANKER
1 NEWPART; HOSE & FITTINGS
1 DRAIN; DRAIN COCK
1 VALVE; TURBO CUT OFF VLV KIT
1 BRAKE; CARTRIDGE DC100
1 VALVE; PURGE VALVE WABCO AIR DRYER

CSHOP-2015-3053

Comments: **NOT BUILDING AIR PRESSURE T21**

Date Opened: 9-23-2015

Date Finished

9-29-2015

Meter 1 Reading:

75,713

TASKS PERFORMED

AIR SYSTEM

Q PARTS

1 GOVERNOR; GOVERNOR D-2

Asset Work Order History 10142546

CSHOP-2015-3122

Comments: **VELCRO STRAP FOR LINE ON TAIL BOARD T21**

Date Opened: 9-28-2015 Date Finished 10-8-2015 Meter 1 Reading: 75,832

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
EQUIPMENT MOUNTING BRACKETS
REAR TIRES

Service Requests:

09/28/2015 SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW
WOULD LIKE SOME KIND OF A MOUNT OR A VELCRO STRAP MOUNT INSTALLED ON LEFT REAR TAIL BOARD AREA TO SECURE A PIGTAIL LINE THAT IS ATTACHED TO THE DIRECT FILL VALVE.

CSHOP-2015-3213

Comments: **ON-CALL T21 AIR LEAK**

Date Opened: 10-5-2015 Date Finished 10-5-2015 Meter 1 Reading: 75,832

TASKS PERFORMED

Q PARTS

AIR SYSTEM

1 SWITCH; NC SW PARK BK SPADE TYPE CONNECTOR

Service Requests:

10/04/2015 BRAKES / 18: LEAKING / TRAVEL FROM HOME TO STATION 21. PREFORMED AIR LEAK DIAGNOST
AIR LEAK BEHIND DASH. ISSUE REPAIRED BY ON CALL MECHANIC.

CSHOP-2015-3569

Comments: **T21**

Date Opened: 10-23-2015 Date Finished 11-3-2015 Meter 1 Reading: 76,149

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
HEADLIGHTS HIGH BEAM
BODY EXTERIOR

Service Requests:

10/22/2015 LIGHTS / 19: LOOSE / REPAIR
NO HIGH BEAMS BOTH SIDES, SEEMS TO BE IN THE SWITCH.

10/22/2015 BODY / 19: LOOSE / INSPECT
DUMP SHOOT APPEARS TO HAVE SHIFTED TO THE LEFT, BOLTS ARE HITTING THE BODY TRIM AND NOT ALLOWING THE SHOOT TO FULLY SLIDE BACK IN.

Asset Work Order History 10142546

CSHOP-2015-4220

Comments: **B21**

Date Opened: 11-30-2015 Date Finished 12-9-2015 Meter 1 Reading: 76,841

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
FAN BELT
TRANSMISSION

1 NEWPART; TRANSMISSION DIPSTICK

Service Requests:

11/30/2015 SERVICE REQUEST / 19: LOOSE / ADJUST
MAIN BELT NEEDS TIGHTENING ALSO TRANSMISSION DIP STICK IS SHOT, THE RUBBER STOPPER SEAL IS SWOLLEN AND FALLING APART AND WILL NO LONGER FIT IN THE HOLE AND TIGHTEN

CSHOP-2015-805

Comments: **T21 HEADLIGHTS AND FOG LAMPS NEED TO BE REPLACED CURB MIRROR PUT ON PASS SIDE DOOR**

Date Opened: 5-26-2015 Date Finished 6-2-2015 Meter 1 Reading: 73,331

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
HEADLIGHTS LOW BEAM
MIRRORS

2 LAMP; HEAD LAMP LOW BEAM CRYSTAL VISION
2 LAMP; HEAD LAMP HIGH BEAM CRYSTAL VISION
1 9IP; MIRROR 28763 GROTE

CSHOP-2016-1763

Comments: **AIR LEAK**

Date Opened: 4-14-2016 Date Finished 4-14-2016 Meter 1 Reading: 78,326

PARK BRAKE SWITCH LEAKING

TASKS PERFORMED

Q PARTS

AIR SYSTEM

1 SWITCH; NC SW PARK BK SPADE TYPE CONNECTOR

CSHOP-2016-1968

Comments: **T21**

Date Opened: 4-26-2016 Date Finished 4-26-2016 Meter 1 Reading: 78,604

TASKS PERFORMED

NO PARTS USED

A/C BELT FRONT A/C

Service Requests:

04/25/2016 ENGINE / 19: LOOSE / ADJUST
BELT SLIPPING ON FRONT OF MOTOR

Asset Work Order History 10142546

CSHOP-2016-2003

Comments: **AUX TANK FILL T21**

Date Opened: 4-27-2016

Date Finished

8-16-2016

Meter 1 Reading:

80,374

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
EQUIPMENT MOUNTING BRACKETS
TANK-RESERVOIR

1 NEWPART; HOSE AND FITTING

CSHOP-2016-2132

Comments: **T21**

Date Opened: 5-3-2016

Date Finished

5-6-2016

Meter 1 Reading:

78,762

TASKS PERFORMED

NO PARTS USED

WAIT TIME TO BE CHARGED TO WORK ORDER
TRAVEL TO BE CHARGED TO WORK ORDER
TANK-RESERVOIR

Service Requests:

05/03/2016

SERVICE REQUEST / 12: BROKEN / EXCHANGE - REBUILT

TENDER WATER SHUTE EXTENSION CAME OFF. CRIMPED WIRES BROKE LOOSE ON BOTH SIDES AND HAS BEEN REMOVED FROM THE TRUCK. WILL ONLY NEED THE WIRE AND CRIMPS TO FIX.

CSHOP-2016-2266

Comments: **TENDER 21**

Date Opened: 5-11-2016

Date Finished

5-12-2016

Meter 1 Reading:

78,947

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
TIRE
STEPS

Service Requests:

05/10/2016

TIRES / 19: LOOSE / REPAIR

RIGHT REAR FRONT OUTSIDE TIRE, SCHRADER VALVE LEAKING, TIRE LOOKED LOW AND WHILE ATTEMPTING TO CHECK THE PRESSURE IT WAS NOTED THAT THE MORE THE CAP WAS UNSCREWED THE WORSE IT LEAKED, CAP WAS RE TIGHTENED.

CSHOP-2016-236

Comments: **T21**

Date Opened: 1-19-2016

Date Finished

4-26-2016

Meter 1 Reading:

78,604

TASKS PERFORMED

Q PARTS

WAIT TIME TO BE CHARGED TO WORK ORDER
TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM

1 NEWPART; AIR TANK SOP

Service Requests:

01/18/2016

SERVICE REQUEST / 18: LEAKING / EXCHANGE - NEW

AIR LEAK, POSS AT MAIN TANK SEEMS TO BE WHERE THE NOISE IS COMING FROM. AIR GAUGE IS AT ZERO EVERY MORNING CAUSING PROLONGED RUNNING IN THE BAY, CHARGING THE BAY WITH FUMES.

Asset Work Order History 10142546

CSHOP-2016-2535

Comments: **T21**

Date Opened: 5-26-2016

Date Finished

5-26-2016

Meter 1 Reading:

79,187

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
EQUIPMENT MOUNTING BRACKETS
SERPENTINE BELT TENSIONER

Service Requests:

05/26/2016 BODY / 12: BROKEN / REPAIR
IN L2 COMPARTMENT, ANGLE ALUMINUM THAT HOLDS THE FLOAT PUMP IN PLACE ON THE LEFT SIDE HAS BROKEN OFF, IT APPEARS THAT THE RIVETS JUST NEED TO BE DRILLED OUT AND REDONE, THE PIECE IS IN THE COMPARTMENT.

05/26/2016 ENGINE / 19: LOOSE / ADJUST
ENGINE BELT SLIPPING

CSHOP-2016-2843

Comments: **T21 CHECK FOR POSSIBLE CONTAMINATION IN THE AIR SYSTEM. THE DASH VALVE SEEMS TO FAIL REGULARLY.**

Date Opened: 6-14-2016

Date Finished

6-21-2016

Meter 1 Reading:

79,593

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
QUARTZ LIGHT
AIR SYSTEM

1 SWITCH; NC SW PARK BK SPADE TYPE CONNECTOR
1 BULB; BULB

Service Requests:

06/14/2016 SERVICE REQUEST / 18: LEAKING / EXCHANGE - NEW
AIR BRAKE HANDLE LEAKING WHEN AIR BRAKE RELEASED. CONSTANT FLOW OF AIR.

CSHOP-2016-3664

Date Opened: 8-1-2016

Date Finished

8-1-2016

Meter 1 Reading:

80,100

TASKS PERFORMED

NO PARTS USED

REAR TIRES

VENDOR? DAN CALLAGHAN ENTERPRISES

Asset Work Order History 10142546

CSHOP-2016-4203

Comments: **L INTAKE 2.5", DISC #3, DIRECT FILL, REAR 2.5" DISCHARGE#2 LEAKING HOSEBED COVER PM FOLLOW UPS**

Date Opened: 8-26-2016 Date Finished 9-29-2016 Meter 1 Reading: 80,839

TASKS PERFORMED

Q PARTS

FIRE PUMP PLUMBING	1	STRAINER; STRAINER 2.5 IN
HOSE REEL	1	VALVE; 8906 VALVE KIT 2.5 IN AKRON
HOSE BED BODY	1	9IP; TEE PLASTIC
FIRE APPARATUS	1	BULB; BULB
WIPER BLADES	1	BULB; BULB
OIL PAN-GASKET	1	BULB; BULB
LIGHTING SYSTEM	2	REFLECTOR; 41032-3 RED REFLECTOR OVAL REFLECTOR
BATTERY TRAY	1	LIGHT; LIGHT MARKER LEDAMBER
SUPPORT BEARING	2	9IP; ATF DETRAN 3
FRONT AXLE	1	P/S GASKET
TIRE		
STEERING		
BODY EXTERIOR		

Service Requests:

08/24/2016 TIRES / 44: WORN / OUTSIDE VENDOR REPAIR
BAD TIRES. FRONT DRIVER SIDE. UNEVEN WEAR

CSHOP-2016-4483

Date Opened: 9-14-2016 Date Finished 9-29-2016 Meter 1 Reading: 8,839

TASKS PERFORMED

Q PARTS

PM SERVICE C	1	FILTER; FUEL FILTER 33813 L/F # LFF5851
	1	9IP; AIR FILTER 46883
	2	FILTER; 51971 OIL FILTER WIX
	38	FLUID; SYN OIL BULK QTS
	1	FILTER; FUEL FILTER 33120 WIX DELCO TP916

CSHOP-2016-4814

Date Opened: 10-5-2016 Date Finished 10-5-2016 Meter 1 Reading: 80,941

TASKS PERFORMED

NO PARTS USED

FRONT TIRES

VENDOR? ELPEX TIRE TIRESOLES

Asset Work Order History 10142546

CSHOP-2016-5052

Comments: **T-21 DOOR AJAR ON ALL THE TIME.**

Date Opened: 10-24-2016 Date Finished 10-25-2016 Meter 1 Reading: 81,257

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
DOOR

2 SWITCH; SWITCH DOOR

Service Requests:

10/23/2016 LIGHTS / 12: BROKEN / REPAIR
DOOR AJAR LIGHT IS ON WHILE IN DRIVE

CSHOP-2016-5120

Date Opened: 10-27-2016 Date Finished 10-31-2016 Meter 1 Reading: 81,407

TASKS PERFORMED

Q PARTS

FIRE FIGHTING EQUIPMENT
PARK-CLEARANCE LIGHTS

1 GROMMET; HONDA FUEL GROMMET
1 LIGHT; LIGHT MARKER LED RED

Service Requests:

10/27/2016 LIGHTS / 12: BROKEN / REPAIR
VEHICLE LIGHTS NOT WORKING. L REAR BOTTOM RUNNING LIGHT (RED) INOP

CSHOP-2016-5159

Date Opened: 10-31-2016 Date Finished 10-31-2016 Meter 1 Reading: 81,407

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE FIGHTING EQUIPMENT
DRIVE BELT

Service Requests:

10/27/2016 SERVICE REQUEST / 18: LEAKING / REPAIR
SERVICE REQUEST. FUEL LEAKING FROM BOTTOM OF GAS SELECTOR

CSHOP-2016-5823

Comments: **ON-CALL AIR LEAK**

Date Opened: 12-13-2016 Date Finished 12-28-2016 Meter 1 Reading: 82,404

TASKS PERFORMED

Q PARTS

AIR SYSTEM

1 SWITCH; NC SW PARK BK SPADE TYPE CONNECTOR
1 SWITCH; 76072-15-DC SWITCH SW76072

Asset Work Order History 10142546

CSHOP-2016-5824

Comments: **ON-CALL B19**

Date Opened: 12-13-2016 Date Finished 12-14-2016 Meter 1 Reading: 82,113

TASKS PERFORMED

NO PARTS USED

ELECTRICAL

CSHOP-2016-5881

Date Opened: 12-16-2016 Date Finished 12-19-2016 Meter 1 Reading: 82,217

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM

Service Requests:

12/15/2016 AIR RIDE / 18: LEAKING / EXCHANGE - NEW
E STOP/PARKING BREAK IS LEAKING WHEN OF POSITION.

CSHOP-2016-6046

Comments: **T-21 PRIMMER STICKING ON.**

Date Opened: 12-28-2016 Date Finished 12-30-2016 Meter 1 Reading: 82,553

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
PRIMING PUMP FIRE PUMP

1 VALVE; VALVE PRIMER PUMP W/HARDWARE

Service Requests:

12/20/2016 SERVICE REQUEST / 44: WORN / EXCHANGE - NEW
PUMP PRIMER STICKING IN THE ON POSITION. HAVE TO SHUT THE TRUCK DOWN TO DISENGAGE THE PRIMER

CSHOP-2016-6057

Comments: **T-21 HOSE CLAMP ON TAIL BOARD**

Date Opened: 12-28-2016 Date Finished 1-19-2017 Meter 1 Reading: 82,962

TASKS PERFORMED

Q PARTS

EQUIPMENT MOUNTING BRACKETS

4 STRAP; STRAP 46 IN
4 STRAP; STRAP ZICO
4 STRAP; STRAP
4 STRAP; STRAP
1 STRAP; STRAP
4 STRAP; STRAP

Service Requests:

12/28/2016 BODY / 12: BROKEN / EXCHANGE - NEW
BODY ISSUE: HOSE CLAMP ON TAIL BOARD NEEDS A STRAP, CLAMP COMES OFF ITS MOUNT WHEN DRIVING DOWN
ROUGH ROADS

Asset Work Order History 10142546

CSHOP-2016-964

Comments: T21

Date Opened: 2-29-2016

Date Finished

3-9-2016

Meter 1 Reading:

77,798

TASKS PERFORMED

Q PARTS

WAIT TIME TO BE CHARGED TO WORK ORDER
TRAVEL TO BE CHARGED TO WORK ORDER
HEADLIGHTS LOW BEAM

2 LAMP; HEAD LAMP LOW BEAM CRYSTAL VISION

Service Requests:

02/28/2016

LIGHTS / 12: BROKEN / REPLACED HEADLIGHT
PASSENGER SIDE LOW BEAM OUT

CSHOP-2017-11

Comments: T-21 CABLE ON DUMP SHOOT BROKEN.

Date Opened: 1-3-2017

Date Finished

1-3-2017

Meter 1 Reading:

82,620

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
BODY EXTERIOR

Service Requests:

12/30/2016

BODY / 12: BROKEN / REPAIR
BODY ISSUE; DUMP SHOOT OVER EXTENDER RETAINER CABLE BROKE ON RIGHT SIDE OF SHOOT

CSHOP-2017-1403

Comments: TENDER 21

Date Opened: 3-7-2017

Date Finished

3-29-2017

Meter 1 Reading:

84,992

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM

10 9IP; BULB
2 9IP; AMBER LED BULB

Service Requests:

03/07/2017

LIGHTS / 12: BROKEN / EXCHANGE - NEW
VEHICLE LIGHTS NOT WORKING PASSENGER SIDE REAR (YELLOW) STROBE ON LIGHT BAR NOT WORKING

03/07/2017

LIGHTS / 12: BROKEN / EXCHANGE - NEW
VEHICLE LIGHTS NOT WORKING 2 ROOF MARKER LIGHTS NOT WORKING

03/07/2017

LIGHTS / 12: BROKEN / EXCHANGE - NEW
VEHICLE LIGHTS NOT WORKING DRIVER SIDE FRONT BUMPER POLE LIGHT NOT WORKING

CSHOP-2017-1800

Date Opened: 3-26-2017

Date Finished

3-26-2017

Meter 1 Reading:

84,945

NOISY BELT

TASKS PERFORMED

NO PARTS USED

SERPENTINE BELT

Asset Work Order History 10142546

CSHOP-2017-2038

Comments: **T21**

Date Opened: 4-7-2017

Date Finished

4-20-2017

Meter 1 Reading:

85,464

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM

Service Requests:

04/07/2017

SERVICE REQUEST / 18: LEAKING / REPAIR

SERVICE REQUEST- AIR PRESSURE LEAK. AIR BRAKES WILL NOT RELEASE UNTIL BUILD UP PRESSURE

CSHOP-2017-2106

Date Opened: 4-11-2017

Date Finished

5-9-2017

Meter 1 Reading:

86,155

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM
INSTRUMENTS-GAUGES-METERS

Service Requests:

04/11/2017

SERVICE REQUEST / 12: BROKEN / INSPECT

SERVICE REQUEST; DIGITAL DISCHARGE READOUT DISPLAY IS CRACKED AND NOT FULLY VISIBLE (PIXELLATED)
PLEASE REPLACE DISCHARGE/VACUUM DISPLAY

CSHOP-2017-2298

Date Opened: 4-19-2017

Date Finished

4-28-2017

Meter 1 Reading:

85,796

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM
AIR SYSTEM

6 1WL; LED FLOOD/SCENE LIGHT
1 VALVE; VALVE AIR CONTROL

Service Requests:

04/19/2017

HAZARD / 12: BROKEN / NEW

HAZARDOUS ISSUE; SCENE LIGHTS VERY POOR BRIGHTNESS HARD TO SEE ANYTHING AT NIGHT. WOULD LIKE TO
GET THE NEWER BRIGHTER LED SCENE AND HEAD LIGHTS PLEASE.

CSHOP-2017-2824

Date Opened: 5-12-2017

Date Finished

5-16-2017

Meter 1 Reading:

86,260

TASKS PERFORMED

Q PARTS

TURN SIGNAL LIGHTS

1 1WL; LED TURN SIGNAL LAMP

Service Requests:

05/12/2017

LIGHTS / 12: BROKEN / EXCHANGE - NEW

VEHICLE LIGHTS NOT WORKING- LEFT REAR TURN SIGNAL OUT

Asset Work Order History 10142546

CSHOP-2017-284

Comments: **T-21 TACH, HAND LIGHT NOT WORKING**

Date Opened: 1-13-2017 Date Finished 2-15-2017 Meter 1 Reading: 83,889

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM
INSTRUMENTS-GAUGES-METERS

1 NEWPART; GUIDE LENS KIT
1 2IH; SENDER

Service Requests:

01/12/2017 SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW
SERVICE REQUEST- TACHOMETER, ONE HAND LIGHT AND DRIVER'S MAPLIGHT NOT WORKING

CSHOP-2017-2923

Date Opened: 5-17-2017 Date Finished 5-18-2017 Meter 1 Reading: 86,260

TASKS PERFORMED

NO PARTS USED

BODY EXTERIOR

Service Requests:

05/17/2017 BODY / 12: BROKEN / EXCHANGE - NEW
RETAINER CABLE ON WATER SHOOT BROKE

CSHOP-2017-2975

Date Opened: 5-19-2017 Date Finished 5-26-2017 Meter 1 Reading: 86,497

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
DISCHARGE GAUGE

2 9IP; DIDITAL VACUUM GAUGE KIT

CSHOP-2017-3129

Date Opened: 5-30-2017 Date Finished 5-31-2017 Meter 1 Reading: 86,539

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM
DOOR ALARM OR OTHER WARNING

4 9IP; 2030-7110-30 CLEAR DOME STEP
1 9IP; EXTENDA GUN SWITCH

Service Requests:

05/27/2017 LIGHTS / 35: RUSTED/CORRODED / EXCHANGE - NEW
VEHICLE LIGHTS NOT WORKING- 5 STEP LIGHTS OUT ON TAIL BOARD

Asset Work Order History 10142546

CSHOP-2017-3250

Date Opened: 6-5-2017 Date Finished 7-14-2017 Meter 1 Reading: 87,204

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM

Service Requests:

06/03/2017 AIR RIDE / 18: LEAKING / REPAIR
AIR RIDE ISSUE- AIR PRESSURE LEAK. 1-2 MINUTES FOR BRAKE RELEASE

CSHOP-2017-34

Comments: **T-21 REAR TIRES ORDERED BY EDDIE 1-3-2017**

Date Opened: 1-3-2017 Date Finished 1-10-2017 Meter 1 Reading: 82,693

TASKS PERFORMED

NO PARTS USED

REAR TIRES

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2017-3758

Date Opened: 6-26-2017 Date Finished 7-14-2017 Meter 1 Reading: 87,204

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
TURN SIGNAL LIGHTS
AIR SYSTEM

Service Requests:

06/25/2017 LIGHTS / 12: BROKEN / REPAIR
VEHICLE LIGHTS NOT WORKING; LEFT REAR TURN SIGNAL, LEFT AND CENTER PUMP PANEL LIGHTS NOT WORKING

CSHOP-2017-4152

Date Opened: 7-17-2017 Date Finished 7-17-2017 Meter 1 Reading: 87,281

TASKS PERFORMED

NO PARTS USED

COMMERCIAL WORK - OUTSIDE AGENCY

VENDOR? DAN CALLAGHAN ENTERPRISES

Asset Work Order History 10142546

CSHOP-2017-4529

Date Opened: 8-4-2017

Date Finished

8-7-2017

Meter 1 Reading:

87,546

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE FIGHTING EQUIPMENT
AIR SYSTEM

1 2FL; SWITCH, NORMAL OPEN
1 2FL; NORM CLSD 2 WIRE PRES SW

Service Requests:

08/04/2017 AIR RIDE / 18: LEAKING / FOUND PARK BRAKE SWITCH LEAKING
AIR RIDE ISSUE- LOUD AIR LEAK WHEN PARKING BRAKE IS APPLIED

08/04/2017 SERVICE REQUEST / 44: WORN / WORN CHAIN STILL OPERABLE TILL NEW CHAIN CAN BE PROV
SERVICE REQUEST- CHAINSAW CHAIN IS DULL

CSHOP-2017-4936

Date Opened: 8-23-2017

Date Finished

8-24-2017

Meter 1 Reading:

87,853

TASKS PERFORMED

Q PARTS

SIREN

1 1WL; SIREN AMPLIFIER

Service Requests:

08/23/2017 SERVICE REQUEST / 38: SHORTED / EXCHANGE - NEW
SERVICE REQUEST: SIREN NOT WORKING.

CSHOP-2017-519

Comments: **T21 REAR TURN SIGNAL NOT WORKING AND LENSES CRACKED.**

Date Opened: 1-23-2017

Date Finished

1-26-2017

Meter 1 Reading:

83,221

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
TURN SIGNAL LIGHTS

1 LAMP; LED TURN SIGNAL LAMP

Service Requests:

01/23/2017 LIGHTS / 12: BROKEN / EXCHANGE - NEW
VEHICLE LIGHTS NOT WORKING RIGHT REAR TURN SIGNAL NOT WORKING PROPERLY, BOTH REAR TURN SIGNAL
LENSES ALSO CRACKED AND FADED.

CSHOP-2017-535

Date Opened: 1-24-2017

Date Finished

2-15-2017

Meter 1 Reading:

83,889

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
SEAT FRONT

1 2FL; AIR SPRING SEAT

Service Requests:

01/24/2017 SERVICE REQUEST / 18: LEAKING / EXCHANGE - NEW
SERVICE REQUEST- AIR PRESSURE IN DRIVERS SEAT HAS A PRETTY FAST AIR LEAK.

01/28/2017 SERVICE REQUEST / 12: BROKEN / REPAIR
SERVICE REQUEST CENTER LIGHT OVER PUMP PANEL OUT.

Asset Work Order History 10142546

CSHOP-2017-5521

Comments: **USE A FORM**

Date Opened: 9-22-2017

Date Finished

10-12-2017

Meter 1 Reading:

88,532

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 FIL; NAPAGOLD FUEL FILTER
78 FLUID; SYN OIL BULK QTS
1 FIL; NAPAGOLD FUEL FILTER
-78 9OC; SYN 15W40
38 9OC; SYN 15W40
40 9OC; SYN 15W40
2 FIL; NAPAGOLD OIL FILTER

CSHOP-2017-5531

Comments: **REPAIRS FROM PM**

Date Opened: 9-23-2017

Date Finished

10-12-2017

Meter 1 Reading:

88,568

TASKS PERFORMED

Q PARTS

INTAKE VALVE
SMALL ENGINE REPAIR
WIPERS-WASHER
LIGHTING SYSTEM
TRANSFER CASE
RESERVOIR
AIR SYSTEM

1 9IP; BULB
3 9IP; BULB
1 1WL; LED FLOOD/SCENE LIGHT
1 LMP; BULB
5 LMP; BULB
2 9LL; BULB
1 8AV; 194 LED AMBER (ADVANCED)
1 NONSTOCK; FREIGHT CHARGE
1 5TN; VPS SHIFT CONTROL PUMP KIT
2 NOS; NAPA OIL SEAL
1 5SC; MIV-M PNL PLCRD & HARNESS
2 9IP; GASKET GEARBOX COVER
2 9IP; GASKET GEARBOX COVER
4 MAC; NON-CHLOR BRAKE CLNR
10 9IP; ALLISON TRANS FLUID GAL
10 9IP; ALLISON TRANS FLUID GAL
6 9IP; ATF DETRAN 3
-10 9OC; BULK TRANS SYN
10 9OC; BULK TRANS SYN
1 9IP; FG/HF6238 PS/HDY FILTER
1 2FL; PS GASKET
2 NTH; ADAPTER

Asset Work Order History 10142546

CSHOP-2017-5811

Date Opened: 10-10-2017 Date Finished 12-28-2017 Meter 1 Reading: 89,771

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
SERPENTINE BELT
LIGHTING SYSTEM

Service Requests:

-
- 10/06/2017 ENGINE / 49: CAN NOT DUPLICATE CONCERN / INSPECT ENGINE
 - 10/09/2017 ENGINE / 19: LOOSE / ADJUST ENGINE BELT SLIPPING
 - 10/09/2017 LIGHTS / 38: SHORTED / REPAIR VEHICLE SCENE LIGHTS ON RIGHT SIDE ARE INTERMITTENT; A LIGHT IS OUT ON PUMP PANEL AS WELL
-

CSHOP-2017-5843

Date Opened: 10-10-2017 Date Finished 12-28-2017 Meter 1 Reading: 89,771

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
COMMERCIAL WORK - OUTSIDE AGENCY
HOSE REEL
HOSE-LINES & FITTINGS

- 1 9HY; 1" 90 FXF STEEL 4000 PSI SUPER SWL JT
- 1 9HY; SWIVEL, 1/2 NPT 90 DEG HANNAY
- 1 9HY; SWIVEL, 1/2 NPT 90 DEG HANNAY

Service Requests:

-
- 10/10/2017 SERVICE REQUEST / 11: BINDS/STICKS / EXCHANGE - NEW
SERVICE REQUEST; HOSE REEL IS LOCKED UP AND WILL NOT TURN. CHECKED REEL LOCK AND IT IS FREE. APPEARS TO BE WHERE THE PIPING FITTING ENTERS AND ATTACHES TO THE REEL. NOT SWIVELING AS THE REEL TRIES SPIN.
 - 11/27/2017 LIGHTS / 38: SHORTED / INSPECT
PASSENGER SIDE SCENE LIGHTS COME ON BRIEFLY THEN GO OFF.
-

CSHOP-2017-6388

Date Opened: 11-6-2017 Date Finished 11-7-2017 Meter 1 Reading: 89,013

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM

- 2 2FL; SWITCH, NORMAL OPEN
- 2 2FL; NORM CLSD 2 WIRE PRES SW

Service Requests:

-
- 11/06/2017 BRAKES / 12: BROKEN / EXCHANGE - NEW
AIR TRANSFER SWITCH BEHIND DASH AT THE PARKING BREAK KNOB AREA LEAKING.
-

Asset Work Order History 10142546

CSHOP-2017-661

Comments: **T21 LIGHTS NOT WORKING**

Date Opened: 1-31-2017 Date Finished 1-31-2017 Meter 1 Reading: 83,314

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM

Service Requests:

01/31/2017 LIGHTS / 12: BROKEN / REPAIR
VEHICLE LIGHTS NOT WORKING- MIDDLE PANEL LIGHT NOT WORKING

CSHOP-2017-6924

Comments: **T21**

Date Opened: 12-4-2017 Date Finished 12-11-2017 Meter 1 Reading: 89,495

TASKS PERFORMED

NO PARTS USED

REAR TIRES

VENDOR? DAN CALLAGHAN ENTERPRISES

Service Requests:

12/04/2017 SERVICE REQUEST / 18: LEAKING / EXCHANGE - NEW
SERVICE REQUEST- DRIVERS SIDE OUTSIDE REAR TIRE NEEDS REPLACED. BRIDGESTONE R268, 12R22.5

CSHOP-2017-701

Comments: **T21**

Date Opened: 2-2-2017 Date Finished 2-9-2017 Meter 1 Reading: 83,608

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
EQUIPMENT MOUNTING BRACKETS

Service Requests:

02/02/2017 SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW
SERVICE REQUEST- E-Z LOCK FITTING MOUNT ON TOP OF FRONT PASSENGER SIDE COMPARTMENT IS BROKEN.
NEEDS TO BE REPLACED

Asset Work Order History 10142546

CSHOP-2017-7123

Date Opened: 12-13-2017 Date Finished 12-28-2017 Meter 1 Reading: 89,771

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
INTAKE VALVE
LIGHT BAR

2 1WL; CORNER TUBE REFELCTOR

Service Requests:

12/13/2017 SERVICE REQUEST / 38: SHORTED / EXCHANGE - NEW
LIGHT BAR ON L SIDE (BULB IS BURNT OUT) RUNNING LIGHT IN THE REAR L SIDE IS HANGING BY THE WIRE

12/15/2017 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / INSPECT
PIV NEEDS TO BE REPLACED. O-RING KEEPS PUSHING INTO VALVE AND NOT LETTING PIV CLOSE ALL THE WAY.
DISCHARGE GAUGE IS FALLING OUT OF PUMP PANEL,

CSHOP-2017-7197

Date Opened: 12-18-2017 Date Finished 12-18-2017 Meter 1 Reading: 89,552

TASKS PERFORMED

NO PARTS USED

REAR TIRES

Service Requests:

12/15/2017 TIRES / 44: WORN / INSPECT
RIGHT REAR AXLE, BOTH TIRES NEED REPLACED. BRIDGESTONE R268 12R 22.5

CSHOP-2017-7260

Date Opened: 12-20-2017 Date Finished 12-20-2017 Meter 1 Reading: 89,555

TASKS PERFORMED

Q PARTS

CRANKING SYSTEM

1 9IP; SWITCH - BATTERY -MASTER

CSHOP-2018-1589

Date Opened: 3-19-2018 Date Finished 3-22-2018 Meter 1 Reading: 91,248

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
TURN SIGNAL LIGHTS
BATTERY

4 1AD; BATTERY 31 SERIES

Service Requests:

03/19/2018 ENGINE / 43: WEAK / EXCHANGE - NEW
ENGINE CRANKING VERY SLOW ESPECIALLY AFTER SITTING OVER NIGHT, DATES ON BATTERIES INSTALLED 1-14

03/21/2018 LIGHTS / 19: LOOSE / ADJUST
LEFT REAR TURN SIG OUT

Asset Work Order History 10142546

CSHOP-2018-1841

Date Opened: 4-2-2018 Date Finished 4-10-2018 Meter 1 Reading: 91,837

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
HEADLIGHTS LOW BEAM

2 9AP; JW SPEAKER LOW BEAM

Service Requests:

03/31/2018 LIGHTS / 38: SHORTED / EXCHANGE - NEW
VEHICLE LIGHTS NOT WORKING-PASSENGER LOW BEAM OUT

CSHOP-2018-2108

Date Opened: 4-16-2018 Date Finished 4-16-2018 Meter 1 Reading: 91,924

TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2018-2211

Date Opened: 4-20-2018 Date Finished 5-15-2018 Meter 1 Reading: 92,352

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM

1 LIT; LED M C LAMP

Service Requests:

04/20/2018 SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW
LIGHTS.....DRIVER SIDE REAR STEP LIGHT OUT. PASSENGER SIDE BOTH SCENE LIGHTS OUTS.

04/20/2018 SERVICE REQUEST / 18: LEAKING / INSPECT
PASSENGER SIDE PIV NOT OPERATING PROPERLY. UNABLE TO FULLY CLOSE.

04/28/2018 LIGHTS / 12: BROKEN / EXCHANGE - NEW
VEHICLE LIGHTS NOT WORKING.....LEFT REAR DRIVER SIDE BULLET LIGHT IS MISSING. THE POLE LIGHT ON THE
FRONT BUMPER DRIVER SIDE IS MISSING A BRACKET.

CSHOP-2018-26

Date Opened: 1-2-2018 Date Finished 1-2-2018 Meter 1 Reading: 89,829

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM
BACK UP CAMERA-MONITOR

Service Requests:

12/29/2017 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / INSPECT
SERVICE REQUEST- BACK UP CAMERA PICTURE NOT CLEAR. ALSO PUMP PANEL LIGHT WORKS INTERMITTENTLY

Asset Work Order History 10142546

CSHOP-2018-3237

Comments: **AIR LEAK IN DASH**

Date Opened: 6-11-2018

Date Finished

7-3-2018

Meter 1 Reading:

92,914

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM
INSTRUMENTS-GAUGES-METERS
A/C BELT FRONT A/C

1 2FL; SWITCH, NORMAL OPEN
2 9IP; XE-IO3100PT3-S0B 600 TRANSDUCER INT
1 2FR; TANKVISION (FOAM KIT)
1 NBH; POWERBANDVBELT
1 NBH; POWERBANDVBELT

Service Requests:

06/10/2018 ENGINE / 44: WORN / EXCHANGE - NEW
MAIN BELT SLIPPING

06/10/2018 LIGHTS / 38: SHORTED / EXCHANGE - NEW
FOAM GAUGE READING EMPTY

CSHOP-2018-4011

Date Opened: 7-16-2018

Date Finished

7-16-2018

Meter 1 Reading:

93,278

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
EQUIPMENT MOUNTING BRACKETS

Service Requests:

07/16/2018 SERVICE REQUEST / 19: LOOSE / REPAIR
FLAT DRAFTING STRAINER BOLTS ARE GONE. VIBRATED OUT

CSHOP-2018-4054

Date Opened: 7-18-2018

Date Finished

7-24-2018

Meter 1 Reading:

93,400

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM
SEAT FRONT

Service Requests:

07/18/2018 SERVICE REQUEST / 19: LOOSE / REPAIR
SMALL ENGINE OIL LEAK & AIR LEAK, PROBABLY AT DRIVER'S SEAT

07/20/2018 BRAKES / 19: LOOSE / REPAIR
BRAKE ISSUES- LARGE AIR LEAK COMING FROM PARKING BRAKE WHEN PUSHED IN.

CSHOP-2018-4102

Date Opened: 7-22-2018

Date Finished

7-24-2018

Meter 1 Reading:

93,400

TASKS PERFORMED

Q PARTS

AIR SYSTEM

1 BK; SWITCH
3 2FL; NORM CLSD 2 WIRE PRES SW

Asset Work Order History 10142546

CSHOP-2018-4561

Date Opened: 8-14-2018 Date Finished 8-15-2018 Meter 1 Reading: 93,777

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM
BELT(S)- A-C COMPRESSOR

Service Requests:

06/30/2018 LIGHTS / 12: BROKEN / REPAIR
VEHICLE LIGHTS NOT WORKING.....OF THE GROUP 4 WHITE LIGHTS THAT ARE ON THE REAR OF THE TENDER, THE
TOP RIGHT SIDE LIGHT IS OUT

CSHOP-2018-4837

Date Opened: 8-27-2018 Date Finished 9-5-2018 Meter 1 Reading: 94,089

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
BACK-UP ALARM

1 BK; BACK-UP ALARM

Service Requests:

08/24/2018 ALARMS / 12: BROKEN / EXCHANGE - NEW
ALARM SIGNALS; BACK UP ALARM NOT WORKING

CSHOP-2018-4865

Date Opened: 8-27-2018 Date Finished 8-27-2018 Meter 1 Reading: 93,922

TASKS PERFORMED

NO PARTS USED

TIRES ALL

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2018-5757

Date Opened: 10-11-2018 Date Finished 11-6-2018 Meter 1 Reading: 95,560

SERVICE COOLANT, REPLACE CAP

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
FOAM SYSTEM
COOLING SYSTEM

1 5HP; STRAINER 6
1 9IP; CHECK VALVE INJECTOR HALE FOAM SYS
1 BK; RADIATOR CAP
-12 9OC; COOLANT
12 9OC; COOLANT
12 FLUID; COOLANT ANTIFREEZE GAL

Service Requests:

10/11/2018 SERVICE REQUEST / 18: LEAKING / EXCHANGE - NEW
FOAM CONCENTRATE IS LEAKING INTO THE PUMP

Asset Work Order History 10142546

CSHOP-2018-5959

Date Opened: 10-19-2018 Date Finished 11-2-2018 Meter 1 Reading: 95,438

TASKS PERFORMED

Q PARTS

PM SERVICE C

36 4PC; 15W40 PREMIUM BLUE OIL
2 FIL; NAPAGOLD OIL FILTER
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPAGOLD FUEL FILTER

CSHOP-2018-6447

Date Opened: 11-13-2018 Date Finished 11-30-2018 Meter 1 Reading: 95,947

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM

Service Requests:

11/12/2018 ALARMS / 18: LEAKING / REPAIR
AIR LEAK

CSHOP-2018-6599

Comments: **DUMP CABLE BROKEN AT HQ**

Date Opened: 11-20-2018 Date Finished 11-27-2018 Meter 1 Reading: 95,903

TASKS PERFORMED

NO PARTS USED

FIRE APPARATUS

CSHOP-2018-6660

Date Opened: 11-26-2018 Date Finished 11-30-2018 Meter 1 Reading: 95,947

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
REAR TIRES

Service Requests:

11/23/2018 TIRES / 44: WORN / INSPECT
BAD TIRES, BALD DRIVERS SIDE REAR BACK TIRE TIRE SIZE 12R22.5 R268

CSHOP-2018-6756

Date Opened: 11-29-2018 Date Finished 11-30-2018 Meter 1 Reading: 95,947

TASKS PERFORMED

NO PARTS USED

INTAKE VALVE

Service Requests:

11/28/2018 SERVICE REQUEST / 18: LEAKING / INSPECT
PIV VALVE PISTON SEAL GASKET GONE AFTER TRAINING, WON'T SEAL, TAKEN OUT OF SERVICE.

Asset Work Order History 10142546

CSHOP-2018-6855

Date Opened: 12-3-2018 Date Finished 12-3-2018 Meter 1 Reading: 96,015

TASKS PERFORMED

NO PARTS USED

TIRES ALL

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2018-6903

Comments: **PUMP TEST REPAIRS SCANNED IN ON RELATED FILES**

Date Opened: 12-5-2018 Date Finished 4-26-2019 Meter 1 Reading: 97,978

DECK GUN ALARM

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS	1	5HP; MIVREPLVLVDISCKIT
FIRE PUMP	1	BK; SPRAYER
PARK-CLEARANCE LIGHTS	1	9IP; GASKET
BELT	1	9HY; GASKETMATERIAL
ABS CODES	-1	5AB; VALVE, 4" DISCHARGE
REAR BRAKE PADS-SHOES	1	5AB; VALVE, 4" DISCHARGE
AIR DRIER	1	9HD; MOD SOLEN VLV ADP KT
DOOR ALARM OR OTHER WARNING	4	TWD; BRAKE DRUM
	12	9AP; BRAKE CLEAN
	4	MBI; GRIP/KIT
	1	FIL; NAPAGOLD AIR FILTER
	6	LMP; LAMP
	1	TWD; VALVE KT
	1	TWD; PURGE VALVE KIT
	1	5TF; REED SWITCH KIT, EXTENDA GUN

Service Requests:

01/25/2019 SERVICE REQUEST / 11: BINDS/STICKS / INSPECT
TYPE PROBLEM INTO DESCRIPTION. MASTER INTAKE VALVE IS STUCK AND WILL NOT TURN OPEN OR CLOSED.THIS TENDER IS A SPARE THAT STATION 14 JUST RECEIVED.

CSHOP-2018-7058

Date Opened: 12-12-2018 Date Finished 1-2-2019 Meter 1 Reading: 96,597

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

Service Requests:

12/12/2018 LIGHTS / 18: LEAKING / REPAIR
VEHICLE LIGHTS NOT WORKING- LEFT REAR TURN SIGNAL OUT. ALSO LOUD AIR LEAK BEHIND DASHBOARD

Asset Work Order History 10142546

CSHOP-2018-7286

Date Opened: 12-26-2018 Date Finished 1-17-2019 Meter 1 Reading: 96,942

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM

1 TWD; E-6VALVE BRAKE

Service Requests:

12/22/2018 AIR RIDE / 18: LEAKING / EXCHANGE - NEW
AIR RIDE ISSUE- AIR LEAK GETTING WORSE TODAY. AIR NOISE BEHIND DASHBOARD

CSHOP-2018-739

Date Opened: 2-5-2018 Date Finished 2-9-2018 Meter 1 Reading: 90,495

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
FAN BELT
PARK-CLEARANCE LIGHTS

2 LIT; LED M C LAMP

Service Requests:

02/05/2018 ENGINE / 19: LOOSE / ADJUST
ENGINE FAN BELT SQUEALING EXCESSIVELY.

02/05/2018 LIGHTS / 12: BROKEN / EXCHANGE - NEW
VEHICLE LIGHTS NOT WORKING DRIVER SIDE REAR TOP MARKER LIGHT MISSING

CSHOP-2018-7400

Date Opened: 12-31-2018 Date Finished 12-31-2018 Meter 1 Reading: 96,597

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
DRIVE BELT

Service Requests:

12/30/2018 ENGINE / 19: LOOSE / ADJUST
ENGINE- BELTS SQUEALING, ESPECIALLY WHEN A/C IS ON

CSHOP-2018-76

Date Opened: 1-4-2018 Date Finished 2-7-2018 Meter 1 Reading: 90,487

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM

Service Requests:

01/04/2018 LIGHTS / 49: CAN NOT DUPLICATE CONCERN / INSPECT
VEHICLE LIGHTS NOT WORKING- BOTH RIGHT SIDE FLOOD LIGHTS AND TOP. LEFT REAR STEP LIGHT OUT

Asset Work Order History 10142546

CSHOP-2019-1005

Date Opened: 2-22-2019 Date Finished 3-12-2019 Meter 1 Reading: 97,774

TASKS PERFORMED

Q PARTS

AIR SYSTEM

1 2FL; NORM CLSD 2 WIRE PRES SW

CSHOP-2019-1155

Comments: **CALLAGHAN NOTIFIED**

Date Opened: 3-4-2019 Date Finished 3-11-2019 Meter 1 Reading: 97,774

TASKS PERFORMED

NO PARTS USED

TIRES ALL

VENDOR? DAN CALLAGHAN ENTERPRISES

Service Requests:

03/03/2019 TIRES / 19: LOOSE / REPAIR
BAD TIRES- OFFICER SIDE REAR TIRE NEEDS TO BE REPLACED

CSHOP-2019-1244

Date Opened: 3-7-2019 Date Finished 3-14-2019 Meter 1 Reading: 97,774

TASKS PERFORMED

Q PARTS

HUB CAP

1 9AP; LUCAS SYN 75W90
1 CR; HUB CAP

CSHOP-2019-237

Date Opened: 1-14-2019 Date Finished 1-17-2019 Meter 1 Reading: 96,942

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM

Service Requests:

01/14/2019 AIR RIDE / 18: LEAKING / EXCHANGE - NEW
AIR RIDE ISSUE- AIR LEAKS DOWN TO 0 PSI. HEAR INTERMITTENT LEAK BEHIND DASHBOARD

CSHOP-2019-4534

Comments: **SPARE AT ST7**

Date Opened: 8-26-2019 Date Finished 10-1-2019 Meter 1 Reading: 99,783

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
WATER TANK LEVEL LIGHTS

1 2FR; TANKVISIONWATERKIT

Service Requests:

08/26/2019 SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW
TANK WATER LEVEL LIGHT INTERMITTENT, RIGHT SCENE LIGHT OUT

Asset Work Order History 10142546

CSHOP-2019-4937

Date Opened: 9-18-2019 Date Finished 10-4-2019 Meter 1 Reading: 99,894

TASKS PERFORMED

NO PARTS USED

LIGHTING SYSTEM

Service Requests:

09/18/2019 LIGHTS / 49: CAN NOT DUPLICATE CONCERN / INSPECT
VEHICLE LIGHTS NOT WORKING PASSENGER SIDE SCENE LIGHTS INOP PUMP ENGAGED LIGHT ON PUMP
TRANSFER SWITCH IS ALWAYS LIT

CSHOP-2019-5067

Date Opened: 9-25-2019 Date Finished 11-1-2019 Meter 1 Reading: 100,298

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM

1 LIT; LED M C LAMP

Service Requests:

09/25/2019 LIGHTS / 12: BROKEN / EXCHANGE - NEW
DRIVER SIDE , SMALL REAR EMERGENCY LIGHT, MISSING RED CONE LENS AND BULB

CSHOP-2019-5654

Date Opened: 10-28-2019 Date Finished 11-1-2019 Meter 1 Reading: 100,298

TASKS PERFORMED

NO PARTS USED

FAULT CODE
TURN SIGNAL LIGHTS

Service Requests:

10/26/2019 LIGHTS / 23: NOT CONNECTED / REPAIR
VEHICLE TURN SIGNALS AND FLASHERS NOT WORKING

10/26/2019 ENGINE / 49: CAN NOT DUPLICATE CONCERN / INSPECT
ENGINE POSSIBLY. CAUTION LIGHT ILLUMINATED ON FUNCTION DISPLAY SCREEN

Asset Work Order History 10142546

CSHOP-2019-5830

Comments: **USE FOR PM FOLLOW UPS SCANNED TO FILES**

Date Opened: 11-6-2019

Date Finished 3-10-2020

Meter 1 Reading: 100,868

TASKS PERFORMED

WIPER BLADES
FAN BELT
ALTERNATOR-GENERATOR
TRANSMISSION
TIE ROD ENDS OUTER
FRONT BRAKE PADS-SHOES
AIR HORN
BELT(S)- A-C COMPRESSOR

Q PARTS

2 1AN; 16" WIPER BLADE
3 NBH; V-BELT
1 1AD; ALTERNATOR 3 BOLT
1 2DD; 2DD
1 2DD; 2DD
1 2DD; SWITCH PRESSURE ALLISON
1 2DD; MODULE TRANS CONTROL
1 TWD; TIE ROD END
1 TWD; TWD
2 TWD; BRAKE DRUM 15 X 4
2 TWD; BRAKE SHOE KITS NEW
2 PTX; PERMATEX
1 NBH; POWERBAND V BELT

Service Requests:

11/06/2019 ELECTRICAL / 12: BROKEN / INSPECT
VEHICLE HORN SOUNDS OFF BY ITSELF INTERMITTENTLY. POSSIBLE SHORT IN WIRE.

CSHOP-2019-6298

Date Opened: 12-4-2019

Date Finished 12-18-2019

Meter 1 Reading: 100,755

TASKS PERFORMED

BRAKES

Q PARTS

1 8GR; SWITCH AIR PRESSURE

Service Requests:

12/04/2019 AIR RIDE / 18: LEAKING / EXCHANGE - NEW
THE BRAKE RELEASE IS LOSING AIR AND MAKING LOUD HISSING SOUND.

CSHOP-2019-6357

Comments: **SPARE AT 14**

Date Opened: 12-9-2019

Date Finished 12-18-2019

Meter 1 Reading: 100,755

TASKS PERFORMED

AIR SYSTEM

NO PARTS USED

Service Requests:

12/07/2019 SERVICE REQUEST / 18: LEAKING / REPAIR
TYPE PROBLEM INTO DESCRIPTION----AIR BRAKE KNOB LEAKS WHEN RELEASED

Asset Work Order History 10142546

CSHOP-2019-6691

Date Opened: 12-28-2019 Date Finished 1-3-2020 Meter 1 Reading: 100,868

TASKS PERFORMED

Q PARTS

PM SERVICE C

40 4PC; 15W40 PREMIUM BLUE OIL
2 FIL; NAPAGOLD OIL FILTER
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPAGOLD AIR FILTER

CSHOP-2020-1615

Comments: **SPARE TENDER AT 22**

Date Opened: 3-20-2020 Date Finished 4-10-2020 Meter 1 Reading: 101,119

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
HOSE REEL
TURN SIGNAL LIGHTS

1 6HR; MOTOR BOOSTER REEL
1 TWD; CIRCUIT BREAKER
1 2PR; STARTER SOLENOID EONE PRESTOLITE
1 TWD; CIRCUIT BREAKER
1 5TF; GAUGE CROSSFIRE
1 LMP; LAMP

Service Requests:

03/20/2020 SERVICE REQUEST / 12: BROKEN / REPAIRED
TYPE PROBLEM INTO DESCRIPTION HOSE REAL REWIND NOT WORKING

03/20/2020 LIGHTS / 49: CAN NOT DUPLICATE CONCERN / REPAIR
VEHICLE LIGHTS NOT WORKING RIGHT SIDE SCENE LIGHTS WORK INTERMITTENT (THEY COME ON AND OFF WHEN SWITCH ON)

03/20/2020 LIGHTS / 49: CAN NOT DUPLICATE CONCERN / REPAIR
VEHICLE LIGHTS NOT WORKING LEFT SIDE TURN SIGNAL ON MIRROR NOT WORKING

CSHOP-2020-1972

Date Opened: 4-13-2020 Date Finished 4-16-2020 Meter 1 Reading: 101,199

TASKS PERFORMED

Q PARTS

PRESSURE SWITCH
BELT

1 9HD; SWITCH 745 275083

CSHOP-2020-3260

Comments: **SPARE TENDER AT 22**

Date Opened: 6-22-2020 Date Finished 7-5-2020 Meter 1 Reading: 101,755

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM

Service Requests:

06/20/2020 LIGHTS / 12: BROKEN / REPAIR
VEHICLE LIGHTS NOT WORKING, PASSENGER SIDE SCENE LIGHTS BOTH FRONT AND BACK ARE NOT WORKING

Asset Work Order History 10142546

CSHOP-2020-4680

Date Opened: 9-9-2020

Date Finished

9-18-2020

Meter 1 Reading:

102,260

TASKS PERFORMED

Q PARTS

DISCHARGE GAUGE	1	5CS; TRANSDUCER 600PSI CLASS 1
FIRE APPARATUS	1	LIT; LED M C LAMP
LIGHTING SYSTEM	8	6WL; LIGHT CLR LED PUMP PNL
FRAME	4	LIT; LED M C LAMP
AIR SYSTEM	1	9AP; METAL TREATMENT
DOOR	1	5PF; DOOR SWITCH CONNECTOR
HVAC SYSTEM	1	5PF; SWITCH DOOR DPST NC MOM

Service Requests:

05/12/2020	SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW TYPE PROBLEM INTO DESCRIPTION - DOOR AJAR WILL NOT TURN OFF AFTER ALL DOORS HAVE BEEN CHECKED AND RECLOSED.
06/19/2020	SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / INSPECT TYPE PROBLEM INTO DESCRIPTION- SIGNIFICANT AIR LEAK. 2 MIN WHEN COLD FOR BRAKES TO RELEASE
06/19/2020	SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW TYPE PROBLEM INTO DESCRIPTION- DIGITAL PUMP PRESSURE GAUGE NOT WORKING

CSHOP-2020-5110

Date Opened: 9-29-2020

Date Finished

9-29-2020

Meter 1 Reading:

102,260

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2020-6021

Date Opened: 11-16-2020

Date Finished

12-1-2020

Meter 1 Reading:

102,260

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER BRAKES	2	2FL; NORM CLSD 2 WIRE PRES SW
---	---	-------------------------------

Service Requests:

11/14/2020	BRAKES / 12: BROKEN / REPAIR BRAKE ISSUES
11/14/2020	BRAKES / 18: LEAKING / REPAIR BRAKE ISSUES. WHEN PARKING BRAKE IS RELEASED THERE IS A CONTINUOUS AIR LEAKING SOUND IN THE AREA OF THE PARKING BRAKE KNOB. WITH TANK PSI BUILT UP AND ENGINE AT IDLE IT TAKES APPROXIMATELY 2 MINUTES FOR LOW PSI ALARM TO SOUND. WHEN ENGINE RPMS ARE ADVANCED THE UNIT IS ABLE MAINTAIN CORRECT PSI.
11/16/2020	BRAKES / 18: LEAKING / REPAIR PARKING BRAKE RELEASE BLOWS AIR OUT CONSTANTLY WHEN DRIVING

Asset Work Order History 10142546

CSHOP-2020-6635

Comments: **PLEASE TURN IN INSPECTION FORM BEFORE CONTINUING WITH LUBE OIL FILTERS AND REPAIRS**

Date Opened: 12-21-2020 Date Finished 12-26-2020 Meter 1 Reading: 102,899

TASKS PERFORMED

NO PARTS USED

PM SERVICE B

CSHOP-2020-6673

Date Opened: 12-22-2020 Date Finished 1-19-2021 Meter 1 Reading: 102,899

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS	2	5CS; GAUGE 3 5 30 600 WH
DISCHARGE GAUGE	38	4PC; 15W40 PREMIUM BLUE OIL
ENGINE AND ACCESSORIES	2	FIL; NAPAGOLD OIL FILTER
PARK-CLEARANCE LIGHTS	1	FIL; NAPAGOLD FUEL FILTER
ALTERNATOR-GENERATOR	1	FIL; NAPAGOLD FUEL FILTER
DRIVE BELT	1	LIT; LED M C LAMP
AIR HORN	1	1AD; ALTERNATOR 3 BOLT
BODY EXTERIOR	4	CRC; CLEAN R CARB 200Z
	1	NBH; PWR BELT
	3	NBH; V-BELT

CSHOP-2021-1427

Comments: **SPARE TENDER AT TRAINING**

Date Opened: 3-16-2021 Date Finished 4-12-2021 Meter 1 Reading: 103,594

TASKS PERFORMED

Q PARTS

EQUIPMENT MOUNTING BRACKETS	1	9ES; BUMPER POLE LIGHT
LIGHTING SYSTEM		
ELECTRICAL		

Service Requests:

- 03/15/2021 SERVICE REQUEST / 38: SHORTED / REPAIR
ELECTRIC HORN BLOWS AT RANDOM TIMES WHILE DRIVING
- 03/18/2021 LIGHTS / 38: SHORTED / EXCHANGE - NEW
RIGHT FRONT MARKER LIGHT OUT.
- 03/21/2021 SERVICE REQUEST / 19: LOOSE / REPAIR
REQUEST VELCRO STRAPS BE ADDED (AS A SAFETY MEASURE) TO THE LEFT SIDE WHERE STRAINERS MOUNT

CSHOP-2021-1873

Date Opened: 4-9-2021 Date Finished 4-15-2021 Meter 1 Reading: 103,719

TASKS PERFORMED

NO PARTS USED

DOOR

Service Requests:

- 04/08/2021 SERVICE REQUEST / 38: SHORTED / ADJUST
B14 HAS A DOOR ALARM GOING OFF ALL OF THE DOORS ARE CLOSED.

Asset Work Order History 10142546

CSHOP-2021-1919

Date Opened: 4-12-2021 Date Finished 4-28-2021 Meter 1 Reading: 103,885

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM

Service Requests:

04/12/2021 LIGHTS / 38: SHORTED / INSPECT
T72 PASSENGER SIDE SCENE LIGHTS WILL TURN ON BUT WILL IMMEDIATELY FLICKER OFF.

CSHOP-2021-1946

Comments: **SPARE AT 72**
Date Opened: 4-13-2021 Date Finished 5-13-2021 Meter 1 Reading: 104,235

TASKS PERFORMED

Q PARTS

HOSE REEL 2 GRO; SWITCH

Service Requests:

04/13/2021 SERVICE REQUEST / 38: SHORTED / EXCHANGE - NEW
BOOSTER LINE RETRACT BUTTON NOT WORKING

CSHOP-2021-2378

Date Opened: 4-29-2021 Date Finished 6-23-2021 Meter 1 Reading: 104,446

TASKS PERFORMED

NO PARTS USED

LIGHTING SYSTEM

Service Requests:

04/29/2021 LIGHTS / 38: SHORTED / INSPECT
LEFT SIDE SCENE LIGHT (TOWARDS THE REAR) NOT WORKING

CSHOP-2021-2780

Date Opened: 5-20-2021 Date Finished 6-24-2021 Meter 1 Reading: 104,446

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER 4 5CS; MODULE POWER DISTIBUTION
BACK UP LIGHTS 1 FREIGHT

Service Requests:

05/19/2021 SERVICE REQUEST / 38: SHORTED / EXCHANGE - NEW
REAR BACKUP LIGHT OUT

05/20/2021 LIGHTS / 38: SHORTED / EXCHANGE - NEW
RIGHT REAR MARKER LIGHT AND AMBER SPINNING LIGHT NOT WORKING

Asset Work Order History 10142546

CSHOP-2021-4822

Date Opened: 8-25-2021 Date Finished 9-1-2021 Meter 1 Reading: 104,446

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM
DOOR HANDLES INSIDE-OUTSIDE

2 5TN; CONNECTOR DEUTSCH
1 FREIGHT
1 9IP; 41032 3 RED REFLECTOR OVAL REFLECTOR

CSHOP-2021-5046

Date Opened: 9-7-2021 Date Finished 9-13-2021 Meter 1 Reading: 104,446

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
HOSE BED BODY

4 5SC; BUCKLE ASSY W STRAPS
3 2AD; SENSOR SEAT SWITCH KIT

CSHOP-2021-5314

Comments: **WATER TANK LEVEL GAUGE NOT READING**

Date Opened: 9-21-2021 Date Finished 11-9-2021 Meter 1 Reading: 106,079

TASKS PERFORMED

NO PARTS USED

WATER TANK LEVEL LIGHTS

Service Requests:

09/21/2021 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / INSPECT
WATER LEVEL GAUGE ONLY READS EMPTY

CSHOP-2021-5449

Date Opened: 9-28-2021 Date Finished 10-19-2021 Meter 1 Reading: 104,894

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
DOOR

Service Requests:

09/28/2021 BODY / 11: BINDS/STICKS / REPAIR
BODY ISSUE - THE DRIVER DOOR HANDLE IS STUCK AND WILL NOT OPEN. NEED TO CLIMB THROUGH THE
PASSENGER SEAT TO GET INTO THE DRIVERS SEAT.

Asset Work Order History 10142546

CSHOP-2021-5501

Comments: **TANK LIGHTS**

Date Opened: 9-30-2021 Date Finished 11-1-2021 Meter 1 Reading: 105,079

TASKS PERFORMED

Q PARTS

WATER TANK LEVEL LIGHTS
EMERGENCY EQUIPMENT

1 2FR; TANKVISION WATER KIT

Service Requests:

09/29/2021 LIGHTS / 38: SHORTED / EXCHANGE - NEW
VEHICLE LIGHTS NOT WORKING THE EMERGENCY LIGHT CONTROL SCREEN IS INTERMITTENT MOST OF THE TIME
YOU CAN NOT TURN ON THE EMERGENCY LIGHTS.

09/29/2021 LIGHTS / 38: SHORTED / EXCHANGE - NEW
VEHICLE LIGHTS FOR THE TANK ARE NOT WORKING. IT IS SHOWING EMPTY WHEN THE TANK IS FULL

CSHOP-2021-5530

Date Opened: 9-30-2021 Date Finished 10-4-2021 Meter 1 Reading: 104,722

TASKS PERFORMED

NO PARTS USED

WINDOW REGULATOR

Service Requests:

09/30/2021 DOOR / 19: LOOSE / REPAIR
VEHICLE DOORS - DRIVER SIDE WINDOW IS ALL THE WAY DOWN AND WILL NOT GO UP.

CSHOP-2021-5757

Date Opened: 10-14-2021 Date Finished 11-1-2021 Meter 1 Reading: 105,079

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
HOSE REEL

Service Requests:

10/09/2021 SERVICE REQUEST / 38: SHORTED / REPAIR
BUTTON FOR THE HOSE REEL DOES NOT WORK HANDLE TO MANUALLY REEL IN THE HOSE ALSO DOES NOT FIT OR
WORK.

CSHOP-2021-5934

Date Opened: 10-22-2021 Date Finished 11-9-2021 Meter 1 Reading: 106,079

TASKS PERFORMED

NO PARTS USED

HIGH-LOW PRESSURE REGULATOR (

Service Requests:

10/21/2021 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / INSPECT
PUMP CONTROLLER ONLY OPERATES IN PRESSURE MODE

Asset Work Order History 10142546

CSHOP-2021-5957

Date Opened: 10-25-2021 Date Finished 11-1-2021 Meter 1 Reading: 105,079

TASKS PERFORMED

NO PARTS USED

FOAM SYSTEM

Service Requests:

10/23/2021 SERVICE REQUEST / 18: LEAKING / INSPECT
PRETTY SURE THAT THE ON BOARD FOAM TANK IS LEAKING INTO WATER TANK. EVERY WEEK THE WATER HAS TO BE DUMPED FOR THE FOUL SMELL AND WATER IT TOTALLY BLACK WHEN IT COMES OUT.

CSHOP-2021-6049

Date Opened: 10-29-2021 Date Finished 11-5-2021 Meter 1 Reading: 105,079

TASKS PERFORMED

NO PARTS USED

GOVERNOR

Service Requests:

10/26/2021 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / INSPECT
PRESSURE GOVERNOR DOES NOT GO INTO PRESSURE AND RPM MODE THE WAY THAT IT SHOULD.

CSHOP-2021-6253

Date Opened: 11-8-2021 Date Finished 11-9-2021 Meter 1 Reading: 105,079

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

Service Requests:

11/08/2021 ENGINE / 49: CAN NOT DUPLICATE CONCERN / INSPECT
ENGINE - ENGINE HAD A VERY HARD TIME STARTING THIS MORNING. HAPPENED THE PAST 2 SHIFTS ALSO. HAVE TO HOLD DOWN THE STARTER BUTTON FOR 20-30 SECONDS BEFORE STARTING. ONCE IT STARTS WHITE SMOKE SPEWS OUT OF THE EXHAUST FOLLOWED BY BLACK SMOKE. THEN IT CLEARS.

CSHOP-2021-6274

Date Opened: 11-9-2021 Date Finished 12-21-2021 Meter 1 Reading: 106,079

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
DOOR

1 2FL; DRIVER EXTERIOR DOOR HANDLE

Service Requests:

11/09/2021 BODY / 12: BROKEN / EXCHANGE - NEW
DRIVERS SIDE CAB DOOR WILL NOT OPEN USING THE INTERIOR OR EXTERIOR LEVERS. ALSO TRIED THE IGNITION KEY IN DOOR LOCK AND PULLING UP ON THE INTERIOR MANUAL PUSH BUTTON LOCK.

Asset Work Order History 10142546

CSHOP-2021-6357

Date Opened: 11-15-2021 Date Finished 12-13-2021 Meter 1 Reading: 106,079

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
WATER PUMP
LIGHTING SYSTEM
LIGHT BAR

Service Requests:

11/15/2021 ENGINE / 10: BENT / REPAIR NEEDED AT SHOP
T-14 WILL NOT GO IN TO PUMP. TRIED SEVERAL TIMES AND GEAR SELECTION DISPLAYS 5. TRIED SHUTTING DOWN AND SWITCHING BATTERY SWITCH OFF AND ON TWICE TOO. I DID NOT TAKE OUT OF SERVICE SINCE THE DUMP TANK CAN STILL BE UTILIZED.

11/15/2021 ALARMS / 10: BENT / NO TIGHT IN REAR
REAR LIGHT BAR IS NOT WORKING

CSHOP-2021-6633

Date Opened: 12-2-2021 Date Finished 12-8-2021 Meter 1 Reading: 106,079

TASKS PERFORMED

NO PARTS USED

INSPECTION

CSHOP-2021-6634

Date Opened: 12-2-2021 Date Finished 12-14-2021 Meter 1 Reading: 106,079

TASKS PERFORMED

Q PARTS

AIR FILTER	1	FIL; NAPAGOLD AIR FILTER
FUEL SYSTEM	1	FIL; NAPAGOLD FUEL FILTER
OIL FILTER	1	FIL; NAPAGOLD FUEL FILTER
AIR DRIER	1	NCB; DEGREASER MULTI PURP
DOOR HANDLES INSIDE-OUTSIDE	2	FIL; NAPAGOLD OIL FILTER
	40	4PC; 15W40 PREMIUM BLUE OIL
	1	1FG; FILTER AIR BRAKE 4374

CSHOP-2022-2123

Date Opened: 4-18-2022 Date Finished 5-4-2022 Meter 1 Reading: 106,079

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM	2	LMP; LAMP
BATTERY	1	9AM; LENS KIT BUMPER GUIDE
	1	ECH; MAS DISCONNECT SWITCH
	4	1AD; 1000 CCA 31 SERIES BATTERY

Asset Work Order History 10142546

CSHOP-2022-2397

Comments: **BELT MAKING NOSIE**

Date Opened: 5-2-2022 Date Finished 5-3-2022 Meter 1 Reading: 106,079

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
PRESSURE SWITCH
LIGHTING SYSTEM
BELT

Service Requests:

05/02/2022 SERVICE REQUEST / 19: LOOSE / REPAIR
BELT IS SQUEALING AND LEFT REAR SCENE LIGHT IS NOT WORKING. PRESSURE/RPM AND IDLE BUTTONS ON GOVERNOR NOT WORKING.

CSHOP-2022-2879

Date Opened: 5-27-2022 Date Finished 6-7-2022 Meter 1 Reading: 106,531

TASKS PERFORMED

NO PARTS USED

LIGHTING SYSTEM

Service Requests:

05/27/2022 LIGHTS / 19: LOOSE / REPAIR
VEHICLE LIGHTS NOT WORKING SPARE T42 ...NO HAZARDS OR TURN SIGNALS WORKING

CSHOP-2022-3392

Comments: **L/F HUB CAP SHOWING OIL SEEPAGE**

Date Opened: 6-23-2022 Date Finished 7-11-2022 Meter 1 Reading: 106,892

TASKS PERFORMED

Q PARTS

HUB CAP

1 CR; HUB CAP

CSHOP-2022-3465

Date Opened: 6-27-2022 Date Finished 7-11-2022 Meter 1 Reading: 106,892

TASKS PERFORMED

NO PARTS USED

QUALITY CHECK-REPAIRS

CSHOP-2022-3608

Comments: **DUMP SHOOT**

Date Opened: 7-6-2022 Date Finished 7-11-2022 Meter 1 Reading: 106,892

TASKS PERFORMED

NO PARTS USED

FIRE PUMP PLUMBING

Service Requests:

07/05/2022 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / INSPECT
WATER IS LEAKING FROM REAR SHOOT

Asset Work Order History 10142546

CSHOP-2022-3686

Date Opened: 7-9-2022 Date Finished 7-12-2022 Meter 1 Reading: 105,320

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM

1 1WL; LED FLOOD SCENE LIGHT

Service Requests:

07/08/2022 LIGHTS / 12: BROKEN / EXCHANGE - NEW
DRIVERSIDE REAR SCENE LIGHT OUT

CSHOP-2022-3720

Comments: **AT STATION 14 REAR TAIL LIGHTS NOT WORKING**

Date Opened: 7-11-2022 Date Finished 7-26-2022 Meter 1 Reading: 106,892

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM
AIR SYSTEM

Service Requests:

07/08/2022 LIGHTS / 49: CAN NOT DUPLICATE CONCERN / INSPECT
REAR TAIL LIGHTS NOT WORKING ON THE BRUSH TRUCK.

07/12/2022 AIR RIDE / 18: LEAKING / REPAIR
AIR RIDE ISSUE - TENDER TAKES SEVERAL MINUTES FOR AIRBAGS TO FILL BEFORE ENGAGING INTO GEAR.

CSHOP-2022-3836

Date Opened: 7-18-2022 Date Finished 7-19-2022 Meter 1 Reading: 106,892

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
BATTERY

CSHOP-2022-4054

Date Opened: 8-2-2022 Date Finished 9-26-2022 Meter 1 Reading: 106,892

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
HOSE BED BODY
AIR SYSTEM

1 5HP; KIT VPS KPS PWR SHIFT AMP CNTRL

Service Requests:

08/02/2022 AIR RIDE / 18: LEAKING / REPAIR
AIR RIDE ISSUE - SIGNIFICANT AIR LEAK CAN BE HEARD UNDER THE TRUCK WHILE TRUCK IS OFF. IT'S COMING FROM A VISIBLE PIN UNDERNEATH. TRIED PUSHING IT IN AND OUT BUT STILL LEAKING.

08/02/2022 BODY / 19: LOOSE / REPAIR
BODY ISSUE - TIE DOWN FOR BUCKLE NEEDS TO BE REMOUNTED ON THE RIGHT REAR SIDE TARP

Asset Work Order History 10142546

CSHOP-2022-4502

Comments: BRAKE

Date Opened: 8-29-2022

Date Finished

10-11-2022

Meter 1 Reading:

107,667

TASKS PERFORMED

NO PARTS USED

ABS CODES

Service Requests:

08/15/2022

BRAKES / 49: CAN NOT DUPLICATE CONCERN / DIAGNOSE COMPLAIN
BRAKE ISSUES. TRACTOR ABS LIGHT IS ILLUMINATED. THANKS KDCOLE19203

CSHOP-2022-4503

Comments: SHORE CHARGER

Date Opened: 8-29-2022

Date Finished

10-11-2022

Meter 1 Reading:

107,667

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
LIGHTING SYSTEM
SHORELINE CHARGER

2	LMP; LAMP
1	LIT; LED M C LAMP
2	LMP; LAMP
1	LIT; LED M C LAMP
1	LIT; LEDKIT

Service Requests:

08/13/2022

SERVICE REQUEST / 12: BROKEN / ADJUST
DIFFICULT TO START THERE IS NO BATTERY PLUG TO PLUG INTO SHORE POWER THAT MIGHT HAVE SOMETHING TO DO WITH IT.

CSHOP-2022-4504

Comments: FOAM/WATER TANK

Date Opened: 8-29-2022

Date Finished

10-11-2022

Meter 1 Reading:

107,667

TASKS PERFORMED

NO PARTS USED

FOAM SYSTEM

Service Requests:

08/13/2022

SERVICE REQUEST / 18: LEAKING / FOAM TANK
FOAM TANK IS LEAKING INTO THE WATER TANK

CSHOP-2022-4697

Comments: CALLAGHAN TIRE

Date Opened: 9-1-2022

Date Finished

9-1-2022

Meter 1 Reading:

0

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

Asset Work Order History 10142546

CSHOP-2022-6121

Date Opened: 11-18-2022 Date Finished 12-8-2022 Meter 1 Reading: 107,695

TASKS PERFORMED

NO PARTS USED

INSPECTION

CSHOP-2022-6122

Comments: **LUBE OIL FILTER AND PM FOLLOW UPS**

Date Opened: 11-18-2022 Date Finished 12-21-2022 Meter 1 Reading: 0

TASKS PERFORMED

Q PARTS

OIL	2	FIL; NAPAGOLD OIL FILTER
SHORELINE CHARGER	1	FIL; NAPAGOLD FUEL FILTER
REPAIR FROM PM - BATTERIES	1	FIL; NAPAGOLD FUEL FILTER
	40	4PC; 15W40 PREMIUM BLUE OIL
	1	6KU; AUTOCHARGE 1200 PUMP PLUS
	1	6KU; AUTO EJECT W STD YEL CVR
	4	1AD; 1000 CCA 31 SERIES BATTERY

CSHOP-2023-86

Date Opened: 1-6-2023 Date Finished 1-9-2023 Meter 1 Reading: 107,695

TASKS PERFORMED

Q PARTS

BODY EXTERIOR	1	MMM; GP ADHESIVE CLNR 200Z
---------------	---	----------------------------

RADIO-2018-633

Date Opened: 6-11-2018 Date Finished 6-11-2018 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

RADIO

Service Requests:

06/11/2018 RADIO / /
RADIO ISSUES. ...VHF RADIO NOT TRANSMITTING. PER CAPT S COLLINS

SSHOP-2019-193

Date Opened: 6-24-2019 Date Finished 6-24-2019 Meter 1 Reading: 98,484

TASKS PERFORMED

NO PARTS USED

DIFFERENTIAL

SSHOP-2022-146

Date Opened: 4-19-2022 Date Finished 4-19-2022 Meter 1 Reading: 106,079

TASKS PERFORMED

NO PARTS USED

BRAKES

Asset Work Order History 10142546

SSHOP-2022-152

Date Opened: 4-20-2022 Date Finished 4-27-2022 Meter 1 Reading: 106,079

TASKS PERFORMED

NO PARTS USED

ELECTRICAL

SSHOP-2022-209

Date Opened: 5-4-2022 Date Finished 5-24-2022 Meter 1 Reading: 0

TASKS PERFORMED

Q PARTS

INSTRUMENTS-GAUGES-METERS

1 5FR; KIT WATER TANKVISION PRO 400

Service Requests:

05/03/2022 SERVICE REQUEST / 12: BROKEN / REPAIR
TANK WATER INDICATOR MALFUNCTION, NOT SHOWING CORRECT WATER LEVEL. *****SPARE TENDER
@STATION 42*****

05/23/2022 SERVICE REQUEST / 19: LOOSE / ADJUST
BELT TENSIONER IS ON BORROWED TIME

SSHOP-2022-263

Comments: **DOOR WONT OPEN / COMPONENTS RUSTED OPENED FROM INSIDE / REPAIRED DOOR**

Date Opened: 5-25-2022 Date Finished 6-1-2022 Meter 1 Reading: 0

TASKS PERFORMED

Q PARTS

DOOR

1 2FL; DRIVER EXTERIOR DOOR HANDLE
1 2FL; DOOR HANDLE

Service Requests:

05/25/2022 SERVICE REQUEST / 12: BROKEN / REPAIR
PASSENGER SEAT DOOR DOES NOT OPEN FROM OUTSIDE OR INSIDE. SEEMS LIKE A LATCH BROKE
