



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142542

SPRINKLER/FSH FLT 2003 SCOTTY FIRESAFETY TRAILER

Workorder: V201

In Date: 10/13/2005
Close Date: 03/28/2006

Meter Reading:

Problem?

A INSPECTION, CHECK FRONT BATTERY, CHECK BRAKES

Task performed:

Parts	Quantity
030866TRAILER JACK 3500 LB	1
1156BULB	2
11949-3-20SLIDE	2
MC24DEEO CYCLE BAT	2
MISC PARTMISC PART	1
UMVS254411STRAP 46 IN	2

Workorder: V3615

In Date: 07/24/2006
Close Date: 08/15/2006

Meter Reading:

Problem?

passenger side front outrigger/stabilizer bent-(firesafety trailer in yard)

Task performed:

Parts	Quantity
12-9059 WAY TRAILER CONNECTOR	1
1232PINSTRIP REMOVAL TOOL	1
4112-RCALARM COLE HERSEE	1
8126482-2106 TOGGLE GUARD	1
947-24POWER STABILIZING JACK	1
CB-104BOX-CIRCUT BREAK BE22040	1
S775COUPLER	1
S777COUPLING NIPPLE	1
S778COUPLING	1
SLS65STOP LITE SWITCH	4

Workorder: V3960

In Date: 08/16/2006
Close Date: 09/15/2006

Meter Reading:

Problem?

INSTALL DOOR LATCH, GET SUPPLIES, (SAFTEY TRAILER)

Task performed:

Parts	Quantity
M93282-2306 SWITCH	1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142542

SPRINKLER/FSH FLT 2003 SCOTTY FIRESAFETY TRAILER

Workorder: V7374

In Date: 03/26/2007

Meter Reading:

Close Date: 04/16/2007

Problem?

roof vent broken (fire safety trailer in yard)

Task performed:

Parts

Quantity

1. R&R roof vent and reseal top
2. E-one school

NO PARTS USED

Workorder: V9234

In Date: 07/09/2007

Meter Reading:

Close Date: 10/15/2007

Problem?

both roof vents broken (safety trailer)

Task performed:

Parts

Quantity

1. check out vents on - order new ones
2. install new vents on roof and rewire units reseal remove old sealer
3. c. t. scan test

NO PARTS USED

Workorder: V13222

In Date: 02/13/2008

Meter Reading:

Close Date: 02/14/2008

Problem?

repair sprinkler system generator 10-7

Task performed:

Parts

Quantity

1. generator inop, exciter inop, installed new exciter
 - 1A. Finished work on item in line 1 above
2. Sprinkler pump inop, pump seized, freed up pump
 - 2A. Finished up work on item in line 2 above.
3. Generator inop, exciter, installed new excitev
4. Sprinkler pump inop, pump seized, freed up pump

NO PARTS USED

Workorder: V13545

In Date: 02/27/2008

Meter Reading:

Close Date: 02/29/2008

Problem?

parts only to repair generator

Task performed:

Parts

Quantity

Parts only to repair generator - Regans Mobile Engine

NO PARTS USED

Vendor?: REGANS SMALL ENG



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142542

SPRINKLER/FSH FLT 2003 SCOTTY FIRESAFETY TRAILER

Workorder: V17070

In Date: 08/15/2008
Close Date: 08/22/2008

Meter Reading:

Problem?

911 Prevention Way- the front (right) stabilizer does not come down. Plus adding the "flat" piece on the bottom of the rear stabilizers BOSS

Task performed:

Svc stabilizer; get drivere side front jack working; rear jacks have ____ blocks on them; don't know what they are looking for. j

Parts

Quantity

NO PARTS USED

Workorder: V18542

In Date: 10/23/2008
Close Date: 01/02/2009

Meter Reading:

Problem?

911 Prevention generator will not stay on. Front stabilizers will not come down. Please add metal plates to back stabilizers (same as front) Check sprinkler pump, pressure would not raise

Task performed:

1. Work on gen; water in fuel sys; pull tank-clean out; cln out carb; refill; test/run.
2. Pull pump after test; replc sea; reinstall; refill sys-test ok; rep leak on pump again-ok.
3. Rem frnt jack motor; free up bolts; lube jacks; reinstall motor.
4. Weld plates on bottom of rear stabilizers; go to Central Auto Trim; install cover on gen. j

Parts

Quantity

UMVS254411STRAP 46 IN

2

2/5/09

Order & isntall gen cover - Vasko j

Workorder: V19916

In Date: 12/22/2008
Close Date: 01/14/2009

Meter Reading: 1.00

Problem?

make cover for generator

Task performed:

Make cover for generator - Central Auto Trim j

Parts

Quantity

NO PARTS USED

Vendor?: CENTRAL AUTO TRIM



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142542

SPRINKLER/FSH FLT 2003 SCOTTY FIRESAFETY TRAILER

Workorder: V20094

In Date: 01/02/2009

Meter Reading:

Close Date: 02/05/2009

Problem?

Front right stabilizer does not go down

Task performed:

Parts

Quantity

Chkd out stabilizers; fnd left frnt stabilizer jammed; disassembled stabilizer mechanism, free up & reassemble. j

NO PARTS USED

Workorder: V17891

In Date: 09/23/2008

Meter Reading:

Close Date: 03/09/2009

Problem?

The generator on the 911 Prevention Trailer did not start with the key, it did start by using the pull cord.

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V21640

In Date: 03/09/2009

Meter Reading:

Close Date: 03/12/2009

Problem?

Please check air pressure and tires for 911 Prevention Way trailer. The trailer will be going out on 3-12-09 for use. Thank you.

Task performed:

Parts

Quantity

All (6) tires low; fill to 65PSI. j

NO PARTS USED

Workorder: V30848

In Date: 03/18/2010

Meter Reading:

6.00

Close Date: 04/01/2010

Problem?

trailer batterys dead

Task performed:

Parts

Quantity

Get gen running; needs carb regult; C/O TLR lites, A/C, etc; charge btrys; get gas can for gen. j

5921SPARK PLUG REPLACES BM6A

1

78-72BATTERY GROUP 78

1

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142542

SPRINKLER/FSH FLT 2003 SCOTTY FIRESAFETY TRAILER

Workorder: V32177

In Date: 05/13/2010
Close Date: 05/20/2010

Meter Reading: 7.00

Problem?

check brakes and bearings, paint wheels (pub ed trailer)

Task performed:

Parts

Quantity

1. Chk brakes; repack bearings.
2. Paint wheels. j

NO PARTS USED

Workorder: V32033

In Date: 05/05/2010
Close Date: 05/21/2010

Meter Reading: 7.00

Problem?

rpeiar pump

Task performed:

Parts

Quantity

1. Rem pump from trailer; take apart pump & cln impeller.
2. Reinstall sprinkler pump; rep leaing pipes. j

NO PARTS USED

Workorder: V36620

In Date: 11/22/2010
Close Date: 11/30/2010

Meter Reading: 6.00

Problem?

need 5 gallon fuel can and funnel for generator

Task performed:

Parts

Quantity

- (1) MAC PUT A GAS CAN ON 2003 SCOTTY FIRESAFETY TRAILER. NO TIME ENTERED UNDER LABOR. J.W.

NO PARTS USED

Workorder: V37282

In Date: 12/20/2010
Close Date: 01/10/2011

Meter Reading: 7.00

Problem?

BATTERYS 10-7

Task performed:

Parts

Quantity

- R/R btrys in parking lot to chk & charge; load tested btrys; reinstalled, clnd all terms & started onboard gen. j

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142542

SPRINKLER/FSH FLT 2003 SCOTTY FIRESAFETY TRAILER

Workorder: V37873

In Date: 12/20/2010
Close Date: 01/25/2011

Meter Reading: 7.00

Problem?

- 1. several interior lights out
- 2. rear stabilizers sticking (don't want to come down)
- 3. smoke generator takes very long time to heat up
- 4. Light cover missing on rear door.

Task performed:

- (1) CHECKED ALL STABILIZERS, WORKED THEM AND LUBED ALL OF THEM.
- (2) ORDERED LENS FOR THE REAR DOOR LOWER GROUND LIGHT.
- (3) CHECKED ALL LIGHTING AND REPLACED ALL BAD BULBS.
- (4) WASN'T ABLE TO GET IN TOUCH WITH COMPANY ABOUT SMOKE GENERATOR.

J.W.

Parts	Quantity
1141BULB	10

Workorder: V38433

In Date: 02/10/2011
Close Date: 02/18/2011

Meter Reading: 7.00

Problem?

- DEAD BATTERY

Task performed:

- went to PB Shores; rem all btry cables; tested btry; fnd bad btry; replc btry; went for parts; R/R (2) pos cable terms; ck starter connections; started & ck ok. j

Parts	Quantity
BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER BATTERY	1
HP-31DBATTERY 950CCA HP-31D	1

Workorder: V43529

In Date: 09/08/2011
Close Date: 09/20/2011

Meter Reading: 7.00

Problem?

- Install smoke machine.

Task performed:

- went out to pub ed trailer put smoke sluid in machine and tested operation system seems to work good maby piping needs to be adjusted clean machine.

Parts	Quantity
NO PARTS USED	



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142542

SPRINKLER/FSH FLT 2003 SCOTTY FIRESAFETY TRAILER

Workorder: V44921

In Date: 11/02/2011

Meter Reading: 7.00

Close Date: 11/16/2011

Problem?

check out trailer

Task performed:

Parts

Quantity

1. Refuel gen & run; chk tire press.
2. Hookup to van; chk all lights. j

NO PARTS USED

Workorder: V49759

In Date: 05/31/2012

Meter Reading: 7.00

Close Date: 06/04/2012

Problem?

replace tires service only

Task performed:

Parts

Quantity

REPLACE TIRES SERVICE ONLY.

NO PARTS USED

Vendor?: BOULEVARD TIRE CENTE

Workorder: V51667

In Date: 08/17/2012

Meter Reading: 7.00

Close Date: 09/17/2012

Problem?

generator not making voltage

Task performed:

Parts

Quantity

TRVL TO SHOP CHK GEN TRY TO EXCITE STARTER W 12V OC GET WORKING LOAD DOWN GEN LOST CHARGE AGAIN TRY TO FLASH WORK FIND GEN W 30 AMP TWIRK LOCK AND INSTALL ON UNIT TEST OK NO BATT CHARGE W/NEW UNIT.

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142542

SPRINKLER/FSH FLT 2003 SCOTTY FIRESAFETY TRAILER

Workorder: V55681

In Date: 02/10/2013

Meter Reading: 7.00

Close Date: 02/11/2013

Problem?

repair door stops, stabilizers

Task performed:

1. DOOR STOPS - FABRICATE PLATE TO SECURE DOOR STOPS, DRILL BOLT THROUGH HOLES IN DOOR PANEL AND BODY. PLATED INSIDE AND OUT TO SUPPORT AND MOUNT DOOR STOP - MOUNT DOOR STOP. SECURE PLATE.
2. ASSIST MAC WITH ABOVE REPAIRS.

Parts

Quantity

10129800338 1/2 HOLDER DOOR 1.5 ZINC

2

Workorder: V56212

In Date: 03/07/2013

Meter Reading: 7.00

Close Date: 04/16/2013

Problem?

Fabricate plenum to blow smoke in back room of trailer Repair lights and license plate holder Check and adj tire pressures as needed

Task performed:

1. TRIED TO FIND HITCH AND BALL FOR VOLY VAN. COULD NOT FIND ANY. GOT ONE FROM PARTS ONI. INSTALL ON VAN. CHARGE BATTERY AND CONNECT VAN TO TRAILER. CONNECT TRAILER PLUG TO VAN AND CHECK LIGHTS (NONE). CLEAN CONTACT AND LUBRICATE. CHECK POWER ON VAN PLUG. (OK). DIAGNOSE PROBLEM WITH TRAILER. OPENED TRAILER BOX AND CHECK WIRING. FOUND BAD CONNECTION FOR GROUND. REPAIR CONNECTION AND LIGHTS COME ON. L REAR TURN/BRAKE NOT WORKING. REPLACED BULB NO GOOD. NO POWER TO SOCKET STARTED TO DIAGNOSE AND RAN OUT OFTIME. LEFT NOTE FOR VOLLY'S ON SEAT. AS THEY WANTED TO USE TRUCK FOR WEEKEND.
2. MOVED SMOKE MACHINE TO CORRECT DISTANCE FROM PLENUM AND INSTALLED SPACER PIPE TESTED GOOD - INSTALLED LISCENCE PLATE

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142542

SPRINKLER/FSH FLT 2003 SCOTTY FIRESAFETY TRAILER

Workorder: V57241

In Date: 04/24/2013

Meter Reading: 7.00

Close Date: 05/10/2013

Problem?

Emergency breakaway cable broken Check trailer emergency brake battery Interior lights several bulbs inop Van and trailer pulls to the right

Task performed:

1. BEGAN CHECKING ABOVE CONCERNS AND ORDERING PARTS.
2. ROAD TESTED TRUCK AND TRAILER TO CHECK FOR PULL DURING BRAKING. FOUND TRUCK AND TRAILER PULLING SLIGHTLY TO THE RIGHT. CHECK BRAKE OPERATION AND WIRING TO EACH WHEEL FOR BRAKES. FOUND NO PROBLEMS. ALSO AIRED UP ALL SIX TIRES. (VERY LOW ON AIR).
3. CHECKED OUT BATTERIES ON TRAILER, BATTERIES FAILED LOAD TEST. HAD TO ORDER NEW BATTERIES. (MARINE/DEEP CYCLE)
4. CHECKED OUT INTERIOR LIGHTS INOP IN KITCHEN AREA. TRACED PROBLEM TO POSSIBLE BROKEN WIRE IN CEILING.
5. CONTINUED WIRING REPAIR INSIDE TRAILER FOR INTERIOR. HAD TO REMOVE A LOT OF INTERIOR TO FISH WIRES FROM LIGHTS BACK TO ELECTRICAL PANEL.
6. COMPLETED INTERIOR LIGHT REWIRING REPAIR. REINSTALLED ALL PARTS COVERS, VENTS AND LIGHT FIXTURES THAT WERE REMOVED TO GAIN ACCESS FOR WIRING. ALL INTERIOR LIGHTS ARE NOW WORKING.
7. ASSIST IN REPAIRS OF DOOR LIGHTS.
8. REPLACED BOTH BATTERIES (DID NOT PASS LOAD TEST) CLEANED ALL WIRE TERM ENDS. REPLACED BATTERY STRAP HOLD DOWNS AND MOUNTING BRACKETS. (WEATHERED/ADJUSTED).
9. REPLACED BRAKE AWAY SWITCH ON TONGUE OF TRAILER. DURING REMOVAL OF OLD SWITCH MOUNTING BOLT BRAKE OFF. GROUND DOWN BROKEN BELT, DRILLED AND TAPPED NEW MOUNTING HOLE AND PAINTED FRAME.
10. TOOK GAS CAN FROM TRAILER AND FILLED AT FUEL PUMPS RETURNED CAN TO TRAILER FULL.

Parts	Quantity
BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER BATTERY	2
M24MF MARINE BATTERY	2
UMVS254411 STRAP 46 IN	2



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142542

SPRINKLER/FSH FLT 2003 SCOTTY FIRESAFETY TRAILER

Workorder: V57701

In Date: 05/13/2013

Meter Reading: 7.00

Close Date: 05/21/2013

Problem?

check trailer for roof leak and plug flat tire

Task performed:

1. BACKED TRAILER INTO BAY UNLOCKED VAN. STARTED INSPECTING ROOF FOR REPORTED WATER LEAKS AT VENTS.
2. INSPECTION OF ROOF REVEALED BROKEN ROOF VENT OVER CONTROL ROOM. DO NOT RECOMMEND REPLACING VENT DUE TO POOR CONDITIN OF ROOF CLEANED AND SILICONED VENT SHUT TO SEAL. REMOVED CRANK HANDLE DO NO ONE WOULD ATTEMPT TO OPEN.
3. R&R LEFT SIDE FRT AXLE TIRE TO REMOVE SCREW AND PLUG TIRE. ALSO CHECKED AIR IN REMAINING 5 TIRES.
4. ALSO FOUND ROOF VENT OVER KITCHEN AREA LOOSE BUT STILL FUNCTIONAL. ALSO IN NEED OF REPLACEMENT (MACHANISM THAT CLOSES VENT TIGHT IS BROKEN) TRIED TO CLOSE MANUAL BUT WOULD NOT CLOSE TIGHT.
5. CHECKED OVER TRAILER FOR REPLACEMENT CONCERN AND REPORTED TO TIM C.
6. HOOKED TRAILER BACK UP TO VAN AND PARKED.

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142542

SPRINKLER/FSH FLT 2003 SCOTTY FIRESAFETY TRAILER

Workorder: V61272

In Date: 10/15/2013

Meter Reading: 7.00

Close Date: 10/25/2013

Problem?

check out trailer stabilizers

Task performed:

1. INSPECT REAR STABILAZER FOR DAMAGE FOUND NEEDS TO BE REMOVE FOR REPAIRS. REMOVE HOSE ASSYABLE. DISMANTLE RIGHT REAR ARM AND ALL COMPONENTS TO IT HEAD UP AND STRAIGHTEN FRAME AND ARM SUPPORT BRACKETS. STRAIGHTEN SCREW. REMOVE ELECTRIC MOTOR AND UP AND DOWN SWITCH NEEDS NEW ONE. REASSEMBLE BACK TOGETHER TEST FOR OPERATION IS WORKING GOOD.
2. CLEAN UP WELDING SHOP AFTER REPAIRS.
3. INSTALL STABILIZERS BACK ON TRAILER AND HOOCH UP WIRES FOR POWER BAK ON.
4. CHARGE BATTERIES ON TRAILER TEST STABILIZERS FOUND NEEDS ADJUSTMENT ADJUST DOWN LEGS AND MOTOR TO IT TEST FOR OPERATION IS GOOD NOW.
5. WORK ON TRAILER GENERATOR. REPAIR GENERATOR ELECTRIC CORE TO TRAILER. NEEDS NEW ENDS.
6. DRIVE TO PALM BEACH RV TO PICK UP GENERATOR POWER CORE ADAPTOR AND ENDS. INSTALL ON TRAILER.

Parts

Quantity

SLS65STOP LITE SWITCH

2

Workorder: V61518

In Date: 10/25/2013

Meter Reading: 7.00

Close Date: 11/26/2013

Problem?

Install new weight dist hitch

Task performed:

installed hitch

Parts

Quantity

3210RECIEVER SHANK

1

7979TRUNNION HEAD RECIEVER

1



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142542

SPRINKLER/FSH FLT 2003 SCOTTY FIRESAFETY TRAILER

Workorder: V62295

In Date: 11/26/2013

Meter Reading: 7.00

Close Date: 01/08/2014

Problem?

repair outside door and step lights/fixtures, check a/c drain

Task performed:

1. SETUP UNIT FOR WEEKEND EVENT.
2. TRAILOR GENERATOR PULL START STRING BROKE- REMOVE ASSEMBLY AND INSTALL NEW PULL STRING. REASSEMBLE AND OPERATE.
3. STEP LIGHT RIGHT LIGHT LEFT INOP- R&R BLOW BULB.
4. PORCH LIGHT R/SIDE BLOWN BULB- REMOVE AND INSTALL NEW BULB L/SIDE REMOVE BULB ASSEMBLY FELL APART REMOVED REMAINING PARTS- TAP OFF EXPOSE WIRE- PART ON ORDER.
5. COMPLAIN OF A/C LEAKING- RUN UNIT NO LEAK FOUND.

Parts

Quantity

NO PARTS USED

Workorder: V62599

In Date: 12/09/2013

Meter Reading: 7.00

Close Date: 02/03/2014

Problem?

Replace leveling jack. Check out sprinkler pump inop.

Task performed:

1. TEST AND REMOVE LEVELING AND NEEDS A NEW ONE. ALSO REMOVE PUMP FOR TESTING SYSTEM.
2. INSTALL PUMP BACK IN TRAILER.
3. TEST PUMP FOR PERFORMANCE IS WARMING GOOD NOW.

Parts

Quantity

030866TRAILER JACK 3500 LB

1

Workorder: V63994

In Date: 02/05/2014

Meter Reading: 7.00

Close Date: 02/05/2014

Problem?

fix pull cord on gen

Task performed:

REPLACED BROKEN PULL CORD ON GENERATOR.

Parts

Quantity

NO PARTS USED



1/10/2023

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10142542

SPRINKLER/FSH FLT 2003 SCOTTY FIRESAFETY TRAILER

Workorder: V64054

In Date: 02/07/2014

Meter Reading: 7.00

Close Date: 02/11/2014

Problem?

batteries dead

Task performed:

1. ASSIST CARL ON MOUNTING 2 CORD BATTERIES UNDER VAN ALSO FILL UP WATER TOMLZ ON TRAILER. SET TO CHARGE BATTERIES ON TRAILER FILL UP GENERATOR WITH GAS.
2. JUMP START VAN OUT IN PARKING LOT DEAD, CHECK OUT FOUND BOTH BATTERIES IN VAN BAD BATTERY UNDER TRUCK NOT CHANGED SENT 11/10 NO GOOD, REPAIR BATTERY CABLES AT BATTERY REINSTALL NEW BATTERY CHECK CHARGING SYSTEM OK.

Parts

Quantity

65-72BXT65750 BATTERY	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	2

Workorder: V70677

In Date: 11/03/2014

Meter Reading: 7.00

Close Date: 01/13/2015

Problem?

check a/c unit tripping breaker

Task performed:

1. Rope broken for generator set. Restring pulley cord.
2. Check a/c unit tripping breaker. No power up at roof top a/c. Checked for power at thermostat. R/R roof top a/c and rewire system.
3. Hole in floor.
4. Replace dead batteries and replace bad fuse holder. Wire and fuel generator set.

Parts

Quantity

63152HVAC UNIT ROOF MOUNTED	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	2
M24MFMARINE BATTERY	2