Palm Beach County Fleet Management Asset Maintenance History 10181119 2010 FORD F150 Pickup, 1/2 Ton

Total Hours: 88.30 Labor: 5,930.90 Parts: 4,896.06 Comm: 184.80 Charged: 11011.76

Work Order: 1005797 Meter: 28 In Date: 06/03/2010 Closed: 06/03/2010 Problem: Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1012927 Meter: 2670 In Date: 11/19/2010 Closed: 11/19/2010

Problem: 2 - Wash ticket(s) issued

Work Completed

- 2 - Wash ticket(s) issued

Hours: 0.00 Comm: 14.40 Labor: 0.00 Parts: 0.00 Total: 14.40

Work Order: 1013384 Meter: 3000 In Date: 12/06/2010 Closed: 12/15/2010

Problem: P. M., request 3 keys, low tire pressure light is on, & check battery (had to jump start)

Work Completed	Parts Issued	Quantity
- P. M.	Shop Supplies	1.00
- C/c: Had to jump start. Recharge battery. Check charging system. Found	1372 Oil Filter Frm Ph2 Wix 51372	1.00
no problem at this time.	5w20 Engine Oil	7.00

- C/c: Low Tps light on. Verify. Nail in F/l tire. Remove nail, dismount, patch, mount, balance, add N2, rotate to R/r.

- Shop Supplies

Hours: 3.50 Comm: 0.00 Labor: 210.00 Parts: 38.59 Total: 248.59

Work Order: 1013525 Meter: 3047 In Date: 12/08/2010 Closed: 12/09/2010

Problem: FLASH CANCEIVER

Work Completed		Parts Issued	Quantity
Reflash Canceiver and reprogramCut and program 3 extra keys		164-r0475 Ign Key 2010-earlier (don't Reorder)	3.00
- Shop Supplies		Shop Supplies	1.00
Hours: 2.00	Comm: 0.00	Labor: 120.00 Parts: 66.35	Total: 186.35

Hours: 2.00

Palm Beach County Fleet Management Asset Maintenance History 10181119 2010 FORD F150 Pickup, 1/2 Ton

Meter: 8276 Work Order: 1111097 In Date: 10/19/2011 **Closed:** 10/26/2011 **Problem:** Low pressure light is on for tire. **Parts Issued** Quantity **Work Completed Shop Supplies** 1.00 - Repair right rear tire. - Shop Supplies Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00 Work Order: 1111768 Meter: 8420 In Date: 11/01/2011 **Closed**: 11/15/2011 Problem: P. M. SERVICE **Parts Issued** Quantity **Work Completed Shop Supplies** 1.00 - P. M. Service. 1372 Oil Filter Frm Ph2 Wix 51372 1.00 - Shop Supplies 5w20 Engine Oil 7.00 Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 38.53 Total: 158.53 Work Order: 1203076 Meter: 9437 In Date: 03/30/2012 **Closed:** 03/30/2012 Problem: 2 - Wash ticket(s) issued **Work Completed** - 2 - Wash ticket(s) issued Hours: 0.00 Comm: 14.40 Labor: 0.00 Parts: 0.00 Total: 14.40 Work Order: 1205006 Meter: 10809 05/30/2012 **Closed**: 06/12/2012 In Date: Problem: P. M. SERVICE **Parts Issued** Quantity **Work Completed Shop Supplies** 1.00 - pm svc 1372 Oil Filter Frm Ph2 Wix 51372 1.00 - Shop Supplies 5w20 Engine Oil 7.00 31-22 Wiper Blades 22" Wiper Blade 2.00

Comm: 0.00

Used Firex Refurbed Fire Extingshers

Parts: 53.67

Labor: 120.00

1.00

Total: 173.67

Hours: 2.00

Palm Beach County Fleet Management Asset Maintenance History 10181119 2010 FORD F150 Pickup, 1/2 Ton

Work Order: 1300361 Problem: P.M.SERVICE	Meter:	13225		In Date:	01/10/2013	Closed:	01/25/2013
Work Completed			Parts Issued			Qı	uantity
- pm			1372 Oil Filter				1.00
- Shop Supplies			Napa Quart 5w20				5.00
			Shop Supplies				1.00
Hours: 2.00		Comm: 0.00	Labor: 120.00	Parts: 25.	97	Total:	145.97
Work Order: 1406971 Problem: pm	Meter:	17480		In Date:	07/15/2014	Closed:	07/22/2014
Work Completed			Parts Issued			Qı	uantity
- pm			Napagold Oil Filter				1.00
- Shop Supplies			Napa Quart 5w20				7.00
			Wiper Blade				2.00
			Used Fire X Refurbisl	ned			1.00
			Shop Supplies				1.00
Hours: 2.00		Comm: 0.00	Labor: 120.00	Parts: 56.	20	Total:	176.20
Work Order: 1504427 Problem: pm	Meter:	19556		In Date:	04/30/2015	Closed:	05/07/2015
Work Completed			Parts Issued			Qı	uantity
- pm			Napagold Oil Filter				1.00
- Shop Supplies			Napa Quart 5w20				7.00
			Wiper Blade				2.00
			Washer Fl				1.00
			Shop Supplies				1.00

Comm: 0.00

Labor: 120.00

Parts: 42.56

Total: 162.56

Palm Beach County Fleet Management Asset Maintenance History 10181119 2010 FORD F150 Pickup, 1/2 Ton

Problem: will not start

Work Completed		Parts Issued		Quantity
- ck and replace bad battery		Battery		1.00
- Shop Supplies		Shop Supplies		1.00
Hours: 0.75	Comm: 0.00	Labor: 45.00	Parts: 120.41	Total: 165.41

Work Order: 1602994 Meter: 21957 In Date: 03/22/2016 Closed: 03/30/2016

Problem: PM,

Work Completed		Parts Issued		Quantity
pmverify needs 4 tires replace 4 tires mount balance add n2Shop Supplies		Napagold Oil Filte	1.00	
		Napa Quart 5w20		7.00
		235 75r17 Advent	4.00	
		Shop Supplies		1.00
		Tire Disposal Fee		4.00
Hours: 4.00	Comm: 0.00	Labor: 240.00	Parts: 887.77	Total: 1,127.77

Work Order: 1700950 Meter: 23627 In Date: 01/30/2017 Closed: 02/21/2017

Problem: PM Service

Work Completed		Parts Issued		Quantity
- Pm Service.		22" Wiper Blade		2.00
- Rotate and balance all.correct N2.relearntpms.		Used Fire X Refurb	pished	1.00
- Shop Supplies		Napagold Oil Filte	r	1.00
		Napa Quart 5w20		7.00
		Shop Supplies		1.00
Hours: 2.75	Comm: 0.00	Labor: 165.00	Parts: 53.08	Total: 218.08

Palm Beach County Fleet Management Asset Maintenance History 10181119 2010 FORD F150 Pickup, 1/2 Ton

Work Order: 1708309 Meter: 24522 In Date: 08/23/2017 Closed: 08/31/2017

Problem: PM Service

Work Completed		Parts Issued		Quantity
- Pm Service		Napagold Oil Filte	r	1.00
- Install floor mats and steering wheel cover.		Napa Quart 5w20		7.00
- Rotate and balance tires.		Washer Fluid Cond	centr	1.00
- Shop Supplies		22" Wiper Blade		2.00
		Napagold Air Filte	er	1.00
		Floor Mat-2pc Rub Bk Stg Wheel Cov - Ford		1.00
				1.00
		Shop Supplies		1.00
Hours: 3.25	Comm: 0.00	Labor: 195.00	Parts: 94.28	Total: 289.28

Work Order: 1801906 Meter: 24888 In Date: 02/20/2018 Closed: 02/28/2018

Problem: PM Service.

Work Completed		Parts Issued		Quantity
- Pm Service.		Napa Quart 5w20		7.00
- Rotate and balance tires.		Washer Fluid Cond	centr	1.00
- Shop Supplies		22" Wiper Blade		2.00
		Used Fire X Refurb	oished	1.00
		Napagold Oil Filte	er	1.00
		Shop Supplies		1.00
Hours: 2.75	Comm: 0.00	Labor: 165.00	Parts: 56.98	Total: 221.98

Work Order: 1900176 Meter: 25292 In Date: 01/04/2019 Closed: 01/14/2019

Problem: P.M.SERVICE

Work Completed		Parts Issued		Quantity
- Pm Service.		Napagold Oil Filte	er	1.00
- Shop Supplies		Napa Quart 5w20		7.00
		22" Wiper Blade		2.00
		Washer Fluid Con	centr	1.00
		Shop Supplies		1.00
Hours: 2.00	Comm: 0.00	Labor: 134.00	Parts: 43.98	Total: 177.98

Palm Beach County Fleet Management Asset Maintenance History 10181119 2010 FORD F150 Pickup, 1/2 Ton

Work Order: 1901742 Meter: 25300 In Date: 02/14/2019 Closed: 02/25/2019

Problem: BATTERY DEAD AT PUMP SHOP

Work Completed	Parts Issued	Quantity
- Jump start vehicle in Wud parking lot.fully recharge and test battery.failed	Battery	1.00
load test.replace battery.	Shop Supplies	1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 67.00 Parts: 135.27 Total: 202.27

Work Order: 1906891 Meter: 27896 In Date: 07/01/2019 Closed: 07/23/2019

Problem: Install trailer hitch.

Work Completed		Parts Issued		Quantity
- Install trailer hitch.	Adapter Trailer W	ire	1.00	
Install brake controller and wiring harness. Reprogram Tbc brake controller with lds.Replace shorted reverse light bulb.		Trailer Hitch		1.00
		Relay		1.00
		Module-tbc		1.00
- Shop Supplies		Kit-trailer Wiring		1.00
		Shop Supplies		1.00
Hours: 6.50	Comm: 0.00	Labor: 435.50	Parts: 588.17	Total: 1,023.67

Work Order: 1907015 Meter: 27350 In Date: 07/08/2019 Closed: 07/08/2019

Problem: Keys locked in vehicle.

Work Completed

- Tow From: Bg water plant To: same

Hours: 0.00 Comm: 60.00 Labor: 0.00 Parts: 0.00 Total: 60.00

Palm Beach County Fleet Management Asset Maintenance History 10181119 2010 FORD F150 Pickup, 1/2 Ton

Work Order: 1907923 Problem: Pm service, install cargo rails.	Meter:	27896		In Date:	07/31/2019	Closed:	08/06/2019
Work Completed			Parts Issued			Qı	uantity
- Pm service.			Napagold Oil Filter				1.00
- Install cargo racks. Cust. supplied.			5w20 Oil Bulk				7.00
- Test drive.			Washer Fluid Conc	entr			1.00
- Rotate and balance tires.			22" Wiper Blade				2.00
- Shop Supplies			Napagold Air Filte	r			1.00
			Shop Supplies				1.00
Hours: 7.00		Comm: 0.00	Labor: 469.00	Parts: 44.	07	Total:	513.07
Work Order: 2004187 Problem: Pm service.	Meter:	33314		In Date:	04/27/2020	Closed:	04/30/2020
Work Completed			Parts Issued			Qı	uantity
- Pm service.			5w20 Oil Bulk				7.00
- Rotate and balance tires.			Napagold Oil Filter				1.00
- Battery failed load test. Replace battery.			22" Wiper Blade				2.00
- Test drive.			Washer Fluid Conc	entr			1.00
- Shop Supplies			Used Fire X Refurbi	ished			1.00
			Battery				1.00
			Shop Supplies				1.00
Hours: 4.50		Comm: 0.00	Labor: 328.50	Parts: 194	4.55	Total:	523.05
Work Order: 2006199 Problem: wont fuel	Meter:	34320		In Date:	06/23/2020	Closed:	06/23/2020
Work Completed			Parts Issued			Qı	uantity
- test and remove canceiver. issue fuel card			Shop Supplies				1.00
- Shop Supplies							
Hours: 1.00		Comm: 0.00	Labor: 73.00	Parts: 4.0	nO	Total	77.00

Palm Beach County Fleet Management Asset Maintenance History 10181119 2010 FORD F150 Pickup, 1/2 Ton

Work Order: 2008677 Meter: 37613 In Date: 08/28/2020 Closed: 09/30/2020

Problem: No start.

Work Completed			Parts Issued		Quantity
- Diagnose starting and charging systems . Battery failed load test . R&r			Pulley		2.00
defective battery .		Battery		1.00	
- Diagnose noise from front of engine . R&r both defective belt idler pullies .			Battery		19.00
- Shop Supplies			Shop Supplies		1.00
Ho	ours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 264.88	Total: 410.88

Work Order: 2008741 Meter: 36594 In Date: 08/28/2020 Closed: 08/31/2020

Problem: No start

Work Completed

- Tow From: 12500 40th st N, Royal Palm Beach To: He shop

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Palm Beach County Fleet Management Asset Maintenance History 10181119 2010 FORD F150 Pickup, 1/2 Ton

Work Order: 2010371 Meter: 38218 In Date: 10/15/2020 Closed: 10/27/2020

Problem: P.M. Service.

Work Completed

- Pm Service
- Pintle Pin missing. Remove old pintle pin chain and reinstall new pin and chain. Secure to hitch.
- Rf rotor grooved and both front pads worn below min spec. Remove and attempt to resurface grooved front rotor. Replace broth front rotors with new. Replace both front pads and caliper assemblies. Lube. Bleed air from system. Test drive.
- Rotate and Balance all 4 tires. Nitrogen fill all tires and reset Tpms.
- Shop Supplies

Parts Issued Quantity Napagold Oil Filter 1.00 5w20 Engine Oil 7.00 Washer Fluid Concentr 1.00 22" Wiper Blade 2.00 Napagold Air Filter 1.00 Pintle Pin W/clip 1.00 Caliper Washer 4.00 Non-chlor Brake Clnr 2.00 Brk Fluid Dot 4-32oz 1.00 Brake Caliper 1.00 **Brake Caliper** 1.00 **Brake Pad** 1.00 2.00 Brake Rotor 1.00 **Shop Supplies** Labor: 496.40 Parts: 562.50 Total: 1,058.90

Hours: 6.80 Comm: 0.00

Palm Beach County Fleet Management Asset Maintenance History 10181119 2010 FORD F150 Pickup, 1/2 Ton

Problem: PM Service

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Washer Fluid Concentr		1.00
 Check all, R & I four new tires, speed balance all, nitro fill Inspect all, R & I new rear brakes, resurface both rotors, service caliper slide pins, bleed and road test Perform front end alignment, road test 		20" Wiper Blade 5w20 Engine Oil		2.00 7.00
		Used Fire X Refurbished		1.00
		- Shop Supplies		Non-chlor Brake C
		Brk Fluid Dot 4-12oz		1.00
		Hankook P235 75r17 Dp At		4.00
		Brake Pad Shop Supplies		1.00
				1.00
		Tire Disposal Fee		4.00
Hours: 10.00 Con	nm: 0.00	Labor: 730.00	Parts: 1,091.36	Total: 1,821.36

Work Order: 2112588 Meter: 49804 In Date: 11/29/2021 Closed: 12/16/2021

Problem: PM Service.

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service - rotate and balance		5w20 Oil Bulk		7.00
		Napagold Oil Filter		1.00
- test drive	Washer Fluid Concentr 22" Wiper Blade		1.00 2.00	
- oil drain plug is stripped replaced oil pan and gasket				
- Shop Supplies		Napagold Air Filter		1.00
		Gasket Oil Pan		1.00
		Oil Pan Asm		1.00
		Non-chlor Brake C	Clnr	1.00
		Shop Supplies		1.00
Hours: 6.50	Comm: 0.00	Labor: 474.50	Parts: 144.47	Total: 618.97

Palm Beach County Fleet Management Asset Maintenance History 10181119 2010 FORD F150 Pickup, 1/2 Ton

Work Order: 2207539 Meter: 51239 In Date: 07/19/2022 Closed: 07/27/2022

Problem: PM Service.

- Preventive Maintenance Service 5		Parts Issued 5w20 Oil Bulk Napagold Oil Filter Washer Fluid Concentr 22" Wiper Blade Used Fire X Refurbished Sensor		7.00 1.00 1.00 2.00 1.00 1.00			
					- Test Drive		
					- Check engine light code P0150 , Pin		
bank 2 sensor 1.							
- Shop Supplies							
					Shop Supplies		1.00
Hours: 5.00	Comm: 0.00				Labor: 365.00	Parts: 225.36	Total: 590.36

Work Order: 2210157 Meter: 51904 In Date: 10/04/2022 Closed: 10/12/2022

Problem: Low tire pressure.

Work Completed		Parts Issued		Quantity	
Found left rear Tpms not responding. R/r tire and replace Tpms sensor.Shop Supplies		Tpms12 Sensor Tire Pr Shop Supplies		1.00	
				1.00	
	Hours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 61.10	Total: 207.10

Work Order: 2300687 Meter: 53658 In Date: 01/24/2023 Closed: 01/24/2023

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 88.30 Total Labor: 5,930.90 Total Comm: 184.80 Total Parts: 4,896.06