1/31/2023 4:51:27 PM	1018784		anagement Asset Maintena & Chassis, 15,000 Gvwr, W/				
Total Hours: 168.70	Labor: 11,094.00	Parts: 8,023.95	Comm: 9,096.18		Charged	: 28214.13	
Work Order: 1209120 Problem: 1061 - P		eter: 341		In Date:	09/24/2012	Closed:	09/24/2012
Work Completed							
- Pre Delivery Inspec	ction						
	Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 0.0	0	Total:	180.00
Work Order: 1211160 Problem: abs light		eter: 760 Shain to tail gate and tarp lock	is not working	In Date:	11/16/2012	Closed:	12/07/2012
Work Completed			Parts Issued			Qı	uantity
- adjust tarp gear bo	х		2848 S Hook				2.00
- weld on tail gate c			Shop Supplies				1.00
- fm to al packer for			3"x24' Sq. Tube 3/1	6"wall Steel			5.00
- repair abs warrant	y ford						
- Shop Supplies							
	Hours: 5.90	Comm: 0.00	Labor: 354.00	Parts: 41.	51	Total:	395.51
Work Order: 1403877 Problem: fuel cap	́Ме	ster: 3352		In Date:	04/21/2014	Closed:	04/23/2014
Work Completed			Parts Issued			Qı	antity
- fuel cap			Fuel Cap Diesel				1.00
·	Hours: 0.00	Comm: 0.00	Labor: 0.00	Parts: 27.	68	Total:	27.68
Work Order: 1404344 Problem: 1 - Key(s		ter: 3352		In Date:	05/02/2014	Closed:	05/02/2014
Work Completed			Parts Issued			Qı	uantity
- 1 - Key(s) issued			Duplicate Vehicle Ke	eys			1.00
	Hours: 0.20	Comm: 0.00	Labor: 12.00	Parts: 3.0	0	Total:	15.00

Work Order: 1404593 Problem: P.M. / Tail Gate Bent	Meter: 4049	In Date: 05/12/2	2014 Closed: 06/02/20
Work Completed		Parts Issued	Quantity
- pm		15-40 Oil	13.00
- replace complete tarp assembly		Napagold Oil Filter	1.00
- remove and straighten rear cargo door		Fuel Filter Kit	1.00
- add def		Wiper Blade	2.00
- test run		Used Fire X Refurbished	1.00
- Shop Supplies		Pm-22-a Additive Dies	1.00
		Brake Cleaner	2.00
		Bracket	2.00
		Spring	2.00
		Swing Arm	2.00
		Connect Arm Kit	1.00
		Bushing	4.00
		Snap Ring	2.00
		Tarp Bracket Bolt	4.00
		Def Quart	20.00
		Shop Supplies	1.00
Hours: 12.50	Comm: 0.00	Labor: 750.00 Parts: 716.33	Total: 1,466.33

Work Order: 1502749 Problem: pm/list	Meter:	5472		In Date:	03/17/2015	Closed:	03/24/2015
Work Completed			Parts Issued			Q	uantity
- Pm			15-40 Oil				13.00
- Rebuild tarp			Napagold Oil Filter	r			1.00
- Replace tail lamp assembly			Fuel Filter Kit				1.00
- Add Def			Wiper Blade				2.00
- Fix mud flap			Tarp Bar				1.00
- Shop Supplies			Connect Arm Kit				1.00
			Lamp Signal Univ	/			1.00
			Used Fire X Refurb	ished			1.00
			Washer Fl				1.00
			Def Quart				7.00
			Shop Supplies				1.00
Hours: 9.00		Comm: 0.00	Labor: 540.00	Parts: 41	6.29	Total:	956.29
Vork Order: 1505293 Problem: wont run	Meter:	5860		In Date:	05/26/2015	Closed:	06/16/2015
Work Completed			Parts Issued			Q	uantity
- replace turbo cooler hose			Air Tube				1.00
- test run			Shop Supplies				1.00
- Shop Supplies							
Hours: 2.00		Comm: 0.00	Labor: 120.00	Parts: 13	9.61	Total:	259.61
Nork Order: 1505326 Problem: stalling problems (turns over	Meter: but wont stay ru			In Date:	05/24/2015	Closed:	05/27/2015
Work Completed							
- Tow From: 12500 40th street north							
Hours: 0.00		Comm: 171.53	Labor: 0.00	Parts: 0.0	00	Total:	171.53

Palm Beach County Fleet Management Asset Maintenance History101878432012 FORD F450 Cab & Chassis, 15,000 Gvwr, W/Dump Body

Work Order: 1507705 Problem: fuel cap	Meter: 5861		In Date: 08/03/201	15 Closed: 08/26/2015
Work Completed		Parts Issued		Quantity
- replace missing fuel cap		Fuel Cap Diesel		1.00
- replace mirrors		Extended Tow Min	rror	1.00
- Shop Supplies		Shop Supplies		1.00
Hours: 2.20	Comm: 0.00	Labor: 132.00	Parts: 359.60	Total: 491.60
Nork Order: 1512786 Problem: 2 - Key(s) issued	Meter: 6728		In Date: 12/18/207	15 Closed: 12/18/2018
Work Completed		Parts Issued		Quantity
- 2 - Key(s) issued		Duplicate Vehicle	Keys	2.00
Hours: 0.60	Comm: 0.00	Labor: 36.00	Parts: 6.00	Total: 42.00

Work Order: 1602959 Problem: pm	Meter:	8237		In Date:	03/21/2016	Closed:	04/08/2016
Work Completed			Parts Issued			Qı	antity
- Pm			15-40 Oil				15.00
- Using scan tool found code U0121. Traced	out wirring a	and found open in	Napagold Oil Filter				1.00
harness	-	·	Fuel Filter Kit				1.00
- Replace light assembly			22" Wiper Blade				2.00
- Service trans			Washer Fluid Concer	ntr			1.00
- Tested and repaced batteries			Used Fire X Refurbish	ned			1.00
- Add Def			Air Filter (gold), Air P	anel			1.00
- Replace hitch pin			Dielect Silicone Com	р			1.00
- To Al Packer for parts			Lamp Signal Univ				1.00
- Repair 12v supply to Abs module			Syn-atf Trans Fluid S				10.00
- Road Test			Battery 65				2.00
- Shop Supplies			Def Quart				14.00
			Wire Lock Pin3/8x2.5				1.00
			wire assy				1.00
			Shop Supplies				1.00
Hours: 21.50		Comm: 0.00	Labor: 1,290.00	Parts: 699	9.88	Total:	1,989.88
Work Order: 1605479 Problem: LRO tire	Meter:	8371		In Date:	05/26/2016	Closed:	06/02/2016
Work Completed							
- Iro tire							
Hours: 0.00		Comm: 477.07	Labor: 0.00	Parts: 0.0	0	Total:	477.07
Work Order: 1609560 Problem: PM	Meter:	8852		In Date:	09/14/2016	Closed:	
Hours: 0.00		Comm: 0.00	Labor: 0.00	Parts: 0.0	0	Total:	0.00

Work Order: 1702842	Meter: 9982	In Date:	03/21/2017 Closed: 06/20/201
Problem: RS Mirror/ PM			
Work Completed		Parts Issued	Quantity
- pm		tow mirror	1.00
- passenger mirror		Pintle Pin W/clip	1.00
- check engine light. scan codes P21b0	reductant sensor level high. replace	Used Fire X Refurbished	1.00
sensor assembly and clear codes		15-40 Oil	13.00
- add Def		Napagold Oil Filter	1.00
- test run		Napagold Fuel Filter	1.00
- replace hitch pin		Wiper Blade	2.00
- Shop Supplies		Washer Fluid Concentr	1.00
		Air Filter (gold), Air Panel	1.00
		Reservoir	1.00
		Def Bulk Qts	10.00
		Shop Supplies	1.00
Hours: 11.50	Comm: 0.00	Labor: 690.00 Parts: 7	89.29 Total: 1,479.29

Work Order: 1804807 Problem: pm/list	Meter:	12015		In Date:	05/08/2018	Closed:	06/01/2018
Work Completed			Parts Issued			Qı	uantity
- pm			15-40 Oil				15.00
- side rail replace wood			Non-chlor Brake Cln	r			1.00
- replace weld chain on tail gate			Napagold Oil Filter				1.00
- replace hitch			Napagold Fuel Filter				1.00
- def			Air Filter (gold), Air F	Panel			1.00
- test run			Used Fire X Refurbis	hed			1.00
- Shop Supplies			Wiper Blade				2.00
			Washer Fluid Concer	ntr			1.00
			2x8x12 Pt Plywood				2.00
			Bent Pin 1 2 X 3				2.00
			S-hook W/ Latch				2.00
			Pntlhk Adpt 51 4 D 9	9k			1.00
			Pin Hook				1.00
			Blue Df				1.00
			Shop Supplies				1.00
Hours: 10.00		Comm: 0.00	Labor: 600.00	Parts: 400	0.61	Total:	1,000.61
Vork Order: 1805421 Problem: All tires	Meter:	11949		In Date:	05/29/2018	Closed:	05/31/2018
Work Completed							
- All Tires							
Hours: 0.00		Comm: 2,466.14	Labor: 0.00	Parts: 0.0	0	Total:	2,466.14
Vork Order: 1807945 Problem: 1 - Key(s) issued	Meter:	12338		In Date:	08/02/2018	Closed:	08/02/2018
Work Completed			Parts Issued			Qı	uantity
- 1 - Key(s) issued			Duplicate Vehicle Ke	eys			1.00
Hours: 0.30		Comm: 0.00	Labor: 18.00	Parts: 3.0	0	Total:	21.00

ork Order: 1906496 Problem: pm	Meter: 13905	In Date: 0	06/20/2019 Closed: 07/25/20
Work Completed		Parts Issued	Quantity
- Pm		15-40 Oil	15.00
- Repair blower for Ac		Napagold Oil Filter	1.00
- Tested and replaced batteries		Napagold Fuel Filter	1.00
- Repaired rear lights		Washer Fluid Concentr	1.00
- Def		Wiper Blade	2.00
- Replaced body mounts		Air Freshener	1.00
- Repaired trailer hitch		Used Fire X Refurbished	1.00
- Replaced front shocks		Micro2 Fuse - 5 Amp	1.00
- Rebuild tarp Assembly		Relay	1.00
- Repaired bent tailgate		Battery 65	2.00
- Test drive		Grommet Mount Kit	1.00
- Repaired greese fittings for liftgate		Sk-7000	1.00
- Shop Supplies		14.1 Ozmap-procyl	1.00
		Body Mount Kit	2.00
		Body Mount Kit	4.00
		Pintle Pin W/clip	1.00
		Pintle Hook Mount	1.00
		Insulator Nut	2.00
		Front Shock Absorber	2.00
		Presto Pin 5 32	1.00
		Tarp 7.5 X 18 In	1.00
		Bushing	4.00
		1/2 Tailgate Pin	4.00
		Shop Supplies	1.00

Labor: 2,211.00

Parts: 1,664.13

Total: 3,875.13

Work Order: Problem:	1908217 Wont Run	Meter:	13911		In Date: 08/07/2019	Closed:	08/07/2019
Work Com	pleted						
	n: 54th street N and Coconut	To [.] He shop					
10001101	Hours: 0.00		Comm: 132.00	Labor: 0.00	Parts: 0.00	Total:	132.00
Work Order: Problem:	1908219 Won't run	Meter:	13918		In Date: 08/07/2019	Closed:	10/16/2019
Work Com	pleted			Parts Issued		Qı	antity
- Replac C	ac pipe			Tube - Outlet			1.00
	es P0093, P00bd, P0401,p0471, 00 Cleared codes had Al Packe		P2456, P2463,	Shop Supplies			1.00
- To Al Pac	ker						
- Shop Sup	oplies						
	Hours: 5.00		Comm: 0.00	Labor: 365.00	Parts: 102.28	Total:	467.28
Work Order: Problem:	1908921 Not running; blocked DPS filt	Meter: er	13911		In Date: 08/23/2019	Closed:	08/26/2019
Work Com	pleted						
WORK COIL	n: He Shop @ Vista To: Al Pac	ker Ford - 1530	N. Military Trl				
			0	Labor: 0.00	Parts: 0.00	Total:	132.00
	Hours: 0.00		Comm: 132.00				
- Tow Fror	Hours: 0.00 1909559	Meter:		20001000	In Date: 09/17/2019	Closed:	10/10/2019
- Tow Fror Work Order:	Hours: 0.00 1909559 DPF	Meter:			In Date: 09/17/2019	Closed:	10/10/2019
- Tow Fror Work Order: Problem: Work Com	Hours: 0.00 1909559 DPF	Meter:			In Date: 09/17/2019	Closed:	10/10/2019

Work Order:		Meter:	15760		In Date:	09/23/2020	Closed:	10/15/2020
Problem:	mirrors.tarp crank handle							
Work Com	pleted			Parts Issued			Qı	uantity
- replace n	nirror and tarp crank handle			Control Crank Box				1.00
- def				tow mirror				1.00
- bend fue	l nozzle bracket			Shop Supplies				1.00
- Shop Sup	oplies			Freight Charge				1.00
	Hours: 7.00		Comm: 0.00	Labor: 511.00	Parts: 457	7.84	Total:	968.84
Nork Order: Problem:	2103798 PM/ bed dump lever	Meter:	16427		In Date:	04/02/2021	Closed:	04/21/202
Work Com	Work Completed			Parts Issued			Qu	uantity
- Preventive Maint. Service / Performed Pm Complete			Air Filter (gold), Air	Panel			1.00	
- Add Def	Insp System/ Topped Off Def			Fuel Fil				1.00
- Road Test Complete/ Performed Road Test			Washer Fluid Conce	entr			2.00	
- Performe	ed A/c System Service Replace C	abin Filters Co	mplete	Wiper Blade				2.00
- Dump Be	ed Not Working Inspect Control	S		Non-chlor Brake Clr	٦r			2.00
- Tail Light	s Broken Cracked Lens Other H	as Leds Out		Air Freshener			1.00	
- Replace I	Hydraulic Pump Control Push/p	ull Cable For D	ump Bed	15-40 Oil			15.00	
- Performe	ed Cooling System Service Com	olete		Napagold Oil Filter			1.00	
- Replace S	Serptine Belt Due To Age Comp	lete		Used Fire X Refurbis	shed			1.00
- Rear Sho	cks Leaking			Shock Absorber Rea	ar			2.00
- Right Sid	e Mud Flap Missing			Blue Df				1.00
- Shop Sup	oplies			Lamp Signal Univ				2.00
				Coolent				8.00
				Belt				1.00
				Mud Flap - Chevron	n De			1.00
				8 Foot Control Cabl	e			1.00
				Shop Supplies				1.00
				Freight Charge				1.00
	Hours: 17.00		Comm: 0.00	Labor: 1,241.00	Parts: 872	2.74	Total:	2,113.74

Work Order: 2111648 **Meter: 17612** In Date: 10/28/2021 Closed: 11/23/2021 Problem: PM Service. Send for Detail. **Work Completed** Parts Issued Quantity 15-40 Oil 15.00 - Preventive Maint, Service Napagold Oil Filter 1.00 - broken brake lights Lamp Signal Univ 1.00 - weld brake light bracket on Used Fire X Refurbished 1.00 - add def Napagold Fuel Filter 1.00 - add coolant Air Filter (gold), Air Panel 1.00 - replaces destroyed wood board rail Air Freshener 1.00 - test drive Washer Fluid Concentr 1.00 - Shop Supplies Wiper Blade 2.00 **Butane Fuel** 1.00 Power Torch 1.00 Blue Def 2.5 Gallon 1.00 Coolant Ford Gold 2.00 2x8x12 Pt Plywood 1.00 Shop Supplies 1.00 Labor: 730.00 Hours: 10.00 Comm: 0.00 Parts: 386.25 Total: 1,116.25 Work Order: 2112479 **Meter:** 17612 In Date: 11/23/2021 Closed: 11/23/2021 Problem: 1 - Detail Vehicle Wash Ticket(s) Issued **Work Completed** - 1 - Detail Vehicle Wash Ticket(s) Issued Hours: 0.00 Comm: 90.40 Labor: 0.00 Parts: 0.00 Total: 90.40

Vork Order:		Meter: 17612		In Date: 01/10/20	22 Closed: 02/28/2022		
Problem:	mirror broken need replacing						
Work Com	pleted		Parts Issued		Quantity		
- Mirror br	oken		Driverside Mirror	16" Arm	1.00		
- Shop Sup	oplies		Shop Supplies		1.00		
			Freight Charge		1.00		
	Hours: 1.50	Comm: 0.00	Labor: 109.50	Parts: 355.17	Total: 464.67		
/ork Order: Problem:	2300162 wont start/ keys are in it/ PM	Meter: 18899		In Date: 01/06/20	23 Closed: 01/17/202		
Work Com	pleted		Parts Issued		Quantity		
- Preventiv	- Preventive Maint. Service			r Panel	1.00		
- Operator states vehicle won't start upon further inspection found starter relay to be internally faulty and starter to be making noise removed and			Wiper Blade		2.00		
			Washer Fluid Conc	centr	1.00		
replaced st	arter and starter relay		Fuel Filter Kit	Fuel Filter Kit			
- Electrical	diag for no start operator concern	1	Air Freshener	1.00			
	emove engine oil filter adapter to g	gain access to starter removed	Non-chlor Brake C	Inr	1.00		
	ed gasket upon reinstall.		15-40 Oil		15.00		
- Road Tes			Napagold Oil Filter	r	1.00		
	and cleared codes related to repain ctive codes	irs scanned after test drive	Relay		1.00		
			Starter				
- Shop Sup	opiles		Gasket		1.00		
			Shop Supplies		1.00		
	Hours: 14.50	Comm: 0.00	Labor: 1,058.50	Parts: 582.76	Total: 1,641.26		
	2300171	Meter: 18795		In Date: 01/05/20	23 Closed: 01/06/202		
Vork Order:							

- Tow From: 12500 40th St N, Royal Palm Beach 33411 To: 2601 Vista Pkwy, West Palm Beach 33411

Comm: 124.30

Labor: 0.00

Parts: 0.00

1/31/2023 4:51:27 PM	Paln 10187843		Management Asset Maintenar b & Chassis, 15,000 Gvwr, W/I				
Work Order: 2300 Problem: Trans	642 Meter: sition Prep Charge	18951		In Date:	01/23/2023	Closed:	01/23/2023
Work Completed	d						
- Transition Prep	Charge						
	Hours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 0.0)	Total:	146.00
Total Hours: 168.70) Total Labor: 1	,094.00	Total Comm: 9,096	.18	Total Parts	: 8,023.95	