Fotal Hours: 317.20 Labor: 21,746.1	0 Parts: 29,189.58	Comm: 4,131.08		Charged: 55066.75	5
Nork Order: 1610176 Me Problem: install trailer plug & runnin	eter: 325 ng boards		In Date:	09/28/2016 <b>Closed:</b>	09/30/201
Work Completed		Parts Issued		Q	uantity
- Install proper trailer plug and wire ir	n	trailer plug			1.00
- Install running board		Running Boards			1.00
- Shop Supplies		Bracket Socket Mo	unt		1.00
		Shop Supplies			1.00
		1 11			

### Work Completed

- Pre Delivery Inspection

	<b>J</b>				
	Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 0.00	Total: 180.00
Work Order:	1610721 <b>M</b>	leter: 325		In Date: 10/18/20	016 Closed:
Problem:	rewire added lights to wo	rk with key on only			
Work Com	pleted				
-	Hours: 0.00	Comm: 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
Vork Order:	1612546 <b>M</b>	leter: 3778		In Date: 12/07/20	016 Closed: 12/07/2016
Problem:	15 - Wash ticket(s) issued	d			
Work Com	pleted				
- 15 - Was	h ticket(s) issued				
	Hours: 0.00	Comm: 143.10	Labor: 0.00	Parts: 0.00	Total: 143.10

Work Order: 1700555	Meter:	9130		In Date:	01/18/2017	Closed:	01/31/2017
Problem: P.M. service.							
Work Completed			Parts Issued			Qı	uantity
- P.m. Service.			5w20 Engine Oil				6.00
- Replace and balance four new tires.			Napagold Oil Filter				1.00
- Complete wheel alignment.test drive.			Used Fire X Refurbis	hed			1.00
- Shop Supplies			P265/70r17 Gdy At/	S			4.00
			Shop Supplies				1.00
			Tire Disposal Fee				4.00
Hours: 7.25		Comm: 0.00	Labor: 435.00	Parts: 756	6.61	Total:	1,191.61
Work Order: 1702733 Problem: Right front tire going flat.	Meter:	14763		In Date:	03/17/2017	Closed:	03/30/2017
Work Completed			Parts Issued			Qu	uantity
- Repair and balance right front tire.			Shop Supplies				1.00
- Shop Supplies							
Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 2.0	0	Total:	62.00
Nork Order: 1703633 Problem: 20 - Wash ticket(s) issued	Meter:	16050		In Date:	04/11/2017	Closed:	04/11/2017
Work Completed							
- 20 - Wash ticket(s) issued							
Hours: 0.00		Comm: 190.80	Labor: 0.00	Parts: 0.0	0	Total:	190.80

<b>Vork Order:</b> 1703850 <b>Problem:</b> P.M. service and brighter headligh	Meter: 17597 nt bulbs.		In Date:	04/17/2017	Closed:	04/28/2017	
Work Completed		Parts Issued			Qı	antity	
- P.m. service.		Napagold Oil Filter				1.00	
- Replace and balance all four tires .nitro filled	d tires.	5w20 Engine Oil				6.00	
- Replace both low beam headlight bulds wit		Washer Fluid Conce	entr			1.00	
- Shop Supplies	0	22" Wiper Blade				2.00	
		P265/70r17 Gdy At,	/s			4.00	
		Halogen Bulb				2.00	
		Shop Supplies				1.00	
		Tire Disposal Fee				4.00	
Hours: 5.75	Comm: 0.00	Labor: 345.00	Parts: 888	3.49	Total:	1,233.49	
<b>Problem:</b> Left front tire going flat.P.M. service	Meter: 23594 ce.		In Date:	06/09/2017			
			In Date:	06/09/2017	Closed:	00/30/201	
<b>Problem:</b> Left front tire going flat.P.M. service		Parts Issued	in Date:	06/09/2017			
Problem: Left front tire going flat.P.M. service Work Completed	ce.		in Date:	06/09/2017		6.00	
<ul><li>Problem: Left front tire going flat.P.M. service</li><li>Work Completed</li><li>Repair left front tire and balance .nitrogen fit</li></ul>	ce.	5w20 Engine Oil	In Date:	06/09/2017		antity	
<ul> <li>Problem: Left front tire going flat.P.M. service</li> <li>Work Completed</li> <li>Repair left front tire and balance .nitrogen find - P.m. Service.</li> </ul>	ce.	5w20 Engine Oil Napagold Oil Filter	In Date:	06/09/2017		6.00	
<ul> <li>Problem: Left front tire going flat.P.M. service</li> <li>Work Completed</li> <li>Repair left front tire and balance .nitrogen fit</li> <li>P.m. Service.</li> <li>Rotate and balance tires.</li> </ul>	ce. ill tires.	5w20 Engine Oil		06/09/2017		6.00	
<ul> <li>Problem: Left front tire going flat.P.M. service</li> <li>Work Completed</li> <li>Repair left front tire and balance .nitrogen fit</li> <li>P.m. Service.</li> <li>Rotate and balance tires.</li> <li>Transpoert vehicle to dealer for leaking right</li> </ul>	ce. ill tires.	5w20 Engine Oil Napagold Oil Filter 22" Wiper Blade		06/09/2017		6.00 1.00 2.00	
<ul> <li>Problem: Left front tire going flat.P.M. service</li> <li>Work Completed</li> <li>Repair left front tire and balance .nitrogen fit</li> <li>P.m. Service.</li> <li>Rotate and balance tires.</li> </ul>	ce. ill tires.	5w20 Engine Oil Napagold Oil Filter 22" Wiper Blade Washer Fluid Conce		06/09/2017		6.00 1.00 2.00 1.00	
<ul> <li>Problem: Left front tire going flat.P.M. service</li> <li>Work Completed <ul> <li>Repair left front tire and balance .nitrogen file</li> <li>P.m. Service.</li> <li>Rotate and balance tires.</li> <li>Transpoert vehicle to dealer for leaking right</li> </ul> </li> </ul>	ce. ill tires.	5w20 Engine Oil Napagold Oil Filter 22" Wiper Blade Washer Fluid Conce Nut Wheel		06/09/2017		6.00 1.00 2.00 1.00 1.00	
<ul> <li>Problem: Left front tire going flat.P.M. service</li> <li>Work Completed</li> <li>Repair left front tire and balance .nitrogen fit</li> <li>P.m. Service.</li> <li>Rotate and balance tires.</li> <li>Transpoert vehicle to dealer for leaking right</li> </ul>	ce. ill tires.	5w20 Engine Oil Napagold Oil Filter 22" Wiper Blade Washer Fluid Conce Nut Wheel Nut Wheel			Qı	6.00 1.00 2.00 1.00 1.00 1.00	
<ul> <li>Problem: Left front tire going flat.P.M. service</li> <li>Work Completed</li> <li>Repair left front tire and balance .nitrogen fit</li> <li>P.m. Service.</li> <li>Rotate and balance tires.</li> <li>Transpoert vehicle to dealer for leaking right</li> <li>Shop Supplies</li> </ul> Hours: 6.75	ce. ill tires. t front strut.	5w20 Engine Oil Napagold Oil Filter 22" Wiper Blade Washer Fluid Conce Nut Wheel Nut Wheel Shop Supplies	entr		Qu Total:	antity 6.00 1.00 2.00 1.00 1.00 1.00 1.00 447.92	
Problem: Left front tire going flat.P.M. service Work Completed - Repair left front tire and balance .nitrogen fit - P.m. Service. - Rotate and balance tires. - Transpoert vehicle to dealer for leaking righ - Shop Supplies Hours: 6.75 Work Order: 1706344	ce. ill tires. t front strut. Comm: 0.00	5w20 Engine Oil Napagold Oil Filter 22" Wiper Blade Washer Fluid Conce Nut Wheel Nut Wheel Shop Supplies	entr Parts: 42.	92	Qu Total:	antity 6.00 1.00 2.00 1.00 1.00 1.00 1.00 447.92	
Work Completed - Repair left front tire and balance .nitrogen fi - P.m. Service Rotate and balance tires Transpoert vehicle to dealer for leaking righ - Shop Supplies Hours: 6.75 Work Order: 1706344 Problem: 20 - Wash ticket(s) issued	ce. ill tires. t front strut. Comm: 0.00	5w20 Engine Oil Napagold Oil Filter 22" Wiper Blade Washer Fluid Conce Nut Wheel Nut Wheel Shop Supplies	entr Parts: 42.	92	Qu Total:	antity 6.00 1.00 2.00 1.00 1.00 1.00 1.00 447.92	
Problem: Left front tire going flat.P.M. service Work Completed - Repair left front tire and balance .nitrogen fi - P.m. Service. - Rotate and balance tires. - Transpoert vehicle to dealer for leaking right - Shop Supplies Hours: 6.75 Nork Order: 1706344 Problem: 20 - Wash ticket(s) issued Work Completed	ce. ill tires. t front strut. Comm: 0.00	5w20 Engine Oil Napagold Oil Filter 22" Wiper Blade Washer Fluid Conce Nut Wheel Nut Wheel Shop Supplies	entr Parts: 42.	92 06/27/2017	Qu Total: Closed:	antity 6.00 1.00 2.00 1.00 1.00 1.00 1.00 447.92	

Work Order:		Meter:	26599		In Date:	07/19/2017	Closed:	07/31/201
Problem:	Right rear tire going flat.							
Work Com	pleted			Parts Issued			Qı	uantity
- Repair rig	ght rear tire and balance .nitrog	en fill tires.		Shop Supplies				1.00
- Shop Sup	oplies							
	Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 2.0	0	Total:	62.00
Work Order:		Meter:	28097		In Date:	08/07/2017	Closed:	08/14/201
Problem:	Right front tire going flat.							
Work Completed			Parts Issued			Qu	uantity	
- Repair rig	ght front tire and balance.nitrog	en fill tires.		Shop Supplies				1.00
- Shop Sup	oplies							
	Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 2.0	0	Total:	62.00
Work Order:	1708238	Meter:	29123		In Date:	08/21/2017	Closed:	08/24/201
Problem:	P.M. service.							
Work Com	pleted			Parts Issued			Qı	uantity
- P.m. serv	ice.			5w20 Engine Oil				6.00
- Mount fo	our new tires.nitrogen fill and hi	gh speed balan	ce all four.	Napagold Oil Filter				1.00
- Complete	e front end alignment.			Napagold Air Filter				1.00
- Shop Sup	oplies			Used Fire X Refurbis	shed			1.00
				Washer Fluid Conce	ntr			1.00
				P265/70r17 Gdy At/	's			4.00
				Shop Supplies				1.00
				Tire Disposal Fee				4.00
	Hours: 7.25		Comm: 0.00	Labor: 435.00	Parts: 861	1.28	Total:	1,296.28

Vork Order:1710125Problem:P.M. service and wipers noisey.	Meter: 35566		In Date:	10/16/2017	Closed:	10/19/2017
Work Completed		Parts Issued			Qı	antity
- P.m. service.		5w20 Engine Oil				6.00
- Install two new tires on front.rotate and high	speed balance all four	Napagold Oil Filter				1.00
wheels.nitro fill all.		22" Wiper Blade				2.00
- Shop Supplies		Washer Fluid Concer	ntr			1.00
		P265/70r17 Gdy At/s	5			2.00
		Shop Supplies				1.00
		Tire Disposal Fee				2.00
Hours: 4.75	Comm: 0.00	Labor: 285.00	Parts: 436	6.01	Total:	721.01
Nork Order: 1710394 Problem: Slow crank.	Meter: 36226		In Date:	10/23/2017	Closed:	10/25/2017
Work Completed		Parts Issued			Qı	antity
- Charge battery fully.test battery and charging	g system.battery failed load	Battry Motorcraft				1.00
test .r&r defective battery.		Shop Supplies				1.00
- Shop Supplies						
Hours: 1.00	Comm: 0.00	Labor: 60.00	Parts: 173	8.54	Total:	233.54
	Meter: 39653		In Date:	11/20/2017	Closed:	11/21/2017
Work Order: 1711447		Parts Issued	In Date:	11/20/2017		11/21/2017 Jantity
<b>Work Order:</b> 1711447 <b>Problem:</b> Left rear tire going flat.	<b>Meter:</b> 39653		In Date:	11/20/2017		
Work Order: 1711447 Problem: Left rear tire going flat. Work Completed	<b>Meter:</b> 39653	Parts Issued	In Date:	11/20/2017		antity

# Work Order:1800148Meter:44503Problem:P.M. service and light bar inop and bumper damage.

### **In Date:** 01/03/2018 **Closed:** 01/16/2018

Work Completed		Parts Issued			Quantity		
- P.m. service.		5w20 Engine Oil				6.00	
- Removed and replaced damaged front bum	per and transfered parts from	Napagold Oil Filter			1.00		
old to new bumper.		22" Wiper Blade	2.00 1.00				
- Replace two tires on front and balance all fo		Elec Battery A23					
damaged side wall .replace two more tires and		Bumper Asy				1.00	
<ul> <li>Diagnoise faulty light bar control panel.remo control panel.retest.</li> </ul>	ove and replace with new	Cover	1.00 4.00				
	P265/70r17 Gdy At/						
- Shop Supplies	Panel Lower Front B	Bomber		1.00			
		Control Center				1.00	
		Shop Supplies			1.00		
		Tire Disposal Fee			4.00		
		Freight Charge			1.00		
Hours: 11.25	Comm: 0.00	Labor: 675.00	Parts: 1,9	50.74	Total:	2,625.74	
Vork Order: 1801118 Problem: Left front tire damaged.	<b>Meter:</b> 45965		In Date:	01/30/2018	Closed:	01/31/201	
Work Completed		Parts Issued			Q	uantity	
- Replace right front tire ,due to side wall dam	P265/70r17 Gdy At/	/s			1.00		
all.	Shop Supplies				1.00		
- Shop Supplies		Tire Disposal Fee				1.00	

Labor: 30.00

Parts: 206.50

Total: 236.50

Hours: 0.50

3/6/2023 11:35:15 AM

Work Order: Problem:	1802817 P.M. service.	Meter:	50095		In Date:	03/15/2018	Closed:	03/19/2018
Work Com	npleted			Parts Issued			Qı	uantity
- P.m. serv	vice.			5w20 Engine Oil				6.00
- Rotate a	nd high speed balance all four ti	res .repair righ	t rear tire.	Napagold Oil Filter				1.00
- Shop Su	pplies			22" Wiper Blade				2.00
				Used Fire X Refurbish	ned			1.00
				Shop Supplies				1.00
	Hours: 4.75		Comm: 0.00	Labor: 285.00	Parts: 39.	37	Total:	324.37
Work Order: Problem:	1803150 5 - Wash ticket(s) issued	Meter:	50728		In Date:	03/26/2018	Closed:	03/26/2018
Work Com	npleted							
- 5 - Wash	n ticket(s) issued							
	Hours: 0.00		Comm: 47.70	Labor: 0.00	Parts: 0.0	0	Total:	47.70
Work Order: Problem:	1804062 Right rear tire going flat.	Meter:	53041		In Date:	04/19/2018	Closed:	04/25/2018
Work Com	npleted			Parts Issued			Qı	uantity
- Replace	both rear tires and balance .nitro	ogen fill all tire	S.	P265/70r17 Gdy At/s	;			2.00
- Shop Su		5		Shop Supplies				1.00
				Tire Disposal Fee				2.00
	Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 411	1.00	Total:	471.00
Work Order: Problem:	1804296 Right low beam headlight inop		53533		In Date:	04/25/2018	Closed:	04/27/2018
Work Com	npleted			Parts Issued			Qu	uantity
- Remove	right headlamp assembly to rep	lace bulb. Rete	est.	Blister Pack Capsules				1.00
- Shop Su	J			Shop Supplies				1.00
	Hours: 0.80		Comm: 0.00	Labor: 48.00	Parts: 13.	88	Total:	61.88

ork Order: 1805659 Problem: P.M. service.	<b>Meter:</b> 57424		In Date: (	)6/04/2018	Closed:	06/07/201	
Work Completed		Parts Issued			Qu	antity	
- P.m. service.		Napagold Oil Filter				1.00	
- Inspect all tires .replace two worn tires of	on front . High speed balance all	5w20 Engine Oil				7.00	
four tires . Nitrofill all.	5 1	22" Wiper Blade				2.00	
- Inspect brakes .resurface rear rotors and		Washer Fluid Conce	ntr			1.00	
calipers and flush and bleed brake system	.road test.	265 / 70 / 17 Sl / Tir	e Gdy			2.00	
- Shop Supplies		Brake Pad			1.00		
		Non-chlor Brake Clr	nr			1.00	
		Shop Supplies				1.00	
Hours: 8.75	Comm: 0.00	Labor: 525.00	Parts: 587.6	6	Total:	1,112.66	
Work Completed		Parts Issued			Qu	antity	
- Tire has nail in sidewall.replace and bala	ance tire	P265/70r17 Gdy At/	s		-	1.00	
The has han in side han epidee and ball	,						
- Diagnose inop back up alarm replace ar	nd rewire alarm	Alarm				1.00	
- Diagnose inop back up alarm.replace ar	nd rewire alarm.					1.00 1.00	
- Diagnose inop back up alarm.replace ar - Shop Supplies	nd rewire alarm.	Alarm Shop Supplies Tire Disposal Fee					
5 1 1 1	nd rewire alarm. Comm: 0.00	Shop Supplies	Parts: 243.1	8	Total:	1.00	
- Shop Supplies Hours: 1.50	Comm: 0.00 Meter: 59674	Shop Supplies Tire Disposal Fee Labor: 90.00	In Date: 0	8 )7/05/2018		1.00 1.00 333.18	
- Shop Supplies Hours: 1.50 /ork Order: 1808123 Problem: : Damage to left front fender,	Comm: 0.00 <b>Meter:</b> 59674 left head light, left fog light, head li	Shop Supplies Tire Disposal Fee Labor: 90.00 ght bezel & front bump	In Date: 0			1.00 1.00 333.18	

## Work Order:1808805Meter:62296Problem:Left front tire going flat and check engine light on .

### In Date: 08/27/2018 Closed: 08/29/2018

Parts Issued Quantity **Work Completed** Ign Coil 1.00 - Computer diagnose check engine light ,code P0305 ,p0316. Perform pinpoint test. Perform tune up . Replace all six spark plugs and number five Spark Plugs 6.00 coil. Clear codes and retest. Gasket 1.00 - Perform air intake decarb and clean throttle body . Flush injectors . 1.00 Throttle Body Cleaner - Repair left front tire and balance . Nitrogen fill tires. **Injector Cleaner** 1.00 - Shop Supplies Intake Cleaner Kit 1.00 Shop Supplies 1.00 Hours: 7.30 Comm: 0.00 Parts: 233.95 Total: 671.95 Labor: 438.00 Work Order: 1810160 Meter: 65403 **In Date:** 10/01/2018 **Closed:** 10/04/2018 Problem: P.M. service.

Quantity **Work Completed Parts Issued** 5w20 Engine Oil 6.00 - P.m. service. Napagold Oil Filter 1.00 - Replace all four tires . Balance and nitrofill all. Reset Tpms. Washer Fluid Concentr 1.00 - Pressure test and inspect cooling system . Flush and refill. 2.00 22" Wiper Blade - Perform wheel alignment and road test. 265 70 R17 Tire 4.00 - Shop Supplies Anti Freeze Motorcraft 2.00 Shop Supplies 1.00 **Tire Disposal Fee** 4.00 Hours: 9.25 Comm: 0.00 Parts: 951.95 Labor: 619.75 Total: 1,571.70

Meter: 71427

### Work Order: 1812668 Problem: P.M. service.

Work Order: 1902115

#### 12/13/2018 Closed: 12/20/2018 In Date:

Work Completed		Parts Issued		Quantity	
- P.m. service.		Napagold Oil Filter	r	1.00	
- Repair right rear tire and replace two tires .	Rotate and balance all four	Napa Quart 5w20	6.00		
tires. Nitrogen fill tires .		22" Wiper Blade		2.00	
- Pressure test cooling system . R&r leaking		Used Fire X Refurb	1.00		
drive belt and A/c belt . Flush cooling system	and retest .	Boxed Miniatures		1.00	
- Shop Supplies	265 70 R17 Tire Anti Freeze Motorcraft				
		Anti Freeze Motoro	craft	2.00	
		Water Pump		1.00	
		Tmermostat Housi	ng	1.00	
		V Belt		1.00	
		Gasket		1.00	
		V Belt		1.00	
		Shop Supplies		1.00	
		Tire Disposal Fee		2.00	
Hours: 11.05	Comm: 0.00	Labor: 740.35	Parts: 881.56	Total: 1,621.91	
ork Order: 1902115	Meter: 77105		In Date: 02/26/20	19 Closed: 03/06/2019	
<b>Problem:</b> P.M. service and tires chopped.					
Work Completed		Parts Issued		Quantity	

Work Completed Parts Issued				Quantity
- P.m. service.		Napagold Oil Filte	r	1.00
- Inspect all tires . Replace two tires and rotate and balance	all four tires .	5w20 Engine Oil	7.00	
Nitrofill all .		22" Wiper Blade	2.00	
- Diagnose noise on right turns . R&r defective left front hu	ıb bearing .	Washer Fluid Cond	1.00	
Retest drive.		Wd40 Spr	1.00	
- Shop Supplies		265 70 R17 Tire		2.00
		Hub Asy	1.00	
		Shop Supplies	1.00	
		Tire Disposal Fee	2.00	
Hours: 7.25 C	Comm: 0.00	Labor: 485.75	Parts: 956.14	Total: 1,441.89

Total: 1,441.89

#### Work Order: 1904617 Meter: 82995 Problem: P.M. service ,right rear tire going flat and recall 18S27 .

#### In Date: 04/29/2019 **Closed:** 05/07/2019

Work Completed		Parts Issued			Qı	uantity	
- P.m. service.		Napagold Oil Filter				1.00	
- Inspect and service transmission .replace filter and flue	sh and refill	5w20 Engine Oil				6.00	
transmission fluid .		Washer Fluid Concentr			1.00		
- Inspect and service transfer case . Drain and refill .		22" Wiper Blade		2.00			
- Replace all four tires . Replace left front and right real Balance all four tires and nitrogen fill all . Reset Tpms .	r Tpm sensors .	Napagold Air Filter			1.00		
- Remove left front seat assembly . disassemble seat to	replace wore seat	Screen Asy				1.00	
pad . Hook up scan tool to clear all codes .		oil auto			18.00		
- Complete front end alignment and road test .	oil auto			2.00			
	- 2 2	Tpms Sens Kit 265 70 R17 Tire			2.00		
- Transport to and from dealer for recalls 18s27 and 17s	533.						
- Shop Supplies		Pad Seat				1.00	
		Shop Supplies				1.00	
		Tire Disposal Fee				4.00	
Hours: 14.75	Comm: 0.00	Labor: 988.25	Parts: 1,3	84.01	Total:	2,372.26	
Work Order:         1905407         Meter           Problem:         Leftr rear tire going flat .         Meter	: 84377		In Date:	05/20/2019	Closed:	05/20/2019	
Work Completed		Parts Issued			Qı	uantity	
- Repair left rear tire and balance . Nitrofill all .		Shop Supplies				1.00	
- Shop Supplies							
Hours: 1.00	Comm: 0.00	Labor: 67.00	Parts: 3.0	0	Total:	70.00	

Work Order: 1906129 Problem: Back up camera inop at times	<b>Meter:</b> 85636		In Date:	06/11/2019	Closed:	06/18/2019
Work Completed		Parts Issued			Qı	uantity
- Computer diagnose back up camera ino	p . Perform pinpoint test . Remove	Camera Back Up				1.00
tailgate handle to replace camera assembl		Shop Supplies				1.00
- Repair left front tire and balance . Nitrof	ll all.					
- Shop Supplies						
Hours: 3.00	Comm: 0.00	Labor: 201.00	Parts: 296	6.19	Total:	497.19
Work Order:1907533Problem:P.M. service and had to jump	Meter: 88825 start.		In Date:	07/22/2019	Closed:	07/23/2019
Work Completed		Parts Issued			Q	uantity
- P.m. service.		Napagold Oil Filter				1.00
- Charge battery fully and test . Battery fai	led load test . R&r defective	5w20 Engine Oil				6.00
battery .		Ford Triton Pvc Swc				1.00
- Repair right rear tire . Rotate and balanc	Washer Fluid Conce	ntr			1.00	
- Shop Supplies		22" Wiper Blade				2.00
		Battry Motorcraft				1.00
		Shop Supplies				1.00
Hours: 5.75	Comm: 0.00	Labor: 385.25	Parts: 226	6.49	Total:	611.74
Nork Order: 1907761 Problem: Passenger headlight out.	<b>Meter:</b> 89431		In Date:	07/26/2019	Closed:	07/31/2019
Work Completed		Parts Issued			Q	uantity
- Replace right headlamp bulb.		Capsule				1.00
Hours: 0.50	Comm: 0.00	Labor: 33.50	Parts: 9.2	9	Total:	42.79
Nork Order: 1908600 Problem: Right rear tire going flat.	<b>Meter:</b> 90868		In Date:	08/16/2019	Closed:	08/19/2019
Work Completed		Parts Issued			Qu	uantity
- Repair righrt rear tire and balance . Nitro	fill all .	Shop Supplies				1.00
- Shop Supplies						
Hours: 1.00	Comm: 0.00	Labor: 67.00	Parts: 3.0	0	Total:	70.00

Vork Order: 1909		Meter: 91987		In Date:	08/28/2019	Closed:	08/29/2019
Problem: Wipe	ers noise and left brake ligh	it inop.					
Work Complete	d		Parts Issued			Qı	uantity
- Test and repla	ce both front wiper blades	. Retest .	22" Wiper Blade				2.00
- Test and repla	ce left brake light bulbs .		Boxed Miniatures				2.00
- Shop Supplies	U U		Shop Supplies				1.00
	Hours: 0.70	Comm: 0.00	Labor: 46.90	Parts: 12.	.87	Total:	59.77
<b>/ork Order:</b> 1909 <b>Problem:</b> P.M.	867 service and check engine	Meter: 94231 light on .		In Date:	09/25/2019	Closed:	09/30/2019
Work Complete	d		Parts Issued			Qı	uantity
- P.m. service.			5w20 Engine Oil				7.00
- Replace all fou	r tires and balance . Nitrofi	ll all.	Napagold Oil Filter				1.00
- Computer diag	nose check engine light ,c	odes P0305 and P3016 . Perform	22" Wiper Blade				2.00
pinpoint test . Perform tune up . Replace all six spark plugs . - Perform complete air intake decarb and cleaning . Flush injectors .			265 70 R17 Tire				4.00
			Spark Plugs				6.00
- Peform evap te	est . R&r defective purge va	alve . Retest .	Intake Cleaner Kit				1.00
- Shop Supplies			Motor Tune-up 16oz	Z			1.00
			Purge Valve				1.00
			Shop Supplies				1.00
			Tire Disposal Fee				4.00
	Hours: 11.45	Comm: 0.00	Labor: 767.15	Parts: 1,0	66.00	Total:	1,833.15
ork Order: 1912 Problem: PM S		Meter: 99533		In Date:	11/21/2019	Closed:	11/25/2019
Work Complete	d		Parts Issued			Qı	uantity
- P.m. service.			Napagold Oil Filter				1.00
- Repair left rear	tire . Rotate and high spee	ed balance all four tires . Nitrofill	5w20 Engine Oil				6.00
all.			22" Wiper Blade				2.00
- Shop Supplies			Used Fire X Refurbis	hed			1.00
			Shop Supplies				1.00
	Hours: 4.75	Comm: 0.00	Labor: 346.75	Parts: 49.	.59	Total:	396.34

Vork Order: 1912577	Meter: 101173		In Date:	12/09/2019	Closed:	12/19/2019
<b>Problem:</b> Right front tire going flat .						
Work Completed		Parts Issued			Qı	uantity
- Repair right front tire and balance . Nitrofill	all.	Gasket				1.00
- Computer diagnose check engine light , co	de P2111 . Perform pinpoint	Throttle Body				1.00
test . R&r defective throttle body . Clear code	and retest . Road test .	Shop Supplies				1.00
- Shop Supplies						
Hours: 2.50	Comm: 0.00	Labor: 182.50	Parts: 75.6	69	Total:	258.19
ork Order: 1913174 Problem: PA. inop .	Meter: 102403		In Date:	12/30/2019	Closed:	01/08/202
Work Completed		Parts Issued			Qı	uantity
- Diagnose Pa system inop . R&r pa controlle	r due to coffee spilled in	Cover And				1.00
control retest .		Control Center				1.00
- Diagnose horn inop . Remove steering whe	el to replace defective clock	Shop Supplies				1.00
spring . Retest horn operation .	Freight Charge				1.00	
- Shop Supplies						
Hours: 3.10	Comm: 0.00	Labor: 226.30	Parts: 875			1,101.58

Meter: 105704

## Work Order: 2001525

### In Date: 02/12/2020 Closed: 02/18/2020

Problem: P.M. service and check headlights .

Work Completed		Parts Issued			Qı	uantity	
- P.m. service.		5w20 Engine Oil				7.00	
- Test and replace left headlight bulb and burnt	connector . Retest .	Napagold Oil Filter			1.00		
- Replace all four tires and balance . Nitrofill all.		22" Wiper Blade		2.00			
- Replace both front brake rotors and pads . Ser	vice calipers . Flush and	Washer Fluid Concentr				1.00	
bleed brake system . Road test .		Blister Pack Capsul	es			1.00	
- Perform complete front end alignment and tes	t drive .	265 70 R17 Tire				4.00	
- Shop Supplies		Brake Pad				1.00	
		Brk Fluid Dot 4-32d	ΟZ			1.00	
		Brake Pad				1.00	
		Socket				1.00	
		Brake Rotor	e Rotor			2.00	
		Shop Supplies				1.00	
		Tire Disposal Fee				4.00	
Hours: 12.05	Comm: 0.00	Labor: 879.65	Parts: 1,4	51.18	Total:	2,330.83	
ork Order: 2002392 Problem: Wiper blades not clearing windshield	<b>Meter:</b> 107711 and washer fluid low .		In Date:	03/09/2020	Closed:	03/11/2020	
Work Completed		Parts Issued			Qı	uantity	

- Test and replace both wiper blades and fill washer fluid . Retest .

Hours: 0.20

Parts Issued		Quantity
Washer Fluid Cor	ncentr	1.00
22" Wiper Blade		2.00
Labor: 14.60	Parts: 10.17	Total: 24.77

Vork Order: 2004702 Problem: P.M. service.	Meter: 111239		In Date: 05/11/2020	Closed:	05/14/2020
Work Completed		Parts Issued		Qı	uantity
- P.m. service.		Napagold Oil Filter			1.00
- Replace cabin air filter and clean fresh air int	ake .	5w20 Engine Oil			7.00
- Replace both rear brake rotors and pads . Se	rvice caliper . Flush and bleed	22" Wiper Blade			2.00
brake system . Road test .	·	Wd40 Spr			1.00
- Replace two worn tires . Rotate and balance	all four tires . Nitrofill all.	Cabin Air Filter			1.00
- Shop Supplies	Brk Fluid Dot 4-32oz			1.00	
		Brake Pad			1.00
		Rotor			2.00
		265 70 R17 Tire			2.00
		Shop Supplies			1.00
		Tire Disposal Fee			2.00
Hours: 9.25	Comm: 0.00	Labor: 675.25	Parts: 926.15	Total:	1,601.40
<b>Vork Order:</b> 2006117 <b>Problem:</b> 15 - Wash ticket(s) issued	Meter: 113590		In Date: 06/19/2020	Closed:	06/19/2020
Work Completed					
- 15 - Wash ticket(s) issued					
Hours: 0.00	Comm: 143.10	Labor: 0.00	Parts: 0.00	Total:	143.10

Work Order:2007571IProblem:P.M. service.	Meter: 117126		In Date:	08/03/2020	Closed:	08/11/2020
Work Completed		Parts Issued			Qı	uantity
- P.m. service.		Napagold Oil Filter				1.00
- Inspect and replace all four worn tires and balan	ce . Nitrofill all. Replace	5w20 Engine Oil				7.00
three worn lug nuts .		22" Wiper Blade				2.00
- Remove drivers seat for repair and reinstall after	repair . Replace missing	Washer Fluid Concer	ntr			1.00
left front assist handle cap .		Nut Wheel				3.00
- Shop Supplies	265 70 R17 Tire				4.00	
		Cover				1.00
		Seat R And R				1.00
		Shop Supplies				1.00
		Tire Disposal Fee				4.00
Hours: 5.75	Comm: 0.00	Labor: 419.75	Parts: 1,5	91.58	Total:	2,011.33
Vork Order:2010511IProblem:Right low beam headlight inop .	Meter: 122047		In Date:	10/20/2020	Closed:	10/21/2020
Work Completed		Parts Issued			Qı	uantity
- Test and replace right low beam headlight bulb		Blister Pack Capsules	5			1.00
- Shop Supplies		Shop Supplies				1.00
Hours: 0.50	Comm: 0.00	Labor: 36.50	Parts: 17.	86	Total:	54.36

Meter: 123802

### Work Order: 2011341 Problem: Pm

### In Date: 11/12/2020 Closed: 11/25/2020

Work Com	npleted			Parts Issued			Qı	uantity
- Performe	ed P.m. service & inspection.			5w20 Engine Oil				6.00
- Mount 2	tires then balance and rotate al	l 4 wheels. Res	et tpms.	Napagold Oil Filter 22" Wiper Blade Anti Freeze Motorcraft			1.00	
- Performe	ed 2 wheel alignment and test d	rove vehicle.						2.00
- Performe	ed coolant pressure test check. F	ound coolant	tank lower hose				1.00	1.00
leaking . R	&r leaking hose . Flush cooling s	system and refi	ll . Retest .	Heater Hose			1.00	
- Shop Su	- Shop Supplies			265 70 R17 Tire			2.00	
				Shop Supplies				1.00
				Tire Disposal Fee				2.00
	Hours: 9.75		Comm: 0.00	Labor: 711.75	Parts: 628	3.15	Total:	1,339.90
/ork Order: Problem:	2012428 Need two spare keys	Meter:	125775		In Date:	12/15/2020	Closed:	12/17/2020
Work Com	npleted			Parts Issued			Qı	uantity
- Have two	o keys made and program to tru	ıck .		ford side key				2.00
- Shop Su	pplies			Shop Supplies				1.00
	Hours: 0.50		Comm: 0.00	Labor: 36.50	Parts: 168	8.58	Total:	205.08

Work Order: 2102971 Problem: Pm service (Emergency Vehicle)	Meter: 128982		In Date: 03/17/20	21 <b>Closed:</b> 03/30/2021
Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		5w20 Engine Oil		6.00
- Replaced 2 tires. rotated and balanced all 4 tire	es. Nitrogen filled all tires.	Napagold Oil Filter		1.00
Diagnose Tpms fault light on. Found to have 2 ba	5	Washer Fluid Conc	entr	1.00
sensors and relearned system.		22" Wiper Blade		2.00
<ul> <li>Performed full front end alignment and road test .</li> <li>Shop Supplies</li> </ul>		Used Fire X Refurb	ished	1.00
		Tpms Sens Kit	2.00	
		265/70/17 Tire Gra	2.00	
		Shop Supplies	1.00	
		Tire Disposal Fee	2.00	
Hours: 7.25	Comm: 0.00	Labor: 529.25	Parts: 698.86	Total: 1,228.11
Work Order:2104183Problem:Driver side headlight out. Left sun vis	Meter: 130623 sor broken off .		In Date: 04/14/20	21 Closed: 04/20/2021
Work Completed		Parts Issued		Quantity
- Test and replace left headlight and connector .	retest .	Blister Pack Capsul	es	1.00
. 5				

- Replace broken left sun visor .

- Shop Supplies

Hours: 1.50

Comm: 0.00

Parts IssuedQuantityBlister Pack Capsules1.00Headlamp Socket H111.00Visor Assy1.00Shop Supplies1.00Labor: 109.50Parts: 167.67Total: 277.17

Vork Order:			133697		In Date:	05/27/2021	Closed:	06/04/202
Problem:	P.M. service and Driver's side low	beam head	d light is loose and c	loes not remain lit.				
Work Com	pleted			Parts Issued			Qu	uantity
- Preventiv	e Maint. Service			Napagold Oil Filter				1.00
- replaced	cabin a/c filter and refresh intake a	ir		5w20 Engine Oil				6.00
- replace a	nd balance all 4 tires . Nitro fill all.			22" Wiper Blade				2.00
- service fr	ont diff by r&i rack and pinion asse	mbly		Steering Wheel Cover Large 22" Wiper Blade Lt265/70/17 Tire Bfg				1.00
- service a	nd inspect rear diff .							1.00
- check,sop	p,replaced defective connector ,bulk	o,and verify	normal operation					4.00
of left head	l light low beam .			Qt/75w90				2.00
	ttery,charging system,after fully har	ge it fail loa	ad test R&r	1qt Syngear Oil 75-9	90			3.00
defective battery . Hook up lds to reset Bsm				Blister Pack Capsule	S			1.00
- Shop Supplies			Headlamp Socket H	11			1.00	
				Battry Motorcraft				1.00
				Cabin Air Filter Shop Supplies				1.00
								1.00
				Tire Disposal Fee				4.00
	Hours: 10.75		Comm: 0.00	Labor: 784.75	Parts: 1,4	18.55	Total:	2,203.30
ork Order: Problem:	2106538 Check engine light remains lit	Meter:	135297		In Date:	06/15/2021	Closed:	06/17/202
Work Com	pleted			Parts Issued			Qu	uantity
- Perform (	Cel diagnosis, pulled codes P0305 8	k P0316. Re	place 6 spark plugs	Ignition Coil				6.00
and coils, service throttle body & upper intake.			Spark Plugs				6.00	
- Shop Sup	- Shop Supplies			Throttle Body Clean	er			1.00
				Shop Supplies				1.00
	Hours: 5.10		Comm: 0.00	Labor: 372.30	Parts: 79	1.98	Total:	1,164.28

Vork Order: 21 Problem: He		Meter: 1	36197		In Date:	07/07/2021	Closed:	07/08/2021
Work Comple	ted			Parts Issued			Qı	antity
- Remove righ	t front inner fender cover t	to test and replace	right low beam	Blister Pack Capsules				1.00
headlight bulb			0	Shop Supplies				1.00
- Shop Supplie	es							
	Hours: 0.80	C	Comm: 0.00	Labor: 58.40	Parts: 12.	81	Total:	71.21
Vork Order: 21 Problem: PM	08893 I Service . Noise from left f	Meter: 1 front wheel and ch		on .	In Date:	08/17/2021	Closed:	08/30/2021
Work Comple	ted			Parts Issued			Qı	antity
- Preventive N	1aint. Service			5w20 Engine Oil				6.00
- Check all tires, R & I two new tires on front, rotate and speed balance all ,			Napagold Oil Filter				1.00	
nitro fill				Washer Fluid Concen	tr			1.00
5 5	on, Perform Ids computer	5		22" Wiper Blade				2.00
•	n power balance, check co injector and coil to verify, F			Silicone Spray 10oz				1.00
	ing noise on left side, R &	<u> </u>		Lt265/70/17 Tire Bfg				2.00
right	ing holse on left side, K &	i bioken motor m	iounts left and	Nut Wheel				5.00
- Shop Supplie	es			Engine Mount				1.00
				Engine Mount				1.00
				Kit Oring				10.00
				Injector				1.00
		Gasket				6.00		
				Shop Supplies				1.00
				Tire Disposal Fee				2.00
	Hours: 14.75	C	Comm: 0.00	Labor: 1,076.75	Parts: 720	).75	Total:	1,797.50

Work Order: 2110498 Problem: Headlight is out	Meter:	141899		In Date:	09/28/2021	Closed:	09/29/202
Work Completed			Parts Issued			Q	uantity
- replace left front headlamp , repair wiring.			Blister Pack Capsules				1.00
- Shop Supplies			Shop Supplies				1.00
Hours: 0.80		Comm: 0.00	Labor: 58.40	Parts: 12.	81	Total:	71.21
Work Order: 2110859 Problem: Headlight out again.	Meter:	142900		In Date:	10/06/2021	Closed:	10/14/202
Work Completed			Parts Issued			Qı	uantity
- Replace left front headlight assembly.			Headlamp				1.00
- Test and replace both front wiper blades			22" Wiper Blade				2.00
- Shop Supplies			Shop Supplies				1.00
Hours: 1.20		Comm: 0.00	Labor: 87.60	Parts: 184	4.47	Total:	272.07
Work Order: 2112105 Problem: PM Service.	Meter:	145693		In Date:	11/10/2021	Closed:	11/16/202
Work Completed			Parts Issued			Q	uantity
- Preventive Maint. Service			5w20 Engine Oil				6.00
- Pressure Test Cooling System To Find Cool	oant Leak, R	&r Failed Radiator	Filter				1.00
Leaking And Replace Coolant.			22" Wiper Blade				2.00
- Steering Wheel Was Not Centered; Comple	te Front End	l Alignment And	Anti Freeze Motorcra	ft			2.00
Road Test.			Radiatiar				1.00
- Rotate And Balance Four Tires. Nitro fill all.			Shop Supplies				1.00
- Shop Supplies							

3/6/2023 11:35:15 AM

Work Order: Problem:	2112647 Charging system needs to be s		146512		In Date:	11/30/2021	Closed:	12/02/2021
Work Con	npleted			Parts Issued			Qı	uantity
- Charge k	attery fully . Test battery and ch	araina svstem	. Computer	Alternator Assy				1.00
diagnose check engine light P0625 ,p065b . Perform pinpoint test . R&r defective alternator and retest .			Shop Supplies				1.00	
- Shop Su	pplies							
	Hours: 2.50		Comm: 0.00	Labor: 182.50	Parts: 328	5.18	Total:	507.68
Work Order: Problem:	2112887 ALTERNATOR ISSUES	Meter:	147229		In Date:	11/30/2021	Closed:	12/06/202
Work Con	npleted							
- Tow Froi	m: Pbia (maintenance) To: Lv Sho	р						
	Hours: 0.00		Comm: 90.40	Labor: 0.00	Parts: 0.0	0	Total:	90.40
Work Order: Problem:	2200136 FRONT END SQUEAKING AN		149672 DISES SOUNDS L	IKE PASSENGER SI	In Date: DE	01/05/2022	Closed:	01/11/2022
Work Con	npleted			Parts Issued			Qı	uantity
- custome	r states front end noise vehicle v	vas inspected o	during inspection	265/70/17tirebfg				2.00
Uca was found to be moving excessively Uca and Lca was replaced. right side frame mount bent , straighten Lca mounting point was found bent in			Control Arm Assy				1.00	
			Control Arm Assy				1.00	
0	causing contact with Lca .			Control Arm Assy				1.00
<ul> <li>mount and balance 2 tires nitro fill both</li> <li>perform front end alignment after suspension repairs test drive vehicle after corrections</li> </ul>			Shop Supplies				1.00	
			Tire Disposal Fee				2.00	
- Shop Su	pplies							

Work Order:	2200637	Meter: 150339		In Date:	01/20/2022	Closed:	01/24/2022
Problem:	PM Service. front end making	loud noise again					
Work Completed			Parts Issued			Q	uantity
- Preventiv	ve Maint. Service		22" Wiper Blade				2.00
<ul> <li>rotate and balance all 4 tire nitro fill all</li> <li>Road test for noise , remove and replace abs sensor right front tire. Road test . Noise gone</li> <li>Shop Supplies</li> </ul>			Used Fire X Refurbished 5w20 Engine Oil				1.00
							6.00
			Napagold Oil Filte	er			1.00
			Sensor		1.00		
			Shop Supplies				1.00
	Hours: 5.55	Comm: 0.00	Labor: 405.15	Parts: 70.	56	Total:	475.71
Vork Order: Problem:	2201396 Front driver tire has big screw	Meter: 151422 in it, bringing vehicle now.		In Date:	02/07/2022	Closed:	02/08/2022
Work Completed			Parts Issued			Q	uantity
- Repair left front tire, balance and nitro service.			Shop Supplies				1.00
- Shop Su	pplies						
	Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 2.6	5	Total:	75.65

Meter: 155221

### Work Order: 2202765

### **In Date:** 03/14/2022 **Closed:** 03/24/2022

1.00

2.00

Total: 655.16

Problem: PM Service. Driver Rear tire loses air.

Work Completed		Parts Issued		Quantity	
- Preventive Maint. Service	5w20 Engine Oil	6.00			
- R&r Both Worn Front Inner Tie Rod Ends.		Napagold Oil Filte	1.00		
- R&r Worn Driver Front Lower Control Arm.		Washer Fluid Cond	1.00		
- Mount Two New Tires; Rotate And Balance Four.	Relearn Tire Sensors.	22" Wiper Blade	2.00		
- Complete Front End Alignment And Road Test.		265/70/17tirebfg	2.00		
- Shop Supplies	Kit Tie	1.00			
		Kit Tie Rod Inner		2.00	
		Control Arm Assy		1.00	
		Arm Asy		1.00	
		Shop Supplies		1.00	
		Tire Disposal Fee		2.00	
Hours: 10.75	Comm: 0.00	Labor: 784.75	Parts: 1,321.04	Total: 2,105.79	
York Order:         2204743         N           Problem:         Front tires need to be inspected one has	<b>leter:</b> 159333 as threads showings / p	ossible need of alignm		2 <b>Closed:</b> 05/03/2022	
Work Completed		Parts Issued		Quantity	
- Inspect, Mount And Balance Two Worn Tires In F	- Inspect, Mount And Balance Two Worn Tires In Front.			2.00	

Shop Supplies

Labor: 255.50

Tire Disposal Fee

Parts: 399.66

- Inspect And Align Front End. Road Test To Verify Repair Complete.

- Shop Supplies

Hours: 3.50

Work Order: 2205409 Meter: 161495 In Date: 05/23/2022 **Closed:** 06/01/2022 Problem: PM Service. Employee stated a jerking issue sometimes, said it felt like transmission related.

Work Completed		Parts Issued	Quantity		
- Preventive Maint. Service		Napagold Oil Filter		1.00	
- Rotated and balanced all 4 tires. Nitrogen filled all tires.		5w20 Engine Oil		6.00	
- Diagnose driver complaint. Scanned for codes and had codes-	22" Wiper Blade		2.00		
P0717. Found to have faulty Lead frame in transmission. R and R	Napagold Air Filter	~	1.00		
frame. Performed transmission service. Cleared codes and tested drove		oil auto		18.00	
- Shop Supplies		Tram Oil Gasket		1.00	
		Screen Asy		1.00	
		Tramission Frame Shop Supplies		1.00	
				1.00	
Hours: 8.75 Comm	n: 0.00	Labor: 638.75	Parts: 565.20	Total: 1,203.95	

Work Order:2207034Meter:165812In Date:07/05/2022Closed:07/12/2022Problem:PM Service.FRONT TIRES NEED TO BE INPECTED TRUCK PULLS LEFT. ENGINE WAS RUNNING ROUGH MISFIRE.

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	Drain Plug	1.00
- Front Brake Pads Squeaking Remove Brake Pads And Inspected Rot	or, Napagold Oil Filter	1.00
Rotors Damanged With Forgin Object, R&r Pads Calipers Brakes Hose	s, And 5w20 Engine Oil	6.00
Resurface Rotors, Bleed System And Test Drive	Non-chlor Brake Clnr	1.00
- Replace Both Front Tires Balance All With Nitro Fill	22" Wiper Blade	2.00
- Test Drive And Perform Front End Alignment Retest	265/70/17tirebfg	2.00
- Computer Diag Noise ,transmisison Output Shaft Speed Sensor Not Reading Intermittently, Removed Valve Body And Inspected Lead Fran		1.00
Connectors , And Oss Sensor, Sensor Damanged R&r Valve Body And	Dual a Lla a	1.00
Tcm Calabration.	Bracketed Caliper	1.00
- Shop Supplies	Bracketed Caliper	1.00
	Non-chlor Brake Clnr	2.00
	Brk Fluid Dot 4-32oz	1.00
	Brake Pad	1.00
	oil auto	14.00
	Non-chlor Brake Clnr	2.00
	Tram Control Assy	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours: 18.05 Comm: 0.0	0 Labor: 1,317.65 Parts: 1,303	3.77 Total: 2,621.42

#### Meter: 173575 Work Order: 2209818 In Date: 09/21/2022 **Closed:** 09/26/2022 Problem: PM Service. Inspect tires employee reported low tread and a brake light or turn signal is out. Parts Issued Quantity **Work Completed** Napagold Oil Filter 1.00 - Preventive Maint, Service 5w20 Engine Oil 6.00 - mount 4 rotate and balance all a tire nitro fill all 22" Wiper Blade 2.00 - Test and remove and replace right brake light bulb .. **Boxed Miniatures** 1.00 - Shop Supplies 265/70r17 Bfg Trail Terrain 4.00 Shop Supplies 1.00 Tire Disposal Fee 4.00 Hours: 5.25 Comm: 0.00 Parts: 774.80 Labor: 383.25 Total: 1,158.05 Work Order: 2210645 Meter: 176187 In Date: 10/18/2022 **Closed:** 12/14/2022 **Problem:** oil light comes on and battery issues. Quantity **Work Completed** Parts Issued Battry Motorcraft 1.00 - Scan for codes all battery low voltage codes . Charge battery fully . Test battery and charging system . Battery failed load test . R&r defective battery . Switch Asy 1.00 Hook Ids to reset Bms . Wire Assy 1.00 - Diagnose low oil pressure light coming on . R&r defective oil pressure Shop Supplies 1.00 switch and pigtail. Retest with manual pressure gauge and at long idle in gear pressure drops major engine damage worn out.

- Shop Supplies

	Hours: 3.00	Comm: 0.00	Labor: 219.00	Parts: 203	.05	Total:	422.05
Work Order: 23 Problem: Re		<b>ter:</b> 176190 onsole , go light and PA system .		In Date:	02/16/2023	Closed:	02/28/2023
Work Comple	ted		Parts Issued			Q	uantity
	ter console and wire , lig e . Fill in all holes in root	ht bar and wire , go light and wire ,pa	Shop Supplies				1.00
- Shop Supplie		0	Lahar 440.00	Dente: 0.00	_	Tatal	4 4 9 9 5
	Hours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 2.68	)	i otai:	148.65
Total Hours: 317.	.20 Total Labo	or: 21,746.10	Total Comm: 4,1	31.08	Total Parts:	: 29,189.5	8