4/3/2023	
9:56:10 AM	

Total Hours: 370.50 Labor: 23,812.25	Parts: 20,374.08	Comm: 387.94		Charged	: 44574.27	
Work Order: 1303526 Me Problem: fill def	ter: 315		In Date:	04/10/2013	Closed:	04/18/2013
Work Completed		Parts Issued			Qı	antity
- parts only		Def Diesel Exh Fluid				5.00
Hours: 0.00	Comm: 0.00	Labor: 0.00	Parts: 8.7	8	Total:	8.78
Work Order: 1305494 Me Problem: 1061 - Pre Delivery Inspec	ter: 316 tion		In Date:	06/04/2013	Closed:	06/04/2013
Work Completed						
- Pre Delivery Inspection Hours: 4.00	Comm: 0.00	Labor: 240.00	Parts: 0.0	0	Total:	240.00
Work Order: 1306193 Me Problem: LADDER RACK	<b>ter:</b> 1695		In Date:	06/20/2013	Closed:	06/28/2013
Work Completed		Parts Issued			Qı	uantity
- install ladder rack		Ladder Rack				1.00
- fabricate bolts and install air comper-	ssor	Shop Supplies				1.00
- remove and adj out riggers						
- thighen leaking hyd filter and ck fluic	level					
- Shop Supplies						
Hours: 8.50	Comm: 0.00	Labor: 510.00	Parts: 651	1.41	Total:	1,161.41
Work Order: 1309192 Me Problem: damaged trailer harness w	ter: 3987 iring alert		In Date:	09/10/2013	Closed:	09/12/2013
Work Completed		Parts Issued			Qı	antity
- replace damage sire harness and trai	ler female connector	5404 Female Connec	ctor			1.00
- Shop Supplies		Shop Supplies				1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 15.	25	Total:	195.25

Meter: 4986

# Work Order: 1309543 Problem: pm, low def

# In Date: 09/20/2013 Closed: 09/27/2013

Work Completed	Parts Issued Quantit	y
- pm	Air Filter (gold), Air Panel 1.0	0
- def service	Napagold Oil Filter 1.0	0
- crane svc	Napagold Fuel Filter 1.0	00
- rear marker removed assy and repaired ground	15w40 Bulk South Reg 14.0	00
- repaired wires for take down and alley lights	Vinyl Electrical Tape 1.0	00
- unsiezed and lubed vise	Mac Wite Lithium Gres 1.0	00
- unsiezed and lubed out rigger pins and leg extentions	Def Fluid 2.5 2.0	00
- repaired lines in rear compartment area	Napa Trans Filter 1.0	00
- Shop Supplies	Shop Supplies 1.0	00
Hours: 14.00 Comm:	0.00 Labor: 840.00 Parts: 159.77 Total: 999.	77
rk Order: 1402475 Meter: 10200		
Problem: P.M.SERVICE/SERVICE DEF SYSTEM	In Date: 03/13/2014 Closed: 03/2	4/201
Problem: P.M.SERVICE/SERVICE DEF SYSTEM Work Completed	In Date: 03/13/2014 Closed: 03/2 Parts Issued Quantit	4/201
Problem: P.M.SERVICE/SERVICE DEF SYSTEM Work Completed - pm	In Date: 03/13/2014 Closed: 03/2 Parts Issued Quantit Napagold Oil Filter 1.0	24/201 <b>y</b> 00
Problem: P.M.SERVICE/SERVICE DEF SYSTEM Work Completed	In Date: 03/13/2014 Closed: 03/2 Parts Issued Quantit Napagold Oil Filter 1.0	24/201 2 <b>y</b> 00
Problem: P.M.SERVICE/SERVICE DEF SYSTEM Work Completed - pm - svc def - svc crane	In Date: 03/13/2014 Closed: 03/2 Parts Issued Quantit Napagold Oil Filter 1.0 Napagold Fuel Filter 1.0	24/201 2 <b>y</b> 00 00
Problem: P.M.SERVICE/SERVICE DEF SYSTEM Work Completed - pm - svc def	In Date: 03/13/2014 Closed: 03/2 Parts Issued Quantit Napagold Oil Filter 1.0 Napagold Fuel Filter 1.0 15w40 Bulk South Reg 14.0	24/201 29 00 00 00
Problem: P.M.SERVICE/SERVICE DEF SYSTEM Work Completed - pm - svc def - svc crane - svc out riggers	In Date: 03/13/2014 Closed: 03/2 Parts Issued Quantit Napagold Oil Filter 1.0 Napagold Fuel Filter 1.0 15w40 Bulk South Reg 14.0 Wiper Blade 2.0	24/201 29 00 00 00 00
Problem: P.M.SERVICE/SERVICE DEF SYSTEM Work Completed - pm - svc def - svc crane - svc out riggers	In Date: 03/13/2014 Closed: 03/2 Parts Issued Quantit Napagold Oil Filter 1.0 Napagold Fuel Filter 1.0 15w40 Bulk South Reg 14.0 Wiper Blade 2.0 Washer Fl 1.0	24/201
Problem: P.M.SERVICE/SERVICE DEF SYSTEM Work Completed - pm - svc def - svc crane - svc out riggers	In Date: 03/13/2014 Closed: 03/2 Parts Issued Quantit Napagold Oil Filter 1.0 Napagold Fuel Filter 1.0 15w40 Bulk South Reg 14.0 Wiper Blade 2.0 Washer Fl 1.0 Used Fire X Refurbished 1.0	24/201

Work Order: Problem:	1403948 dead battery	Meter:	11044		In Date:	04/23/2014	Closed:	04/29/2014
Work Com	npleted			Parts Issued			Qı	uantity
0	ed batt rechecked failed ps 13 955a ds batt passed test	8.5v 369 cca replac	e batt aces code he	Shop Supplies				1.00
- transport	t and pickup vehicle at deale	r passenger batter	y defective					
- Shop Sup	pplies							
	Hours: 2.00		Comm: 0.00	Labor: 120.00	Parts: 2.0	0	Total:	122.00
Nork Order: Problem:		Meter:	12000		In Date:	05/23/2014	Closed:	05/28/2014
Work Com	npleted			Parts Issued			Qı	uantity
- svc def sy	ys			Def Fluid 2.5				1.00
- Shop Sup	pplies			Shop Supplies				1.00
	Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 18.	53	Total:	78.53
Vork Order: Problem:	1407177 P.M.SERVICE	Meter:	14555		In Date:	07/22/2014	Closed:	07/28/2014
Work Com	npleted			Parts Issued			Qı	uantity
- pm				Air Filter (gold), Air	<sup>r</sup> Panel			1.00
- def avc				Napagold Oil Filter	r			1.00
- crane svo	C			Napagold Fuel Filte	er			1.00
- repaired	ground for tag light			15w40 Bulk South	Reg			14.00
- repaired	bracket and bolts on light ba	ar		Wiper Blade				2.00
- unsiezed	l and lubed vise			Washer Fl				1.00
- unsiezed	l and lubed outriggers pins a	nd leg extentions		Def Fluid 2.5				1.00
- Shop Sup	pplies			Napa Trans Filter				1.00
				Wd40 16oz				1.00
				Macs Chain Cable	Lube			1.00
				Shop Supplies				1.00
	Hours: 12.50		Comm: 0.00	Labor: 750.00	Parts: 159	9.74	Total:	909.74

4/3/2023 9:56:10 AM

Vork Order: 1409 Problem: flat tir		Meter:	15595		In Date:	09/08/2014	Closed:	09/15/2014
Work Completed	ł			Parts Issued			Qı	uantity
- replace left real	r inner tire with good used 19	.5 tire from	stock room nc	Shop Supplies				1.00
- Shop Supplies	-							
	Hours: 1.50		Comm: 0.00	Labor: 90.00	Parts: 2.0	0	Total:	92.00
Vork Order: 1500 Problem: PM, [		Meter:	15655		In Date:	01/05/2015	Closed:	01/15/2015
Work Completed	ł			Parts Issued			Qı	uantity
- pm				Napagold Oil Filter				1.00
- def svc				Napagold Fuel Filter				1.00
- crane svc				15w40 Bulk South Re	g			14.00
- repaired open i	n cabinet for runnig lights			Washer Fl				1.00
- disassembled li	ght and repaired connection	at strobe		Wiper Blade				2.00
- unsiezed and lu	lbed vise			Def Fluid 2.5				1.00
- unsiezed and lu	bed outrigger pins and leg ex	ĸt		Napa Trans Filter				1.00
	eed circuit and pump operatic eration excercised valve bank			Shop Supplies				1.00
again ds batt 947	t start ck batt removed to recl bolts occa batt bad he00p dt ices he50p dtc 9c794w	0						
- ckecked for cod	les b1318 v0212 u3003							
- transport pick ι battery	up vehicle at dealer for warran	ty repair p	assenger side					
- Shop Supplies								
	Hours: 17.75		Comm: 0.00	Labor: 1,065.00	Parts: 130	).93	Total:	1,195.93

	1503800	Meter:	17647		In Date:	04/14/2015	Closed:	04/15/2015
Problem:	replaced broken pendant switch							
Work Com	pleted			Parts Issued			Qı	uantity
- rr pendar	nt switch with a good used one			Shop Supplies				1.00
- Shop Sup	oplies							
	Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 2.0	0	Total:	62.00
Nork Order: Problem:	1504960 rs inside tire has blot in it and car	Meter: ne apart	18668		In Date:	05/14/2015	Closed:	05/19/2015
Work Com	pleted			Parts Issued			Qı	uantity
- replace d	lamage right rear inner tire with rir	n		19.5 Continental				1.00
- Shop Sup	oplies			Shop Supplies				1.00
				Tire Disposal Fee				1.00
			• • • • •		<b>D</b> / /0	4.00	<b>T</b> . ( . 1	F00 00
	Hours: 1.25		Comm: 0.00	Labor: 75.00	Parts: 464	4.23	l otal:	539.23
Nork Order:	1505850	Meter:	19383	Labor: 75.00	Parts: 464	4.23		
			19383	Labor: 75.00				
	1505850 inner cooler hose broke off, steer		19383	Parts Issued			Closed:	
Problem: Work Com	1505850 inner cooler hose broke off, steer		19383		In Date:		Closed:	06/19/2015
Problem: Work Com - install ste	1505850 inner cooler hose broke off, steer	ing whee co	19383 ver	Parts Issued	In Date:		Closed:	06/19/2015 Jantity
Problem: Work Com - install ste - inner coc warranty	1505850 inner cooler hose broke off, steer pleted eering wheel cover	ing whee co d sent to the	19383 ver dealer for	<b>Parts Issued</b> Stg Wheel Cov - Fo	In Date:		Closed:	06/19/2015 Jantity 1.00
Problem: Work Com - install ste - inner coc warranty - transport air cooler	1505850 inner cooler hose broke off, steer apleted eering wheel cover oler boot broken verify concern and	ing whee co d sent to the warrenty rep	19383 ver dealer for	<b>Parts Issued</b> Stg Wheel Cov - Fo	In Date:		Closed:	06/19/2015 Jantity 1.00
Problem: Work Com - install ste - inner coc warranty - transport air cooler	1505850 inner cooler hose broke off, steer opleted eering wheel cover oler boot broken verify concern and and pickup[ vehicle at dealer for y performed recall 14e0s pcm prog	ing whee co d sent to the warrenty rep	19383 ver dealer for	<b>Parts Issued</b> Stg Wheel Cov - Fo	In Date:		Closed:	06/19/2015 Jantity 1.00

Vork Order: 1507188 Problem: pm	Meter: 21152		<b>In Date:</b> 07/20/	/2015 Closed:	07/22/2015
Work Completed		Parts Issued		Q	uantity
- pm		Air Filter (gold), Air	r Panel		1.00
- def svc		Napagold Oil Filter	r		1.00
- crane svc		Napagold Fuel Filte	er		1.00
- repaired open in cabinet to marker light		15w40 Bulk South	Reg		15.00
- repaired wiring connections to light		Wiper Blade			2.00
- unsiezed and lubed vise		Def Fluid 2.5			3.00
- unsiezed and lubed outrigger and leg ext		Napa Trans Filter			1.00
- repaired line leak on crane		Shop Supplies			1.00
- Shop Supplies					
Hours: 14.50	Comm: 0.00	Labor: 870.00	Parts: 177.88	Total:	1,047.88
ork Order: 1511467 Problem: bad batteries and tires worn out	<b>Meter:</b> 24610		In Date: 11/09/	/2015 Closed:	11/30/2015
Work Completed		Parts Issued		Q	uantity
- ck batteries and failed load test recharged b	att and retested failed again	225 70r19.5 G Tire	New		2.00
- rotate 4 tires replaced two tires		Shop Supplies			1.00
- dealer to replace I side battery warranty		Tire Disposal Fee			2.00
- transport and pickup vehicle at dealer for wa	arranty repair				
- Shop Supplies					
Hours: 4.50	Comm: 0.00	Labor: 270.00	Parts: 1,040.19	Total:	1,310.19

# Work Order:1513110Meter:25382Problem:pm, tires, crane leaking hyd fluid needs a new crane cable

# **In Date:** 12/31/2015 **Closed:** 01/15/2016

Work Completed		Parts Issued		Quantity
- pm		Air Filter (gold), Air	Panel	1.00
- svc def		Napagold Oil Filter		1.00
- svc crane		Napagold Fuel Filte	1.00	
- repaired open in cabinet for running lights		15w40 Bulk South	Reg	15.00
- repaired connection in strobe light connection	on	22" Wiper Blade		2.00
- frt and rear brakes		Used Fire X Refurbi	ished	1.00
- rr 4 tires	Def Fluid 2.5		2.00	
- remove cable for cranereinstalled cable and	lock and line assy	Napa Trans Filter	1.00	
- remove boom tip lever and micro switch ass	y straightened and repaired	Brake Cleaner	2.00	
wiring		B Fluid Dot 3-32oz	1.00	
- unsiezed and lubed outrigger pins and leg e	xtentions	225 70r19.5 G Tire	New	4.00
- ck for crane leaks tightened and reseled line	to winch	Brake Pads		2.00
- Shop Supplies		Winch Cable Liftmo	1.00	
		Shop Supplies		1.00
		Tire Disposal Fee		4.00
Hours: 28.50	Comm: 0.00	Labor: 1,710.00	Parts: 2,682.04	Total: 4,392.04
ork Order: 1602590 Problem: Spot light	Meter: 26821		In Date: 03/11/2016	<b>Closed:</b> 03/21/201
Work Completed		Parts Issued		Quantity
- install go light		Golight & Mo	unt Kit	1.00
Chara Guardian		Pole Surface Moun	+	1.00

Comm: 0.00

- Shop Supplies

Faits issued		Quantity
Golight & Mou	nt Kit	1.00
Pole Surface Mount		1.00
U-bolt		2.00
Cable Tie		1.00
Paint Pen - Red		1.00
Shop Supplies		1.00
Labor: 480.00	Parts: 1,543.48	Total: 2,023.48

Vork Order: 1 Problem: C	604240 Crane not working.	Meter:	29046		In Date:	04/22/2016	Closed:	04/27/2016
Work Comp	leted			Parts Issued			Qu	uantity
- C/c Crane ı	not working.found no power	to crane.found	blown fuse for	Fuse				2.00
trailer lights.r	repair short on plug harness.	r&r fuse.test cra	ne.	Shop Supplies				1.00
- Shop Supp	lies							
	Hours: 3.00		Comm: 0.00	Labor: 180.00	Parts: 11.	.30	Total:	191.30
Vork Order: 1 Problem: D		Meter:	29848		In Date:	05/12/2016	Closed:	05/18/2016
Work Comp	leted			Parts Issued			Qı	uantity
- C/c Def lov	v.verify Def low.service Def sy	ystem.		Def Fluid 2.5				1.00
- Shop Supp	lies			Shop Supplies				1.00
	Hours: 1.00 605631 P.M.SERVICE,CRAKE BOOM	Meter: M PISTON LEA		Labor: 60.00 STEERING WHEEL (	Parts: 17. In Date: COVER	65 06/01/2016		77.65 06/16/201
Vork Order: 1 Problem: F Work Comp	605631 P.M.SERVICE,CRAKE BOOM		30261		In Date:		Closed:	
Problem: F	605631 P.M.SERVICE,CRAKE BOOM leted		30261	STEERING WHEEL	In Date: COVER		Closed:	06/16/201
Problem: F Work Comp	605631 P.M.SERVICE,CRAKE BOOM leted		30261	STEERING WHEEL ( Parts Issued	<b>In Date:</b> COVER r Panel		Closed:	06/16/2010 Jantity
Problem: F Work Comp - Pm service	605631 P.M.SERVICE,CRAKE BOOM leted		30261	STEERING WHEEL ( Parts Issued Air Filter (gold), Ai	In Date: COVER r Panel r		Closed:	06/16/2010 Jantity 1.00
Problem: F Work Comp - Pm service - Def Service - Crane servi	605631 P.M.SERVICE,CRAKE BOOM leted		30261	STEERING WHEEL ( Parts Issued Air Filter (gold), Ai Napagold Oil Filte	In Date: COVER r Panel r er		Closed:	06/16/2010 Jantity 1.00 1.00
Problem: F Work Comp - Pm service - Def Service - Crane servi - Steering co	605631 P.M.SERVICE,CRAKE BOOM leted		30261	STEERING WHEEL ( Parts Issued Air Filter (gold), Ai Napagold Oil Filte Napagold Fuel Filt	In Date: COVER r Panel r er		Closed:	06/16/2010 Jantity 1.00 1.00 1.00
Problem: F Work Comp - Pm service - Def Service - Crane servi - Steering co - Repaired b	605631 P.M.SERVICE,CRAKE BOOM leted		30261	STEERING WHEEL ( Parts Issued Air Filter (gold), Ai Napagold Oil Filte Napagold Fuel Filt 15w40 Bulk South	In Date: COVER r Panel r er		Closed:	06/16/2010 Jantity 1.00 1.00 1.00 15.00
Problem: F Work Compl - Pm service - Def Service - Crane servi - Steering co - Repaired b - Rear tripple	605631 P.M.SERVICE,CRAKE BOOM leted e. ice. over replaced. racket for lightbar		30261	STEERING WHEEL ( Parts Issued Air Filter (gold), Ai Napagold Oil Filte Napagold Fuel Filt 15w40 Bulk South 22" Wiper Blade	In Date: COVER r Panel r er		Closed:	06/16/2010 uantity 1.00 1.00 1.00 15.00 2.00
Problem: F Work Comp - Pm service - Def Service - Crane servi - Steering cc - Repaired b - Rear tripple - Vise and he	605631 P.M.SERVICE,CRAKE BOOM leted e. ice. over replaced. rracket for lightbar e light out.repaired ground.	M PISTON LEA	30261	STEERING WHEEL ( Parts Issued Air Filter (gold), Ai Napagold Oil Filte Napagold Fuel Filt 15w40 Bulk South 22" Wiper Blade Def Fluid 2.5	In Date: COVER r Panel r er Reg		Closed:	06/16/2010 Jantity 1.00 1.00 1.00 15.00 2.00 2.00
Problem: F Work Comp - Pm service - Def Service - Crane servi - Steering cc - Repaired b - Rear tripple - Vise and he - Boom tip s - Boom cylin	605631 P.M.SERVICE,CRAKE BOOM leted	M PISTON LEAH	30261 KING OIL, NEED	STEERING WHEEL ( Parts Issued Air Filter (gold), Ai Napagold Oil Filte Napagold Fuel Filt 15w40 Bulk South 22" Wiper Blade Def Fluid 2.5 Napa Trans Filter	In Date: COVER r Panel r er Reg ord		Closed:	06/16/201 Jantity 1.00 1.00 15.00 2.00 2.00 1.00
Problem: F Work Compl - Pm service - Def Service - Crane servi - Steering co - Repaired b - Rear tripple - Vise and he - Boom tip s - Boom cylin good used pi	605631 P.M.SERVICE,CRAKE BOOM leted	M PISTON LEA I. Id replaced cylin itch.	30261 KING OIL, NEED	STEERING WHEEL O Parts Issued Air Filter (gold), Ai Napagold Oil Filte Napagold Fuel Filt 15w40 Bulk South 22" Wiper Blade Def Fluid 2.5 Napa Trans Filter Stg Wheel Cov - F	In Date: COVER r Panel r er Reg ord		Closed:	06/16/201 Jantity 1.00 1.00 15.00 2.00 2.00 1.00 1.00
Problem: F Work Compl - Pm service - Def Service - Crane servi - Steering co - Repaired b - Rear tripple - Vise and he - Boom tip s - Boom cylin good used pi	605631 P.M.SERVICE,CRAKE BOOM leted	M PISTON LEA I. Id replaced cylin itch.	30261 KING OIL, NEED	STEERING WHEEL O Parts Issued Air Filter (gold), Ai Napagold Oil Filte Napagold Fuel Filt 15w40 Bulk South 22" Wiper Blade Def Fluid 2.5 Napa Trans Filter Stg Wheel Cov - F Rep Hydraulic Cyin	In Date: COVER r Panel r er Reg ord		Closed:	06/16/201 Jantity 1.00 1.00 1.00 2.00 2.00 1.00 1.00 1.00

Work Order:		Meter:	36049		In Date:	12/05/2016 <b>Clo</b>	osed:	12/12/2016
Problem:	Low DEF fluid.Missing hydra	aulic tank cap.						
Work Com	pleted			Parts Issued			Q	uantity
- Service D	ef System			Def Fluid 2.5				2.00
- Replace h	ydraulic tank fill neck assem	oly		Hydraulic Cap W S	creen			1.00
- Shop Sup	plies			Shop Supplies				1.00
	Hours: 1.50		Comm: 0.00	Labor: 90.00	Parts: 149	9.02	Total:	239.02
Work Order: Problem:	1613226 P.M.SERVICE,SPOT LIGHT	Meter: INOP.	36672		In Date:	12/30/2016 <b>Clo</b>	osed:	01/25/2017
Work Com	pleted			Parts Issued			Q	uantity
- Pm servic	e.			Napagold Oil Filter	ſ			1.00
- Service D	ef system.			Napagold Fuel Filt	er			1.00
- Service cr	ane			22" Wiper Blade				2.00
- Remove k	patteries.clean corrosion and	repaint brackets.		15w40 Bulk South	Reg			15.00
- Install inv	erter.			Washer Fluid Conc	entr			1.00
- Unsiezed	outriggers, remove slip plate	s and lube.		Used Fire X Refurb	ished			1.00
- Repair sp	ot light.			Def Fluid 2.5				1.00
- Shop Sup	plies			Aw68 Bulk Sr				5.00
				Napa Trans Filter				1.00
				Bulk Battery Cable				20.00
				Bat/cabl				20.00
				Cb185-150 Cir Brk	r			1.00
				Cabl/lug				4.00
				Vinyl Electrical Tap	е			2.00
				Glos Blk				2.00
				Terminal				2.00
				Cpi 1575 Inverter 1	500 W			1.00

Labor: 960.00

Parts: 463.03

Total: 1,423.03

Work Order: Problem:	1703278 Low DEF fluid	Meter:	38644		In Date:	04/03/2017	Closed:	04/10/2017
Work Com				Parts Issued			Qı	uantity
- Service D	•			Def Fluid 2.5				1.00
- Shop Sup				Shop Supplies				1.00
	Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 17.	.65	Total:	77.65
Work Order: Problem:	1706617 PM Servvice.Dead Batteries	Meter:	41725		In Date:	07/06/2017	Closed:	07/31/201
Work Com	pleted			Parts Issued			Qı	uantity
- Pm Servio	ce.			Napagold Oil Filter				1.00
- Both batt	teries replaced.test starting and	d charging syste	m.	15w40 Bulk South F	Reg			15.00
- Crane Pm	n.service out riggers.r/r right o	utrigger(stuck)tc	clean and scrape	Napagold Fuel Filte	r			1.00
	e channels and lube all.			22" Wiper Blade				2.00
- Rotate ar	nd balance six tires.			Washer Fluid Conce	entr			1.00
- R/r Def ta	ank frame and brackets to rem	ove reductant ta	ank.dismantle and	Battery				2.00
	iter assembly.reasemble tank a	ind pump and re	eseal.clean all	Napa Trans Filter				1.00
corrosion.				Air Filter (gold), Air	Panel			1.00
	l used to perform regen for cle and activate Def level sensor.	0	iter system.reset	Aw68 Bulk Sr				5.00
- Def Servi				Reservoir				1.00
- Shop Sup				lock ring				1.00
2.100 000				Seal Spe				1.00
				Retainer				2.00
				Retainer				2.00
				Shop Supplies				1.00
	Hours: 22.25		Comm: 0.00	Labor: 1,335.00	Parts: 77	7.79	Total:	2,112.79

Work Order: 1711606	Meter: 45851		In Date:	11/28/2017 Closed: 11/30/201
Problem: Low DEF fluid				
Work Completed		Parts Issued		Quantity
- Inspect and service Def system.		Def Fluid 2.5		2.00
- Shop Supplies		Shop Supplies		1.00
Hours: 1.00	Comm: 0.00	Labor: 60.00	Parts: 37.3	7 Total: 97.37

Meter: 49126

## Work Order: 1801236 Problem: PM Service.

#### In Date: 02/01/2018 **Closed:** 02/22/2018

Work Completed	Parts Issued	Quantity
- Pm Service.	Napagold Oil Filter	1.00
- Pm crane and service outriggers.	15w40 Bulk South Reg	15.00
- Mount four tires.rotate and balance all six.	Napagold Fuel Filter	1.00
- Replace three lamp light bar above rear bumper.	Air Filter (gold), Air Panel	1.00
- Replace both front rotors, pads and calipers, rear pads and calipers also cut	22" Wiper Blade	2.00
rear rotors.service caliper mounts.bleed system and flush fluid.	Washer Fluid Concentr	1.00
- Remove rust and treatment applied paint rear bumper and outrigger right	Aw68 Bulk Sr	5.00
side.	Napagold Oil Filter	2.00
- Repaired wiring to rear spot light assembly and replace remote battery	Napa Trans Filter	1.00
- Unseized vise and lube to work properly.	225-70r19.5 Mounted Endurance Rsa	4.00
- Shop Supplies	Ford Original Brake Pads	2.00
	Brake Rotor Assy	2.00
	Brake Caliper	2.00
	Brake Caliper	2.00
	B Fluid Dot 3-32oz	2.00
	Non-chlor Brake Clnr	2.00
	Elec Battery A23	1.00
	Silicone Spray 10oz	1.00
	Gl Whit	2.00
	Led Id Bar 6 Ctrs	1.00
	Macs Chain Cable Lube	1.00
	6 Inch Id Bar Kit	1.00
	Weatherguard Key K751	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
	Freight Charge	1.00
Hours: 24.50 Comm: 0.00	Labor: 1,470.00 Parts: 3,016.50	Total: 4,486.50

Work Order: Problem:	1806124 Low on DEF Fluid.No power.	Meter: 51825		In Date:	06/15/2018	Closed:	06/26/201
Work Con	npleted		Parts Issued			Q	uantity
- Inspect a	and service Def system.		Def Fluid 2.5				2.00
	e for no power.perform Def reg ter then test drive.	eneration with scan tool to clean	Shop Supplies				1.00
- Shop Su	pplies						
	Hours: 3.50	Comm: 0.00	Labor: 210.00	Parts: 36	14	Total:	246.14
Vork Order: Problem:	1809315 P.M.SERVICE	Meter: 53555		In Date:	09/11/2018	Closed:	09/28/201
Work Con	npleted		Parts Issued			Q	uantity
- Pm Servi	ice.		15w40 Bulk South	Reg			15.00
- Pm Cran	e and outriggers		Napagold Oil Filte	r			1.00
	Def system.		Napagold Fuel Filt	er			1.00
- Replace	both left rear tires and rotate ne	ew tires to the front.	22" Wiper Blade				2.00
- Replace	both windshield washer nozzles		Washer Fluid Conc	centr			1.00
- Check Pt	to for leaking fluid.found leaking	9 Pto pressure sensor.clean Pto	Syn Atf Bulk South	1			4.00
and replac	e pressure sensor.		Aw68 Bulk Sr				5.00
- Shop Su	pplies		Napa Trans Filter				1.00
			Def Fluid 2.5				2.00
			225-70r19.5 Moun	ited Enduranc	e Rsa		2.00
			Washer Nozzle				2.00
			Pto Pressure Switc	h			1.00
			Shop Supplies				1.00
			Tire Disposal Fee				2.00
	Hours: 12.00	Comm: 0.00	Labor: 720.00	Parts: 1,1	96.37	Total:	1,916.37

#### Work Order: 1905503 Meter: 58546 05/23/2019 Closed: 05/31/2019 In Date: Problem: PM Service. Parts Issued Quantity **Work Completed** Napagold Oil Filter 1.00 - Pm Service 15w40 Bulk South Reg 15.00 - Service crane and outriggers and replace retainer pin assembly to left outrigger slider. Napagold Fuel Filter 1.00 - Def service. Air Filter (gold), Air Panel 1.00 - Replaced 3rd brake lamp bulbs Washer Fluid Concentr 1.00 - Replaced 6 way socket and replace wiring harness (corrosion damage). 22" Wiper Blade 2.00 - Rotate and balance 6 tires. Used Fire X Refurbished 1.00 - Performed exhaust regeneration with scan tool.reset adaptives and cleared Outrigger Pin 1.00 codes. Aw68 Bulk Sr 5.00 - Repaired right rear cabinet lock linkages fell off. Napa Trans Filter 1.00 - Shop Supplies Def Fluid 2.5 2.00 **Boxed Miniatures** 3.00 trailer plug 1.00 Shop Supplies 1.00 Hours: 14.50 Comm: 0.00 Labor: 971.50 Parts: 398.78 Total: 1,370.28 06/03/2019 Closed: 06/06/2019 Work Order: 1905840 Meter: 58546 In Date: Problem: replace tail gate & repair end cap Parts Issued **Work Completed** Quantity Shop Supplies 1.00 - R/r tailgate(s) from vehicle and swap with surplus truck; weld, paint, and silicone missing endcap on utility box - Shop Supplies Hours: 4.00 Comm: 0.00 Labor: 268.00 Parts: 3.00 Total: 271.00

Meter: 59349 In Date: 11/19/2019 Closed: 12/16/2019 Work Order: 1911955 Problem: PM Service.Dead batteries. **Work Completed** Parts Issued Quantity 15w40 Bulk South Reg 15.00 - Pm Service. Napagold Oil Filter 1.00 - Service crane and outriggers. Napagold Fuel Filter 1.00 - Replace and rewire left front utility body marker lamp. 22" Wiper Blade 2.00 - Service Def system. Washer Fluid Concentr 1.00 - Test and replace both batteries. Aw68 Bulk Sr 5.00 - Shop Supplies Napa Trans Filter 1.00 Grommet Mount Kit 1.00 Def Fluid 2.5 1.00 2.00 Battery Flat Blk 1.00 Shop Supplies 1.00 Hours: 9.50 Comm: 0.00 Labor: 693.50 Parts: 459.46 Total: 1,152.96 Work Order: 2003827 Meter: 61470 In Date: 04/16/2020 Closed: 04/27/2020 Problem: Turbo inlet hose broken. Dante lecuad Augustites, **Work Completed** - Replace turbo outlet hose assembly and clean engine area. - Inspect Def system. - Diagnose for no power.perform Regen with scan tool to clean Def filter.roadtest and clear codes. - Shop Supplies

Hours: 5.50

Comm: 0.00

Parts Issued		Quantity
Tube - Outlet		1.00
Def Nozzle		1.00
Def Fluid 2.5		1.00
Shop Supplies		1.00
Labor: 401.50	Parts: 129.79	Total: 531.29

Meter: 61476

## Work Order: 2006785 Problem: PM Service

## **In Date:** 07/13/2020 **Closed:** 07/22/2020

Work Completed	Parts Issued	Quantity
- Pm Service.	Napagold Fuel Filter	1.00
- Service crane and outriggers.	Air Filter (gold), Air Panel	1.00
- Def Service.	Used Fire X Refurbished	1.00
- Perform exhaust filter regeneration with scan tool and reset adaptive	es. Napagold Oil Filter	1.00
- Balance and rotate six tires.	15w40 Bulk South Reg	13.00
- Fabricate and replace guide for the crane reel two block cable.	Washer Fluid Concentr	1.00
- Repaired wiring to Id lamp assembly.	22" Wiper Blade	2.00
- Unseized and service vise.	Aw68 Bulk Sr	6.00
- Clean engine compartment.	Napa Trans Filter	1.00
- Shop Supplies	Macs Chain Cable Lube	1.00
	Def Fluid 2.5	2.00
	Shop Supplies	1.00
Hours: 15.50 Comm: 0.00	Labor: 1,131.50 Parts: 204.04	Total: 1,335.54

Work Order: 2012993 Meter: 62881 Problem: PM Service.Vehicle cuts off while driving.All warning lights flashing on dash.

Quantity **Work Completed** Parts Issued Wd40 Spr 1.00 - Preventive Maint, Service 15w40 Bulk South Reg 13.00 - service crane and outriggers. Napagold Oil Filter 1.00 - service Def system. Washer Fluid Concentr 1.00 - replace corroded trailer socket. 22" Wiper Blade 2.00 - replace how's my driving decal. Napagold Fuel Filter 1.00 - c/s vehicle cuts off while driving. scan and test drive and was unable verify customer concern at this time. Air Filter (gold), Air Panel 1.00 - perform Dpf regeneration. Mac Battery Protect 1.00 - Shop Supplies Aw68 Bulk Sr 6.00 Napa Trans Filter 1.00 trailer plug 1.00 Shop Supplies 1.00 Hours: 12.75 Comm: 0.00 Labor: 930.75 Parts: 177.64 Total: 1,108.39 Work Order: 2100491 Meter: 62881 In Date: 01/14/2021 **Closed:** 01/14/2021 Problem: Dead batteries. Has to jump start in WUD parking lot **Work Completed** Parts Issued Quantity Shop Supplies 1.00 - Fully recharge both batteries.test starting and charging system, all tested ok.had to jump start in Wud parking lot. - Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 4.00

Total: 77.00

In Date: 12/31/2020 Closed: 01/12/2021

# Work Order:2108519Meter:63750Problem:PM Service.Message on dash to put in Park.

# In Date: 08/06/2021 Closed: 08/25/2021

Work Completed		Parts Issued			Qı	lantity
- Preventive Maint. Service		Washer Fluid Concentr 22" Wiper Blade				1.00
- Service crane, outrigger, change filter & top of	f fluid.				2.00	
- Service Def system. Top off tank. Preform Rege	n with scan tool and reset	Napagold Oil Filter				1.00
parameters.		15w40 Bulk South F	Reg			13.00
- Computer diagnose for message on dash with		Napagold Fuel Filte	r			1.00
restrain sensor.replace front impact severity sense several times and recheck for codes.all checked of		Air Filter (gold), Air	Panel			1.00
- Fill all tires with nitrogen, balance & rotate.	out ok.	Used Fire X Refurbi	shed			1.00
- Fill all tires with hitrogen, balance & rotate. - Shop Supplies		Aw68 Bulk Sr				6.00
		Napa Trans Filter				1.00
		Def Fluid 2.5				1.00
		Sensor				1.00
		Shop Supplies				1.00
Hours: 12.00	Comm: 0.00	Labor: 876.00	Parts: 164	1.61	Total:	1,040.61
ork Order: 2112359	Meter: 65977		In Date:	11/18/2021	Closed:	12/01/202
<b>Problem:</b> Oil leaking from crane, wiper blades.	<b>Meter:</b> 65977	Parts Issued	In Date:	11/18/2021		
Problem: Oil leaking from crane,wiper blades. Work Completed			In Date:	11/18/2021		antity
<b>Problem:</b> Oil leaking from crane, wiper blades.		Aw68 Bulk Sr		11/18/2021		
<ul><li>Problem: Oil leaking from crane,wiper blades.</li><li>Work Completed</li><li>Diagnose and repair hydraulic oil leak in crane</li></ul>		Aw68 Bulk Sr Non-chlor Brake Cli		11/18/2021		<b>iantity</b> 5.00 2.00
<ul><li>Problem: Oil leaking from crane,wiper blades.</li><li>Work Completed</li><li>Diagnose and repair hydraulic oil leak in crane when done.</li></ul>		Aw68 Bulk Sr		11/18/2021		<b>iantity</b> 5.00
<ul> <li>Problem: Oil leaking from crane,wiper blades.</li> <li>Work Completed <ul> <li>Diagnose and repair hydraulic oil leak in crane when done.</li> <li>Replace wiper blades</li> </ul> </li> </ul>		Aw68 Bulk Sr Non-chlor Brake Cli			Qı	<b>iantity</b> 5.00 2.00
<ul> <li>Problem: Oil leaking from crane,wiper blades.</li> <li>Work Completed <ul> <li>Diagnose and repair hydraulic oil leak in crane when done.</li> <li>Replace wiper blades</li> <li>Shop Supplies</li> </ul> </li> </ul>	housing.de-grease residue	Aw68 Bulk Sr Non-chlor Brake Cli Shop Supplies	nr		Qu Total:	<b>antity</b> 5.00 2.00 1.00 184.21
Problem: Oil leaking from crane,wiper blades. Work Completed - Diagnose and repair hydraulic oil leak in crane when done. - Replace wiper blades - Shop Supplies Hours: 2.25	housing.de-grease residue Comm: 0.00	Aw68 Bulk Sr Non-chlor Brake Cli Shop Supplies	nr Parts: 19.	96	Qu Total: Closed:	<b>antity</b> 5.00 2.00 1.00 184.21
Problem: Oil leaking from crane,wiper blades. Work Completed - Diagnose and repair hydraulic oil leak in crane when done. - Replace wiper blades - Shop Supplies Hours: 2.25 York Order: 2202375 Problem: Bad tire rear right	housing.de-grease residue Comm: 0.00 Meter: 71692	Aw68 Bulk Sr Non-chlor Brake Clu Shop Supplies Labor: 164.25	nr Parts: 19. In Date:	96 03/02/2022	Qu Total: Closed:	antity 5.00 2.00 1.00 184.21 03/04/2022
Problem: Oil leaking from crane,wiper blades. Work Completed - Diagnose and repair hydraulic oil leak in crane when done. - Replace wiper blades - Shop Supplies Hours: 2.25 York Order: 2202375 Problem: Bad tire rear right Work Completed	housing.de-grease residue Comm: 0.00 Meter: 71692	Aw68 Bulk Sr Non-chlor Brake Clu Shop Supplies Labor: 164.25	nr Parts: 19. In Date:	96 03/02/2022	Qu Total: Closed:	antity 5.00 2.00 1.00 184.21 03/04/2022
Problem: Oil leaking from crane,wiper blades. Work Completed - Diagnose and repair hydraulic oil leak in crane when done. - Replace wiper blades - Shop Supplies Hours: 2.25 York Order: 2202375 Problem: Bad tire rear right Work Completed - R/r tires and wheels right rear. Rotate front tire	housing.de-grease residue Comm: 0.00 Meter: 71692	Aw68 Bulk Sr Non-chlor Brake Clu Shop Supplies Labor: 164.25 Parts Issued 225/70r19.5 Mount	nr Parts: 19. In Date:	96 03/02/2022	Qu Total: Closed:	antity 5.00 2.00 1.00 184.21 03/04/2022 antity 2.00

Nork Order: 2202997 Problem: PM Service.	<b>Meter:</b> 72547		In Date:	03/18/2022	Closed:	03/30/2022	
Work Completed		Parts Issued			Qı	uantity	
- Preventive Maint. Service		15w40 Bulk South	Reg			13.00	
- Clean To Diagnose Bad Brake Booster.	Replaced Leaking Hydrobooster	Napagold Oil Filter	r			1.00	
Assy.clean Off Resedue From Around Lea	ak And Under Truck. Fill System And	Napagold Fuel Filte	er			1.00	
Bleed Air/test		Air Filter				1.00	
- Service Crane And Out Riggers		Washer Fluid Conc	entr			1.00	
<ul> <li>Fill/top Off Def Fluid</li> <li>R&amp;r Right Front Head Lamp To Replaced Side Marker Bulb</li> <li>Shop Supplies</li> </ul>	22" Wiper Blade				2.00		
	ed Side Marker Bulb	Non-chlor Brake Clnr				1.00	
		Mercon V Atf				2.00	
		Brakr Booster				1.00	
		Macs Chain Cable	Lube			1.00	
		Aw68 Bulk Sr				6.00	
		Napa Trans Filter				1.00	
		Def Fluid 2.5				1.00	
		Boxed Miniatures				1.00	
		Shop Supplies				1.00	
Hours: 9.75	Comm: 0.00	Labor: 711.75	Parts: 40	1.83	Total:	1,113.58	
<b>/ork Order:</b> 2204146 <b>Problem:</b> Light bar inopNeed lights w	<b>Meter:</b> 74425 hen working in nights.		In Date:	04/19/2022	Closed:	04/22/2022	
Work Completed		Parts Issued			Qu	uantity	
- Emergency Light Bar Inop. Diagnose A	nd Replaced Module In Light Bar	Circuit Board - Libe	erty Lightbar			1.00	
Assy.		Shop Supplies				1.00	
- Shop Supplies		Freight Charge				1.00	

Hours: 2.50

Comm: 0.00

Circuit Board - Libe	erty Lightbar	1.00
Shop Supplies		1.00
Freight Charge		1.00
Labor: 182.50	Parts: 545.91	Total: 728.41

Vork Order: Problem:	2206181 Bad tire (nail) drivers rear.	<b>Meter:</b> 76445		In Date:	06/13/2022	Closed:	06/15/202
Work Com	pleted		Parts Issued			Qu	uantity
- Tire unde	er crane not repairable.also bo	th tires worn out.replace both tires	225/70r19.5 Mounte	ed Gy Endur	ance		2.00
	Nitrogen fill all.		Shop Supplies				1.00
- Shop Sup	oplies		Tire Disposal Fee				2.00
	Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 89	6.48	Total:	969.48
/ork Order: Problem:	2207116 PM Service.	Meter: 78715		In Date:	07/07/2022	Closed:	07/15/202
Work Com	pleted		Parts Issued			Qı	uantity
- Preventiv	e Maint. Service		Napagold Oil Filter				1.00
- service cr	rane and outriggers		15w40 Bulk South Reg				13.00
- replaced	broken pintle pin and tighten	loose hitch /ball	Used Fire X Refurbished			1.00	1.00
- replaced	front and rear brake pads serv	vice rotors ,calipers, and unseized	Napagold Fuel Filter				1.00
	blaced front and rear brake pads service rotors ,calipers, and unseized n caliper slides. Lube hardware and reinstall. Test drive to "break in"	Washer Fluid Concentr 22" Wiper Blade				1.00	
	placed broken pintle pin and tighten loose hitch /ball placed front and rear brake pads service rotors ,calipers, and unseized en caliper slides. Lube hardware and reinstall. Test drive to "break in" es after repair					2.00	
			Air Filter				1.00
	n tool performed exhaust filter	regeneration top of def fluid reset	Aw68 Bulk Sr				6.00
adaptives			Napa Trans Filter				1.00
- Shop Sup	opnes		Pintle Pin W/clip			Qa Total: 2 Closed: Qa	1.00
			Brake Pads				2.00
			Non-chlor Brake Clnr			2.00	
			225/70r19.5 Mounted Gy Endurance Def Fluid 2.5			2.00	
						2.00	
			Shop Supplies				1.00
			Tire Disposal Fee				2.00
	Hours: 20.50	Comm: 0.00	Labor: 1,496.50	Parts: 1,2	37.24	Total:	2,733.74

Vork Order: Problem:	2209941 Both batteries dead. Will not	Meter: 78725		In Date:	09/26/2022	Closed:	10/05/202
		t charge					
Work Com	pleted		Parts Issued			Q	uantity
•		arge both batteries, test battery &	Battery				2.00
	ystem, batteries failed the load	t test. Replace both batteries.	Shop Supplies				1.00
- Shop Suj							
	Hours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 257			403.37
/ork Order: Problem:		Meter: 82542 ng. Leak from Hydraulic system (tanl	k in bed/lines?)	In Date:	01/09/2023	Closed:	02/10/202
Work Com		ig. Loak nom hydradio byotom (tam	Parts Issued			0	uantity
	-		Napagold Oil Filter			4	1.00
	ve Maint. Service		15w40 Bulk South				13.00
	0,	te & replace leaking Hydraulic tank.	Washer Fluid Conc	5			
	rane & outriggers.			entr			1.00
	windshield. Repair by Bob's Au	uto Glass. See attachment.	22" Wiper Blade Fuel Filter Kit				2.00
- Replace	how's my driving decal.						1.00
- Remove	tool, bed liner & pressure clea	an hydraulic fluid from utility body.	Napa Trans Filter				1.00
- Service D	Def system.		Non-chlor Brake Cl	nr			3.00
- Fill all tire	es with nitrogen, balance & ro	tate.	Aw68 Bulk Sr				80.00
- Shop Su	pplies		Hydraulic Tank		257.37 Total: e: 01/09/2023 Closed: Qu 1,050.62 Total:	1.00	
			1"x2"x4' Steel Tube	2			1.00
			Def Fluid 2.5				2.00
			Shop Supplies				1.00
	Hours: 14.25	Comm: 387.94	Labor: 1,040.25	Parts: 1,0	50.62	Total:	2,478.81
Vork Order:	2301148	Meter: 82448		In Date:	02/02/2023	Closed:	
Problem:	Cracked Windshield						
Work Com	pleted						
- Glass,cab	-						

Parts: 0.00

Labor: 0.00

4/3/2023 9:56:11 AN	_	Palm 0189849		Management Asset Maintenand Utility Body, 16,500 Gvwr, Hear		ane		
Work Order:	2301660	Meter:	82834		In Date:	02/21/2023	Closed:	
Problem:	Hydraulic crane not wo	orking.						
Work Com	pleted							
- Hydraulic	& Pressure Sys							
	Hours: 0.00		Comm: 0.00	Labor: 0.00	Parts: 0.00	)	Total:	0.00
Vork Order:	2302464	Meter:	83124		In Date:	03/10/2023	Closed:	03/10/2023
Problem:	Transition Prep Charg	е						
Work Com	pleted							
- Transition	n Prep Charge							
	Hours: 2.00		Comm: 0.00	Labor: 146.00	Parts: 0.00	)	Total:	146.00
Fotal Hours: 3	70.50 Total I	_abor: 23	3,812.25	Total Comm: 387.94		Total Parts	: 20,374.08	}