

3/2/2017
8:52:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162775 2006 GMC 1500 Pickup, 1/2 Ton, Wideside

Workorder: 635399 **Problem:** WASH VEHICLE

Meter Reading: 0	Labor	Parts
In Date: 03/07/2006	Hours	Description
Close Date: 03/07/2006		Quantity
- Wash Vehicle	2.80	
- Pre-Delivery Inspection		
- Make Duplicate Keys For New Vehicle		
Parts Charge:	0.00	Labor Charge: 15.00

Workorder: 635431 **Problem:** INSTALL KNOCK BOX

Meter Reading: 40	Labor	Parts
In Date: 03/07/2006	Hours	Description
Close Date: 03/20/2006		Quantity
- Mount Knck Box Fabricate Wiring	3.50	80865 FUSEHOLDER IMPERIAL 80865
- Shop Supplies		SHOP SUPPLIES
Parts Charge:	7.87	Labor Charge: 175.00

Workorder: 635699 **Problem:** 001 DETAIL VEHICLE 03/07/06

Meter Reading: 0	Labor	Parts
In Date: 03/07/2006	Hours	Description
Close Date: 04/03/2006		Quantity
- 001 Detail Vehicle		03/07/06
Parts Charge:	0.00	Labor Charge: 0.00 Commercial Charge: 7.14

Workorder: 646836 **Problem:** P.M.SERVICE

Meter Reading: 3424	Labor	Parts
In Date: 10/06/2006	Hours	Description
Close Date: 10/10/2006		Quantity
- Pm Service	2.75	10W30 MOTOR OIL
- Fill Tires W/Nitrogen		1066 WHITE LITHIUM (CRC 05037)
- Shop Supplies		SHOP SUPPLIES
		10020 INJECTOR CLEANER DON'T REORDER
		1036 OIL FILTER FRM PH3980 WIX 51036
Parts Charge:	26.76	Labor Charge: 41.25

3/2/2017
8:52:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162775 2006 GMC 1500 Pickup, 1/2 Ton, Wideside

Workorder: 649490

Problem: DEAD BATTERY

Meter Reading: 3813	Labor	Parts	
In Date: 12/04/2006	Hours	Description	Quantity
- Test Starting/Charging Sys; Test For Drain Charge; Test Battery; No Problem Found	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 2.00	Labor Charge: 55.00		

Workorder: 737066

Problem: P.M.SERVICE

Meter Reading: 5380	Labor	Parts	
In Date: 04/11/2007	Hours	Description	Quantity
- Pm Service	3.00	1036 OIL FILTER FRM PH3980 WIX 51036	1.00
- Service Rear Brakes & Test Drive		SHOP SUPPLIES	1.00
- Shop Supplies		10W30 MOTOR OIL	5.00
Parts Charge: 17.09	Labor Charge: 55.00		

Workorder: 745942

Problem: P.M.SERVICE

Meter Reading: 7192	Labor	Parts	
In Date: 10/19/2007	Hours	Description	Quantity
- Pm Service	3.50	10W30 MOTOR OIL	5.00
- Service Rear Brakes		1036 OIL FILTER FRM PH3980 WIX 51036	1.00
- Test Drive		1066 WHITE LITHIUM (CRC 05037)	1.00
- Shop Supplies		10020 INJECTOR CLEANER DON'T REORDER	1.00
		SHOP SUPPLIES	1.00
		31-22 WIPER BLADES 22" WIPER BLADE	2.00
Parts Charge: 38.12	Labor Charge: 30.00		

3/2/2017
8:52:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162775 2006 GMC 1500 Pickup, 1/2 Ton, Wideside

Workorder: 837890

Problem: P.M.SERVICE

Meter Reading: 8955	Labor	Parts	
In Date: 05/01/2008	Hours	Description	Quantity
- Pm Service	4.00	10W30 MOTOR OIL	5.00
- Rear Brake Service		6678 AIR FILTER FRM CA8755A WIX 46678	1.00
- Glue & Screw Bed Protection Side Caps		1036 OIL FILTER FRM PH3980 WIX 51036	1.00
- Test Drive		31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Shop Supplies		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
		SHOP SUPPLIES	1.00
Parts Charge:	46.61	Labor Charge:	15.00

Workorder: 838895

Problem: R/R FLAT TIRE

Meter Reading: 9233	Labor	Parts	
In Date: 05/22/2008	Hours	Description	Quantity
- Repair R/R Tire	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

Workorder: 838897

Problem: SISTERS TOWING & TRANSPORTATON TOW FROM 451 S. CON

Meter Reading: 0	Labor	Parts	
In Date: 05/22/2008	Hours	Description	Quantity
- Sisters Towing & Transportaton Tow From 451 S. Congress - Tow To Sr Fleet			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	78.00

3/2/2017
8:52:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162775 2006 GMC 1500 Pickup, 1/2 Ton, Wideside

Workorder: 846897

Problem: P.M.SERVICE

Meter Reading: 11914	Labor	Parts	
In Date: 11/07/2008	Hours	Description	Quantity
- Pm Service	5.50	31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Clean & Adjust Rear Brakes		10W30 MOTOR OIL	5.00
- Test Drive		1036 OIL FILTER FRM PH3980 WIX 51036	1.00
- Transport & Pick Up At Dealer; Ft Crank Seal Leaking & Inter Shaft Noisy		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	28.99	Labor Charge:	60.00

Workorder: 938644

Problem: P.M.SERVICE

Meter Reading: 14276	Labor	Parts	
In Date: 06/04/2009	Hours	Description	Quantity
- Pm Service	3.25	10W30 MOTOR OIL	5.00
- Clean & Adjust Rear Brakes; Test Drive		1036 OIL FILTER FRM PH3980 WIX 51036	1.00
- Install New Decal		09997 BRAKE CLEAN	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		1066 WHITE LITHIUM (CRC 05037)	1.00
Parts Charge:	27.16	Labor Charge:	195.00

Workorder: 942618

Problem: NEEDS ALL TIRES

Meter Reading: 15560	Labor	Parts	
In Date: 08/27/2009	Hours	Description	Quantity
- C/S Flat Tire; Verify Concern; Put Spare Back Under Vehicle; Tires Are Rotted & Unsafe To Use; Replace All 4 Tires & Test Drive	2.25	758508188 245/70R17 WRG SILENT ARMOR 108T	4.00
		SHOP SUPPLIES	1.00
- Shop Supplies		TIRE DISPOSAL FEE	4.00
Parts Charge:	725.41	Labor Charge:	135.00

3/2/2017
8:52:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162775 2006 GMC 1500 Pickup, 1/2 Ton, Wideside

Workorder: 942717

Problem: Flat tire, 245/70R17

Meter Reading: 15560	Labor	Parts
In Date: 08/26/2009	Hours	Description
Close Date: 08/31/2009	Quantity	
- N/A		
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 66.00

Workorder: 946367

Problem: P. M. SERVICE

Meter Reading: 17114	Labor	Parts
In Date: 11/24/2009	Hours	Description
Close Date: 11/30/2009	Quantity	
- P. M. Service	3.00	10W30 MOTOR OIL
- Clean, Adjust & Test Drive Rear Brakes.		31-22 WIPER BLADES 22" WIPER BLADE
- Shop Supplies		6678 AIR FILTER FRM CA8755A WIX 46678
		09997 BRAKE CLEAN
		SHOP SUPPLIES
		1036 OIL FILTER FRM PH3980 WIX 51036
Parts Charge: 43.25	Labor Charge: 360.00	

Workorder: 1005407

Problem: P. M. SERVICE

Meter Reading: 19951	Labor	Parts
In Date: 05/25/2010	Hours	Description
Close Date: 05/27/2010	Quantity	
- P. M.	4.00	SHOP SUPPLIES
- Lubricate Adjusters On Ladder Rack, Fasten Down Rack.		10W30 MOTOR OIL
- Service Rear Brake Drum Service. Adjust Shoes.		09997 BRAKE CLEAN
- Shop Supplies		1036 OIL FILTER FRM PH3980 WIX 51036
Parts Charge: 22.01	Labor Charge: 240.00	

Workorder: 1008894

Problem: NO A/C, not blowing at all

Meter Reading: 20920	Labor	Parts
In Date: 08/18/2010	Hours	Description
Close Date: 08/25/2010	Quantity	
- C/S: A/C Blower Not Working. Verify, Perform Pinpoint Test & Found Burned Wire Harness For Resistor.	2.75	A/C RESISTER HARNESS
- Replace Wire Harness & Blower Resistor.		SHOP SUPPLIES
- Shop Supplies		A/C BLOWER RESISTER
Parts Charge: 134.82	Labor Charge: 165.00	

3/2/2017
8:52:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162775 2006 GMC 1500 Pickup, 1/2 Ton, Wideside

Workorder: 1012601

Problem: P. M., & Check engine light is on

Meter Reading: 21762 In Date: 11/09/2010	Close Date: 11/18/2010	Labor Hours	Description	Parts	Quantity
- P. M.		7.00	SHOP SUPPLIES		1.00
- Clean & Adjust Rear Brakes.			6678 AIR FILTER FRM CA8755A WIX 46678		1.00
- C/S: Check Engine Light Is On, Scan For Codes, Found Code P0171, P0174. Perform Pinpoint Test & Found Brake Vac Hose. Repair Vac Hose, Clear Code & Test Drive.			10W30 MOTOR OIL		5.00
			31-22 WIPER BLADES 22" WIPER BLADE		2.00
			09997 BRAKE CLEAN		1.00
			1036 OIL FILTER FRM PH3980 WIX 51036		1.00
- Service Ladder Rack.					
- Shop Supplies					
Parts Charge:		42.58	Labor Charge:		420.00

Workorder: 1105185

Problem: P. M. SERVICE

Meter Reading: 25283 In Date: 05/16/2011	Close Date: 05/20/2011	Labor Hours	Description	Parts	Quantity
- P. M. Service.		5.50	SHOP SUPPLIES		1.00
- Service Rear Brake Drums.			1036 OIL FILTER FRM PH3980 WIX 51036		1.00
- Tighten Ladder Rack, Check.			10W30 MOTOR OIL		6.00
- Repair Tail Light, R&R Bad Bulb On Cargo Light.			31-22 WIPER BLADES 22" WIPER BLADE		2.00
- Shop Supplies			USED FIREX REFURBED FIRE EXTINGUISHERS		1.00
Parts Charge:		46.10	Labor Charge:		330.00

Workorder: 1109300

Problem: L/REAR BRAKE LIGHT INOP.

Meter Reading: 26766 In Date: 08/31/2011	Close Date: 08/31/2011	Labor Hours	Description	Parts	Quantity
- Repair Left Rear Brake Light.		0.50			
Parts Charge:		0.00	Labor Charge:		30.00

3/2/2017
8:52:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162775 2006 GMC 1500 Pickup, 1/2 Ton, Wideside

Workorder: 1112141

Problem: P.M.SERVICE

Meter Reading: 27991	Labor	Parts	Quantity
In Date: 11/14/2011	Hours	Description	Quantity
- P. M. Service.	4.00	10W30 MOTOR OIL	6.00
- Service Rear Brakes.		1036 OIL FILTER FRM PH3980 WIX 51036	1.00
- Tighten Ladder Rack Bolts.		09997 BRAKE CLEAN	1.00
- Shop Supplies		6678 AIR FILTER FRM CA8755A WIX 46678	1.00
		SHOP SUPPLIES	1.00
Parts Charge:	34.27	Labor Charge:	240.00

Workorder: 1207543

Problem: pm

Meter Reading: 31220	Labor	Parts	Quantity
In Date: 08/10/2012	Hours	Description	Quantity
- Pm	9.00	SHOP SUPPLIES	1.00
- Rear Tail Light Out Rr Bulb And Repaired Socket Rr Bulb		31-22 WIPER BLADES 22" WIPER BLADE	2.00
For Center Brake		09997 BRAKE CLEAN	1.00
- Rr Oring For Regulator		10W30 MOTOR OIL	6.00
- Vacuum Out Leaves Binding Wiper Operation Touch Up		1036 OIL FILTER FRM PH3980 WIX 51036	1.00
Tag		3157 TAIL LIGHT BULBS	1.00
- Tightened Ladder Rack		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Rear Brake Service			
- Repair Rear Tire And Balance			
- Shop Supplies			
Parts Charge:	47.93	Labor Charge:	540.00

Workorder: 1301051

Problem: pm

Meter Reading: 33425	Labor	Parts	Quantity
In Date: 01/30/2013	Hours	Description	Quantity
- Pm	4.00	SHOP SUPPLIES	1.00
- Rear Brake Drum Svc		10W30 BULK SR	6.00
- Tighten Ladder Rack Inspect		NAPAGOLD OIL FILTER	1.00
- Shop Supplies			
Parts Charge:	27.95	Labor Charge:	240.00

3/2/2017
8:52:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162775 2006 GMC 1500 Pickup, 1/2 Ton, Wideside

Workorder: 1308032

Problem: PM

Meter Reading: 35810	Labor	Parts	
In Date: 08/12/2013	Hours	Description	
Close Date: 08/27/2013		Quantity	
- Pm	3.25	10W30 MOTOR OIL	6.00
- Rear Brake Drum Service		SHOP SUPPLIES	1.00
- Verify Dome Light Out Repair Dome Light		BULB	1.00
- Shop Supplies		10W30 BULK SR	6.00
		WIPER BLADE	2.00
		PH3980 OIL FILTER LBF	1.00
Parts Charge:	35.13	Labor Charge:	195.00

Workorder: 1308760

Problem: right tail light not working

Meter Reading: 35963	Labor	Parts	
In Date: 08/29/2013	Hours	Description	
Close Date: 08/30/2013		Quantity	
- Replace Right Rear Turn Signal Bulb	0.50	BULB	1.00
Parts Charge:	0.99	Labor Charge:	30.00

Workorder: 1310640

Problem: stalls run rough engine light

Meter Reading: 36595	Labor	Parts	
In Date: 10/23/2013	Hours	Description	
Close Date: 10/30/2013		Quantity	
- Recharge And Test Battery And Charging Sys Found Bad	6.50	SHOP SUPPLIES	1.00
Battery Replace Battery		GROUP 78 ACD	1.00
- Stalls And Run Rouigh Scan And Found No Codes Test			
Drive And Perform Pinpoint Test And Found Intermittent			
Problem With Ign Trace Wire Harness And Found Broken			
Wire In Ign Circuit Repair Harness			
- Test Drive Before And After Repair To Verify No More			
Problems With Ign Sys			
- Shop Supplies			
Parts Charge:	120.27	Labor Charge:	390.00

3/2/2017
8:52:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162775 2006 GMC 1500 Pickup, 1/2 Ton, Wideside

Workorder: 1401347

Problem: pm

Meter Reading: 37578	Labor	Parts	
In Date: 02/10/2014	Hours	Description	Quantity
- Pm	5.00	NAPAGOLD OIL FILTER	1.00
- Clean And Adj Rear Brakes		10W30 BULK SR	6.00
- Svc Ladder Rack		USED FIRE X REFURBISHED	1.00
- Ck Engine Lightin On Scan And Found Code Po128		NAPAGOLD AIR FILTER	1.00
Perfoirm Cooling Sys Test And Found No Problem At This		WASHER FL	1.00
Time Clear Code		BRAKE CLEANER	1.00
- Shop Supplies		WIPER BLADE	2.00
		SHOP SUPPLIES	1.00
Parts Charge:	64.22	Labor Charge:	300.00

Workorder: 1407947

Problem: pm

Meter Reading: 38946	Labor	Parts	
In Date: 08/12/2014	Hours	Description	Quantity
- Pm	6.00	THERMOSTAT	1.00
- Rear Brake Drum Svc		NAPAGOLD OIL FILTER	1.00
- Svc Ladder Rack		10W30 BULK SR	6.00
- Ck Engine Light Scan Found Po128 Coolant Thermostat		SHOP SUPPLIES	1.00
Rr Thermostat Clear Code Test Drive			
- Shop Supplies			
Parts Charge:	31.14	Labor Charge:	360.00

3/2/2017
8:52:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162775 2006 GMC 1500 Pickup, 1/2 Ton, Wideside

Workorder: 1502482 **Problem:** pm, engine light come and goes from time to time truck rides rough at highway speeds

Meter Reading: 40172		Labor		Parts	
In Date: 03/10/2015	Close Date: 03/13/2015	Hours	Description	Quantity	
- Pm		7.00	10W30 BULK SR		6.00
- Clean And Adj Rear Brakes			NAPAGOLD AIR FILTER		1.00
- Service Ladder Rack			WASHER FL		1.00
- Ck Engine Light Is On Scan Found Code P0171 P0174			USED FIRE X REFURBISHED		1.00
Perform Pinpoint Test Found Leaking Vacuum Hose			MAC WITE LITHIUM GRES		1.00
Repair Hose Clear Codes			BRAKE CLEANER		1.00
- Shop Supplies			WIPER BLADE		2.00
			NAPAGOLD OIL FILTER		1.00
			SHOP SUPPLIES		1.00
Parts Charge: 71.90		Labor Charge: 420.00			

Workorder: 1505809 **Problem:** right brake light out

Meter Reading: 41369		Labor		Parts	
In Date: 06/10/2015	Close Date: 06/16/2015	Hours	Description	Quantity	
- Ck Right Rear Tail Light Repair Tail Light		0.50	BULB		1.00
Parts Charge: 0.75		Labor Charge: 30.00			

Workorder: 1508980 **Problem:** pm, vehicle shakes at highway speeds

Meter Reading: 43424		Labor		Parts	
In Date: 09/08/2015	Close Date: 09/14/2015	Hours	Description	Quantity	
- Pm		5.25	TIRE DISPOSAL FEE		4.00
- Ck Shakes At Highway Speeds Replace 4 Tires Mount			10W30 BULK SR		6.00
Balance Test Drive			NAPAGOLD OIL FILTER		1.00
- Rear Brake Drum Svc			SHOP SUPPLIES		1.00
- Shop Supplies			P245/70R17 MIC TIRE		4.00
Parts Charge: 1,006.86		Labor Charge: 315.00			

3/2/2017
8:52:36AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162775 2006 GMC 1500 Pickup, 1/2 Ton, Wideside

Workorder: 1603517

Problem: Pm service.

Meter Reading: 47631		Labor		Parts	
In Date: 04/04/2016	Close Date: 04/13/2016	Hours	Description	Quantity	
- Pm Service.		5.50	SHOP SUPPLIES		1.00
- Rear Drum Brake Service.			WASHER FLUID CONCENTR		1.00
- Replace Right Rear Reverse Bulb.			BRAKE CLEANER		1.00
- Verify Washer Motor Leaking And Broken.Replace Washer Motor.			NAPAGOLD OIL FILTER		1.00
			10W30 BULK SR		6.00
- Service And Inspect Ladder Rack.			BULB		1.00
- Shop Supplies			W S WASH		1.00
Parts Charge: 46.29		Labor Charge: 330.00			

Workorder: 1611149

Problem: Pm Service

Meter Reading: 51790		Labor		Parts	
In Date: 10/27/2016	Close Date: 11/14/2016	Hours	Description	Quantity	
- Pm Service.		4.75	WASHER FLUID CONCENTR		1.00
- Rear Drum Brake Service.			22" WIPER BLADE		2.00
- Tighten All Tool Box And Ladder Rack Fasteners.			NAPAGOLD OIL FILTER		1.00
- Rotate And Balance All Tires.			SHOP SUPPLIES		1.00
- Shop Supplies			10W30 BULK SR		6.00
Parts Charge: 32.40		Labor Charge: 285.00			

Workorder: 1700437

Problem: Transition Prep Charge

Meter Reading: 52469		Labor		Parts	
In Date: 01/13/2017	Close Date: 01/13/2017	Hours	Description	Quantity	
- Transition Prep Charge		2.00			
Parts Charge: 0.00		Labor Charge: 120.00			

Total Parts Charges:	2,730.87	Total Labor Charges:	6,176.25	Total Comm. Charges:	151.14
----------------------	-----------------	----------------------	-----------------	----------------------	---------------