Palm Beach County Fleet Management Asset Maintenance History 10195554 2014 FORD EXPLORER Suv, Lg Mid Size, 4X4

Total Hours: 100.20 Labor: 6,777.65 Parts: 6,300.43 Comm: 8,037.30 Charged: 21115.38

Work Order: 1411341 Meter: 433 In Date: 11/13/2014 Closed: 11/13/2014

Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1504302 Meter: 3626 In Date: 04/27/2015 Closed: 05/07/2015

Problem: Pm service

Work Completed Parts Issued Quantity 5w20 Engine Oil 6.00 - Pm service. Napagold Oil Filter 1.00 - Rotate and balance all four tires. **Shop Supplies** 1.00 - Shop Supplies Hours: 3.75 Comm: 0.00 Labor: 225.00 Parts: 21.19 Total: 246.19

Work Order: 1511197 Meter: 9033 In Date: 11/02/2015 Closed: 11/12/2015

Problem: Pm service.

Work Completed	Parts Issued	Quantity
- Pm service.	L / F Seat Belt Bucket	1.00
- Replace defective left front seatbelt buckle .buckle housng coming apart.	Napagold Oil Filter	1.00
- Rotate and balance all four tires.	5w20 Engine Oil	6.00
- Shop Supplies	Accufit Beam	1.00
	Accufit Beam	1.00
	Blade	1.00
	Shop Supplies	1.00
Hours: 4.25 Comm: 0.00	Labor: 255.00 Parts: 191.98	Total: 446.98

Palm Beach County Fleet Management Asset Maintenance History 10195554 2014 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 1605028 Meter: 12092 05/13/2016 **Closed:** 05/20/2016 In Date: Problem: P.M. Service. **Work Completed Parts Issued** Quantity 5w20 Engine Oil 6.00 - P.m. Service. Napagold Oil Filter 1.00 - Rotate and balance all tires Washer Fluid Concentr 1.00 - Shop Supplies Accufit Beam 1.00 **Accufit Beam** 1.00 Blade 1.00 1.00 **Shop Supplies** Hours: 3.75 Comm: 0.00 Labor: 225.00 Parts: 71.71 Total: 296.71

Work Order: 1703065 Meter: 17185 In Date: 03/27/2017 Closed: 04/06/2017

Problem: P.M. Service.

Work Completed		Parts Issued		Quantity
- P.m. Service.		5w20 Engine Oil		6.00
- Replace leaking rear shocks		Napagold Oil Filter		1.00
- Rotate and balance tires.		Accufit Beam		1.00
- Shop Supplies		Accufit Beam		1.00
		Wpr/blde		1.00
		Washer Fluid Conc	entr	1.00
		Real Shock		2.00
		Shop Supplies		1.00
Hours: 5.35	Comm: 0.00	Labor: 321.00	Parts: 231.74	Total: 552.74

Work Order: 1703466 Meter: 17185 In Date: 04/06/2017 Closed: 04/06/2017

Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 9.54 Labor: 0.00 Parts: 0.00 Total: 9.54

Palm Beach County Fleet Management Asset Maintenance History 10195554 2014 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 1708004 No. 1708004 Problem: Inspect for holes in cab that could allow	leter: 20049 v exhaust fumes.		In Date: 08/15/20	17 Closed:	09/28/2017
Work Completed		Parts Issued		Q	uantity
- P.m. service.		5w20 Engine Oil			6.00
- Replace broken ignition key with new key fob an	nd program.	Napagold Oil Filte	r		1.00
- Rotate and balance four tires.		Washer Fluid Cond	centr		1.00
- Transport to and from dealer for repairs for Tsb 1	7-0044. Exhaust fumes.	Napa Cabin Air Filt	ter		1.00
- Shop Supplies		Accufit Beam			1.00
		Accufit Beam			1.00
		Wpr/blde			1.00
		Key W/ Remote			1.00
		Shop Supplies			1.00
Hours: 6.55	Comm: 0.00	Labor: 393.00	Parts: 215.18	Total:	608.18

Work Order: 1710024 Meter: 20177 In Date: 10/12/2017 Closed: 10/17/2017

Problem: Dead battery.

Work Completed		Parts Issued	Quantity	
- Recharge battery and test battery and charg	ing system.fail load	Battery	1.00	
test.replace defective battrery.		Shop Supplies	1.00	
- Shop Supplies				
Hours: 1.00	Comm: 0.00	Labor: 60.00	Parts: 156.59	Total: 216.59

Palm Beach County Fleet Management Asset Maintenance History 10195554 2014 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 1802920 Meter: 23346 In Date: 03/19/2018 Closed: 03/29/2018

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service.		5w20 Engine Oil		6.00
- Replace two front tires .balance and rotate all four		Napagold Oil Filte	er	1.00
- Complete alignment and road test.		Napagold Air Filt	er	1.00
- Shop Supplies		26in Exactfit-beam		1.00
		22in Exactfit-bean	n	1.00
		Wpr/blde P245/60/18 Tire Michelin Shop Supplies		1.00
				2.00
				1.00
		Tire Disposal Fee		2.00
Hours: 7.25	Comm: 0.00	Labor: 435.00	Parts: 648.20	Total: 1,083.20

Problem: Right front tire going flat.

Work Completed	Parts Issued	Quantity
- Leak test wheel assembly . Replace leaking valve stem .retest and nitrogen	Tire Pressure Monitoring System Sensor (1.00
fill tires.	Shop Supplies	1.00
- Shop Supplies		

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 5.35

Work Order: 1809396 Meter: 24963 In Date: 09/12/2018 Closed: 09/24/2018

Total: 65.35

Problem: P.M. service and detail.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filte	r	1.00
- Rotate and high speed balance all four wheels . Nitrofill all.		5w20 Engine Oil		6.00
- Shop Supplies		22in Exactfit-beam		1.00
		26in Exactfit-beam		1.00
		Blade		1.00
		Washer Fluid Concentr		1.00
		Shop Supplies		1.00
Hours: 3.75	Comm: 0.00	Labor: 225.00	Parts: 66.40	Total: 291.40

Palm Beach County Fleet Management Asset Maintenance History 10195554 2014 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 1809742 Meter: 24927 In Date: 09/20/2018 Closed: 09/20/2018

Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 1903581 Meter: 26430 In Date: 04/02/2019 Closed: 04/11/2019

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filte	r	1.00
- Rotate and balance all four tires .nitrofill all.	5w20 Engine Oil		6.00	
- Transport to and from dealer for recall 17n04 and	11in Exactfit-rear	1.00		
- Shop Supplies		22in Exactfit-beam	1.00	
		26in Exactfit-beam	1.00	
		Washer Fluid Concentr		1.00
		Shop Supplies		1.00
Hours: 5.75	Comm: 0.00	Labor: 385.25	Parts: 62.43	Total: 447.68

Work Order: 1910151 Meter: 27286 In Date: 10/01/2019 Closed: 10/21/2019

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filte	r	1.00
Replace two tires . Rotate and balance all four tires . Nitrofill all.Transport to and from dealer for recall 19s17 .		5w20 Engine Oil	6.00	
		11in Exactfit-rear	1.00	
- Shop Supplies		22in Exactfit-beam	1.00	
		26in Exactfit-beam	1.00	
		P245/60/18 Tire Mic Shop Supplies		2.00
				1.00
		Tire Disposal Fee		2.00
Hours: 6.75	Comm: 0.00	Labor: 492.75	Parts: 677.17	Total: 1,169.92

Palm Beach County Fleet Management Asset Maintenance History 10195554 2014 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 1911288 Meter: 27579 In Date: 10/30/2019 Closed: 11/02/2019

Problem: Windshield molding weather strip fell off.

Work Completed		Parts Issued		Quantity	
- Replace both windshield side weatherstrips and moldings .		Moulding		1.00	
- Shop Supplies		Moulding		1.00	
		Moulding		1.00	
		Moulding		1.00	
		Shop Supplies		1.00	
Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 546.48	Total: 619.48	

Work Order: 2000680 Meter: 28503 In Date: 01/21/2020 Closed: 02/10/2020

Problem: Install visor strobe lights and rear traffic advisor.

Work Completed		Parts Issued		Quantity
- Fabericate and install visor lights and rear traffic a	dvisor and switch panel .	Switch Panel		1.00
Wire all in .test operation .	·	L-bracket		2.00
- Shop Supplies		9" Mini Led Bar Vi	sor	2.00
		8pod Commander	r Stick	1.00
		Fuse Holder	1.00	
		Primary Wire Mini Add Circut 6-pod Commander Amber Shop Supplies Freight Charge		3.00
				1.00
				1.00
				1.00
				1.00
		Freight Charge		1.00
Hours: 8.00	Comm: 0.00	Labor: 584.00	Parts: 1,719.84	Total: 2,303.84

- Shop Supplies

Hours: 1.50

Palm Beach County Fleet Management Asset Maintenance History 10195554 2014 FORD EXPLORER Suv, Lg Mid Size, 4X4

4:27:51 PM	1019555	4 2014 FOR	EXPLORER SU	v, Lg Mid Size, 4X4				
Work Order:		Meter:	29488		In Date:	05/04/2020	Closed:	05/12/2020
Problem:	P.m. service and towed in for	no start .						
Work Com	pleted			Parts Issued			Qı	uantity
- P.m. servi	ce.			5w20 Engine Oil				6.00
Replace cabin air filter and clean frsh air intake .Charge battery fully. Test battery and charging system . Battery failed load		Napagold Oil Filter				1.00		
		11in Exactfit-rear				1.00		
test and lea	king . R&r defective battery an	d retest .	•	26in Exactfit-beam				1.00
- Test and replace rear liftgate strut supports .				22in Exactfit-beam				1.00
- Rotate and balance all four tires . Nitrofill all.			Napa Cabin Air Filter				1.00	
- Shop Sup	plies			Battery				1.00
				Lift Asy				1.00
				Lift Asy				1.00
				Shop Supplies				1.00
	Hours: 6.05		Comm: 0.00	Labor: 441.65	Parts: 336	6.76	Total:	778.41
Nork Order: Problem:	2004513 No Start/ Due for PM	Meter:	29296		In Date:	05/04/2020	Closed:	05/05/2020
Work Com	pleted							
- Tow From	: 301 N Olive next to Loading	Dock To: Lv sho	ор					
	Hours: 0.00		Comm: 96.00	Labor: 0.00	Parts: 0.0	0	Total:	96.00
Work Order: Problem:	2004806 Has trouble starting, Battery s	Meter: eems good.	29492		In Date:	05/13/2020	Closed:	05/20/2020
Work Com	pleted			Parts Issued			Qı	uantity
- Compute	r diagnose no start , codes U30	003 and B1300 .	Perform pinpoint	Relay				1.00
•	efective starter relay . Retest .			Shop Supplies				1.00

Comm: 0.00

Labor: 109.50

Parts: 24.60

Total: 134.10

Palm Beach County Fleet Management Asset Maintenance History 10195554 2014 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 2100808 Meter: 35215 In Date: 01/25/2021 Closed: 02/03/2021

Problem: P.M. service.

Work Completed		Parts Issued		Quantity	
- Preventive Maint. Service		Napagold Oil Filter		1.00	
		5w20 Engine Oil		6.00	
		Washer Fluid Concentr		1.00	
- Shop Supplies		Blade		1.00	
		22in Exactfit-beam		1.00	
		26in Exactfit-bean	n	1.00	
		Shop Supplies		1.00	
Hours: 3.75	Comm: 0.00	Labor: 273.75	Parts: 76.00	Total: 349.75	

Work Order: 2108600 Meter: 39975 In Date: 08/09/2021 Closed: 08/12/2021

Problem: PM Service. Send for Detail.

Work Completed		Parts Issued		Quantity	
- Preventive Maint. Service			Napagold Oil Filter		
- Rotate and speed balance , nitro fill			5w20 Engine Oil		
- Check steering vibrates at idle, Perform Ssm # 47	Washer Fluid Concentr 22in Exactfit-beam		1.00		
reprogramming, clear all codes			2.00		
- Shop Supplies		11in Exactfit-rear		1.00	
		Shop Supplies		1.00	
Hours: 4.75	Comm: 0.00	Labor: 346.75	Parts: 50.18	Total: 396.93	

Work Order: 2108784 Meter: 39863 In Date: 08/12/2021 Closed: 08/12/2021

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 90.40 Labor: 0.00 Parts: 0.00 Total: 90.40

- Shop Supplies

Hours: 1.00

Palm Beach County Fleet Management Asset Maintenance History 10195554 2014 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: Problem:	2203156 P.M. service and low tire pressu	Meter: ure light and L			In Date:	03/23/2022	Closed:	03/31/2022
Work Completed		Parts Issued			Qı	antity		
- Perform	Pm Service			Washer Fluid Concer	ntr			1.00
- Replace cabin filter and service fresh air ducts		11in Exactfit-rear				1.00		
- Replace two tires due to damaged drivers side tire, balance and nitro service all.		20in Exactfit-beam				1.00		
			26in Exactfit-beam				1.00	
- Perform	- Perform 4 wheel alignment . Road test .		Napagold Oil Filter				1.00	
- Diagnose and repair emergency lighting wiring harness. Excessive		5w20 Engine Oil				6.00		
	resistance on ground circuits.			Cabin Filter				1.00
- Shop Supplies			245/60/18 Tire Mic				2.00	
			Shop Supplies				1.00	
				Tire Disposal Fee				2.00
	Hours: 8.75		Comm: 0.00	Labor: 638.75	Parts: 491	1.07	Total:	1,129.82
Vork Order: Problem: Work Com	Damage to left front fender, left		ont bumper & right d	oors	In Date:	07/08/2022		08/19/2022
	Hours: 0.00		Comm: 7.745.36	Labor: 0.00	Parts: 0.0	U	Total:	7.745.36
- Damage	Hours: 0.00 2208604	Meter:	Comm: 7,745.36 48539	Labor: 0.00	Parts: 0.0			7,745.36
- Damage		Meter:	<u> </u>	Labor: 0.00	Parts: 0.0	08/17/2022		7,745.36 08/18/2022
- Damage	2208604 Battery dead in ready line	Meter:	<u> </u>	Parts Issued			Closed:	-
- Damage Vork Order: Problem: Work Com	2208604 Battery dead in ready line		48539				Closed:	08/18/2022

Comm: 0.00

Labor: 73.00

Parts: 152.24

Total: 225.24

Palm Beach County Fleet Management Asset Maintenance History 10195554 2014 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 2209443 Meter: 49000 In Date: 09/12/2022 Closed: 09/19/2022

Problem: PM Service.

Work Completed	Parts Issued		Quantity	
- Performed Service & Inspection.	Napagold Oil Filter		1.00	
- Performed Tire Rotation & Balance On All4 Wheels, reset Tpms.	5w20 Engine Oil 11in Exactfit-rear 20in Exactfit-beam 26in Exactfit-beam Brake Fluid Fot 4 Lv Non-chlor Brake Clnr Brake Rotor Brake Pad		6.00 1.00	
- Front & Rear Brakes Where Below Specs, Removed Front And Rear Brake				
Pads & Rotors. Resurface The Front Brake Rotors, Replaced Both Rear Brake			1.00 1.00 1.00	
Rotors, Bleed And Flush Entire Brakes. Test Drove And Burnish Brakes.				
- Shop Supplies				
			2.00	
			2.00	
			1.00	
	Brake Pad		1.00	
	Shop Supplies		1.00	
Hours: 11.75 Comm: 0.00	Labor: 857.75	Parts: 346.91	Total: 1,204.66	

Work Order: 2300135 Meter: 51012 In Date: 01/05/2023 Closed: 01/30/2023

Problem: Screw in pass rear tire.

Work Completed		Parts Issued		Quantity	
 replace right rear tire, due to screw in sidewall. Balance and nitro service Shop Supplies 		245/60/18 Tire Mic Shop Supplies		1.00	
				1.00	
		Tire Disposal Fee		1.00	
Hours: 0.50	Comm: 0.00	Labor: 36.50	Parts: 208.47	Total: 244.97	

Work Order: 2303666 Meter: 53402 In Date: 04/12/2023 Closed: 04/12/2023

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 100.20 Total Labor: 6,777.65 Total Comm: 8,037.30 Total Parts: 6,300.43