

6/9/2023
5:16:36 PM

Palm Beach County Fleet Management Asset Maintenance History
10185018 2011 FORD F350 Utility Body, 14,000 Gvwr, with Topper

Work Order: 1503194 **Meter:** 11568 **In Date:** 03/27/2015 **Closed:** 07/21/2015
Problem: Pm service.Check rear door hinge.

Work Completed

- P.m. Service.
- Replace four tires,rotate and balance all six.
- Transport vehicle to Total Truck for rear door freplacement.(reading body warranty).
- Shop Supplies

Parts Issued

Quantity

Tr416 Valve Stem	4.00
15-40 Oil	13.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Wiper Blade	2.00
Lt245 75r17 M/s2 Tire	4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 8.50

Comm: 0.00

Labor: 510.00 Parts: 1,299.49 Total: 1,809.49

Work Order: 1510767 **Meter:** 13717 **In Date:** 10/26/2015 **Closed:** 10/29/2015
Problem: Pm service.

Work Completed

- Pm service.
- Replace two tires.rotate and balance all six.
- Inspect electrical circuit to right rear brake light Ok.replace defective red brake lamp.
- Inspect and replace broken right side Ac vent.
- Shop Supplies

Parts Issued

Quantity

A/c Vent	1.00
Def Quart	20.00
15-40 Oil	13.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Wiper Blade	2.00
Washer Fluid Concentr	1.00
Mac Wite Lithium Gres	1.00
Lt245 75r17 M/s2 Tire	2.00
Air Filter (gold), Air Panel	1.00
Led Sup Mdl 44 42 Dio	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 7.50

Comm: 0.00

Labor: 450.00 Parts: 817.38 Total: 1,267.38

6/9/2023
5:16:36 PM

Palm Beach County Fleet Management Asset Maintenance History
10185018 2011 FORD F350 Utility Body, 14,000 Gvwr, with Topper

Work Order: 1600420 **Meter:** 14833 **In Date:** 01/13/2016 **Closed:** 01/22/2016
Problem: replace cracked windsheid

Work Completed

Parts Issued

Quantity

- Set up repair and reasset
- Shop Supplies

Shop Supplies 1.00

Hours: 1.00 Comm: 279.01 Labor: 60.00 Parts: 2.00 Total: 341.01

Work Order: 1602592 **Meter:** 15273 **In Date:** 03/11/2016 **Closed:** 03/17/2016
Problem: Left rear tire flat.

Work Completed

Parts Issued

Quantity

- Repair and balance left rear inner tire.
- Shop Supplies

Shop Supplies 1.00

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1606490 **Meter:** 17097 **In Date:** 06/24/2016 **Closed:** 07/12/2016
Problem: P.M. Service.Check rear door latch.Recall.

Work Completed

Parts Issued

Quantity

- P.m. Service.
- Replace left tail lamp.
- Flush and refill transmission system.
- Rotate and balance all six tires.
- Transport vehicle to dealer for recall #14e03 & 16b24b.
- Shop Supplies

15-40 Oil 13.00

Napagold Oil Filter 1.00

Fuel Filter Kit 1.00

22" Wiper Blade 2.00

Used Fire X Refurbished 1.00

Stg Wheel Cov - Ford 1.00

Bp Fmx-lp F Mx Fuse 1.00

Led Sup Mdl 44 42 Dio 1.00

Syn-atf Trans Fluid S 18.00

Def Quart 10.00

Shop Supplies 1.00

Hours: 9.50 Comm: 0.00 Labor: 570.00 Parts: 345.62 Total: 915.62

6/9/2023
5:16:36 PM

Palm Beach County Fleet Management Asset Maintenance History
10185018 2011 FORD F350 Utility Body, 14,000 Gvwr, with Topper

Work Order: 1700639 **Meter:** 20643 **In Date:** 01/20/2017 **Closed:** 04/18/2017
Problem: P.M. Service.Light under hood inop.

Work Completed

Parts Issued

Quantity

- P.m. Service.
- Test batteries and charging system.replace both bad batteries.
- Diagnose check engine light.p21b0.reductant sensor voltage high.perform pin point test.replace defective sensor.clear codes and retest.
- Rotate and balance all six tires.
- Shop Supplies

15-40 Oil	13.00
Napagold Oil Filter	1.00
Fuel Filter Ford Only	1.00
20" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Battery	2.00
Napagold Oil Filter	1.00
Fuel Filter Kit	1.00
Air Filter (gold), Air Panel	2.00
Seal Spe	1.00
Reservoir	1.00
Def Bulk Qts	13.00
Shop Supplies	1.00

Hours: 11.50 Comm: 0.00 Labor: 690.00 Parts: 894.17 Total: 1,584.17

Work Order: 1704063 **Meter:** 20643 **In Date:** 04/04/2017 **Closed:** 04/24/2017
Problem: Damage to right front door & step

Work Completed

- Damage to right front door & step

Hours: 0.00 Comm: 2,753.12 Labor: 0.00 Parts: 0.00 Total: 2,753.12

Work Order: 1705122 **Meter:** 21550 **In Date:** 05/24/2017 **Closed:** 05/25/2017
Problem: Right rear outter tire going flat.

Work Completed

Parts Issued

Quantity

- Repair right rear outter tire and balance .nitrogen fill tires.
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

6/9/2023
5:16:36 PM

Palm Beach County Fleet Management Asset Maintenance History
10185018 2011 FORD F350 Utility Body, 14,000 Gvwr, with Topper

Work Order: 1709232 **Meter:** 23873 **In Date:** 09/22/2017 **Closed:** 09/27/2017

Problem: Re-attach left rear inside door latches, Replace right rear tail light.

Work Completed

- P.m. service.
- Replace faulty right rear led brake lamp with new.
- Replace broken pintel pin with new.
- Rotate and balance six tires.
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	13.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Used Fire X Refurbished	1.00
20" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Led Sup Mdl 44 42 Dio	1.00
Pintle Pin W/clip	1.00
Shop Supplies	1.00

Hours: 6.10

Comm: 0.00

Labor: 366.00 Parts: 179.96 Total: 545.96

Work Order: 1709429 **Meter:** 23873 **In Date:** 09/27/2017 **Closed:** 09/29/2017

Problem: repair & fabricate stricker bracket

Work Completed

- Fab weld and install rear door strikers
- Shop Supplies

Parts Issued

Quantity

GI Whit	1.00
Shop Supplies	1.00

Hours: 2.00

Comm: 0.00

Labor: 120.00 Parts: 7.82 Total: 127.82

Work Order: 1709430 **Meter:** 23839 **In Date:** 09/27/2017 **Closed:** 10/05/2017

Problem: replace cracked windsheild

Work Completed

- Set up repairs and reasset
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 285.38

Labor: 60.00 Parts: 2.00 Total: 347.38

6/9/2023
5:16:37 PM

Palm Beach County Fleet Management Asset Maintenance History
10185018 2011 FORD F350 Utility Body, 14,000 Gvwr, with Topper

Work Order: 1802769 **Meter:** 25741 **In Date:** 03/14/2018 **Closed:** 03/15/2018

Problem: Rear cargo door lock rod loose.

Work Completed

- Diagnose lock rod .adjust rod mount and replace missing rivet in left rear cargo door.

Hours: 0.50 Comm: 0.00 Labor: 30.00 Parts: 0.00 Total: 30.00

Work Order: 1804171 **Meter:** 26740 **In Date:** 04/20/2018 **Closed:** 04/27/2018

Problem: PM Service, Drivers front compartment door is hard to latch, Left rear tail light needs replaced.

Work Completed

- P.m. service.
- Test and replace right brake light assembly.replace both front marker light bulbs and right front turn signal bulb .retest.
- Replace broken pintle pin . Adjust doorlatch on left box door so lock rod engages easier.
- Rotate and balance all six tires .nitrogen fill tires.
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	13.00
Napagold Oil Filter	1.00
Air Filter (gold), Air Panel	1.00
Napagold Fuel Filter	1.00
22" Wiper Blade	2.00
Boxed Miniatures	2.00
Bulb	1.00
Led Sup Mdl 44 42 Dio	1.00
Pintle Pin W/clip	1.00
Blue Df	2.00
Shop Supplies	1.00

Hours: 7.00 Comm: 0.00 Labor: 420.00 Parts: 211.21 Total: 631.21

Work Order: 1805091 **Meter:** 27412 **In Date:** 05/16/2018 **Closed:** 05/21/2018

Problem: Cranks but won't start, leaking fuel.

Work Completed

- Diagnose cranks but no start and leaking fuel .replace frame rail fuel pump cover and drain plug .bleed fuel system .clear codes and test drive.
- Shop Supplies

Parts Issued

Quantity

Fuel Filter Cap	1.00
Plug Asy	1.00
Shop Supplies	1.00

Hours: 1.50 Comm: 0.00 Labor: 90.00 Parts: 34.15 Total: 124.15

6/9/2023
5:16:37 PM

Palm Beach County Fleet Management Asset Maintenance History
10185018 2011 FORD F350 Utility Body, 14,000 Gvwr, with Topper

Work Order: 1811341
Problem: PM Service

Meter: 29557

In Date: 11/02/2018 **Closed:** 11/08/2018

Work Completed

- P.m. service.
- Inspect and replace all six tires . Balance and nitrofill all.
- Inspect brakes . Resurface rear rotors . Replace brake calipers and pads . Bleed and flush system . Road test.
- Inspect and replace all six body mounts and front bump stops .
- Test both rear brake lights . R&r defective brake light and retest.
- Replace broken pintle pin .
- Perform complete front end alignment and road test.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
15-40 Oil	13.00
Napagold Fuel Filter	1.00
Air Filter (gold), Air Panel	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Blue Df	1.00
B Fluid Dot 3-32oz	1.00
Non-chlor Brake Clnr	1.00
Reman Brake Caliper	1.00
Reman Brake Caliper	1.00
Brake Pad	1.00
Body Mount Kit	4.00
Body Mount Kit	2.00
bumper	2.00
Led Sup Mdl 44 42 Dio	2.00
Pintle Pin W/clip	1.00
Lt245/75r17 Mich Defend Ltx	6.00
Caliper Washer	4.00
Shop Supplies	1.00
Tire Disposal Fee	6.00

Hours: 21.30

Comm: 0.00

Labor: 1,427.10

Parts: 2,670.63

Total: 4,097.73

6/9/2023
5:16:37 PM

Palm Beach County Fleet Management Asset Maintenance History
10185018 2011 FORD F350 Utility Body, 14,000 Gvwr, with Topper

Work Order: 1905625 **Meter:** 33531 **In Date:** 05/29/2019 **Closed:** 06/10/2019
Problem: P.M. Service.ABS light on,a/c not cold.

Work Completed

- P.m. service.
- Test and replace left front turnsignal bulb .
- Computer diagnose Abs light , code C1145 . Perform pinpoint test . R&r defective right front wheel speed sensor . Clear codes and retest .
- Replace one tire . Rotate and balance all six . Nitrofill all.
- A/c performance test . Leak test . R&r leaking evaporator core, condenser, evaporator temp sensor and high schrader valve . Recover , vacuate system and complete recharge to factory spec. Test drive.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
15-40 Oil	13.00
Blue Df	2.00
Napagold Fuel Filter	1.00
Ford Triton Pvc Swc	1.00
22" Wiper Blade	2.00
Bulb	1.00
Abs Sensor	1.00
Lt245/75r17 Mich Defend Ltx	1.00
Ac Valve Core High	1.00
Freon Lv Shop 1	2.00
E8 A/c Oil Univ W Dye	1.00
Evaporator Core	1.00
Seal Kits	4.00
sensor	1.00
Kit O	1.00
A/c Condenser	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 21.70

Comm: 0.00

Labor: 1,453.90 Parts: 1,174.69 Total: 2,628.59

Work Order: 1906573 **Meter:** 33940 **In Date:** 06/21/2019 **Closed:** 06/27/2019
Problem: Check engine light on, Wheel cover missing.

Work Completed

- Computer diagnose check engine light ,code P247b .perform pinpoint test . R&r all four defective Egt sensors . Clear codes and retest .
- Replace missing left front dust cover.
- Shop Supplies

Parts Issued

Quantity

Sensor	4.00
Cap	1.00
Cap	1.00
Shop Supplies	1.00

Hours: 3.20

Comm: 0.00

Labor: 214.40 Parts: 230.28 Total: 444.68

6/9/2023
5:16:37 PM

Palm Beach County Fleet Management Asset Maintenance History
10185018 2011 FORD F350 Utility Body, 14,000 Gvwr, with Topper

Work Order: 2101411 **Meter:** 43840 **In Date:** 02/05/2021 **Closed:** 02/10/2021

Problem: Dist.2 Tommy, truck is over-due for PM Rear end makes noise on turns.

Work Completed

- Preventive Maint. Service
- Replaced missing pintle pin
- Diagnose noise when turning. Serviced rear diff, and replaced leaking left side axle seal
- Rotated and balanced all 6 tires. Nitrogen filled all tires.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
15-40 Oil	13.00
Air Filter (gold), Air Panel	1.00
Steering Wheel Cover Large	1.00
22" Wiper Blade	2.00
element	1.00
Used Fire X Refurbished	1.00
Blue Df	2.00
Wd40 Spr	1.00
Pintle Pin W/clip	1.00
Non-chlor Brake Clnr	2.00
Px Grey Rtv Silicone	1.00
Napa Oil Seal	1.00
Friction Modifier	2.00
75w140 Ford Axle Lube	4.00
Shop Supplies	1.00

Hours: 8.70

Comm: 0.00

Labor: 635.10

Parts: 460.39

Total: 1,095.49

Work Order: 2103653 **Meter:** 45500 **In Date:** 03/31/2021 **Closed:** 04/07/2021

Problem: Dist.2 Tom, truck A/C not working

Work Completed

- Diagnose Ac inop.. A/c performance test Found to have leaking evaporator. R and R evaporator and condenser assemblies. Recharged Freon to factory spec.
- Shop Supplies

Parts Issued

Quantity

A/c Condenser	1.00
Evaporator Core	1.00
Seal Kits	2.00
Kit O	1.00
Freon Lv Shop 2	2.00
Shop Supplies	1.00

Hours: 12.70

Comm: 0.00

Labor: 927.10

Parts: 673.59

Total: 1,600.69

6/9/2023
5:16:37 PM

Palm Beach County Fleet Management Asset Maintenance History
10185018 2011 FORD F350 Utility Body, 14,000 Gvwr, with Topper

Work Order: 2113375 **Meter:** 49179 **In Date:** 12/17/2021 **Closed:** 12/21/2021
Problem: A/C not working. Will drop off truck Fri 12/17/2021 Thank you

Work Completed

- Diagnose Ac not cooling. Found high side service fitting Schrader valve to be leaking. Replaced both high and low side service Schrader valves. Recharge Freon to factory spec.
- Shop Supplies

Parts Issued

Quantity

Freon Lv Shop 2	2.00
valve assy	1.00
Ac Valve Core High	1.00
Shop Supplies	1.00

Hours: 2.00

Comm: 0.00

Labor: 146.00 Parts: 25.94 Total: 171.94

Work Order: 2200138 **Meter:** 49180 **In Date:** 01/06/2022 **Closed:** 01/06/2022
Problem: DRIVER SIDE REAR NAIL IN TIRE

Work Completed

- Replace left rear outer tire due to sidewall damage and balance . Nitro fill all.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
Tires / Lt245/75r17	1.00
Tire Disposal Fee	1.00

Hours: 0.50

Comm: 0.00

Labor: 36.50 Parts: 114.64 Total: 151.14

6/9/2023
5:16:37 PM

Palm Beach County Fleet Management Asset Maintenance History
10185018 2011 FORD F350 Utility Body, 14,000 Gvwr, with Topper

Work Order: 2203837

Meter: 51254

In Date: 04/08/2022 **Closed:** 04/13/2022

Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Test And Replace Defective Auxiliary Roof Fan . Drill Out All Rivets And Reseal .
- Load Test Batteries And Check Charging System. Recharge And Retest Both Batteries But Failed. R&r Batteries Due To Normal Wear.
- R&r All Six Worn Body Mounts Making Noise While Engine Is At Idle.
- R&r Broken Pintel Pin On Hitch.
- Rotate And Balance Six Tires. Nitro Fill All .
- Shop Supplies

Parts Issued

Quantity

22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Napagold Oil Filter	1.00
15-40 Oil	13.00
Blue Df	2.00
Napagold Fuel Filter	1.00
Used Fire X Refurbished	1.00
Permatex	1.00
Battery	2.00
Body Mount Kit	2.00
Body Mount Kit	4.00
Pintle Pin W/clip	1.00
Roof Top Fan Vent	1.00
Shop Supplies	1.00

Hours: 15.70

Comm: 0.00

Labor: 1,146.10

Parts: 1,081.55

Total: 2,227.65

Work Order: 2209561

Meter: 55921

In Date: 09/14/2022 **Closed:** 09/15/2022

Problem: Dist.2 Tom, left rear out tire has a screw in it

Work Completed

- Repaired Lr inner tire and balance . Nitro fill all.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 2.65

Total: 75.65

6/9/2023
5:16:37 PM

Palm Beach County Fleet Management Asset Maintenance History
10185018 2011 FORD F350 Utility Body, 14,000 Gvwr, with Topper

Work Order: 2210694 **Meter:** 56461 **In Date:** 10/19/2022 **Closed:** 10/27/2022
Problem: PM Service. will turn in today

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Replace All 6 Tires Balance With Nitro Fill
- Test Drive And Perform Front End Alignment Road Test
- Window Washer Pump Not Working Confirm Power And Ground And Replace Pump Retest
- Shop Supplies

Napagold Fuel Filter	1.00	
15-40 Oil	14.00	
Napagold Oil Filter	1.00	
22" Wiper Blade	2.00	
Blue Df	2.00	
Lt245/75r17 Mich Defend Ltx	6.00	
Non-chlor Brake Clnr	2.00	
Air Filter (gold), Air Panel	1.00	
Washer Pump	1.00	
Permatex	1.00	
Shop Supplies	1.00	
Tire Disposal Fee	6.00	
Labor: 781.10	Parts: 1,699.06	Total: 2,480.16

Hours: 10.70 Comm: 0.00

Work Order: 2304672 **Meter:** 59844 **In Date:** 05/10/2023 **Closed:** 05/10/2023
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00

Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 260.10

Total Labor: 17,030.50

Total Comm: 4,572.05

Total Parts: 17,073.12