

1/5/2024
5:03:13 PM

Palm Beach County Fleet Management Asset Maintenance History
10179139 2009 FORD E250 Van, Cargo, 3/4 Ton

Total Hours: 173.30 Labor: 11,463.90 Parts: 7,015.59 Comm: 981.60 Charged: 19461.09

Work Order: 940114 **Meter:** 0 **In Date:** 07/02/2009 **Closed:** 07/02/2009
Problem: Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1001244 **Meter:** 1212 **In Date:** 02/03/2010 **Closed:** 02/09/2010
Problem: P. M.

Work Completed

- P. M.
- Tightened roof rack.
- R/front head light inop. Transport & pick up vehicle at dealer for warranty repair.
- Shop Supplies

Parts Issued	Quantity
Shop Supplies	1.00
1372 Oil Filter Frm Ph2 Wix 51372	1.00
5w20 Engine Oil	7.00

Hours: 5.75 Comm: 0.00 Labor: 345.00 Parts: 38.66 Total: 383.66

Work Order: 1008933 **Meter:** 2800 **In Date:** 08/18/2010 **Closed:** 08/25/2010
Problem: P. M. SERVICE

Work Completed

- P. M.
- Tighten fastening bolts. Lubricate slide tracks.
- Shop Supplies

Parts Issued	Quantity
Shop Supplies	1.00
1372 Oil Filter Frm Ph2 Wix 51372	1.00
5w20 Engine Oil	7.00
Used Firex Refurbed Fire Extingshers	1.00

Hours: 3.25 Comm: 0.00 Labor: 195.00 Parts: 51.46 Total: 246.46

1/5/2024
5:03:13 PM

Palm Beach County Fleet Management Asset Maintenance History
10179139 2009 FORD E250 Van, Cargo, 3/4 Ton

Work Order: 1012656 **Meter:** 3415 **In Date:** 11/10/2010 **Closed:** 11/18/2010

Problem: Driver's side, exterior door handle does not open door.

Work Completed

Parts Issued

Quantity

- Remove driver door panel & perform visual inspection. Found broken clip that hold rod to outer door handle. Send vehicle to dealer for warranty repair.

Shop Supplies

1.00

- Transport & pick up vehicle at dealer for warranty repair. (broken outer handle clip).

- Shop Supplies

Hours: 2.50

Comm: 0.00

Labor: 150.00

Parts: 2.00

Total: 152.00

Work Order: 1102729 **Meter:** 3762 **In Date:** 03/11/2011 **Closed:** 03/22/2011

Problem: P. M., & Check engine light came on

Work Completed

Parts Issued

Quantity

- P. M. Service.

Shop Supplies

1.00

- Adjust & tighten roof rack.

1372 Oil Filter Frm Ph2 Wix 51372

1.00

- Install "how's my driving" decal. Repair fire extinguisher bracket.

5w20 Engine Oil

7.00

- Remove & turn spare tire over. Reprogram T.p.m. Repair R/r tire.

Nb-19 Wiper Blades 19" Anco 31-19

2.00

- Install grease fittings on both lower ball joints.

- Shop Supplies

Hours: 7.50

Comm: 0.00

Labor: 450.00

Parts: 48.71

Total: 498.71

1/5/2024
5:03:13 PM

Palm Beach County Fleet Management Asset Maintenance History
10179139 2009 FORD E250 Van, Cargo, 3/4 Ton

Work Order: 1111395 **Meter:** 5913 **In Date:** 10/27/2011 **Closed:** 11/15/2011
Problem: P. M., & Check engine light is on

Work Completed

Parts Issued

Quantity

- Performed service.
- Retightened roof rack.
- R&r bulb for center brake.
- Repaired Lr tire, & reprogrammed Tpm. Road tested.
- Installed scanner for check engine light. No codes present, & no light on. Unable to verify complaint. Road tested.
- Batt failed load. Recharged & retested, failed again. 12.41v, 408 Cca, replace batt aces code Hc80p, Dtc code 84a54l.
- Transport & pick up vehicle at dealer (defective battery).
- Dealer to replace defective battery.
- Shop Supplies

Shop Supplies	1.00
1372 Oil Filter Frm Ph2 Wix 51372	1.00
5w20 Engine Oil	7.00
Nb-19 Wiper Blades 19" Anco 31-19	2.00
Used Firex Refurbed Fire Extingshers	1.00

Hours: 9.25 Comm: 0.00 Labor: 555.00 Parts: 62.19 Total: 617.19

Work Order: 1201347 **Meter:** 6190 **In Date:** 02/09/2012 **Closed:** 02/13/2012
Problem: reflash canceiver

Work Completed

Parts Issued

Quantity

- Reflash coneceiver test ok
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1201468 **Meter:** 6190 **In Date:** 01/27/2012 **Closed:** 02/14/2012
Problem: damage to dr door, left rear fndr & rear bumper

Work Completed

- damage to dr door, left rear fndr & rear bumper

Hours: 0.00 Comm: 981.60 Labor: 0.00 Parts: 0.00 Total: 981.60

1/5/2024
5:03:13 PM

Palm Beach County Fleet Management Asset Maintenance History
10179139 2009 FORD E250 Van, Cargo, 3/4 Ton

Work Order: 1406024 **Meter:** 9777 **In Date:** 06/19/2014 **Closed:** 06/26/2014
Problem: pm, door pass. side not working, rf tire has a nail

Work Completed

- pm
- replace both rear tires and rotate to the front
- remove right front door lock assembly and replace broken clip
- fill all tires with nitrogen
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w20	7.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Napagold Air Filter	1.00
744395900 245-75r16	2.00
Door Clip	1.00
retainer	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 6.75

Comm: 0.00

Labor: 405.00

Parts: 552.77

Total: 957.77

Work Order: 1500917 **Meter:** 10657 **In Date:** 01/27/2015 **Closed:** 02/09/2015
Problem: pm

Work Completed

- pm
- svc ladder rack
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w20	7.00
Shop Supplies	1.00

Hours: 3.75

Comm: 0.00

Labor: 225.00

Parts: 31.55

Total: 256.55

Work Order: 1507922 **Meter:** 11748 **In Date:** 08/07/2015 **Closed:** 08/11/2015
Problem: pm

Work Completed

- P.m.service
- Nail In R/rear Tire.
- Dismount,patch,mount,balance Add N2.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w20	7.00
Wiper Blade	2.00
Washer Fluid Concentr	1.00
Shop Supplies	1.00

Hours: 3.75

Comm: 0.00

Labor: 225.00

Parts: 42.07

Total: 267.07

1/5/2024
5:03:13 PM

Palm Beach County Fleet Management Asset Maintenance History
10179139 2009 FORD E250 Van, Cargo, 3/4 Ton

Work Order: 2000804 **Meter:** 17010 **In Date:** 01/24/2020 **Closed:** 02/18/2020
Problem: PM Service.ABS light and Check engine light on.

Work Completed

- Pm Service.
- Replace both rear tires.rotate to the front.
- Check engine light is on.scan and found code P0456.perform pin point test and found bad purge valve.replace valve.clear code and retest.remove engine cover to acess valve.
- Abs light on.scan and found code C1096.perform pinpoint test and found bad Abs pump.replace pump and module.reprogram new module.clear code..
- Resurface front rotors.replace pads.and calipers.r/r both front brake hoses.bleed and flush brake system.
- Test drive before and after repairs.
- Service ladder rack.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w20	7.00
Wiper Blade Anco	2.00
Washer Fluid Concentr	1.00
Napagold Air Filter	1.00
744395900 245-75r16	2.00
Valve Assy	1.00
B Fluid Dot 3-32oz	3.00
Non-chlor Brake Clnr	2.00
Abs Hydraulic Module	1.00
Abs Control	1.00
Caliper As	1.00
Caliper	1.00
Brake Pad	1.00
Brake Hose F/r	1.00
Brake Hose L/f	1.00
L/f Caliper Bracket	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 21.00

Comm: 0.00

Labor: 1,533.00

Parts: 2,105.80

Total: 3,638.80

Work Order: 2002135 **Meter:** 17065 **In Date:** 02/28/2020 **Closed:** 02/28/2020
Problem: wont fuel

Work Completed

- test and remove fuel canceiver. issue fuel card
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 4.00

Total: 77.00

1/5/2024
5:03:13 PM

Palm Beach County Fleet Management Asset Maintenance History
10179139 2009 FORD E250 Van, Cargo, 3/4 Ton

Work Order: 2103103 **Meter:** 19764 **In Date:** 03/19/2021 **Closed:** 04/01/2021
Problem: Engine light on, Misfires

Work Completed

- Computer diagnose check engine light and misfire . Code P0304 . Perform pinpoint test . Perform complete tune up and replace number four and six coils . Clear code and retest .
- Perform complete air intake decarb and cleaning . Flush injectors
- Diagnose check engine light P0442 perform evap test . R&r defective evap canister assembly . Clear codes and retest .
- Replace broken front grill assembly .
- Shop Supplies

Parts Issued

Quantity

Ford Ignition Coil	2.00
Spark Plug	8.00
Intake Cleaner Kit	1.00
Motor Tune-up 16oz	1.00
Evap Cannister	1.00
Grille	1.00
Shop Supplies	1.00

Hours: 8.80

Comm: 0.00

Labor: 642.40

Parts: 816.13

Total: 1,458.53

Work Order: 2109930 **Meter:** 20714 **In Date:** 09/14/2021 **Closed:** 09/30/2021
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Mount 4 tires, fill with nitrogen, balance & reset Tpms.
- service ladder rack.
- Replace how's my driving decal.
- Shop Supplies

Parts Issued

Quantity

744395900 245-75r16	4.00
Napa Quart 5w20	7.00
Napagold Oil Filter	1.00
Wiper Blade Anco	2.00
Washer Fluid Concentr	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 7.25

Comm: 0.00

Labor: 529.25

Parts: 623.24

Total: 1,152.49

1/5/2024
5:03:13 PM

Palm Beach County Fleet Management Asset Maintenance History
10179139 2009 FORD E250 Van, Cargo, 3/4 Ton

Work Order: 2308669 **Meter:** 22438 **In Date:** 08/29/2023 **Closed:** 09/26/2023
Problem: PM Service. Send for Detail. laptop stand.

Work Completed

- Preventive Maint. Service
- Repaired r/f and l/r tires patched rotate balanced 4tires
- replaced damaged lap top stand
- replaced left side head lamp and repaired wiring plug
- replaced worn how's my driving sticker
- Shop Supplies

Hours: 6.50 Comm: 0.00

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w20	6.00
Washer Fluid Concentr	1.00
20" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Halogen Sealed Beams	1.00
Shop Supplies	1.00

Labor: 474.50 Parts: 62.30 Total: 536.80

Work Order: 2309996 **Meter:** 22438 **In Date:** 09/29/2023 **Closed:** 09/29/2023
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00

Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 173.30

Total Labor: 11,463.90

Total Comm: 981.60

Total Parts: 7,015.59