1/8/2024 6:52:49 PM

10210048

Palm Beach County Fleet Management Asset Maintenance History 2019 JOHN DEERE GATOR HPX815E Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Total Hours: 62.50 Labor: 4,550.50		Parts: 6,883.93	Comm: 0.00	Charged: 11434.43				
Work Order: 1 Problem: p	903699 re delivery inspection	Meter:	1		In Date:	04/04/2019	Closed:	04/08/2019
Work Completed			Parts Issued			Qı	ıantity	
- pre delivery inspection			Shop Supplies				1.00	
- Shop Supp	lies							
	Hours: 2.00		Comm: 0.00	Labor: 134.00	Parts: 3.0	0	Total:	137.00
Work Order: 2 Problem: It		Meter:	274		In Date:	02/12/2020	Closed:	03/17/2020
Work Compl	eted			Parts Issued			Qı	ıantity
- Verify engine oil level above fill mark.drain oil and refill.			15w40 Bulk South Re	eg			3.00	
- C/c wont start.found blown fuse.arrange for warranty repairs.found defective fuel shut off solenoid.			Shop Supplies				1.00	
- Shop Supp	lies							
	Hours: 1.00		Comm: 0.00	Labor: 73.00	Parts: 13.	99	Total:	86.99
Work Order: 2 Problem: p		Meter:	295		In Date:	04/23/2020	Closed:	05/07/2020
Work Completed			Parts Issued			Qı	ıantity	
- pm service				Napagold Air Filter				1.00
- Shop Supplies			Napagold Air Filter				1.00	
				Napagold Oil Filter				1.00
				Napagold Fuel Filter				1.00
				Napa Qt 15w40				3.00
				Shop Supplies				1.00
	Hours: 4.00		Comm: 0.00	Labor: 292.00	Parts: 45.	21	Total:	337.21

1/8/2024 6:52:49 PM

10210048

Palm Beach County Fleet Management Asset Maintenance History 2019 JOHN DEERE GATOR HPX815E Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Work Order: 2007252 Meter: 365 In Date: 07/24/2020 Closed: 09/30/2020

Problem: Wont start.

Work CompletedParts IssuedQuantity- C/c wont start.found blown starting fuse.call John Deere to replace fuelShop Supplies1.00

shut of f solenoid. reassemble.

- Shop Supplies

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 4.00

Total: 77.00

Work Order: 2103260 Meter: 541 In Date: 03/23/2021 Closed: 04/23/2021

Problem: pm/ turn signals/ P brake/ trans slip uphill

Work Completed	Parts Issued		Quantity		
- Preventive Maint. Service	15-40 Oil		3.00		
- Diag, check electrical, clean electrical connec	Diag, check electrical, clean electrical connections and replace the flasher		Napagold Oil Filter		
Check trans and clutches. Replace flat spotted belt.		Napagold Air Filter		1.00	
- Adjust parking brake cables. Remove center	console and disassemble	Napagold Air Filter		1.00	
nandle assembly. Clean corrosion off internal p	parts and free up release	Napagold Fuel Filte	er	1.00	
nechanism.		Flasher		1.00	
- Replace front tires	24x9.5x10 At Tire		2.00		
- Replace side curtain buckles	Napagold Fuel Filt	er	1.00		
- Replace corroded clamps, filter housing with	Napagold Fuel Filt	er	1.00		
- Wash equipment		Fuel Line Hose		2.00	
- Shop Supplies		13 Oz Aero Kroil		1.00	
		Drive Belt Buckle		1.00	
				1.00	
		Buckle		1.00	
		Buckle		2.00	
		Shop Supplies		1.00	
		Tire Disposal Fee		2.00	
Hours: 13.50	Comm: 0.00	Labor: 985.50	Parts: 812.75	Total: 1,798.2	

10210048

Palm Beach County Fleet Management Asset Maintenance History 2019 JOHN DEERE GATOR HPX815E Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Work Order: 2203284 Meter: 878 In Date: 03/28/2022 Closed: 05/05/2022

Problem: pm/ Transmission issues/ Parking brake issues.

Work Completed	Parts Issued	Quantity	
- Preventive Maint. Service	15-40 Oil	3.00	
- Check Transmission Issues, Replaced Broken Shifter Cable, Worn Ball Jo	int Napagold Oil Filter	1.00	
And Adjusted	Napagold Fuel Filter	1.00	
- Check Parking Brake Issue, Free Up And Adjust Parking Brake Cable	Napagold Air Filter	1.00	
- Replaced 4 Worn Tires	Napagold Air Filter	1.00	
- Replaced Worn Front Brake Pads And Rotors, Replaced Worn Rear Bral	Pro Undercoating	1.00	
Pads And Rotors	Rust Fix	1.00	
- Service Front Diff	Ty22000 Trans Fluid J	1.00	
- Service Transaxle	24-1050-10b Nhs All Trail	2.00	
- Dismounted Old Worn Tires To Discard And Put Rims Into Scrap Metal	Bin, 24x9.5x10 At Tire	2.00	
Replaced All 4 Rims	Hy-gard Quart Low Vis	1.00	
- Chip Off Rust, Wash Asset, Apply Rust Fix And Undercoating	Tailgate Cable	2.00	
- Shop Supplies	Push Pull Cable	1.00	
	Hub/rotor	2.00	
	Hub Kit	2.00	
	Brake Pad	2.00	
	10x7.75 5/4.5 Rim	4.00	
	Ball Joint	1.00	
	Fuel Filter Asm	1.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	4.00	
Hours: 19.00 Comm: 0.00	Labor: 1,387.00 Parts: 2,489.87	Total: 3,876.87	

10210048

Palm Beach County Fleet Management Asset Maintenance History 2019 JOHN DEERE GATOR HPX815E Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Work Order: 2210590 Meter: 1008 In Date: 10/17/2022 Closed: 10/18/2022

Problem: Need a battery replacement. Staff will bring the old one in to swap out. Thanks!

Work CompletedParts IssuedQuantity- secure battery for deptBattery1.00- Shop SuppliesShop Supplies1.00

- Shop Supplies Shop Supplies 1.00

Hours: 0.50 Comm: 0.00 Labor: 36.50 Parts: 116.19 Total: 152.69

Work Order: 2300871 Meter: 1109 In Date: 01/27/2023 Closed: 01/30/2023

Problem: Emergency brake is not working. Will bring it in today. Thank you!

Work Completed Parts Issued Quantity

- readjust parking brake Shop Supplies 1.00

- replace one seat and asset numbers

- Shop Supplies

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 2.65 Total: 148.65

Work Order: 2301313 Meter: 1109 In Date: 02/09/2023 Closed: 02/15/2023

Problem: Issue with the anti-freeze hose/pipe. Will be brought back to you tomorrow.

Work CompletedParts IssuedQuantity- replace rusted thru hose clampsHose Clamp2.00- Shop SuppliesShop Supplies1.00Hours: 1.00Comm: 0.00Labor: 73.00Parts: 4.52Total: 77.52

10210048

Palm Beach County Fleet Management Asset Maintenance History 2019 JOHN DEERE GATOR HPX815E Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Work Order: 2306338 Meter: 1230 In Date: 06/28/2023 Closed: 07/31/2023

Problem: PM Service. wont start in neutral- indent area has issue. Torque converter making noise. Transmission leak

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service- Replaced Drive Belt, Driver And Driven Pulleys		Napa Qt 15w40	3.00	
		Napagold Oil Filter	1.00	
- Front And Rear Brake Calipers Seized, Replaced And Bleed (Calipers	Napagold Fuel Filte	1.00	
- Replaced Neutral Saftey Switch		Napagold Air Filter	1.00	
 Replaced Both Front Tires R&i Driver Front Axle, Replaced Boots Wash Transmission And Test Drove, Found Transmission Leaking At Dipstick, Replaced Dipstick O-ring Replaced Broken Passenger Seat 		Drive Belt	1.00	
		24x9.5x10 At Tire	2.00	
		Inner Air Filter Replaces 2845		
		Clutch	1.00	
		Switch	1.00	
- Shop Supplies		Axle Kit		1.00
		Clutch		1.00
		Axle Kit		1.00
		Disk Brake Cali		2.00
		Disk Brake Cali		1.00
		Disc Brake Cali		1.00
		Brk Fluid Dot 4-320	Z	1.00
		Bleed Valve		2.00
		Bolt		2.00
		Shop Supplies		1.00
		Tire Disposal Fee		2.00
Hours: 15.50 Col	mm: 0.00	Labor: 1,131.50	Parts: 3,389.10	Total: 4,520.6

Work Order: 2308207 Meter: 1249 In Date: 08/16/2023 Closed: 09/06/2023

Problem: Mount that the drive shaft is connected to is rotted out. Also, the flashers do not work. Thank you!

Work Completed		Parts Issued	Quantity	
- rusted frame not cost effective	Shop Supplies	1.00		
- Shop Supplies				
Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 2.65	Total: 75.65

10210048

Palm Beach County Fleet Management Asset Maintenance History

2019 JOHN DEERE GATOR HPX815E Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Work Order: 2309427 Meter: 1249 In Date: 09/18/2023 Closed: 09/18/2023

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 62.50 Total Labor: 4,550.50 Total Comm: 0.00 Total Parts: 6,883.93