

1/8/2024
6:55:08 PM

Palm Beach County Fleet Management Asset Maintenance History
10198023 2015 JACOBSON GROOM MASTER II Ballfield Groomer

Total Hours: 81.00 Labor: 5,509.00 Parts: 2,294.08 Comm: 0.00 Charged: 7803.08

Work Order: 1502557 **Meter:** 1 **In Date:** 03/11/2015 **Closed:** 03/11/2015
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1602014 **Meter:** 8 **In Date:** 02/26/2016 **Closed:** 03/08/2016
Problem: P.M.SERVICE, C/K FRONT TIRE

Work Completed

- pm
- svc hyd sys correct fluid level rr filter
- wash eq
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Napagold Fuel Filter	1.00
Napagold Oil Filter	1.00
15w40 Bulk South Reg	4.00
Napa Trans Filter	1.00
Aw68 Bulk Sr	3.00
Shop Supplies	1.00

Hours: 6.00 Comm: 0.00 Labor: 360.00 Parts: 45.88 Total: 405.88

Work Order: 1702508 **Meter:** 88 **In Date:** 03/10/2017 **Closed:** 03/27/2017
Problem: PM Service.Fluid leak.

Work Completed

- Pm service
- C/c leaking diesel fuel.replace bad fuel filter housing.
- Service hyd. system.inspect lines and hoses.replace filter,correct fluid levels.
- Wash equipment.
- Repair L/r tire.correct all N2
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Napagold Fuel Filter	1.00
Napagold Oil Filter	1.00
15w40 Bulk South Reg	4.00
Napa Trans Filter	1.00
Aw68 Bulk Sr	2.00
Fuel Filter Assy	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 9.50 Comm: 0.00 Labor: 570.00 Parts: 193.99 Total: 763.99

1/8/2024
6:55:08 PM

Palm Beach County Fleet Management Asset Maintenance History
10198023 2015 JACOBSON GROOM MASTER II Ballfield Groomer

Work Order: 2005142 **Meter:** 274 **In Date:** 05/21/2020 **Closed:** 06/23/2020
Problem: PM Service.Leaking oil.

Work Completed

- Pm Service.
- Service hyd.system.r/r hyd.filter.correct fluid level.replace leaking hose,install anti chaffing gear.
- Replace three tires,mount,add N2.
- Wash equipment.
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Napagold Air Filter	1.00
Fuel Element	1.00
15w40 Bulk South Reg	4.00
Napagold Oil Filter	1.00
Hd Heater Hose	5.00
Aw68 Bulk Sr	3.00
Napa Trans Filter	1.00
20x11.00-10 4ply Carl Turf Tamer	3.00
Mako Hose	1.00
Shop Supplies	1.00
Tire Disposal Fee	3.00

Hours: 9.50

Comm: 0.00

Labor: 693.50 Parts: 653.67 Total: 1,347.17

Work Order: 2009355 **Meter:** 280 **In Date:** 09/17/2020 **Closed:** 10/19/2020
Problem: Will not shutdown with key.

Work Completed

- C/c Will not shut down.replace fuel shut off solenoid.replace linkage,injector pump lever and banjo fitting.install inline fuel filter and test drive.
- Wash equipment for repairs.
- Shop Supplies

Parts Issued

Quantity

Napagold Fuel Filter	1.00
Lock Washer	2.00
Hex Nut 1/4-28	2.00
Ball Joint	2.00
Solenoid Fuel	1.00
Spring Pin	1.00
Lever, Engine Stop	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 6.00

Comm: 0.00

Labor: 438.00 Parts: 498.14 Total: 936.14

1/8/2024
6:55:08 PM

Palm Beach County Fleet Management Asset Maintenance History
10198023 2015 JACOBSON GROOM MASTER II Ballfield Groomer

Work Order: 2106275 **Meter:** 363 **In Date:** 06/09/2021 **Closed:** 06/18/2021
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Service hydraulic system, replace filter, correct fluid level.
- Customers complaint unit will not turn off. verify fuel shut off solenoid linkage broke. Replace joint connector reinstall and adjust solenoid and linkage.
- Wash equipment for service and repair.
- Shop Supplies

Parts Issued

Quantity

15w40 Bulk South Reg	1.00
Napagold Oil Filter	1.00
Fuel Element	1.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Aw68 Bulk Sr	2.00
Napa Trans Filter	1.00
Ball Joint	2.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 8.00

Comm: 0.00

Labor: 584.00 Parts: 151.40 Total: 735.40

Work Order: 2206338 **Meter:** 470 **In Date:** 06/15/2022 **Closed:** 07/05/2022
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- C/c key is broken off in the ignition. Disassemble dash to replace ignition assembly with key. reassemble and test run.
- Service hydraulic system, replace filter, correct fluid level, inspect al hoses, and fittings.
- Verify headlight switch is broken. Replace headlight switch
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Napagold Air Filter	1.00
15w40 Bulk South Reg	3.00
Napagold Oil Filter	1.00
Fuel Element	1.00
Keyswitch	1.00
Aw68 Bulk Sr	2.00
Napa Trans Filter	1.00
Headlight Switch	1.00
Ign Switch Replces 4283269	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 8.00

Comm: 0.00

Labor: 584.00 Parts: 192.35 Total: 776.35

1/8/2024
6:55:08 PM

Palm Beach County Fleet Management Asset Maintenance History
10198023 2015 JACOBSON GROOM MASTER II Ballfield Groomer

Work Order: 2310325 **Meter:** 480 **In Date:** 10/12/2023 **Closed:** 10/25/2023
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Service hydraulic, inspect lines and hoses and correct fluid level.
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Napagold Air Filter	1.00
Napagold Fuel Filter	1.00
Fuel Element	1.00
15w40 Bulk South Reg	1.00
Aw68 Bulk Sr	1.00
Napa Trans Filter	1.00
Napagold Oil Filter	1.00
Shop Supplies	1.00

Hours: 5.00

Comm: 0.00

Labor: 365.00

Parts: 45.18

Total: 410.18

Work Order: 2311596 **Meter:** 480 **In Date:** 11/20/2023 **Closed:** 11/20/2023
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 0.00

Total: 146.00

Total Hours: 81.00

Total Labor: 5,509.00

Total Comm: 0.00

Total Parts: 2,294.08