Palm Beach County Fleet Management Asset Maintenance History 10198873 2015 GKB CB160 Planer/Remover, Mechanical Turf

Total Hours: 6	65.50 Labor: 4,544.5	0 Parts: 13,900.53	Parts: 13,900.53 Comm: 0.00		ed: 18445.03
Work Order: Problem:	1503217 I 1061 - Pre Delivery Insp	Meter: 0		In Date: 03/27/20	15 Closed: 03/27/2015
Work Com	pleted				
- Pre Deliv	ery Inspection				
	Hours: 2.00	Comm: 0.00	Labor: 120.00	Parts: 0.00	Total: 120.00
Work Order: Problem:	1510532 I adjust belt	Meter: 0		In Date: 10/19/20	15 Closed:
Work Com	pleted				
-	Hours: 0.00	Comm: 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
Work Order: Problem:		Meter: 0		In Date: 03/16/20	16 Closed : 03/24/2016
Work Com	pleted		Parts Issued		Quantity
- pm			Shop Supplies		1.00
- to Jpp					
- Shop Sup	pplies				
	Hours: 4.00	Comm: 0.00	Labor: 240.00	Parts: 2.00	Total: 242.00
Work Order: Problem:	1702698 I pm service	Meter: 0		In Date: 03/16/20	17 Closed: 03/21/2017
Work Com	pleted		Parts Issued		Quantity
- Pm			Shop Supplies		1.00
- Shop Sup	oplies				
	Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 2.00	Total: 182.00

- pm service

- Shop Supplies

Hours: 3.00

Palm Beach County Fleet Management Asset Maintenance History 10198873 2015 GKB CB160 Planer/Remover, Mechanical Turf

Work Order: Problem:	1705701 bearing failed	Meter:	0		In Date:	06/08/2017	Closed:	06/16/2017
Work Com	pleted			Parts Issued			Qı	ıantity
- Replaced	upper roller bearing and lube	and test run		Eb Bearing				2.00
- Shop Sup				Shop Supplies				1.00
				Freight Charge				1.00
	Hours: 2.00		Comm: 0.00	Labor: 120.00	Parts: 29	7.96	Total:	417.96
Work Order: Problem:	1800375 u joint for pto shaft	Meter:	0		In Date:	01/10/2018	Closed:	01/30/2018
Work Com	pleted			Parts Issued			Qı	uantity
- Replace ι	ijoint in Pto shaft			Cross Bearing				1.00
- Shop Sup	pplies			Shop Supplies				1.00
				Freight Charge				1.00
	Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 108	8.55	Total:	168.55
Work Order: Problem:	1802909 pm service	Meter:	0		In Date:	03/19/2018	Closed:	03/20/2018
Work Com	pleted			Parts Issued			Qı	uantity

Comm: 0.00

Non-chlor Brake Clnr

Parts: 12.26

Shop Supplies

Labor: 180.00

3.00

1.00

Total: 192.26

Palm Beach County Fleet Management Asset Maintenance History 10198873 2015 GKB CB160 Planer/Remover, Mechanical Turf

Work Order: 1902776 Meter: 0 In Date: 03/13/2019 Closed: 03/25/2019

Problem: pm/ rollers

Work Completed	Parts Issued		Quantity	
- Pm Service		Non-chlor Brake C	lnr	1.00
- Repl. rollers and support bracket; repl. safety cover ro	oll	Macs Chain Cable	Lube	1.00
- Shop Supplies		Wd40 Spr		1.00
		Safety Cover Roll (Cb240	1.00
		Conveyor Roller H	older	2.00
		Troughed Roller, C	Cb200 245mm	4.00
		Shop Supplies		1.00
		Freight Charge		1.00
Hours: 7.00	Comm: 0.00	Labor: 469.00	Parts: 684.39	Total: 1,153.39

Work Order: 2002356 Meter: 0 In Date: 03/06/2020 Closed:

Problem: Drive Shaft

Work Completed

-

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

Work Order: 2002449 Meter: 0 In Date: 03/10/2020 Closed: 04/07/2020

Problem: pm/ broken pto shaft

Work Completed		Parts Issued		Quantity
- pm service		1cart Palladium 2	Grs	1.00
- R&r Pto shaft rebuilt tractor end		Macs Chain Cable	Lube	1.00
- Shop Supplies		Shop Supplies		1.00
Hours: 6.00	Comm: 0.00	Labor: 438.00	Parts: 15.40	Total: 453.40

Palm Beach County Fleet Management Asset Maintenance History 10198873 2015 GKB CB160 Planer/Remover, Mechanical Turf

Work Order: 2101328 Meter: 0 In Date: 02/04/2021 Closed: 06/16/2021

Problem: replace shaft and blades/ pm

Work Completed		Parts Issued	Quantity
- Preventive Maint. Service		Blaster Penetrant	1.00
- Replace all Blades		1cart Palladium 2 Grs	1.00
- Shop Supplies		Bearing	2.00
		Cover Side Plate (right)	1.00
		Cover Side Plate (left)	1.00
		Cb160 Rotor	1.00
		Blade Bolt	130.00
		Frasing Blade (left)	64.00
		Shop Supplies	1.00
		Freight Charge	1.00
		Freight Charge	1.00
Hours: 29.00	Comm: 0.00	Labor: 2,117.00 Parts: 10,273.78	Total: 12,390.78

Work Order: 2202408 Meter: 0 In Date: 03/03/2022 Closed: 03/22/2022

Problem: Needs 4 new belts. Current ones are frayed. Item #11 on the parts list manual. Will send an email.

Work Completed		Parts Issued	Quantity
- secure parts for dept		Hanging Bearing Uchb205	3.00
- Shop Supplies		Coupler	2.00
		Side Sealing Biege	1.00
		Gkb Side Conveyor Safety Cover, Cb160	1.00
		V-belt	4.00
		Shop Supplies	1.00
		Freight Charge	1.00
		Freight Charge	1.00
Hours: 0.50	Comm: 0.00	Labor: 36.50 Parts: 1,809.89	Total: 1,846.39

Palm Beach County Fleet Management Asset Maintenance History 10198873 2015 GKB CB160 Planer/Remover, Mechanical Turf

Work Order: 2206558 Meter: 0 In Date: 06/22/2022 Closed: 08/31/2022

Problem: PM Service.

Work Completed			Parts Issued		Quantity						
- Preventive Maint. Service- Replace Star Spidex Coupling Right Lower Roller- Shop Supplies			Non-chlor Brake Clnr 1cart Palladium 2 Grs Shop Supplies		2.00 1.00 1.00						
						Н	lours: 5.00	Comm: 0.00	Labor: 365.00	Parts: 14.08	Total: 379.08
							N. 4 -	1		I D-1- 04/04/00	000 01 1 00/00/00/

Work Order: 2304033 Meter: 0 In Date: 04/24/2023 Closed: 06/22/2023

Problem: Please order 4 rollers (Part # 0703-0002 / troughed roller 245mm. We will pick up. Thank you!

Work Completed			Parts Issued	Quantity	
- secure rollers fo	r dept		Conveyor Suppor	ting Roller	4.00
- Shop Supplies			Shop Supplies		1.00
			Freight Charge		1.00
	Hours: 0.50	Comm: 0.00	Labor: 36.50	Parts: 557.57	Total: 594.07

Work Order: 2305072 Meter: 0 In Date: 05/22/2023 Closed: 06/02/2023

Problem: needs bearings

Work Completed			Parts Issued		Quantity
- secure parts for dept			Bearing (0201-0006)		2.00
- Shop Supplies			Bearing (ucf208-40mm)		2.00
			Shop Supplies		1.00
	Hours: 0.50	Comm: 0.00	Labor: 36.50	Parts: 122.64	Total: 159.14

Work Order: 2309474 Meter: 0 In Date: 09/19/2023 Closed: 09/19/2023

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 65.50 Total Labor: 4,544.50 Total Comm: 0.00 Total Parts: 13,900.53