

1/8/2024
6:54:42 PM

L00728

Palm Beach County Fleet Management Asset Maintenance History
2009 TORO GRNMASTER 7210 Mower, 72in, Ztr, Side Discharge

Total Hours: 207.50 Labor: 13,194.50 Parts: 17,695.83 Comm: 0.00 Charged: 30890.33

Work Order: 940247 **Meter:** 7 **In Date:** 07/02/2009 **Closed:** 07/02/2009
Problem: Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1001552 **Meter:** 137 **In Date:** 02/11/2010 **Closed:** 02/19/2010
Problem: tire

Work Completed

- Repair tire
- Shop Supplies

Parts Issued	Quantity
Shop Supplies	1.00
15-600-6 Ribbed Tire	1.00
Tire Disposal Fee	1.00
Labor: 60.00 Parts: 46.23 Total: 106.23	

Hours: 1.00 Comm: 0.00

Work Order: 1008643 **Meter:** 222 **In Date:** 08/11/2010 **Closed:** 09/23/2010
Problem: tire only

Work Completed

- Replace 1 caster tire and repair 1 tire
- Shop Supplies

Parts Issued	Quantity
Shop Supplies	1.00
15x6.00x6 Tire	1.00
Tire Disposal Fee	1.00
Labor: 60.00 Parts: 47.02 Total: 107.02	

Hours: 1.00 Comm: 0.00

1/8/2024
6:54:42 PM

L00728

Palm Beach County Fleet Management Asset Maintenance History
2009 TORO GRNDMASTER 7210 Mower, 72in, Ztr, Side Discharge

Work Order: 1010875 **Meter:** 308 **In Date:** 10/04/2010 **Closed:** 10/28/2010
Problem: pm / light switch broken / replace shield

Work Completed

- Pm
- Replace burnt out lights 3 ea replace bad switch
- Replace Deflector on Deck
- Shop Supplies
- Clean mower

Parts Issued

Quantity

Shop Supplies	1.00
P8043 Fuel Filter Lbf Lff8062 Wix 33472	1.00
6438 Air Filterfrm Ca9550 Wix 46438	1.00
Oil Filter	1.00
Hyd Filter	1.00
15/40 Oil	4.00
Switch Assy	1.00
Bulb	1.00
Deflector Rubber	1.00
Rear Hinge	1.00
Front Hinge	1.00

Hours: 8.00

Comm: 0.00

Labor: 480.00 Parts: 191.41 Total: 671.41

Work Order: 1105844 **Meter:** 363 **In Date:** 06/02/2011 **Closed:** 06/10/2011
Problem: cant remove center blade bolt

Work Completed

- replace center spindle shaft and bolt, spindle thread damaged
- Replace missing safety chute flap
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
Blade Bolt	1.00
Rubber Chute Deflector	1.00
Spindle Shaft	1.00

Hours: 1.50

Comm: 0.00

Labor: 90.00 Parts: 265.82 Total: 355.82

1/8/2024
6:54:42 PM

L00728

Palm Beach County Fleet Management Asset Maintenance History
2009 TORO GRNDMASTER 7210 Mower, 72in, Ztr, Side Discharge

Work Order: 1109914 **Meter:** 462 **In Date:** 09/16/2011 **Closed:** 09/30/2011
Problem: BLADE BOLT / CENTER ROTTEN / CHECK FOR BENT SHAFT

Work Completed

- r/r right hand spindle shaft blade bolt
- r/r frt rolelr and hardware
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
Shaft Assy	1.00
Blade Bolt	1.00
Anti Scalp Cup	1.00
Roller	1.00
Roller Shaft	1.00

Hours: 1.50

Comm: 0.00

Labor: 90.00

Parts: 261.71

Total: 351.71

Work Order: 1110990 **Meter:** 462 **In Date:** 10/14/2011 **Closed:** 10/19/2011
Problem: repair tire (tire only)

Work Completed

- Repair tire
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 60.00

Parts: 2.00

Total: 62.00

1/8/2024
6:54:42 PM

L00728

Palm Beach County Fleet Management Asset Maintenance History
2009 TORO GRNMASTER 7210 Mower, 72in, Ztr, Side Discharge

Work Order: 1113496

Meter: 510

In Date: 12/28/2011 **Closed:** 01/05/2012

Problem: pm service

Work Completed

- Pm Mower
- Hydraulic Sys Service
- Coolant Sys Service
- Reattached Rt Rr Scalping Wheel And Bracket
- Rotate Left Rear Tire On Rim For Longevity
- Rebuild Rt Deck Spindle
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
6438 Air Filterfrm Ca9550 Wix 46438	1.00
P8043 Fuel Filter Lbf Lff8062 Wix 33472	1.00
Oil Filter	1.00
Hyd Filter	1.00
Ty22000 Trans Fluid John Deere	2.00
15/40 Oil	4.00
Green Antifreeze Stock #060030002	2.00
Thermostat	1.00
Thermostat Gasket	1.00
O-ring	1.00
Seal	2.00
Bearing	2.00
Spacer	1.00

Hours: 10.00

Comm: 0.00

Labor: 600.00

Parts: 292.02

Total: 892.02

Work Order: 1205907

Meter: 574

In Date: 06/22/2012 **Closed:** 07/11/2012

Problem: Repair or replace tires as needed

Work Completed

- Replace 3 tires
- Repair 3 tires
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
15x6.00-6 Ribbed Tire	3.00
Tire Disposal Fee	3.00

Hours: 3.00

Comm: 0.00

Labor: 180.00

Parts: 154.61

Total: 334.61

1/8/2024
6:54:42 PM

L00728

Palm Beach County Fleet Management Asset Maintenance History
2009 TORO GRNDMASTER 7210 Mower, 72in, Ztr, Side Discharge

Work Order: 1302804
Problem: PM

Meter: 746

In Date: 03/21/2013 **Closed:** 03/29/2013

Work Completed

- pm service
- hyd service
- replace all scalper wheels and rollers
- adjust control rods to strap mower from creeping
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Oil Filter Ph7317	1.00
Napagold Fuel Filter	1.00
15-40 Oil	4.00
Filter	1.00
Deck Roller	2.00
Shaft	2.00
Spacer-roller	1.00
Roller,deck	1.00
Roller	1.00
Bolt	1.00
Shaft,roller	1.00
Plate-roller	1.00
Screw	2.00
Tube-spanner	2.00
Roller Scalp	2.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 7.00

Comm: 0.00

Labor: 420.00

Parts: 455.77

Total: 875.77

Work Order: 1305116

Meter: 781

In Date: 05/23/2013 **Closed:** 05/31/2013

Problem: replace tire (tire only)

Work Completed

- replace tire
- Shop Supplies

Parts Issued

Quantity

Tire	1.00
Shop Supplies	1.00

Hours: 1.00

Comm: 0.00

Labor: 60.00

Parts: 32.21

Total: 92.21

1/8/2024
6:54:42 PM

**L00728 Palm Beach County Fleet Management Asset Maintenance History
2009 TORO GRNMASTER 7210 Mower, 72in, Ztr, Side Discharge**

Work Order: 1311885 **Meter:** 845 **In Date:** 11/26/2013 **Closed:** 12/20/2013
Problem: spindles bent/ bolt stripped/ see notes

Work Completed

- R&r all 3 spindle assembly r&r both belts clean surface from delivers install new spindles w/pullies
- R&r front roller (scalping wheel)
- Shop Supplies

Parts Issued

Quantity

Roller	1.00
Shaft,roller	1.00
Flange Nut Ni	1.00
Spindle Assy	1.00
Double Spindle Assy	1.00
High Spindle Assy	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 5.50

Comm: 0.00

Labor: 330.00 Parts: 1,589.13 Total: 1,919.13

Work Order: 1400953 **Meter:** 857 **In Date:** 01/29/2014 **Closed:** 02/10/2014
Problem: dead battery

Work Completed

- Battery fell cord test. replace battery clean terminal
- Shop Supplies

Parts Issued

Quantity

Group 26 Delco	1.00
Shop Supplies	1.00

Hours: 1.00

Comm: 0.00

Labor: 60.00 Parts: 82.10 Total: 142.10

1/8/2024
6:54:42 PM

L00728

Palm Beach County Fleet Management Asset Maintenance History
2009 TORO GRNDMASTER 7210 Mower, 72in, Ztr, Side Discharge

Work Order: 1402386

Meter: 872

In Date: 03/11/2014 **Closed:** 03/27/2014

Problem: pm/ deck belt comes off

Work Completed

- Pm Mower
- Hydr sys service
- Replace damaged deck chute and tension spring
- Replace both damaged deck belts-rt side deck tension pulley and rt side spindle pulley
- Remove hazzard lights and fab and install new style light assembly
- Tire flip on rim for longevity of tire
- Repalce left lens scalping wheel
- Replace deck mounted bunge and deck cover knobs (wiring)
- Service gear box
- Clean radiator
- Shop Supplies

Parts Issued

Quantity

Face Lmp	2.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Napagold Fuel Filter	1.00
Napa Hydraulic Filtr	1.00
15-40 Oil	4.00
Aw68 Hydro Fluid Hydr	2.00
Rubber Deflector Assy	1.00
Torsion Spring	1.00
Belt	1.00
Belt	1.00
Idler Pulley	1.00
Roller Scalp	1.00
Tube-spanner	1.00
Tube Spacer	1.00
Jack Bungee	1.00
Knob	1.00
85-140 Gear Oil Gear	1.00
Lens	1.00
V-belt	1.00
V-belt	1.00
Low Driven Pulley	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 15.00

Comm: 0.00

Labor: 900.00

Parts: 852.93

Total: 1,752.93

1/8/2024
6:54:42 PM

L00728

Palm Beach County Fleet Management Asset Maintenance History
2009 TORO GRNDMASTER 7210 Mower, 72in, Ztr, Side Discharge

Work Order: 1407157 **Meter:** 946 **In Date:** 07/21/2014 **Closed:** 07/24/2014
Problem: flat tire (tire only)

Work Completed

- Repair tire repalce valve stem

Hours: 0.50 Comm: 0.00 Labor: 30.00 Parts: 0.00 Total: 30.00

Work Order: 1407395 **Meter:** 953 **In Date:** 07/28/2014 **Closed:** 07/30/2014
Problem: cutting uneven/ see notes

Work Completed

- replace rf caster wheel tire
- adjust deck and blades to cut correctly
- Shop Supplies

Parts Issued

Quantity

Tire	1.00
Shop Supplies	1.00

Hours: 3.00 Comm: 0.00 Labor: 180.00 Parts: 33.73 Total: 213.73

Work Order: 1501140 **Meter:** 1034 **In Date:** 01/30/2015 **Closed:** 02/10/2015
Problem: tires only / see notes

Work Completed

- apply New Valve Stem and ck and replaced 1 tire
- Shop Supplies

Parts Issued

Quantity

15-600-6 Nhs Str Rib 04	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 1.50 Comm: 0.00 Labor: 90.00 Parts: 68.35 Total: 158.35

1/8/2024
6:54:42 PM

L00728

Palm Beach County Fleet Management Asset Maintenance History
2009 TORO GRNDMASTER 7210 Mower, 72in, Ztr, Side Discharge

Work Order: 1502556

Meter: 1060

In Date: 03/11/2015 **Closed:** 03/27/2015

Problem: pm service

Work Completed

- Pm Service
- Hyd Service
- Replace Deck Chute assy w/bracket
- Replace both deck belts
- Repair Front Left Tire'
- Coding Sys S.v.
- Replace L/h Scalp wheel w/bracket replace r/h scalp roller
- Replace universal signal lights
- Clean adjust parking Brake
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	4.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Napagold Fuel Filter	1.00
Napa Hydraulic Filtr	1.00
Aw68 Hydro Fluid Hydr	2.00
Rubber Deflector Assy	1.00
Spacer	1.00
Torsion Spring	1.00
V-belt	1.00
V-belt	1.00
15-600-6 Nhs Str Rib 04	1.00
Napa Antifreeze Gal	1.00
Brake Cleaner	1.00
Plate-roller	1.00
Roller Scalp	2.00
Tube-spanner	2.00
Tube Spacer	2.00
Face Lmp	2.00
Screw	1.00
Shop Supplies	1.00
Tire Disposal Fee	0.00
Freight Charge	1.00

Hours: 12.50

Comm: 0.00

Labor: 750.00

Parts: 652.63

Total: 1,402.63

1/8/2024
6:54:42 PM

L00728

Palm Beach County Fleet Management Asset Maintenance History
2009 TORO GRNMASTER 7210 Mower, 72in, Ztr, Side Discharge

Work Order: 1507571 **Meter:** 1086 **In Date:** 07/29/2015 **Closed:** 08/25/2015
Problem: fan belt & blades damaged

Work Completed

- Replace V-belt
- Test cooling sys repalce cooling fan
- Replace 3 blades and hardware
- Replace spindle assy R/r belt and shields
- Replace all scalp rollers and replace bump skid deck unit
- Shop Supplies

Parts Issued

Quantity

Belt	1.00
Rotary Atomic Blade	3.00
Anti-scalp Cup	3.00
Blade Bolt	3.00
Roller Scalp	2.00
Tube-spanner	2.00
Bumper Keck	1.00
Deck Roller	2.00
Shaft	2.00
Spacer-roller	1.00
Roller,deck	1.00
Roller	1.00
Screw	2.00
Engine Fan	1.00
Spindle Assy	1.00
Shaft,roller	1.00
Shop Supplies	1.00

Hours: 7.00

Comm: 0.00

Labor: 420.00

Parts: 1,304.33

Total: 1,724.33

Work Order: 1509796 **Meter:** 1108 **In Date:** 09/28/2015 **Closed:** 10/14/2015
Problem: overheats

Work Completed

- Overheating replace thermostat renew coolant
- Shop Supplies

Parts Issued

Quantity

Thermostat Assy	1.00
Thermostat Gasket	1.00
Napa Antifreeze Gal	2.00
Shop Supplies	1.00

Hours: 2.00

Comm: 0.00

Labor: 120.00

Parts: 89.20

Total: 209.20

1/8/2024
6:54:42 PM

L00728

Palm Beach County Fleet Management Asset Maintenance History
2009 TORO GRNMASTER 7210 Mower, 72in, Ztr, Side Discharge

Work Order: 1513058 **Meter:** 1147 **In Date:** 12/30/2015 **Closed:** 02/26/2016

Problem: deck damage, adj broken, missing bumper, missing wheel, check tank for leaks, broken shute, look ov

Work Completed

- Pm
- Replace Deck bumper and rubber deflector
- Replace front left caster tires tires and rear left
- Replace left front headlight
- Shop Supplies

Parts Issued

Quantity

cover deck rh	1.00
head light assmbly	1.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Napagold Fuel Filter	1.00
15-40 Oil	4.00
Bumper Keck	1.00
Rubber Deflector Assy	1.00
Tire & Wheel Assy	1.00
Clevis Adjust	4.00
caster seal	2.00
24-1200-12b Turf M Carl	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 8.00

Comm: 0.00

Labor: 480.00

Parts: 947.61

Total: 1,427.61

Work Order: 1601921

Meter: 1163

In Date: 02/24/2016 **Closed:** 04/13/2016

Problem: leaking fuel tank

Work Completed

- Install left fuel tank replace fuel filter (bleed fuel sys)
- Shop Supplies

Parts Issued

Quantity

Rh Fuel Tank	1.00
Lh Fuel Tank	1.00
Napagold Fuel Filter	1.00
Shop Supplies	1.00

Hours: 2.00

Comm: 0.00

Labor: 120.00

Parts: 997.63

Total: 1,117.63

1/8/2024
 6:54:42 PM

L00728

**Palm Beach County Fleet Management Asset Maintenance History
 2009 TORO GRNMASTER 7210 Mower, 72in, Ztr, Side Discharge**

Work Order: 1603888 **Meter:** 1163 **In Date:** 04/13/2016 **Closed:** 04/20/2016

Problem: replace tire, tire only

Work Completed

- Replace Tire
- Shop Supplies

Parts Issued

Quantity

15-600-6 Nhs Str Rib 04	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 55.15 Total: 115.15

Work Order: 1608612 **Meter:** 1225 **In Date:** 08/18/2016 **Closed:** 08/24/2016

Problem: replace tire, tire only

Work Completed

- Replace Tire
- Shop Supplies

Parts Issued

Quantity

Tire	1.00
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 36.46 Total: 96.46

Work Order: 1608657 **Meter:** 1229 **In Date:** 08/19/2016 **Closed:** 08/30/2016

Problem: deck damage/ see notes

Work Completed

- Ck Damage-straighten L/f frame rail and order new retainer pin, r&r both scalper wheel mounts and straightne and replace. mounting bolts installed new retainer pin and scalper wheels and blade and test run
- Shop Supplies

Parts Issued

Quantity

Tube-spanner	2.00
Roller Scalp	2.00
Screw	2.00
Flange Nut Ni	2.00
Retainer Pin	1.00
Shop Supplies	1.00

Hours: 3.00 Comm: 0.00 Labor: 180.00 Parts: 121.85 Total: 301.85

1/8/2024
6:54:42 PM

**L00728 Palm Beach County Fleet Management Asset Maintenance History
2009 TORO GRNDMASTER 7210 Mower, 72in, Ztr, Side Discharge**

Work Order: 1609048 **Meter:** 1229 **In Date:** 08/31/2016 **Closed:** 09/19/2016

Problem: battery/ smells coolant/ see notes

Work Completed

- Ck wont start, Load Test and replace battery, and positive terminal
- Pressure test cooling sys, replace radiator and upper and lowe hoses.
flush sys
- Shop Supplies

Hours: 4.50

Comm: 0.00

Parts Issued

Quantity

Upper Radiator Hose	1.00	
Lower Radiator Hose	1.00	
Napa Antifreeze Gal	2.00	
Group 26 Delco	1.00	
Batt Cable Terminal	1.00	
Radiator	1.00	
Shop Supplies	1.00	
Labor: 270.00	Parts: 1,382.56	Total: 1,652.56

1/8/2024
6:54:42 PM

**L00728 Palm Beach County Fleet Management Asset Maintenance History
2009 TORO GRNDMASTER 7210 Mower, 72in, Ztr, Side Discharge**

Work Order: 1610611 **Meter:** 1249 **In Date:** 10/13/2016 **Closed:** 10/28/2016

Problem: bent chute/ deck belt/ deck adjuster/ see notes

Work Completed

- Replace chute and hardware kit Straighten bracket
- Replace both deck belts
- Broken deck adj arm-straighten bracket and repalce hardware kit -replace deck roller anti scalp right front and right rear
- Shop Supplies

Parts Issued

Quantity

Rubber Deflector Assy	1.00
Spacer	1.00
Torsion Spring	1.00
Screw	1.00
V-belt	1.00
V-belt	1.00
Retainer Pin	1.00
Grease Zerk	1.00
Plate Roller	1.00
Roller Scalp	1.00
Tube Spacer	1.00
Screw	1.00
Roller,deck	1.00
Spacer-roller	1.00
Bolt	1.00
Tube-spanner	1.00
Baffle	1.00
Bushing	1.00
Shop Supplies	1.00

Hours: 6.00

Comm: 0.00

Labor: 360.00

Parts: 608.08

Total: 968.08

1/8/2024
6:54:42 PM

**L00728 Palm Beach County Fleet Management Asset Maintenance History
2009 TORO GRNMASTER 7210 Mower, 72in, Ztr, Side Discharge**

Work Order: 1611408 **Meter:** 1259 **In Date:** 11/03/2016 **Closed:** 11/29/2016
Problem: fuel tank leak left side/ poss hydro leak

Work Completed

- Replace front left headlight assy
- Replace hydro lines Oring seals
- Diagnose -found fuel leak replace gromments on fuel tank
- Shop Supplies

Parts Issued

Quantity

Worklight	1.00
Hyd Hose	1.00
Straight Fitting	1.00
O Ring	1.00
Elbow Fitting	1.00
O R Ing	1.00
Aw68 Hydro Fluid Hydr	3.00
Bushing	2.00
Elbow Fitting	1.00
Hose Clamp	2.00
Shop Supplies	1.00

Hours: 2.50

Comm: 0.00

Labor: 150.00 Parts: 344.51 Total: 494.51

Work Order: 1700553 **Meter:** 1266 **In Date:** 01/18/2017 **Closed:** 02/14/2017
Problem: Repair tire (tire only)

Work Completed

- Repair Tire
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 60.00 Parts: 2.00 Total: 62.00

1/8/2024
6:54:42 PM

L00728

Palm Beach County Fleet Management Asset Maintenance History
2009 TORO GRNDMASTER 7210 Mower, 72in, Ztr, Side Discharge

Work Order: 1703047 **Meter:** 1280 **In Date:** 03/27/2017 **Closed:** 03/31/2017
Problem: pm service

Work Completed

- Pm
- Hydro Service
- Left rear fuel leak-replace grommets on fuel tank
- Diag take apart seat weld/fab seat rails and seat structure
- Fix broken wires for turn signals
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Napagold Fuel Filter	1.00
15-40 Oil	4.00
Non-chlor Brake Clnr	2.00
Napa Hydraulic Filtr	1.00
Aw68 Hydro Fluid Hydr	2.00
Bushing	2.00
Shop Supplies	1.00

Hours: 10.50

Comm: 0.00

Labor: 630.00

Parts: 74.51

Total: 704.51

Work Order: 1704860 **Meter:** 1288 **In Date:** 05/16/2017 **Closed:** 05/22/2017
Problem: seat switch/ seat latch/ roll bar stop/ see notes

Work Completed

- replace seat switch and fix seat latch
- fabricate roll bar stop and weld
- Shop Supplies

Parts Issued

Quantity

Bail Switch	1.00
Shop Supplies	1.00

Hours: 3.50

Comm: 0.00

Labor: 210.00

Parts: 16.84

Total: 226.84

1/8/2024
6:54:42 PM

**L00728 Palm Beach County Fleet Management Asset Maintenance History
2009 TORO GRNDMASTER 7210 Mower, 72in, Ztr, Side Discharge**

Work Order: 1707570 **Meter:** 1328 **In Date:** 08/02/2017 **Closed:** 08/09/2017
Problem: spindle/ e brake/ chute/ see notes

Work Completed

- pto pump loose on deck resecure pump and reinstall deck belt, lube spindles and test run
- rewire front head lights
- adj frt caster wheel bearings
- Replace mower chute
- Adj traction rods to stop mower from creeping
- Shop Supplies

Parts Issued

Quantity

Rubber Deflector Assy	1.00
Shop Supplies	1.00

Hours: 5.50 Comm: 0.00 Labor: 330.00 Parts: 165.02 Total: 495.02

Work Order: 1708782 **Meter:** 1351 **In Date:** 09/06/2017 **Closed:** 09/20/2017
Problem: blades wont engage/ parking brake adjustment

Work Completed

- Ck blades operation-traced to center blade spindle seized. r&r belts to replace center spindle housing assembly and test run
- Adjust parking brake
- Shop Supplies

Parts Issued

Quantity

Double Spindle Assy	1.00
Shop Supplies	1.00

Hours: 3.00 Comm: 0.00 Labor: 180.00 Parts: 481.93 Total: 661.93

Work Order: 1710126 **Meter:** 1358 **In Date:** 10/16/2017 **Closed:** 10/27/2017
Problem: needs tire and rim (tire only)

Work Completed

- Replace Tire recondition rim
- Shop Supplies

Parts Issued

Quantity

Tire	1.00
Seal	2.00
Shop Supplies	1.00

Hours: 1.50 Comm: 0.00 Labor: 90.00 Parts: 58.48 Total: 148.48

1/8/2024
6:54:42 PM

L00728

Palm Beach County Fleet Management Asset Maintenance History
2009 TORO GRNMASTER 7210 Mower, 72in, Ztr, Side Discharge

Work Order: 1712597 **Meter:** 1396 **In Date:** 12/21/2017 **Closed:** 01/18/2018
Problem: p brake wont hold/ missing scalp wheels

Work Completed

- Replace all deck wheels
- Test and readjust brakes-replace lr & rr brakes
- Shop Supplies

Parts Issued

Quantity

Deck Roller	2.00
Shaft	2.00
Tube-spanner	2.00
Roller Scalp	2.00
Roller,deck	1.00
Spacer-roller	1.00
Shaft,roller	1.00
Roller	1.00
Bolt	1.00
Left Brake Caliper	1.00
Right Brake Caliper	1.00
Shop Supplies	1.00

Hours: 3.00

Comm: 0.00

Labor: 180.00

Parts: 852.08

Total: 1,032.08

Work Order: 1803249 **Meter:** 1401 **In Date:** 03/28/2018 **Closed:** 04/06/2018
Problem: pm service

Work Completed

- pm service
- hydraulic service
- Shop Supplies

Parts Issued

Quantity

Napa Hydraulic Filtr	1.00
Napagold Air Filter	1.00
Napagold Oil Filter	1.00
15-40 Oil	4.00
Napagold Fuel Filter	1.00
1cart Palladium 2 Grs	1.00
Shop Supplies	1.00

Hours: 5.00

Comm: 0.00

Labor: 300.00

Parts: 57.76

Total: 357.76

1/8/2024
6:54:42 PM

L00728

Palm Beach County Fleet Management Asset Maintenance History
2009 TORO GRNMASTER 7210 Mower, 72in, Ztr, Side Discharge

Work Order: 2001977

Meter: 1438

In Date: 02/26/2020 **Closed:** 04/14/2020

Problem: pm/ pto is inop

Work Completed

- pm service
- hyd. service
- diagnose and repair/replace Pto switch and control unit
- R&r discharge chute & slow moving sign
- R&r deck roller wheel and shaft
- R&r lft. frt. caster wheel& tire assembly, wheel bearings and seals
- Replace two amber pedestal lights & flasher control unit
- wash equipment
- clean and adjust parking brake
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
15-40 Oil	4.00
Napagold Air Filter	1.00
Napagold Fuel Filter	1.00
Non-chlor Brake Clnr	1.00
Napa Hydraulic Filtr	1.00
Aw68 Hydro Fluid Hydr	2.00
Rubber Deflector Assy	1.00
Smv Emblem Aluminum	1.00
Roller	1.00
Pto Switch	1.00
Shaft,roller	1.00
Amber Lens	2.00
Tail Lights	2.00
Control Module Assy	1.00
Stop Nut	1.00
Front Caster Spacer	1.00
Screw	1.00
Tire & Wheel Assy	1.00
Seal	2.00
Bearing	2.00
Flasher	1.00
Shop Supplies	1.00
Freight Charge	1.00
Freight Charge	1.00
Freight Charge	1.00

Hours: 15.50

Comm: 0.00

Labor: 1,131.50

Parts: 1,806.07

Total: 2,937.57

1/8/2024
6:54:42 PM

L00728

Palm Beach County Fleet Management Asset Maintenance History
2009 TORO GRNDMASTER 7210 Mower, 72in, Ztr, Side Discharge

Work Order: 2005353 **Meter:** 1444 **In Date:** 05/28/2020 **Closed:** 06/26/2020
Problem: check for mowing low in center

Work Completed

- replace pull link assy, bushings and flange, replace missing scalping
- Shop Supplies

Parts Issued

Quantity

Anti-scalp Cup	1.00
Bushing Flange	6.00
Zerk	4.00
Pin Retainer	2.00
Bushing	2.00
Pull Link Assy	2.00
Shop Supplies	1.00
Freight Charge	1.00
Freight Charge	1.00
Freight Charge	1.00

Hours: 4.00

Comm: 0.00

Labor: 292.00 Parts: 747.80 Total: 1,039.80

Work Order: 2008866 **Meter:** 1461 **In Date:** 09/02/2020 **Closed:** 09/14/2020
Problem: replace tire (tire only)

Work Completed

- replace tire
- Shop Supplies

Parts Issued

Quantity

24x12.00-12 Toro 6 Ply	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 1.00

Comm: 0.00

Labor: 73.00 Parts: 246.12 Total: 319.12

1/8/2024
6:54:42 PM

**L00728 Palm Beach County Fleet Management Asset Maintenance History
2009 TORO GRNDMASTER 7210 Mower, 72in, Ztr, Side Discharge**

Work Order: 2100282 **Meter:** 1510 **In Date:** 01/11/2021 **Closed:** 02/01/2021

Problem: Blades will not turn (Mower Damage) Please go through mower for further damage.

Work Completed

- Replace Both Front Tires
- Replace Deck Adjustment Clevis Bolt
- Replace Gearbox Mount Bushings,drill Out And Tap Broken Bolts In Box
- Wash Mower
- Replace Left Turn Signal Lamp Assembly
- Shop Supplies

Parts Issued

Quantity

15-600-6 Nhs Str Rib 04	2.00
Grommet	2.00
Rubber Mount	3.00
Clevis Adjust	1.00
Face Lmp	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 8.50

Comm: 0.00

Labor: 620.50 Parts: 197.36 Total: 817.86

Work Order: 2102303 **Meter:** 1511 **In Date:** 03/01/2021 **Closed:** 03/26/2021

Problem: pm/ Belt pops off when you engage PTO.

Work Completed

- Preventive Maint. Service
- replaced deck belt tensioner bushings & deck belts
- Shop Supplies

Parts Issued

Quantity

Napa Qt 15w40	4.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Napagold Fuel Filter	1.00
V-belt	1.00
V-belt	1.00
Pulley	1.00
Castor Bushing	2.00
Shop Supplies	1.00

Hours: 6.00

Comm: 0.00

Labor: 438.00 Parts: 264.70 Total: 702.70

1/8/2024
6:54:42 PM

Palm Beach County Fleet Management Asset Maintenance History
L00728 2009 TORO GRNDMASTER 7210 Mower, 72in, Ztr, Side Discharge

Work Order: 2205084 **Meter:** 1598 **In Date:** 05/11/2022 **Closed:** 06/30/2022

Problem: PM Service. At PBIA . Let me know when close to work order and I will bring it asap.

Work Completed

- Preventive Maint. Service
- replace bulbs and fix broken lights rewire
- replace mower deck pulley bushings and 2 new brackets - replace all hardware
- Shop Supplies

Parts Issued

Quantity

Napa Qt 15w40	4.00	
Napagold Oil Filter	1.00	
Napagold Fuel Filter	1.00	
Napagold Air Filter	1.00	
Non-chlor Brake Clnr	2.00	
Lucas Red-tacky Grs	1.00	
Boxed Miniatures	2.00	
Boxed Miniatures	2.00	
Rubber Mount	3.00	
Gearbox Bracket Rh	1.00	
Gearbox Bracket Lh	1.00	
Shop Supplies	1.00	
Freight Charge	1.00	
Labor: 511.00	Parts: 248.13	Total: 759.13

Hours: 7.00 Comm: 0.00

Work Order: 2306725 **Meter:** 1652 **In Date:** 07/10/2023 **Closed:** 07/20/2023

Problem: PM Service

Work Completed

- pm cancelled. customer declines deck repair
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00	
Labor: 73.00	Parts: 2.65	Total: 75.65

Hours: 1.00 Comm: 0.00

Total Hours: 207.50

Total Labor: 13,194.50

Total Comm: 0.00

Total Parts: 17,695.83