

1/8/2024  
6:53:19 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**L01401 2019 TORO WORKMAN HDX Utility Cart, Diesel**

---

**Total Hours: 22.50    Labor: 1,642.50    Parts: 883.28    Comm: 0.00    Charged: 2525.78**

---

**Work Order:** 2000019      **Meter:** 1      **In Date:** 01/02/2020    **Closed:** 01/08/2020  
**Problem:** pre delivery inspection

**Work Completed**

**Parts Issued**

**Quantity**

- pre delivery inspection
- Shop Supplies

Shop Supplies 1.00

Hours: 2.00      Comm: 0.00      Labor: 146.00      Parts: 4.00      Total: 150.00

---

**Work Order:** 2004613      **Meter:** 14      **In Date:** 05/07/2020    **Closed:** 06/02/2020  
**Problem:** has intermitting starting problems

**Work Completed**

**Parts Issued**

**Quantity**

- check safety switches and relay operation. unable to verify condition
- Shop Supplies

Shop Supplies 1.00

Hours: 1.00      Comm: 0.00      Labor: 73.00      Parts: 4.00      Total: 77.00

---

**Work Order:** 2101506      **Meter:** 53      **In Date:** 02/09/2021    **Closed:** 03/18/2021  
**Problem:** Over heating/ PM

**Work Completed**

**Parts Issued**

**Quantity**

- Preventive Maint. Service
- Diag over heat issues, send for switch and radiator warranty. Verify repair completed.
- Shop Supplies

15-40 Oil 4.00  
Napagold Oil Filter 1.00  
Napagold Fuel Filter 1.00  
Napagold Air Filter 1.00  
Shop Supplies 1.00

Hours: 5.50      Comm: 0.00      Labor: 401.50      Parts: 43.56      Total: 445.06

1/8/2024  
6:53:19 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**L01401 2019 TORO WORKMAN HDX Utility Cart, Diesel**

---

**Work Order:** 2203276      **Meter:** 92      **In Date:** 03/28/2022      **Closed:** 04/29/2022  
**Problem:** PM Service. key in machine

**Work Completed**

- Preventive Maint. Service
- Leaking Hydraulic Fluid From Tank. Replace Tank, Replace Filters, Drain And Fill.
- Shop Supplies

**Parts Issued**

**Quantity**

Qt Hd40w	4.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Napagold Air Filter	1.00
Aw68 Hydro Fluid Hydr	20.00
Napa Hydraulic Filtr	2.00
Non-chlor Brake Clnr	1.00
1cart Palladium 2 Grs	2.00
Hydraulic Tank	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 7.00

Comm: 0.00

Labor: 511.00

Parts: 829.08

Total: 1,340.08

---

**Work Order:** 2301196      **Meter:** 222      **In Date:** 02/06/2023      **Closed:** 03/17/2023  
**Problem:** Employee stated hard start and blows white smoke from exhaust.

**Work Completed**

- Remove Spredder Hopper Cover To Diagnose, Mounting Hardware Rusted, Seized, And Broken
- Ck Hard Start And White Smoke When Running. Added Water To Radiator, Pressure Test Cooling System, Perform Combustion Test. Failed Test, Fan Inop, Cooling System Not Circulating, Overheating.
- Shop Supplies

**Parts Issued**

**Quantity**

Shop Supplies	1.00
---------------	------

Hours: 7.00

Comm: 0.00

Labor: 511.00

Parts: 2.65

Total: 513.65

**Total Hours: 22.50**

**Total Labor: 1,642.50**

**Total Comm: 0.00**

**Total Parts: 883.28**