

2/1/2024
3:55:38 PM

Palm Beach County Fleet Management Asset Maintenance History
10198475 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Total Hours: 266.90 Labor: 18,306.40 Parts: 22,546.63 Comm: 1,246.65 Charged: 42099.68

Work Order: 1508312 **Meter:** 426 **In Date:** 08/19/2015 **Closed:** 08/19/2015
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection
- Minor weld repair or machining

Hours: 3.00 Comm: 0.00 Labor: 180.00 Parts: 0.00 Total: 180.00

Work Order: 1509046 **Meter:** 590 **In Date:** 09/09/2015 **Closed:** 10/20/2015
Problem: Install Pump

Work Completed

- Install fire pump
- Wire up pump
- Shop Supplies

Parts Issued

Quantity

Bulk Battery Cable	50.00
Bulk Battery Cable	50.00
Batt Cable Connector	2.00
Cb185-150 Cir Brkr	4.00
Bulk Battery Cable	50.00
Bat/cabl	50.00
Batt Cable Connector	4.00
Steel Order	1.00
3/4" Spring Latch	12.00
Glos Blk	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 15.00 Comm: 0.00 Labor: 900.00 Parts: 1,974.33 Total: 2,874.33

2/1/2024
3:55:38 PM

Palm Beach County Fleet Management Asset Maintenance History
10198475 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 1700308 **Meter:** 14477 **In Date:** 01/10/2017 **Closed:** 01/26/2017

Problem: Left rear tire going flat.

Work Completed

- Repair and balance left rear tire.
- Shop Supplies

Parts Issued

Parts Issued	Quantity
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1702656 **Meter:** 16146 **In Date:** 03/15/2017 **Closed:** 03/29/2017

Problem: P.M. service.

Work Completed

- P.m. Service.
- Resurface rear brake rotors,replace rear pads and parking brake shoes.clean mud from backing plates and hardware.flush and bleed system.
- Replace leaking left rear axle seal.
- Flush and refill rear differential,had water.
- Flush and refill front differential,had water.
- Inspect and service winch.
- Rotate and balance tires.
- Shop Supplies

Parts Issued

Parts Issued	Quantity
5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Napagold Air Filter	1.00
Real Brake Pad	1.00
Brake Shoes Park	1.00
Non-chlor Brake Clnr	2.00
Seal	1.00
Axle O Ring	1.00
Napa Gear 80w-90 Qt	4.00
Friction Modifier	1.00
75w140 Ford Axle Lube	3.00
brake fluid	1.00
Shop Supplies	1.00

Hours: 15.00 Comm: 0.00 Labor: 900.00 Parts: 368.27 Total: 1,268.27

2/1/2024
3:55:38 PM

Palm Beach County Fleet Management Asset Maintenance History
10198475 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 1810176

Meter: 31492

In Date: 10/01/2018 **Closed:** 10/17/2018

Problem: P.M. service.

Work Completed

- P.m. service.
- Inspect and service front differential . Due to water intrusion. Flush and refill and clean front differential.
- Inspect and service rear differential . drain and refill .
- Inspect and service winch .
- Rotate and high speed balance all four tires . Nitrofill.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Napagold Air Filter	1.00
22" Wiper Blade	2.00
Wd40 Spr	1.00
Used Fire X Refurbished	1.00
75w140 Ford Axle Lube	2.00
Ptex Ultra Grey 3oz	1.00
Friction Modifier	2.00
75w140 Ford Axle Lube	3.00
Pedal Pad	1.00
Shop Supplies	1.00

Hours: 8.00

Comm: 0.00

Labor: 536.00

Parts: 241.35

Total: 777.35

2/1/2024
3:55:38 PM

Palm Beach County Fleet Management Asset Maintenance History
10198475 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 1903366 **Meter:** 35281 **In Date:** 03/27/2019 **Closed:** 04/16/2019
Problem: P.M. service.

Work Completed

- P.m. service.
- Clean and power wash all brakes to remove mud and dirt . Resurface rear brake rotors . Replace rear brake calipers and pads and parking brake shoes . Flush and bleed brake system . Road test .
- Remove right rear axle and hub assembly to replace damaged hub and replace axle seal . refill rear differential and road test .
- Inspect and service winch .
- Rotate and balance all four tires . Nitrofill all tires and reset Tpms .
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	8.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
oil auto	1.00
Brake Pad	1.00
Brake Shoes Park	1.00
Brake Caliper	1.00
Brake Caliper	1.00
Non-chlor Brake Clnr	1.00
B Fluid Dot 3-32oz	1.00
75w140 Ford Axle Lube	1.00
Axle O Ring	1.00
Seal	1.00
Rear Axle Nut	1.00
Hub Bearing Assy	1.00
Shop Supplies	1.00

Hours: 17.00

Comm: 0.00

Labor: 1,139.00

Parts: 1,168.47

Total: 2,307.47

Work Order: 1906224 **Meter:** 36657 **In Date:** 06/13/2019 **Closed:** 06/13/2019
Problem: no start

Work Completed

- Tow From: 2300 Jog east side of garage To: lv shop

Hours: 0.00

Comm: 96.00

Labor: 0.00

Parts: 0.00

Total: 96.00

2/1/2024
3:55:38 PM

Palm Beach County Fleet Management Asset Maintenance History
10198475 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 1911379 **Meter:** 40122 **In Date:** 11/01/2019 **Closed:** 11/06/2019
Problem: ABS light and Advance trac light on

Work Completed

Parts Issued

Quantity

- Computer diagnose Abs light , code C0034. Perform pinpoint test .
Remove right front wheel , caliper and rotor to drill out broken sensor bolt .
Replace defective right front wheel speed sensor and bolt . Clear code and
road test .

Abs Sensor	1.00
Shop Supplies	1.00

- Shop Supplies

Hours: 2.50 Comm: 0.00 Labor: 182.50 Parts: 108.48 Total: 290.98

Work Order: 2000470 **Meter:** 41268 **In Date:** 01/15/2020 **Closed:** 01/22/2020
Problem: replace lost key

Work Completed

Parts Issued

Quantity

- make and program 1 extra key
- Shop Supplies

Ford Ignition Key Blank	1.00
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 30.60 Total: 103.60

Work Order: 2005337 **Meter:** 44877 **In Date:** 05/28/2020 **Closed:** 06/15/2020
Problem: P.M. service.

Work Completed

Parts Issued

Quantity

- P.m. service.
- Replace missing pintle pin .
- Replace all four tires and balance . Nitrofill all .
- Perfrom complete front end alignment . Install caster /camber adjusting
cams on both front upper ball joints . Road test .

Napagold Oil Filter	1.00
5w20 Engine Oil	8.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Napagold Air Filter	1.00
Used Fire X Refurbished	1.00
Pintle Pin W/clip	1.00
Tire 35x12.50r17lt	4.00
Caster-camber Bushing	2.00
Caster-camber Bushing	2.00
Shop Supplies	1.00

- Inspect and service winch .
- Shop Supplies

Hours: 11.80 Comm: 0.00 Labor: 861.40 Parts: 1,933.08 Total: 2,794.48

2/1/2024
3:55:38 PM

Palm Beach County Fleet Management Asset Maintenance History
10198475 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 2103858

Meter: 53462

In Date: 04/06/2021 **Closed:** 04/26/2021

Problem: asset number 10198475? It's making a grinding noise in the rear area.

Work Completed

- Flushed/removed Sand From Front Differential Housing Removed Pinion Gear, Ring Gear, Seals And Replaced New Bearings, Seals Pinion & Ring Gear, New Wheel Hubs
- R&r Rear Axle Seals & O-rings Flushed Rear Differential Filled To Spec
- Shop Supplies

Parts Issued

Quantity

Big G Degreaser 1 Gal	1.00
75w140 Ford Axle Lube	4.00
Non-chlor Brake Clnr	2.00
Cup	2.00
Bearing	2.00
Ring & Pinion Kit	1.00
Hub Beringn	2.00
Seal	2.00
Front Inner Diff Seal	2.00
Left Axle Out Seal	2.00
Left Axle Seal	2.00
Rear Axle Nut	2.00
Nut	1.00
Axle O Ring	2.00
Seal	2.00
Px Grey Rtv Silicone	1.00
Non-chlor Brake Clnr	2.00
75w140 Ford Axle Lube	4.00
Shop Supplies	1.00

Hours: 14.30

Comm: 0.00

Labor: 1,043.90

Parts: 2,441.95

Total: 3,485.85

2/1/2024
3:55:38 PM

Palm Beach County Fleet Management Asset Maintenance History
10198475 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 2106793 **Meter:** 55705 **In Date:** 06/22/2021 **Closed:** 06/30/2021

Problem: P.M. service and check engine light is on and power steering inop .

Work Completed

- P.m. service.
- Complaint Of No Power Steering No Visual Defects Power Steering Works If Reving . Perform Power Steering Pressure Test . R&r Power Steering Pump. Bleed System And Retest .
- Check Engine Light On Code P06b6 Misfire Cylinder 4 . Tune Up . Replace All Sixteen Spark Plugs . Clear Codes And Retest .
- Rotate And Balance Tires With Nitro Fill
- Check and service winches
- Shop Supplies

Parts Issued

Quantity

Used Fire X Refurbished	1.00
Napagold Oil Filter	1.00
5w20 Engine Oil	8.00
Napagold Air Filter	1.00
oil auto	2.00
Power Steering Pump	1.00
Espak Plug Wire	2.00
Coil	2.00
Espak Plug Wire	2.00
Coil	2.00
Spark Plug	16.00
Intake Cleaner Kit	1.00
Motor Tune-up 16oz	1.00
22" Wiper Blade	2.00
Shop Supplies	1.00

Hours: 14.40

Comm: 0.00

Labor: 1,051.20

Parts: 1,346.70

Total: 2,397.90

2/1/2024
3:55:38 PM

Palm Beach County Fleet Management Asset Maintenance History
10198475 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 2108993 **Meter:** 56639 **In Date:** 08/19/2021 **Closed:** 08/25/2021
Problem: Brakes locking up, bad smell

Work Completed

- Front Left Break Pads Worn And Burnt Rotors Unable To Cut Due To Low Thickness R&r Front Brake Pads , Rotors, Calipers, And Hoses
- Complaint Of Breaks Locking Up. Computer Diagnose Abs . Inspected Left Front Wheel Abs Sensor Pinched
- Inspected Front Differential Found Water In Pan, Remove Pan Clean And Install Pan, Fill To Spec
- Shop Supplies

Parts Issued

Quantity

Brk Fluid Dot 4-32oz	1.00
Non-chlor Brake Clnr	2.00
Reman/ca	1.00
Reman/ca	1.00
Front Brake Pad	1.00
Px Grey Rtv Silicone	1.00
Napa Gear 80w-90 Qt	4.00
Non-chlor Brake Clnr	1.00
Front Rotor Assy	2.00
Brake Hose	1.00
Brake Hose	1.00
Abs Sensor	1.00
Shop Supplies	1.00

Hours: 8.00

Comm: 0.00

Labor: 584.00

Parts: 699.90

Total: 1,283.90

Work Order: 2109103 **Meter:** 56570 **In Date:** 08/19/2021 **Closed:** 08/23/2021
Problem: Run Rough

Work Completed

- Tow From: Frenchmen Forest off Prosperity Frms n of Pbg w/sid To: Lv shop

Hours: 0.00

Comm: 90.40

Labor: 0.00

Parts: 0.00

Total: 90.40

2/1/2024
3:55:39 PM

Palm Beach County Fleet Management Asset Maintenance History
10198475 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 2111044 **Meter:** 58496 **In Date:** 10/13/2021 **Closed:** 10/28/2021

Problem: It has a oil change light on, check gas cap light on and has an exhaust leak noise.

Work Completed

Parts Issued

Quantity

- Computer diagnose loose cap warning , code P0457 . Perform evap test .
- Purge valve stuck open . R&r defective purge valve and retest and clear code
- Diagnose exhaust leak , smoke exhaust system to locate leak . R&r cracked left exhaust manifold and studs and gaskets . retest
- Shop Supplies

Valva Asy	1.00
Nut	2.00
Manifold	1.00
Bolt	2.00
Nut	8.00
Stud	8.00
Stud	2.00
Gasket	2.00
Shop Supplies	1.00

Hours: 4.50

Comm: 0.00

Labor: 328.50 Parts: 245.12 Total: 573.62

Work Order: 2202403 **Meter:** 62233 **In Date:** 03/03/2022 **Closed:** 03/10/2022

Problem: PM Service. 4x4 inop .

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Perform battery Analyzing Charging & load test, failed. R & I new battery
- Rotate and speed balance all 4 tires , nitro fill
- Check circuit to right head light, inop. R & I new bulb
- Inspect and service winches
- Check and inspect locking front Hub, will not lock, Clean and R & I new lock hub. Inspect and service Front diff
- Shop Supplies

Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
5w20 Engine Oil	8.00
Napagold Oil Filter	1.00
Battery	1.00
Boxed Capsules	1.00
Px Grey Rtv Silicone	1.00
Syn Gear Oil 75w90 Qt	3.00
Air Tool Lube 16oz	1.00
Link Asm	1.00
Shop Supplies	1.00

Hours: 10.00

Comm: 0.00

Labor: 730.00 Parts: 366.55 Total: 1,096.55

2/1/2024
3:55:39 PM

Palm Beach County Fleet Management Asset Maintenance History
10198475 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 2208944

Meter: 67171

In Date: 08/25/2022 **Closed:** 09/08/2022

Problem: PM Service and A/c not cold, washer inop , trailer light inop ,winch inop tires

Work Completed

- Preventive Maint. Service
- R & I both washer nozzles, broken
- Inspect all, R & I two new tires on front, speed balance all 4 ,nitro fill
- Inspect and service winches, Repair wiring at winches controller asm.winches inop
- Inspect all brakes, R & I rear brakes, Resurface both rotors, service rear caliper slide pins, bleed brakes
- R & I new trailer connector and rewire as needed and replace pintle pin
- Check both front axle locker, inop, R & I two front axle locker assembly
- Check noise at front, R & I new belt and tensioner, Pressure test cooling system. leaking radiator, R & I new radiator assembly Replace upper and lower hose
- A/c performance test, Evacuate & ckeck refrigerant level normal, in spec. Recharge and check pressures High/ Low normal, no fault found at this time
- Shop Supplies

Parts Issued

Quantity

Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Napagold Oil Filter	1.00
5w20 Engine Oil	8.00
Used Fire X Refurbished	1.00
Napagold Air Filter	1.00
Washer Jet	2.00
Non-chlor Brake Clnr	1.00
Pintle Pin W/clip	1.00
trailer plug	1.00
Brake Pads	1.00
Link Asm	2.00
V Belt	1.00
Tensioner	1.00
Coolent	2.00
Radiator	1.00
Tire 35x12.50r17 Roadian Mtx	2.00
Hose Rad	1.00
Upper Hose	1.00
Shop Supplies	1.00

Hours: 22.20

Comm: 0.00

Labor: 1,620.60

Parts: 1,936.11

Total: 3,556.71

2/1/2024
3:55:39 PM

Palm Beach County Fleet Management Asset Maintenance History
10198475 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 2301078 **Meter:** 71951 **In Date:** 02/01/2023 **Closed:** 02/23/2023
Problem: PM Service and 4X4 inop and traction light on

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Road Test And Inspect 4x4 Inop. Inspect And Found Front Axels Worn And Leaking Oil. R&r Both Front Axels With New Seals And Hub Locks. Clean Front Differential Due To Water And Sand Inside. Reseal Differential Cover And Refill, Repair Complete.
- R&r Both Rear Axel Seals And Hub Seals Leaking Oil And Cleaned Away Sand And Oil. Cleaned Rear Differential Reseal Cover And Refill With Gear Oil. Road Test To Verify Repair.
- Mount Two New Tires, Rotate And Balance Four. Relearn Tire Sensors.
- Inspect And Service Front Power Winch.
- R&r Worn Rear Emergency Brakes, Clean And Adjust. Readjusted Bent Rear Brake Backing Plate Rubbing Against Rotors. Road Test To Verify Repair Complete.
- Shop Supplies

5w20 Engine Oil	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Napagold Oil Filter	1.00
Px Grey Rtv Silicone	1.00
Napa Gear 80w-90 Qt	3.00
Shaft Front	1.00
Axle Shaft L/f	1.00
Link Asm	2.00
Left Axle Out Seal	2.00
Front Inner Diff Seal	2.00
Friction Modifier	2.00
75w140 Ford Axle Lube	4.00
Px Grey Rtv Silicone	1.00
Non-chlor Brake Clnr	2.00
Left Axle Seal	2.00
Seal	2.00
Axle O Ring	2.00
Tire 35x12.50r17 Roadian Mtx	2.00
Napa Quart 5w20	7.00
Brake Shoes Park	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 21.00

Comm: 0.00

Labor: 1,533.00

Parts: 2,331.60

Total: 3,864.60

2/1/2024
3:55:39 PM

Palm Beach County Fleet Management Asset Maintenance History
10198475 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 2304776 **Meter:** 73817 **In Date:** 05/12/2023 **Closed:** 05/17/2023
Problem: passenger rear tire flat

Work Completed

- check ,sop and replaced right rear
- Shop Supplies

Parts Issued

Quantity

Tire 35x12.50r17 Roadian Mtx	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 0.50 Comm: 0.00 Labor: 36.50 Parts: 407.50 Total: 444.00

Work Order: 2305331 **Meter:** 73950 **In Date:** 05/11/2023 **Closed:** 05/30/2023
Problem: passenger rear tire flat

Work Completed

- Tow From: indiantown rd, 2 Mi east of Pratt whittney, E boun To: 2601 Vista Pkwy, West Palm Beach 33411

Hours: 0.00 Comm: 124.30 Labor: 0.00 Parts: 0.00 Total: 124.30

2/1/2024
3:55:39 PM

Palm Beach County Fleet Management Asset Maintenance History
10198475 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 2308194 **Meter:** 76147 **In Date:** 08/16/2023 **Closed:** 08/31/2023
Problem: PM Service , A/C warm and left front speaker inop , console ok

Work Completed

- Preventive Maint. Service. Inspect Front Speaker For Concern But It Is Ok At This Time..console Over Full
- Check A/c Performance And Pressures For Insufficient Cooling. Added Dye And Inspect For Leaks But No Leaks Detected And Cooling At This Time.
- Drain And Refill Front Differential Due To Water Contamination From Broken Venthose. R&r Front Differential Vent Hose.
- R&r Two Worn Front Body Mounts.
- Inspect And Service Front Power Winch.
- Rotate And Balance Four Tires. Relearn Tire Sensors.
- R&r Left Rear Axel Seal Leaking Oil. Clean Off Oil Leak And Top Off Gear Oil.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Steering Wheel Cover Large	1.00
Big G Degreaser 1 Gal	1.00
Freon Lv Shop 1	2.00
Ac Uv Dye 5 Shot	1.00
Red Angel Ac Stop Lk	1.00
Fuel Line Hose	4.00
Non-chlor Brake Clnr	1.00
Px Grey Rtv Silicone	1.00
Napa Gear 80w-90 Qt	4.00
Body Mount Kit	2.00
Non-chlor Brake Clnr	2.00
Axle O Ring	1.00
Seal	1.00
Shop Supplies	1.00

Hours: 13.50 Comm: 0.00

Labor: 985.50 Parts: 368.35 Total: 1,353.85

Work Order: 2310802 **Meter:** 77753 **In Date:** 10/26/2023 **Closed:** 10/26/2023
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00

Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 266.90

Total Labor: 18,306.40

Total Comm: 1,246.65

Total Parts: 22,546.63