#### Palm Beach County Fleet Management Asset Maintenance History 10198477 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Total Hours: 215.30 Labor: 14,757.20 Parts: 13,411.26 Comm: 675.94 Charged: 28844.40

Work Order: 1508306 Meter: 389 In Date: 08/19/2015 Closed: 08/19/2015

Problem: 1061 - Pre Delivery Inspection

**Work Completed** 

- Pre Delivery Inspection

- Minor weld repair or machining

Hours: 3.00 Comm: 0.00 Labor: 180.00 Parts: 0.00 Total: 180.00

Work Order: 1600081 Meter: 3645 In Date: 01/05/2016 Closed: 01/27/2016

Problem: Pm service.

Work Completed		Parts Issued	Quantity
- P.m. Service.		Napagold Oil Filter	1.00
- Rotate and balance all tires.		5w20 Engine Oil	7.00
- Inspect and service winch.		Washer Fluid Concentr	1.00
- Shop Supplies		Macs Chain Cable Lube	1.00
		F75z6730ba Drain Plug	1.00
		Shop Supplies	1.00
Hours: 6.00	Comm: 0.00	Labor: 360.00 Parts: 39.68	Total: 399.68

# Palm Beach County Fleet Management Asset Maintenance History 10198477 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 1610399 Meter: 9983 In Date: 10/04/2016 Closed: 10/31/2016

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. Service.		5w20 Engine Oil		7.00
- Inspect and service front differential.		Napagold Oil Filte	r	1.00
- Replace one defective Tpms sensor,rotate and balance all	l four tires.	Napagold Air Filte	er	1.00
- Inspect and service winch.		Used Fire X Refurb	pished	1.00
- Transport vehicle to dealer for leaking left rear axle seal.		Dickie Floor Mat B	lk	1.00
- Shop Supplies		Stg Wheel Cov - Fe	ord	1.00
		Washer Fluid Cond	centr	1.00
		Mac Wite Lithium	Gres	1.00
		Wd40 Spr		1.00
		75w140 Ford Axle	Lube	3.00
		Non-chlor Brake C	Clnr	1.00
		Ptex Ultra Grey 3o.	Z	1.00
		Tpms12 Sensor Tir	re Pr	1.00
		Shop Supplies		1.00
Hours: 9.50	Comm: 0.00	Labor: 570.00	Parts: 288.16	Total: 858.16

Work Order: 1703536 Meter: 14166 In Date: 04/10/2017 Closed: 05/11/2017

**Problem:** P.M. service and towed in smoking.

Work Completed		Parts Issued		Quantity
- P.m. service.		Real Brake Pad		1.00
- Installed new pindle pin.		Fuse Relocate Kit		1.00
- Check and replacerear brake pads,parking brake shoes.resurface rear		5w20 Engine Oil		8.00
rotors, service calipers, bleed system and road test .		Napagold Oil Filte	r	1.00
- Balance and totate all four tires.		22" Wiper Blade		2.00
- Transport to and from dealer for short block and intake	replacement.	Non-chlor Brake C	Inr	1.00
- Shop Supplies		Pintle Pin W/clip		1.00
		Brake Shoes Park		1.00
		Shop Supplies		1.00
Hours: 12.50	Comm: 0.00	Labor: 750.00	Parts: 200.00	Total: 950.00

#### Palm Beach County Fleet Management Asset Maintenance History 10198477 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 1703563 Meter: 14024 In Date: 04/07/2017 Closed: 04/10/2017

Problem: leaking Oil and PM service

#### **Work Completed**

- Tow From: Corner of 45th and Military Trail To: lv shop

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 1708974 Meter: 18762 In Date: 09/19/2017 Closed: 09/21/2017

Problem: Won't start.

# Work CompletedParts IssuedQuantity- Diagnoise no start,dead battery.charge battery.will not hold charge,failed<br/>load test.replace battery,check starting and charging system,,good.no draw.Battery 65<br/>Shop Supplies1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 156.59 Total: 216.59

Work Order: 1709393 Meter: 18762 In Date: 09/27/2017 Closed: 10/11/2017

**Problem:** P.M. service and check tires.

Work Completed		Parts Issued		Quantity
- P.m. service.	m. service.			7.00
- Inspect and replace four worn tires.perform hi	gh speed balance all four	Napagold Oil Filte	r	1.00
nitro fill all.	-	22" Wiper Blade		2.00
- Inspect all brakes .worn fronts .r&i front brakes .resurface both rotors and	Washer Fluid Cond	centr	1.00	
service calipers and new pads .road test.		Used Fire X Refurb	pished	1.00
	nspect and service winch binding.water intrusion.dissasseble and clean d lube all gears.replace shredded cable with new.	Napagold Air Filter  35x12.5r17 Nitto Grap  Brake Pad  Non-chlor Brake Clnr  Napagold Oil Filter  Napagold Air Filter  Rep/rope  Shop Supplies		1.00
				4.00
- Perform complete front end alignment.road to	est.			1.00
- Shop Supplies				1.00
				1.00
				1.00
				1.00
				1.00
		Tire Disposal Fee		4.00
Hours: 16.50	Comm: 0.00	Labor: 990.00	Parts: 2,372.59	Total: 3,362.5

#### Palm Beach County Fleet Management Asset Maintenance History 10198477 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 1804346 Meter: 22685 In Date: 04/26/2018 Closed: 05/04/2018

**Problem:** P.M. service.

Hours: 12.40

Work Completed	Parts Issued	Quantity
- P.m. service. Replace missing antenna.	Set Lug Kit	1.00
- Remove and replace broken winch assembly and rewire .test operation.	Warn Vr12 Winch	1.00
Weld all anchor bolts.	5w20 Engine Oil	7.00
- Replace leaking valve stem in left front wheel .rotate and balance all four tires.nitrgen fill tires.	Napagold Oil Filter	1.00
	Napagold Air Filter	1.00
- Remove and replace two stripped wheel studs on right front hub.replace lug nuts.	Washer Fluid Concentr	1.00
	22" Wiper Blade	2.00
- Shop Supplies	Tire Pressure Monitoring System Sensor (	1.00
	Bolt Wheel	2.00
	Antenna	1.00
	Shop Supplies	1.00

Labor: 744.00

Parts: 1,182.52

Total: 1,926.52

Comm: 0.00

#### Palm Beach County Fleet Management Asset Maintenance History 10198477 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 1810969 Meter: 26591 In Date: 10/24/2018 Closed: 11/06/2018

Problem: P.M. service.

Work	Comp	leted
------	------	-------

- P.m. service.
- Perform tune up for arcing coils . Replace number one and two coils . Replace all eight spark plug wires and sixteen spark plugs . Retest.
- Service and inspect front differential, due to water contamination.
- Service and inspect rear differential, due to water contamination.
- Replace both rear rotors , pads ,parking brake shoes and hub oil seals . Flush and bleed brake system and road test.
- Inspect and service winch.
- Rotate and balance all four tires. Nitrofill all.
- Shop Supplies

Parts Issued	Quantity
Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Ptex Ultra Grey 3oz	2.00
Napa Gear 80w-90 Qt	3.00
Friction Modifier	2.00
75w140 Ford Axle Lube	4.00
Non-chlor Brake Clnr	1.00
Seal	2.00
B Fluid Dot 3-32oz	2.00
Brake Shoes Park	1.00
Real Brake Pad	1.00
Brake Frotor	2.00
Coil	2.00
Espak Plug Wire	4.00
Spark Plug	16.00
Espak Plug Wire	4.00
Shop Supplies	1.00
Labor: 1.306.50 Parts: 1.251.80	Total: 2.558.30

Hours: 19.50 Comm: 0.00 Labor: 1,306.50 Parts: 1,251.80 Total: 2,558.30

Hours: 0.00

# Palm Beach County Fleet Management Asset Maintenance History 10198477 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: Problem:	1904446 P.M. Service.	Meter: 29520		In Date:	04/24/2019	Closed:	05/13/2019
Work Com	pleted		Parts Issued			Qı	ıantity
- P.m. servi	ce.		Napagold Oil Filter				1.00
- Diagnose	play in steering . Remove after	market steering bracket to	5w20 Engine Oil				7.00
•	ctor nut . Repostion aftermarket	shock bracket rubbing against	22" Wiper Blade				2.00
, ,	eeve . Retest .		Washer Fluid Concer	ntr			1.00
•	nd service winch .		Used Fire X Refurbish	hed			1.00
	nd balance all four tires . Nitrofill	all.	Ford Triton Pvc Swc				1.00
- Shop Sup	pplies		Shop Supplies				1.00
	Hours: 7.50	Comm: 0.00	Labor: 502.50	Parts: 64.	29	Total:	566.79
Work Order: Problem:	1908200 Dead battery.	<b>Meter:</b> 30969		In Date:	08/07/2019	Closed:	08/08/2019
Work Com	pleted		Parts Issued			Qı	ıantity
- Recahrge	battery and test system.battery	failed load test.replace defective	Battery 65				1.00
battery.	, , ,	•	Shop Supplies				1.00
- Shop Sup	pplies						
	Hours: 1.00	Comm: 0.00	Labor: 67.00	Parts: 179	9.69	Total:	246.69
Work Order: Problem:	1908216 no run	Meter: 30960		In Date:	08/07/2019	Closed:	08/07/2019
Work Com	pleted						
- Tow From	n: 2300 vista 4th floor						

Comm: 96.00

Labor: 0.00

Parts: 0.00

Total: 96.00

#### Palm Beach County Fleet Management Asset Maintenance History 10198477 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 1911544 Meter: 32499 In Date: 11/06/2019 Closed: 11/14/2019

Problem: P.M. Service.Radio/clock inop.

Work Completed		<b>Parts Issued</b>		Quantity
- P.m. service . Check radio and clock all working good at this time .		Napagold Oil Filter		1.00
- Rotate and high speed balance all four tires . Nitrofill all.		5w20 Engine Oil		7.00
- Inspect and service winch .		Washer Fluid Cond	centr	1.00
- Shop Supplies		22" Wiper Blade		2.00
		Mac Wite Lithium Gres  Macs Chain Cable Lube  Napagold Air Filter		1.00
				1.00
				1.00
		Used Fire X Refurb	pished	1.00
		Shop Supplies		1.00
Hours: 6.00 Co	mm: 0.00	Labor: 438.00	Parts: 79.44	Total: 517.44

Work Order: 2004557 Meter: 35186 In Date: 05/06/2020 Closed: 05/14/2020

Problem: P.M. Service.

Ork Completed		Parts Issued		Quantity
- P.m. service.	m. service.			7.00
- Test and replace defective trailer plug connector and retest . Rewie as		Napagold Oil Filter		1.00
needed.		Washer Fluid Conc	entr	1.00
- Computer diagnose no oil pressure on dash . Perform pinpoint test . Replace defective leaking oil pressure sending unit . Retest .		22" Wiper Blade		2.00
		trailer plug		1.00
- Inspect and service winch .		Engine Oil Pressure	e Switch	1.00
- Rotate and balance all four tires . Nitrofill all.		Shop Supplies		1.00
- Shop Supplies				
Hours: 9.00 Co	omm: 0.00	Labor: 657.00	Parts: 53.59	Total: 710.59

#### Palm Beach County Fleet Management Asset Maintenance History 10198477 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 2008781 Meter: 37495 In Date: 09/01/2020 Closed: 09/02/2020

**Problem:** Check engine light on and check washer fluid.

Work CompletedParts IssuedQuantity- Computer diagnose check engine light , Code P06b6 . Perform pinpointShop Supplies1.00

test . Clear codes and road test . System ok at this time . Fill washer fluid .

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 4.00 Total: 77.00

Work Order: 2011112 Meter: 38845 In Date: 11/03/2020 Closed: 11/24/2020

Problem: PM Service - Please check tires and radio. Thank you

Work Completed		Parts Issued		Quantity
- performed pm service		5w20 Engine Oil		7.00
- check,replaced all 4 tires and balance . Nitro fill a	all	Napagold Oil Filte	r	1.00
- check ,performed pin point test electrical system	,removed defective radio	22" Wiper Blade		2.00
assembly send for repair then reinstalled and verify			pished	1.00
- check and performed transfer case flid service		oil auto		2.00
- Inspect and service front differential		Non-chlor Brake C	Inr	1.00
- inspect and service winch		1qt Syngear Oil 75-90		3.00
- completed front end alignment and road test		Px Grey Rtv Silicone		2.00
- Shop Supplies		35x12.50r/17/10 Tire Terrain T/a		4.00
		Radio		1.00
		Shop Supplies		1.00
		Tire Disposal Fee		4.00
Hours: 13.50	Comm: 0.00	Labor: 985.50	Parts: 2,619.74	Total: 3,605.24

Work Order: 2101602 Meter: 40985 In Date: 02/11/2021 Closed: 02/16/2021

**Problem:** Rear passage side - Light bulb is out. Thank you

Work Completed		Parts Issued		Quantity		
- Test and replace right brake light bulb . Retest .		Boxed Miniatures		1.00		
Hours: 0.50	Comm: 0.00	Labor: 36.50	Parts: 0.77	Total: 37.27		

Palm Beach County Fleet Management Asset Maintenance History 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4 10198477

Work Order: 2102293

Meter: 41938

In Date:

03/01/2021 **Closed:** 03/01/2021

Problem: Towed in driver rear flat

**Work Completed Parts Issued**  Quantity

- Repair left rear tire and balance . Nitro fill all.

**Shop Supplies** 

1.00

- Shop Supplies

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 4.00

Total: 77.00

Work Order: 2102353

Meter: 42095

In Date:

03/01/2021 **Closed:** 03/02/2021

Problem: driver rear flat

**Work Completed** 

- Tow From: Lake Worth Rd, just E of 95 To: vista

Hours: 0.00

Comm: 96.00

Labor: 0.00

Parts: 0.00

Total: 96.00

#### Palm Beach County Fleet Management Asset Maintenance History 10198477 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 2104097 Meter: 44213 In Date: 04/12/2021 Closed: 04/29/2021

**Problem:** pm service and check engine light on .

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	Napagold Oil Filter	1.00
- Computer Diag Check Engine Light Perform Full Tune Up P0306 P0316	5w20 Engine Oil	8.00
P06b6 . Replace all sixteen spark plugs and wire set and six coils .	22" Wiper Blade	2.00
- Remove Defective Pinin Bearing & Rebuild With New Seals And Bearings	Lubricant	1.00
Flush Differentail Housing	Coil	1.00
- Remove Rear Differential Cover And Inspect Fluid Drain & Flush With New Fluid	Espak Plug Wire	4.00
- Inspect & Service Winch	Espak Plug Wire	4.00
- Perform Fuel Injection Cleaner and clean and decarb air intake system .	Coil	4.00
Clean throttle body.	Spark Plug	16.00
- Shop Supplies	Non-chlor Brake Clnr	1.00
	Friction Modifier	2.00
	75w140 Ford Axle Lube	4.00
	Clip	2.00
	Motor Tune-up 16oz	1.00
	Intake Cleaner Kit	1.00
	White Mp Grs Cart	1.00
	Non-chlor Brake Clnr	2.00
	Px Grey Rtv Silicone	1.00
	75w140 Ford Axle Lube	3.00
	Ring & Dinion Kit	1.00
	Left Axle Out Seal	2.00
	Front Inner Diff Seal	2.00
	Left Axle Seal	2.00

Hours: 23.60 Comm: 0.00 Labor: 1,722.80 Parts: 2,305.41 Total: 4,028.21

**Shop Supplies** 

1.00

#### Palm Beach County Fleet Management Asset Maintenance History 10198477 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 2109355 Meter: 49973 In Date: 08/27/2021 **Closed**: 09/20/2021 Problem: PM Service. Winch is not working. Parts Issued Quantity **Work Completed** Napagold Oil Filter 1.00 - Preventive Maint, Service 5w20 Engine Oil 8.00 - Missing Winch Chain Inspected Winch For Operation Install New Winch Chain Washer Fluid Concentr 1.00 - Checked Charging System And Load Tested Battery, Battery Failed Load 22" Wiper Blade 2.00 Test R&r Battery 1.00 Battery - Inspect Front Brakes Replace Brake Pads, Resurface Rotors And Brake Hose 1.00 Remeasure, Replace Calipers And Bleed System Brake Hose 1.00 - Rotate And Balance All Tires With Nitro Fill 1.00 Reman/ca - Front Differentail Pan Leaking Remove Pan, Drain, Clean And Reseal Reman/ca 1.00 - Operated Window Washer No Fluid Coming Out Tested Pump Tested Bad Front Brake Pad 1.00 R&r Washer Pump And Retest Gear Oil 3.00 - Shop Supplies Permatex 1.00 Washer Pump 1.00 Washer Pump 1.00 Winch Cable Fabrication 1.00 3/8 Clevis Slip Hook 1.00 **Shop Supplies** 1.00 Hours: 14.50 Comm: 0.00 Parts: 903.88 Labor: 1,058.50 Total: 1,962.38

Work Order: 2113610 Meter: 52991 In Date: 12/28/2021 Closed: 01/04/2022

Problem: broken winch

Work Completed		Parts Issued		Quantity
- Perform electrical diagnostic winches solenoid inop .check for shorted circuit, R $\&$ I three new solenoids $\&$ test . service winch		Repl Solenoid Term Up		3.00
		Shop Supplies		1.00
- Shop Supplies				
Hours: 3.00	Comm: 0.00	Labor: 219.00	Parts: 72.91	Total: 291.91

# Palm Beach County Fleet Management Asset Maintenance History 10198477 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 2202254 Meter: 54402 In Date: 02/28/2022 Closed: 03/07/2022

Problem: PM Service.

Work Completed		Parts Issued		Quantity					
<ul> <li>Preventive Maint. Service</li> <li>Rotate and speed balance, nitro fill, Repair one tire valve sensor</li> <li>Check all brakes, R &amp; I new rear brakes, resurface both rotors, service caliper slide pins, Clean debris/mud from caliper area, Road test</li> </ul>		Washer Fluid Concentr		1.00					
		22" Wiper Blade Napagold Oil Filter 5w20 Engine Oil		2.00 1.00 8.00					
					- Shop Supplies		Napagold Air Filter		1.00
							Tire Pressure Mon	itoring System Sensor (	1.00
	Non-chlor Brake C	Inr	1.00						
	Brk Fluid Dot 4-12	loz	1.00						
	Real Brake Pad		1.00						
	oil auto		1.00						
	Shop Supplies		1.00						
Hours: 11.00	Comm: 0.00	Labor: 803.00	Parts: 121.86	Total: 924.86					

Work Order: 2205899 Meter: 56410 In Date: 06/02/2022 Closed: 06/03/2022

Problem: Hitch Locking Pin. Also raise hitch on plate.

Work Completed		Parts Issued		Quantity
- Adjust hitch height and install locking hitch pin .		Hitch Pin Lock		1.00
- Shop Supplies		Shop Supplies		1.00
Hours: 0.80	Comm: 0.00	Labor: 58.40	Parts: 14.78	Total: 73.18

## Palm Beach County Fleet Management Asset Maintenance History 10198477 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 2209540 Meter: 58360 In Date: 09/13/2022 Closed: 09/26/2022

Problem: PM Service.

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napagold Oil Filte	r	1.00
- Inspect And Service Power Winch Stuck. R&r Winch To Clean Gears And Lubricate Due To Water Intrusion. Verified Repair Is Complete. Respool Ca		5w20 Engine Oil		7.00
		Washer Fluid Cond	centr	1.00
- Rotate And Balance Four Tires.	22" Wiper Blade		2.00	
- Road Test And Felt Steering Not Centered. Co	mplete Front End Alignment	Steering Wheel Cover Large		1.00
And Road Test To Verify Repair Complete.  - R&r Siezed Right Front Hublock, Clean And Lubricate Axel Splines. Verified Repair Complete.		Used Fire X Refurb	oished	1.00
		Pedal Pad		1.00
		Drain Plug		1.00
- Shop Supplies		Link Asm		1.00
		Pedal Pad		1.00
		Shop Supplies		1.00
Hours: 13.00	Comm: 0.00	Labor: 949.00	Parts: 215.79	Total: 1,164.79

Problem: PM Service.

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napagold Oil Filter		1.00
- Rotated and balanced all 4 tires. Nitrogen fill	ed all tires.	Napa Quart 5w20		8.00
- Battery tested bad. Charged battery fully and retested bad. Replaced bac		22" Wiper Blade		2.00
battery.	·	Mac Wite Lithium (	Gres	1.00
- Diagnose noise in front. Found to have worn	9	Battery		1.00
- Serviced front diff due to water intrusion. Replaced damaged vent tubing.		Hub Beringn		1.00
		Link Asm		2.00
		Fuel Line Hose		4.00
- Diagnose winch inop. Removed winch, clean connections. Reinstalled winch. Inspect and ser	Non-chlor Brake Cl	nr	2.00	
- Shop Supplies		Permatex		1.00
		Napa Gear 80w-90	Qt	3.00
		Shop Supplies		1.00
Hours: 14.50	Comm: 0.00	Labor: 1,058.50	Parts: 927.31	Total: 1,985.8

#### Palm Beach County Fleet Management Asset Maintenance History 10198477 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 2305944 Meter: 63349 In Date: 06/14/2023 Closed: 06/20/2023

**Problem:** replace cracked windshields

Work CompletedParts IssuedQuantity- setup repairs & reassetShop Supplies1.00

- Shop Supplies

Hours: 1.00 Comm: 387.94 Labor: 73.00 Parts: 2.65 Total: 463.59

Work Order: 2306033 Meter: 63527 In Date: 06/20/2023 Closed: 06/21/2023

Problem: Brake lights stay on .

 Work Completed
 Parts Issued
 Quantity

 - Test and replace defective brake light switch .
 Switch
 1.00

 - Shop Supplies
 Shop Supplies
 1.00

 Hours: 0.80
 Comm: 0.00
 Labor: 58.40
 Parts: 46.36
 Total: 104.76

Work Order: 2309320 Meter: 65584 In Date: 09/13/2023 Closed: 10/03/2023

Problem: PM Service

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	Napagold Oil Filter	1.00
- Rotate and speed balance, nitro fill	5w20 Engine Oil	8.00
- Inspect and service winches	Washer Fluid Concentr	1.00
- Check suspension, leaking front Shocks, R & i two new shocks, Fabrica	e 22" Wiper Blade	2.00
and cut rusty left front shock ,	Excel-g Shock	2.00
- Inspect and service winches, inoperable Check eletrical circuit and sole	noid Used Fire X Refurbished	1.00
shorted, R & i electrical solenoid box, install another to operate motor binding water intrusion, R & i motor clutch gears, drain water and clean	Pro-comp Shock	2.00
lube all gears, reset	Shop Supplies	1.00
- Shop Supplies		
Hours: 11.20 Comm: 0.00	Labor: 817.60 Parts: 30	03.49 Total: 1,121.09

Work Order: 2311408 Meter: 65987 In Date: 11/15/2023 Closed: 11/15/2023

**Problem:** Transition Prep Charge

## **Work Completed**

- Transition Prep Charge

## Palm Beach County Fleet Management Asset Maintenance History 10198477 2015 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 215.30 Total Labor: 14,757.20 Total Comm: 675.94 Total Parts: 13,411.26