Palm Beach County Fleet Management Asset Maintenance History 10198305 2015 FORD F350 Utility Body, 13,700 Gvwr

Total Hours: 190.25 Labor: 12,980.25 Parts: 9,291.63 Comm: 388.31 Charged: 22660.19

Work Order: 1509142 Meter: 323 In Date: 09/11/2015 Closed: 09/11/2015

Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 3.00 Comm: 0.00 Labor: 180.00 Parts: 0.00 Total: 180.00

Work Order: 1603267 Meter: 6713 In Date: 03/29/2016 Closed: 04/06/2016

Problem: P.M. Service.Install power inverter

Work Completed		Parts Issued	Quantity
- P.m. Service.		Vinyl Electrical Tape	1.00
- Install power inverter.fabricate and i	nstall wiring.	Friction Modifier	1.00
- Rotate and balance all tires.	-	Napagold Oil Filter	1.00
- Shop Supplies		5w20 Engine Oil	7.00
		22" Wiper Blade	2.00
		Mac Wite Lithium Gres	1.00
		Cpi 1575 Inverter 1500 W	1.00
		Cb185-100 Cir Brkr	1.00
		Cabl/lug	5.00
		Terminal	2.00
		Bulk Battery Cable	10.00
		Bulk Battery Cable	10.00
		Fab Loom-split Poly	9.00
		Shop Supplies	1.00
Hours: 9.50	Comm: 0.00	Labor: 570.00 Part	ts: 352.96 Total: 922.96

Palm Beach County Fleet Management Asset Maintenance History 10198305 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 1606408 Meter: 9005 In Date: 06/23/2016 Closed: 06/27/2016

Problem: Right front tire flat.

Work CompletedParts IssuedQuantity- Repair and balance right front tire.Shop Supplies1.00- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1610248 Meter: 12062 In Date: 09/29/2016 Closed: 10/24/2016

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. Service.		Napagold Oil Filte	r	1.00
- Test battery and charging system.recharge and retest battery,fo	ail load	22" Wiper Blade		2.00
test.replace defective battery.		Washer Fluid Cond	centr	1.00
- Rotate and balance tires.		Napagold Air Filte	er	1.00
- Shop Supplies		5w20 Engine Oil		8.00
		Battery 65		1.00
		Used Fire X Refurbished		1.00
		Shop Supplies		1.00
Hours: 6.50 Comm	n: 0.00	Labor: 390.00	Parts: 204.37	Total: 594.37

Palm Beach County Fleet Management Asset Maintenance History 10198305 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 1703601 Meter: 17444 In Date: 04/10/2017 Closed: 04/20/2017

Problem: P.M. Service.

Work Completed		Parts Issued		Quantity
- P.m. Service.		5w20 Engine Oil		8.00
- Replace right side tail lamps.		Napagold Oil Filte	r	1.00
- Replace pintle pin.		Used Fire X Refurb	ished	1.00
- Replace and balance six new tires.		22" Wiper Blade		2.00
- Complete wheel alignment.test drive.		4 Led S T T Lamp		2.00
- Shop Supplies		Pintle Pin W/clip		1.00
		179636492 Lt245-	75r17	6.00
		Floor Mat-2pc Rub Bk Stg Wheel Cov - Ford		1.00
				1.00
		Shop Supplies		1.00
		Tire Disposal Fee		6.00
Hours: 10.75	Comm: 0.00	Labor: 645.00	Parts: 1,678.88	Total: 2,323.88

Work Order: 1707975 Meter: 23027 In Date: 08/14/2017 Closed: 08/28/2017

Problem: PM Service

Work Completed		Parts Issued		Quantity
- Pm Service.		Napagold Oil Filte	er	1.00
- Rotate and balance six tires.		Napa Quart 5w20		8.00
- Lube rear leaf springs and contact points and tigl	hten shackles.	Napagold Air Filte	er	1.00
- Shop Supplies		Drain Plug		1.00
		22" Wiper Blade		2.00
		Washer Fluid Cond	centr	1.00
		Shop Supplies		1.00
Hours: 7.25	Comm: 0.00	Labor: 435.00	Parts: 56.80	Total: 491.80

Palm Beach County Fleet Management Asset Maintenance History 10198305 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 1800991 Meter: 27777 In Date: 01/26/2018 Closed: 01/31/2018

Problem: Has to jump start all the time.Bad battery.

Work CompletedParts IssuedQuantity- Test starting and charging system with Rotunda tester.battery failed load
test after recharge.aces code Hd6jg . Dtc code 948 M4q.replace bad battery.Battery 651.00Shop Supplies1.00

- Shop Supplies

Hours: 0.75 Comm: 0.00 Labor: 45.00 Parts: 159.74 Total: 204.74

Problem: PM Service

Work Completed		Parts Issued		Quantity
- Pm Service		Napagold Oil Filter		1.00
- Service roof rack.		Napa Quart 5w20		8.00
- Rotate and balance 6 tires.		22" Wiper Blade		2.00
- Shop Supplies		Washer Fluid Cond	1.00	
		Shop Supplies		1.00
Hours: 6.50	Comm: 0.00	Labor: 390.00	Parts: 45.31	Total: 435.31

Work Order: 1805657 Meter: 32331 In Date: 06/04/2018 Closed: 06/12/2018

Problem: Left tail lamp inop

Work Completed		Parts Issued		Quantity
- Diagnose and repaired for left tail la	amp inop.replace Led lamp and pigtail.	Led Adapter Plug		1.00
- Shop Supplies		Led Sup Mdl 44 4	2 Dio	1.00
		Shop Supplies		1.00
Hours: 1.00	Comm: 0.00	Labor: 60.00	Parts: 70.25	Total: 130.25

Palm Beach County Fleet Management Asset Maintenance History 10198305 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 1806855 Meter: 33322 In Date: 07/03/2018 Closed: 07/23/2018

Problem: P.M.SERVICE, LIGHT BAR ONE SIDE NOT WORKING

 - Pm Service. - Replace pintle pin. - Tighten body mount bolts and paint bracket. - Replace defective power control switch box for light bar. - Rotate and balance tires. 	Napa Quart 5w20 Napagold Oil Filter Washer Fluid Concentr 22" Wiper Blade Napagold Air Filter	8.00 1.00 1.00 2.00 1.00
- Tighten body mount bolts and paint bracket Replace defective power control switch box for light bar.	Washer Fluid Concentr 22" Wiper Blade	1.00 2.00
- Replace defective power control switch box for light bar.	22" Wiper Blade	2.00
·	<u>'</u>	
- Rotate and balance tires.	Napagold Air Filter	1.00
		1.00
- Service ladder rack.	Used Fire X Refurbished	1.00
- Shop Supplies	Pintle Pin W/clip	1.00
	Glos Blk	2.00
	Pawer Control Boss	1.00
	Shop Supplies	1.00
	Freight Charge	1.00
Hours: 9.75 Comm: 0.00	Labor: 585.00 Parts: 276.90	Total: 861.90

Work Order: 1812482 Meter: 37948 In Date: 12/07/2018 Closed: 12/19/2018

Problem: PM Service

Work Completed		Parts Issued		Quantity
- Pm Service.		Napagold Oil Filter		1.00
- Mount and balance 6 tires.		Napa Quart 5w20		8.00
- Replace front and rear brake pads.service rotors and calipers.lu	ubed slides	Napagold Air Filter		1.00
and mounting pins.bleed system.		Washer Fluid Conce	entr	1.00
an debris from radiator and ac condenser(clogged)		22" Wiper Blade	2.00	
- Shop Supplies		179636492 Lt245-7	6.00	
		Real Brake Pad		1.00
		Front Brake Pad		1.00
		Shop Supplies		1.00
		Tire Disposal Fee		6.00
Hours: 17.75 Comn	n: 0.00	Labor: 1,189.25	Parts: 2,295.36	Total: 3,484.61

Palm Beach County Fleet Management Asset Maintenance History 10198305 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 1906199 Meter: 44653 In Date: 06/12/2019 Closed: 06/26/2019

Problem: PM Service.Check engine light on.

Work Completed		Parts Issued		Quantity
- Pm Service		Napa Quart 5w20		8.00
- Replace steering wheel cover.		Napagold Oil Filte	r	1.00
- Replace 6 way trailer socket and wiring harness.		Wd40 Spr		1.00
- Rotate and balance 6 tires.replace one bent valve ste	m.	Napagold Air Filte	er	1.00
- Secure and fabricate bracket to frame for pipe rack a	ssembly.	Used Fire X Refurb	pished	1.00
- Computer diagnose for check engine light on.code P	06b6.clear code and	22" Wiper Blade		2.00
reprogram Pcm with updated clibration#fc-12a650-bcc		Washer Fluid Cond	centr	1.00
- Shop Supplies		Ford Triton Pvc Sw	/C	1.00
		trailer plug		1.00
		Shop Supplies		1.00
Hours: 12.25	Comm: 0.00	Labor: 820.75	Parts: 110.58	Total: 931.33

Work Order: 1912715 Meter: 48420 In Date: 12/11/2019 Closed: 12/16/2019

Problem: Power outlets inop.

Work Completed		Parts Issued	Quantity	
Diagnose for power dutiets inopitest und repair willing und replace open		Bp Fmx-Ip F Mx Fuse		1.00
		Shop Supplies		1.00
- Shop Supplies				
Hours: 2.50	Comm: 0.00	Labor: 182.50	Parts: 8.71	Total: 191.21

Palm Beach County Fleet Management Asset Maintenance History 10198305 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: Problem:	2001298 P.M.SERVICE,CHECK ENGIN	Meter: 50068 E LIGHT STAYS ON.		In Date:	02/06/2020	Closed:	03/23/2020
Work Com	pleted		Parts Issued			Qı	uantity
- Pm Servi	ce.		Napagold Oil Filter				1.00
- Jump sta	rt vehicle in Wud parking lottes	st and replace battery.	Napa Quart 5w20				8.00
- Replace	- Replace 6 way socket and repaired wiring harness.		Washer Fluid Concer	ntr			1.00
- Rotate and balance 6 tires Wash engine compartment.		22" Wiper Blade				2.00	
		Napagold Air Filter				1.00	
 Transport vehicle to and from dealer for replacing left exhaust manifold and Pcm under factory warranty. Computer diagnose for check engine light on and noise after start up in 		Battery				1.00	
		Vinyl Electrical Tape				1.00	
		trailer plug				1.00	
	bad Pcm and crack left exhaust	manifold.	Shop Supplies				1.00
- Shop Տսլ	oplies Hours: 13.75	Comm: 0.00	Labor: 1,003.75	Parts: 217	7.29	Total:	1,221.04
Work Order: Problem:	2004949 Hitch loose and noisy.	Meter: 51741		In Date:	05/15/2020	Closed:	05/26/2020
Work Com	pleted		Parts Issued			Qı	uantity
- Fabricate	repair and service loose hitch to	o body.	Shop Supplies				1.00
- Shop Su	pplies						
	Hours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 4.0	0	Total:	150.00
Work Order: Problem:	2007232 Check engine light on.Broken v	Meter: 53372 wiper blades.		In Date:	07/23/2020	Closed:	08/17/2020
Work Com	pleted		Parts Issued			Qı	uantity
- Diagnose	e for check engine light on.remo	ve and clean trottle body and air	Throttle Body Cleane	er			1.00
	codes and test drive.	·	22" Wiper Blade				2.00
- Replace	oroken wiper blades.		Shop Supplies				1.00
- Shop Su	oplies						
	•						

Hours: 1.00

Palm Beach County Fleet Management Asset Maintenance History 10198305 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: Problem:	2010087 PM Service.	Meter:	55280		In Date:	10/06/2020	Closed:	10/28/2020
Work Com	pleted			Parts Issued			Qı	uantity
- Pm Servi	ce.			Used Fire X Refurbi	shed			1.00
- Mount ar	nd balance six new tires.			Napa Quart 5w20				8.00
- Replace e	engine oil drain plug.clean thread	s in oil pan w	ith chaser tap	Napagold Oil Filter				1.00
- Replace s	ix way socket and repaired wiring	harness.		Napagold Air Filter				1.00
- Disassem	ble vise to repaired and replace k	oroken parts.ı	einstall to bumper.	Washer Fluid Conce	entr			1.00
- Clean en	gine compartment.			22" Wiper Blade				2.00
- Fabricate	drain holes in pipe rack to drain	properly.		Drain Plug				1.00
- Service w	inch in back of bed.			trailer plug				1.00
- Adjust ta	ilgate to close properly.			179636492 Lt245-7	5r17			6.00
- Replace o	alstart decal and reflective sticke	rs.		Shop Supplies				1.00
- Shop Sup	pplies			Tire Disposal Fee				6.00
	Hours: 14.50		Comm: 0.00	Labor: 1,058.50	Parts: 1,4	22.48	Total:	2,480.98
Work Order: Problem:	2011221 Driver side mirror broken	Meter:	55575		In Date:	11/06/2020	Closed:	11/19/2020
Work Com	pleted			Parts Issued			Qı	uantity
- R/r driver	· side mirror.			Mirror Assembly				1.00
- Shop Sup	pplies			Shop Supplies				1.00
	Hours: 1.25		Comm: 0.00	Labor: 91.25	Parts: 234	4.55	Total:	325.80
Work Order: Problem:	2102362 replace chipped windshield	Meter:	58698		In Date:	03/02/2021	Closed:	03/04/2021
Work Com	pleted			Parts Issued			Qı	uantity
- set up re	pairs & reasset			Shop Supplies				1.00
- Shop Sup								

Comm: 388.31

Labor: 73.00

Parts: 4.00

Total: 465.31

Palm Beach County Fleet Management Asset Maintenance History 10198305 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 2102817 Meter: 58951 In Date: 03/12/2021 Closed: 03/25/2021

Problem: PM

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napa Quart 5w20		8.00
- Replaced Worn Decals		Napagold Oil Filte	r	1.00
- Rotate Balance 6 Tires		22" Wiper Blade		2.00
- Clean Debris From Engine Compartment		Shop Supplies		1.00
- Shop Supplies				
Hours: 6.25	Comm: 0.00	Labor: 456.25	Parts: 48.93	Total: 505.18

Work Order: 2110200 Meter: 62287 In Date: 09/21/2021 Closed: 09/30/2021

Problem: PM Service.

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napagold Oil Filte	1.00	
- Fill all tires with nitrogen, balance & rotate.	Napa Quart 5w20 Washer Fluid Concentr 22" Wiper Blade Used Fire X Refurbished Napagold Air Filter 13 Oz Aero Kroil		8.00 1.00 2.00 1.00	
- Service pipe rack.				
- Scan and found code #b1d09, repair trailer connector &				
- Shop Supplies				
			1.00	
			1.00	
		Shop Supplies		1.00
Hours: 8.00	Comm: 0.00	Labor: 584.00	Parts: 80.41	Total: 664.41

Palm Beach County Fleet Management Asset Maintenance History 10198305 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 2204888 Meter: 64845 In Date: 05/05/2022 Closed: 05/19/2022

Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Replaced Front Brake Pads Service Calipers Rotors Slides And Repacked Front Bearings
- Replaced Worn Steering Wheel Cover And Brake Pedal Pad. Replaced worn asset numbers on front and rear
- Replaced #3 Id Led Lamp and repaired wiring
- Replaced Corodded 6 Way Socket And Repaired Wiring
- Tune Up Replaced Arcing #5 #6 #1#2 Coils , Removed Broken Coil Boots In Plug Tubes To Replace 16 Spark Plugs.and Plug Wires
- R&r Throttle Body For Servicing And Flush Intake System. Fuel system service
- Rotate Balanced 6 Tires
- Shop Supplies

Parts Issued	Quantity
Used Fire X Refurbished	1.00
Drain Plug	1.00
Napa Quart 5w20	8.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Napagold Air Filter	1.00
Non-chlor Brake Clnr	2.00
Wheel Seal - Front Wheel	2.00
Front Brake Pad	1.00
Steering Wheel Cover Large	1.00
Pedal Pad	1.00
Lamp-grommet Kit	1.00
trailer plug	1.00
Espak Plug Wire	4.00
Espak Plug Wire	4.00
Spark Plug	16.00
Coil	2.00
Intake Cleaner Kit	1.00
Coil	2.00
Shop Supplies	1.00
Labor: 1,259.25 Parts: 854.39	Total: 2,113.6

Hours: 17.25 Comm: 0.00

Palm Beach County Fleet Management Asset Maintenance History 10198305 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 2207547 Meter: 65964 In Date: 07/19/2022 Closed: 08/03/2022

Problem: A/C

Work Completed		Parts Issued		Quantity
- Recharged And Test Ac System .evac.to Replace Leaking Eva	ng Evap Core W/h	Freon Sr Shop		4.00
Block, Condenser W/drier ,seals/o'rings And Both Service Valve	e Cores	A/c Valve		1.00
Recharged Test For Leaks Again To Verify Repairs. Test Drive to	o verify fix.	Ac Valve Core Hig	h	1.00
- Shop Supplies		Seal Kits		4.00
		Kit O		1.00
		Condenser Evaporator Core		1.00
				1.00
		E8 A/c Oil Univ W	Dye	1.00
		Shop Supplies		1.00
Hours: 12.00 Cor	mm: 0.00	Labor: 876.00	Parts: 667.15	Total: 1,543.15

Work Order: 2211786 Meter: 66699 In Date: 11/21/2022 Closed: 12/09/2022

Problem: PM Service.

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napagold Oil Filter		1.00
- rotate balanced 6 tires		Grommet Mount Kit		1.00
- replaced one id led lamp		Napa Quart 5w20		7.00
- Shop Supplies		Washer Fluid Cond	centr	1.00
		22" Wiper Blade		2.00
		Shop Supplies		1.00
Hours: 6.00	Comm: 0.00	Labor: 438.00	Parts: 57.41	Total: 495.41

Palm Beach County Fleet Management Asset Maintenance History 10198305 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 2302557 Meter: 66886 In Date: 03/14/2023 Closed: 03/16/2023

Problem: PM Service. Has to jump start all the time.

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napagold Oil Filter		1.00
- recharged and tested battery replaced failed battery		Motor Oil		7.00
- rotate balanced 6 tires		Washer Fluid Concentr		1.00
- Shop Supplies		22" Wiper Blade		2.00
		Used Fire X Refurb	pished	1.00
		Battery		1.00
		Shop Supplies		1.00
Hours: 6.50	Comm: 0.00	Labor: 474.50	Parts: 220.43	Total: 694.93

Work Order: 2309515 Meter: 68497 In Date: 09/19/2023 Closed: 10/02/2023

Problem: Dead Battery. PM.

Work Completed	Parts Issued	Quantity
- Battery Dead. Jump start and move to shop to charge battery. Battery	Battery	1.00
failed load test. Replace battery under warranty.	Shop Supplies	1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 127.97 Total: 200.97

Work Order: 2310035 Meter: 68685 In Date: 10/02/2023 Closed: 10/10/2023

Problem: PM Service.

Work Completed	Parts Issued		Quantity	
- Preventive Maint. Service	Napagold Oil Filter			1.00
- Replace & rewire rear center marker light.	Napa Quart 5w20		7.00	
- Roof Rack had multiple loose bolts. Go over roof rack and ve	Washer Fluid Concentr		1.00	
truck properly. - Fill all tires with nitrogen, balance, rotate & reset Tpms.		22" Wiper Blade Napagold Air Filter Lamp-grommet Kit		2.00
				1.00
				1.00
		Shop Supplies		1.00
Hours: 7.00 Com	nm: 0.00	Labor: 511.00	Parts: 72.76	Total: 583.76

Palm Beach County Fleet Management Asset Maintenance History 10198305 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 2311472 Meter: 68685 In Date: 11/16/2023 Closed: 11/16/2023

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 190.25 Total Labor: 12,980.25 Total Comm: 388.31 Total Parts: 9,291.63