Palm Beach County Fleet Management Asset Maintenance History 10198308 2015 FORD F350 Utility Body, 13,700 Gvwr

Total Hours: 172.15 Labor: 11,789.95 Parts: 9,537.25 Comm: 192.00 Charged: 21519.20

Work Order: 1509468 Meter: 316 In Date: 09/18/2015 Closed: 09/18/2015

Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 4.00 Comm: 0.00 Labor: 240.00 Parts: 0.00 Total: 240.00

Problem: Has to jump start over week end. Rides like there is no shocks.

Work Completed Parts Issued Quantity

- Fully recharge then test battery and charging system.fuond draw due to one of two way radio harness plug disconnected.connect harness plug and

recheck.ok

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

Shop Supplies

1.00

Work Order: 1603111 Meter: 5030 In Date: 03/23/2016 Closed: 03/31/2016

Problem: Pm service.

Work Complete	d		Parts Issued	Quantity
- Pm service.			5w20 Engine Oil	7.00
- Inspect and ser	rvice power tailgate.		Napagold Oil Filter	1.00
- Rotate and bal	ance all six tires.		Washer Fluid Concentr	1.00
- Shop Supplies			Shop Supplies	1.00
	Hours: 6.50	Comm: 0.00	Labor: 390.00 Parts: 21.7	76 Total: 411.76

Palm Beach County Fleet Management Asset Maintenance History 10198308 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 1606871 Meter: 8025 In Date: 07/07/2016 Closed: 07/25/2016

Problem: Install power inverter in left front utility bin.

Work Completed	Parts Issued		Quantity
- Install inverter in first bin on left side of truck.fabricate and install wir	ng. Bat/cabl		20.00
- Shop Supplies	Bulk Battery Cable		3.00
	Cb185-150 Cir Brkr		1.00
	Terminal		2.00
	Cobra Inverter		1.00
	Fab/loom		20.00
	Shop Supplies		1.00
Hours: 4.00 Comm: 0.00	Labor: 240.00	Parts: 407.93	Total: 647.93

Work Order: 1610454 Meter: 10314 In Date: 10/11/2016 Closed: 10/19/2016

Problem: P.M. service install floor mats and steering wheel cover.

Work Completed		Parts Issued		Quantity
- P.m. Service.		5w20 Engine Oil		7.00
- Replace both tail lights.		Napagold Oil Filter		1.00
- Inspect and service liftgate.		Used Fire X Refurb	oished	1.00
- Rotate and balance all six tires.		22" Wiper Blade		2.00
- Shop Supplies		Dickie Floor Mat Blk		1.00
		Stg Wheel Cov - F	ord	1.00
		4 Led S T T Lamp		2.00
		Shop Supplies		1.00
Hours: 7.00	Comm: 0.00	Labor: 420.00	Parts: 139.60	Total: 559.60

Work Order: 1703284 Meter: 14137 In Date: 04/03/2017 Closed: 04/10/2017

Problem: Left rear outter tire going flat.

Work Completed	Parts Issued	Quantity
- Repair and balance left rear outer tire.	Shop Supplies	1.00
- Shop Supplies		

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

Palm Beach County Fleet Management Asset Maintenance History 10198308 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 1703615 Meter: 14307 In Date: 04/10/2017 Closed: 04/18/2017

Problem: P.M. Servic3e.

Work Completed		Parts Issued		Quantity
- P.m. Service.		Napagold Oil Filter		1.00
- Adjust front wheel bearing.		5w20 Engine Oil		7.00
- Rotate and balance all six tires.		22" Wiper Blade		2.00
Inspect and service rear lift gate.Shop Supplies		Washer Fluid Concentr Napagold Air Filter		1.00
				1.00
		Shop Supplies		1.00
Hours: 7.00	Comm: 0.00	Labor: 420.00	Parts: 38.24	Total: 458.24

Work Order: 1709748 Meter: 19076 In Date: 10/04/2017 Closed: 10/31/2017

Problem: P.M. service and Inverter inop and right front tire going flat.

Work Completed		Parts Issued		Quantity
- P.m. service.		5w20 Engine Oil		7.00
- Inspect and replace two worn tires on front .rotate and high	Napagold Oil Filter	r	1.00	
all six wheels.nitro fill all .repair right rear inner tire.		22" Wiper Blade		2.00
- Perform eletrical charging and starting test.load test battery	Washer Fluid Concentr		1.00	
load test, no drain, alternator output 162 amps. r&i new battery.		Wd40 Spr		1.00
- Perform complete front end alignment.road test.	Mac Wite Lithium Gres		1.00	
- Transport to and from dealer for transmission fluid leak fron	179636492 Lt245-	75r17	2.00	
seal.		Battery 65		1.00
- Shop Supplies		Shop Supplies		1.00
		Tire Disposal Fee		2.00
Hours: 12.50 Cor	mm: 0.00	Labor: 750.00	Parts: 640.14	Total: 1,390.14

Palm Beach County Fleet Management Asset Maintenance History 2015 FORD F350 Utility Body, 13,700 Gvwr 10198308

Work Order: 1805863 Meter: 25960 In Date: 06/07/2018 **Closed**: 06/14/2018

Problem: PM Service

Work Completed		Parts Issued		Quantity
- P.m. Service.		Napagold Oil Filte	r	1.00
- Replace four tires,rotate and balance all six.		5w20 Engine Oil		7.00
- Inspect and service liftgate.		22" Wiper Blade		2.00
- Shop Supplies		Washer Fluid Concentr		1.00
		Used Fire X Refurb	oished	1.00
		179636492 Lt245-	75r17	4.00
		Shop Supplies		1.00
Hours: 8.00	Comm: 0.00	Labor: 480.00	Parts: 920.69	Total: 1,400.69

Work Order: 1810419 Meter: 28768 **In Date:** 10/10/2018 **Closed:** 10/11/2018

Problem: Right rear outer tire flat.

Work Completed Parts Issued Quantity **Shop Supplies** - Repair right rear outer tire and balance . Nitrogen fill tires. 1.00 - Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 67.00 Parts: 3.00 Total: 70.00 Work Order: 1812705

In Date: 12/13/2018 **Closed:** 12/26/2018

Meter: 30178

Problem: P.M. service and detail.

Work Completed Parts Issued		Quantity		
- P.m. service Rotate and balance all six tires . Nitrofill all.		Napagold Oil Filte	r	1.00
		Napa Quart 5w20		7.00
- Inspect and service power liftgate .		Napagold Air Filter		1.00
- Shop Supplies		Used Fire X Refurbished		1.00
		22" Wiper Blade		2.00
		Shop Supplies		1.00
Hours: 6.50	Comm: 0.00	Labor: 435.50	Parts: 65.55	Total: 501.05

Palm Beach County Fleet Management Asset Maintenance History 10198308 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 1812975 Meter: 30030 In Date: 12/21/2018 Closed: 12/21/2018

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 1907835 Meter: 36282 In Date: 07/29/2019 Closed: 08/08/2019

Problem: PM Service

Work Completed	Parts Issued		Quantity
- P.m. Service.	Napagold Oil Filte	r	1.00
- Resurface front brake rotors, replace pads. service and lube calipers. flush	5w20 Engine Oil		8.00
and bleed system.	22" Wiper Blade		2.00
- Inspect and service liftgate.	Washer Fluid Cond	entr	1.00
- Rotate and balance all six tires.	Front Brake Pad		1.00
- Shop Supplies	Non-chlor Brake Clnr		1.00
	B Fluid Dot 3-32oz		1.00
	Shop Supplies		1.00
Hours: 11.50 Comm: 0.00	Labor: 770.50	Parts: 167.60	Total: 938.10

Work Order: 1909572 Meter: 37948 In Date: 09/17/2019 Closed: 10/07/2019

Problem: Install arrow board.

Work Completed		Parts Issued		Quantity
- Fabericate and install new arrow board and controller .		Fuse Holder		1.00
- Shop Supplies		Primary Wire		5.00
		Primary Wire Large Led Arrow Board		5.00 1.00
		Shop Supplies		1.00
		Freight Charge		1.00
Hours: 6.00	Comm: 0.00	Labor: 438.00	Parts: 1,967.48	Total: 2,405.48

Palm Beach County Fleet Management Asset Maintenance History 10198308 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 1910133 Meter: 37947 In Date: 10/01/2019 Closed: 10/08/2019

Problem: fabricate light brks

Work Completed		Parts Issued		Quantity	
- Fabricate, weld and install mounting fram for arrow board		3/16 Plate 4' X 8'		1.00	
- Shop Supplies		Shop Supplies		1.00	
Но	urs: 7.00	Comm: 0.00	Labor: 511.00	Parts: 449.50	Total: 960.50

Work Order: 1910581 Meter: 38145 In Date: 10/15/2019 Closed: 10/21/2019

Problem: Check battery.L/R tire has nail.

Work Completed	Parts Issued	Quantity
- Charge battery fully . Test battery and charging system . Battery failed load	Battery 65	1.00
test . R&r defective battery . No draws detected.	Shop Supplies	1.00

- Repair left rear tire and balance . Nitrofill all.

- Shop Supplies

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 180.69 Total: 326.69

Work Order: 2002635 Meter: 42465 In Date: 03/16/2020 Closed: 03/19/2020

Problem: P.M. service.

Work Completed	P	arts Issued		Quantity
- P.m. service.	Ν	lapagold Oil Filter		1.00
 Test and replace tag light assemblies and rewire. Test and replace defective right alley light switch. Rotate and balance all four tires. Nitrofill all. Inspect and service power liftgate. 		5w20 Engine Oil		8.00
		lapagold Air Filte	r	1.00
		Washer Fluid Concentr 22" Wiper Blade		1.00 2.00
Т	1.00			
R	1.00			
N	2.00			
		hop Supplies		1.00
Hours: 7.75 Comr	n: 0.00 L	abor: 565.75	Parts: 88.66	Total: 654.41

Palm Beach County Fleet Management Asset Maintenance History 10198308 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 2008432 Meter: 46945 In Date: 08/25/2020 Closed: 09/29/2020

Problem: P.M. service ,strobes and arrow board inop,right front tire flat and detail .

Work Completed	Parts Issued	Quantity
- P.m. service.	5w20 Engine Oil	8.00
- Diagnose strobe light and arrow board inop . Replace harness and	I inline Napagold Oil Filter	1.00
fuse holder and retest .	22" Wiper Blade	2.00
- Computer diagnose engine misfire . Perform complete tune up . R	, , , , , , , , , , , , , , , , , , , ,	6.00
all sixteen spark plugs, wire set and two right side coils . Clear codes retest .	and Primary Wire	6.00
	Clear Vinyl Tubing	6.00
- Perform complete air intake decarb and cleaning . Flush injectors .	Espak Plug Wire	4.00
- Repair right front tire . Rotate and balance all six tires . Nitrofill all.	Espak Plug Wire	4.00
- Transport to and from dealerfor rear end noise .	Spark Plug	16.00
- Shop Supplies	Coil	2.00
	Motor Tune-up 16oz	1.00
	Intake Cleaner Kit	1.00
	Aerokroil 13oz	1.00
	Fuse Holder	1.00
	Shop Supplies	1.00
Hours: 17.60 Comm: 0.	00 Labor: 1,284.80 Parts: 615.49	Total: 1,900.29

Work Order: 2009750 Meter: 46931 In Date: 09/28/2020 Closed: 09/28/2020

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Palm Beach County Fleet Management Asset Maintenance History 10198308 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 2104176 Meter: 51827 In Date: 04/13/2021 Closed: 05/05/2021

Problem: P.M. service and power (lift gate) Inop .

Work Completed	Parts Issued		Quantity
- Preventive Maint. Service	Drain Plug		1.00
- replaced all six tires and balance . Nitro fill all.	Napagold Oil Filt	ter	1.00
- check , replaced defective trailer plug connector Fabricated wires as	5w20 Engine Oil		8.00
needed.	22" Wiper Blade		2.00
- check,replaced all six body mounts	Used Fire X Refu	rbished	1.00
- check , , replaced both defective pivot support to platform with bushings,	2 Tr416 Valve Sten	n	6.00
pins by platform assembly then verify normal operation Lube and retest	Lt245/75r17 Mic	h Defend Ltx	6.00
operation.	trailer plug		1.00
- completed front end alignment and road test	Body Mount Kit		4.00
- Shop Supplies	Body Mount Kit		2.00
	Pin Weld		1.00
	Pin Weld		1.00
	Pins		2.00
	Shop Supplies		1.00
	Tire Disposal Fee	1	6.00
	Freight Charge		1.00
Hours: 20.50 Comm: 0.00	Labor: 1,496.50	Parts: 2,589.98	Total: 4,086.4

Work Order: 2111861 Meter: 56494 In Date: 11/02/2021 Closed: 11/09/2021

Problem: PM SERVICE

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	Napagold Oil Filter	1.00
- Rotated and balanced all 6 tires. Nitrogen filled all tires.	5w20 Engine Oil	7.00
- Battery tested bad. Charged battery fully and retested bad. Replaced	pad 22" Wiper Blade	2.00
battery.	Battery	1.00
- Inspect and serviced power tail gate.	Shop Supplies	1.00
- Shop Supplies		
Hours: 7.50 Comm: 0.00	Labor: 547.50 Parts: 165.41	Total: 712.91

Palm Beach County Fleet Management Asset Maintenance History 10198308 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 2203957 Meter: 61525 In Date: 04/12/2022 Closed: 04/18/2022

Problem: PM Service.

Work Completed		Parts Issued		Quantity
 Preventive Maint. Service Rotated and balanced all 6 tires. Nitrogen filled all tires. Inspect and serviced power lift gate. Shop Supplies 		Napagold Oil Filter		1.00
		5w20 Engine Oil 22" Wiper Blade Used Fire X Refurbished Napagold Air Filter		7.00
				2.00
				1.00
				1.00
		Shop Supplies		1.00
Hours: 6.50	Comm: 0.00	Labor: 474.50	Parts: 51.12	Total: 525.62

Work Order: 2208208 Meter: 65226 In Date: 08/08/2022 Closed: 08/10/2022

Problem: STROBE LIGHTS INOP. wipers stay on ,arrow board inop and L/R window leaking

Work Completed		Parts Issued		Quantity
- Hook up Ids to scan for codes . Monitor pids . R&r defective wiper switch		Switch Asy		1.00
stuck on . Retest	·			2.00
Test light bar inop . Replace both burnt inline fuse holders and retest .Water leak test . Remove 3rd brake cover to reseal and retest .Shop Supplies		22" Wiper Blade		2.00
		Permatex		1.00
		Shop Supplies		1.00
Hours: 3.30	Comm: 0.00	Labor: 240.90	Parts: 92.86	Total: 333.76

Work Order: 2210534 Meter: 66439 In Date: 10/13/2022 Closed: 10/19/2022

Problem: PM Service.

Work Completed		Parts Issued	Quantity
- Preventive Maint. Service		Napagold Oil Filter	1.00
- Inspect and service power lift gate		5w20 Engine Oil	7.00
- Rotate and speed balance all six wheels, nitro fill		Washer Fluid Concentr	1.00
- Shop Supplies		22" Wiper Blade	2.00
		Tire Crayon	1.00
		Shop Supplies	1.00
Hours: 6 50	Comm: 0 00	Labor: 474 50 Parts: 38 39	Total: 512.89

Palm Beach County Fleet Management Asset Maintenance History 10198308 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 2304207 Meter: 71484 In Date: 04/27/2023 Closed: 05/04/2023

Problem: PM Service. water leak at left assist handle.

Work Completed		Parts Issued	Quantity
- Preventive Maint. Service		22" Wiper Blade	2.00
- Check and service power lift gate		Washer Fluid Concentr	1.00
- Perform water leak testing Partially remove headliner	to test , water leak	5w20 Engine Oil	7.00
at head liner, over head lighting, R & I 2 lamps. Retest - R & I two new, Rotate and speed balance, nitro fill all Six tires - Inspect all b rakes, R & I new front brakes, Resurface both rotors, R & I both calipers, service caliper slide pins, Bleed flush brake system, Burnish		Napagold Oil Filter	1.00
		Used Fire X Refurbished	1.00
		Roof Lamp Housing	2.00
		Lt245/75r17 Mich Defend Ltx	2.00
- Shop Supplies	Front Brake Pad	1.00	
		Non-chlor Brake Clnr	1.00
		Brake Fl-dot 3-4 32oz	1.00
		Bracketed Caliper	1.00
	Bracketed Caliper	1.00	
		Shop Supplies	1.00
		Tire Disposal Fee	2.00
Hours: 14.50	Comm: 0.00	Labor: 1,058.50 Parts: 886.54	Total: 1,945.04

Work Order: 2308867 Meter: 74811 In Date: 08/31/2023 Closed: 09/07/2023

Problem: Remove inverter from truck to be installed in CA 017330.

Work Completed	Parts Issued	Quantity
- Remove power inverter and wiring and circuit breaker .	Shop Supplies	1.00
- Shop Supplies		

Work Order: 2311405 Meter: 74811 In Date: 11/15/2023 Closed: 11/15/2023

Labor: 73.00

Parts: 2.65

Total: 75.65

Comm: 0.00

Problem: Transition Prep Charge

Hours: 1.00

Work Completed

- Transition Prep Charge

Palm Beach County Fleet Management Asset Maintenance History 10198308 2015 FORD F350 Utility Body, 13,700 Gvwr

Hours: 2.00 C

Comm: 0.00

Labor: 146.00

Parts: 0.00

Total: 146.00

Total Hours: 172.15

Total Labor: 11,789.95

Total Comm: 192.00

Total Parts: 9,537.25