Palm Beach County Fleet Management Asset Maintenance History 10198310 2015 FORD F350 Utility Body, 14,000 Gvwr, 4X4

Total Hours: 174.65 Labor: 11,872.10 Parts: 18,386.89 Comm: 1,426.80 Charged: 31685.79

Work Order: 1511900 Meter: 334 In Date: 11/20/2015 Closed: 11/20/2015

Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 4.00 Comm: 0.00 Labor: 240.00 Parts: 0.00 Total: 240.00

Work Order: 1512190 Meter: 6694 In Date: 12/02/2015 Closed: 04/29/2016

Problem: Install pipe bin,toolbox in truck bed and Spotlight.

Hours: 13.75

Comm: 0.00

Work Completed Quantity **Parts Issued** Golight & Dount Kit 1.00 - Fabricate and install tootbox in truck bed.mount and secure pipe bin on left side of utility box.install spot lamp.fabricate wiring. 1.00 Pole Surface Mount - P.m. Service. 48" Chest Box 1.00 - Fabricate and install trailer plug mounting.rewire plug. 5w20 Engine Oil 7.00 - Rotate and balance all six tires. Napagold Oil Filter 1.00 - Shop Supplies Floor Mat-2pc Rub Bk 1.00 U-bolt 1.00 Carr Bolt 6.00 Carr Bolt 6.00 Fab Loom-split Poly 25.00 **Shop Supplies** 1.00

Labor: 825.00

Parts: 2,186.65

Total: 3,011.65

Palm Beach County Fleet Management Asset Maintenance History 10198310 2015 FORD F350 Utility Body, 14,000 Gvwr, 4X4

Work Order: 1604590 Meter: 7274 In Date: 05/02/2016 Closed: 05/19/2016

Problem: Repair damage to front grill and locate power inverter to inside cab.

Work Completed		Parts Issued		Quantity
- Replace damaged condensor and oower steering oil cool	er.vacuum a/c	Grille		1.00
system and recharge to specs.replace broken grill assemble. - Install on-off switch for power inverter inside cab.fabricate and install wiring. - Shop Supplies		Name Plate		1.00
	Condenser		1.00	
		Seal Kits R134a Lv Shop 2 E8 A/c Oil Univ W Dye Toggle Switch Fab Loom-split Poly Cooler		2.00
				2.00
				1.00
				1.00
				29.00
				1.00
		Shop Supplies		1.00
Hours: 7.00	Comm: 0.00	Labor: 420.00	Parts: 885.41	Total: 1,305.4

Work Order: 1608427 Meter: 11887 In Date: 08/15/2016 Closed: 08/30/2016

Problem: P.M. service and check A/C. and spot light inop.

Work Completed		Parts Issued		Quantity
- P.m. Service.		Napagold Oil Filte	r	1.00
- Rplace two tires,rotate and balance all six.		5w20 Engine Oil		7.00
- Repair spotlight wiring.replace blown fuse.		Napagold Air Filte	er	1.00
- Check a/c system.clean cowl inlet.		22" Wiper Blade		2.00
- Complete wheel alignment.test drive.		Tire		2.00
- Shop Supplies		Used Fire X Refurb	oished	1.00
		Shop Supplies		1.00
		Tire Disposal Fee		2.00
Hours: 11.00	Comm: 0.00	Labor: 660.00	Parts: 573.92	Total: 1,233.9

Palm Beach County Fleet Management Asset Maintenance History 10198310 2015 FORD F350 Utility Body, 14,000 Gvwr, 4X4

Work Order: 1610247 Meter: 14907 09/29/2016 **Closed:** 04/18/2017 In Date: Problem: Check shimmy /vibration in front end. **Work Completed Parts Issued** Quantity **Shop Supplies** 1.00 - Test drive vehicle and varify concern.r&r tires and roadforce and match rebalance all tires. - Shop Supplies Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 2.00 Total: 122.00 Work Order: 1611879 **In Date:** 11/17/2016 **Closed:** 01/03/2017 Meter: 13385 Problem: Spare wheels **Parts Issued** Quantity **Work Completed** Ac3z1015a 8.00 - Mount and balance eight new tires on rims per department request. 179636492 Lt245-75r17 8.00 - Shop Supplies **Shop Supplies** 1.00 Tire Disposal Fee 8.00 Parts: 4,532.64 Hours: 4.00 Comm: 0.00 Labor: 240.00 Total: 4,772.64 Work Order: 1705215 Meter: 15687 In Date: 05/25/2017 **Closed:** 06/02/2017 Problem: P.M. service. Work Completed Darte Issued Quantity

Work Completed		Parts Issued		Quantity
- P.m. service.	5w20 Engine Oil	7.00		
- Replace four worn tireswith new.balance six tire	Napagold Oil Filte	1.00		
- Repair rear vise due to broken spline gear pin a	22" Wiper Blade Washer Fluid Concentr Slip Plate Spray 12oz Tire Shop Supplies		2.00	
Lubricate and replace broken pin Shop Supplies				
			1.00	
			4.00	
			1.00	
		Tire Disposal Fee		4.00
Hours: 7.80	Comm: 0.00	Labor: 468.00	Parts: 1,103.44	Total: 1,571.44

Palm Beach County Fleet Management Asset Maintenance History 10198310 2015 FORD F350 Utility Body, 14,000 Gvwr, 4X4

Work Order: 1808593 Meter: 21358 In Date: 08/21/2018 Closed: 08/30/2018

Problem: P.M. service and noise from brakes.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filter		1.00
battery. - Test and replace both red brake lights .replace blow fuse for cigar lighter .	5w20 Engine Oil		7.00	
	22" Wiper Blade		2.00	
	Washer Fluid Conce	entr	1.00	
Mount fire extguisher bracket .		Used Fire X Refurbished Battery 65		1.00
- Resurface front and rear brake rotors . Service all				1.00
front and rear brake pads . Flush and bleed brake s	Fmx-20lp Fuse		2.00	
- Rotate and high speed balance all six wheels . N	itrofiii aii .	Led Sup Mdl 44 42 Dio B Fluid Dot 3-32oz Non-chlor Brake Clnr Real Brake Pad		2.00
- Shop Supplies				1.00
				1.00
				1.00
	Brake Pad		1.00	
		Shop Supplies		1.00
Hours: 17.80	Comm: 0.00	Labor: 1,068.00	Parts: 540.10	Total: 1,608.10

Problem: 1 - Key(s) issued

Work Completed		Parts Issued		Quantity
- 1 - Key(s) issued		Duplicate Vehicle	Keys	1.00
Hours: 0.30	Comm: 0 00	Labor: 20.10	Parts: 3.00	Total: 23.10

Palm Beach County Fleet Management Asset Maintenance History 10198310 2015 FORD F350 Utility Body, 14,000 Gvwr, 4X4

Work Order: 2000130 Meter: 34926 In Date: 01/06/2020 Closed: 01/16/2020

Problem: P.M. Sdervice.Brakes noisy.

Work Completed		Parts Issued		Quantity
- P.m. service.	5w20 Engine Oil		7.00	
- Test and replace defective back up alarm . Test	Napagold Oil Filte	r	1.00	
overhead light bar . Replace defective switch and	22" Wiper Blade		2.00	
- Replace broken pole for go light .	Used Fire X Refurbished		1.00	
- Test drive for brake noise . Remove rear brake p	Napagold Air Filter		1.00	
rotors . Road test .		oil auto		1.00
- Rotate and balance all four tires . Nitrofill all.	- Rotate and balance all four tires . Nitrofill all.			1.00
- Shop Supplies		Shop Supplies		1.00
Hours: 10.00	Comm: 0.00	Labor: 730.00	Parts: 108.06	Total: 838.06

Work Order: 2001749 Meter: 34926 In Date: 01/15/2020 Closed: 02/20/2020

Problem: damage to frt bumper & valance

Work Completed

- damage to frt bumper & valance

Hours: 0.00 Comm: 1,059.60 Labor: 0.00 Parts: 0.00 Total: 1,059.60

Palm Beach County Fleet Management Asset Maintenance History 10198310 2015 FORD F350 Utility Body, 14,000 Gvwr, 4X4

Work Order: 2006401 Meter: 41234 In Date: 06/29/2020 Closed: 07/07/2020

Problem: P.M. service and dead battery.

Hours: 15.80

Work Completed	Parts Issued	Quantity
- P.m. service.	Napagold Oil Filter	1.00
 Replace broken right front utility bin door strut. Replace missing pintle pin. Charge battery fully. Test battery and charging system .battery failed load test. R&r defective battery. Diagnose go light inop. R&r defectivegolight and rewire as needed. Test and replace defective traffic advisor light switch. Replace defective right marker light bulb. Replace two tires. Rotate and balance all six tires. Nitrofill all. 	5w20 Engine Oil	7.00
	22" Wiper Blade	2.00
	Mac Wite Lithium Gres	1.00
	Support	1.00
	Pintle Pin W/clip	1.00
	Battery 65	1.00
	Rocker Switch	1.00
	Grommet Mount Kit	1.00
- Shop Supplies	Tire	2.00
S. S. P. S. S. P. S. S.	Ford Triton Pvc Swc	1.00
	Brake Pedal Pad	1.00
	Golight Flood Light Kit	1.00
	Electrical Tape	1.00
	Shop Supplies	1.00

Comm: 0.00

Tire Disposal Fee

Labor: 1,153.40

Parts: 2,262.34

2.00

Total: 3,415.74

Palm Beach County Fleet Management Asset Maintenance History 10198310 2015 FORD F350 Utility Body, 14,000 Gvwr, 4X4

Work Order: 2007205 Meter: 43560 07/23/2020 **Closed**: 08/11/2020 In Date: Problem: Towed in for check engine light and said trans slipping. **Parts Issued** Quantity **Work Completed** 2.00 Coil - Computer diagnose check engine light, P0300, p0316, P0307, P0306, P0304 and P0302 . perfrom pinpoint test . Perfrom tune up . Replace all Coil 2.00 sixteen spark plugs and wire set and four coils. Clear codes and retest. Espak Plug Wire 4.00 - Perfrom complete air intake decarb and cleaning . Flush injectors . Espak Plug Wire 4.00 - Computer diagnose returning code P0302 . Perfrom pinpoint test . Replace Spark Plug 16.00 defective power control module . and reprogram to updated calibration . Throttle Body Cleaner 1.00 Retest operation . Road test . Motor Tune-up 16oz 1.00 - Shop Supplies Intake Cleaner Kit 1.00 1.00 Ecm Module Assy **Shop Supplies** 1.00 Hours: 10.30 Comm: 0.00 Labor: 751.90 Parts: 2,038.08 Total: 2,789.98 Work Order: 2007249 Meter: 43558 In Date: 07/23/2020 Closed: 07/24/2020 Problem: tranny slipping, hard to drive. Hood up keys inside

Work Completed

- Tow From: 8100 Forest Hill, Croc

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Palm Beach County Fleet Management Asset Maintenance History 10198310 2015 FORD F350 Utility Body, 14,000 Gvwr, 4X4

Work Order: 2009702 Meter: 45425 In Date: 09/28/2020 Closed: 10/05/2020

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filter		1.00
- Test and replace both Led brake light s .		5w20 Engine Oil		7.00
- Replace two tires . Rotate and balance all six tires . N	itrofill all.	22" Wiper Blade		2.00
- Shop Supplies		Washer Fluid Concer	ntr	1.00
		Used Fire X Refurbisl	hed	1.00
		Stt Lamp		2.00
		Tr416 Valve Stem		2.00
		Tire		2.00
		Shop Supplies		1.00
		Tire Disposal Fee		2.00
Hours: 7.00	Comm: 0.00	Labor: 511.00	Parts: 605.39	Total: 1,116.39

Palm Beach County Fleet Management Asset Maintenance History 10198310 2015 FORD F350 Utility Body, 14,000 Gvwr, 4X4

Work Order: 2104525 Meter: 48995 In Date: 04/23/2021 Closed: 06/01/2021

Problem: PM Service, Nail in left outer tire, Install water tank.

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napagold Oil Filter		1.00
- Fabricate and Install water tank on top of left side pipe b	oin .	5w20 Engine Oil		7.00
- Drain Tranmission & Replace Filter Flush And Test Drive	Recheck Fluid	Napagold Air Filter		1.00
- Remove Rear Differential Cover Drain & Clean Refill And	l Test Drive	Washer Fluid Concent	r	1.00
- Dismount And Mount 2 Front Tires Rotate And Balance	All six tires With	22" Wiper Blade		2.00
Nitro Fill		Trams Filter		1.00
- Shop Supplies		oil auto		21.00
	Px 16br Blk Rtv Silic		1.00	
		1qt Syngear Oil 75-90		5.00
		Non-chlor Brake Clnr		2.00
		Tire		2.00
		Water Tank		1.00
		Lock Cylinder		1.00
		Tank Fitting		1.00
		Shop Supplies		1.00
		Tire Disposal Fee		2.00
Hours: 14.00	Comm: 0.00	Labor: 1,022.00	Parts: 1,232.54	Total: 2,254.54

Problem: PM Service.

Work Completed		Parts Issued		Qı	uantity
- Preventive Maint. Service		Napagold Oil Filter			1.00
- Rotate and speed balance all six wheels, nitro fill		5w20 Engine Oil			7.00
- Check and replace broken pintle pin .		Washer Fluid Conc	entr		1.00
- Shop Supplies		22" Wiper Blade			2.00
		Pintle Pin W/clip			1.00
		Shop Supplies			1.00
Hours: 5.70	Comm: 0.00	Labor: 416.10	Parts: 41.67	Total:	457.77

Palm Beach County Fleet Management Asset Maintenance History 10198310 2015 FORD F350 Utility Body, 14,000 Gvwr, 4X4

Work Order: 2200894 Meter: 52207 In Date: 01/26/2022 Closed: 02/10/2022

Problem: PM Service. Detail

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		22" Wiper Blade		2.00
- Rotate And Balance All 6 Tires With Nitro Fill		Napagold Oil Filte	r	1.00
- Emergency Lights Not Working Verify Power And Ground R	&r Circuit	5w20 Engine Oil		8.00
Board		Used Fire X Refurb	ished	1.00
- Weld Vise Handle		ridgid vise handle		1.00
- Shop Supplies		Tire Crayon		1.00
		I/o Board - Liberty	li	1.00
		Shop Supplies		1.00
		Freight Charge		1.00
Hours: 7.00 Cor	mm: 0.00	Labor: 511.00	Parts: 608.68	Total: 1,119.68

Work Order: 2201559 Meter: 52207 In Date: 02/11/2022 Closed: 02/11/2022

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 90.40 Labor: 0.00 Parts: 0.00 Total: 90.40

Work Order: 2201661 Meter: 52207 In Date: 02/14/2022 Closed: 02/16/2022

Problem: Battery dead needs change

Work Completed		Parts Issued		Quantity	
- Charge battery fully . Test battery and charging system . Battery failed load			Battery		1.00
		Shop Supplies		1.00	
- Shop Supplies					
Н	ours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 144.95	Total: 217.95

Palm Beach County Fleet Management Asset Maintenance History 10198310 2015 FORD F350 Utility Body, 14,000 Gvwr, 4X4

Work Order: 2202708 Meter: 52423 In Date: 03/11/2022 Closed: 03/21/2022

Problem: Invertor is not coming on please fix or replaced. Send for Detail.

Work CompletedParts IssuedQuantity- check ,pin point test,replaced defective power inverter and remote controlCobra Inverter Remote1.00- Shop SuppliesInverter1.00

Shop Supplies 1.00

Hours: 4.00 Comm: 0.00 Labor: 292.00 Parts: 237.26 Total: 529.26

Meter: 52243

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

Work Order: 2202993

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 90.40 Labor: 0.00 Parts: 0.00 Total: 90.40

In Date:

03/17/2022 **Closed**: 03/17/2022

Work Order: 2203218 Meter: 52973 In Date: 03/25/2022 Closed: 03/30/2022

Problem: changed or replace inverter is not working.

Work Completed	Parts Issued	Quantity
- replaces wiper blades - test , pin point test , R&r defective power inverter due over loaded	22" Wiper Blade	2.00
	Inverter	1.00
inverter.	Shop Supplies	1.00

- Shop Supplies

Hours: 1.20 Comm: 0.00 Labor: 87.60 Parts: 213.89 Total: 301.49

Palm Beach County Fleet Management Asset Maintenance History 10198310 2015 FORD F350 Utility Body, 14,000 Gvwr, 4X4

Work Order: 2208807 Meter: 58767 In Date: 08/23/2022 Closed: 08/31/2022

Problem: PM Service. Send for Detail.

Work Completed		Parts Issued		Quantity
- Performed P.m. Service & Inspection		Napagold Oil Filter		1.00
- Passenger Side Rear Inner Tire Has A Nail, Performed F	lat Repair Then	5w20 Engine Oil		8.00
Balance & Rotate All 6 Tires.		Washer Fluid Conce	entr	1.00
- Removed Items Out Of Rear Tool Box Storage Then Re	move Toolbox From	22" Wiper Blade		2.00
Rear Of Vehicle As Per Customer Request.		Big G Degreaser 1 (Sal	1.00
 Front Brakes Below Specs, Removed Front Brake Pads & Calpers, Resurfaced Both Front Brake Rotors, Replaced Both Brake Front Calipers & Pads Then Lubricate Caliper Slides, Test Drove Vehicle And Burnish Brakes. Emergency Light Bar Inop, Dissaseble Light Bar & Check For Power And 	Caliper Washer		2.00	
	Bracketed Caliper		1.00	
	Bracketed Caliper		1.00	
Ground To Main Circuit Board, Found Fusible Wire Shorted, Repair And		Non-chlor Brake Cli	nr	1.00
Check, Alley Lights, Where Reversed, Removed Connectors & Reverse Then Reprogram And Check. - As Per Last Work Order A New Inverter Was Installed, New Remote Was Unavalible, Removed Old Remote And Install Then Fabricate For New Remote.	Brk Fluid Dot 4-320	Z	1.00	
	Brake Pad		1.00	
	Remote Pawer Swi	tch	1.00	
	Body Mount Kit		4.00	
- Removed And Replaced All 6 Cab Mount Bushings.		Body Mount Kit		2.00
- Shop Supplies		Shop Supplies		1.00
Hours: 22.00	Comm: 0.00	Labor: 1,606.00	Parts: 844.49	Total: 2,450.49

Work Order: 2209132 Meter: 58661 In Date: 08/30/2022 Closed: 08/30/2022

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued WO: 2208807 for: Rajin Deoraj

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued Wo: 2208807 for: Rajin Deoraj

Hours: 0.00 Comm: 90.40 Labor: 0.00 Parts: 0.00 Total: 90.40

Palm Beach County Fleet Management Asset Maintenance History 2015 FORD F350 Utility Body, 14,000 Gvwr, 4X4 10198310

Work Order: 2209261 **Meter:** 58768 09/02/2022 **Closed:** 09/06/2022 In Date:

Problem: Dead Battery

Work Completed	Parts Issued	Quantity
- vehicle would not start battery was tested and failed battery was replaced	Battery	1.00
vehicle working as design	Shop Supplies	1.00
- Shon Supplies		

Shop Supplies

Comm: 0.00 Hours: 1.00 Labor: 73.00 Parts: 155.11 Total: 228.11

Work Order: 2305039 Meter: 61250 In Date: 05/22/2023 Closed: 05/25/2023

Problem: PM Service and right rear inner tire flat .

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	Napagold Oil Filter	1.00
- Repair Right Rear Tire Flat, Rotate And Balance Six.	5w20 Engine Oil	7.00
- Shop Supplies	Washer Fluid Concentr	1.00
	22" Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Steering Wheel Cover Large	1.00
	Shop Supplies	1.00
Hours: 6.00 Comm: 0.00	Labor: 438.00 Parts: 67.31	Total: 505.31

Work Order: 2309997 Meter: 62218 09/29/2023 **Closed**: 09/29/2023 In Date:

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Labor: 11,872.10 Total Comm: 1,426.80 **Total Parts: 18,386.89** Total Hours: 174.65