

2/1/2024
3:58:38 PM

Palm Beach County Fleet Management Asset Maintenance History
10196262 2015 FORD F450 Cab & Chassis, 16,500 GVWR, w/Dump Body

Total Hours: 251.00 Labor: 17,563.00 Parts: 17,465.16 Comm: 2,979.40 Charged: 38007.56

Work Order: 1501773 **Meter:** 326 **In Date:** 02/19/2015 **Closed:** 02/19/2015
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 4.00 Comm: 0.00 Labor: 240.00 Parts: 0.00 Total: 240.00

Work Order: 1502041 **Meter:** 329 **In Date:** 02/26/2015 **Closed:** 02/26/2015
Problem: Repair tarp release

Work Completed

- Reattach door holder

Hours: 0.50 Comm: 0.00 Labor: 30.00 Parts: 0.00 Total: 30.00

Work Order: 1509648 **Meter:** 988 **In Date:** 09/24/2015 **Closed:** 09/30/2015
Problem: PM

Work Completed

- Pm
- Add Def
- Test Drive
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	13.00
Napagold Oil Filter	1.00
Fuel Filter Kit	1.00
Air Filter (gold), Air Panel	1.00
Wiper Blade	2.00
Washer Fl	1.00
Used Fire X Refurbished	1.00
Def Quart	2.00
Shop Supplies	1.00

Hours: 5.00 Comm: 0.00 Labor: 300.00 Parts: 199.60 Total: 499.60

2/1/2024
3:58:38 PM

Palm Beach County Fleet Management Asset Maintenance History
10196262 2015 FORD F450 Cab & Chassis, 16,500 GVWR, w/Dump Body

Work Order: 1603718
Problem: PM

Meter: 2279

In Date: 04/08/2016 **Closed:** 04/13/2016

Work Completed

- Pm
- Add Def
- Test Drive
- Replace pindle pin
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	15.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Air Filter (gold), Air Panel	1.00
22" Wiper Blade	1.00
Washer Fluid Concentr	1.00
Def Quart	8.00
Paint Pen - Pellow	1.00
Used Fire X Refurbished	1.00
Pintle Pin W/chain	1.00
Shop Supplies	1.00

Hours: 5.50

Comm: 0.00

Labor: 330.00

Parts: 158.92

Total: 488.92

Work Order: 1608844
Problem: Attach Cable

Meter: 3525

In Date: 08/25/2016 **Closed:** 08/29/2016

Work Completed

- install door latch
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.50

Comm: 0.00

Labor: 90.00

Parts: 2.00

Total: 92.00

2/1/2024
3:58:38 PM

Palm Beach County Fleet Management Asset Maintenance History
10196262 2015 FORD F450 Cab & Chassis, 16,500 GVWR, w/Dump Body

Work Order: 1612878
Problem: PM

Meter: 4373

In Date: 12/15/2016 **Closed:** 01/24/2017

Work Completed

- Pm
- Install hitch pin
- Test drive
- Shop Supplies

Parts Issued

Quantity

Napa Qt 15w40	15.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Air Filter (gold), Air Panel	1.00
Def Bulk Qts	3.00
Wiper Blade	2.00
Washer Fluid Concentr	1.00
Fuel Filter Cap	1.00
sensor	1.00
Pin W/clip 5/8 For Hitch	1.00
2141 Hitch Ball 1in	1.00
Ball Mount 3/4"	1.00
Shop Supplies	1.00

Hours: 5.00

Comm: 0.00

Labor: 300.00

Parts: 241.04

Total: 541.04

Work Order: 1705222
Problem: DEF

Meter: 7310

In Date: 05/26/2017 **Closed:** 05/30/2017

Work Completed

- Def
- Shop Supplies

Parts Issued

Quantity

Def Bulk Qts	15.00
Shop Supplies	1.00

Hours: 0.50

Comm: 0.00

Labor: 30.00

Parts: 24.95

Total: 54.95

2/1/2024
3:58:39 PM

Palm Beach County Fleet Management Asset Maintenance History
10196262 2015 FORD F450 Cab & Chassis, 16,500 GVWR, w/Dump Body

Work Order: 1913104 **Meter:** 19038 **In Date:** 12/27/2019 **Closed:** 01/03/2020
Problem: Tires

Work Completed

Parts Issued

Quantity

- Tire	225/70r19.5fstone	1.00		
- Shop Supplies	Shop Supplies	1.00		
	Tire Disposal Fee	1.00		
Hours: 0.00	Comm: 0.00	Labor: 0.00	Parts: 1,862.42	Total: 1,862.42

Work Order: 2000049 **Meter:** 19228 **In Date:** 01/03/2020 **Closed:** 01/10/2020
Problem: Ck engine light

Work Completed

Parts Issued

Quantity

- Pulled codes P2459 and checked Def	Shop Supplies	1.00		
- Shop Supplies				
Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 4.00	Total: 77.00

Work Order: 2001190 **Meter:** 20067 **In Date:** 02/04/2020 **Closed:** 02/07/2020
Problem: Not starting

Work Completed

Parts Issued

Quantity

- Tested and replaced betteries	Battery 65	2.00		
- To R&b	Shop Supplies	1.00		
- Shop Supplies				
Hours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 357.37	Total: 503.37

2/1/2024
3:58:39 PM

Palm Beach County Fleet Management Asset Maintenance History
10196262 2015 FORD F450 Cab & Chassis, 16,500 GVWR, w/Dump Body

Work Order: 2007833 **Meter:** 25193 **In Date:** 08/10/2020 **Closed:** 08/26/2020
Problem: pm

Work Completed

- pm
- def
- replace hitch pin and tarp
- replace driver ac vent
- water in hyd fluid. remove tank weld repair and reinstall
- tire
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	14.00
Napagold Oil Filter	1.00
Air Filter (gold), Air Panel	1.00
Napagold Fuel Filter	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Blue Df	2.00
Pintle Pin W/clip	1.00
Tarp 84x12	1.00
A/c Vent	1.00
Aw68 Hydro Fluid Hydr	44.00
225/70r19	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 13.50

Comm: 0.00

Labor: 985.50

Parts: 780.66

Total: 1,766.16

Work Order: 2008086 **Meter:** 25127 **In Date:** 08/11/2020 **Closed:** 08/13/2020
Problem: RRO flat

Work Completed

- Tire Service He - Rro flat

Hours: 0.00

Comm: 104.96

Labor: 0.00

Parts: 0.00

Total: 104.96

Work Order: 2011216 **Meter:** 27651 **In Date:** 11/06/2020 **Closed:** 11/10/2020
Problem: Storm Water, Mike rear Lt. tail light is out

Work Completed

- Lighting, Other
- Shop Supplies

Parts Issued

Quantity

Boxed Miniatures	2.00
Shop Supplies	1.00

Hours: 1.50

Comm: 0.00

Labor: 109.50

Parts: 5.53

Total: 115.03

2/1/2024
3:58:39 PM

Palm Beach County Fleet Management Asset Maintenance History
10196262 2015 FORD F450 Cab & Chassis, 16,500 GVWR, w/Dump Body

Work Order: 2011368 **Meter:** 28037 **In Date:** 11/13/2020 **Closed:** 11/18/2020
Problem: Storm Water Mike, issue with A/C

Work Completed

Parts Issued

Quantity

- recharge Freon diagnose system
- test ac system/ test run
- Shop Supplies

Freon He Shop	2.00
Shop Supplies	1.00

Hours: 4.00 Comm: 0.00 Labor: 292.00 Parts: 16.42 Total: 308.42

Work Order: 2011862 **Meter:** 28353 **In Date:** 12/01/2020 **Closed:** 12/07/2020
Problem: Storm Water, truck low on coolant

Work Completed

Parts Issued

Quantity

- Cooling System Add coolant to cooling system do to low level. (for engine side)
- Force regen Performed regen due to soot build up inside Dpf.
- Shop Supplies

Distilled Water 1gal	3.00
Anti Freeze Motorcraft	3.00
Shop Supplies	1.00

Hours: 3.00 Comm: 0.00 Labor: 219.00 Parts: 93.33 Total: 312.33

Work Order: 2012798 **Meter:** 29002 **In Date:** 12/23/2020 **Closed:** 01/05/2021
Problem: DEF

Work Completed

Parts Issued

Quantity

- Add Def Fluid
- Shop Supplies

Blue Df	1.00
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 19.51 Total: 92.51

2/1/2024
3:58:39 PM

Palm Beach County Fleet Management Asset Maintenance History
10196262 2015 FORD F450 Cab & Chassis, 16,500 GVWR, w/Dump Body

Work Order: 2102859 **Meter:** 31149 **In Date:** 03/12/2021 **Closed:** 03/17/2021
Problem: pm

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Tarp rip, Rr tarp
- Water on fuel add Seafoam to rid off water.
- Small ac leak recharge system needs new evaporator
- Check engine light on force regen
- Test runs X2
- Add def
- washer fluid not coming out of sprayers found line cut under fender cover remove cover and fix washer line .
- Shop Supplies

15-40 Oil	15.00
Used Fire X Refurbished	1.00
Air Filter (gold), Air Panel	1.00
Napagold Fuel Filter	1.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Slime Tire Sealant	1.00
Non-chlor Brake Clnr	4.00
Tarp 84x12	1.00
Motor Tune-up 16oz	2.00
Blue Df	1.00
Shop Supplies	1.00

Hours: 12.00 Comm: 0.00 Labor: 876.00 Parts: 305.47 Total: 1,181.47

Work Order: 2104719 **Meter:** 31842 **In Date:** 04/28/2021 **Closed:** 05/05/2021
Problem: Trailer lights

Work Completed

Parts Issued

Quantity

- Lighting, Other Replace multiple shorted out fuses on both fuse boxes.
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 4.00 Total: 150.00

Work Order: 2110446 **Meter:** 36217 **In Date:** 09/28/2021 **Closed:** 09/28/2021
Problem: Dist.3 Robert, needs to raise up the hitch on the truck

Work Completed

Parts Issued

Quantity

- Move hitch to higher position. Install new hardware.
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 2.65 Total: 75.65

Work Order: 2111672 **Meter:** 36532 **In Date:** 10/28/2021 **Closed:** 01/24/2022

2/1/2024
3:58:39 PM

Palm Beach County Fleet Management Asset Maintenance History
10196262 2015 FORD F450 Cab & Chassis, 16,500 GVWR, w/Dump Body

Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Add Def
- A/c System Service
- Peformed Cooling System Service Drain And Refill
- Performed Road Test
- Front Brakes Below Specs
- Rear Brakes Below Specs
- Check Engine Light On
- Brake Fluid Flush
- Cab Mount Bushings Are Disintegrated Need Replacemeant
- Front Shocks Worn
- Rear Shocks Worn Leaking
- Alignment
- To Weber 2xs
- To Al Packer 2xs
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	15.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Air Filter (gold), Air Panel	1.00
Wiper Blade	2.00
Washer Fluid Concentr	1.00
Anti Freeze Motorcraft	6.00
Distilled Water 1gal	1.00
Air Freshener	1.00
Wd40 Spr	1.00
Pm-22-a Additive Dies	1.00
Blue Df	1.00
Distilled Water 1gal	3.00
Silicone Spray 10oz	1.00
Body Mount Kit	4.00
Body Mount Kit	2.00
Shock Absorber Rear	2.00
Insulator	2.00
Front Shock Absorber	2.00
Anti Freeze Motorcraft	6.00
lube	1.00
Brake Caliper	1.00
Brake Caliper	1.00
Brake Rotor Assy	2.00
Ford Original Brake Pads	1.00
Non-chlor Brake Clnr	2.00
B Fluid Dot 3-32oz	3.00
75w140 Ford Axle Lube	1.00
Brake Caliper	1.00

2/1/2024
3:58:39 PM

Palm Beach County Fleet Management Asset Maintenance History
10196262 2015 FORD F450 Cab & Chassis, 16,500 GVWR, w/Dump Body

Parts Issued	Quantity
Brake Caliper	1.00
F81z1001ba Seal Ring	2.00
Napa Oil Seal	2.00
Brake Rotor	2.00
Ford Original Brake Pads	1.00
Shop Supplies	1.00

Hours: 40.50 Comm: 0.00 Labor: 2,956.50 Parts: 2,116.53 Total: 5,073.03

Work Order: 2111862 **Meter:** 36532 **In Date:** 10/29/2021 **Closed:** 11/02/2021
Problem: 6 tires

Work Completed

- Tire Service: He Problem: 6 tires

Hours: 0.00 Comm: 350.27 Labor: 0.00 Parts: 0.00 Total: 350.27

Work Order: 2111865 **Meter:** 36532 **In Date:** 11/02/2021 **Closed:** 11/05/2021
Problem: 6 Tires

Work Completed

- Tire Service: He Problem: 6 Tires

Hours: 0.00 Comm: 1,525.64 Labor: 0.00 Parts: 0.00 Total: 1,525.64

Work Order: 2112609 **Meter:** 36532 **In Date:** 11/30/2021 **Closed:** 03/14/2022
Problem: DPF replacement

Work Completed

- Dpf System
- To Al Packer 2xs
- Shop Supplies

Parts Issued	Quantity
Shop Supplies	1.00

Hours: 4.00 Comm: 180.80 Labor: 292.00 Parts: 2.65 Total: 475.45

Work Order: 2200791 **Meter:** 36532 **In Date:** 01/24/2022 **Closed:**
Problem: dpf codes/outsourced 11/17/21

Work Completed

-

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

2/1/2024
3:58:39 PM

Palm Beach County Fleet Management Asset Maintenance History
10196262 2015 FORD F450 Cab & Chassis, 16,500 GVWR, w/Dump Body

Work Order: 2202923 **Meter:** 36532 **In Date:** 03/17/2022 **Closed:** 03/21/2022
Problem: Dist.3 Lee, truck low on coolant

Work Completed

- Cooling System/ add coolant.

Hours: 0.50 Comm: 0.00 Labor: 36.50 Parts: 0.00 Total: 36.50

Work Order: 2203362 **Meter:** 36758 **In Date:** 03/29/2022 **Closed:** 04/07/2022
Problem: Dist.3 Robert, truck is leaking fluid

Work Completed

- Operator states unit leaking fluid. Found coolant level low. Top off coolant and perform cooling system pressure test. Found faulty lower radiator hose.
- Replace faulty lower hose.
- Cooling system service.
- Left rear inner hub seal blown out. R&r hub seal. Remove Rr axle and retorque axle nut to proper specs. Fill rear differential with fluid.
- Test Run
- Shop Supplies

Parts Issued

Quantity

Hose Made Mako	1.00
Anti Freeze Motorcraft	3.00
Distilled Water 1gal	3.00
Radiator Hose	1.00
Oil Seal	1.00
F81z1001ba Seal Ring	2.00
Axle Seal	2.00
Coolant Cap	1.00
75w140 Ford Axle Lube	6.00
Shop Supplies	1.00

Hours: 8.50 Comm: 0.00 Labor: 620.50 Parts: 605.34 Total: 1,225.84

Work Order: 2206126 **Meter:** 37321 **In Date:** 06/10/2022 **Closed:** 06/13/2022
Problem: Dist.3 Robert, truck has a dead battery it is in roads yard

Work Completed

- No start condition, test batteries and fail load test also leaking. replace both batteries and clean acid from engine compartment
- Jump start Vehicle
- To Roads Lot
- Shop Supplies

Parts Issued

Quantity

Battery	2.00
Shop Supplies	1.00

Hours: 4.00 Comm: 0.00 Labor: 292.00 Parts: 287.24 Total: 579.24

Work Order: 2207517 **Meter:** 37423 **In Date:** 07/19/2022 **Closed:** 10/31/2022
Problem: PM Service. Dist3 Lee, A/C not working

2/1/2024
3:58:39 PM

Palm Beach County Fleet Management Asset Maintenance History
10196262 2015 FORD F450 Cab & Chassis, 16,500 GVWR, w/Dump Body

Work Completed

- Preventive Maint. Service
- One of rear markers non-functioning
- Transmission Service
- Add Def
- Customer states A/c not working, perform system performance test and diagnostics. Found system was low on refrigerant, evac and recharge. Use leak tester, and found leaking evaporator.
- Upon diagnosis found that wipers were not functional, including a section where sprayer is broke and hose section is cut.
- Perform hot and cold side cooling system services
- Diag found leaking evaporator.r&r dash and vehicle interior. R&r evaporator, expansion valve, blend door actuator, mode door actuator, recirculation actuator, and heater core.
- R&r Front grille, lights, and coolers, replace condensor and drier assembly. Perform evac, vacuum, leak test, and recharge system
- Shop Supplies

Parts Issued

Quantity

Washer Fluid Concentr	2.00
Used Fire X Refurbished	1.00
Washer Pump	1.00
Transmission Filter	1.00
trans pan gasket	1.00
Syn-atf Trans Fluid S	16.00
Non-chlor Brake Clnr	3.00
Air Filter (gold), Air Panel	1.00
Napagold Fuel Filter	1.00
Proformer Oil Filter	1.00
15-40 Oil	15.00
Washer Jet	1.00
Wiper Blade	2.00
Hose Wacher	1.00
Blue Df	2.00
Frig Oil	2.00
Freon He Shop	10.00
Air Filter	1.00
degas tank	1.00
Blower Motor	1.00
A/c Condenser	1.00
Evaporator Core	1.00
Valve	1.00
A/c Actuator	1.00
A/c Door Actuator	2.00
A/c Resistor	1.00
Seal Kits	2.00
Kit O	1.00
clamp	1.00
Led M C 12v Grommet	1.00

2/1/2024
3:58:39 PM

Palm Beach County Fleet Management Asset Maintenance History
10196262 2015 FORD F450 Cab & Chassis, 16,500 GVWR, w/Dump Body

Parts Issued	Quantity
A/c Hose	1.00
Distilled Water 1gal	5.00
Coolent	5.00
Shop Supplies	1.00
Labor: 2,044.00	Parts: 1,907.07
Total: 3,951.07	

Hours: 28.00

Comm: 0.00

Work Order: 2212641

Meter: 38626

In Date: 12/15/2022 **Closed:** 12/23/2022

Problem: POSSIBLE TURBO OF DEF ISSUE

Work Completed

Parts Issued	Quantity
Tube - Outlet	1.00
Shop Supplies	1.00

- Cac hose blown - replace hose assy

- test drive

- Shop Supplies

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 109.97

Total: 255.97

Work Order: 2212869

Meter: 38626

In Date: 12/14/2022 **Closed:** 12/23/2022

Problem: POSSIBLE TURBO OF DEF ISSUE

Work Completed

- Tow From: 9011 Lantana Rd, Lake Worth 33467(mosquito Contrl) To: 2601

Vista Pkwy, West Palm Beach 33411(he Shop)

Hours: 0.00

Comm: 124.30

Labor: 0.00

Parts: 0.00

Total: 124.30

2/1/2024
3:58:39 PM

Palm Beach County Fleet Management Asset Maintenance History
10196262 2015 FORD F450 Cab & Chassis, 16,500 GVWR, w/Dump Body

Work Order: 2303039 **Meter:** 40196 **In Date:** 03/24/2023 **Closed:** 04/05/2023
Problem: Dist.3 Robert, truck has a check engine light

Work Completed

- Diagnosis, operator states truck has check engine light, use scan tool to find trouble codes, trouble code found P0088, this being said truck needs to be reflashed to newest flash ford offers
- Upon inspection found Ccv Filter to be clogged, needs replaced replace and verify concern
- Upon inspection found turbo hose about to blow, replace and verify concern
- Upon inspection found batteries to be leaking battery acid, replace and clean battery brackets
- P0088 code present during scan and diag. Reflash Pcm, Nox module, and instrument cluster per bulletin.
- Upon inspection found coolant hose to thermostat to be collapsed and about to rip, replace and add coolant
- Coolant service to avoid making a mess
- Road test to verify repairs, ensure coolant stays at correct level, and verify check engine light is gone
- Shop Supplies

Parts Issued

Quantity

oil separator	1.00
Tube - Outlet	1.00
Battery	2.00
Radiator Hose	1.00
Thermostat	1.00
Coolant Cap	1.00
Distilled Water 1gal	2.00
Coolent	2.00
Shop Supplies	1.00

Hours: 14.50

Comm: 0.00

Labor: 1,058.50

Parts: 763.21

Total: 1,821.71

2/1/2024
3:58:39 PM

Palm Beach County Fleet Management Asset Maintenance History
10196262 2015 FORD F450 Cab & Chassis, 16,500 GVWR, w/Dump Body

Work Order: 2305866

Meter: 40905

In Date: 06/13/2023 **Closed:** 10/12/2023

Problem: PM Service

Work Completed

- Preventive Maint. Service
- Add Def
- Cab Mounts
- Replace crank case filter
- Check engine light on vehicle sluggish on test drive
- Operator states Pto not working verified operator concern Diagnosing cause of concern found pto unit to be faulty causing concern. Removed and replaced pto assembly replaced lines replaced wiring
- Travel time to mako plus wait while they made custom hoses and grabbed replacement fittings.
- Transmission drain and refill due to aps pto repairs
- Drain and refill hydraulic tank due to pto repairs
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	15.00
Used Fire X Refurbished	1.00
Lucas Oil Stabl 32oz	1.00
Tr New Car Scent 3pk	1.00
Non-chlor Brake Clnr	3.00
Napagold Oil Filter	1.00
Fuel Filter	1.00
Air Filter (gold), Air Panel	1.00
Wiper Blade	2.00
Washer Fluid Concentr	2.00
Blue Df	2.00
Body Mount Kit	4.00
Body Mount Kit	2.00
13 Oz Aero Kroil	1.00
oil separator	1.00
Delvac 15w40 1 Ga	4.00
Pto Pump	1.00
Gasket	1.00
Prem Aw 68 Hyd Fl 5g	2.00
oil auto	18.00
Hose Made Mako	1.00
Shop Supplies	1.00
Freight Charge	1.00
Freight Charge	1.00

Hours: 25.00

Comm: 0.00

Labor: 1,825.00

Parts: 4,719.10

Total: 6,544.10

2/1/2024
3:58:39 PM

Palm Beach County Fleet Management Asset Maintenance History
10196262 2015 FORD F450 Cab & Chassis, 16,500 GVWR, w/Dump Body

Work Order: 2308097 **Meter:** 40905 **In Date:** 08/14/2023 **Closed:** 08/14/2023
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 251.00

Total Labor: 17,563.00

Total Comm: 2,979.40

Total Parts: 17,465.16