



1/29/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V650

In Date: 11/21/2005
Close Date: 12/28/2005

Meter Reading:

Problem?

set up new unit for service E41

Task performed:

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
180R002HURST HYD. FLUID QT	3
3085-195-000HORIZ.MOUNT	2
353R023HURST HOSE W/O SWIVEL	4
4025-190BRACKET	1
5269LPVM-5 SM MOUNT	7
58Z01C58Z01C BRACKET-PIKE POLE	2
CYBS21237011CYBS21237011 STRAP	2
PAPCAXE COVER PLASTIC W/CHAIN	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
SAHSVS2510STRAP	4
SWT1277EL57755 SWITCH DOOR 2PCS	2
TB510AX HOLDER ZA115101C	1
TH1QUICK MOUNT TOOL HOLDER	1
TH92CUTTER MOUNT HURST 30	1
TH92JHS60 DEGREE JL RAM HOLDER	1
UMVS111611STRAP	1
UMVS254411STRAP 46 IN	2
906-181-00-86OIL FILTER M2 SPINNER 57140	1

Workorder: V1075

In Date: 12/30/2005
Close Date: 01/06/2006

Meter Reading:

Problem?

ADJUST SHELVES IN MED COMPT, RE-41

Task performed:

Parts	Quantity
NO PARTS USED	



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V1063

In Date: 12/29/2005
Close Date: 01/10/2006

Meter Reading:

Problem?

PRESET PUMP PANEL GAUGES, LIGHTS ON PUMP PANEL WILL NOT TURN OFF RE-41

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1084

In Date: 01/03/2006
Close Date: 01/10/2006

Meter Reading:

Problem?

CHECK FRONT END, RE-41

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1286

In Date: 01/25/2006
Close Date: 03/02/2006

Meter Reading:

Problem?

AIR HOSE WILL NOT FIT PUMP PANEL RE-41

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1706

In Date: 03/02/2006
Close Date: 03/24/2006

Meter Reading:

Problem?

R/FRONT HOOD STROBE LIGHT INOP, LT. SEAT HAS AIR LEAK, NO FOG NOZZLE, R/REAR STROBE INOP, AIR HOSE WILL NOT FIT PUMP PANEL, RE-41

Task performed:

Parts

Quantity

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V1300

In Date: 01/25/2006
Close Date: 03/27/2006

Meter Reading:

Problem?

FRONT LEFT BOXLIGHT INOP, RE-41

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1579

In Date: 02/21/2006
Close Date: 03/27/2006

Meter Reading:

Problem?

LT'S DOOR WILL NOT SHUT PROPERLY,

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1684

In Date: 03/01/2006
Close Date: 03/27/2006

Meter Reading:

Problem?

R/REAR EMERGENCY LIGHT INOP, RE-41

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1925

In Date: 03/22/2006
Close Date: 04/05/2006

Meter Reading:

Problem?

REAR A/C INOP, RE-41

Task performed:

Parts

Quantity

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V2002

In Date: 03/28/2006

Meter Reading:

Close Date: 04/10/2006

Problem?

DOOR AJAR LIGHT STAYS ON, RE-41

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V2364

In Date: 04/24/2006

Meter Reading:

Close Date: 04/28/2006

Problem?

TANK TO PUMP VALVE HARD TO CLOSE, MAP LIGHT GOES ON AND OFF, RE-41

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1151

In Date: 01/06/2006

Meter Reading:

Close Date: 05/11/2006

Problem?

water in fuel light on E41

Task performed:

Parts

Quantity

RAIRK30880N122WSKL4000 SENSOR WATER IN FUEL

1

Workorder: V2280

In Date: 04/18/2006

Meter Reading:

Close Date: 05/12/2006

Problem?

INSTALL LOCK ON MED COMPT, DOOR, E-41

Task performed:

Parts

Quantity

R00178BOTTOM RAIL ASSBLY

1



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V2551

In Date: 05/10/2006

Meter Reading:

Close Date: 05/17/2006

Problem?

REAR A/C INOP, RE-41

Task performed:

Parts	Quantity
52-27452-274 BLOCK TERMINAL	1
VF4-15F11RELAY 40/30	1

Workorder: V2565

In Date: 05/11/2006

Meter Reading:

Close Date: 05/19/2006

Problem?

FRONT A/C INTERMITTINT, RE-41

Task performed:

Parts	Quantity
VCC/36000006A/C FILTER CAB M2	1

Workorder: V2789

In Date: 05/29/2006

Meter Reading:

Close Date: 06/07/2006

Problem?

complete pump computer failure. would not allow truck to pump. road mechanic looked at truck and did not have lap top. swaped into spair.

Task performed:

Parts	Quantity
600000003NODE HERCULES V-MUX	1



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V2827

In Date: 06/01/2006

Meter Reading:

Close Date: 06/09/2006

Problem?

B INSPECTION, REPLACE OFFICER SEAT, RE-41

Task performed:

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
211-2BULB	2
5008414CARTRIDGE DC100	1
6535SPARK PLUG CR5HSB	1
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
BPR5ESSPARK PLUG 7734	1
27-102A22-54259-000 DOOM LIGHT SWITCH M2	1
29526898 29548988 TRANS FILTER ALLISON	1
42809AIR FILTER M2	1
5648056480 PLUG-POWER/ACCESS.	1
7131BPR6ESUSE 7131 OR BPR6ES SPARK PLUG	1
31-22USE 91-22 WIPER BLADES	2
7460967AIR FILTER 17210-ZE2-515 HONDA	1
524740830-805 A/F HONDA 17210-ZE1-505	1
FZ51368FEET RUBBER RAM-FAN	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
VF4-15F11RELAY 40/30	1

Workorder: V3146

In Date: 06/26/2006

Meter Reading: 6,805.00

Close Date: 06/27/2006

Problem?

A INSPECTION RE 41

Task performed:

Parts	Quantity
048009000SPEEDCOUNTER PUMP PANEL	1
8126482-2106 TOGGLE GUARD	1
9550 BELT	1
PVG-KITORING KIT	1



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V3169

In Date: 06/27/2006

Meter Reading:

Close Date: 06/28/2006

Problem?

REPLACE REAR TIRES E41

Task performed:

Parts

Quantity

NO PARTS USED

Vendor?: VC-15214

Workorder: V3264

In Date: 07/03/2006

Meter Reading:

Close Date: 07/05/2006

Problem?

ON CALL DOME LTS WONT SHUT OFF

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V3255

In Date: 07/02/2006

Meter Reading:

Close Date: 07/14/2006

Problem?

The interior cab lights flicker on/off and door open buzzer intermittenly comes on with no doors open. Problem is occuring more often in past few hours.RE 41

Task performed:

Parts

Quantity

27-102A22-54259-000 DOOM LIGHT SWITCH M2

4

Workorder: V3554

In Date: 07/20/2006

Meter Reading:

Close Date: 07/20/2006

Problem?

REPAIR BACKUP CAMERA RE41

Task performed:

Parts

Quantity

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V3599

In Date: 07/23/2006
Close Date: 07/31/2006

Meter Reading:

Problem?

RIGHT REAR STROBE MALFUNCTION RE41

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V3854

In Date: 08/09/2006
Close Date: 08/18/2006

Meter Reading:

Problem?

BATTERIES READING 11.5 WHEN PULLING PRIMER CAUSING PRIMER TO FOUL, RT REAR WARNING LIGHT STROBE DII UNABLE TO SEE FFROM BAY FLOOR.

Task performed:

Parts

Quantity

CV1F12PMF-RCAVIDEO CABLE

1

Workorder: V4026

In Date: 08/21/2006
Close Date: 08/21/2006

Meter Reading:

Problem?

ON CALL NO A/C E41

Task performed:

Parts

Quantity

87499RY48 RELAY

1

Workorder: V4173

In Date: 08/29/2006
Close Date: 09/01/2006

Meter Reading: 8,668.00

Problem?

watp system 10/7 not working E41

Task performed:

Parts

Quantity

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V4180

In Date: 08/31/2006
Close Date: 09/01/2006

Meter Reading: 8,668.00

Problem?

ON CALL AMP SHUNT BURNED OFF RE41

Task performed:

Parts	Quantity
0R80-0615-00INTERFACE MODULE	1

Workorder: V4203

In Date: 08/31/2006
Close Date: 09/08/2006

Meter Reading: 802.00

Problem?

tighten seat belt rear drivers side so it does nt move. thanks E41

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V4053

In Date: 08/22/2006
Close Date: 09/11/2006

Meter Reading:

Problem?

REPAIR RT REAR COMP DOOR RE41

Task performed:

Parts	Quantity
01-02698572 CH LED FLASHER	1

Workorder: V4346

In Date: 09/08/2006
Close Date: 09/25/2006

Meter Reading: 802.00

Problem?

leaking foam out of bottom of truck, noted small puddle on floor when sitting. RE41

Task performed:

1. R/R FOAM FITTING ON FOAM PUMP.

Parts	Quantity
NO PARTS USED	



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V4286

In Date: 09/06/2006

Meter Reading: 802.00

Close Date: 09/26/2006

Problem?

foam system not working. RE41

Task performed:

Parts

Quantity

1. TRAVELED TO STN 41 CHECKED FOAM SYSTEM FOUND IT TO BE-OK.
2. READJUSTED AIR PACK BRACKETS IN SEATTS THAT WERE NOT RELEASING.
3. CHECKED OUT BACK UP CAMERA FOUND TO BE O/S. INSTALLED NEW CAMERA.

NO PARTS USED

Workorder: V4229

In Date: 09/03/2006

Meter Reading: 8,668.00

Close Date: 10/03/2006

Problem?

yellow reflecter, drivers side by step up to pump panel, broken RE41

Task performed:

Parts

Quantity

1. INSTALLED NEW YELLOW REFLECTOR, DRIVERS SIDE BY STEP UP TO PUMP.

35200R35200-R LIGHT MARKER LED

3

78241USE 8550A250A

3

94862PIGTAIL LED MARKER LIGHTS

3

B480AREFLECT-AMBER

2

Workorder: V4643

In Date: 09/28/2006

Meter Reading: 8,668.00

Close Date: 10/03/2006

Problem?

pedal for telescoping steering wheel came off. Spring attached to pedal also off. Both iems stored in engineers compartment. R41

Task performed:

Parts

Quantity

1. REPAIRED STEERING WHEEL PEDEL.

RGT-452258FFOOT PEDAL STERRING COLUMN

1



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V4228

In Date: 09/03/2006
Close Date: 10/16/2006

Meter Reading: 802.00

Problem?

back up camera does not work RE41

Task performed:

Parts

Quantity

- 1. REPAIRED ON ANOTHER TICEKET...VOID
- VOID
- VOID
- VOID.

NO PARTS USED

Workorder: V4764

In Date: 10/06/2006
Close Date: 10/23/2006

Meter Reading: 935.00

Problem?

bottom center light in walk thru knocked out RE41

Task performed:

Parts

Quantity

- 1. REPAIRED CENTER LIGHT IN WALK WAY.
- 2. REPLACE STEERING WHEEL ADJUST PEDAL.

NO PARTS USED

Workorder: V4797

In Date: 10/08/2006
Close Date: 11/06/2006

Meter Reading: 939.00

Problem?

stroblight 10-7 on tailboard on officers side. E-41

Task performed:

Parts

Quantity

- 1. check stroblight right rear

NO PARTS USED

Workorder: V4938

In Date: 10/17/2006
Close Date: 11/06/2006

Meter Reading: 977.00

Problem?

airbrakes leaking, light on back of pump E-41 panel fell out.

Task performed:

Parts

Quantity

- 1. repair light in pump panal walkway
- 2. check for air leek in braking system

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V5321

In Date: 11/08/2006
Close Date: 11/13/2006

Meter Reading: 987.00

Problem?

RIGHT REAR AIRPACK BRACKET LOOSE e41

Task performed:

1. TRAVELED TO STN 41. REPAIRED L SIDE AIR
PACK BRACKET.

Parts

NO PARTS USED

Quantity

Workorder: V6026

In Date: 01/01/2007
Close Date: 01/03/2007

Meter Reading: 1,228.00

Problem?

RIGHT-FRONT TIRE DAMAGE. E-41

Task performed:

1. Tires were replaced

Parts

NO PARTS USED

Quantity

Workorder: V6111

In Date: 01/05/2007
Close Date: 01/08/2007

Meter Reading: 13,154.00

Problem?

REPAIR A/C BELT E41

Task performed:

1. Replaced belt

Parts

9545BELT M2 ENGINE
9550 BELT

Quantity

2
2

Workorder: V6138

In Date: 01/08/2007
Close Date: 01/09/2007

Meter Reading: 1,228.00

Problem?

Wheel chalk door will not stay closed. E-41

Task performed:

1. Repaired air bottle door

Parts

101291015434 LATCH TRIGGER S/O

Quantity

2



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V6370

In Date: 01/19/2007 Meter Reading: 14,461.00
Close Date: 01/23/2007

Problem?

wipers come on for no reason E-41

Task performed:

1. R/R TURN SIGNAL SWITCH. TEST/ OK.

Parts

Quantity

A06-36956-000A06-36956-003 WIPER-TURN SWITCH

1

Workorder: V6371

In Date: 01/19/2007 Meter Reading: 1,307.80
Close Date: 01/23/2007

Problem?

back up alarm comes on when moving forward E-41

Task performed:

1. TRAVELED TO STN 41. REPLACED MULITPLEX CONNECTOR, WATER INTRUSION.

Parts

Quantity

DT043PP007DEUTSCH RECEPTACLE

1

Workorder: V6259

In Date: 01/12/2007 Meter Reading: 14,108.00
Close Date: 01/25/2007

Problem?

spontaneous and intermittent self activation of hazard flashers re41

Task performed:

1. TRAVELED TO STN 41. CLEANED CONTACTS OF SWITCH AND TESTED/ OK.

Parts

Quantity

NO PARTS USED

Workorder: V6373

In Date: 01/19/2007 Meter Reading: 1,307.80
Close Date: 01/26/2007

Problem?

burned up primer motor E-41

Task performed:

Parts

Quantity

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V6372

In Date: 01/19/2007
Close Date: 02/01/2007

Meter Reading: 1,307.80

Problem?

handle broke off of the garden hose fill valve on left side panel E-41

Task performed:

Parts

Quantity

1. Repaired broken handle

NO PARTS USED

Workorder: V6638

In Date: 02/06/2007
Close Date: 02/07/2007

Meter Reading: 1,392.80

Problem?

trash line compartment door hinge missing screws, about to fall offr41

Task performed:

Parts

Quantity

1. Repaired door that was missing screws

NO PARTS USED

Workorder: V6866

In Date: 02/21/2007
Close Date: 03/06/2007

Meter Reading: 15,353.00

Problem?

RPLACE HOSE BED COVER CENTRAL AUTO TRIM E41

Task performed:

Parts

Quantity

Replace hose bed cover Central Auto Trim E41

NO PARTS USED

Vendor?: CENTRAL AUTO TRIM

Workorder: V6911

In Date: 02/23/2007
Close Date: 03/07/2007

Meter Reading: 15,353.00

Problem?

align front end (outside agency-tiresoles) E41

Task performed:

Parts

Quantity

Align ront end E41 Tiresoles

NO PARTS USED

Vendor?: TIRESOLES



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V6784

In Date: 02/15/2007

Meter Reading: 15,353.00

Close Date: 03/08/2007

Problem?

B INSPECTION AND REPAIRS AS NEEDED RE41

Task performed:

1. B Inspection
2. Air leak. Found cab air bag leaking. Replaced both air bags per conversation with Frieghtliner.
3. Repaired broken dash panel
4. Service power steering
5. Repaired line to front suction gauge
6. Replaced rear brakes
7. Repaired pump panel lights
8. Insulated fitting for rear a/c line
9. Replaced left side door open switch
10. Secure right rear cab door handle
11. R&R both cab a/c filters
12. R&R wipers and added washer solvent
13. Service small engine equipment
14. Failed dry vacume test. Repaired trash line and deck gun valves. Repaired RPM counter. Vacume tested passed
15. Pressure relief drain support bracket loose removed stripped screws and secured
16. Repaired handle on siemese valve
17. R3 roll up door slots damaged. Remove rail,slots, and wiring. Reassemble and install
18. Replaced missing chains for discharge caps
19. Install crossley nets
20. Clean work area
21. Checked drivers seat seemed loose. All fasteners tight. Showed ED E. he said ok

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
048009000SPEEDCOUNTER PUMP PANEL	1
108-12FBEADED CHAIN W/CONN 12	1
18-40977-00018-52651-000 AIR SPRING CAB M2	2
27-102A22-54259-000 DOOM LIGHT SWITCH M2	1
42809AIR FILTER M2	1
68-3963453-30LENS CLEAR FOR STRIP LIGHT	2
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91378905 VALVE KIT 2 IN AKRON	1
A22-54059-000DASH PANEL R/H M2	1
CT4515METBRAKE LINNING	4
RV17YCUSE 25 AUTOLITE SPARK PLUG NGK 6630	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
U-22RWIPER REFILL	1
VCC/36000006A/C FILTER CAB M2	1
VML/T1808D2503221C1 FILTER POWER STEERING	1
3576REAR BRAKE DRUMS	2

Workorder: V7125

In Date: 03/09/2007

Meter Reading: 1,444.00

Close Date: 03/14/2007

Problem?

REPAIR FLAT TIRE CALLAGHAN ENT

Task performed:

Found rear tire flat called tire co.

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN ENT



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V7282

In Date: 03/20/2007 Meter Reading: 15,353.00
Close Date: 03/23/2007

Problem?

re41 would not go into pump gear due to electronic interlock on a brush fire last night. several attempts to reset the pto were made before getting the pump in gear.

Task performed:

Found bad connection on pump case switch. Repaired and tested

Parts

NO PARTS USED

Quantity

Workorder: V6980

In Date: 02/28/2007 Meter Reading: 1,444.00
Close Date: 04/02/2007

Problem?

Need 1 hose clamp mount for engine, 1 spare bottler O2 bracket if possible, and main drain on water tank is leaking. re41

Task performed:

1. Installed hose clamp on rear of truck
2. Rebuilt master drain valve

Parts

104967DIAPHRAM FOR 6 PORT DUMP VALVE 1
 3802600USE 046-8020-00-0 SEAL DRAIN VALVE FERRARA 1
 589589 BRACKET HOSE CLAMP 1
 SAHSVS2510STRAP 2
 UMVS-0811-11STRAP ZICO 2
 UMVS111611STRAP 2

Quantity

Workorder: V7358

In Date: 03/24/2007 Meter Reading: 1,444.00
Close Date: 04/03/2007

Problem?

Lt side rear wheel lug nut cover missing e41

Task performed:

1. Replaced lug nut cover
2. Repaired right side entry door latch

Parts

NO PARTS USED

Quantity

Workorder: V7558

In Date: 04/06/2007 Meter Reading: 15,353.00
Close Date: 04/06/2007

Problem?

ON CALL HURST UNIT 10-7 RE41

Task performed:

Road call to STN41 to swap out power unit

Parts

NO PARTS USED

Quantity



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V7620

In Date: 04/10/2007
Close Date: 04/13/2007

Meter Reading: 1,444.00

Problem?

light bar was not working onlast call. push buttons would not make it work and the panel showed that it was on. shut vehicle off an batteries and restarted. light bar works at this time. E-41

Task performed:

No problem

Parts

NO PARTS USED

Quantity

Workorder: V7938

In Date: 04/26/2007
Close Date: 04/30/2007

Meter Reading: 15,353.00

Problem?

REPAIR CAB DOOR SWITCH E41

Task performed:

Replc door switch; dome lights only came on manually.
Crew did not want to wait

Parts

27-102A22-54259-000 DOOM LIGHT SWITCH M2

1

Quantity

Workorder: V8045

In Date: 05/01/2007
Close Date: 05/17/2007

Meter Reading: 15,353.00

Problem?

repair hurst power unit E41 (outside agency-team equipment)

Task performed:

Repair Hurst power unit - Team Equipment

Parts

NO PARTS USED

Quantity

Vendor?: TEAM EQUIPMENT

Workorder: V9302

In Date: 07/13/2007
Close Date: 07/17/2007

Meter Reading: 19,261.00

Problem?

REPLACE HANDLIGHTS (THEY HAD PELIGAN)

Task performed:

1. TRAVEL TO 41. REPLACED HANDLIGHTS FOR STREAMLIGHT HANDLIGHTS.

Parts

NO PARTS USED

Quantity



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V9547

In Date: 07/25/2007 Meter Reading: 21,375.00

Close Date: 07/26/2007

Problem?

Repair saw E41 (outside agency-regan's small engine service)

Task performed:

Repair saw-Regan's Small Engine

Parts

NO PARTS USED

Quantity

Vendor?: REGANS SMALL

Workorder: V9465

In Date: 07/23/2007 Meter Reading: 21,375.00

Close Date: 07/27/2007

Problem?

E 41 MAP LT 10-7

Task performed:

1. Map light inop; replc map light
2. Air leak; traced & repaired were needed
3. Chain saw inop; gave spare
4. Water leak under pump; rep fitting under pump

Parts

LF18TS-LEDMAP LIGHT LED 18 IN

1

Workorder: V9831

In Date: 08/11/2007 Meter Reading: 2,069.00

Close Date: 08/30/2007

Problem?

E41 4 MARKER LIGHTS OUT. YELLOW LEFT AND RIGHT SIDE UNDER DISCHARGES. RIGHT SIDE REAR UNDER HURST TOOL COMPARTMENT OUT. CENTER OF THREE REAR TAILBOARD STEP E41

Task performed:

Traced out problem w/marker lights; fnd bad ground
Rep R-side spotlights; rep dome ring

Parts

NO PARTS USED

Quantity

Workorder: V10024

In Date: 08/21/2007 Meter Reading: 2,069.00

Close Date: 09/11/2007

Problem?

L.REAR LIGHT BRACKET WITH CIRLCE SCENE LIGHT IS BENT, SCREWS STRIPPED. LIGHTS WORK. E41

Task performed:

1. installed & wired left rear light bar bracket
2. Foam leak; fnd tank overfilled

Parts

STANTION STANCHION

1



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V10138

In Date: 08/27/2007
Close Date: 09/18/2007

Meter Reading: 2,069.00

Problem?

E-41 is leaking foam

Task performed:

Parts

Quantity

1. Went to Stn41; truck at a call
2. Reseal foam tower & lowered level of foam
3. Rep L-side steps that were falling off

NO PARTS USED

Workorder: V9983

In Date: 08/17/2007
Close Date: 09/18/2007

Meter Reading: 22,134.00

Problem?

repair station blower and hurst power unit Sta 41 (outside agency-Regan's small engine service)

Task performed:

Parts

Quantity

Repair station blower/Hurst power unit - Regan's Small Engine

NO PARTS USED

Vendor?: REGAN SMALL

Workorder: V10304

In Date: 09/07/2007
Close Date: 09/25/2007

Meter Reading: 23,040.00

Problem?

install o2 bottle e41

Task performed:

Parts

Quantity

1. Installed O2 Bottle.

NO PARTS USED

Workorder: V10419

In Date: 09/13/2007
Close Date: 09/28/2007

Meter Reading: 23,040.00

Problem?

replace damaged rear tire e41

Task performed:

Parts

Quantity

REPAIR DAMAGED REAR TIRE ON E41

NO PARTS USED

Vendor?: CALLAGHAN TIRE



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V6750

In Date: 02/14/2007
Close Date: 10/15/2007

Meter Reading: 15,353.00

Problem?

emergency lights innop. (E41)

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V8089

In Date: 05/03/2007
Close Date: 10/15/2007

Meter Reading: 15,353.00

Problem?

REPLACE 4 REAR TIRES (CALLAGHAN)

Task performed:

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V10829

In Date: 10/03/2007
Close Date: 10/22/2007

Meter Reading: 1,396.00

Problem?

back up lights not working. no audible signal when backing. open door buzzer sounds when truck in park and brake engaged. e41

Task performed:

Parts

Quantity

1. tracing out problem with back up lights.
2. tracing out problem with back up light. found water in system.

NO PARTS USED

Workorder: V10884

In Date: 10/05/2007
Close Date: 10/22/2007

Meter Reading: 1,396.00

Problem?

Interior alarm will sound showing doors open while driving.

Task performed:

Parts

Quantity

reported interior alarm sounding while driving. found no problem at this time.

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V11049

In Date: 10/16/2007

Meter Reading: 23,040.00

Close Date: 10/23/2007

Problem?

emergency flasher on l front of engine grill out e41

Task performed:

Parts

Quantity

1. found no llights out on truck

NO PARTS USED

Workorder: V11083

In Date: 10/17/2007

Meter Reading: 23,040.00

Close Date: 10/23/2007

Problem?

replace comand master e41

Task performed:

Parts

Quantity

1. checked out command master. swapped out command master from engine 47.

NO PARTS USED

Workorder: V8020

In Date: 01/01/1900

Meter Reading: 15,353.00

Close Date: 10/25/2007

Problem?

*

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V11304

In Date: 10/29/2007

Meter Reading: 1,396.00

Close Date: 11/05/2007

Problem?

light bar damaged from hitting bay door. e41

Task performed:

Parts

Quantity

Light bar & search light damaged; rep light bar & replc search light

9UCAPCC9UCAPCC END CAP CLEAR

1

LGHGO-2020GOLIGHT MODEL 2020 SEARCH LIGHT

1



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V11360

In Date: 11/01/2007

Meter Reading: 1,396.00

Close Date: 11/14/2007

Problem?

DRIVERS SIDE FIXED FLOOD/SPOT LIGHT CENTER OF THREE BURNED OUT E41

Task performed:

Parts

Quantity

1. Instaled new bulb for left side spot light
2. Traled out problem with light bar not comming on at time- found bad ground wire in light bar.

4007BULB NIGHT FIGHTER

1

Workorder: V11361

In Date: 11/01/2007

Meter Reading: 1,396.00

Close Date: 11/14/2007

Problem?

DRIVERS SIDE PUMP WALK WAY LIGHT FELL OUT. IT IS THERE, NEEDS TO BE REMOUNTED E41

Task performed:

Parts

Quantity

1. Remounted center walkway lights that fell out of holder
2. Adjusted air horn that were out of adjustment.
3. Traced out problem with primer not working found bad connection on solenoid.
4. traced out problem with map light found broken wire- repaired and tested.

NO PARTS USED

Workorder: V11433

In Date: 11/05/2007

Meter Reading: 23,040.00

Close Date: 11/14/2007

Problem?

WATER LEAK IN CAB (LIGHT BAR HIT BAY DOOR) E-41

Task performed:

Parts

Quantity

1. Resealed top light bar holes.

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V11625

In Date: 11/15/2007

Meter Reading: 23,040.00

Close Date: 11/28/2007

Problem?

replace fan assembly cracking badly e41

Task performed:

1. Upon inspection of belts found cracks in fan were clutch attaches remove belts , fan and fan shroud. replace fan and repair crack in shroud. reassemble and road test.

Parts

Quantity

FREIGHTSHIPPING CHARGES

1

YS/4735-43782-01FAN

1

Workorder: V11505

In Date: 11/07/2007

Meter Reading: 23,040.00

Close Date: 11/30/2007

Problem?

b inspection and repairs as needed e41

Task performed:

1. B-Service
2. Change oil in gen and hurst pwoer plant, service T-case
3. Service air dryer and purge valve, tourque all U bolts, Service coolent system, drain and refill system.
4. R+R wiper blades, repair washer, R+R all battery, clean cables, insulated terminal protector, insulated cone strap on rear of truck.
5. R+R rear brakes, R+R A/C filters, R+R fan belts.
6. R+R light on left rear step., R+R red step light, Insulated screw on strobe pack to light to ground
7. Installed snaps on hose bed cover, R+R foam pump, clean reinstalled, waiting on new.
8. Clean up bay.

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT

1

0000902051FILTER FUEL 03 MERCEDES

1

0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH

1

01-29866-118BELT ALT. M2

1

05-17223-002RAD CAP 20 LB

1

35200-RLIGHT MARKER LED RED

2

3530016HOSE HURST 16 ORANGE

1

3576REAR BRAKE DRUMS

2

42809AIR FILTER M2

1

440-5 VALVE EXT.

4

67BULB 12 VOLT

1

78R536078R5360M 2PK FILTER AIR COND

1

906-181-00-86OIL FILTER M2 SPINNER 57140

1

91-22WIPER BLADE

2

9550 BELT

1

CT4515METBRAKE LINNING

2

HP-31DBATTERY 950CCA HP-31D

4

5008414CARTRIDGE DC100

1

800404USE K022105 PURGE KIT AD-IP-IS

1

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

4

KIT9081BRAKE HARDWARE KIT

2

S3226FL02FUEL FILTER 33813 L/F # LFF5851

1

UMVS254411STRAP 46 IN

1

VCC/36000006A/C FILTER CAB M2

1



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V11610

In Date: 11/14/2007 Meter Reading: 23,040.00
Close Date: 12/20/2007

Problem?

REPLACE TIRES AT SHOP E41

Task performed:

Parts

Quantity

Replace tire at shop E41 - Callaghan j

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V6032

In Date: 01/01/2007 Meter Reading: 1,228.00
Close Date: 01/08/2008

Problem?

Truck needs to have right-front end realigned as per Callaghan Tires. Both tires were replaced on 01/01/2007.

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V11079

In Date: 10/17/2007 Meter Reading: 1,396.00
Close Date: 01/15/2008

Problem?

Engine pump circuit board not working.

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V12244

In Date: 12/26/2007 Meter Reading: 2,357.60
Close Date: 01/16/2008

Problem?

discharge gauge number 2 shows pressure when doing morning check, poss leak in guage.

Task performed:

Parts

Quantity

1. Removed discharge No# 2 valve and rebuilt valve and tested for leaks.
2. Checked for air leaks found fitting on rear air tank leaking.

91388906 VALVE KIT 2.5 IN AKRON

1



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V12523

In Date: 01/11/2008
Close Date: 01/18/2008

Meter Reading: 2,407.00

Problem?

lower rear side red clearance light out...generator compartment e41

Task performed:

Parts

Quantity

1. Emergency light out, repaired bad connection in right rear rotator.
2. Light out, repaired bad connection.

NO PARTS USED

Workorder: V12591

In Date: 01/15/2008
Close Date: 01/18/2008

Meter Reading: 2,407.00

Problem?

Rt rear emergency light is out e41

Task performed:

Parts

Quantity

1. Rear LED light out repaired bad connection.

NO PARTS USED

Workorder: V12476

In Date: 01/09/2008
Close Date: 01/22/2008

Meter Reading: 2,407.00

Problem?

Windshield wiper reservoir cap is broken. r32

Task performed:

Parts

Quantity

1. Repaired cap for washer bottle.
2. Adjusted strecher latch.

22-58581-000WASHER RESIVOR CAP

1

Workorder: V12785

In Date: 01/24/2008
Close Date: 02/04/2008

Meter Reading: 2,407.00

Problem?

RIGHT REAR STROBE, TOP, BY HOSE BED OUT e41

Task performed:

Parts

Quantity

1. Rep bad conn in light bar.
2. Rep parking brake valve knob that fell off.

NO PARTS USED

j



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V3193

In Date: 06/28/2006
Close Date: 02/07/2008

Meter Reading:

Problem?

AM FM RADIO 10-7

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V4996

In Date: 10/20/2006
Close Date: 02/07/2008

Meter Reading: 979.00

Problem?

air brakes still leak E-41

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V5410

In Date: 11/15/2006
Close Date: 02/07/2008

Meter Reading: 10,782.00

Problem?

CHANGE PLUMBING ON PUMP COOLER E41

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V12786

In Date: 01/24/2008
Close Date: 02/13/2008

Meter Reading: 26,202.00

Problem?

RT REAR EMERGENCY LIGHT OUT AGAIN e41

Task performed:

Parts

Quantity

- 1. Installed new pigtail for rear led light

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V13151

In Date: 02/09/2008 Meter Reading: 26,933.00
Close Date: 02/13/2008

Problem?

small ram from e41 hose burst in sw side of bay at 41

Task performed:

- | | <u>Parts</u> | <u>Quantity</u> |
|---|------------------------------|-----------------|
| 1. Replaced hoses on small ram | 353R023HURST HOSE W/O SWIVEL | 2 |
| 2. Repaired right side warning light that was not working | | |

Workorder: V13299

In Date: 02/17/2008 Meter Reading: 2,448.00
Close Date: 02/20/2008

Problem?

3 discharge pressurizes when valve is closed. Also # 1 crosslay charged when valve was closed last week per officer. Has not done it for me. E41

Task performed:

- | | <u>Parts</u> | <u>Quantity</u> |
|---|---------------|-----------------|
| 1. Ran pump and checked for leaks and found none at this time | NO PARTS USED | |

Workorder: V13312

In Date: 02/18/2008 Meter Reading: 2,448.00
Close Date: 02/20/2008

Problem?

officer cab door latch inoperative from inside cab. needs service E-46

Task performed:

- | | <u>Parts</u> | <u>Quantity</u> |
|---------------------------------|---------------|-----------------|
| 1. Adjusted driver's door latch | NO PARTS USED | |

Workorder: V13441

In Date: 02/22/2008 Meter Reading: 2,448.00
Close Date: 03/04/2008

Problem?

foam sensor appears to be malfunctioning. shows down 3 blocks on panel when only a gallon or two down E41

Task performed:

- | | <u>Parts</u> | <u>Quantity</u> |
|---|---------------|-----------------|
| 1. CHECKED FOAM GAUGE FOUND NO PROBLEM. | NO PARTS USED | |



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V13442

In Date: 02/22/2008
Close Date: 03/04/2008

Meter Reading: 2,448.00

Problem?

marker lights; lower yellow drivers comp. out lower red generator comp. out rear bottom center three, right very dim right top red under strobe, very dim lower red medic comp. out E41

Task performed:

1. INSTALLED TWO YELLOW AND TWO RED MARKER LIGHTS.

Parts

NO PARTS USED

Quantity

Workorder: V13450

In Date: 02/23/2008
Close Date: 03/04/2008

Meter Reading: 26,933.00

Problem?

main drain leaking on driver side causing rust stains on the bay floors. E41

Task performed:

1. PUMP LEAKING WATER, INSTALLED NEW KIT FOR MASTER DRAIN.

Parts

104967DIAPHRAM FOR 6 PORT DUMP VALVE

Quantity

1

Workorder: V13505

In Date: 02/26/2008
Close Date: 03/20/2008

Meter Reading: 26,933.00

Problem?

REPLACE 3 REAR TIRES AT 41 CALLAGHAN

Task performed:

Replace (3) rear tire Stn41 - Callaghan j

Parts

NO PARTS USED

Quantity

Vendor?: CALLAGHAN

Workorder: V13903

In Date: 03/17/2008
Close Date: 03/24/2008

Meter Reading: 28,117.00

Problem?

pump leaking water e41

Task performed:

1. checked for leaks and found master drain leaking, replaced seal.

Parts

5460370530VPS SHIFT KIT 546-0370-53-0

Quantity

1



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V14131

In Date: 03/27/2008 Meter Reading: 2,578.00

Close Date: 04/01/2008

Problem?

driver side front blinker 10-7. e41

Task performed:

Parts

Quantity

- 1. replaced bad fuse for left turn signal, tested OK

NO PARTS USED

Workorder: V13311

In Date: 02/18/2008 Meter Reading: 26,933.00

Close Date: 04/07/2008

Problem?

Rt front officer's door will not open from the inside. E41 ? NO ASSET ENTERED

Task performed:

Parts

Quantity

- 1. Found no problem with Cab door not opening

NO PARTS USED

Workorder: V14231

In Date: 04/02/2008 Meter Reading: 23,808.00

Close Date: 04/10/2008

Problem?

REPAIR TURN SIGNALS E41

Task performed:

Parts

Quantity

- 1. traced out turn signals not working / found wiring shorting on frame rail repaired wires and tested
- 2. rear marker lights inop. found bad ground and repaired.

NO PARTS USED

Workorder: V14406

In Date: 04/10/2008 Meter Reading: 28,679.00

Close Date: 04/22/2008

Problem?

E41 LIGHT BAR IS OUT OF ALIGNMENT IT POINTS INTO THE AIR NOT TOWARDS THE TAFFIC. WAS DAMAGED MONTHS AGO WHEN IT STRUCK THE BAY DOOR.

Task performed:

Parts

Quantity

- 1. need new brakets for light bar will need to order.

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V14630

In Date: 04/23/2008 Meter Reading: 2,605.00
Close Date: 04/30/2008

Problem?

wipers come on when you use the turn signal E-41

Task performed:

1. replaced wiper switch and tested.

Parts	Quantity
A06-36956-000A06-36956-003 WIPER-TURN SWITCH	1

Workorder: V14631

In Date: 04/23/2008 Meter Reading: 2,605.00
Close Date: 04/30/2008

Problem?

front, dash, a/c not working E-41

Task performed:

1. a/c inop- repaired bad connection in switch.

Parts	Quantity
NO PARTS USED	

Workorder: V14921

In Date: 05/07/2008 Meter Reading: 2,605.00
Close Date: 05/13/2008

Problem?

RIGHT SIDE TELESCOPING SCENE LIGHT CENTER OUT e41

Task performed:

1. replaced bulb

Parts	Quantity
4007BULB NIGHT FIGHTER	1

Workorder: V14871

In Date: 05/05/2008 Meter Reading: 2,605.00
Close Date: 05/14/2008

Problem?

front a/c blower motor not working. drain valve dripping. E-41

Task performed:

1. a/c blower motor inop, replaced blower motor.

Parts	Quantity
VCC/3500003BLOWER MOTOR VCCT1000904A M2	1
VCC/83000038AC WIRE HARNESS	1



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V15362

In Date: 05/27/2008
Close Date: 06/02/2008

Meter Reading: 2,697.00

Problem?

primer valve sticks. E42

Task performed:

Primer inop; installed new primer valve. j

Parts

Quantity

538028052VALVE PRIMER PUMP W/HARDWARE

1

Workorder: V15381

In Date: 05/28/2008
Close Date: 06/02/2008

Meter Reading: 2,697.00

Problem?

It. door will not open from inside the cab E-41

Task performed:

Cleaned/adj cab door j

Parts

Quantity

T69-15.5 STRAP FOR TOOL HOLDER

1

Workorder: V14988

In Date: 05/10/2008
Close Date: 06/04/2008

Meter Reading: 2,605.00

Problem?

RED MARKER LIGHT OUT. RIGHT OF THREE, CENTER LOWER TAILBOARD E41

Task performed:

1. lights out; rep bad grd to marker lights.
2. Noise in frnt wheel when driving; road tested & tested;
ok-no noise.
j

Parts

Quantity

NO PARTS USED

Workorder: V15267

In Date: 05/22/2008
Close Date: 06/05/2008

Meter Reading: 2,697.00

Problem?

****hurst generator will not start**** 10163049 e41

Task performed:

No start; installed new plug & ran pump; j

Parts

Quantity

6535SPARK PLUG CR5HSB

4



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V15493

In Date: 06/03/2008

Meter Reading: 29,740.00

Close Date: 06/16/2008

Problem?

B INSPECTION AND REPAIRS AS NEEDED E41

Task performed:

- 6-3 to 6-5 B Inspection
- 6-4 Service both Battery & trash Line Slide Drawers - Levers froze
- 6-4 Hose adapters Compartment Door
- 6-4 Replace front ac bracket high pressure hose mount & bracket
- 6-5 replace rear ac compressor belt
- 6-5 Remove rear bumper light bar and replacce all 3 fixtures reinstall
- 6-5 Check L3 compartment RS light stripping Note Light stripping is part of ROM roll up door frame ordered parts
- 6-4 Checked ac problem found bad wiring ot servo and blower motor
- 6-5 replace wipers
- 6-5 replace five pump panel gauges leaking oil
- 6-5 to 6-9 Check out problem with city horns inop check through all books to find circuits that ferrara used to splice into factory wiring. could only find factory circuit - trace wiring to figure out ciruits - problem found in steering column - disassemble and make repairs
- 6-5 to 6-6 Assist Stan w/ horns
- 6-6 to 6-10 Disaassemble cab light bar mount call bent up notes this is a custom made bracket by ferrara - replace bent up brackets with new style whelen mounts - fabrication necessary for installation

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
15W40BSYN OIL BULK QTS	24
23-12982-770COVER SCREWS M2	2
35200-RLIGHT MARKER LED RED	3
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
9550 BELT	1
A0631117003HORN LOW NEW #06-52125-041	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
VCC/36000006A/C FILTER CAB M2	1
8550A250A8550A250A BULB	1
91553941GAUGE	5
S775COUPLER	2
MAKJ29ADJ. LIGHT BAR MOUNT	1

Workorder: V14920

In Date: 05/07/2008

Meter Reading: 2,605.00

Close Date: 06/17/2008

Problem?

MARKER LIGHTS OUT...YELLOW MEDICS COMPARTMENT...YELLOW DRIVERS COMPARTMENT e41

Task performed:

- 1. replaced marker lights where needed.

Parts

Quantity

35200-YLIGHT MARKER LEDAMBER	4
------------------------------	---



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V15488

In Date: 06/03/2008
Close Date: 07/01/2008

Meter Reading: 29,740.00

Problem?

REPAIR A/C E41

Task performed:

1. recharged A/C system / checked for leaks

Parts

NO PARTS USED

Quantity

Workorder: V15523

In Date: 06/04/2008
Close Date: 07/01/2008

Meter Reading: 29,740.00

Problem?

replace bad harness for blower motor e41

Task performed:

a/c blower harness defective, replaced harness.

Parts

VCC/83000038AC WIRE HARNESS

Quantity

1

Workorder: V16238

In Date: 07/09/2008
Close Date: 07/22/2008

Meter Reading: 30,642.00

Problem?

replace rear tires at callagan

Task performed:

Replace rear tires at Callaghan j

Parts

NO PARTS USED

Quantity

Vendor?: CALLAGHAN

Workorder: V16295

In Date: 07/11/2008
Close Date: 07/23/2008

Meter Reading: 30,642.00

Problem?

repair foam leak e41

Task performed:

Foam leak; fnd fitting leaking & repaired. j

Parts

NO PARTS USED

Quantity



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V16385

In Date: 07/16/2008 Meter Reading: 30,642.00
Close Date: 07/23/2008

Problem?

repair pump comander e41

Task performed:

Installed new sender & tested system. j

Parts

100581TRANSDUCER COMMAND MASTER 300 PSI

Quantity

1

Workorder: V17133

In Date: 08/18/2008 Meter Reading: 31,166.50
Close Date: 08/20/2008

Problem?

on call e41 hurst unit wont start

Task performed:

repair the hurst power unit on e41. won't start.

Parts

NO PARTS USED

Quantity

Workorder: V17363

In Date: 08/27/2008 Meter Reading: 2,822.90
Close Date: 09/22/2008

Problem?

Steering is pulling to the right. E41

Task performed:

Road tested & tested ok. j

Parts

NO PARTS USED

Quantity

Workorder: V17274

In Date: 08/24/2008 Meter Reading: 2,822.90
Close Date: 10/07/2008

Problem?

Foam will only come out on tank water. Hydrant water was pumped 3 x intake pressure with no results of foam. All 3 drivers had same problem. E-41

Task performed:

1-tested system and tested ok

Parts

NO PARTS USED

Quantity



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V18167

In Date: 10/06/2008
Close Date: 10/15/2008

Meter Reading: 2,910.60

Problem?

Left front headlamp/highbeam is inoperative. The low beam is operational. E41

Task performed:

- 1-headlight inop, replaced head light on left side.
- 2-Replace dash, removed broken dash on bouth side and installed new ones.
- 3-Ram fan missing fleet/ motor moonts installed new feet and new motor moonts.
- 4-Relocated radio speacker, move radio speakers to dash.

Parts	Quantity
9005SX9005XS HIGH BEAM BULB	2
9006XSLLEHEADLAMP M2 HI	2

Workorder: V14008

In Date: 03/20/2008
Close Date: 10/28/2008

Meter Reading: 28,117.00

Problem?

repair a/c e41

Task performed:

- Rep bad connection on blower motor. j

Parts	Quantity
NO PARTS USED	

Workorder: V18492

In Date: 10/22/2008
Close Date: 10/28/2008

Meter Reading: 3,000.90

Problem?

Discharge number 4 leaking alot. e41

Task performed:

- Adj valve linkage on #4 valve. j

Parts	Quantity
15W40QSYN OIL QT	12



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V18740

In Date: 10/30/2008
Close Date: 11/05/2008

Meter Reading: 3,029.50

Problem?

rear roll up door electrical problem, door alarm will not shut off. e41

Task performed:

Parts

Quantity

Ck rear roll-up door ajar alarm going off; went to Stn41; rem magnet at switch; reinstalled; alarm still on; unplugged sensor; no change; cut/jumped wires at switch; no change; rem panels; unplugged lite & alarm.
j

NO PARTS USED

Workorder: V18681

In Date: 10/29/2008
Close Date: 11/06/2008

Meter Reading: 33,388.70

Problem?

FOAM FILL 10-7 E41

Task performed:

Parts

Quantity

Air leak; fnd no air leaks at this time... j

NO PARTS USED

Workorder: V18713

In Date: 10/30/2008
Close Date: 11/06/2008

Meter Reading: 33,736.00

Problem?

FOAM PICK-UP INOP, E-41

Task performed:

Parts

Quantity

Foam PU inop; FNP with foam pickup. j

NO PARTS USED

Workorder: V18719

In Date: 10/30/2008
Close Date: 11/06/2008

Meter Reading: 3,029.50

Problem?

leaking antifreeze fluid bottom of engine.e41

Task performed:

Parts

Quantity

coolant leak; fnd hose clamp loose. j

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V18741

In Date: 10/31/2008

Meter Reading: 33,736.00

Close Date: 11/18/2008

Problem?

door open alarm wont shut off e41

Task performed:

Door light on; traced problem with door open light; fnd bad grd. j

Parts

Quantity

R00011MAGNETS ROM DOORS

2

R00781R01078 SWITCH ROM ROLL UP DOOR

1

Workorder: V19219

In Date: 11/20/2008

Meter Reading: 33,736.00

Close Date: 11/25/2008

Problem?

CHECK ENG STOP ENG LT ON

Task performed:

Chk engine; stop eng light on; possible defective Eqr cooler; swapped out with (4) spare btrys. j

Parts

Quantity

NO PARTS USED

Workorder: V18785

In Date: 11/01/2008

Meter Reading: 3,029.50

Close Date: 12/01/2008

Problem?

rear roll down door sensor shows door open everytime you turn the batt switch on. E41

Task performed:

Traced out problem w/dooropen light; fnd 2nd switch was installed in door. j

Parts

Quantity

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V19355

In Date: 11/26/2008

Meter Reading: 46,352.00

Close Date: 12/15/2008

Problem?

C INSPECTION AND REPAIRS AS NEEDED E41

Task performed:

- 01-Perform C service.
- 02-Perform abbreviated nfpa low voltage electrical test. (as per management)
- 03-Serviced T case.
- 04-Rebuilt air dryer.
- 05-Replaced rear brakes shoes.
- 06-replaced engine air filter.
- 07-Replaced rear a/c filter.
- 08-Installed bolts and nuts in B3 compartment shelf to secured.
- 09-Replaced wiper blades, unclogged passenger side window washer & top off washer fluid.
- 10-Removed a/c clamp from a/c line, installed new insulated clamp to keep from rubbing hole in line.
- 11-Replaced pump panel gauge.(pressure leaking)
- 12-Replaced belts.
- 13-Rebuilt both primer pumps handle valves.
- 14-Replaced RPM cable head. also R&R cable to check
- 15-Rebuilt deck gun valve. (vacume leak).
- 16-Rebuilt #3 discharge.(vacume leak).
- 17-Rebuilt #1 discharge valve.(would not hold vacume) retested.
- 18-Rebuilt tank fill valve and adjust rod length. (would not hold vacume) retested, now holds vacume. start: 22 inches finished 19 inches.
- 19-Road tested truck, filled with water and ran pump.
- 20-Clean shop bay after C inspection

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
01-29866-118BELT ALT. M2	1
048009000SPEEDCOUNTER PUMP PANEL	1
073004100PISTON	1
15W40BSYN OIL BULK QTS	24
42809AIR FILTER M2	1
5008414CARTRIDGE DC100	1
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
91368904 VALVE KIT 1 1/2 IN	1
9550 BELT	1
PVG-KITORING KIT	2
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
KIT9081BRAKE HARDWARE KIT	2
800404USE K022105 PURGE KIT AD-IP-IS	1
91388906 VALVE KIT 2.5 IN AKRON	2
91398907 VALVE KIT 3 IN AKRON	1
94553941 USE 91553941 3.5 IN	1
CT4515METBRAKE LINNING	4

Workorder: V19242

In Date: 11/21/2008

Meter Reading: 33,736.00

Close Date: 01/13/2009

Problem?

repair egr cooler fla detroit

Task performed:

Repair EGR cooler - Florida Detroit j

Parts

Quantity

NO PARTS USED

Vendor?: FLORIDA DETROI



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V19220

In Date: 11/20/2008 Meter Reading: 33,736.00
Close Date: 01/14/2009

Problem?

TOW UNIT TO FLA DETROIT FT PIERCE

Task performed:

Tow unit to Fla Detroit Ft. Pierce - Sisters Towing j Parts ----- Quantity
NO PARTS USED

Vendor?: SISTERS TOWING

Workorder: V20291

In Date: 01/12/2009 Meter Reading: 3,155.00
Close Date: 01/27/2009

Problem?

Foam system 10-7 e41

Task performed:

1- Found selector knob hard to turn, greased up selector and tested. j Parts ----- Quantity
NO PARTS USED

Workorder: V20586

In Date: 01/26/2009 Meter Reading: 349,040.00
Close Date: 01/27/2009

Problem?

BRAKE LIGHTS INOP, BATTERY SWITCH INOP, E-41

Task performed:

Batry swtch not shutting off; replcd btry switch. j Parts ----- Quantity
75908SWITCH BATTERY MASTER 300A 1

Workorder: V20683

In Date: 01/29/2009 Meter Reading: 3,155.00
Close Date: 02/13/2009

Problem?

back up alarm and lights 10-7. E-41

Task performed:

No backup alarm & light; reprogrammed node & tested. j Parts ----- Quantity
NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V21157

In Date: 02/17/2009 Meter Reading: 3,208.00
Close Date: 02/25/2009

Problem?

E41 power steering fluid level @ low line

Task performed:

Chkd fluid line & ckd ok. j

Parts

NO PARTS USED

Quantity

Workorder: V21158

In Date: 02/17/2009 Meter Reading: 3,208.00
Close Date: 02/25/2009

Problem?

driver side high beam head light is out e41

Task performed:

Fnd no headlight out. j

Parts

9006XSLLEADLAMP M2 HI

1

Quantity

- 2. Gen no start; replcd plug.
- 3. Replcd headlight bulb.

Workorder: V21159

In Date: 02/17/2009 Meter Reading: 3,208.00
Close Date: 02/25/2009

Problem?

missing an electrical Y splitter for generator. Generator is currently only capable of running one light or just the fan. e41

Task performed:

DC will order new Y-connection. j

Parts

NO PARTS USED

Quantity

Workorder: V21160

In Date: 02/17/2009 Meter Reading: 3,208.00
Close Date: 02/25/2009

Problem?

driver and OIC side panel lights are missing light covers. e41

Task performed:

installed new covers on pump panel lights. j

Parts

01-06635060-C90PSC0CDCR STRIP LIGHT STEADY WHITE
68-3963453-30LENS CLEAR FOR STRIP LIGHT

1

2

Quantity



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V21161

In Date: 02/17/2009

Meter Reading: 3,208.00

Close Date: 02/25/2009

Problem?

Dewalt recip-saw is not working properly. When it is running it doesn't sound right. e41

Task performed:

Will have DC order new one. j

Parts

Quantity

NO PARTS USED

Workorder: V18010

In Date: 09/29/2008

Meter Reading: 2,910.60

Close Date: 03/02/2009

Problem?

Officer side dashboard broken. Screw clips are missing.e41

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V20081

In Date: 01/02/2009

Meter Reading: 3,155.00

Close Date: 03/02/2009

Problem?

foam selector a/b knob stuck...will not turn

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V21354

In Date: 02/26/2009

Meter Reading: 3,280.00

Close Date: 03/05/2009

Problem?

Head light high beam is burned out. Could not find any bulbs in the station. e41

Task performed:

replaced headlight bulb. j

Parts

Quantity

9006XSLLEHEADLAMP M2 HI

1



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V21297

In Date: 02/23/2009 Meter Reading: 3,297.80
Close Date: 03/06/2009

Problem?

there is a sound of air leaking. It took awhile for air to build up. e41

Task performed:

- Hurst unit not running; clnd carb/tested.
- Ram leaking oil; rep fitting on pump. j

Parts

NO PARTS USED

Quantity

Workorder: V21473

In Date: 03/02/2009 Meter Reading: 36,655.00
Close Date: 03/06/2009

Problem?

INSTALL BATTERY CHARGER AND AUTO EJECT

Task performed:

- Installed battery charger. j

Parts

0913912CHARGER 2000 1
 0915520120AUTO EJECT 20 AERO OTL3925 1
 91-20WIPER BLADE 20 IN 2
 91-22WIPER BLADE 2

Quantity

Workorder: V21520

In Date: 03/03/2009 Meter Reading: 3,280.00
Close Date: 03/06/2009

Problem?

ladder compartment door ajar sensor missing E41

Task performed:

- Rear switc h broken for ladder; replcd door swtch.
- Foam leak; rep foam leak at filter.
- Water level gauges out on sides;r ep c onnection at node #6.
- Air leak; traced out air leaks & rep where needed. j

Parts

SWT1277EL57755 SWITCH DOOR 2PCS

Quantity

1

Workorder: V21688

In Date: 03/10/2009 Meter Reading: 37,123.00
Close Date: 03/13/2009

Problem?

damage to left rear light bar E41

Task performed:

- Repair L/R upper light brkt asy & remount on truck. j

Parts

NO PARTS USED

Quantity



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V21864

In Date: 03/17/2009
Close Date: 03/23/2009

Meter Reading: 37,123.00

Problem?

repair cab light e41

Task performed:

1. Lights out in rear of truck; fnd bad connection in rear.
2. Cab lights out; rep door swtch which turns on cab lights.
3. Night fighter lights out. rep broken wires. j

Parts	Quantity
4007BULB NIGHT FIGHTER	2

Workorder: V21963

In Date: 03/20/2009
Close Date: 04/03/2009

Meter Reading: 37,448.60

Problem?

REPLACE COMMAND MASTER, E-41

Task performed:

- Traced out problem w/command master; fnd water i connectors. j

Parts	Quantity
111085COMMAND MASTER CLASS 1	2

Workorder: V22061

In Date: 03/25/2009
Close Date: 04/10/2009

Meter Reading: 3,340.70

Problem?

the garden hose fill valve, faucet handle, is broken and needs to be replaced e41

Task performed:

- Replcd garden hose fill valve that was broken. j

Parts	Quantity
NO PARTS USED	

Workorder: V21851

In Date: 03/16/2009
Close Date: 04/17/2009

Meter Reading: 37,123.00

Problem?

Right rear scene spot light out. e41

Task performed:

- Repl cd spotlight bulb. j

Parts	Quantity
4537BULB 100W SPOT	1



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V22330

In Date: 04/06/2009 Meter Reading: 37,448.60
Close Date: 04/17/2009

Problem?

OJN CALL NO EME LTS E41

Task performed:

No emergency lighths; fnd bad connection. j

Parts

RSR03ZCRLIGHT LED RED TIR3 SERIES

Quantity

1

Workorder: V22363

In Date: 04/06/2009 Meter Reading: 38,155.60
Close Date: 04/17/2009

Problem?

ADJUSTMENT FOR STEERING WHEEL BROKEN e41

Task performed:

Adjustment for steering column brkn; replcd steering wheel adjustment. j

Parts

012-0010-00KNOB DRAIN

7605-666764-0023 SWITCH FOOT SIREN

RGT-452258FFOOT PEDAL STERRING COLUMN

RGT401737ESPRING PEDAL RETURN

TRW401741CSRING CABLE EXTENSION

Quantity

1

1

1

1

1

Workorder: V22541

In Date: 04/14/2009 Meter Reading: 3,427.60
Close Date: 04/20/2009

Problem?

pump primer not working E41

Task performed:

Replaced faulty primer. j

Parts

501-3090-00PRIMER PUMP MOTOR

Quantity

1

Workorder: V22262

In Date: 04/01/2009 Meter Reading: 37,448.60
Close Date: 04/23/2009

Problem?

Windshield fluid is not spraying. Thanks. e41

Task performed:

Rep windshield washer for window. j

Parts

NO PARTS USED

Quantity



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V22294

In Date: 04/02/2009
Close Date: 04/23/2009

Meter Reading: 3,340.70

Problem?

left rear side lower stobe out, under generator compartment E-41

Task performed:

Parts

Quantity

1. Rear LED inop; replcd rear LED lite.
 2. Compt lites out on L-side inop; rep bad connection on swtch.
 3. Pump leaking water; fnd fitting on pump leaking & rep
 4. Fuel gauge on pump panel inop; rep bad connection.
- j

NO PARTS USED

Workorder: V22295

In Date: 04/02/2009
Close Date: 04/23/2009

Meter Reading: 3,340.70

Problem?

windshied wiper fluid will not spray on windshield. only covers bottom 6 inches E-41

Task performed:

Parts

Quantity

Rep windshield wiper washers. j

NO PARTS USED

Workorder: V23023

In Date: 05/04/2009
Close Date: 05/04/2009

Meter Reading: 38,584.00

Problem?

replace 4 rear tires E41 (outside agency-callaghan tire)

Task performed:

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V22978

In Date: 05/01/2009
Close Date: 05/21/2009

Meter Reading:

Problem?

cab dash a/c not working e41

Task performed:

Parts

Quantity

1. A/C inop; replcd blower motor.
2. Water leak; rep leak on pump.
3. Cab doors hard to close; adj doors. j

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V23180

In Date: 05/10/2009

Meter Reading:

Close Date: 05/26/2009

Problem?

A/C blower motor not working E-41

Task performed:

- 1. Replcd blower motor & tested.
- 2. Roof leaking water; resealed top of roof. j

Parts

Quantity

VCC/35000003BLOWER MOTOR VCCT1000904A M2

1

VCC/83000038AC WIRE HARNESS

1

Workorder: V23529

In Date: 05/26/2009

Meter Reading: 38,584.00

Close Date: 06/02/2009

Problem?

CHAIN SAW10-7

Task performed:

- rep chain saw that wld not start. j

Parts

Quantity

NO PARTS USED

Workorder: V23965

In Date: 06/10/2009

Meter Reading: 3,516.00

Close Date: 07/06/2009

Problem?

The charger for the T.I.C. does not work. The spare battery will charge, not the unit when in the cradle. E41

Task performed:

- Remounted TIC charger & rep.

Parts

Quantity

NO PARTS USED

j

Workorder: V23994

In Date: 06/11/2009

Meter Reading: 3,516.00

Close Date: 07/06/2009

Problem?

Swap location of TIC charger and flashlight. e41

Task performed:

- Rem handlights & relocated tic charger. j

Parts

Quantity

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V24386

In Date: 06/26/2009 Meter Reading: 3,516.00
Close Date: 07/08/2009

Problem?

Emergency light switch is sticking in the on position. E41

Task performed:

Parts

Quantity

1. Rear light bar inop; rep left rear LED light.
2. Chain saw inop; rep/tested. j

NO PARTS USED

Workorder: V24091

In Date: 06/15/2009 Meter Reading: 39,615.00
Close Date: 07/09/2009

Problem?

replace 2 front tires E41 (outside agency-callaghan tire)

Task performed:

Parts

Quantity

Replace (2) front tires E41 - Callaghan j

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V24932

In Date: 07/21/2009 Meter Reading: 3,516.00
Close Date: 08/05/2009

Problem?

front blinker light drivers side not working.

Task performed:

Parts

Quantity

1. Gen not inop; rep fuel ine on unit.
2. turn signals not working in frnt; fnd shorted wire; rep/tested.
3. Cab A/C not blowing air; fnd bad connection i blower motor. j

NO PARTS USED

Workorder: V25693

In Date: 08/21/2009 Meter Reading: 41,787.00
Close Date: 08/26/2009

Problem?

VISTA SCREEN FAILED, E-41

Task performed:

Parts

Quantity

Emergency lights rear A/C vista screen inop; burnt wire feeding brkr bus bar; rep wiring to bus bar; rplc brkr & rep relay wiring. j

54-140CIRCUIT BREAK 40 AMP

1



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V25880

In Date: 08/29/2009
Close Date: 09/02/2009

Meter Reading: 3,692.10

Problem?

electrical controll panel not secure inside of cab that controls all the electrical functions. E41

Task performed:

Parts

Quantity

Fnd vista screen loose; rem center console; replc msg bolts/nuts; rem screen; reassemble all parts; went to Stn32. j

NO PARTS USED

Workorder: V25551

In Date: 08/15/2009
Close Date: 09/14/2009

Meter Reading: 41,448.00

Problem?

UNABLE TO MOVE HOSE DIVIDER IN BED FOR BLITZ LINE. LOOKING FOR SUGGESTIONS. E41

Task performed:

Parts

Quantity

1. Moved hose bed divider over.
2. Preconnect leaking; adj linkage & tested.
3. Air leak; traced out air leaks. j

NO PARTS USED

Workorder: V25935

In Date: 08/31/2009
Close Date: 09/21/2009

Meter Reading: 3,692.10

Problem?

vent saw would not start in am, thought i flooded. waited till late afternoon and still couldnt start. e41

Task performed:

Parts

Quantity

Cld not start; rem spark plug; cldn plug; started/adj fuel/mixture screws; ck opn; ck ok; went to Stn45. j

NO PARTS USED

Workorder: V25677

In Date: 08/21/2009
Close Date: 09/23/2009

Meter Reading: 41,787.00

Problem?

REAR LED LIGHT, E-41

Task performed:

Parts

Quantity

1. Rep rear light bar that had bad grd.
2. Air seat officers side inop; rep air ine. j

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V25575

In Date: 08/17/2009

Meter Reading: 41,448.00

Close Date: 09/25/2009

Problem?

B INSPECTION AND REPAIRS AS NEEDED E41

Task performed:

1. B-Inspection
2. Rear brakes worn; replc rear brakes.
3. Sec/remount hose bed & blitz ines S.O.P.; installed straps & brkts for hose bed blitz lines.
4. Washers inop; nozzles clogged; clnd out nozzle lines & flushed out tank; ordere new tank cap.
5. Deck gun rotation lock inop - worn; replcd rotator lock.
6. A/C filters clogged; replc cab filter & clnd rear filter.
7. Ram fan inop; stalls under load; clnd out carb jet; replc fuel & oil; torqued fan bolt.
8. Backup camera inop - shield wire touching signal wire in connector; located & rep wiring problem.
9. Btry box wont open; screws loose & stripped; rep track screw & cln & lubed.
10. Dog house screw stripped; drilled/tapped new thrds & rep loose cover.
11. Door open alarm inop; open connector in overhead compt; rep door alarm wiring.
12. L-3 compt shelf loose & missing hardware; rep shelf.
13. Tires pulls to the right; swapped front tires. j

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
15W40BSYN OIL BULK QTS	4
22-58581-000WASHER RESIVOR CAP	1
25-358SWITCH COVER	2
3576REAR BRAKE DRUMS	2
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
FREIGHTSHIPPING CHARGES	1
KIT9081BRAKE HARDWARE KIT	2
ABM-1BASE MOUNT ALUMINUM	3
B480AREFLECT-AMBER	2
CT4515METBRAKE LINNING	4
R00523LENS FOR ROLL UP DOOR LIGHT FARRARA	10
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
UMVS162511STRAP	4
UMVS254411STRAP 46 IN	2
VCC/36000006A/C FILTER CAB M2	1
X170DECK GUN ROTATION LOCK INSERT	1

Workorder: V26814

In Date: 10/12/2009

Meter Reading: 3,737.00

Close Date: 10/21/2009

Problem?

medical compartment alarm wont turn off in cab. mechanic called and worked on but did not have all parts. sts will return. E41

Task performed:

1. Door open warning stays on; ordered new sensor. j

Parts	Quantity
R00011MAGNETS ROM DOORS	2
R00781R01078 SWITCH ROM ROLL UP DOOR	2



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V26700

In Date: 10/06/2009 Meter Reading: 3,737.00
Close Date: 11/06/2009

Problem?

Leaf Blower leaking gas from hose. 10-7 e41

Task performed:

Parts ----- Quantity

1. Rep leaf blower that was leaking gas.
2. Gen inop; rep con-off switch. j

NO PARTS USED

Workorder: V26968

In Date: 10/19/2009 Meter Reading: 42,283.00
Close Date: 11/12/2009

Problem?

DOOR ALARM GONG OFF E41

Task performed:

Parts ----- Quantity

1. Door alarm going off; rep door switch.
2. K12 saw inop; cln carb & tested. j

NO PARTS USED

Workorder: V23854

In Date: 06/05/2009 Meter Reading: 3,516.00
Close Date: 12/01/2009

Problem?

TIC batteries not holding a charge. Need to be replaced.

Task performed:

Parts ----- Quantity

see 23965

NO PARTS USED

Workorder: V24336

In Date: 06/25/2009 Meter Reading: 3,516.00
Close Date: 12/01/2009

Problem?

please check emergency lights push button for the on and off switch, it sticks causing lights to remain on. switch is located on the console.R41

Task performed:

Parts ----- Quantity

Replcd emergency switch that was not working. j

OK00-1958-00KEY PAD 7 POSITION

1



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V27018

In Date: 10/20/2009
Close Date: 12/04/2009

Meter Reading: 42,283.00

Problem?

chain saw on E41 starts but does not continue running. r41

Task performed:

Tested saw & tested ok.

j

Parts

Quantity

NO PARTS USED

Workorder: V28183

In Date: 12/08/2009
Close Date: 01/15/2010

Meter Reading: 44,220.00

Problem?

door open light 10-7 E41

Task performed:

Rep R-4 door switch.

j

Parts

Quantity

NO PARTS USED

Workorder: V28686

In Date: 12/30/2009
Close Date: 01/15/2010

Meter Reading: 3,899.00

Problem?

Computer control relief valve was not operating, causing engine to pump discharges at 200 psi before opening. Had to gate down discharges. If a line was shut down it would fill with 200 psi. e41

Task performed:

Ran pump & tested relief valve & tested ok. j

Parts

Quantity

NO PARTS USED

Workorder: V28840

In Date: 01/05/2010
Close Date: 02/22/2010

Meter Reading: 3,899.00

Problem?

rubber holder for t.i.c. ripped, needs to be replaced. E41

Task performed:

Replaced rubber holder on tic.

j

Parts

Quantity

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V29165

In Date: 01/15/2010
Close Date: 02/22/2010

Meter Reading: 3,899.00

Problem?

With pump engaged, smart pump screen was blank. Had to turn of battery and restart to make work. Heads up.

Task performed:

Tested pump & chkd out ok; will monitor. j

Parts

NO PARTS USED

Quantity

Workorder: V30601

In Date: 03/09/2010
Close Date: 03/17/2010

Meter Reading: 46,352.00

Problem?

driver side above pump panel spot light E41 out. middle light only.

Task performed:

replace rt side middle flood light

2. Rep grnd wire for spotlight. j

Parts

4007BULB NIGHT FIGHTER

Quantity

1

Workorder: V29118

In Date: 01/13/2010
Close Date: 03/19/2010

Meter Reading: 3,899.00

Problem?

Driver side head light bulb burned out. E41

Task performed:

1. Replcd headlight.

2. Air leak; traced out air leaks & rep. j

Parts

NO PARTS USED

Quantity

Workorder: V29829

In Date: 02/09/2010
Close Date: 03/19/2010

Meter Reading: 44,220.00

Problem?

Need Synthetic motor oil at station. Dip stick on E41 shows no oil. Also could use some radiator fluid. Thanks

Task performed:

Air leak; rep leak at drivers seat. j

Parts

NO PARTS USED

Quantity



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V29946

In Date: 02/12/2010
Close Date: 03/29/2010

Meter Reading: 46,352.00

Problem?

Officer side LED lense over discharge fell off. E41

Task performed:

Rep lite that was falling off. j

Parts

Quantity

NO PARTS USED

Workorder: V30523

In Date: 03/07/2010
Close Date: 04/21/2010

Meter Reading: 46,352.00

Problem?

drivers side scene light, by pump panel, middle flood or spot light out E41

Task performed:

rep rear spotlight that had bad grd. j

Parts

Quantity

NO PARTS USED

Workorder: V31354

In Date: 04/08/2010
Close Date: 04/28/2010

Meter Reading: 46,352.00

Problem?

on call coolant leak E41

Task performed:

Went to shop for parts to rep coolant leak; cld not find parts; called Ed Woodland; parts not in stock. Rep coolant leak; brkn clamp replaced. j

Parts

Quantity

NO PARTS USED

Workorder: V31812

In Date: 04/26/2010
Close Date: 04/30/2010

Meter Reading: 46,352.00

Problem?

engine shutdown light on (on-call) E41

Task performed:

Chkd codes; fnd truck low on coolant; top off coolant. j

Parts

Quantity

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V31568

In Date: 04/15/2010 Meter Reading: 46,352.00
Close Date: 05/11/2010

Problem?

replace rear tires boulevard tire

Task performed:	Parts	Quantity
Replace rear tires - Boulevard j	NO PARTS USED	

Vendor?: BOULEVARD TIRE

Workorder: V32356

In Date: 05/21/2010 Meter Reading: 46,352.00
Close Date: 06/03/2010

Problem?

ON CALL CHECK ENG LT ON E41

Task performed:	Parts	Quantity
Fnd code I computer; coolant level; add 2-1/2 gal of coolant; may need EGR cooler. j	ALA00350-50 EXTENDED LIFE COOLANT GAL	3

2. Fnd low on coolant; refilled. j

Workorder: V32355

In Date: 05/21/2010 Meter Reading: 46,352.00
Close Date: 06/10/2010

Problem?

poss erg per mechanic, check engine light activated. poss coolant leak, mechanic will advise shop in the am. E41

Task performed:	Parts	Quantity
Fnd low on coolant; refilled; will monitor. j	NO PARTS USED	

Workorder: V32495

In Date: 05/28/2010 Meter Reading: 46,352.00
Close Date: 06/25/2010

Problem?

Engine coolant levels drop. Add approx 1 gallon every 4-5 days. No puddles. E41

Task performed:	Parts	Quantity
Press tested; fnd no leaks at this time. j	NO PARTS USED	



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V31955

In Date: 05/03/2010
Close Date: 06/28/2010

Meter Reading: 46,352.00

Problem?

Dial for the foam system is stuck in the off position. It will not turn in either direction. The engine is unable to supply foam. E41

Task performed:

worked on foam valve; will have rep at B-Inspection. j

Parts

NO PARTS USED

Quantity

Workorder: V32268

In Date: 05/18/2010
Close Date: 06/28/2010

Meter Reading: 46,352.00

Problem?

PUMP PANEL SHOWS CHECK ENGINE WITH AN ALARM SOUNDING SIMILAR TO THE TANK LOW/EMPTY ALARM. e41

Task performed:

1. Chk eng alarm; reset eng status center & road tested.
2. Map lite inop; replcd map lite. j

Parts

LF18TS-LEDMAP LIGHT LED 18 IN

1

Quantity

Workorder: V32435

In Date: 05/25/2010
Close Date: 06/28/2010

Meter Reading: 46,352.00

Problem?

A/C blower motor not working in dashboard. Foam nob unable to turn on pump panel. E41

Task performed:

A/C blower inop; fnd bad connection at motor; rep/tested. j

Parts

NO PARTS USED

Quantity



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V32510

In Date: 05/28/2010

Meter Reading: 49,648.00

Close Date: 07/13/2010

Problem?

C INSPECTION AND REPAIRS AS NEEDED E41 COOLANT LEAK POSSIBLE EGR PRESSURE GOV. CONVERSION

Task performed:

Parts

Quantity



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

1. Changed out gov controls.	000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
2. Installed tank level light conversion for rainbow ights on body.	0000902051FILTER FUEL 03 MERCEDES	1
3. C-Inspection	0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
4. Replcd heat stickers on all (3) ladders.	008-0070-00-0SPEEDCOUNTER CAP	1
5. Replc all (4) btrys.	15W40BSYN OIL BULK QTS	24
6. Svc diff.	15W40QSYN OIL QT	5
7. Svc T-case.	219496LABLE	8
8. Svc air brake dryer.	35200-RLIGHT MARKER LED RED	1
9. Svc trans.	42809AIR FILTER M2	1
10. Svc cooling sys.	5720USE 5764 COMPRESSOR A/C OLD #03-3405	1
11. Replcd EGR cooler & EGR valve; leaking coolant.	68-3963453-30LENS CLEAR FOR STRIP LIGHT	1
12. Replc upper rad hose clamp;; brkn/leaking.	78R536078R5360M 2PK FILTER AIR COND	1
13. Replc wiper blades.	906-181-00-86OIL FILTER M2 SPINNER 57140	1
14. R/R windshield squirters & clean - clogged.	91-22WIPER BLADE	1
15. Replce frt & rear cab A/C filter.	91398907 VALVE KIT 3 IN AKRON	1
16. Replcd L/hi-beam headlight bulb.	91523933 GAUGE VAC/PRESS.	1
17. Painted fuel cap yellow.	91553941GAUGE	2
18. Replcd L&R crosslay nozzle holders & mntng brkts - bent/rusted.	9550 BELT	1
19. Lube/adj L/rear upper compt door latch - binding/bent.	EA9061420619RA9061420619 EGR VALVE	1
20. Replcd L/side pump panel light lens & rewired; lens was msgng & lights had a faulty grnd.	0913912CHARGER 2000	1
21. Replcd R/frnt door sill - brkn.	104967DIAPHRAM FOR 6 PORT DUMP VALVE	1
22. Foam sys in tank level sensor; R/R tank sensor & replc; (given the wrng sensor by parts dept).	ALA00350-50 EXTENDED LIFE COOLANT GAL	1
23. C/O low changing condition; clnd all frame grnd & chkd/clnd all positive connections; traced problem to faulty alt; replc alt; now charging 14.1.	0915520120AUTO EJECT 20 AERO OTL3925	1
24. A/C compressor, dryer & expansion valve for rear A/C unit.	105244CAPTAIN PRESSURE GOV CLASS ONE	1
25. Replcd A/C belt - did not have fan belt in stock.	108661ENFO IV	1
26. Svc frt A/C sys; also recvrd, vac & recharge.	110346PIGTAIL ENFO IV	2
27. Replcd eng air cleaner.	3030362LIGHT DRIVER	1
28. Relocated garden hose tank fill frm left side of truck to right side of truck - fire fighter request.	394880TANK MAST 49.5 DEPTH	1
29. Rebuilt primer valve - seized/sticking.	480377FOAM LEVEL GAUGE AND SENDER	1
30. R/R hose for hose reel to inspect for cracks; hose ok'd by Eddie E.	16-3007TAPE 8990	1
31. rebuilt master drain valve - seized/brkn.	160012-2012A EXPANSION VALVE 71R8301	1
32. Svc gen/ram fan; fuel in tanks old; drained/treated w/stabil.	18-46375-00118-46375-005 TREAD PLATE RH M2	1
33. Foam cntrl knob won't turn; rem valve; complete rebuild; kit not avail; replc o-rings & reassembled valve; put back in pump panel; test opn.	194BULB	1
34. Tighten mntng of L2 & R3 compt brkt.	29526898 29548988 TRANS FILTER ALLISON	1
35. Loose wire under tailboard; sec wires w/tie straps.	5008414CARTRIDGE DC100	1
36. Both pass side air pack release on wrong side; rem brkts & switch release.	35200-YLIGHT MARKER LEDAMBER	1
37. L/rear seat belt twisted; rem mntng & untwisted seat belt.	372000084MARKER LIGHT	1
38. Shore charger inop;blown fuse at autocharger; replc fuse/lug in.	55845584 WELD IN PORT	1
	9005SX9005XS HIGH BEAM BULB	1
	91388906 VALVE KIT 2.5 IN AKRON	2
	923182-2151 SWITCH MOMENTARY 24-372	1
	A9061420580GASKET	1
	A90614206791EA9061421179 EGR COOLER	1
	A9061420880GASKET	1
	A9061421080GASKET EGR COOLER	1



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

- 39. Trans cooler hose rubbing cross member; sec hose away frm cross member.
- 40. Did not pas vac test; fnd (2) 2-1/2" leaking; rebuilt valves; still not pass; fnd hosebed discharge 3" leaking; rebuilt/test again; all ok.
- 41. RPM cntr inop; cable too short; lengthen cable. j

DDE/A0039973352EGR COOLING HOSE	2
A0014949PA4949PA/4962 320 AMP UPGRADE SADDLE MC	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
BPR5ESSPARK PLUG 7734	1
BPR6ESSPARK PLUG 7131	1
HP-31DBATTERY 950CCA HP-31D	4
K022105PURGE VALVE AD-IP-IS	1
RD-5-7063-OP07-2618A A/C DRIER 7155	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	2
VCC/36000006A/C FILTER CAB M2	1
PVG-KITORING KIT	1
M-284-01SWITCH BATTERY MASTER	1

Workorder: V33250

In Date: 06/30/2010 Meter Reading: 46,352.00
Close Date: 07/16/2010

Problem?

replace hose bed cover central

Task performed:

Replc hose bed cover - Cental Auto j

Parts

NO PARTS USED

Quantity

Vendor?: CENTRAL AUTO

Workorder: V33302

In Date: 07/02/2010 Meter Reading: 46,352.00
Close Date: 07/23/2010

Problem?

repair front a/c blower 10-7 E41

Task performed:

- 1. R/R blower motor asy; R/R blower wiring harness/connector.
- 2. Deliver E41 to Stn41 & return to C/S. j

Parts

VCC/35000003BLOWER MOTOR VCCT1000904A M2
VCC/83000038AC WIRE HARNESS

Quantity

1
1

Workorder: V33946

In Date: 08/02/2010 Meter Reading: 46,352.00
Close Date: 08/12/2010

Problem?

pump noise E41 (callout repair)

Task performed:

Fnd pump RPM countercable strip; need new cable & drive gear; deferred to next PM for repair. ja

Parts

NO PARTS USED

Quantity



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V33762

In Date: 07/23/2010
Close Date: 08/16/2010

Meter Reading: 46,352.00

Problem?

compression fitting blew off tank fill line, in pump panel, fixed this a.m. by tommy R41

Task performed:

Pump leak; fnd wtr line fell off; rep/tested. j

Parts

NO PARTS USED

Quantity

Workorder: V33906

In Date: 07/30/2010
Close Date: 08/30/2010

Meter Reading: 46,352.00

Problem?

Hurst power unit on E41 (10163049) 10-7 with oil leak.

Task performed:

1. Ran Hurst unit & fnd leak at fitting & replcd.
2. Pump leak; rep leak at primer motor. ja
3. Diss, replc sight glass, fill. js

Parts

180R002HURST HYD. FLUID QT
V84156730154SIGHT GLASS/ORING SIMO

Quantity

4
1

Workorder: V33933

In Date: 07/31/2010
Close Date: 09/08/2010

Meter Reading: 46,352.00

Problem?

e41 cable to verify rpm for pump test broken. mechanic mcintosh in to look at it. will be fixed at next maintenance. E41

Task performed:

1. Air leak; rep leak at tank.
 2. Door open alarm going off; readj door switches.
- j

Parts

NO PARTS USED

Quantity

Workorder: V34760

In Date: 09/05/2010
Close Date: 10/20/2010

Meter Reading: 46,352.00

Problem?

rear a/c on E41 is not working

Task performed:

Traced out problem w/no rear A/C; fnd shorted wires; installed new relay. j

Parts

38083075551 75 AMP RELAY

Quantity

1



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V35776

In Date: 10/19/2010

Meter Reading: 52,098.00

Close Date: 11/09/2010

Problem?

break lights on E41 10-7

Task performed:

Replc air valvwe for brake lights. j

Parts

Quantity

NRG-27-SWA-010R BRAKE NGR-27-SWA-110R MODULE M

1

Workorder: V35722

In Date: 10/18/2010

Meter Reading: 52,098.00

Close Date: 11/16/2010

Problem?

air brake system is leaking (green ldh) hurst tool fluid is low on the power unit

Task performed:

1. inspected truck, repaired air leaks.
2. repaired hurst unit that was leaking. jab

Parts

Quantity

NO PARTS USED

Workorder: V36981

In Date: 12/07/2010

Meter Reading: 52,098.00

Close Date: 12/07/2010

Problem?

parts only for vent saw E41

Task performed:

Parts

Quantity

TV426-026SAW GAURD

1

Workorder: V36368

In Date: 11/10/2010

Meter Reading: 53,597.00

Close Date: 12/15/2010

Problem?

noise noted and pull to the left when you apply brakes. E41

Task performed:

(1) TRAVELED TO STATION 41 TO CHECK OUT E41 FOR PULLING TO THE LEFT AND NOISE WHEN APPLYING THE BRAKES. ROAD TESTED, CHECKED FOR NOISE AND BRAKES PULLING TO THE LEFT, ALL CHECKED OUT OK. J.W.

Parts

Quantity

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V37782

In Date: 01/13/2011 Meter Reading: 56,377.00
Close Date: 01/24/2011

Problem?

middle spotlight on pumpanel not working. driver side. E41

Task performed:

(1) SEE # V37785 LINE 6. J.W.

Parts

NO PARTS USED

Quantity

Workorder: V37785

In Date: 01/13/2011 Meter Reading: 56,406.00
Close Date: 01/24/2011

Problem?

B INSPECTION AND REPAIRS AS NEEDED E 41

Task performed:

- (1) "B" INSPECTION AND NEEDED REPAIRS.
- (2) R&R REAR BRAKES.
- (3) R&R ONE BATTERY.
- (4)R&R RT REAR BRAKE SHOES.
- (5) R&R BOTH BELTS.
- (6) REPAIR COMPARTMENT TRACK LIGHT AND BULB ON SPOTLIGHT.
- (7) R&R DISCHARGE #1, REBUILT VALVE & REPAIRED LEFT INTAKE DRAIN HANDLE.
- (8) REPAIRED STRAP ON TIC CHARGER.
- (9) ROAD TEST & FILLED TANK WITH H2O.
- (10) Q&A INSPECTION.
- (11) CHECKED FAST IDLE AND FOUND BROKEN WIRE.ISCB46 REPAIRED. TALKED TO KEVIN AT FARRARA.
- (12) CHECKED FOAM PUMP AND FOUND PUMP STUCK. REMOVED, CLEANED AND LUBED IT. TESTED GOOD. REINSTALLED BACK IN. J.W.

Parts

- 000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT 1
- 0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH 1
- 01-29866-118BELT ALT. M2 1
- 0773094TRUNNION 1
- 15W40BSYN OIL BULK QTS 30
- 906-181-00-86OIL FILTER M2 SPINNER 57140 1
- 91388906 VALVE KIT 2.5 IN AKRON 1
- 9550 BELT 1
- CT4515METBRAKE LINNING 4
- 322502BULB PATIENT GH22 2
- 4007BULB NIGHT FIGHTER 1
- 8550A250A8550A250A BULB 1
- 3576REAR BRAKE DRUMS 2
- BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY 1
- HP-31DBATTERY 950CCA HP-31D 1
- KIT9081BRAKE HARDWARE KIT 2
- R00523LENS FOR ROLL UP DOOR LIGHT FARRARA 16
- S3226FL02FUEL FILTER 33813 L/F # LFF5851 1

Quantity



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V37799

In Date: 01/14/2011 Meter Reading: 56,377.00
Close Date: 01/27/2011

Problem?

replace 2 front tires E41(outside agency-TCI Tire)

Task performed:

Replace (2) frnt tires E41 - TCI Tire j

Parts

Quantity

NO PARTS USED

Vendor?: TCI TIRE

Workorder: V37431

In Date: 12/27/2010 Meter Reading: 55,422.00
Close Date: 02/07/2011

Problem?

driver side middle spotlight out. E41

Task performed:

Rep spotlight that was out.
2. Rep handlights that were not working. j

Parts

Quantity

NO PARTS USED

Workorder: V37634

In Date: 01/04/2011 Meter Reading: 55,910.00
Close Date: 02/07/2011

Problem?

Strap for the "TIC" is broken. E41

Task performed:

1. Rep strap for tic charger.
2. Air leak; rep leak at air tank & rechkd. j

Parts

Quantity

NO PARTS USED

Workorder: V37702

In Date: 01/10/2011 Meter Reading: 55,910.00
Close Date: 02/08/2011

Problem?

need engine oil for station E41

Task performed:

1. Dropped off oil at stn.
2. Rep auto-eject plug; fnd bad connection. j

Parts

Quantity

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V37728

In Date: 01/10/2011
Close Date: 02/08/2011

Meter Reading: 56,085.00

Problem?

STATION 41 HAS NO MOTOR OIL. E41 TOOK 6-8 QUARTS AT SOUTH SHOP TODAY. PLEASE DELIVER TO 41 ASAP E41

Task performed:

dropped off oil. j

Parts

15W40QSYN OIL QT

Quantity

12

Workorder: V37757

In Date: 01/12/2011
Close Date: 02/08/2011

Meter Reading: 56,313.10

Problem?

the strap on the TIC is broken E41

Task performed:

Rep strap on tic charger that fell off. j

Parts

NO PARTS USED

Quantity

Workorder: V38039

In Date: 01/25/2011
Close Date: 03/08/2011

Meter Reading: 56,595.00

Problem?

battery charger cord does not pop out on drivers side of engine when you start the truck. E41

Task performed:

Installed new auto-eject plug & tested. j

Parts

NO PARTS USED

Quantity

Workorder: V38916

In Date: 03/02/2011
Close Date: 04/08/2011

Meter Reading: 58,719.00

Problem?

REPLACE REAR TIRES E41

Task performed:

Replc rear tires E41 - Boulevard j

Parts

NO PARTS USED

Quantity

Vendor?: BOUOLEVARD



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V39510

In Date: 03/29/2011 Meter Reading: 59,651.00
Close Date: 04/13/2011

Problem?

headlight out on passenger side. E41

Task performed:

Replcd headlight. j

Parts

Quantity

NO PARTS USED

Workorder: V39609

In Date: 04/01/2011 Meter Reading: 59,793.00
Close Date: 05/05/2011

Problem?

wipers come on when they are in the off position, sta 41.

Task performed:

Replcd wiper switch. j

Parts

Quantity

A06-36956-000A06-36956-003 WIPER-TURN SWITCH

1

Workorder: V39836

In Date: 04/11/2011 Meter Reading: 60,054.40
Close Date: 05/09/2011

Problem?

coolant low...none in station, Sta.41.

Task performed:

Dropped off coolant at stn; chkd for leaks at coolant tank. j

Parts

Quantity

NO PARTS USED

Workorder: V40674

In Date: 05/17/2011 Meter Reading: 61,259.00
Close Date: 05/17/2011

Problem?

check engine fan for cracks, E-41

Task performed:

1.travel to sta-41
2.check engine fan for cracks, no cracks found

Parts

Quantity

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V40375

In Date: 05/03/2011

Meter Reading: 60,769.00

Close Date: 06/02/2011

Problem?

battery charger guage on outside connection does not show positive charging on engine41.

Task performed:

Rep bad connection on charger. j

Parts

Quantity

NO PARTS USED

Workorder: V40396

In Date: 05/04/2011

Meter Reading: 60,835.00

Close Date: 06/02/2011

Problem?

E41 ~ T.I.C. not holding a charge. Spare battery not charging. Sta 41.

Task performed:

Rep contacts on charger & tested. j

Parts

Quantity

NO PARTS USED

Workorder: V40416

In Date: 05/04/2011

Meter Reading: 60,835.00

Close Date: 06/03/2011

Problem?

TIC DOES NOT APPEAR TO BE CHARGING AND SPARE BATTERY CHRAGE LIGHT IS NOT ON AND BATTERY IS DEAD E4

Task performed:

Rep tic charger & tested. j

Parts

Quantity

NO PARTS USED

Workorder: V41139

In Date: 06/06/2011

Meter Reading: 61,742.00

Close Date: 06/08/2011

Problem?

*

Task performed:

Fnd fault code for remote throttle; FF said throttle drops out after switching frm pump to road gear. j

Parts

Quantity

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V41199

In Date: 06/08/2011 Meter Reading: 61,900.60
Close Date: 06/08/2011

Problem?

hurst power unit low on fluid, E-41

Task performed:

1. check hurst fluid level, add fluid and run unit

Parts	Quantity
180R002HURST HYD. FLUID QT	2

Workorder: V40707

In Date: 05/18/2011 Meter Reading: 61,321.00
Close Date: 06/09/2011

Problem?

spotlight on pump panel officer side middle light out when switch to officer side. E41

Task performed:

Rep grnd on pump panel for lights. j

Parts	Quantity
NO PARTS USED	

Workorder: V40877

In Date: 05/26/2011 Meter Reading: 61,511.00
Close Date: 06/28/2011

Problem?

E41 - T.I.C. strap broken. Needs two new batteries. They will not hold a charge.

Task performed:

Replaced tic strap ak

Parts	Quantity
NO PARTS USED	

Workorder: V41098

In Date: 06/03/2011 Meter Reading: 61,742.00
Close Date: 06/28/2011

Problem?

battery shore line not charging and not plugging in properly R41

Task performed:

rewired unit and tested all tested good ak

Parts	Quantity
NO PARTS USED	



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V41351

In Date: 06/15/2011
Close Date: 07/11/2011

Meter Reading: 61,992.30

Problem?

SHORELINE NOT CHARGING. PLUGED IN SHOWS 1 BAR ALL THE TIME. Sta 41.

Task performed:

Rep bad connection on charger. j

Parts

Quantity

NO PARTS USED

Workorder: V41573

In Date: 06/24/2011
Close Date: 07/19/2011

Meter Reading: 62,354.00

Problem?

tic not charging battery dead. Sta 41.

Task performed:

CLEAN CONTACTS ON TIC AND TESTED OK AK

Parts

Quantity

NO PARTS USED

Workorder: V42332

In Date: 07/27/2011
Close Date: 08/11/2011

Meter Reading: 63,014.00

Problem?

E41, asset- 10164638. Check engine light came on and at same time Error code ECU12.8. Both came on went off while driving.

Task performed:

see w/o#42456

Parts

Quantity

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V42456

In Date: 08/01/2011

Meter Reading: 63,322.00

Close Date: 08/11/2011

Problem?

C INSPECTION AND REPAIRS AS NEEDED E 41

Task performed:

1. C inspection
2. r/side air horn inop, install 2 new kits in air horns and adj.
- 3.replace wiper blades
- 4.MIV valve red lite inop, remove bulb and clean connector
- 5.replace all discharge & intake cap chains
- 6.L-3 track lighting cover missing, replace bulbs and track cover
- 7.L-3 pull out tray strut broken, reintall pin and new strut
- 8.hose bed cover torn, R&R cover
- 9.r/side & l/side red reflector missing, replace both
- 10.pump panel walkway lights 1/2 lite, replace all 3 LED lites
- 11.L/side pump panel lites inop, replace all 3 led lites (screws stripped, install new)
- 12.L/side spot lite has middle bulb out, replace bulb
- 13.RPM counter on pump panel inop, cable broken replace cable and adapter
- 14.check engine lite came on and went off (w/o#42332) check for codes found tps switch low voltage 2 counts erase code and road test, lite did not come back on and no codes in computer
- 15.L/side headlight had broken bulb inside lens cover, remove lite assy. and remove broken bulb
- 16.both headlight lens dull, restore headlight lens with 3l
- 17.L/side & R/ side hood led lites have water in lens, remove lens and water reseal lens
- 18.service p/s
- 19.front shocks leaking, replace front shocks
- 20.failed vacuum test, rebuild tank fill valve, l/side intake valve,, passed vac.
21. chrome lug nut covers are all missing, replace front and rear covers
- 22.service air drier
- 23.service T case
- 24.replace air filter
25. replace front a/c filter
- 26.replace rear a/c filter

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	2
0000902051FILTER FUEL 03 MERCEDES	2
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	2
01-06635060-C90PSC0CDCR STRIP LIGHT STEADY WHITE	1
048009000SPEEDCOUNTER PUMP PANEL	1
073004100PISTON	1
108-12FBEADED CHAIN W/CONN 12	5
1094KIT-AIR HORN-GROVER	2
14-15612-000GASKET RVR PWR STRG M2	1
15W40BSYN OIL BULK QTS	28
2FC00ZCR4 IN ROUND LED	3
39045HEADLITE KIT WITH SEALER	1
4007BULB NIGHT FIGHTER	1
42809AIR FILTER M2	1
5008414CARTRIDGE DC100	1
65140FRONT SHOCK NEW M2	2
75W90GEAR OIL SYN QT	5
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	2
91-22WIPER BLADE	2
91368904 VALVE KIT 1 1/2 IN	1
91388906 VALVE KIT 2.5 IN AKRON	1
91398907 VALVE KIT 3 IN AKRON	1
98032R 41032-3 RED REFLECTOR OVAL REFLECTOR	2
ACX-84534LUG NUT COVER PK10	40
K022105PURGE VALVE AD-IP-IS	1
PVG-KITORING KIT	1
R00523LENS FOR ROLL UP DOOR LIGHT FARRARA	8
S3226FL02FUEL FILTER 33813 L/F # LFF5851	2
VCC/36000006A/C FILTER CAB M2	1
VML/T1808D2503221C1 FILTER POWER STEERING	1
8550A250A8550A250A BULB	4
101281011GSS6297UM 60# DOOR STRUT QUINT	1



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V42136

In Date: 07/19/2011 Meter Reading: 62,732.00
Close Date: 08/25/2011

Problem?

Rear A/C not working. No power. E 41

Task performed:

removed a/c cover and repaired fuse that was melted
repaired rear rollup door that was hard to open

Parts

NO PARTS USED

Quantity

Workorder: V42493

In Date: 08/02/2011 Meter Reading: 63,270.00
Close Date: 08/25/2011

Problem?

Retractable lanyard on the T.I.C. broke. Need a new one. sta 41.

Task performed:

unit replaced on tic charger

Parts

NO PARTS USED

Quantity

Workorder: V43191

In Date: 08/31/2011 Meter Reading: 63,758.00
Close Date: 09/08/2011

Problem?

makes noise and pulls to the left when applying brakes. e41

Task performed:

diagnose faulty slack adjusters and replace install front
brake shoes and drums adjust all brakes and check
alignment and wheel berings test drive
assist with brakes

Parts

3758FRONT DRUM M2 ENGINE 3598 107453
ACX-84534LUG NUT COVER PK10
KSR3014720QPBRAKE SHOES FRONT M2

Quantity

2
1
2

Workorder: V43421

In Date: 09/04/2011 Meter Reading: 63,974.00
Close Date: 09/08/2011

Problem?

T.I.C. - Both batteries not charging. Both completely dead. Again. E 41

Task performed:

installed tic must be bad spare battery charging but tic
not get new one at shop call and said work ok after
charging some ok

Parts

NO PARTS USED

Quantity



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V42424

In Date: 08/01/2011

Meter Reading: 63,270.00

Close Date: 09/13/2011

Problem?

ON CALL LIGHT 10-7 E 41

Task performed:

traced out problem

found bad connection repaired and tested

Parts

NO PARTS USED

Quantity

Workorder: V43698

In Date: 09/15/2011

Meter Reading: 64,232.10

Close Date: 09/16/2011

Problem?

check engine lite comes on intermintent E-41

Task performed:

1. hook up computer and check for codes, found code for the tps switch, check wiring and connector found no problems (Ed E will order tps)

2. tps in stock, replace tps switch, erease codes, road test vehicle

Parts

WIL-131973TPS SENSOR

1

Workorder: V43461

In Date: 09/06/2011

Meter Reading: 63,974.00

Close Date: 09/19/2011

Problem?

REPLACE FRONT TIRES E41

Task performed:

Replace front tires E41 - Tiresoles j

Parts

NO PARTS USED

Quantity

Vendor?: TIRESOLES

Workorder: V43656

In Date: 09/14/2011

Meter Reading: 64,100.00

Close Date: 10/03/2011

Problem?

wipers running when in the off position. intermitent st 41

Task performed:

replaced wiper switch and tested

repaired foam leak at pump panel

Parts

A06-36956-000A06-36956-003 WIPER-TURN SWITCH

1



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V44153

In Date: 10/04/2011 Meter Reading: 64,707.00
Close Date: 10/05/2011

Problem?

mount hurst tool brackets, E-41

Task performed:

Parts ----- Quantity

1. mount hurst tool brackets for hurst equipment taken off of Q-57 and put on E-41

NO PARTS USED

Workorder: V43998

In Date: 09/28/2011 Meter Reading: 64,573.00
Close Date: 10/07/2011

Problem?

drivers side light in pump panel walk thru missing, sta 41.

Task performed:

Parts ----- Quantity

repaired lgith and tested

NO PARTS USED

Workorder: V43999

In Date: 09/28/2011 Meter Reading: 64,573.00
Close Date: 10/14/2011

Problem?

need spare gaskets for the hard suction, sta 41.

Task performed:

Parts ----- Quantity

DROPPED OFF GASKETS AND INSTALLED

REDG6S14023 GASKET 6 IN

4

Workorder: V43820

In Date: 09/21/2011 Meter Reading: 64,328.00
Close Date: 11/07/2011

Problem?

There is a clicking noise coming from the pump pannel. It sounds like its coming from the foam injection system underneathe the pannel. Sta 41.

Task performed:

Parts ----- Quantity

1. Chkd problem w/foam valve; fnd switch NG; will order new one.
2. Replc switch on panel for foam sys. j

111602SPS PANEL

1

23920-9213UTILITY PUMP

1

3F60BM1KZ FOAM VALVE/PUMP

1

50-1500USE FAN KIT PANCAKE MOTOR DANHARD

2



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V43832

In Date: 09/21/2011
Close Date: 11/07/2011

Meter Reading: 64,405.50

Problem?

foam flush vavle makes clicking sound. advised by tommy mechanic, disconnect power will come repair on 09/22/10. sta 41.

Task performed:

- 1. Replc hose reel switch.
- 2. Replc foam valve switch & tested. j

Parts	Quantity
923182-2151 SWITCH MOMENTARY 24-372	2

Workorder: V44677

In Date: 10/25/2011
Close Date: 11/07/2011

Meter Reading:

Problem?

could we have a bottle of "sta-bil" for our gas powered equipment? Sta 41.

Task performed:

- 1. Rep slide up door that fell off track.
- 2. Rep c ab door that was hard to open. j

Parts	Quantity
NO PARTS USED	

Workorder: V44756

In Date: 10/29/2011
Close Date: 11/08/2011

Meter Reading:

Problem?

Driver's compartment door shows it being open on the screen, with the warning light on. Door is shut and secure. R41

Task performed:

- Rep door switch & tested. j

Parts	Quantity
R00781R01078 SWITCH ROM ROLL UP DOOR	2

Workorder: V43391

In Date: 09/02/2011
Close Date: 11/09/2011

Meter Reading: 63,887.00

Problem?

Replace slack adjusters.

Task performed:

- Replace slack adjusters - Total Truck j

Parts	Quantity
NO PARTS USED	

Vendor?: TOTAL TRUCK



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V44421

In Date: 10/16/2011

Meter Reading:

Close Date: 11/14/2011

Problem?

shore line charging cord not connecting to fire engine charging port properly E 41

Task performed:

Parts

Quantity

Replcd auto-eject. j

NO PARTS USED

Workorder: V44675

In Date: 10/25/2011

Meter Reading: 65,356.00

Close Date: 11/15/2011

Problem?

grill, front right, stobe out, Sta 41.

Task performed:

Parts

Quantity

Rep brkn wire. j

NO PARTS USED

Workorder: V44868

In Date: 11/01/2011

Meter Reading:

Close Date: 11/15/2011

Problem?

all emergency lights on officer side rear not working including blinker. and door open alarm still going off intermitint. Sta 41.

Task performed:

Parts

Quantity

Replaced node #3. j

600000003NODE HERCULES V-MUX

1

Workorder: V44923

In Date: 11/02/2011

Meter Reading:

Close Date: 11/21/2011

Problem?

check engine light came on twice went off after couple of seconds. E41

Task performed:

Parts

Quantity

found codes low on coolant

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V45179

In Date: 11/15/2011

Meter Reading:

Close Date: 12/02/2011

Problem?

may we please have a bottle of stabil, sta 41.

Task performed:

Parts

Quantity

dropped off stabil

NO PARTS USED

Workorder: V45623

In Date: 12/05/2011

Meter Reading: 66,214.00

Close Date: 12/05/2011

Problem?

wont start e 41

Task performed:

Parts

Quantity

recharged battery

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V45486

In Date: 11/29/2011

Meter Reading: 66,214.00

Close Date: 12/06/2011

Problem?

A INSPECTION / COOLANT LEAK E 41

Task performed:

1. A INSPECTION/COOLANT LEAK E 41
2. E GR COLLER LEAKING - REMOVE CLEAN AIR INTAKE PASSAGE, DISASSEMBLE COLLER - ASSEMBLE NEW COOLER AND VALVE, REINSTALL FILL COLLANT OPERATE AND CHECK FOR LEAK.
3. A-INSPECTION
4. POWER STEERING FLUID LOW AND LEAK FOUND - TOP OFF FLUID LEVEL.
5. TAG LIGHT 10-7 - REMOVE BLOWN BULB INSTALL NEW BULB.
6. REPLACE WORN WINDSHIELD WIPER BLAD - ADD BUG SOLVENT TO TOP OFF FLUID RESOVOR.
7. ROM DOOR SYSTEM ON L-2 & R-1 INOP - DIAGNOSE FAULT FOUND, CART AND LOOSE CONNECTION, BURNT WIRES - REPAIR OUTS, LOOSE CONNECTIONS AND REPLACE BURNT SECTIONS OF WIRE.
8. STEERING WHEEL VIBRATION - CHECK TIRE AND SUSPENSION NO VISABLE PROBLEM SEEN - REMOVED FRONT WHEEL ALIGNMENT.
9. PUMP COMP LIGHT INOP - FOUND CORRODED GROUND CONNECTION AND BROKEN LENSE. REMOVE ASSEMBLY - CLEAN GROUND CONTACT AND CHANGE DAMAGE LENSE - REASSEMBLE AND OPERATE.
10. ROAD TEST AFTER EGR COOLER INSTALL - NO LEAKES FOUND.

Parts

Quantity

31-24WIPER BLADES	2
A9061420580GASKET	1
A90614206791EA9061421179 EGR COOLER	1
A9061420880GASKET	1
A9061421080GASKET EGR COOLER	1
DDE/A0039973352EGR COOLING HOSE	2
EA9061420619RA9061420619 EGR VALVE	1



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V45330

In Date: 11/21/2011

Meter Reading:

Close Date: 12/12/2011

Problem?

Leaking oil and coolant, sta 41.

Task performed:

Parts

Quantity

claen oil and coolant and repaired leak

NO PARTS USED

Workorder: V45819

In Date: 12/12/2011

Meter Reading: 66,600.00

Close Date: 12/13/2011

Problem?

REPAIR FLAT E 41

Task performed:

Parts

Quantity

REPAIR FLAT E 41.

NO PARTS USED

Vendor?: BOULEVARD

Workorder: V45901

In Date: 12/16/2011

Meter Reading: 66,658.00

Close Date: 12/16/2011

Problem?

Repair door switch that was falling off.

Task performed:

Parts

Quantity

DOOR OPEN LIGHT ON.

02028345000REFLECTOR

1

REPAIRED REAR DOOR SWITCH THAT WAS FAILING OFF.

H50SN12BULB

1

Workorder: V46047

In Date: 12/23/2011

Meter Reading: 66,934.00

Close Date: 12/28/2011

Problem?

ldrivers side brake light 10-7. mechanic allready called.

Task performed:

Parts

Quantity

REPLACED L/R BRAKE LIGHT, STILL INOP. PERFORMED V MUX TROUBLESHOOTING REMOVED PANEL TO NRSE 3. FOUND LOOSE WIRE IN CONNECTOR.

60R00XRRBRAKE/TAILLIGHT LED

1



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V45894

In Date: 12/15/2011

Meter Reading:

Close Date: 01/03/2012

Problem?

shoreline charger on engine 41 broken

Task performed:

repaired battery charger and tested

Parts

NO PARTS USED

Quantity

Workorder: V46418

In Date: 01/09/2012

Meter Reading: 67,386.00

Close Date: 01/10/2012

Problem?

Light bar crash.

Task performed:

HAD TO DRILL AND TAP NEW BOLT HOLES TO
RESCUE LIGHT BAR.

Parts

NO PARTS USED

Quantity

Workorder: V46630

In Date: 01/17/2012

Meter Reading: 67,764.00

Close Date: 01/27/2012

Problem?

need oil for engine 41.

Task performed:

TOP OFF ENGINE OF OIL AND REPAIRED SMALL OIL
LEAK

Parts

15W40QSYN OIL QT

Quantity

12

Workorder: V46963

In Date: 01/30/2012

Meter Reading: 68,084.00

Close Date: 01/31/2012

Problem?

replace tire

Task performed:

REPLACE TIRE.

Parts

NO PARTS USED

Quantity

Vendor?: BOULEVARD TIRE CENTE



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V47286

In Date: 02/13/2012
Close Date: 02/28/2012

Meter Reading: 68,458.00

Problem?

Officers side rear, emergency lights mount very lose and appears to be coming appart. Sta 41

Task performed:

Parts

Quantity

TRACED OUT PROBLEM FOUND BAD CONNECTION
ON NODE REPAIRED AND TESTED.

NO PARTS USED

Workorder: V46854

In Date: 01/25/2012
Close Date: 03/06/2012

Meter Reading: 67,997.00

Problem?

strap that secures the tic needs to be replaced will not allow tic to constant charge.E 41

Task performed:

Parts

Quantity

REPAIRED STRAP ON TIC CHARGER.

NO PARTS USED

Workorder: V43864

In Date: 09/22/2011
Close Date: 03/09/2012

Meter Reading: 64,423.00

Problem?

check engine light on R41

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V47864

In Date: 03/10/2012
Close Date: 03/16/2012

Meter Reading: 69,404.00

Problem?

ENGINE 41 FRONT AIR BRAKES NOT HOLDING AIR PRESSURE. TAKES 2 MINUTES TO FILL EFORE BRAKE WII RELEASE
TO MOVE FORWARD. Sta 41

Task performed:

Parts

Quantity

TRACED OUT AIR LEAKS FOUND NONE AT THIS
TIME.

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V47935

In Date: 03/13/2012
Close Date: 04/02/2012

Meter Reading: 69,445.60

Problem?

gas fan will not stay running. asset number 10132092. E41

Task performed:

CLEAN CARB AND TESTED.

Parts

Quantity

NO PARTS USED

Workorder: V47941

In Date: 03/13/2012
Close Date: 04/02/2012

Meter Reading: 69,445.60

Problem?

check air brakes for poss leak. E41

Task performed:

CHECKED FOR AIR LEAKS FOUND NONE.

Parts

Quantity

NO PARTS USED

Workorder: V48389

In Date: 04/03/2012
Close Date: 04/09/2012

Meter Reading: 70,057.00

Problem?

REPAIR RAM FAN E 41

Task performed:

REMOVED BENT ENGINE MOUNT TAKE TO PRESS AND STRAIGHTEN OUT MOUNT REINSTALL ENGINE MOUNT BRACKET.

Parts

Quantity

NO PARTS USED

Workorder: V48155

In Date: 03/23/2012
Close Date: 04/16/2012

Meter Reading: 69,728.30

Problem?

parking break knob difficult to push in...dash board flexing abnormally

Task performed:

REPAIRED DASH PANEL AND PARKING BRAKE.

Parts

Quantity

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V48427

In Date: 04/04/2012
Close Date: 04/20/2012

Meter Reading: 70,057.00

Problem?
tire wear

Task performed:

REPLACED TIRES.

Parts

NO PARTS USED

Quantity

Workorder: V49012

In Date: 05/01/2012
Close Date: 05/03/2012

Meter Reading: 70,257.00

Problem?
REPLACE REAR TIRES

Task performed:

REPLACE REAR TIRES.

Parts

NO PARTS USED

Quantity

Vendor?: BOULEVARD TIRE CENTE

Workorder: V48915

In Date: 04/26/2012
Close Date: 05/08/2012

Meter Reading: 70,257.00

Problem?
Chainsaw leaking fuel E41

Task performed:

PICKED UP SAW CHECKED FOUND LEAKING FROM CARBURATOR DELIVERED TO SHOP.

Parts

NO PARTS USED

Quantity

Workorder: V49186

In Date: 05/08/2012
Close Date: 05/08/2012

Meter Reading: 70,588.00

Problem?
driver states a rotten egg smell in cab, E-41

Task performed:

1. check vehicle for rotten egg smell, found smell coming from battery's, replace battery's, check charging system, ok 13.7, plug shore line in and let battery's become fully charged voltage stayed at 13.0 no problem found

Parts

BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER BATTERY
HP-31D BATTERY 950CCA HP-31D

Quantity

4
4



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V48656

In Date: 04/13/2012

Close Date: 05/09/2012

Meter Reading: 70,193.00

Problem?

B INSPECTION E41

Task performed:

Parts

Quantity



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

1. B-INSPECTION.	0769027STRAINER 2.5 IN	1
2. DIAGNOSE AIR LEAK FOUND AMU UNIT LEAKING - REMOVE AMU LEAKING AT RETAINING RING. CLEAN AND INSTALL NEW PROTECTION PRESSURE VALVE, TEST OPERATE AND FOUND NO LEAK.	111602SPS PANEL	1
3. A/C SYSTEM FILTERS DIRTY. REMOVE AND INSTALL NEW FILTERS.	18-46375-00018-46375-004 TREAD PLATE LH M2	1
4. L/SIDE REAR DOOR WAY MOLDING BROKEN - REMOVE AND INSTALL NEW MOLDING. CLEAN AREA AND REPLACE CLIPS AND FASTENERS.	23-11345-707SCREW DASH	20
5. RIGHT SIDE BODY MARKER LIGHT 10-7 - FOUND LEDS BLOWN - REMOVE AND INSTALL NEW LEDES.	23-11829-050SCREW	2
6. HURST TOOL SPREADER UNSECURE - HOLD DOWN STRAP BROKEN - REMOVE PIECES, PRESSON NEW BUNGY STRAP ON TO HOOK AND SECURE TO TOOL HOLDER WITH NUT.	23-11865-000SPRING NUT	3
7. R-3 COMPARTMENT TOOL LOOSE DAMAGING DOOR RAIL AND LIGHT ASSEMBLY - FABRICATE PLATE, INSTALL PLATE ON PULL OUT DRAW TO PROTECT DOOR RAIL AND LIGHT ASSEMBLY.	23-12981-707DASH SCREWS M2	10
8. CHARGER INOP - DIAGNOSE FAULT - FOUND BLOWN CHARGER FUSE - DIAGNOSE FAULT TO BAD CHARGER - REMOVE CHARGER - INSTALL (DNI) CHARGER. CHECK SYSTEM.	35200-RLIGHT MARKER LED RED	1
9. REAR BRAKE SHOES 40% WORN - BRAKE SERVICE AND ADJUSTED.	35200-YLIGHT MARKER LEDAMBER	1
10. DASHBOARD HOLD DOWN DIPS AND PLASTIC SUPPORT BROKEN - DISASSEMBLY DASHBOARD AND ORDER REPLACEMENT PARTS. INSTALL NEW DASHBOARD, DASHBOARD SUPPORT BRACKET AND ALL ASSOCIATED DASH PARTS - SECURE AND CHECK THE OPERATION OF ALL REINSTALLED PARTS.	680-10LAMERICAN FLAG W UV CLEAR LEFT	2
11. AIR LEAK IN DASH PARK BRAKE SWITCH - REMOVE PARK BRAKE SWITCH ASSEMBLY AND INSTALL NEW PARK SWITCH.	680-10RAMERICAN FLAG W UV CLEAR RIGHT	2
12. FOAM FULL PUMP INOP - DIAGNOSE FAULT - FOUND SWITCH INTERNAL FAILURE WILL NOT SHUT OFF - REMOVE SWITCH AND INSTALL NEW CLASS ONE SWITCH TEST OPERATE - WORKING NORMAL.	801315PARKING VALVE NEWER M2 5009249	1
13. HI IDLE INOP - DIAGNOSING HI IDLE FAILURE, RELAYS HAS POWER IN/POWER OUT - VISTA ACT NOW/EDGE SIGNAL AND LAP TOP ACKNOWLEDGE IN PUT AND OUT PUT UNIT OK AS PER MIKE LEHAN NO FURTHER ACTION NEEDED.	A18-51840-000PILLAR COVER	1
14. REAR STATION # HOLDER LOOSE - REPLACE STRIP OUT NUT AND BOLTS; L-3 COMPARTMENT SHELF FAILING - REPLACE MISSING NUT AND BOLT SECURE SHELF.	A22-51677-000PANEL ASSY DASH TOP COVER	1
15. WINDSHIELD WIPER SPRAY INOP - FOUND SPRAY NOZZLE CLOGGED AND PICK UP TUBE AT PUMP CLOGG - CLEAN NOZZLE AND PICK UP TUBE	A22-62508-000UPPER DASH	1
16. HURST TOOL SPREADER FITTING HAS OIL - CLEAN AND CHECK SCREWS, OPERATE UNDER	ACX-84534LUG NUT COVER PK10	5
	CT4515METBRAKE LINNING	4
	KIT9081BRAKE HARDWARE KIT	2
	NRG-27-PPV-B55RA12-19772-355 AMU03 M2 VALVE ASSY	1
	VCC/36000006A/C FILTER CAB M2	1
	A22-57394-001CUP HOLDER ASSY	1
	87123USE 9185 RELAY CONNECTOR 99025	1



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

PRESSURE CHECK FOR LEAK - TOOL OPERATING
?????, NO LEAKS.

17. TANK EMPTY FILL TANK - REPLACE DAMAGE
L/SIDE INTAKE SCREW.

18. ROAD TEST AFTER CLEARING ABS CODE -
RECHECK NO CODE REAPPEAR.

19. INSTALL INTERIOR BODY MOLDING AND SECURE
INPLACE. DRILL NEW HOLD DOWN HOLES.

20. INSTALL INTERIOR PARTITION PANEL AND
SECURE.

21. Q.C. TRUCK, GET ASSET #S.

Workorder: V49197

In Date: 05/08/2012 **Meter Reading:** 70,588.00
Close Date: 05/15/2012

Problem?

Rear AC not turning on.. e41

Task performed:

- CONTINUED LIGHT AND WIRING REPAIR/REPLACE.
- CONTINUED LIGHT AND WIRING REPAIR/REPLACE.
- CONTINUED BRAUW LIGHT AND TELE LIGHT REPLACE/REWIRE.
- COMPLETED LIGHT AND REWIRE: REPLACED LEFT BROKEN LIGHT AND BOTH REAR CAB TELES WITH L.E.D. STYLE LIGHTS. REWIRED ENTIRE CIRCUITS FOR BROWN LIGHTS AND TELEIES ALL THE WAY TO F USE/BREAKER PANEL. REWIRED FUSE BLOCK /FUSE HOLDER WITH 12 GAUGE WIRE AND UPGRADES RELAYS AND BREAKERS. TESTED CIRCUITS EXTENSIVELY. LIGHTS WORKING NORMALLY. NO SIGNS OF OVERHEATING BREAKERS.

Parts

Quantity

NO PARTS USED

Workorder: V49911

In Date: 06/05/2012 **Meter Reading:** 71,262.70
Close Date: 06/05/2012

Problem?

r/side rear light bar inop, gen. inop, E-41

Task performed:

- driver stated that the r/side upper stanchion fell off, drill holes and tap threads in truck body to hold stanchion on. drill holes in stanchion for light bar, spot light, marker light. connect wires.
- check generator for stalling, clean carb. let run, runs ok now

Parts

Quantity

4537BULB 100W SPOT

1

NI STANCHION14 IN

1



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V50067

In Date: 06/12/2012 Meter Reading: 71,472.00
Close Date: 06/15/2012

Problem?

fire exhaust fan pull cord broke ON E41

Task performed:

REPLACED PULL CORD AND REPAIRED SPRING IN PULLY.

Parts

NO PARTS USED

Quantity

Workorder: V50070

In Date: 06/12/2012 Meter Reading: 71,472.00
Close Date: 06/15/2012

Problem?

generator will not run ON E41

Task performed:

CLEANED CARB AND REPLACED PLUG AND RAN UNIT TESTED OK.

Parts

NO PARTS USED

Quantity

Workorder: V50410

In Date: 06/26/2012 Meter Reading: 71,792.00
Close Date: 07/09/2012

Problem?

generator will not stay running. poss throttle repair. E41

Task performed:

REMOVED CARB AND CLEANED JETS AND FUEL SYSTEM CHECKED OK. REINSTALLED CARB.

Parts

16957-ZE1-812HONDA FUEL GROMET

1

Quantity

Workorder: V50982

In Date: 07/19/2012 Meter Reading: 72,594.00
Close Date: 07/24/2012

Problem?

CHECK ENGINE FAN FOR CRACKS E 41

Task performed:

1. remove eng fan belt, remove radiator support brackets, remove fan shroud, air line to fan and fan, remove fan from fan clutch and install new fan, install fan assy on eng hub, install belt, air line and radiator support brackets, top off coolant and road test...

Parts

4735-43782-01KYS FAN ASSBLY

1

Quantity



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V51418

In Date: 08/07/2012
Close Date: 08/07/2012

Meter Reading: 72,950.00

Problem?

CHECK UNIT FOR CRACKED FAN E 41

Task performed:

CHECK UNIT FOUND FAN CRACKED SWAPED UNIT FOR REPAIR.

Parts

NO PARTS USED

Quantity

Workorder: V52370

In Date: 09/06/2012
Close Date: 09/13/2012

Meter Reading: 73,946.60

Problem?

foam tank leaking, E-41

Task performed:

1. travel to sta-41, check for foam leak, found 1/4 turn shut off valve broken off of fitting, need to get new shut off valve and fittings, travel back to s/shop
2. travel to sta-41, remove broken nipple from inside of elbow, install new foam shut off valve and fittings, install drain hose, driver on shift said he will fill foam tank....

Parts

NO PARTS USED

Quantity

Workorder: V51165

In Date: 07/27/2012
Close Date: 09/14/2012

Meter Reading:

Problem?

Left front turn signal/hazard light out. E41

Task performed:

REPAIRED LIGHT AND REPAIRED BAD CONNECTION IN LIGHT HEAD.

Parts

NO PARTS USED

Quantity

Workorder: V51191

In Date: 07/29/2012
Close Date: 09/14/2012

Meter Reading:

Problem?

rear a/c not working E 41

Task performed:

REWIRED RELAY AND INSTALLED NEW CIRCUIT BREAKER AND TESTED OK.

Parts

NO PARTS USED

Quantity



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V51577

In Date: 08/13/2012

Meter Reading:

Close Date: 09/17/2012

Problem?

rear ac no power poss fuse. E 41

Task performed:

Parts

Quantity

1. REWIRED A/C POWER AND TESTED.

54-140CIRCUIT BREAK 40 AMP

2

Workorder: V52077

In Date: 08/31/2012

Meter Reading:

Close Date: 09/17/2012

Problem?

foam pump ball valve rotten fell off. mechanic sts need to go to shop 09-04-12.foam pump out of service. E 41

Task performed:

Parts

Quantity

CHK FOAM SYST

NO PARTS USED

Workorder: V51990

In Date: 08/29/2012

Meter Reading:

Close Date: 09/21/2012

Problem?

wipers come on by themselves...without turning them on E41

Task performed:

Parts

Quantity

REPLACED WIPER SWITCH.

A06-36956-000A06-36956-003 WIPER-TURN SWITCH

1

Workorder: V52494

In Date: 09/18/2012

Meter Reading:

Close Date: 09/25/2012

Problem?

firefighter door latch inside cab falling out of door. E41

Task performed:

Parts

Quantity

REPAIRED DOOR HANDLE THAT HAD FALLEN OFF.

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V52495

In Date: 09/18/2012

Meter Reading:

Close Date: 09/25/2012

Problem?

pump panel lock switch on driver side will not lock and panel moves forward. E41

Task performed:

Parts

Quantity

REPLACED LOCK ON PUMP PANEL AND REPAIRED HINDGE.

101291015434 LATCH TRIGGER S/O

1

Workorder: V52493

In Date: 09/18/2012

Meter Reading:

Close Date: 10/01/2012

Problem?

deck gun leaking at base. mechanic allready eval problem. E41

Task performed:

Parts

Quantity

ADJUSTED VALVE LINKAGE AND TESTED.

NO PARTS USED

Workorder: V52992

In Date: 10/10/2012

Meter Reading: 74,683.00

Close Date: 10/12/2012

Problem?

PARTS FOR K12..... E41

Task performed:

Parts

Quantity

PARTS ONLY NO LABOR.

502471801TRIGGER PARTNER SAW

1

Workorder: V52554

In Date: 09/21/2012

Meter Reading:

Close Date: 10/16/2012

Problem?

k12 saw throttle cuts in and out on speed.

Task performed:

Parts

Quantity

REPAIRED AND ADJUSTED CARB.

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V52712

In Date: 09/29/2012

Meter Reading:

Close Date: 10/16/2012

Problem?

throttle broke/sticks on K-12 E 41

Task performed:

Parts

Quantity

A/C INOP RECHARGED A/C AND CHKD FOR LEAKS.
FOAM LEAK- REPAIRED LEAK AT FOAM VALVE.

NO PARTS USED

Workorder: V53517

In Date: 11/03/2012

Meter Reading:

Close Date: 11/08/2012

Problem?

will not pump E 41

Task performed:

Parts

Quantity

TRAVEL TO ST 41 CHECK OUT PUMP.

NO PARTS USED

Workorder: V50485

In Date: 06/29/2012

Meter Reading: 71,957.00

Close Date: 12/10/2012

Problem?

DOOR ALARM STAYS ON E 41

Task performed:

Parts

Quantity

1. DOOR ALARM STARTS ON INTERMITTENT, CAN GATEWAY LOOSES COMMUNICATION, TROUBLESHOOT DOOR AND SENSOR CHECKED WIRING AND WELDER MUX DOWNLOADER FOUND PROBLEM WITH MODE #2. ORDERED NEW GATEWAY WILL INSTALL NEW PART AT STATION AND REPROGRAM.

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V53724

In Date: 11/13/2012

Close Date: 12/18/2012

Meter Reading: 75,479.00

Problem?

C INSPECTION E93

Task performed:

Parts

Quantity



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

1. C INSP	000000001085OIL DRAIN GASTKET M2	1
2. DRAINING OIL FOUND DRAIN PLUG BAD AND I HAD TO REMOVE WITH AIR CHESILE AND REPLACE PLUG.	000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
3. REMOVE SLACK ADJUSTER TO INSTALL NEW ONES BUT NEW ONES WERE WRONG, SO TALK TO ED W AND HE ORDERED THE RIGHT ONES, INSTALLED NEW SLACK ADJUSTER AND TEST DROVE.	0000902051FILTER FUEL 03 MERCEDES	1
4. INSTALLED FRONT SHOCKS.	0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
5. SERVICE T-CASE.	000908022011OIL DRAIN PLUG M2	1
6. CLEAN OFF OLD # AND PUT NEW RED BACKINGS AND NEW # ON PLACKER.	01-29866-118BELT ALT. M2	1
7. R&R FOSE HOLDER ON BATTERY CHARGE.	05-17223-002RAD CAP 20 LB	1
8. R&R BATTERIES.	0913912CHARGER 2000	1
9. ENGINE FAN ASSY WOBBLES, WASHER MONTED BENING FLANGE, REMOVED WASHER AND INSTALLED FAN ASSY PROPERLY.	101281012GSS6298UH STRUTS 90#	1
10. REPLACE BATTERY CHARGER AND WIRING CHARGER SHORTED, REPLACED CHARGER AND WIRING.	103385NDRAIN COCK	2
11. BATTERY BOX LOCK AND SLIDE OUT INOP, REPAIRED AND LUBED BATT BOX SLIDE OUT TRAY.	194-ABULB	4
12. STARTED ON WATER PUMP DRAIN COOLANT AND REMOVE TWO HOSE.	5-20PHBL5366C 20AMP PLUG	1
13. BACK ON WATER REMOVE FAN, CLUTCH AND SHOUD TO GET TO WATER PUMP, REMOVE THERMAST HOUSING AND WATER PUMP CLEAN UP GASKET SURFACES AND MAKE ALIGNMENT STUD AND INSTALLED WATER PUMP AND THRMAST HOUSING.	5-20PH1PGK4 CONNECTOR 120V 20A FEMALE	1
14. FINISH WATER, NEW BELTS TOP OFF COOLANT AND TEST DRIVE.	5008414CARTRIDGE DC100	1
15. SERV AIR DRYER R&R FILTER.	529008000529-0080-10-0 1 1/4 ANODE KIT	1
16. SERV DRYER R&R PURGE VALVE-CHK OK.	64000000006444-0000-00 VDR RVCAN	1
17. CHECK LIGHT FOR DOOR ALARM, FOUND WIRE CUT IN DASH REPAIRED WIRE AND FOUND ALARM FOR SPOT LIGHT NOT WORKING CHECK MODES AND FOUND BAD PROXIMITY SWITCH BAD ORDER SWITCH.	65140FRONT SHOCK NEW M2	2
18. ASIST W/ TROUBLESHOOTING NIGHT FIGHTER UP WARNING INOP.	906-181-00-86OIL FILTER M2 SPINNER 57140	1
19. TORQUE ALL AXLE BOLTS.	9062030015PIPE SOCKET TO WP	1
20. CHK FOR AIR LEAKS, SPRAYED TANK LINES AND FITTINGS-R&R 2 DRAIN VALVES-R&R FITTING BY AIR TANK, REPAIRED LEAK AT TANK FITTING CHK OK.	9550 BELT	1
21. REPAIR DOME LIGHTS, FOUND LTS INOP W/ DOOR AND MUX REMOVED KICK PANEL DASH, DASH PANEL AND A PILAR-TROUBLESHOOT AND REPAIR WIRING CHK OK.	A0149972845ORING WATER PUMP M2	1
22. FOUND LFT REAR DOOR LOOSE, OTHER DOOR PANEL LOOSE FROM INNER PANEL-REMOVED SIDE PANEL, DOOR WIRES AND DOOR ASSEMBLY-CLEANED WELDED DOOR SKIN.	BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
	DDE-0052035975A0052032675 THERMOSTAT ELEMENT M	2
	DDE-9062030180GASKET SOCKET TO HEAD M2	2
	DDE-R90620043019062006301 WATER PUMP SOME M2 CI	1
	DDE/0209971148A0249972848 SEAL RING	4
	DDE/A0039973352EGR COOLING HOSE	2
	DDE/A0279976048O-RINGS M2 WATER PUMP	3
	HP-31DBATTERY 950CCA HP-31D	4
	K022105PURGE VALVE AD-IP-IS	1
	N917003022003GASKET/SEAL M2 WATER PUMP	1
	S PLACARDFRONT AND BACK PLACARD	4
	S PLACARD INSERTFRONT AND BACK INSERT CARD	4
	S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
	WAT61403STRAINER 6 IN	1
	PR13BULB	1
	203FFBEARING PULLEY	1
	EXO3AH00015SPLUG RAD. DRAIN	1
	23920-9213UTILITY PUMP	1
	91388906 VALVE KIT 2.5 IN AKRON	1
	78R536078R5360M 2PK FILTER AIR COND	1
	VCC/36000006A/C FILTER CAB M2	1
	A06-40131-000MARKER LIGHT M2 HOOD	2
	AS1172SLACK ADJ	2
	N000000001069SEAL BANJO	2



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

- 23. REPAIR DOOR CONT- REINSTALLED AND ADJ DOOR REASSEMBLED ALL PARTS CHK OK.
- 24. REPAIR DOOR LTS CONT-TIED UP WIRING, REINSTALLED DASH AND ALL PANELS-CHK OK.
- 25. WELD DOOR, REMOVE CLEAN AND WELD INSTALLED DOOR BACK ON TRUCK.
- 26. VAC TEST PUMP AND FAILED TEST. TROUBLESHOOT LEAKING VALVES.
- 27. VAC TEST PUMP, REMOVED LINKAGE PIPE AND #4 VALVE, REBUILD VALVE REASSEMBLED AND VAC TEST- ADJ AND TIGHT'D LINKAGE TEST OK.
- 28. REPLACE A NODE FOUND NO A NODE IN SYSTEM-GET CORRECT FOAM PUMP-RETURN OTHER PUMP.
- 29. REPLACE ANODE,REMOVED PLATE CLEANED PUMP-REPLACED PLATE AND ANODE CHK OK.
- 30. FOUND FOAM PUMP NOISEY-REMOVED HOSES WIRES AND PUMP ASSEMBLY DISASSEMBLED AND REPLACED PUMP-REASSEMBLED-CHK OK.
- 31. FOUND RT SIDE PUMP PANEL LTS OUT. TROUBLESHOOT, REMOVED MT PLATE REPAIRED AND CLEANED GROUNDS-REASSEMBLED AND CH OK.
- 32. FOUND FRT FENDER MARKER TURN SIGNAL LTS OUT. TRIED TO CLEAN AND REPLACE BULBS AND SOCKET R&R BOLT LT, ASSEMBLIES CHK OK.
- 33. FOUND TRASHLINE COVER LOOSE-ADJ LATCHES-TIGHTEN AND ADJ WHEL CHECK DOORS AND SCBA CYLINDER DOORS.
- 34. Q INSPECTION.
- 35. FOUND L-3 RER AND R-3 SLIDE TRAYS.
- 36. FILL TANK WITH WATER.
- 37. REMOVED STATION 41 STICKERS.

Workorder: V54513

In Date: 12/19/2012

Meter Reading:

Close Date: 01/14/2013

Problem?

compound pressure gauge does not move when pump has pressure built up.

Task performed:

REPLACED COMPOUND GAUGE AND TESTED.

Parts

91553941GAUGE

Quantity

1



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V54609

In Date: 12/25/2012

Meter Reading: 75,710.80

Close Date: 01/25/2013

Problem?

steering column has foot lock for tilt and telecope functions. when locked telescoping does not lock. st. wheel will move in and out
E93

Task performed:

REPAIRED STEERING COLUM AND TESTED.

Parts

Quantity

RGT-452258FFOOT PEDAL STERRING COLUMN

1

RGT401737ESPRING PEDAL RETURN

1

RGT401741CRETURN SPRING

1

Workorder: V54849

In Date: 01/05/2013

Meter Reading: 3,626.00

Close Date: 01/25/2013

Problem?

Thermal Imaging Camera in middle of cab is not charging, possible electrical issue E93

Task performed:

1. FOUND BAD CONNECTION, REPAIRED FOR TIC CHARGER.
2. COOLANT LEAK REPAIRED.

Parts

Quantity

NO PARTS USED

Workorder: V55712

In Date: 02/11/2013

Meter Reading: 76,680.00

Close Date: 02/14/2013

Problem?

replace steering column

Task performed:

FOUND STEERING COLUMN AND PEDAL RELEASE LOOSE- TIGHTENED COLOUR REPLACED PEDAL ASSEMBLY AND SPRINGS- LUBED AND ADJUSTED CABLE AND LINKAGE CHK OK- INSTALLED PARTS.

Parts

Quantity

RGT-452258FFOOT PEDAL STERRING COLUMN

1

RGT401737ESPRING PEDAL RETURN

1

RGT401741CRETURN SPRING

1

Workorder: V54517

In Date: 12/19/2012

Meter Reading: 75,668.60

Close Date: 02/22/2013

Problem?

request for soft cabel cutters. new e93 has bracket for pair, never had a pair on old e93. curved cutting jaws type.

Task performed:

DC WILL EMAIL WAYNE AT SHOP.

Parts

Quantity

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V55894

In Date: 02/21/2013

Meter Reading: 77,052.90

Close Date: 03/15/2013

Problem?

Door open warning E-93

Task performed:

CHECK TRUCK FOUND DOOR SWITCH LOOSE IN DISH BECAUSE DISH WAS BROKEN. ED E. SAID GET IT TO TOM SO I UNPLUGED SWITCH FOR THE NIGHT AND MAKE A TEMPLIT TO MAKE ALUM. PLATE FOR DISH BUT NIGHT I FOUND THEY HAVE A NEW DISH SO I GOT IT.

Parts

Quantity

A22-54059-000DASH PANEL R/H M2

1

E2K-XME2SWITCH PROXIMITY FERRARA POLE LIGHTM3

1

Workorder: V56389

In Date: 03/13/2013

Meter Reading: 77,544.40

Close Date: 04/05/2013

Problem?

right side of dash replaced for dome lights, replaced 2 weeks ago. switch is very loose in the hole and moves at a angle and causes lights to stay on. plastic dash appears ok, might need new switch E-93

Task performed:

REPAIRED SWITCH AND TESTED.

Parts

Quantity

27-102A22-54259-000 DOOM LIGHT SWITCH M2

1

Workorder: V54515

In Date: 12/19/2012

Meter Reading:

Close Date: 04/08/2013

Problem?

truck has mounts for oval fuel cans. old e93 has round cans. need two new fuel cans, oval in shape.

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V54516

In Date: 12/19/2012

Meter Reading:

Close Date: 04/08/2013

Problem?

hurst tool mounts will not work with lake worth hurst equipment. need mounts modified or replaced.

Task performed:

Parts

Quantity

620122SPOT LIGHT REMOTE

1

A14-15776-000STEERING COLUMN

1



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V56119

In Date: 03/03/2013

Meter Reading: 77,310.10

Close Date: 04/10/2013

Problem?

rear compartment rail lights shorted out - lights turned off - need to be check.. E93

Task performed:

INSTALLED NEW COMPARTMENT LIGHTS.

Parts

Quantity

39045HEADLITE KIT WITH SEALER

1

AY-904242 IN LED LIGHT STRIP SUTPHEN STAND ALONE

2

AY-9400-040H20 LED

2

Workorder: V55268

In Date: 01/24/2013

Meter Reading: 76,185.50

Close Date: 04/18/2013

Problem?

replace proximity switch, ask Kevin

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V56782

In Date: 04/02/2013

Meter Reading: 78,092.00

Close Date: 04/26/2013

Problem?

Generator - oil over full - looks thin and E-93 milky - smells like gasoline - took out of service.....

Task performed:

CHANGED OIL IN GENERATOR.

Parts

Quantity

NO PARTS USED

Workorder: V56867

In Date: 04/06/2013

Meter Reading: 78,168.00

Close Date: 04/26/2013

Problem?

driver side highbeam bulb needs replaced, is not working.

Task performed:

1. REPAIRED GROUND WIRE IN HEADLIGHT.

Parts

Quantity

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V56817

In Date: 04/03/2013

Meter Reading:

Close Date: 05/02/2013

Problem?

request for 4 spring loaded clamps that hold nozzles and couplings 2.5 inch mounted in drivers compartment, also tools need to b mounted over left wheel. Tommy asked for a reminder work order. E-93

Task performed:

Parts

Quantity

TRAVEL TO ST 93 INSTALL NOZZLE CLAMPS IN FRONT COMPT AND MOUNT NOZZLES.

NO PARTS USED

Workorder: V57311

In Date: 04/28/2013

Meter Reading:

Close Date: 05/02/2013

Problem?

pump panel walk thru lower right step light is missing. need new one. E93

Task performed:

Parts

Quantity

TRAVEL TO ST 93 REWIRE LIGHT AND REINSTALL.

NO PARTS USED

Workorder: V57362

In Date: 04/30/2013

Meter Reading:

Close Date: 05/16/2013

Problem?

Please mount loose equipment in compartments. Numerous requests have been made verbal and IBEM E93

Task performed:

Parts

Quantity

MOUNTED ALL LOOSE EQUIPMENT AS PER CAPTAIN

NO PARTS USED

Workorder: V57633

In Date: 05/10/2013

Meter Reading:

Close Date: 05/20/2013

Problem?

power to rear a/c turns off by itself and minutes later turns back on by itself. also request for new wiper blades, chattering badly. thanks.

Task performed:

Parts

Quantity

1. TRAVEL TO ST 95 CHECK OUT A/C SYST FOUNG WIRES ON RELAY BURNT WIRING END.
2 R&R WIPER BLADES.

91-22WIPER BLADE

2



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V57814

In Date: 05/17/2013
Close Date: 05/21/2013

Meter Reading: 78,982.40

Problem?

Coolant leak E93

Task performed:

TRAVEL TO MAKO GET PARTS GO TO ST 91
REPLACE TEAR IN COOLING SYSTEM. REPAIR
MORE COOLANT LEAKS.

Parts

Quantity

ALA00350-50 EXTENDED LIFE COOLANT GAL
ANTICOOLANT ANTIFREEZE GAL

1
3

Workorder: V57798

In Date: 05/17/2013
Close Date: 05/29/2013

Meter Reading: 78,982.40

Problem?

turn signal inop

Task performed:

TRAVEL TO ST 93 CHECK OUT TURN SIGNAL ALL
WORKING NOW REPAIR WIRING ON FRONT LIGHT.

Parts

Quantity

NO PARTS USED

Workorder: V58058

In Date: 05/30/2013
Close Date: 06/04/2013

Meter Reading: 79,491.40

Problem?

replace 2 front tires

Task performed:

REPLACE 2 FRONT TIRES.

Parts

Quantity

NO PARTS USED

Vendor?: ELPEX

Workorder: V58615

In Date: 06/22/2013
Close Date: 07/03/2013

Meter Reading: 79,931.80

Problem?

Hurst power unit - throttle sticking open -sprayed carb linkage with WD-40 at carb and unit rpm went back to idle - need to be checked.... E93

Task performed:

CHECK OUT HURST UNIT FOUND NO PROBLEM
MUST HAVE STUCK AND LUBE CORRECTED THE
PROBLEM.

Parts

Quantity

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V58629

In Date: 06/23/2013
Close Date: 07/05/2013

Meter Reading: 79,931.80

Problem?

Leak in the Piston intake valve on the driver's side. There is a gasket missing on the piston that closes the unit. Need a gasket. Tr gasket that connects the unit to the 6" main intake is good.

Task performed:

TRAVEL TO ST 93 CHECK OUT STROTZ VALVE. LUBE VALVE TEST STILL LEAKING BROKEN SEAL PLATE. SWAP OUT UNIT TO GET REPAIRED.

Parts

NO PARTS USED

Quantity

Workorder: V59035

In Date: 07/12/2013
Close Date: 07/12/2013

Meter Reading: 80,297.60

Problem?

replace husrt spreader tip

Task performed:

LIGHT DUTY DELIVERED.

Parts

NO PARTS USED

Quantity

Workorder: V58897

In Date: 07/07/2013
Close Date: 07/19/2013

Meter Reading: 80,193.00

Problem?

air horns need adjusting/tuning. E93

Task performed:

1. REMOUNTED TOOL IN L-1 COMPT.
2. ADJUSTED AIR HORNS AND REPAIRED AIR LINES.

Parts

NO PARTS USED

Quantity

Workorder: V59236

In Date: 07/22/2013
Close Date: 07/23/2013

Meter Reading: 80,481.90

Problem?

E93 broken side mirror

Task performed:

REPLACED DRIVER'S SIDE MIRROR.

Parts

A22-59713-001MIRROR HEAD

Quantity

1



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V59186

In Date: 07/24/2013

Meter Reading: 80,481.90

Close Date: 07/25/2013

Problem?

Driver's side mirror, the bottom smaller one, came off while responding to a call on a bumpy road. The mirror is intact, just needs to be glued back on.

Task performed:

Parts

Quantity

REPAIRED.

NO PARTS USED

Workorder: V59209

In Date: 07/19/2013

Meter Reading: 80,481.90

Close Date: 07/30/2013

Problem?

engine has small oil leak. level on dip stick shows just below the max mark.

Task performed:

Parts

Quantity

TRAVEL TO ST 93 SMALL OIL FROM SIDE OF PAN
TRY TO TIGHTEN GOING IN FOR SERVICE SOON PER
FOREMAN.

NO PARTS USED

Workorder: V59354

In Date: 07/25/2013

Meter Reading: 80,685.30

Close Date: 07/30/2013

Problem?

Replace rear tires

Task performed:

Parts

Quantity

TIRES

18611411R22.5 M726EL BRIDGESTONE

4

Vendor?: BOULEVARD TIRE CENTE

Workorder: V59359

In Date: 07/25/2013

Meter Reading: 80,685.30

Close Date: 07/30/2013

Problem?

E93 has a small oil leak. Oil checked and fluid level was ok.

Task performed:

Parts

Quantity

REPAIRED ON WORK ORDER #.

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V59626

In Date: 08/06/2013

Meter Reading: 80,942.00

Close Date: 08/16/2013

Problem?

Generator oil is cloudy looking and smells like gasoline - problem was lbem a few weeks ago - please checked ...

Task performed:

Parts

Quantity

TRAVEL TO ST 93 CHECK OUT GEN OIL LOOKS OK AND NO FUEL IN OIL DRIVER SAID HE WOULD WATCH IT.

NO PARTS USED

Workorder: V57948

In Date: 05/24/2013

Meter Reading: 81,523.10

Close Date: 09/10/2013

Problem?

left front tire worn thin. warning wear bars flush with tread on the inside edge.

Task performed:

Parts

Quantity

REPAIRED D0-440-051613-18061

NO PARTS USED

Workorder: V59781

In Date: 08/13/2013

Meter Reading: 81,120.00

Close Date: 09/11/2013

Problem?

there is a strong smell of gas in the crankcase of the generator and oil is milky looking e93

Task performed:

Parts

Quantity

TRAVEL TO ST 93 SERVICE GENE.

NO PARTS USED

Workorder: V60454

In Date: 09/12/2013

Meter Reading: 81,742.00

Close Date: 09/23/2013

Problem?

no oil in station. need two qts today for e93. can we get a case please. thanks Cioffoletti

Task performed:

Parts

Quantity

DROP OFF OIL TO ST 93 PER W. O.

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V59133

In Date: 07/16/2013

Meter Reading:

Close Date: 10/09/2013

Problem?

generator -gas in oil - please chage oil and check carb for possible leakage into engine oil area..

Task performed:

Parts

Quantity

REPAIRED ON WO V59626.

NO PARTS USED

Workorder: V59664

In Date: 08/07/2013

Meter Reading:

Close Date: 10/11/2013

Problem?

ROLL UP DOOR TO COMPARTMENT R1 HAS BROKEN SPRING IN THE HANDLE/BAR. DOOR IS A R.O.M. DESIGN.

Task performed:

Parts

Quantity

REPAIRED ON PM.

NO PARTS USED

Workorder: V61123

In Date: 10/09/2013

Meter Reading: 82,121.00

Close Date: 10/11/2013

Problem?

Both headlights not working

Task performed:

Parts

Quantity

TRAVEL TO ST 93 CHECK OUT NO HEADLIGHT PROBLEM ON TRUCK AT STATION WITH CREW ASSET NOT THE SAME AS TRUCK IN STATION 10164638 IS IN SHOP THE TRUCK HERE IS OK.

NO PARTS USED

Workorder: V60387

In Date: 09/09/2013

Meter Reading: 81,581.00

Close Date: 10/16/2013

Problem?

red and yellow lights out on master intake control panel. located on right side of truck.

Task performed:

Parts

Quantity

MASTER INTAKE LIGHTS - RED AND GREEN LIGHTS ON MASTER INTAKE - INOP - CHECK OUT PROBLEM - FOUND BOTH LIGHT SOCKETS CORROIDED - REPLACE BOTH S OCKETS - RECHECK WORK INTAKE VALVE NOW OK.

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V60754

In Date: 09/24/2013

Close Date: 10/18/2013

Meter Reading: 81,941.90

Problem?

B inspection E93

Task performed:

Parts

Quantity



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

1. B-Inspection.
2. Wiper blades - Replace both wiper blades.
3. Decals - Remove accreditation decals and buff out areas.
4. Under trucks lights - Replace 5 under truck lights - have to rewire to attach new style led lighting.
5. Batt slide drawer - Batt slide drawer very hard to open and locking latches inop also - wash and clean out debris from tracks and rollers - lube and work drawer to free up wash and lube several times to free up and the same for the locking latches.
6. Trash line drawer - Same problem as above repair to batt draws.
7. Tank fill valve - Tank fill valve leaks water badly - remove valve and disassemble on bench - valve was so badly worn out it couldn't be rebuilt - replace with new valve and adjust push/pull rod.
8. Master drain valve - master drain valve constantly drips water - empty pump and remove valve assembly on bench rebuild and reinstall fill tank and pump check for leaks ok.
9. Step lights - Both rear step board lights inop - replace both light assemblies.
10. Lt. bar mounting - L/rear light bar station very loose - check out and found only one bolt remaining and it was very loose all three bolt hole we stripped out - drill and install thread inserts - install new bolts - tighten and reassemble.
11. Clearance light inop - Replace r/rear clearance light.
12. Flood light inop checkout problem with flood light. found had no power - trace down wiring and found broken wire - repair check now ok.
13. Mansaver - Replace L/side mansaver - note: parts didn't have right length (was and 1 1/2 to short) - cut padding from old mansaver and unfold end of new and pushed in old piece of padding rerolled end and glued together - install new mansaver on post.
14. R/side dash panel - check with parts on new dash panel - note: parts checked back history and found this is the 4th panel installed on this vehicle and the last one was on last service - checkout problem for so many brakeage - found two problems - one was with missing lower panel holding screws mounts broken inside dash - make up my own mounting system to hold lower panel corner tight.
15. R/3 compt. light - inop - Check out problem - bulbs check good and power in ok trace down ground wire - found poor ground repair - recheck now ok.
16. R/rear light bar inop. R/rear upper emerg light inop. R/rear scene light inop - checkout problem all lights had power but no ground - trace back wiring and found faulty ground connection repair and now all ok.
17. L/side back up light inop - checkout light had 95% of LEDs burnt out replace light fixture.

000000001085OIL DRAIN GASKET M2	2
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
000908022011OIL DRAIN PLUG M2	1
01-0269881-00IO FREEDOM BOARD	1
103385NDRAIN COCK	3
1094KIT-AIR HORN-GROVER	2
1891BULB	3
330-3024HUB COVER GASKET	2
370001ASEAL 35066	2
372000084MARKER LIGHT	1
5SCA0CCRLLIGHT STEP LED	2
60C00FCRCLEAR BACKUP 600 SERIES	1
68118358130600 SER OPTIC CLEAR	2
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
AMH-1AMH-1 VALVE EXTENSION	1
104967DIAPHRAM FOR 6 PORT DUMP VALVE	1
3576REAR BRAKE DRUMS	2
78158915 VALVE 1 1/2	1
15W40BSYN OIL BULK QTS	28
ACX-84534LUG NUT COVER PK10	10
27-102A22-54259-000 DOOM LIGHT SWITCH M2	1
2FC00ZCR4 IN ROUND LED	5
A22-54059-000DASH PANEL R/H M2	1
42809AIR FILTER M2	1
BKS-KD2262CAB LEVELING VALVE	1
CT4515METBRAKE LINNING	4
DDE-0000100285OIL CAP M2	1
ETNO817018TIE ROD END FTR3477	1
ETNO817019TIE ROD END FTR3476	1
FREIGHTSHIPPING CHARGES	1
H35SN12BULB	1
KIT8042S CAM BUSHING KIT	1
KIT8081BK SPRING KIT	2
KIT9081BRAKE HARDWARE KIT	2
MSA150-A16MANSAYER COVER	1
N000908020004PLUG OIL PAN MERC	1
R00178BOTTOM RAIL ASSBLY	2
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
AS1173SLACK AS11903 ADJUSTER M2	2



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

18. Front end bounces at 35 mph. Remove front tires - both front tires had seam bulges had good year rep. look at them - they replaced both tires - reinstall - install all missing lugnut covers on all four wheels.

19. Pulls to the right checkout front end - found one bad tie rod end - remove tie rod and replace both tie rod ends - reinstall tie rod and set toe.

20. L/side of front light bar no flash - Check out light bar - disassemble lights and remove complete control board - negative replace board assembly and reassemble light bar.

21. Rear brakes - set up vehicle on stands and do rear brake job - clean out debrie from anti brake rings on back of hubs - caked with mud and debrie and wash off all other debrie from brake shoe spider and etc. before reassembly.

22. Front brake pull to the left - remove drums and check out problem - found seals blow out and grease entering into brake area - disassemble and remove 5 cams and mounting brackets - rebuild spiders and brakes with new bushings and seals - install new spring kits, etc. reassemble all.

Workorder: V61357

In Date: 10/18/2013
Close Date: 10/23/2013

Meter Reading: 82,095.40

Problem?

Replace front tires

Task performed:

REPLACE FRONT TIRES.

Parts

NO PARTS USED

Quantity

Vendor?: ELPEX

Workorder: V61917

In Date: 11/10/2013
Close Date: 11/14/2013

Meter Reading:

Problem?

Generator on Engine - breaker switch - loose and fell inside case - switch is on and working E93

Task performed:

TRUCK HAS GEN THAT WAS REPAIRED.

Parts

NO PARTS USED

Quantity



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V62113

In Date: 11/18/2013

Meter Reading:

Close Date: 11/21/2013

Problem?

E93 CAPTAINS DOOR OPEN WARNING SENSOR RED LIGHT FLASHES.

Task performed:

Parts

Quantity

TRAVEL TO ST-93 DOWN INOP BAD SWITCH
R&R SWITCH TEST OK.

52-624SWITCH DOOR

1

Workorder: V61751

In Date: 11/04/2013

Meter Reading:

Close Date: 12/31/2013

Problem?

Driver side 2-1/2 intake female connection hard to turn

Task performed:

Parts

Quantity

TRAVEL TO ST-93 2 1/2 SWIVEL INOP LUBE
BEARINGS FREE UP SWIVEL WORN OUT WILL GET
NEW ONE.

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V61410

In Date: 10/21/2013

Meter Reading: 82,142.00

Close Date: 01/03/2014

Problem?

B INSPECTIONN CONTINUED FROM 60754

Task performed:

Parts

Quantity

23. R-1 COMPART. LOCK BAR BROKEN. LOCK DOWN LATCH ON R-1 COMP. ROLL UP DOOR IS BROKEN INSTALL SPECIAL ORDERED LOWER SECTION OF DOOR - REMOVE TRACKS AND DISASSEMBLE DOOR - NOTE: SECTION WAS ORDERED WITH KEY LOCK SYSTEM BUT AME IN WITHOUT - MEASURE AND BORE HOLES IN NEW SECTION, USING OLD KEY OLOCK ASSEMBLY INSTALLIN NEW SECTION - LOCK RODS WERE BENT - STRAIGHTEN AND INSTALL - ASSEMBLE SECTION TO DOOR - MODIFY HOILES IN SIDE TRACKS FOR LOCK RODS TO FIT PROPERLY.

NO PARTS USED

24.BAD AIR LEAKS - SPRAY AND CHECK FOR LEAKS -REPLACE ALL FITTINGS ON SEC. TANK - SOME ON DRI. TANK - REPLACE CONTROL VALVE ON CAB LEFT BAGS - FOUND TWO LEAKING IN LINE CONNECTORS LEAKING - ETC.

25. R3 AND L-3 ROLL UP COMPT. DOORS - MISSING DOOR STUDS ON COMPT ROLL UP DOORS DISASSEMBLE LOWER SECTIONS AND INSTALL MISSING STOPS REASSEMBLE.

26. AIR HORNS - REBUILD BOTH AIR HORN HEADS AND ADJUST TO TONES.

Workorder: V63092

In Date: 01/03/2014

Meter Reading: 83,845.80

Close Date: 01/03/2014

Problem?

on call not charging E93

Task performed:

Parts

Quantity

TESTED VOLTAGE AND WAS AT 142 ROAD TESTED AND CHECKED ALL CONNECTION AND TESTED.

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V63105

In Date: 01/03/2014
Close Date: 01/06/2014

Meter Reading: 83,845.80

Problem?

low voltage

Task performed:

CHECK CHARGING SYSTEM FOUND NEEDS A ALTERNATOR. REMOVE AND REPLACE ALTERNATOR ALSO REPAIR COOLANT LEAK.

Parts

Quantity

A0014949PA4949PA/4962 320 AMP UPGRADE SADDLE MC

1

Workorder: V63565

In Date: 01/21/2014
Close Date: 01/21/2014

Meter Reading: 84,250.50

Problem?

c/e light

Task performed:

FOUND COOLANT LOW ADDED FLUID CHECKED OK

Parts

Quantity

NO PARTS USED

Workorder: V62853

In Date: 12/20/2013
Close Date: 01/23/2014

Meter Reading: 83,640.70

Problem?

no power to triptix charger. 12 volt lighter port in dash came loose with posible blown fuse.

Task performed:

WENT TO 93 CHECK RESCUE 12 PARTS - CHECK OK.

Parts

Quantity

NO PARTS USED

Workorder: V63080

In Date: 01/02/2014
Close Date: 01/23/2014

Meter Reading: 83,845.80

Problem?

Low Voltage alarm showing 11.5V

Task performed:

TRAVEL TO ST 93 CHECK OUT BATTs AND CHARGING SYSTEM. R&R BATTs CHARGING F4.V.

Parts

Quantity

BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER BATTERY

4

HP-31D BATTERY 950CCA HP-31D

4



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V63301

In Date: 01/10/2014

Meter Reading:

Close Date: 02/03/2014

Problem?

hose bed cover in bad shape. 3/4 of all snaps or twist fastners are broke. cover has some velcro to the side walls that will not hold flapping while driving at highway speed. one rear buckle broke at hand rail.

Task performed:

Parts

Quantity

TRAVEL TO ST-93 REPLACE BROKEN HOSE BED COVER SNAPS AND 1/4 TURN HOLDERS ON COVER

NO PARTS USED

Workorder: V63521

In Date: 01/19/2014

Meter Reading:

Close Date: 02/06/2014

Problem?

Medic jump seat door (drivers side) weather stripping is falling off. E93

Task performed:

Parts

Quantity

1. REPAIRED DOOR GASKETS ON ALL DOORS.
2. REPAIRED AIR LEAK AT PUMP SHIFTER AND TESTED.

NO PARTS USED

Workorder: V64073

In Date: 02/08/2014

Meter Reading:

Close Date: 02/13/2014

Problem?

Missing O-ring on regulator - 300 psi air chisel

Task performed:

Parts

Quantity

CHECK OUT AIR CHISEL LEAK, NEED PLASTIC RING FOR SCBA BOTTLE WILL LET ROCKY KNOW.

NO PARTS USED

Workorder: V64333

In Date: 02/19/2014

Meter Reading:

Close Date: 02/25/2014

Problem?

cab a/c goes to ambient temp while driving or while parked with engine idling. have to shut off a/c wait 3-5 minutes, turn back on, a/c starts to blow cold again. thanks.

Task performed:

Parts

Quantity

TRAVEL TO ST-93 CHECK A/C INOP TEST DRIVE UNIT NO PROBLEM FOUND.

NO PARTS USED



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V63903

In Date: 02/01/2014

Meter Reading:

Close Date: 03/13/2014

Problem?

The triptix cable does not charge unless the engine is running. It would appear the the cable is not directly connected to the batter preventing it from charging while in the bay. E93

Task performed:

TRIPTIX CHARGER INOP INSTALL AND WIRE UP PLUG FOR TRIPTIX ON SIDE OF CONSOL.

Parts

56415CIG. LIGHTER ACCES.

Quantity

1

Workorder: V65014

In Date: 03/18/2014

Meter Reading:

Close Date: 03/20/2014

Problem?

DOME LIGHTS ON AND OFF WHILE DRIVING. HAD TO PUT SMALL NOTE PAD BETWEEN BUTTON AND DOOR TO SHUT C WHILE DRIVING. RIGHT FRONT OFFICERS DOOR. PLASTIC BUTTON,NOT METAL ONE IN JAM. R93

Task performed:

TRAVEL TO ST-93 R&R DOOR SWITCHES THAT WERE INOP.

Parts

3579984C1DOOR SWITCH

Quantity

3

Workorder: V64958

In Date: 03/16/2014

Meter Reading:

Close Date: 03/26/2014

Problem?

A/C is not blowing cold..... E93

Task performed:

CHECK A/C INOP CHECK FREON ECT. COULD NOT GET TO FAIL UNFOUNDED.

Parts

NO PARTS USED

Quantity

Workorder: V64980

In Date: 03/17/2014

Meter Reading:

Close Date: 03/26/2014

Problem?

air leak at splice fitting behind drivers seat, on the floor behind the drivers seat. E93

Task performed:

REPAIR AIR LEAK CHECK OUT FITTING R&R TIME AND FITTING.

Parts

NO PARTS USED

Quantity



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V65711

In Date: 04/15/2014
Close Date: 04/15/2014

Meter Reading: 86,132.00

Problem?

Air leak

Task performed:

AIR LEAK, FITTINGS AT FOOT VALVE. TRAVEL BACK TO SHOP FOR PARTS AND REPAIRED AIR LEAKS.

Parts

NO PARTS USED

Quantity

Workorder: V65574

In Date: 04/09/2014
Close Date: 04/17/2014

Meter Reading:

Problem?

Smoke exhaust fan/gas - running rough and the stalling - runs a little better when choke is at half - but still stalls

Task performed:

REPAIRED AT SHOP.

Parts

NO PARTS USED

Quantity

Workorder: V65980

In Date: 04/25/2014
Close Date: 05/13/2014

Meter Reading:

Problem?

front a/c goes warm at times. written up before, not sure if a problem has been found. lately (today) truck has done it three times, either while driving or while on a scene. turn a/c off, wait 10min, cold again.

Task performed:

INSTALLED HIGH PRESSURE SWITCH AND RAY SYSTEM AND TESTED OK AT THIS TIME.

Parts

22-51296-000BINARY SWITCH 1514 11-0640

78R536078R5360M 2PK FILTER AIR COND

FRT 65980FREIGHT CHARGE

Quantity

1

3

1

Workorder: V65242

In Date: 03/26/2014
Close Date: 05/22/2014

Meter Reading:

Problem?

AIR LEAK. TRUCK LOSES 60-70PSI OVER A 5 HR PERIOD. BOTH BANKS DROP EQUALLY. NO LEAK HEARD.

Task performed:

REPAIRED ON ANOTHER W.O#.

Parts

NO PARTS USED

Quantity



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V65915

In Date: 04/23/2014

Meter Reading:

Close Date: 05/22/2014

Problem?

E93 Air Chisel (no asset # from LW) bit retainer does not hold the bit in place resulting in bit falling out. Tagged and placed on work bench E93

Task performed:

Parts

Quantity

CREW SAID CAPT TOOK.

NO PARTS USED

Workorder: V66224

In Date: 05/05/2014

Meter Reading:

Close Date: 05/22/2014

Problem?

front a/c still acting up. blows but warm. Tommy replaced cut out switch on drier past week. had no power to compressor when blowing warm. acted up saturday and sunday. thanks Cioff

Task performed:

Parts

Quantity

CHECK OUT A/C ON E-93 TEST A/C TEMP AND COMPRESOR WORKING OK UNFOUNDED TRAVEL TO ST-93.

NO PARTS USED

Workorder: V66398

In Date: 05/12/2014

Meter Reading: 86,636.20

Close Date: 06/10/2014

Problem?

trans slipping

Task performed:

Parts

Quantity

E93 BROKE DOWN AT DIXIE HWY AND 10TH AVE LAKE WORTH DUMPED WATER TANK AND DROVE BACK TO STATION DID A FAST ADAPT REFILLED TANK THEN TEST DROVE TRANNY WORKS FINE DUE FOR SERVICE.

NO PARTS USED

Workorder: V66174

In Date: 05/02/2014

Meter Reading:

Close Date: 06/17/2014

Problem?

red oval shaped reflector fell off, need new one glued back on

Task performed:

Parts

Quantity

REPLACE MISSING REFLECTOR.

98032R 41032-3 RED REFLECTOR OVAL REFLECTOR

1

B484RB484R REFLECT-RED

1



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V66576

In Date: 05/19/2014

Close Date: 06/24/2014

Meter Reading: 86,762.00

Problem?

C inspection E93

Task performed:

Parts

Quantity



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

1. C-INSP.
2. MARKER LTS, REPLACE BOTH CTR. SIDE MARKER LTS. MODIFY HOUSING IN ORDER TO INSTALL.
3. MARKER LTS- REMOVE CTR LT. FIXTURE FROM INSIDE TAIL BOARD- ON BENCH DISASSEMBLE TO REPLACE CTR. TRIO FIXTURE- REINSTALL.
4. TRASHLINE COMPT DOOR VERY LOOSE AND RATTLES CHECK OUT PROBLEM- ADJUST ONE LATCH- THE OTHER HAD MISSING ADJUSTMENT STUD- LOOK THROUGH SPARE PART AND FOUND A STUD- INSTALL AND ADJUST.
5. WIPER BLADES REPLACE WIPER BLADES.
6. WASHERS INOP- CHECK OUT PROBLEM- FOUND PUMP RUNNING BUT NO OUT PUT- DRAIN BOTTLE AND REMOVE FROM VEHICLE- ON BENCH REMOVE PUMP AND FOUND TRASH IN SIDE BOTTLE PLUGGING UP PUMP- WASH AND CLEAN OUT BOTTLE- REINSTALL IN VEHICLE- FILL WITH CLEAN FLUID AND TEST- NOW OK.
7. ALL SLIDE OUT STEPS BINDING- BLOW OUT AND WASH OUT ROAD DEBRIS FROM SLIDE STEPS- RELUBE AND WORK SLIDES IN AND OUT UNTIL FREE.
8. A/C AIR FILTERS REPLACE CAB INTAKE FILTER AND REAR CAB FILTER- ALL BUT ONE SCREW IN FRT A/C FILTER COVER- MOUNTING EARS BROKEN- REPAIR EARS AND INSTALL NEW SCREWS.
9. BATTERIES FAILED BATT TEST- REPLACE ALL BATTS.
10. BATTSLIDE DRAWER BATT SLIDE DRAWER BINDING- WASH AND BLOW OUT ROAD DEBRIS FROM SLIDE- LUBE AND WORK DRAW IN AND OUT UNTIL FREE.
11. LADDERS HEAT SENSORS REPLACE LADDER HEAT SENSORS.
12. DRIVERS DOOR WINDOW CHECKOUT PROBLEM WITH ROLLING UP OF WINDOW- BINDS UP BAD ON LAST QUARTER OF ROLLING UP-FIRST LUBE WINDOW GUILS-NG-REMOVE ENTER DOOR PANEL- CHECK OUT TRACK AND ROLL UP GEAR- REASSEMBLE DOOR PANEL.
13. TIRE ROTATION SET UP VEHICLE ON STANDS AND ROTATE FRONT TIRES.
14. SERVICE AIR DRYER.
15. PUMP INTAKE SCREENS AND ANOIDS. DRAIN PUMP AND REPLACE ANOIDS AND BOTH INTAKE SCREENS.
16. ENG AIR INTAKE REPLACE ENG AIR INTAKE FILTER REMINDER- EXTARCT BROKEN PIECE AND INSTALL NEW AIR FILTER REMINDER.
17. ENG BELTS REPLACE ALL ENG BELTS- ALSO REPLACE BELT TENSIONER.
18. ENG NOISE THERE IS NOISE FROM OF ENG- FOUND ADJUSTER PULLY AND IDLE HAS BAD

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
01-29866-118BELT ALT. M2	1
0128042000PULLY TENSION	1
05-16062-051LOWER RAD HOSE M2	1
05-23195-000Z05-30740-000 SURGE TANK	1
0515923000HOSE RAD.	1
14-14527-001STEERING SHAFT 14-17013-007	1
470920HOSE AND FITTING	1
5008414CARTRIDGE DC100	1
0100030000SCREEN 6 IN	2
029-0511-00-0ANODE ONLY	2
35200-RLIGHT MARKER LED RED	1
35200-YLIGHT MARKER LEDAMBER	2
042-0091-00SPRING PRIMER	1
073004100PISTON	1
200-2450-00NC SWITCH OK TO PUMP	1
0773095TRUNNION THREAD	1
22-51374-000SENSOR AIR RESTRICTION	1
161812-0617A EXPANSION VALVE VCC88000030	1
203FFBEARING PULLEY	2
533303-0609 A/C COMPRESSOR M2 4485	1
719707-0614A AC DRIER M2	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
9550 BELT	1
A0924LADDER OUT OF SERVICE STICKER	6
A14-12612-002STEERING WHEEL M2	1
A14-15776-000STEERING COLUMN	1
A22-60405-001A/C HOSE	1
A9060160280GASKET	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	5
DDE/A9062003170BELT TENSIONOR MERCEDES	1
HP-31DBATTERY 950CCA HP-31D	5
K022105PURGE VALVE AD-IP-IS	1
PVG-KITORING KIT	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
VCC/36000006A/C FILTER CAB M2	1
91398907 VALVE KIT 3 IN AKRON	1
52-624SWITCH DOOR	4
91368904 VALVE KIT 1 1/2 IN	2
91378905 VALVE KIT 2 IN AKRON	3
91388906 VALVE KIT 2.5 IN AKRON	1



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

BEARINGS- REMOVE FROM VEHICLE AND REPLACE BEARINGS IN BOTH- REINSTALL.

19. CAB DOOR LT-SYSTEM CHECK OUT PROBLEM WITH INTERIOR CAB DOOR LTS ON CONTINUOUSLY ENDED WHEN MOVING- PULL OUT AND DISCONNECT ALL SWS LTS STILL ON- SEARCH THROUGH LIBRARY TO FIND WIRING SCHEMATIC- CHECK NODE SWITCHING- FOUND EVEN WITH OUTPUT SIDE OF NODE DISCONNECTED LTS ARE STILL ON- DISCUSS PROBLEM WITH SUPER (ED) AND IT WAS DECIDED TO PUT VEHICLE BACK TOGETHER AND LET IT BE AS IS.

20. FAILED VAC TEST- INSTALL GLOVES ON ALL INTAKE AND DISCHARGE OUTLETS- PRESSURIZE SYSTEM - REMOVE AND REBUILD EIGHT VALVES SOME VERY DIFFICULT TO ACCESS AND REMOVE- AFTER VALVE REBUILT AND REINSTALLED VACUUM TEST AGAIN- NOW PULLS HIGH VACUUM AND DROPED 2" IN 20 MINS.

21. PRIMER PULL VALVE VERY HARD TO PULL AND HAVE TO SLAM WITH A-LIST TO SHUT OFF- REMOVE PRIMER VALVE REINSTALL NOW WORKS- GODD.

22. FOAM SYSTEM FROM SIDE WALLS OF ALL THREE FOAM HOSES- NOTE: HOSES ARE DRY ROTTED AND CRACKED- REMOVE ALL THREE SEND TO MANKIND HOSE FOR NEW HOSES REINSTALL AND CHECK FOR LEAKS- NOW ALL GOOD.

23. EXPANSION BOTTLE COOLING SYSTEM LEAKING- CRACKS ON SIDES. ALSO FOUND TWO LOWER TRANS COOLER HOSES LEAKING- DRAINED OUT ENTIRE COOLING SYSTEM- INSTALL NEW EXPANSION BOTTLE AND BOTH INTAKE COOLER HOSES- REFILL REPRESSURE TEST- NOW OK.

24. FRT- CAB BLOWER HAS VERY LOW AIR VOLUMN FROM DASH REGISTERS- DISASSEMBLE AIR INTAKE AND CLEAN OUT AND CLEAN CONDENSER FINNS PLUGGED WITH TRASH- REMOVE FILTER AND CLEAN CONDENSER FINNS- REASSEMBLE- TEST- NOW HAS GOOD AIR.

25. FRT CAB A/C SYSTEM BLOWS WARM COOL CHECK OUT PROBLEM CHECK OUT PRESSURES AND FOUND HIGH SIDE PRESSURE LOW- EVACUATE RECHARGE SYSTEM TO FULL.

26. STEERING- THE STEERING COLUMN HAS ALOT OF SLOPP FROM SIDE TO SIDE AND HARSH KNOCKING IN STEERING WHEEL IN TILT COLUMN- REPLACED STEERING WHEEL AS COVERING IS LOOSE AND TWISTING.



1/29/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10164638

M2 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V68402

In Date: 08/04/2014

Meter Reading: 86,843.00

Close Date: 08/04/2014

Problem?

adjust scba brackets, E-920

Task performed:

1. adjust scba brackets on all 3 seats in cab

Parts

NO PARTS USED

Quantity

Workorder: V68135

In Date: 07/24/2014

Meter Reading:

Close Date: 12/18/2014

Problem?

1. Discharge #3 leaked during vacuum test 2. Right intake leaked during vacuum test 3. Discharge #2 gaugeneedle sticks 4. Left : intake screen missing

Task performed:

Close ticket repairs done on 66576 no charge

Parts

0769027STRAINER 2.5 IN

5W20MOTOR OIL 3360

Quantity

2

1

Workorder: V70169

In Date: 10/15/2014

Meter Reading: 86,843.00

Close Date: 12/24/2014

Problem?

Need spare keys

Task performed:

Parts

22-54495-000IGN KEY

Quantity

3

Workorder: V73539

In Date: 03/01/2015

Meter Reading: 88,034.00

Close Date: 03/12/2015

Problem?

B inspection

Task performed:

1. B insp
2. replace wiper blades

Parts

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT

0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH

906-181-00-86OIL FILTER M2 SPINNER 57140

91-22WIPER BLADE

S3226FL02FUEL FILTER 33813 L/F # LFF5851

Quantity

1

1

1

2

1



Palm Beach County Fire Rescue Fleet Maintenance Asset History

Asset: (10164638) 2005 - FERRARA M2 1250 Gpm Pumper E920

10164638

CSHOP-2015-1726

Comments: AIR NOT BLOWING FROM THE VENTS ON THE DASH.

Date Opened: 7-13-2015 Date Finished 7-13-2015 Meter 1 Reading: 88,556

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

CSHOP-2015-1761

Comments: GROUND LIGHT FLASHING NOT WORKING

Date Opened: 7-15-2015 Date Finished 7-16-2015 Meter 1 Reading: 88,599

INSATLLED NEW LIGHT AND REPAIRED WIRING

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM

1 LIGHT; LED GROUND LITE CLEAR

CSHOP-2015-2663

Comments: GENERATOR LEAKING FUEL

Date Opened: 9-2-2015 Date Finished 9-23-2015 Meter 1 Reading: 89,018

NEW GASKET

TASKS PERFORMED

Q PARTS

FIRE APPARATUS

6 9IP; GASKET 2 1/2"
1 FUEL VALVE AND SCREEN HONDA GENERATOR

CSHOP-2016-1106

Comments: C INSPECTION E920

Date Opened: 3-8-2016 Date Finished 3-16-2016 Meter 1 Reading: 90,000

TASKS PERFORMED

Q PARTS

PM SERVICE C

26 FLUID; SYN OIL BULK QTS
1 FILTER; FUEL FILTER 33813 L/F # LFF5851
1 FILTER; OIL FILTER M2 SPINNER 57140
1 FILTER; 33634 FUEL FILTER WIX
MERCEDES/FREIGHTLINE
1 FILTER; OIL FILTER 03 57215 WIX
MERCEDES/FREIGHTLINER

Asset Work Order History 10164638

CSHOP-2016-1426

Comments: **PM FOLLOW UPS E920**

Date Opened: 3-25-2016

Date Finished

4-5-2016

Meter 1 Reading:

90,057

TASKS PERFORMED

FIRE PUMP PLUMBING
FIRE PUMP
HOSE REEL
WIPER BLADES
AIR FILTER
SPOT LIGHTS
HEADLIGHTS HIGH BEAM
EMERGENCY EQUIPMENT

Q PARTS

1 PUMP; TRUNNION
1 VALVE; 8906 VALVE KIT 2.5 IN AKRON
1 PUMP; TRUNNION THREAD
1 VALVE; 8907 VALVE KIT 3 IN AKRON
1 GAUGE; VAC TEST GAUGE 0-30
1 VALVE; 8907 VALVE KIT 3 IN AKRON
1 9IP; GAUGE PRESSURE 0-100 PSI
1 VALVE; 8906 VALVE KIT 2.5 IN AKRON
4 COUPLING; COUPLING NIPPLE
2 9IP; GASKET
1 GAUGE; GAUGE AND BOOT
1 CHAIN; BEADED CHAIN W/CONN 12
2 WIPER; WIPER BLADE
1 FILTER; AIR FILTER M2
1 BULB; BULB
1 LIGHT; HEADLITE KIT WITH SEALER
16 CONNECTOR; 1PGK4 CONNECTOR 120V 20A FEMALE
2 REFLECTOR; 41032-3 RED REFLECTOR OVAL REFLECTOR

CSHOP-2017-1586

Comments: **PLEAS DO A D.O.T. B INSPECTION**

Date Opened: 3-14-2017

Date Finished

3-16-2017

Meter 1 Reading:

91,699

TASKS PERFORMED

PM SERVICE C

NO PARTS USED

CSHOP-2017-2325

Date Opened: 4-20-2017

Date Finished

5-10-2017

Meter 1 Reading:

92,032

TASKS PERFORMED

CONTROL VALVE FIRE PUMP
CHARGING SYSTEM

Q PARTS

3 5TF; DECK GUN WEAR STRIP
3 SEAL; QUAD SEAL FOR CROSSFIRE
1 BK; TESTER
1 CONNECTOR; 1PGK4 CONNECTOR 120V 20A FEMALE

Service Requests:

04/20/2017

BODY / 19: LOOSE / REPAIR

Asset Work Order History 10164638

CSHOP-2017-554

Date Opened: 1-25-2017 Date Finished 3-2-2017 Meter 1 Reading: 91,642

TASKS PERFORMED

NO PARTS USED

FIRE APPARATUS

Service Requests:

01/24/2017 ENGINE / 18: LEAKING / REPAIR
ENGINE WILL NOT DRAFT. DISCHARGE # 3'S VALVE WILL NOT CLOSE ALL THE WAY AND THIS MIGHT BE PREVENTING TRUCK FROM DRAFTING. NEED NEW HOSEBED TARP.

CSHOP-2017-5993

Date Opened: 10-18-2017 Date Finished 12-6-2017 Meter 1 Reading: 93,642

TASKS PERFORMED

Q PARTS

FIRE APPARATUS 1 NONSTOCK; FREIGHT CHARGE
ENGINE AND ACCESSORIES -1 9IP; VISTA III SREEN WELDON
BACK UP CAMERA-MONITOR 1 9IP; VISTA III SREEN WELDON
1 2FL; GAS PEDAL
1 5CS; CAPTAIN GOV. KIT
1 5SC; VISTA III SREEN WELDON REFURB

CSHOP-2017-6308

Date Opened: 11-1-2017 Date Finished 11-14-2017 Meter 1 Reading: 93,411

TASKS PERFORMED

Q PARTS

TIRES & WHEELS 2 9IP; AMH-1 VALVE EXTENSION

CSHOP-2017-7316

Date Opened: 12-22-2017 Date Finished 12-22-2017 Meter 1 Reading: 93,776

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2018-1200

Date Opened: 2-27-2018 Date Finished 3-16-2018 Meter 1 Reading: 94,111

TASKS PERFORMED

Q PARTS

PM SERVICE C 1 FIL; NAPAGOLD FUEL FILTER
26 9IP; 15W40 MOTOR OIL NON SYN
1 FIL; NAPAGOLD AIR FILTER
1 FIL; NAPA GOLD OIL FILTER
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPAGOLD OIL FILTER

Asset Work Order History 10164638

CSHOP-2018-1346

Comments: **P.M. REPAIR WORK ORDER**

Date Opened: 3-6-2018

Date Finished

3-16-2018

Meter 1 Reading:

94,111

TASKS PERFORMED

WIPER BLADES
ENGINE AND ACCESSORIES
LIGHTING SYSTEM
CRANKING SYSTEM
STEERING
BRAKES
AIR DRIER
EVAPORATOR-EVAPORATOR MOTOR

Q PARTS

2 1AN; 22" WIPER BLADE
3 9IP; 30055-20 CIRCUIT BREAKER
3 9AP; LIGHT
-2 9IP; 4 IN ROUND LED
2 9IP; 4 IN ROUND LED
4 1AD; BATTERY 31 SERIES
1 FIL; POWER STEERING FILTER
2 2TP; SLACK ADJUSTER FRONT
-1 TWD; PURGE VALVE KIT
1 TWD; PURGE VALVE KIT
1 TWD; PURGE VALVE ASSY KIT
1 FIL; NAPAGOLD AIR FILTER
1 FIL; NAPA CABIN AIR FILTER
1 2FL; HARNESS, BLOWER
1 2TK; FILTER
1 2FL; MOTOR, BLOWER

CSHOP-2018-1729

Date Opened: 3-27-2018

Date Finished

4-13-2018

Meter 1 Reading:

94,468

TASKS PERFORMED

TRAILER
WHEEL STUD
MIRRORS

Q PARTS

2 2IH; CHAIN BINDER
10 2FL; LUG NUT COVER 33M
1 2FL; CARRIER

CSHOP-2018-218

Date Opened: 1-10-2018

Date Finished

1-10-2018

Meter 1 Reading:

93,968

TASKS PERFORMED

COUPLERS

NO PARTS USED

CSHOP-2018-2218

Date Opened: 4-20-2018

Date Finished

5-23-2018

Meter 1 Reading:

94,554

TASKS PERFORMED

INTAKE VALVE

Q PARTS

2 5SC; ORING
2 5SC; SCREW
2 5SC; ORING
2 5SC; GASKET
2 5SC; WASHER
2 5SC; GUIDE PIN

Asset Work Order History 10164638

CSHOP-2018-2989

Date Opened: 5-30-2018

Date Finished

6-5-2018

Meter 1 Reading:

94,658

TASKS PERFORMED

Q PARTS

HURST TOOL CUTTERS

1 9LH; HONDA, PETCOCK GASKET
1 NGK; SPARK PLUG

CSHOP-2018-3139

Date Opened: 6-6-2018

Date Finished

6-14-2018

Meter 1 Reading:

94,658

TASKS PERFORMED

Q PARTS

SMALL ENGINE REPAIR

48 9AP; 2 CYCLE MIX

CSHOP-2018-3456

Date Opened: 6-19-2018

Date Finished

7-24-2018

Meter 1 Reading:

94,996

TASKS PERFORMED

Q PARTS

CONTROL VALVE FIRE PUMP
FIRE APPARATUS
LIGHTING SYSTEM

1 5SC; PINROLLER
1 5SC; SCREW
1 5SC; ORING
1 5SC; STEMVALVE
1 5SC; SHIM
1 5SC; PLATESEATVALVE
1 5SC; ORING
1 8HD; 20AMPMALEPLUG
1 8HD; STRAIGHTBLADE20A125V

CSHOP-2018-5182

Date Opened: 9-12-2018

Date Finished

9-13-2018

Meter 1 Reading:

94,996

TASKS PERFORMED

Q PARTS

FIRE PUMP

1 5TN; GOVERNOR

Asset Work Order History 10164638

CSHOP-2018-6190

Date Opened: 10-30-2018 Date Finished 2-21-2019 Meter 1 Reading: 95,729

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE PUMP
HOSE REEL
ENGINE AND ACCESSORIES
HEADLIGHTS LOW BEAM
ALTERNATOR-GENERATOR
FRONT TIRES
AIR SYSTEM
CAB-INTERIOR ACCESSORIES

1 5HP; ESP12 MOTORPRIMER PUMP WPVG PRIMER VLV
2 5AB; 15 VALVE SUB ASS SS BALL
2 5AB; 3- 3.5 BALL KIT COMPOSITE
1 5TN; CONVERSION KIT SS BALL 15
1 5TF; CUP SEAL
1 5HP; SOLENOID 12V, ESP
-2 5TN; 15 SUB ASSY SS WO R1 HANDLE
2 5TN; 15 SUB ASSY SS WO R1 HANDLE
1 5TF; DECK GUN WEAR STRIP
1 9AP; SILICONE LUBE
3 5AB; 2.5 BALL KIT COMPOSITE
1 5TF; ROTATION LOCK INSERT KIT
1 9ME; MOTOR BOOSTER REEL
1 2DD; GASKET
4 9OC; BULK COOLANT SOUTH SHOP
1 2DD; EGR VALVE
3 PAF; ANTIFRZ
1 MMM; LENS KIT
1 9IP; STARTER GRIP
1 5HP; VPS/KPS PWR SHIFT & CNTRL KIT
1 5SC; 4 WAY VALVE AIR SWITCH

CSHOP-2018-6853

Date Opened: 12-3-2018 Date Finished 12-3-2018 Meter 1 Reading: 95,463

TASKS PERFORMED

NO PARTS USED

TIRES ALL

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2018-811

Date Opened: 2-8-2018 Date Finished 2-13-2018 Meter 1 Reading: 94,111

TASKS PERFORMED

Q PARTS

WIPERS-WASHER
SPOT LIGHTS

2 1AN; 22" WIPER BLADE
2 ECH; SWITCH
2 GRO; SWITCH, BOOT

Asset Work Order History 10164638

CSHOP-2020-1594

Date Opened: 3-19-2020 Date Finished 4-9-2020 Meter 1 Reading: 97,142

TASKS PERFORMED

Q PARTS

PM SERVICE C

1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPAGOLD AIR FILTER
1 FIL; NAPA GOLD OIL FILTER
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPAGOLD OIL FILTER
26 4PC; 15W40 PB OIL DRM QT

CSHOP-2021-1455

Date Opened: 3-17-2021 Date Finished 3-22-2021 Meter 1 Reading: 97,885

TASKS PERFORMED

NO PARTS USED

PM SERVICE B

CSHOP-2021-1456

Date Opened: 3-17-2021 Date Finished 3-23-2021 Meter 1 Reading: 97,974

TASKS PERFORMED

Q PARTS

STORAGE CABINET EMERGENCY VEH
WIPER BLADES
EXHAUST SYSTEM
OIL FILTER
LIGHTING SYSTEM
ALTERNATOR-GENERATOR
REPAIR FROM PM - BELTS
INTERIOR TRIM-MOLDINGS-UPHOLS
A/C FILTER

2 1AN; 22 WIPER BLADE
1 GRO; REFLECTOR
1 GRO; REFLECTR
-1 NBH; V BELT
1 NBH; NBH
1 NBH; V BELT
1 1AD; SUTPHEN ALTERNATOR
1 NBH; SERPENTINE BELT
1 2FL; TREADPLATE RH
1 FIL; NAPA CABIN AIR FILTER
1 2RD; FILTER 17 5X5 5 MASTER PK 2

CSHOP-2022-1087

Date Opened: 2-24-2022 Date Finished 3-10-2022 Meter 1 Reading: 98,832

TASKS PERFORMED

NO PARTS USED

INSPECTION

CSHOP-2022-1088

Comments: **LUBE OIL FILTER AND PM FOLLOW UPS**

Date Opened: 2-24-2022 Date Finished 5-18-2022 Meter 1 Reading: 99,035

TASKS PERFORMED

Q PARTS

WIPER BLADES
WIPERS-WASHER
ENGINE AND ACCESSORIES
LIGHTING SYSTEM

1 2FL; RESERVOIR
1 LIT; REFLECTOR

Asset Work Order History 10164638

RADIO-2018-195

Comments: **REMOVAL OF 10141658, INSTALL OF 10199548 INTO 10164638 (ENGINE 920)**

Date Opened: 3-21-2018 Date Finished 3-21-2018 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

MOBILE RELATED

Service Requests:

03/21/2018 RADIO / /
REMOVAL & INSTALL OF MOTOROLA MOBILE RADIO INTO ENGINE 920

SSSHOP-2015-21

Date Opened: 4-23-2015 Date Finished 4-23-2015 Meter 1 Reading: 88,151

TASKS PERFORMED

NO PARTS USED

EMERGENCY EQUIPMENT

SSSHOP-2019-377

Date Opened: 11-5-2019 Date Finished 11-5-2019 Meter 1 Reading: 96,592

TASKS PERFORMED

NO PARTS USED

EMERGENCY EQUIPMENT

SSSHOP-2019-421

Date Opened: 12-12-2019 Date Finished 1-17-2020 Meter 1 Reading: 96,760

TASKS PERFORMED

Q PARTS

CONTROL VALVE FIRE PUMP
DISCHARGE GAUGE

10 5CS; GAUGE 3 5 30 600 WH

SSSHOP-2019-51

Date Opened: 2-19-2019 Date Finished 3-8-2019 Meter 1 Reading: 95,863

TASKS PERFORMED

Q PARTS

WIPERS-WASHER
ENGINE AND ACCESSORIES
BRAKES
HVAC SYSTEM

2 1AN; 22" WIPER BLADE
3 2FL; COOLANT SENSOR TEMP
4 9XX; 10177987 AC RECYCLER

SSSHOP-2019-54

Date Opened: 2-20-2019 Date Finished 2-22-2019 Meter 1 Reading: 95,729

TASKS PERFORMED

NO PARTS USED

PM SERVICE C

Asset Work Order History 10164638

SSHOP-2019-55

Date Opened: 2-21-2019

Date Finished

9-24-2019

Meter 1 Reading:

96,592

TASKS PERFORMED

Q PARTS

TANK SUCTION VALVE FIRE PUMP
FIRE PUMP
SIDE COMPARTMENT BODY
FIRE APPARATUS
FUEL SYSTEM
FAN
LIGHTING SYSTEM
ELECTRICAL
TIRES & WHEELS
DRIVESHAFT

1 5FF; AIRACTUATORWBUTTERFLYVALVE
1 5EO; BUTTERFLY VALVE PNEUMATIC ACTUATOR
4 5AB; 1.5 BALL KIT
1 5HP; MIVEBOTTOMLSFRRSREWORELIEFVALV
1 9IP; N122WSKL4000 SENSOR WATER IN FUEL
1 FIL; NAPA FUEL FILTER
1 5HP; MIVINSTALLKIT
1 FIL; NAPA FUEL FILTER
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPAGOLD FUEL FILTER
1 2FL; SENSOR, WIF (DOR9047370)
2 9AP; PLUG

SSHOP-2020-140

Date Opened: 5-12-2020

Date Finished

6-2-2020

Meter 1 Reading:

97,222

TASKS PERFORMED

Q PARTS

BATTERY
BODY EXTERIOR

4 1AD; 1000 CCA 31 SERIES BATTERY
6 5SC; ROM DOOR SPRING

SSHOP-2020-217

Date Opened: 7-1-2020

Date Finished

8-11-2020

Meter 1 Reading:

97,222

TASKS PERFORMED

Q PARTS

FUEL SYSTEM
LIGHTING SYSTEM

1 9ES; GO LIGHT LED BULB
4 1WL; LED FLOODLIGHT
3 GRO; SWITCH BOOT
4 GRO; SWITCH
2 1WL; SPOTLIGHT LED
2 ECH; TOGGLE SWITCH
2 GRO; SWITCH

SSHOP-2020-239

Comments: **TRUCK NOT STARTING**

Date Opened: 7-15-2020

Date Finished

7-16-2020

Meter 1 Reading:

97,222

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM
STARTER
DIAGNOSE ELECTRICAL
ELECTRICAL

1 2FL; STARTER 38MT

Asset Work Order History 10164638

SSHOP-2020-273

Date Opened: 8-13-2020 Date Finished 8-13-2020 Meter 1 Reading: 97,222

TASKS PERFORMED

NO PARTS USED

ENGINE MOUNT

SSHOP-2020-284

Date Opened: 8-18-2020 Date Finished 9-1-2020 Meter 1 Reading: 97,222

TASKS PERFORMED

Q PARTS

UNDERBODY COMPARTMENT BODY
HANDLIGHT
HEADLIGHTS LOW BEAM
BODY EXTERIOR

2 5EF; 434 LATCH TRIGGER S O
2 9ES; BULB LED 9006
2 9ES; BULB LED 9005

SSHOP-2020-375

Date Opened: 11-17-2020 Date Finished 12-21-2020 Meter 1 Reading: 97,420

TASKS PERFORMED

Q PARTS

SERPENTINE BELT
ENGINE AND ACCESSORIES

1 2FL; BELT
2 BRG; ALTERNATOR BEARING
1 NBH; V BELT
2 5SC; TEE FITTING
1 2FL; PULLEY IDLER
1 2FL; TENSIONER

SSHOP-2020-54

Date Opened: 2-5-2020 Date Finished 2-7-2020 Meter 1 Reading: 96,974

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM

1 LIT; GROMMET
1 5GI; LED LIGHT

SSHOP-2020-61

Date Opened: 2-13-2020 Date Finished 2-13-2020 Meter 1 Reading: 96,974

TASKS PERFORMED

NO PARTS USED

LIGHTING SYSTEM

SSHOP-2020-69

Comments: **HANDLE**

Date Opened: 3-2-2020 Date Finished 3-3-2020 Meter 1 Reading: 97,057

TASKS PERFORMED

NO PARTS USED

TAILGATE HANDLE-LINKAGE

Asset Work Order History 10164638

SSHOP-2020-98

Date Opened: 3-25-2020 Date Finished 4-9-2020 Meter 1 Reading: 97,142

TASKS PERFORMED

	Q	PARTS
WIPER BLADES	2	1AN; 22 WIPER BLADE
LIGHTING SYSTEM	1	1WL; SPOTLIGHT LED
STEERING	1	1WL; LED FLOODLIGHT
BODY EXTERIOR	1	FIL; POWER STEERING FILTER

SSHOP-2021-21

Date Opened: 1-15-2021 Date Finished 3-4-2021 Meter 1 Reading: 97,763

TASKS PERFORMED

	Q	PARTS
FIRE PUMP	10	8HY; GASKET KAMLOCK 1 5
LIGHTING SYSTEM	10	9HY; GASKET KAMLOCK 2 5
BODY EXTERIOR		

SSHOP-2021-279

Comments: **TICKET TO BE CLOSED AND FINISHED ON WO# SSHOP 2022-651**

Date Opened: 8-4-2021 Date Finished 9-9-2022 Meter 1 Reading: 99,257

TASKS PERFORMED

	Q	PARTS
SCBA BRACKETS	1	5CS; GOVERNOR 10 8
FIRE PUMP	2	4PC; 15W40 PREMIUM BLUE OIL
ENGINE AND ACCESSORIES	2	9AP; LED LIGHT
LIGHTING SYSTEM	1	8GR; PLUG 5 15P 15A 125VAC
SHORELINE CHARGER	1	8GR; BATTERY TENDER
SHIFTER CONTROLS-SELECTOR	1	6KU; AUTO EJECT W STD YEL CVR
INSTRUMENTS-GAUGES-METERS	2	8GR; CONNECTOR 5 20R 20A 125VAC
	2	1WL; LIGHT STRIP TANK STATUS

SSHOP-2021-3

Comments: **REAR CHAMBERS NOT RETRACTING ALL TH WAY**

Date Opened: 1-4-2021 Date Finished 1-11-2021 Meter 1 Reading: 97,420

TASKS PERFORMED

	Q	PARTS
BRAKE CHAMBER	1	DEL; DEL
AIR SYSTEM	2	TWD; AIR BRAKE CHAMBER
REPAIR FROM PM - BRAKES	1	2FL; SWITCH AIR
AIR BAG SYSTEM	2	TWD; KIT-CLEVIS LW
	1	2FL; MODULE
	1	2FL; AIRVALVE
	4	2FL; AIR VALVE
	2	9AP; AUTO SLACK ADJ
	2	2FL; CAB AIR BAG

Asset Work Order History 10164638

SSHOP-2021-89

Comments: **AXE HOLDER**

Date Opened: 3-9-2021

Date Finished

3-9-2021

Meter 1 Reading:

97,763

TASKS PERFORMED

NO PARTS USED

EQUIPMENT MOUNTING BRACKETS

SSHOP-2021-90

Date Opened: 3-9-2021

Date Finished

3-18-2021

Meter 1 Reading:

97,885

TASKS PERFORMED

NO PARTS USED

IGNITION SWITCH

SSHOP-2022-318

Comments: **WASHER TANK**

Date Opened: 6-14-2022

Date Finished

6-27-2022

Meter 1 Reading:

99,098

TASKS PERFORMED

NO PARTS USED

WIPERS-WASHER

SSHOP-2022-651

Date Opened: 9-9-2022

Date Finished

8-18-2023

Meter 1 Reading:

100,501

TASKS PERFORMED

Q PARTS

WATER TANK LEVEL LIGHTS

HURST TOOL CUTTERS

FIRE PUMP

HOOD

CANOPY

FUEL SYSTEM

LIGHTING SYSTEM

SHORELINE CHARGER

DOOR

SEAT FRONT

1	5CS; TRANSDUCER 300PSI 0 5V CAT CUMM
1	5EO; HOOD SHOCK
2	2IH; 50 50 COOLANT FLEETGUARD
1	FREIGHT
2	2FL; HOOD SUPPORT WIRE
1	5EO; 5EO
1	5EO; HOOD SUPPORT LEFT
1	8AM; 8 X 6 INDUSTRIAL SHELVING BRACKET 4PK
1	9AP; CRC DIESEL JUMP START
1	2DD; VALVE CHECK FUEL FILTER ASSEMBLY
1	NOL; NAPA GAL 15W40
12	MAC; SILICONE SPRAY 10OZ
1	2FL; SWITCH DOOR JAMB

SSHOP-2023-1016

Date Opened: 9-1-2023

Date Finished

9-28-2023

Meter 1 Reading:

0

TASKS PERFORMED

NO PARTS USED

HOSE BED BODY

VENDOR? CENTRAL AUTO TRIM CO.

Asset Work Order History 10164638

SSHOP-2023-1030

Date Opened: 9-6-2023

Date Finished

9-15-2023

Meter 1 Reading:

100,609

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM

1 9ES; 9005 LED HI BEAM

1 9ES; BULB HEADLIGHT LED 9006

SSHOP-2023-216

Date Opened: 2-17-2023

Date Finished

3-1-2023

Meter 1 Reading:

99,603

TASKS PERFORMED

NO PARTS USED

INSPECTION
