



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V26690**

In Date: 10/06/2009  
Close Date: 11/17/2009

Meter Reading: 37,678.00

**Problem?**  
repair comp door e 91

**Task performed:**

Parts \_\_\_\_\_ Quantity

Lake Worth - 10180867

NO PARTS USED

1. Rep left side compt door that wld not close.
2. Chk for air leaks; fnd none at this time. j

**Workorder: V26960**

In Date: 10/18/2009  
Close Date: 11/17/2009

Meter Reading: 37,678.00

**Problem?**  
pump panel water tank 3/4 indicator light out.( pierce contender) E91

**Task performed:**

Parts \_\_\_\_\_ Quantity

Lake Worth - 10180687

NO PARTS USED

1. Rep water level gauge.
2. Rep rear rollup door. j

**Workorder: V27231**

In Date: 10/28/2009  
Close Date: 11/30/2009

Meter Reading: 37,678.00

**Problem?**  
AC 10-7 E 91

**Task performed:**

Parts \_\_\_\_\_ Quantity

Recharged A/C sys & tested. j

NO PARTS USED



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V28298**

**In Date:** 12/12/2009

**Meter Reading:** 37,678.00

**Close Date:** 12/08/2009

**Problem?**

A inspection E91

**Task performed:**

1. For onboard btry charge; rem plug & wires for remote btry charger hookup.
2. Start T-shoot jake brake inop.
3. Start install comp shelves.
4. Start installing all shelving in compt of truck; mk shelf to fit each compt.
5. Rem light bar off top of truck; start to install.
6. Installed new light bar on top of truck; wire into controller in truck.
7. Work on installing shelf in rear compt of truck; cut/weld to fit.
8. Mov hose bed cvr over speed lay.
9. Complete shelf & nozzle rep hold down; screw coming thru plate; safety hazard; rep; mov other eqmpt to other places; install fire extinguisher brkt.
10. R/R rear light on tailboard; cut off plate to make it repairable.
11. Mnt grd monitor.
12. Install/adj new SCBA brkts.
13. Assist flush out of foam tank & sys.
14. Start install hard suction line.
15. Start install hard suction hose mounts.
16. Finish install of R/L hard suction hose mnts; unwrap/cut/drill (2) more mnts for next trk.
17. R/R both rear streamlight chargers.
18. A-Inspection
19. R/R w/washer reservoir in order to till it.
20. R/S washer nozzle squirts away frm windshield; R/R nozzle/install correctly.
21. Adj A/C belts.
22. R/R L-1 compt lt lens; R/R bulb.
23. Install msng screw in \_\_\_ Q. siren shield. j

**Parts**

**Quantity**

|   |    |
|---|----|
| 101305009SS0001 CPI SHELF BRACKET ONE HOLE 2005 | 20 |
| 1142BULB  | 1  |
| 15200RRED MARKER LIGHT RECTANGULAR              | 3  |
| 4020362171 GRO LAMP DOME 4 IN                   | 1  |
| 60351STEPWELL LIGHT                             | 2  |
| 68118147555RLENS EDGE SERIES                    | 5  |
| 9ECAPR9ECAPR END CAP RED                        | 2  |
| 9UTUBELINEAR REF CORNER                         | 1  |
| H27SN12BULB                                     | 1  |
| R950013TURBO CUT OFF VLV KIT                    | 1  |
| UMVS162511STRAP                                 | 2  |
| 9ULENSCCLEAR LENS FREEDOM BAR                   | 1  |
| 51731HYDRAULIC FILTER DR2 &3                    | 1  |
| 9MMEDGEPRRFLMINI EDGE 4 STRB                    | 2  |

**Workorder: V27909**

**In Date:** 11/24/2009

**Meter Reading:** 37,678.00

**Close Date:** 12/10/2009

**Problem?**

repair cutoff saw E91 (outside agency-regan's small engine service)

**Task performed:**

Repair cutoff saw E91 - Regan j

**Parts**

**Quantity**

NO PARTS USED

**Vendor?:** REGANS SMALL ENG



1/29/2024

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V27186**

**In Date:** 10/27/2009

**Meter Reading:** 37,678.00

**Close Date:** 12/16/2009

**Problem?**

C INSPECTION AND REPAIRS AS NEEDED E 91 CAB LIFT CYLINDER 10-7 INSTALL SHELVES IN COMPTS. BOX FOR MED GEAR IN COMP.

**Task performed:**

Parts

Quantity



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10180687

### CONTENDER FIRE DEPARTMENT PUMPER NFPA

- Road test & C-Inspection; general recently serviced
- 2. Use key pad on Allison trans & ECU button to gain flash code reading; unable to communicate w/ECU & Wabco sys via laptop.
- 3. Grease fitting left frnt slack adjuster bad; R/R new zert fitting & grease.
- 4. Rem leaking R/side cab lift cyl & diss for seal replacement; cln, inspect tube & rod; install new seals; reinstall cyl; fill reservoir & operate.
- 5. Gen data sheet fell off; reinstall.
- 6. Rem (2) 731H btry & install (6) 310.
- 7. Press wash eng compt frame rail frt/rear suspension & brake slack adjuster sys.
- 8. Complete C-Inspection
- 9. T-Case svc.
- 10. Diff oil svc.
- 11. Diff hi-water kit asy & install.
- 12. Trans fluid/filter svc.
- 13. Exh sys loose; rem brkn u-clamp & support; fab & install clamp/support; secure all loose fasteners.
- 14. Air dryer svc; rebuild purge valve asy & install filter.
- 15. Cut spring u-bolts in order to retorquing suspension; retorquing suspension bolts.
- 16. Air compressor blowing oil in air sys; diss & rem compressor out of eng.
- 17. Prep install new air compressor,
- 18. Air compressor air lines to tank & dryer leaking; rem, cut & install new air supply lines.
- 19. Coolant sys svc; change filter/fluid.
- 20. Air compressor coolant lines - rem/install new coolant line.
- 21. Rad cap failed press test; rem/install new radiator cap; coolant smell in cab due to bad radiator.
- 22. P/S leaking at sight glass; R/R bad sight glass o-ring; secure loose fitting to reservoir tank.
- 23. P/S filter & fluid svc.
- 24. Svc eng & A/C belts.
- 25. Ladder hyd leaking; inspect line; line fitting loose.
- 26. Ladder hyd leak; sec loose hyd line fitting; install hose protection shield on points that contact metal edges; tap cvr plate hoes & sec cvr plate in place.
- 27. Fuel cap paint; cln/prep fuel cap & fuel cap door inner section; paint yellow.
- 28. P/S supply hose to pump leaking; Rem/install new hose.
- 29. L-1 & R-1 compt door hinge bolt holes worn; rem doors; drill/retap holes; drill out hinge bolt holes; rehung doors & torque fastners.
- 30. L-side frnt bumper bolts msng; instlal replacement nut/bolt; torque bolts.
- 31. Cab lift safety bar loose; replc seat bar bolt & locking pad hold down bolt/nut.
- 32. Replc A/C filter & fab filter support brkt.
- 33. Rear seats unsecure; install (2) hinges on seat &

|                   |  |   |
|-------------------|--|---|
| 0769027           | STRAINER 2.5 IN                                    | 2 |
| 11-26521487       | SWITCH NC O 340 - C 210 HIGH PRESS                 | 1 |
| 1141              | BULB   | 2 |
| 1319A             | MARKER LAMP PIERCE LW                              | 2 |
| 160012-2012A      | EXPANSION VALVE 71R8301                            | 2 |
| 1817862           | C10 RING OIL PUMP                                  | 2 |
| 1818727           | C1 GASKET  | 1 |
| 1820287           | C2 IDLER BOLT                                      | 1 |
| 1821098           | C2 RING  | 2 |
| 1822708           | C1 SEAL  | 1 |
| 1824627           | C1 SCREW TIMING PLATE                              | 3 |
| 1824948           | C1 RING  | 6 |
| 1824984           | C95 SEAL KIT DT466 FRONT COVER                     | 1 |
| 1825685           | C1 SEAL  | 1 |
| 1826587           | C1 OIL PAN GASKET INTERNATIONAL                    | 1 |
| 40055R1           | IDLER BOLT   | 1 |
| 589903-3798       | AC COMPRESSOR EONE AND QUINTS PIER                 | 1 |
| 690437            | C95 CRANK SEAL                                     | 1 |
| 8943A             | MARKER LAMP LENS PIERCE LW                         | 2 |
| 91-20             | WIPER BLADE 20 IN                                  | 2 |
| EL36074           | RELAY VF4-15F11S05                                 | 1 |
|                   | FREIGHTSHIPPING CHARGES                            | 1 |
| PTX51813          | ANEROBIC SEALER                                    | 1 |
| UCB30             | FUSE 30AMP   | 1 |
| R950014           | PURGE VALVE WABCO AIR DRYER                        | 1 |
| 1142              | BULB   | 2 |
| 1157              | BULB   | 1 |
| B-1100B-1100      | CLAMP TOP LENS                                     | 1 |
| B-1102            | SPACER LENS  | 1 |
| 1820353           | C1 RING  | 1 |
| 29526898 29548988 | TRANS FILTER ALLISON                               | 1 |
| PH713851799       | FILTER OIL   | 1 |
| 3152310231/R31    | NEW SUTPHENS RAD CAP                               | 1 |
| FG83284           | DFG/HF6238 PS/HDY FILTER                           | 1 |
| PR338324070       | WIX FILTER WATER                                   | 1 |
| 347721            | HOSE AND FITTING                                   | 1 |
| 35799             | FLAT CLAMP 4 IN                                    | 1 |
|                   | BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER BATTERY | 6 |
| HP-31D            | BATTERY 950CCA HP-31D                              | 6 |
| JEIBC207M2BW      | JEIBC207M2BWS CABLE BATT                           | 1 |
| JEIBC207M2RW      | JEIBC207M2RWS CABLE BATT                           | 1 |
| JEIBC207M3BW      | JEIBC207M3BWS CABLE BATT                           | 1 |
| JEIBC207M3RW      | CABLE BATT   | 1 |
| 5004613           | AIR COMPRESSOR DT466                               | 1 |
| 5008414           | CARTRIDGE DC100                                    | 1 |



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10180687

### CONTENDER FIRE DEPARTMENT PUMPER NFPA

secure seat, allowing seat to swing open for compt access.

34. Dia eng oil leak; cln/run eng; oil leaking frm frnt cvr plate; need to pull rad & frt cver off to do repairs.

35. Look for electrical schematics for truck to dia electrical faults.

36. Grnd light inop; use of electrical schematics & test eqmpt to locate & rep lighting fault.

37. Assist w/grnd light ckt T-shoot. J. George

38. Left/right pump step light & tailboard light inop; fnd bulbs blown; rem/install new bulbs.

39. A/C fan motor knob msng; install replacment control knobs.

40. taglight inop; fnd corrosive grnd connection & blown bulb; cln contact & replc blown bulb.

41. R/rear brake light inop; replc blown bulb.

42. Pump compt light inop; bulb blown; replc bulb.

43. Dia A/C sys cooling problem

44. Rem bad windshield wiper blades; install new blades

45. Rear tool compt light out; rem blown bulb & install new bulb.

46. Left/right pump intake screen msng; install (2) new screens.

47. Chk points where excess heat entering cab & seal.48. Ladder rack arm padding msng; install new.

49. Parts research & eng specs for frnt cvr repair.

50. A/C sys dia fault.

51. A/C sys repair; vac sys; rem dryer; install new E. valve; reassemble, vac sys & charge.

52. Assisted with A/C compressor replacement - Reines.

53. Cab markeer lights asy damage; rem/rewire, reseal & install new asy.

54. A/C compressor damage; rem, diss, isntall clutch & belt pulley to new compressor; reassemble, vac sys & charge.

55. Eng compt light - no power; run new wiring for ompat.

56. Drain eng oil; fill pan, run eng; chk for oil leaks.

57. Get 3500 series gen; chk oil, fuel, frame, run unit.

j

74R258607-2613A RED DOT DRIER 7127

1

921LIGHT BULB

7

95809580 BELT

2

R950013TURBO CUT OFF VLV KIT

1

**Workorder:** V27573

**In Date:** 11/10/2009

**Meter Reading:** 37,678.00

**Close Date:** 12/29/2009

**Problem?**

repair oil leak e91 fla detroit diesel

**Task performed:**

Parts

Quantity

NO PARTS USED

**Vendor?:** FL DETROIT



1/29/2024

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V27243**

In Date: 10/28/2009

Meter Reading: 37,678.00

Close Date: 01/15/2010

**Problem?**

install graphics E91

**Task performed:**

Parts

Quantity

Install graphics E91 - Graphic Designs

NO PARTS USED

Vendor?: GRAPHIC DESIGNS

**Workorder: V27818**

In Date: 11/20/2009

Meter Reading: 37,678.00

Close Date: 01/15/2010

**Problem?**

replace 2 front tires E91 (outside agency-callaghan tire)

**Task performed:**

Parts

Quantity

Replc (2) front tires E91 - Callaghan j

NO PARTS USED

Vendor?: CALLAGHAN

**Workorder: V28756**

In Date: 01/03/2010

Meter Reading: 5,893.00

Close Date: 02/01/2010

**Problem?**

Officer's side Generator outlet may be wired incorrectly. The Hot and Neutral wires are reversed compared to the other outlet and other cords. Spoke to A-Tech 13 on the phone. Outlet breaker is turned off.

**Task performed:**

Parts

Quantity

Tested wires & outlet; rewired. j

NO PARTS USED

**Workorder: V29146**

In Date: 01/14/2010

Meter Reading: 5,848.00

Close Date: 02/01/2010

**Problem?**

AC unit is not working. Blowing hot. E91

**Task performed:**

Parts

Quantity

Recharged unit & tested. j

NO PARTS USED



1/29/2024

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V29825**

In Date: 02/09/2010

Meter Reading: 42,807.00

Close Date: 03/02/2010

**Problem?**

The glass in the officer's door shattered when the door was closed. E91

**Task performed:**

Parts

Quantity

The glass in the officer's door shattered when door was closed E91 - Charlies j

NO PARTS USED

Vendor?: CHARLIES AUTO GLASS

**Workorder: V29468**

In Date: 01/27/2010

Meter Reading: 5,880.00

Close Date: 03/03/2010

**Problem?**

Emergency light out, left lower rear. No bulbs here. e91

**Task performed:**

Parts

Quantity

replcd bulb inrear emergency light. j

NO PARTS USED

**Workorder: V29785**

In Date: 02/08/2010

Meter Reading: 42,730.00

Close Date: 03/03/2010

**Problem?**

running light out above cab. the float mechanic advised us we need a new lense for flasher on left rear tail board, just below tail light. Thank you. E91

**Task performed:**

Parts

Quantity

Rep running light that was not working. j

NO PARTS USED

**Workorder: V29795**

In Date: 02/08/2010

Meter Reading: 42,730.00

Close Date: 03/03/2010

**Problem?**

on call light 10-7 e91

**Task performed:**

Parts

Quantity

L/R lower strobe inop; replcd bulb. j

H50TL12BULB

1



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V30315**

In Date: 03/01/2010  
Close Date: 03/17/2010

Meter Reading: 43,182.00

**Problem?**

replace starter (on-call) E91

**Task performed:**

ON CALL WONT START FOUND STARTER BAD  
REPLACE STARTER

**Parts**

NTS-1562STARTER C SERIES USE 10461277

**Quantity**

1

**Workorder: V30738**

In Date: 03/15/2010  
Close Date: 03/17/2010

Meter Reading: 43,695.00

**Problem?**

air leak E91 (on-call repair)

**Task performed:**

ON CALL WENT TO H.Q. CHECK FOR AIR LEAK NONE  
FOUND TALKED WITH OPERATOR SAID PROBLEM  
HAD NOT HAPPENED SINCE EVENT FOUND AIR  
DRYER REBUILT 11/09 R&R PURGE VALVE FOUND  
DRYER OILY AND WET RAN UNIT AND CHECK NPF

**Parts**

R950014PURGE VALVE WABCO AIR DRYER

**Quantity**

1

**Workorder: V29228**

In Date: 01/19/2010  
Close Date: 03/19/2010

Meter Reading: 4,329.00

**Problem?**

on call fuel leak e91

**Task performed:**

Rep fuel leak at fuel filter. j

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V29826**

In Date: 02/09/2010  
Close Date: 03/19/2010

Meter Reading: 42,807.00

**Problem?**

We discovered fuel dripping from the area under the on-board generator. Could not find the source. On-call mechanic notified and the leak stopped on it's own. After a short drive with no leak, the truck is in-service. E91

**Task performed:**

1. Light bar inop; rep grnd wire.
2. Fuel leak; fnd hole in fuel line; replc fuel line & ran gen. j

**Parts**

15W40QSYN OIL QT

9UTUBELINEAR REF CORNER

**Quantity**

12

2





1/29/2024

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V30387**

In Date: 03/02/2010  
Close Date: 03/26/2010

Meter Reading: 43,401.00

**Problem?**

E- 91 water leak

**Task performed:**

ran pump; rep wtr leak at master drain. j

Parts

Quantity

NO PARTS USED

**Workorder: V29552**

In Date: 01/30/2010  
Close Date: 04/21/2010

Meter Reading:

**Problem?**

foam system not working E91

**Task performed:**

tested foam sys & tested ok. j

Parts

Quantity

6091410009FOAM LEVEL SENSOR

1

**Workorder: V30334**

In Date: 03/01/2010  
Close Date: 04/21/2010

Meter Reading: 43,401.00

**Problem?**

THE TIC CHARGER IS SITTING ON THE DASH NOT SECURED. THE WIRES ARE CONNECTED BUT IT IS NOT FASTENED TO THE DASHBOARD.E91

**Task performed:**

Will reinstall tic at later time. j

Parts

Quantity

NO PARTS USED

**Workorder: V30342**

In Date: 03/01/2010  
Close Date: 04/21/2010

Meter Reading: 43,401.00

**Problem?**

E91 HAS MULTIPLE TOOLS THAT NEED TO BE PLACED WITH BRACKETS. SLEDGE HAMMER, BOLT CUTTER, PRY BAR, TOOL, CLOSET HOOK, NY HOOK. B SHIFT HAS LIST WITH LOCATIONS. PLEASE CONTACT CAPTAIN ISLER OR COME ON SHIFT.

**Task performed:**

Will mount tools at later time. j

Parts

Quantity

NO PARTS USED



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V30830**

In Date: 03/18/2010  
Close Date: 04/21/2010

Meter Reading: 43,695.00

**Problem?**

install comp in cab e91

**Task performed:**

1. Installed compt in rear cab.
2. Chkd oil leak; will rep at B. j

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V30853**

In Date: 03/19/2010  
Close Date: 04/21/2010

Meter Reading: 43,695.00

**Problem?**

install extra lighting on rear of unit e91

**Task performed:**

1. install new LEDS on rear of truck.
2. Replc rear totator.
3. Install storage box in cab.
4. Water level gauge inop; recalibrated. j

**Parts**

60R00FRR600 SERIES RED LED W/O FLANGE  
 90RR5FCR900 LED SUPER RED CLEAR  
 RB6DRPRB6PRP RED ROTATING BEACON  
 RSR03ZCRLIGHT LED RED TIR3 SERIES

**Quantity**

2  
2  
1  
3



1/29/2024

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V31163**

**In Date:** 03/30/2010

**Meter Reading:** 43,955.00

**Close Date:** 04/26/2010

**Problem?**

**B INSPECTION AND REPAIRS AS NEEDED E91**

**Task performed:**

Parts

Quantity



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10180687

### CONTENDER FIRE DEPARTMENT PUMPER NFPA

#### B-Inspection

2. Rem leaking eng oil feed line to press switches; install new hose after having hose made up; see rep below.
3. Rem leaking hi-press power steering hose; take hoses to Mako Hose & wait for new hoses to be made up; install new hose.
4. Rem leaking fuel rail line; order parts; install new fuel line.
5. Remove oil dipstick & order parts.
6. Rem 1" coolant hose frm bottom of rad tank; cut off bad end & reconnect; tighten hose lcamp to proper torque.
7. Rem upper tank "coolant low level sensor" & order parts; put a plug in tank until new sensor arrives; drain down rad & install new sensor; also rep wiring.
8. Rem leaking eng oil cooler frm side of block; diss cooler on bench; wash & cln all oil ring grooves & flat surfaces; install all new seals & o-rings; reassemble on bench & reinstall in veh.
9. Adj all tire press.
10. Rem eng belt tensioner-broke; install new tensioner; fnd that new tens wld not adj belt; research problem & fnd that new belt installed previously was wrng application; try diff belts untill proper one was fnd.
11. Loosen A/C compressor brkts & with a straight edge; align misaligned pulleys/belts; lock in proper position.
12. Install (2) cab clearance lites; rep one socket & install bulbs.
13. Install wiper blades.
14. Install proper rad cap; NOTE: had new 16 lbs cap on rad; proper cap is 10 lbs.
15. Rem dash & replc all illumination bulbs.
16. Install all eqmpt mentioned by captain after we went over areas to install the eqmpt; gather up new eqmpt from Wayne to use for set up; NOTE: some will stay, others to be returned to Wayne; some mod to shelving was ness for installation.
17. Rep pump panel lites; some bulbs & entire fixtures; rep wiring.
18. Retorque all spering u-bolts; search shop for socket to fit nuts.
19. Reglue heat & sound padding udner cab (eng compt).
20. Rep left/right side, center primeter lighting; chk power to fixtures; only one had power; trace wires & fnd bad splice; rep; now has power but bad bulb; replc; bulb also on R/side.
21. Install new LED tail/brake lite fixture to fit inside lite fixture hsng.
22. Install new style placard brkts.
23. Install more eqmpt brkts as crew was changing out veh; swap out some old eqmpt for new. j

|  |    |
|--|----|
| 05-17223-000CAP RADIATOR 10 LB           | 1  |
| 15W40BSYN OIL BULK QTS                   | 30 |
| 1812348C1FUEL LINE SLEEVE INT            | 4  |
| 1817677C91FUEL FILTER SCREEN ASSY        | 1  |
| 1820396C2OIL FILL GUAGE INT DT466 PIERCE | 1  |
| 1821098C2RING                            | 2  |
| 1823182C95OIL COOLER SEAL KIT DT466      | 2  |
| 194BULB                                  | 10 |
| 33403FUEL FILTER LW                      | 1  |
| 33411FILTER FUEL SERIES 40               | 1  |
| 42-1436SWITCH LOW COOLANT                | 1  |
| 91-20WIPER BLADE 20 IN                   | 2  |
| FREIGHTSHIPPING CHARGES                  | 10 |
| LPVM-7LG MOUNT                           | 3  |
| PH713851799 FILTER OIL                   | 2  |
| PR338324070 WIX FILTER WATER             | 1  |
| SAHSVS2510STRAP                          | 1  |
| L PLACARDLARGE SIDE PLACARD              | 2  |
| 1829801C91FUEL TUBE DT466                | 1  |
| 1830033C2TENSIONER                       | 1  |
| 356029HOSE/FITTING                       | 1  |
| 4020362171 GRO LAMP DOME 4 IN            | 2  |
| 70R00XRR700 SER LED STOP LIGHT           | 2  |
| 60351STEPWELL LIGHT                      | 1  |
| K080716BELT                              | 1  |



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

## Workorder: V31809

In Date: 04/26/2010  
Close Date: 04/30/2010

Meter Reading: 44,300.00

### Problem?

won't start E91 (on-call)

### Task performed:

Traced out problem; unable to rep; swapped out.

### Parts

1771114END CAP ROLL UP DOOR WPB

### Quantity

6

## Workorder: V31810

In Date: 04/26/2010  
Close Date: 04/30/2010

Meter Reading: 44,300.00

### Problem?

pump leaking E91 (on-call)

### Task performed:

1. Fnd fitting on pump leaking; rem/rep.
2. Air leak; fnd fitting on air tank was brkn; re/installed new.

### Parts

NO PARTS USED

### Quantity

## Workorder: V28804

In Date: 01/04/2010  
Close Date: 05/01/2010

Meter Reading: 42,029.00

### Problem?

install foam sender e91 part is in see art

### Task performed:

replc t-signals lites that were switched to LEDS. j

### Parts

60-9141-0001PROBE FOAM LEVEL PIERCE  
 70R00XRR700 SER LED STOP LIGHT  
 FREIGHTSHIPPING CHARGES

### Quantity

1  
2  
45

## Workorder: V29602

In Date: 02/01/2010  
Close Date: 05/01/2010

Meter Reading: 5,915.50

### Problem?

indicator lights for foam tank are staying on. Drained tank, lights stayed on.E91

### Task performed:

1. wrng sender; need to order new one.
2. Installed new sender & tested.

### Parts

NO PARTS USED

### Quantity



1/29/2024

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V31027**

In Date: 03/25/2010      Meter Reading: 43,792.00  
Close Date: 05/01/2010

**Problem?**

Secure TIC charger to dash safety issue. e91

**Task performed:**

Reinstalled tic charger to dash. j

Parts

Quantity

NO PARTS USED

**Workorder: V31144**

In Date: 03/30/2010      Meter Reading: 43,955.00  
Close Date: 05/05/2010

**Problem?**

left rear brake light out. also we need motor oil for engine. E91

**Task performed:**

Rep L/rear brake lite. j

Parts

Quantity

NO PARTS USED

**Workorder: V31772**

In Date: 04/25/2010      Meter Reading: 44,300.00  
Close Date: 05/05/2010

**Problem?**

Engine will no start after morning checks. Electronic ignition does nothing. On call mechanic notified via dispatch (AT13).

**Task performed:**

1. No start; loose wire in relay panel.
2. Cab lift inop; loose wire in relay panel; also manual pump brkn; rem pump asy to locate part.
3. Assist w/wire problem - Sheedy.
4. Rep cab lift pump;pivot bar brkn; fab new pivot bar.
5. Assist w/cab lift pump repair - Larson.
6. A-Inspection
7. Top off eng oil low; top off eng oil.
8. Fill wtr tank; filled tank; also back flushed L/S aux inlet to get leak to stop.
9. L/R/O low; valve core leaking; replc valve core. j

Parts

Quantity

2505183C91LEVELING VALVE

2

2506796C1INTERNATIONAL INSTRAMENT LIGHTS

10



1/29/2024

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V31864**

In Date: 04/28/2010  
Close Date: 05/05/2010

Meter Reading: 44,300.00

**Problem?**

WHILE YOU HAVE e91 AT SHOP, CAN YOU INSTALL AN INTERIOR LIGHT OVER HEAD OF DRIVERSIDE REAR FOR FF NE EQUIPMENT CABINET.

**Task performed:**

Install light per stn request; will install at another time; seems like it needs (2) lites in box behind driver. j  
2. Installed light in rear cab.  
3. Remntd 5" hose on side. j

| Parts               | Quantity |
|---------------------|----------|
| ECVDMLT00DOME LIGHT | 1        |

**Workorder: V31603**

In Date: 04/17/2010  
Close Date: 05/11/2010

Meter Reading: 44,158.00

**Problem?**

#2 speedlay(preconnect) and front discharge(preconnect) gauges are not working. several gauges are discolored E91

**Task performed:**

Air leak; rep fitting on air tank. j

| Parts         | Quantity |
|---------------|----------|
| NO PARTS USED |          |

**Workorder: V31676**

In Date: 04/20/2010  
Close Date: 05/11/2010

Meter Reading: 44,158.00

**Problem?**

We have 3 pressure gauges that are not working. #2, #4 and front discharge. e91

**Task performed:**

Replc five gauges on pump panel that were bad. j

| Parts                           | Quantity |
|---------------------------------|----------|
| 1452878-00012.5 IN 30-0-400 PSI | 5        |
| 91553941GAUGE                   | 1        |
| 91553943GUAGE                   | 2        |
| FREIGHTSHIPPING CHARGES         | 10       |

**Workorder: V32140**

In Date: 05/11/2010  
Close Date: 05/19/2010

Meter Reading: 44,300.00

**Problem?**

won't start E91 (on-call) sister towing

**Task performed:**

Won't start E91 - Sisters Towing j

| Parts         | Quantity |
|---------------|----------|
| NO PARTS USED |          |

**Vendor?: SISTERS TOWING**



1/29/2024

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V32334**

In Date: 05/20/2010  
Close Date: 06/04/2010

Meter Reading: 44,825.00

**Problem?**

engine oil leak E91

**Task performed:**

Chk for leak; will monitor. j

Parts

Quantity

NO PARTS USED

**Workorder: V32325**

In Date: 05/19/2010  
Close Date: 06/25/2010

Meter Reading: 44,825.00

**Problem?**

HAVE STORX JAFFE VALVE NEED REBUILT LEAKS WATER SEAL BAD. OFFICERS SIDE PLACED BLANK IN PLACE. E91

**Task performed:**

PU valve to have repaired. j

Parts

Quantity

NO PARTS USED

**Workorder: V32625**

In Date: 06/03/2010  
Close Date: 06/30/2010

Meter Reading: 45,153.00

**Problem?**

repair oil leaks e91 fla detroit

**Task performed:**

Repair oil leaks E91 - Fla. Detroit j

Parts

Quantity

NO PARTS USED

Vendor?: FLA. DETROIT

**Workorder: V32980**

In Date: 06/18/2010  
Close Date: 07/20/2010

Meter Reading: 45,486.00

**Problem?**

Both side warning beacons on the roof are not working. E91

**Task performed:**

Fnd bad connection on lights; rep/tested. j

Parts

Quantity

NO PARTS USED





1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V33200**

In Date: 06/28/2010  
Close Date: 08/18/2010

Meter Reading: 45,486.00

**Problem?**

Looking to have straps mounted on Capt. side for soft suction. Thanks. e91

**Task performed:**

Top clearance lights msng on cab; reinstalled all (5) clearance lights; used silicone to seal holes; tested opn; ok. j

| Parts                      | Quantity |
|----------------------------|----------|
| 1319AMARKER LAMP PIERCE LW | 5        |
| FREIGHTSHIPPING CHARGES    | 15       |

Air leak; traced out air leaks; fnd one at tank; rep/tested. ja 8/18/10 ja

**Workorder: V34614**

In Date: 08/30/2010  
Close Date: 09/03/2010

Meter Reading: 46,576.00

**Problem?**

generator 10-7 E91 (callout repair)

**Task performed:**

To shop for spare gen for eng 91; requested by DC3. js

| Parts         | Quantity |
|---------------|----------|
| NO PARTS USED |          |

**Workorder: V33986**

In Date: 08/02/2010  
Close Date: 09/10/2010

Meter Reading: 45,758.00

**Problem?**

replace front tires at 91 boulevard

**Task performed:**

replc front tires at Stn91 - Boulevard j

| Parts         | Quantity |
|---------------|----------|
| NO PARTS USED |          |

Vendor?: BOULBVARD TIRE

**Workorder: V34453**

In Date: 08/23/2010  
Close Date: 09/15/2010

Meter Reading: 46,576.00

**Problem?**

generator cranks, but won't start E91 (callout repair)

**Task performed:**

Gen wont start; fuel shut off solenoid; very hot; suspect it is faulty; no fuel getting thru injector pump; offered FF spare gen; said they wld hold off. j

| Parts         | Quantity |
|---------------|----------|
| NO PARTS USED |          |



1/29/2024

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V34454**

In Date: 08/23/2010  
Close Date: 10/06/2010

Meter Reading: 46,576.00

**Problem?**

generator cranks, but won't start E91

**Task performed:**

Dia intermittent problem; replcd cracked fuel line; test oil press switch-ok; connect wires properly to swtch; test fuel shut off solenoid - ok; tried to bleed pump -pump bad; ordered parts. j  
2. installed fuel shut off solenoid, tried to start , unit will stiil not stort, towing to shop. jab

| Parts                   | Quantity |
|-------------------------|----------|
| FREIGHTSHIPPING CHARGES | 10       |
| SA4569TSOLENOID         | 1        |
| UMVS111611STRAP         | 2        |

**Workorder: V32918**

In Date: 06/15/2010  
Close Date: 10/19/2010

Meter Reading: 44,825.00

**Problem?**

verify oil leaks repaired (just back from fla detroit diesel) replace shock on cabinet, put door edge guard around cabinet E91

**Task performed:**

Completed j

| Parts                            | Quantity |
|----------------------------------|----------|
| 101281012GSS6298UH STRUTS 90#    | 1        |
| 1141BULB                         | 1        |
| 20036BRACKET BALL MT             | 1        |
| EAA-8350-60UGSS6557UP STRUT-LIFT | 1        |
| HA24121HA24121 BRACKET-BALL MT   | 2        |
| KR-CCLCATHODE COMPARTMENT LIGHT  | 2        |

**Workorder: V34444**

In Date: 08/23/2010  
Close Date: 10/20/2010

Meter Reading: 46,576.00

**Problem?**

Drivers side window handle broken. E91

**Task performed:**

Rep window handle j

| Parts         | Quantity |
|---------------|----------|
| NO PARTS USED |          |



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V35008**

In Date: 09/16/2010  
Close Date: 10/20/2010

Meter Reading: 46,687.00

**Problem?**

On board foam system does not work. E91

**Task performed:**

- 1. Ran foam sys & tested ok.
  - 2. Installed new ejector pump for gen & new fuel lines.
- j

Parts

Quantity

NO PARTS USED

**Workorder: V35048**

In Date: 09/19/2010  
Close Date: 10/20/2010

Meter Reading: 46,687.00

**Problem?**

vent fan on E 91 won't throttle up, only runs in choke mode.

**Task performed:**

- CIn carb & tested fan. j

Parts

Quantity

NO PARTS USED

**Workorder: V35369**

In Date: 10/04/2010  
Close Date: 10/25/2010

Meter Reading: 46,687.00

**Problem?**

ON CALL AIR LEAK E 91

**Task performed:**

- 1. road call, check for air leak, found air leak at pump panel air switch, repaired, test ok. jab

Parts

Quantity

NO PARTS USED



1/29/2024

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V35528**

**In Date:** 10/09/2010

**Meter Reading:** 46,687.00

**Close Date:** 10/25/2010

**Problem?**

Officer's door, inside handle is not opening the door. Door opens using the outside handle. E91

**Task performed:**

1. check truck for no power, check turbo and after cooler found no problem, hook up laptop, check - has a misfiring cylinder and speed sensor code. r&r speed sensor, checks ok.
2. officer door inop, check door found broken clip , r&r clip and seized screws, tested ok. jab
3. Sent to shop to rep handle.
4. Mnt tools in L-1 compt.
5. Rep drivers seat belt that was not latching. j

**Parts**

**Quantity**

29543432INPUT SENSOR ALLISON

1

**Workorder: V35632**

**In Date:** 10/13/2010

**Meter Reading:** 47,763.40

**Close Date:** 10/27/2010

**Problem?**

check out low power problem.

**Task performed:**

- C/O low power problem - Rechten Intl j
2. C/O motor eng msg; test drive; chk filters; order new filters & injectors; get truck to swap into; get gen for Stn91.
3. Change fuel filters; chk idle quality (rough); chk exh temps of cyl #1 low; test drive - eng msg; to be sent to vendor for repair.
4. Foam sys inop; t-shoot foam sys; foam tank fuel full; dlrvy valve operating; suspect eductor valve or % cntrl valve; rem hand cntrl & fnd locked up.
5. Assist w/foam sys - Sheedy.
6. Finished foam sys rep; tested foam sys - all ok.
7. Install spotlight; had to mnt on light bar; drilled hose thru roof; had to rem several \_\_\_\_\_ panels to route cable; fab mntng plate for dash cntrl. j

**Parts**

**Quantity**

33403FUEL FILTER LW

1

33411FILTER FUEL SERIES 40

1

H27SN12BULB

1

LGHGO-2020GOLIGHT MODEL 2020 SEARCH LIGHT

1

UMVS056511STRAP

2

UMVS111611STRAP

2

**Vendor?:** RECHTIEN INTL



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V35936**

In Date: 10/26/2010

Meter Reading: 47,970.00

Close Date: 11/12/2010

**Problem?**

mount hose and repair molding e91

**Task performed:**

Mntd hose & installed tools. j

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V36533**

In Date: 11/17/2010

Meter Reading: 48,370.20

Close Date: 11/30/2010

**Problem?**

starter stays engaged e91

**Task performed:**

(1) TRAVELED TO ST91 TO REPAIR ENGINE STARTER THAT IS LOCKED UP. CHECKED ALL CABLES AND CONNECTIONS, VOLTAGE OF BATTERIES AND LOAD TESTED THEM. ALL CHECKED OUT OK. REMOVED THE STARTER AND REPLACED WITH A NEW ONE. TESTED STARTING OF E91. ALL CHECKED OUT OK. J.W.

**Parts**

10461277USE 10461089

**Quantity**

1

**Workorder: V36598**

In Date: 11/22/2010

Meter Reading: 48,370.20

Close Date: 11/30/2010

**Problem?**

starter stays engaged e91 (on-call)

**Task performed:**

(1) TRAVELED TO ST91 TO CHECK OUT E91 STARTER. THE STARTER IS STAYING ENGAGED WHICH IE LOCKING IT UP. HAD UNIT SWAPPED OUT. J.W.

**Parts**

NO PARTS USED

**Quantity**



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10180687

### CONTENDER FIRE DEPARTMENT PUMPER NFPA

#### Workorder: V35972

In Date: 10/28/2010  
Close Date: 12/02/2010

Meter Reading: 47,970.00

#### Problem?

Hose bed cover is tearing on both sides at the rear and around several of the fasteners. E91

#### Task performed:

(1) TRAVELED TO ST91 TO CHECK OUT HOSE BED COVER ON E91. WILL HAVE NEW ONE MADE UP AT "B" INSPECTION. J.W.

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V36812

In Date: 12/02/2010  
Close Date: 12/02/2010

Meter Reading: 48,421.00

#### Problem?

parts only

#### Task performed:

parts only no labor

#### Parts

104610896386 NEW STARTER 37MT 1993928

#### Quantity

1

#### Workorder: V36646

In Date: 11/24/2010  
Close Date: 12/07/2010

Meter Reading: 48,421.00

#### Problem?

Starter making noise

#### Task performed:

1. Ck all connections-ck ok; volt drop in pos/neg cables-ck ok; ck volt/opn at starter solenoid-ck ok; turned eng & chk flywheel teeth-ck ok; fnd flywheel to crank shaft loose.  
2. Fnd lts out; R/R cab cl lt bulb; R/R (2) pump panel lts - ck ok.3. Rem all cables; rem starter; swapped & grd strd; reinstalled old starter; clnd bay. j

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V36719

In Date: 11/29/2010  
Close Date: 12/08/2010

Meter Reading: 48,421.00

#### Problem?

repair flywheel e 91 rechtien

#### Task performed:

Rep flyweel E91 - Rechtien j

#### Parts

NO PARTS USED

#### Quantity

Vendor?: RECHTIEN



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V36382**

In Date: 11/11/2010  
Close Date: 12/16/2010

Meter Reading: 48,252.90

**Problem?**

The "grip" is missing from the rear handle of the Hurst Cutters. This is a bicycle handlebar style grip. E91

**Task performed:**

Parts

Quantity

(1) TRAVELED TO ST91 TO CHECK OUT MISSING REAR HANDLE GRIP ON HURST CUTTER ON E91. REPAIRED CAB DOOR HANDLE THAT WAS FALLING OFF. J.W.

NO PARTS USED

**Workorder: V32777**

In Date: 06/09/2010  
Close Date: 12/22/2010

Meter Reading: 45,153.00

**Problem?**

WOULD LIKE TO HAVE WINDOWS TINTED. THIS WOULD HELP COOL DOWN INTERIOR OF CAB... e91

**Task performed:**

Parts

Quantity

NO PARTS USED

**Workorder: V33183**

In Date: 06/28/2010  
Close Date: 12/22/2010

Meter Reading: 45,486.00

**Problem?**

E91 HIT BAY DOOR. CLEARANCE LIGHTS AND LIGHT BAR DISPLACED...

**Task performed:**

Parts

Quantity

NO PARTS USED

**Workorder: V35113**

In Date: 09/22/2010  
Close Date: 12/22/2010

Meter Reading: 46,687.00

**Problem?**

vent fan needs repaired, also two lightboxes are not holding charges. these are located in st 91 bay.

**Task performed:**

Parts

Quantity

(1) GENERATOR NOT WORKING. REPLACED FUEL INJECTOR PUMP.  
(2) TWO LIGHT BOXES NOT WORKING. REPAIRED BOTH. WORKING OK. J.W.

NO PARTS USED



1/29/2024

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V35598**

In Date: 10/12/2010  
Close Date: 12/22/2010

Meter Reading: 47,763.40

**Problem?**

Replace injector pump on generator

**Task performed:**

| Parts                     | Quantity |
|---------------------------|----------|
| 16030-51010INJECTION PUMP | 1        |

**Workorder: V35967**

In Date: 10/27/2010  
Close Date: 12/22/2010

Meter Reading: 47,970.00

**Problem?**

E91 replace foam hand control knob

**Task performed:**

| Parts                        | Quantity |
|------------------------------|----------|
| 80753001240P METER VALVE WPB | 1        |

**Workorder: V36889**

In Date: 12/05/2010  
Close Date: 01/11/2011

Meter Reading: 48,421.00

**Problem?**

Bottom section mirror on driver side is missing. Wiring and mirror housing are in good condition. Mirror just needs to be replaced.  
E91

**Task performed:**

replcd bottom of mirror. j

| Parts         | Quantity |
|---------------|----------|
| NO PARTS USED |          |

**Workorder: V37068**

In Date: 12/10/2010  
Close Date: 01/11/2011

Meter Reading: 48,421.00

**Problem?**

repair seat E91 (outside agency-central auto)

**Task performed:**

Repair seat E91 - Central Auto j

| Parts         | Quantity |
|---------------|----------|
| NO PARTS USED |          |

**Vendor?:** CENTRAL AUTO





1/29/2024

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V37067**

**In Date:** 12/10/2010

**Meter Reading:** 48,421.00

**Close Date:** 01/13/2011

**Problem?**

repair hose bed cover E91 (outside agency-central auto)

**Task performed:**

Parts

Quantity

Repair hose bed cover E91 - Central Auto j

NO PARTS USED

**Vendor?:** CENTRAL AUTO

---



1/29/2024

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V36938**

**In Date:** 12/06/2010

**Meter Reading:** 48,549.00

**Close Date:** 01/14/2011

**Problem?**

C INSPECTION AND REPAIRS AS NEEDED E 91

**Task performed:**

Parts

Quantity



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10180687

### CONTENDER FIRE DEPARTMENT PUMPER NFPA

- (1) "C" INSPECTION AND NEEDED REPAIRS ON E91.
- (2) DIAGNOSE TANK FILL GAUGE. DIMLEY UT WHEN EMPTY, BRIGHT WHEN FULL.
- (3) FUEL LINE LEAKING. HAD MAKO HOSE FABRICATE A NEW HOSE. INSTALLED NEW HOSE, PRIMED FUEL SYSTEM.
- (4) COOLANT LOW. TEST FOR LEAKS. NO LEAK FOUND, TOPPED OFF COOLANT LEVEL.
- (5) PRESSURE TEST RADIATOR CAP, FAILED, INSTALLED NEW CAP.
- (6) ABS SENSOR LIGHT ON. REMOVED FRONT SENSOR, CLEAN, INSPECT, REINSTALLED. REMOVED REAR SENSOR, CLEAN, REINSTALLED. CLEARED CODES.
- (7) T- CASE SERVICE
- (8) AIR DRYER SERVICE.
- (9) CAB TILT RESERVOIR LOW ON FLUID. CHECKED FOR LEAKS AND TOPPED OFF LEVEL.
- (10) REMOVED DRIVER SEAT FOR REPAIRS. REINSTALLED THE DRIVER SEAT.
- (11) LADDER RACK HYDRALIC SYSTEM LEAK. CLEANED PUMP & ASSEMBLY, LINES & WHEEL WELL. FILLED RESERVOIR THAT WAS LOW ON FLUID. OPERATE SYSTEM, FASTEN LOOSE HOSE FITTING & REASSEMBLED.
- (12) LADDER POLE HOLDER LINES FRAYING. (HAZZARD) CHANGED PIN RING & LOOME PIN CABLE.
- (13) ASSIST MAC WITH TIGHTENING OF FRONT SPRING HANGER, BOTH SIDES. MADE UP SPECIAL WRENCH TO HOLD BOLT HEADS WHILE TIGHTENING.
- (14) TIGHTENED FRONT SPRING HANGERS LF/RT SIDES. BOLT AND NUT WAS LOOSE TO HAND TIGHT ONLY.
- (15) CHECKED GEAR BOX MOUNTING BOLTS FOR LOOSENESS. BOTH ARE TIGHT.
- (16) POWER STEERING FLUID LEAKING. SECURED LOOSE SUPPLY LINE FITTING. CLEAN AREA.
- (17) LADDER RACK PIVOTING SUPPORT BOLTS LOOSE. CLEANED, INSPECT & TORQUE BOLTS.
- (18) DIAGNOSE PUMP, VACCUME TEST FAILE. FOUND TANK TO PUMP VALVE LEAKING. DISSEMBLED VALVE, CLEANED PARTS, INSPECT & ORDERED PARTS. REASSEMBLED VALVE WITH NEW KIT. RELUBE PARTS, RESEMBBLED, CHECKED ALL VALVES, FILL TANK & TESTED WITH MIKE LEHAN. SYSTEM WORKING OK NOW.
- (19) REMOVED TANK TO PUMP CHECK VALVE, REASSEMBLED WITH NEW CHECK VALVE & CHECK VALVE ROCKER CRADLE BUSHING.
- (20) REMOVED A/C VENT COVER FOR REFABRICATING SUPPORT STRAP. CUT

|                                      |   |
|--------------------------------------|---|
| 0913912CHARGER 2000                  | 1 |
| 0915520120AUTO EJECT 20 AERO OTL3925 | 1 |
| 1817677C91FUEL FILTER SCREEN ASSY    | 1 |
| 19570 AMP RELAY                      | 1 |
| 33411FILTER FUEL SERIES 40           | 1 |
| 52545FLAPPER BEARING                 | 2 |
| 62981VALVE FLAPPER                   | 1 |
| 91-20WIPER BLADE 20 IN               | 2 |
| 921LIGHT BULB                        | 3 |
| K681-1WATEROUS KIT                   | 1 |
| PH713851799 FILTER OIL               | 1 |
| 9797 BULB                            | 1 |
| 60351STEPWELL LIGHT                  | 5 |
| 91398907 VALVE KIT 3 IN AKRON        | 1 |
| B-1100B-1100 CLAMP TOP LENS          | 1 |
| B-1102SPACER LENS                    | 1 |
| B-1103A1131 LENS (AMBER)             | 1 |
| 91368904 VALVE KIT 1 1/2 IN          | 1 |



1/29/2024

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

WELD, DRILLED, CLEAN, PAINTED NEW FABRICATED SUPPORT. INSTALLED VENT COVER, DRILLED, TAPPED NEW HOLD DOWN HOLES.

(21) A/C FILTER REMOVE SHIELD, BLOW OUT PRIMARY FITTING, CUT SECONDARY FILTER HOLE, INSTALLED.

(22) TAG LIGHT ASSEMBLY BROKEN. REMOVED, REWIRED AND REINSTALLED.

(23) GUIDE POLE LIGHT MISSING. INSTALLED NEW POLE LIGHT ASSEMBLY.

(24) LEFT SIDE SIGNAL 10-7. REMOVED LENS, CLEANED ASSEMBLY FOR CORROSION. INSTALLED NEW BULB.

(25) L-3 COMPARTMENT TOOL MOUNTS LOOSE. REMOVED TOOLS, TIGHTEN BACKING SPRING BOLT & REMOUNTED TOOLS.

(26) LEFT REAR MARKER 10-7. CLEANED LIGHT ASSEMBLY OF CORROSION, REPLACED BLOWN BULB.

(27) 110 VOLT CHARGER SYSTEM & AUTO EJECT INSTALLED.

(28) REPLACED SMOKE ALARM LOGO ON BLANK CARD.

(29) CLEARANCE LIGHTS 10-7. FOUND ASSEMBLIES MELTED FROM HIGH BULB INTENSITY. REPLACED 5 LIGHT ASSEMBLIES.

(30) HELP MAC INSTALL TTP VALVE.

(31) NO IGNITION POWER. DIAGNOSE START FAILURE. SECURE LOOSE IGNITION SWITCH WIRE.

(32) RADIATOR HOSE CLAMP DAMAGED. REMOVED & INSTALLED A NEW HOSE CLAMP TO ELIMINATE WEeping LEAK.

(33) STARTING SYSTEM PROBLEM IS INTERMITTENT. NOT CRANKING. CHECKED VOLTAGE DROP AT CONNECTORS.

(33) STILL NOT CRANKING, STARTED TRACING WIRES.

(33) STILL NOT CRANKING. REMOVED ALL CONNECTORS & PLUGS TO LIFT UP MAIN CENTER COLUMN BREAKER & RELAY BOARD. FOUND BURNT & LOOSE WIRES FOR STARTER CIRCUIT. REPAIRED WIRES, MOVED TO NEW STUD, REASSEMBLED.

(34) DIAGNOSE PUMP PROBLEM, FILL TANK, FOUND QUICK CONNECT FITTINGS ON VACCUM & PRESSURE GAUGES LEAKING, ALSO FITTING ON PRESSURE RELIEF AND ENGINE COOLER. REPLACED ALL FITTINGS. TANK TO PUMP VALVE ALSO LEAKING.

(35) FOAM SYSTEM CLEANED CONTROL VALVE, REASSEMBLED, RAN FOAM SYSTEM, OPERATING PROPERLY NOW. FLUSHED FOAM FROM PUMP SYSTEM.

(36) FINAL VACCUM TEST PASSED. 22.5 IN VAC, WITHIN 20 MIN LOST .5 INCHES VAC.



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

(37) REMOVED & INSTALLED NEW WIPER BLADES, TOPPED OFF H2O RESERVOIR WITH BUG SOLVENT MIXED IN.

(38) TAIL BOARD MARKER LIGHTS 10-7. REPLACED BLOWN BULB & CLEANED CORRODED CONTACTS.

(39) PERFORMED QA INSPECTION.

**Workorder: V37866**

**In Date:** 01/18/2011  
**Close Date:** 02/08/2011

**Meter Reading:** 48,884.90

**Problem?**

We are down to one box light on our engine, second one showing dim. We have 5 or 6 spares in need of repair. Thank you. E91

**Task performed:**

rep all SL-40 handlights. j

Parts

Quantity

NO PARTS USED

**Workorder: V38522**

**In Date:** 02/15/2011  
**Close Date:** 02/18/2011

**Meter Reading:** 49,546.60

**Problem?**

The MDT needs to be remounted on a pull out tray on the dashboard the current location is unsafe and obstructs the drivers view. Please repair ASAP. E 91

**Task performed:**

1. Weigh truck.
2. Fnd computer mnt obstructing captain's vision; rem computer/mnts; fab, drill & mnt computer; ck ok. j

Parts

Quantity

NO PARTS USED

**Workorder: V38184**

**In Date:** 01/31/2011  
**Close Date:** 03/08/2011

**Meter Reading:** 49,237.00

**Problem?**

Electrical Burning smell in the cab when the A/C is on. No problem when the A/C is off. Both Front and Rear A/C. e91

**Task performed:**

A/C inop; fnd condensor fans inop; fnd bad relay; replcd relays & tested. j

Parts

Quantity

NO PARTS USED



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V38290**

In Date: 02/04/2011

Meter Reading: 49,237.00

Close Date: 03/08/2011

**Problem?**

A/C unit smells like something is burning E91

**Task performed:**

**Parts**

**Quantity**

1. Ran A/C; fnd relay was melted; rem relay & tested sys.
  2. Condensor fan inop; replcd condensor fan & tested.
- j

3568MP06-3568M 16 IN FAN

1

**Workorder: V38444**

In Date: 02/11/2011

Meter Reading: 49,237.00

Close Date: 03/21/2011

**Problem?**

Box Light chargers do not charge. Used a meter to determine there is no power to the chargers. E91

**Task performed:**

**Parts**

**Quantity**

1. Fnd no power to lts; rem center doghouse cvr, panels head \_\_\_\_; ck for use at btry swtch - not there; raised cab & cnhk btry; no fuse; cld not find fuse; reassem.
  2. Assist w/t-shoot for box light chargers.
- j

NO PARTS USED

**Workorder: V38987**

In Date: 03/06/2011

Meter Reading: 50,083.00

Close Date: 03/21/2011

**Problem?**

Hose between tank and tank recirc valve leaking. hose is cracked and dried. Attempt to tighten by Tommy unsuccessful. E91

**Task performed:**

**Parts**

**Quantity**

1. Ck wtr leak; fnd hose/fitting at tank fill; rem hose/fitting; replc fittin/hose; filled tank; ck for leaks; ck ok.
  2. Assisted w/pipe fitting/hose replacement for tank fill; also drive to Mako for new fitting/hose.
- j

378088HOSE ASSMBLY

1

**Workorder: V38819**

In Date: 02/28/2011

Meter Reading: 50,000.30

Close Date: 03/24/2011

**Problem?**

Door for medical gear compartment in jumpseat area has broken weld. Door will not close properly. E91

**Task performed:**

**Parts**

**Quantity**

1. Rep box iab that was brkn; install screws to rep door.
  2. Air leak; rep all air leaks; will monitor air leaks.
- j

NO PARTS USED



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V38984**

In Date: 03/06/2011  
Close Date: 03/24/2011

Meter Reading: 50,083.00

**Problem?**

generator fuel pump constantly runs when battery is on, will ruin pump if not repaired. E91

**Task performed:**

Fuel leak; rep fuel leak at fuel pump. j

Parts

NO PARTS USED

Quantity

**Workorder: V39409**

In Date: 03/24/2011  
Close Date: 04/01/2011

Meter Reading: 50,400.00

**Problem?**

The diamond-plate equip cabinet door is again out of alignment and binding when opening and closing. E91

**Task performed:**

Travel to stn91; C/O door; replc door shock to a lighter one; isntall bolts on hinge & adj door. j

Parts

EAA-8350-30UGSS1783UQ STRUT-LIFT

1

Quantity

**Workorder: V38998**

In Date: 03/07/2011  
Close Date: 04/04/2011

Meter Reading: 50,083.00

**Problem?**

ON CALL BRAKES SPOUNGY E91

**Task performed:**

Road tested; brakes C/O ok. j

Parts

NO PARTS USED

Quantity

**Workorder: V38997**

In Date: 03/07/2011  
Close Date: 04/06/2011

Meter Reading: 50,083.00

**Problem?**

ON CALL FUEL LEAK E 91

**Task performed:**

Fnd fuel line rubbing on frame which made hole; rem section of bad hose & replcd. j

Parts

NO PARTS USED

Quantity



1/29/2024

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V39761**

In Date: 04/07/2011

Meter Reading: 50,871.40

Close Date: 04/14/2011

**Problem?**

REPAIR FLAT TIRE E 91

**Task performed:**

Parts

Quantity

Rep flat tire E91 - Boulevard j

NO PARTS USED

Vendor?: BOULEVARD

**Workorder: V39996**

In Date: 04/19/2011

Meter Reading: 51,123.20

Close Date: 04/20/2011

**Problem?**

left rear window crank broken, sta. 91.

**Task performed:**

Parts

Quantity

Travel to Stn91; C/O window crank knob off; R/R handle, reinstall knob & handle. j

NO PARTS USED

**Workorder: V39741**

In Date: 04/06/2011

Meter Reading: 50,788.50

Close Date: 05/06/2011

**Problem?**

light out below tail board, rr corner. E91

**Task performed:**

Parts

Quantity

Rep bad ground wire. j

NO PARTS USED

**Workorder: V40378**

In Date: 05/04/2011

Meter Reading: 51,487.50

Close Date: 06/03/2011

**Problem?**

Several bulbs need replacing. Sta 91.

**Task performed:**

Parts

Quantity

Replc all grnd lights. j

4020362171 GRO LAMP DOME 4 IN

5





1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V40627**

In Date: 05/16/2011      Meter Reading: 51,566.00  
Close Date: 06/03/2011

**Problem?**

E91's Box-Lite chargers are not charging. There appears to be no power to either one. Sta 91.

**Task performed:**

Rep SL-40 handlight that was not charging.      j

Parts

Quantity

NO PARTS USED

**Workorder: V40173**

In Date: 04/26/2011      Meter Reading: 51,269.60  
Close Date: 06/28/2011

**Problem?**

Failed dry vacuum test. Sta 91.

**Task performed:**

passed vacum test ak

Parts

Quantity

NO PARTS USED

**Workorder: V40920**

In Date: 05/27/2011      Meter Reading: 51,904.10  
Close Date: 06/28/2011

**Problem?**

TO MOVE SIREN SWITCHES FROM SIDE OF CONSOLE TO TOP.THE INSTALLATION OF MDT HAS MADE DIFFICULT TO ACCESS SWITCHES.. Sta 91.

**Task performed:**

will do at later time per DC ak

Parts

Quantity

|   |   |
|---|---|
| 9006XSSLHEADLAMP M2 HI                          | 1 |
| SWT54916V2D1000B-00000-000 SW ROCKER SPST NON-I | 2 |
| SWT5492744435 ACTUATOR-BLACK                    | 2 |

**Workorder: V41338**

In Date: 06/15/2011      Meter Reading: 52,241.50  
Close Date: 06/30/2011

**Problem?**

Right rear reverse bulb out. Sta 91.

**Task performed:**

1. Replc bulb in rear light.  
2. Chkd A/C & tested ok.      j

Parts

Quantity

NO PARTS USED



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V41638**

In Date: 06/27/2011

Meter Reading: 52,431.00

Close Date: 07/19/2011

**Problem?**

Small Orange Hazard Light on Driver side front corner does not blink. E 91

**Task performed:**

Parts

Quantity

REPAIRED HAZARD LIGHT ON DRIVERS SIDE AK

NO PARTS USED

**Workorder: V41721**

In Date: 06/30/2011

Meter Reading: 52,507.60

Close Date: 07/19/2011

**Problem?**

Can you please remove the wire basket from E91's old Hurst Pump and have it sent to Sta. 91 to be put on our current unit? Sta 9

**Task performed:**

Parts

Quantity

REINSTALLED WIRE BASKE ON HURST UNIT

NO PARTS USED

AIR LEAK CHECK FOR AIR LEAKS FOUND NONE AT THIS TIME AK

**Workorder: V41773**

In Date: 07/03/2011

Meter Reading: 52,276.30

Close Date: 07/19/2011

**Problem?**

The Master Stream Device leaks from the connection to either the base or truck pipe. Poss. a gasket problem. E91

**Task performed:**

Parts

Quantity

REMOVED DECK GUN FLANGE AND GASKET REINSTALLED AND TESTED AK

NO PARTS USED

**Workorder: V41774**

In Date: 07/03/2011

Meter Reading: 52,276.30

Close Date: 07/19/2011

**Problem?**

5" intake valve from R side of E91 leaking at the control valve when the pump is running, and needs to be repaired or replaced. Al needs a new main gasket for treaded connection. On Sta. workbench.

**Task performed:**

Parts

Quantity

PICK UP UNIT AND WILL SEND OUT FOR REPAIR AK

NO PARTS USED



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V41668**

In Date: 06/28/2011

Meter Reading: 52,507.60

Close Date: 07/26/2011

**Problem?**

Rear tires are worn, Sta 91.

**Task performed:**

Parts

Quantity

Rear tires are worn Stn91 - Tiresoles j

NO PARTS USED

Vendor?: TIRESOLE

**Workorder: V42122**

In Date: 07/19/2011

Meter Reading: 52,915.00

Close Date: 08/08/2011

**Problem?**

UNKNOWN ASSET # POWERPLANT HURST STARTED RAN AND STOPPED WOULD NOT RESTART. HAS SPARK AND FUEL TO CARB, Sta 91.

**Task performed:**

Parts

Quantity

unit sent to shop

NO PARTS USED

**Workorder: V42683**

In Date: 08/09/2011

Meter Reading: 53,112.00

Close Date: 08/16/2011

**Problem?**

Hurst power unit leaking.

**Task performed:**

Parts

Quantity

cleaned bottom of pump installed new seal and pan

180R014HURST HYD. FLUID GAL

2

filled with fluid started and checked functions 5200 psi

354R019OIL PAN

1

CT8415010541SEAL

1

**Workorder: V42108**

In Date: 07/18/2011

Meter Reading: 52,915.00

Close Date: 08/25/2011

**Problem?**

AC in cab working intermittently between blowing warm and cold air. E91

**Task performed:**

Parts

Quantity

replaced condenser fan and tested

3568MP06-3568M 16 IN FAN

2



1/29/2024

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

### Workorder: V42699

In Date: 08/10/2011

Meter Reading: 53,112.00

Close Date: 08/25/2011

#### Problem?

OIL LEAK E 91

#### Task performed:

cleaned oil pan and installed new filter

#### Parts

PH713851799 FILTER OIL

#### Quantity

1

repaired window track that was falling out

### Workorder: V43402

In Date: 09/03/2011

Meter Reading: 53,677.00

Close Date: 09/07/2011

#### Problem?

capt. door window will roll down but not up. appears to be off track E 91

#### Task performed:

remove door panel found glass loose on regulator

glass mount missing a bolt

track out of adjustment

secured all loose items and adjusted track

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V41923

In Date: 07/11/2011

Meter Reading: 52,630.90

Close Date: 09/12/2011

#### Problem?

power pack is broken off its rubber mounts. Placed in bay of 91.

#### Task performed:

removed cage from hurst unit and installed all new motor mounts

#### Parts

HR149460107MOUNT VIBRATION (NEWER POWER UNITS

#### Quantity

4



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V43473**

**In Date:** 09/06/2011

**Meter Reading:** 53,824.00

**Close Date:** 09/15/2011

**Problem?**

**B INSPECTION AND REPAIRS AS NEEDED E 91**

**Task performed:**

- B-Inspection; oil filter changed in field approx 2-3 weeks prior to PM as per T.Torchia.
- 2. Bumper jump line drain leaking; rem drain valve, diss, cln, lube & reassem; charge line - no leaks present.
- 3. Oil pan gskt leak; retorque bolts & cln area.
- 4. Fuel leak; press test sys; fnd injector supply line gskt leaking; rem line; rem gskt/install new gskt; retest - no leaks fnd.
- 5. Pole marker light 10-7; rewire & fused pole marker light; secure wire & wire lines.
- 6. Trans dipstick tube support brkn; install new support clamp.
- 7. Taglight 10-7; replc blown b ulb.
- 8. L.S pump panel light 10-7; lighting asy crystalized; replc asy & bulb.
- 9. Cab lock leaking; lift cab; rem cab lock mechanism; install new cab lock asy along w/new o-rings; operate sys; chk for leaks.
- 10. Officer window opn complaint; cld not find adj fault w/window function; spoke to office at stn "A" shift; advisd tech fixed unit at stn.
- 11. Box light not charging; rewire to btry switch; positive side mnt; handlight charging stn.
- 12. ABS light stays on; chk & fnd no stored codes; rem ring sensor; cln sensors & secur ports; reinstall & test drive; light stayed off..
- 13. Quality check truck - Hines. j

**Vendor?: \***

**Parts**

**Quantity**

|                                   |   |
|-----------------------------------|---|
| 1812348C1FUEL LINE SLEEVE INT     | 2 |
| 1817677C91FUEL FILTER SCREEN ASSY | 1 |
| 33403FUEL FILTER LW               | 1 |
| 33411FILTER FUEL SERIES 40        | 1 |
| 46748AIR FILTER PIERCE            | 1 |
| 53-4470LATCH CAB HYDRAULIC WPB    | 1 |
| 906LIGHT BULB 12CP                | 2 |
| 60351STEPWELL LIGHT               | 1 |

**Workorder: V42743**

**In Date:** 08/11/2011

**Meter Reading:** 53,287.40

**Close Date:** 09/19/2011

**Problem?**

**Rear Driver side peremeter light under tailboard is out. Sta 91.**

**Task performed:**

repaired ground wire

**Parts**

**Quantity**

NO PARTS USED



1/29/2024

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

### Workorder: V43136

In Date: 08/29/2011

Meter Reading: 53,613.90

Close Date: 09/19/2011

#### Problem?

Light on pump panel is out, tag light out. Sta 91.

#### Task performed:

repaired connection for pump panel lights

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V43643

In Date: 09/13/2011

Meter Reading: 53,847.40

Close Date: 10/03/2011

#### Problem?

(L) SIDE PUMP PANEL LIGHTING OUT , TAG LIGHT OUT, REAR PRIMETER LIGHT OUT, OFFICER SIDE NEEDS A HYDRA AND SPANNER WRENCH MOUNT BY THE PUMP PANEL.....

#### Task performed:

repaired all lights taht were out

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V43771

In Date: 09/19/2011

Meter Reading: 53,913.60

Close Date: 10/07/2011

#### Problem?

No. 3 discharge guage not working, high pressure lines on spreaders are cracked but not leaking, peremeter light under tailboard on driver side is out, light out on pump panel

#### Task performed:

repalced gauges and tested

replaced all hoses on hurst units

#### Parts

1452878-00012.5 IN 30-0-400 PSI

4020362171 GRO LAMP DOME 4 IN

#### Quantity

2

3

### Workorder: V43866

In Date: 09/23/2011

Meter Reading: 53,985.00

Close Date: 10/07/2011

#### Problem?

Need hydraulic fluid for hurst equipment. Sta 91.

#### Task performed:

repalce hurst hoses and tested

#### Parts

353R023HURST HOSE W/O SWIVEL

353R222ML28 SPREADER HOSE

#### Quantity

2

2



1/29/2024

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V44371**

In Date: 10/13/2011

Meter Reading:

Close Date: 10/28/2011

**Problem?**

Need spreader mount and hydraulic hose basket mounted on E91.

**Task performed:**

Parts

Quantity

Mntd hose bskt & rep hose clamp. j

NO PARTS USED

**Workorder: V44540**

In Date: 10/20/2011

Meter Reading: 54,443.00

Close Date: 10/28/2011

**Problem?**

Hydraulic fluid is leaking from sight glass on power unit. Sta 91.

**Task performed:**

Parts

Quantity

Installed new sight glass & ran unit. j

NO PARTS USED

**Workorder: V44572**

In Date: 10/20/2011

Meter Reading:

Close Date: 10/28/2011

**Problem?**

need circle D light for E 91

**Task performed:**

Parts

Quantity

1. Replc light & tested.
  2. A/C inop; rep connection on relay for condensor fan.
- j

NO PARTS USED

**Workorder: V44568**

In Date: 10/20/2011

Meter Reading:

Close Date: 11/07/2011

**Problem?**

Hurst hose burst. replaced bt Tommy 10/20

**Task performed:**

Parts

Quantity

DROPPED OFF NEW HOSE AND REPAIRED HURST UNIT

353R091USE 353R403 HURST HOSE 16 GREEN

1



1/29/2024

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V44614**

In Date: 10/23/2011

Meter Reading:

Close Date: 11/07/2011

**Problem?**

left rear spotlight not working. gas fan throttle not working E 91

**Task performed:**

Parts

Quantity

1. Rep fan throttle & tested.

NO PARTS USED

2. Rep rear spotlight. j

**Workorder: V44903**

In Date: 11/02/2011

Meter Reading: 54,669.90

Close Date: 11/08/2011

**Problem?**

Coolant leak. sta 91.

**Task performed:**

Parts

Quantity

Raised cab; fnd coolant line frm radiator to turbo brkn & spraying coolant; rem bad hose; replcd w/new; filled w/coolant; chk ok. j

ALA00350-50 EXTENDED LIFE COOLANT GAL

2

**Workorder: V44926**

In Date: 11/03/2011

Meter Reading: 54,669.90

Close Date: 11/09/2011

**Problem?**

coolant leak. Sta 91.

**Task performed:**

Parts

Quantity

Coolant leak & buzzer going off; OOS EGR leaking & hoses. j

NO PARTS USED

**Workorder: V44746**

In Date: 10/28/2011

Meter Reading:

Close Date: 11/14/2011

**Problem?**

Female side of seat belt broke in drivers seat. Sta 91.

**Task performed:**

Parts

Quantity

1. Rep seat belt; swapped w/one in rear.

NO PARTS USED

2. Rep rear door latch that was hard to open. j





1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V44834**

In Date: 11/01/2011

Meter Reading:

Close Date: 11/14/2011

**Problem?**

Water leaking from ceiling liner behind driver side visor. sta 91.

**Task performed:**

**Parts**

**Quantity**

- 1. Resealed roof.
- 2. Rep grnd lights that were out. j

NO PARTS USED

**Workorder: V44959**

In Date: 11/04/2011

Meter Reading: 54,728.00

Close Date: 11/28/2011

**Problem?**

B inspection.

**Task performed:**

**Parts**

**Quantity**

- b service x 2 days
- replace cap lock on left side leaking
- replace wiper blades and fluids
- tighten up clamp on hoses for leaks
- tightne belts on oil pan for some leaks
- replace new tail board light on back

15200RRED MARKER LIGHT RECTANGULAR 1  
 33403FUEL FILTER LW 1  
 33411FILTER FUEL SERIES 40 1  
 53-4470LATCH CAB HYDRAULIC WPB 1  
 91-20WIPER BLADE 20 IN 2  
 PH713851799 FILTER OIL 1

**Workorder: V45444**

In Date: 11/28/2011

Meter Reading: 54,841.50

Close Date: 12/05/2011

**Problem?**

ON CALL COOLANT E 91

**Task performed:**

**Parts**

**Quantity**

- PRESSURE TESTED FOUND HOSE CLAMP LEAKING - REPAIRED.

NO PARTS USED

**Workorder: V45249**

In Date: 11/17/2011

Meter Reading: 54,669.90

Close Date: 12/16/2011

**Problem?**

Make shelf and install lock in medical compartment, Sta 91.

**Task performed:**

**Parts**

**Quantity**

- INSTALLED SHELF AND LOCK IN R-4.

101305009SS0001 CPI SHELF BRACKET ONE HOLE 2005 | 5



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V45923**

In Date: 12/18/2011

Meter Reading:

Close Date: 01/03/2012

**Problem?**

Peremeter light under drivers door is out. Sta 91

**Task performed:**

repaired bad ground wire in light

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V45820**

In Date: 12/12/2011

Meter Reading: 55,129.30

Close Date: 01/13/2012

**Problem?**

Orange light on front bumper corner marker broken. Light bulb is still good. Sta 91

**Task performed:**

REPAIRED LIGHT ON POLE.

**Parts**

26390YMARKER LIGHT AMBER WPB

B-1103A1131 LENS (AMBER)

**Quantity**

1

2

**Workorder: V46756**

In Date: 01/22/2012

Meter Reading: 55,819.70

Close Date: 02/03/2012

**Problem?**

rear warning light, officers side, is out, Sta 91

**Task performed:**

REPAIRED BAD CONNECTION ON LIGHT

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V47001**

In Date: 02/01/2012

Meter Reading: 55,944.10

Close Date: 02/03/2012

**Problem?**

Just as a reminder, we need a bulb for RR beacon. Also we replaced head light and no longer have any of back ups in storage.

Thanks. Sta 91

**Task performed:**

1. REPAIRED GROUND WIRE ON REAR LIGHT.
2. AIR LEAK FOUND LEAK AND REPAIRED.

**Parts**

H4651USE CV TYPE SEALED BEAM

H4656USE CV TYPE HEAD LIGHT

**Quantity**

2

2



1/29/2024

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

### Workorder: V46918

In Date: 01/30/2012

Meter Reading: 55,882.90

Close Date: 02/10/2012

#### Problem?

No siren. sta 91

#### Task performed:

REPLACED SIREN SPEAKER.

#### Parts

SD-210RSIREN DRIVER

#### Quantity

1

### Workorder: V47093

In Date: 02/05/2012

Meter Reading: 55,999.40

Close Date: 02/10/2012

#### Problem?

noticed ABS light illuminated on the dash, wasn't sure if it should be on or not. Sta 91

#### Task performed:

ROAD TESTED FOUND NO LIGHT ON AND NO ABS CODES.

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V47683

In Date: 03/01/2012

Meter Reading: 56,583.40

Close Date: 03/13/2012

#### Problem?

oil leak. sta 91

#### Task performed:

1. CLEANED OIL OFF ENGINE AND CHECKED FOR LEAK.
2. REINSTALLED TOOLSIN L-1.

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V48164

In Date: 03/24/2012

Meter Reading: 57,074.20

Close Date: 04/02/2012

#### Problem?

map light out

#### Task performed:

REPAIRED MAP LIGHT THAT HAD BAD CONNECTION

#### Parts

NO PARTS USED

#### Quantity



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V48078**

In Date: 03/20/2012      Meter Reading: 56,828.00

Close Date: 04/16/2012

**Problem?**

Digital milage display..."gorked" can't tell the milage reading e 91

**Task performed:**

FOUND NO PROBLEM WITH DASH GAUGE.

Parts

NO PARTS USED

Quantity

**Workorder: V48646**

In Date: 04/13/2012      Meter Reading: 57,384.20

Close Date: 04/20/2012

**Problem?**

failed vac test e 91

**Task performed:**

VACUUM TESTED, PASSED.

Parts

NO PARTS USED

Quantity

**Workorder: V48942**

In Date: 04/27/2012      Meter Reading: 57,597.00

Close Date: 05/07/2012

**Problem?**

BATTERY SHORTED E91

**Task performed:**

1. INSTALLED NEW BATTERIES.
2. WHILE REPLACING BATTERIES ONE CONDENSOR FAN NOT WORKING TROUBLESHOOT WIRING FOUND BAD CONNECTOR REPAIRED.

Parts

BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER BATTERY  
HP-31D BATTERY 950CCA HP-31D

3  
3

Quantity

**Workorder: V49179**

In Date: 05/08/2012      Meter Reading: 57,929.90

Close Date: 05/08/2012

**Problem?**

engine noise

**Task performed:**

NOISE FROM ENGINE COMPARTMENT/ALTERNATOR STARTING TO SEIZE/ TRAVEL BACK TO SHOP FOR ALTERNATOR TRIED TO INSTALL WAS WRONG ONE TRAVEL BACK TO SHOP FOUND CORRECT ALTERNATOR INSTALLED ALTERNATOR ALSO HAD TO REPAIR BRACKET MOUNTING STUD WAS STRIPPED TESTED OK.

Parts

A1-607C630 NEW A1-608 290AMP ALT. NIEHOFF

1

Quantity



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10180687

### CONTENDER FIRE DEPARTMENT PUMPER NFPA

#### Workorder: V48678

In Date: 04/14/2012

Meter Reading: 57,400.00

Close Date: 05/11/2012

#### Problem?

pump shift switch has air leak. pump did not throw back into drivetrain until repeated attempts of putting it back into pump.  
also,odometer not reading properly.

#### Task performed:

FOUND NO AIR LEAK - TESTED SYSTEM AND TESTED OK.

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V50032

In Date: 06/11/2012

Meter Reading: 58,616.10

Close Date: 06/13/2012

#### Problem?

no cab a/c

#### Task performed:

TRAVEL TO STATION 91 CHECK E91 A/C BOTH BELTS BROKEN NEED COMPRESSOR TALKED TO CREW SAID THEY WILL BRING TRUCK TO SHOP MONDAY.

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V50257

In Date: 06/20/2012

Meter Reading: 99,999.00

Close Date: 06/25/2012

#### Problem?

rear top Emergency spinning light is out on OIC side. E91

#### Task performed:

REPLACE R/R ROTATER LIGHT BULB.

#### Parts

795 BULB

#### Quantity

2

#### Workorder: V50258

In Date: 06/20/2012

Meter Reading: 99,999.00

Close Date: 06/25/2012

#### Problem?

cap on top of front OIC side turn signal pole is missing. AMBER CLEARANCE LIGHT?? E91

#### Task performed:

INSTALLED CAP.

#### Parts

1319AMARKER LAMP PIERCE LW  
B-1103A1131 LENS (AMBER)

#### Quantity

1

1



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10180687

### CONTENDER FIRE DEPARTMENT PUMPER NFPA

#### Workorder: V50005

In Date: 06/09/2012  
Close Date: 06/26/2012

Meter Reading: 58,616.10

#### Problem?

Driver seat air cushion system broken. Wont hold air, immediatly sinks to bottom position making seat low (for shorter persons) E91

#### Task performed:

REPLACE AIR VALVE FOR SEAT AND ORDER AIR BAG.

#### Parts

B-1103A1131 LENS (AMBER)

#### Quantity

1

#### Workorder: V50006

In Date: 06/09/2012  
Close Date: 06/26/2012

Meter Reading: 58,616.10

#### Problem?

one of the four front top running lights missing orange cap E91

#### Task performed:

1. DIAGNOSE A/C COMPRESSOR - REPLACE A/C COMPRESSOR, BELTS AND DRIER. EVACUATE AND RECHARGE A/C SYSTEM.
2. REPLACE MARKER LIGHT COVER.

#### Parts

1319AMARKER LAMP PIERCE LW

16-3007TAPE 8990

589603-3758 COMPRESSOR QUNIT

74R258607-2613A RED DOT DRIER 7127

9680BELT

#### Quantity

1

1

1

1

2

#### Workorder: V50340

In Date: 06/23/2012  
Close Date: 06/28/2012

Meter Reading: 59,034.00

#### Problem?

a/c not blowing cold air R91

#### Task performed:

1. TRAVEL TO ST 93 CHECK A/C FOUND BAD HIGH PRESSURE HOSE REMOVE TAKE TO MAKO TO BE MADE TRAVEL TO SHOP FOR TOOLS.
2. TRAVEL BACK TO 93 INSTALL HOSE CONNECT AND RECHARGE A/C.

#### Parts

411572HOSE & FITTING ASSY

#### Quantity

1

#### Workorder: V50523

In Date: 07/02/2012  
Close Date: 07/13/2012

Meter Reading: 59,034.00

#### Problem?

E 91 top light bar possibly has short,as it will temporarily turn off when traveling over bumps.

#### Task performed:

REPAIRED GROUND WIRE ON TOP OF RELAY BOARD.

#### Parts

NO PARTS USED

#### Quantity



1/29/2024

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V50136**

In Date: 06/14/2012

Meter Reading: 99,999.00

Close Date: 07/25/2012

**Problem?**

odometer is not working, it is digital and flashing. No numbers are shown.

**Task performed:**

REPLACED UNIT AND TESTED.

Parts

Quantity

60-9115SPEEDO GAUGE

1

**Workorder: V50318**

In Date: 06/22/2012

Meter Reading: 99,999.00

Close Date: 07/25/2012

**Problem?**

emergency light out on left side of front tailboard

**Task performed:**

REPAIRED EMERGENCY LIGHT AND TESTED.

Parts

Quantity

H35TL12H35TL12 BULB

2

H6054USE CV TYPE SEALED BEAM

2

**Workorder: V50826**

In Date: 07/13/2012

Meter Reading: 59,052.00

Close Date: 08/03/2012

**Problem?**

RT rear 'under scene light' is out E91

**Task performed:**

REPAIRED GROUND ON SCENE LIGHTS.

Parts

Quantity

1305672AIR BAG SEAT

1



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10180687

### CONTENDER FIRE DEPARTMENT PUMPER NFPA

**Workorder: V51111**

**In Date:** 07/25/2012

**Meter Reading:** 59,098.50

**Close Date:** 08/07/2012

**Problem?**

C INSPECTION E 91

**Task performed:**

1. C SERVICE; C SERVICE; PUMP TEST, VAC PASS.
2. BATTERY REPLACEMENT AND PARTS FOR REPAIRS AT PARTS ROOM.
3. TIGHTEN ALL BOLTS TO SPRING MOUNT TO FRAME FRONT AND REAR CHECK AND REPAIR.
4. SERVICE DRYER SYSTEM, REMOVE FROM FRAME, CLEAN OUT, REBUILD ON BENCH REINSTALL ON TRUCK.
5. SERVICE P/S UNIT FLUID AND FILTER AND GASKET.
6. CALL PIERCE ABOUT SPEEDO PULSH SET UP TO RESET NUMBER ON SPEEDO AND RESET SPEEDO.
7. COOLANT SYSTEM CUT TO FIT HOSES TO UPPER THERMOSTAT, INSTALLED NEW THERMOSTAT AND GASKET, OPEN FLOWING RECHECK FOR LEAKS, HEAD GASKET AND BACK OF MOTOR COOLANT LEAKING AND OIL LEAK HEAD.
8. AIR TURBO HOSE WORK, AIR CHARGER HOSE TO MOTOR FROM INTERCOOLER. CUT TO FIT HOSE TO FIT MOTOR AND NOT HIT CAB OF TRUCK. INSTALLED AIR FILTER.

| Parts   | Quantity |
|---|----------|
| 05-16062-005HOSE - LOWER RAD.                     | 1        |
| 05-17223-000CAP RADIATOR 10 LB                    | 1        |
| 1484594-0010SEAT BELT ASSY.                       | 1        |
| 1619296P/S RESERVOIR SEAL                         | 1        |
| 1691397-0010SEAT BELT                             | 1        |
| 1817677C91FUEL FILTER SCREEN ASSY                 | 1        |
| 1830256C93THERMOSTAT INT.                         | 1        |
| 29526898 29548988 TRANS FILTER ALLISON            | 1        |
| 33403FUEL FILTER LW                               | 1        |
| 33411FILTER FUEL SERIES 40                        | 1        |
| 40-6313BUSHING CAB TILT PIERCE                    | 2        |
| 40-6317PINS CAB TILT PIERCE                       | 2        |
| 4020362171 GRO LAMP DOME 4 IN                     | 1        |
| 46748AIR FILTER PIERCE                            | 1        |
| 5008414CARTRIDGE DC100                            | 1        |
| 6805010082HOSE TURBO                              | 2        |
| 91-20WIPER BLADE 20 IN                            | 2        |
| BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY | 10       |
| FG83284DFG/HF6238 PS/HDY FILTER                   | 1        |
| FGQ59267COVER GASKET STEERING                     | 1        |
| HP-31DBATTERY 950CCA HP-31D                       | 10       |
| P-C-2688HOSE TRAY R/H SUTPHEN                     | 1        |
| PH713851799 FILTER OIL                            | 1        |
| R950013TURBO CUT OFF VLV KIT                      | 1        |
| R950014PURGE VALVE WABCO AIR DRYER                | 1        |
| TRW-L24VC0109DRAG LINK BOOT                       | 2        |

**Workorder: V51318**

**In Date:** 08/02/2012

**Meter Reading:** 59,098.50

**Close Date:** 09/13/2012

**Problem?**

REPAIR COOLANT LEAK POSS HEAD GASKET

**Task performed:**

REPAIR COOLANT LEAK POSS HEAD GASKET.

| Parts         | Quantity |
|---------------|----------|
| NO PARTS USED |          |

**Vendor?:** RECHTIEN INTERNATION





1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V50902**

In Date: 07/17/2012

Meter Reading:

Close Date: 09/14/2012

**Problem?**

Newly replaced speedometer/odometer not functioning. E91

**Task performed:**

Parts

Quantity

RECALABRATED GAUGE AND TESTED.

NO PARTS USED

**Workorder: V50942**

In Date: 07/18/2012

Meter Reading:

Close Date: 09/14/2012

**Problem?**

The spot light on light bar is out. Also light below tail board (ground clearance) is out. E91

**Task performed:**

Parts

Quantity

INSTALLED NEW GROUND WIRE IN P.C BOARD AND TESTED LIGHT.

H9SPOT LIGHT BULB

1



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V52212**

**In Date:** 09/06/2012

**Meter Reading:** 59,098.50

**Close Date:** 09/27/2012

**Problem?**

**NORMAL REPAIRS FROM C INSPECTION**

**Task performed:**

1. REPAIR STEP LIGHTS INSTALLED HOSE BED COVER AND NEW SNAP ON RAILS REPLACE SINK ON GROUND LADDER.
2. FILL PUMP RUN PUMP AND CHCK SHIFT LEVEL AND MANUEL OVER RIDE FOR OPP OK DRIVE TRUCK FOR BRACKET NOISE IN FRT.
3. FOUND NOISE IN FRT END CAB LIFT RUNS VERY LOOSE, REPAIR PINS SKIM FOR PLAY INSTALL NEW WASHER.
4. Q.A
- 5.ASSIST CARL R W/ SHIMMING SHAFT ON CAB LIFTS.
6. PICK UP PARTS ORDER INSTALLED NEW GROUND LIGHT, TOP OF FLUIDS AFTER REPAIR.
7. INSTALLED TIRE ROD AND BOOTS ON BOTH ENDS OF TIE RODS.
8. CAB LEFT BUSHING PIN AND BUSHING IN FRT MONT, PULL OUT OLD BUSHING PUT IN NEW BUSHING.
9. ASSIST REED W/ REMOVAL AND INSTALL OF CAB PIVOT PINS.
10. WORK ON CAB PIVOT FINISH INSTALL GREASE INSTALLED NEW NUT ZURTS IN GRILL.
11. WORK ON REPAIRS ON LIST REAR SEAT FRT SEAT BELTS SPAT LIGHT ON TOP LIGHT RAN, HOSE BED COVER ECT.
12. REPAIR SHAFTER TO PUMP, HARD, REMOVE AND LUBE REINSTALLED WORK OK.
13. START ON BRAKE WORK, REMOVE TIRES AND BRAKE DRUM AND HARDWARE.
14. CHK OUT A/C FILTER IN CENTER A/C UNIT MAKE NEW GRATE FOR NEW FILTER TO FIT RIGHT.
15. REMOVE HOSE BED COVER TO HAVE REPAIR DONE AND NEW SNAP PIN TO MOUNT ON TRUCK.
16. INSTALL ARE NEW BRAKES SPRING KITS AND DRUM REINSTALL ALL TIRE AND WHEELS TORQUE.
17. CHK AND REPLACE LEFT REAR ARE HEAD LIGHT OUT, WIRES BRAKES OFF SWITCHS REPLACE W/ NEW ONE.

**Parts**

**Quantity**

|   |   |
|---|---|
| 3576REAR BRAKE DRUMS                            | 2 |
| 4020362171 GRO LAMP DOME 4 IN                   | 1 |
| 65166BDRUM                                      | 2 |
| 66-04928080-0000-13 LIGHT DOME RED/CLR LENS WPB | 2 |
| AB4515Q685REXP4515Q BRAKE SHOES                 | 4 |
| E-2769MKT4515QB BRAKE KIT                       | 2 |
| H9SPOT LIGHT BULB                               | 1 |
| KSR4034715QPSHOE KIT                            | 2 |
| TRW-L24VC0109DRAG LINK BOOT                     | 1 |



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V52663**

In Date: 09/26/2012

Meter Reading:

Close Date: 10/16/2012

**Problem?**

E91 CHECK ENG LIGHT CAME ON AND GAS PEDAL WAS UNRESPONSIVE.

**Task performed:**

Parts

Quantity

TRACED OUT PROBLEM FOUND FOOT THROTTLE NO GOOD REMOVED AND REPLACED. REPAIRED A/C THAT WAS NOT BLOWING ANY AIR - REPAIRED CONNECTION.

WIL-131973TPS SENSOR

1

**Workorder: V53110**

In Date: 10/16/2012

Meter Reading:

Close Date: 11/09/2012

**Problem?**

The K12 saw on E91 is running rough. Asset not found 10180673. Please repair as soon as possible or replace as this unit is very old and is consistently down.

**Task performed:**

Parts

Quantity

CLEANED CARB AND REPLACED FUEL.

NO PARTS USED

**Workorder: V53269**

In Date: 10/23/2012

Meter Reading:

Close Date: 11/16/2012

**Problem?**

ABS warning light occasionally on for a few miles at time. Both temp gauges(pump panel & cab) reading around 100 degrees, not accurate. Continuing loud clunking inside cab. Finally rear driver ground light out.

**Task performed:**

Parts

Quantity

ROAD TESTED UNIT AND TESTED OK.

NO PARTS USED

**Workorder: V53361**

In Date: 10/29/2012

Meter Reading:

Close Date: 11/16/2012

**Problem?**

Onboard generator's sylenoid sticking when not running and truck's battery switch is on. e91

**Task performed:**

Parts

Quantity

RAN GENERATOR AND CLEANED SOLENOID AND TESTED UNIT.

NO PARTS USED



1/29/2024

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V53985**

In Date: 11/26/2012

Meter Reading: 60,370.00

Close Date: 11/28/2012

**Problem?**

ON CALL FUEL LEAK E 91

**Task performed:**

Parts

Quantity

OPERATE COMPLAIN ENGINE MISSING RETURN LINE  
LEAKING NO PART ON TRUCK UNIT CAPTIAN SWAPE  
INTO BATTERIES SPARE.

NO PARTS USED

**Workorder: V53691**

In Date: 11/11/2012

Meter Reading:

Close Date: 11/30/2012

**Problem?**

driver's side rear groundlight out. E91

**Task performed:**

Parts

Quantity

REWIRED GROUND LIGHT AND REPAIRED ALL THAT  
WERE OUT.

NO PARTS USED

**Workorder: V53840**

In Date: 11/17/2012

Meter Reading:

Close Date: 12/14/2012

**Problem?**

one pump panel light is out E91

**Task performed:**

Parts

Quantity

NO LIGHTS OUT ON PUMP PANEL.

NO PARTS USED

**Workorder: V53841**

In Date: 11/17/2012

Meter Reading:

Close Date: 12/14/2012

**Problem?**

2 drains have missing labels on the Officer's side of the pump panel E91

**Task performed:**

Parts

Quantity

REINSTALLED LABELS ON PUMP PANEL.

NO PARTS USED



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V53842**

In Date: 11/17/2012

Meter Reading:

Close Date: 12/14/2012

**Problem?**

need a quart of hydraulic fluid for hurst tool E91

**Task performed:**

DROPPED OFF OIL.

Parts

NO PARTS USED

Quantity

**Workorder: V53865**

In Date: 11/19/2012

Meter Reading:

Close Date: 12/14/2012

**Problem?**

Driver's side back-up light not working. E91

**Task performed:**

REPAIRED SHORTED WIRES.

Parts

NO PARTS USED

Quantity

**Workorder: V54182**

In Date: 12/04/2012

Meter Reading: 60,370.00

Close Date: 12/17/2012

**Problem?**

A INSPECTION FUEL LEAK/ CHECK A/C E91

**Task performed:**

- CHECK OUT TRUCK BURNING SMOKE LINE FOUND ON CYLINDER NOT FIRING, CHECK W/ LAPTOP FOUND CLINDER 1 NOT WORKING R&R COVER TEST INJECTOR, PO CONSOLE ON CYLINDER ORDER INJECTOR FOR ENGINE.
- CHECK OUT SPOT LIGHT, FOUND BAD LIGHT, TOMMY HAD NEW LIGHT FOR TRUCK INSTALLED NEW LIGHT ON TOP OF TRUCK.
- INSTALLED INJECTOR, REINSTALLED ALL PARTS.
- A SERVICE.
- R&R A/C COMPRESSOR LEAK IN SITEGLASS ON SIDE OF COMPRESSOR. REMOVED AND REPAIRED LEAK REINSTALLED PUMP POWN AND RECHARGE SYSTEM.
- REMOVE LIGHTT CORD TO SEE WHAT IS WRONG W/ IT TOMMY GAVE ME LIGHT TO REPAIR FOR E-91 ORDER PART, BY E-MAIL TO PARTS, HOLD ON PARTS.

Parts

- 2593597C91INJECTOR
- 8201L17-3428 ESTER OIL E7
- H9SPOT LIGHT BULB

Quantity

- 1
- 1
- 1



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10180687

### CONTENDER FIRE DEPARTMENT PUMPER NFPA

**Workorder: V53866**

In Date: 11/19/2012  
Close Date: 12/26/2012

Meter Reading: 69,049.00

**Problem?**

Several D/O's report being shocked while raising the right side telescoping scene light. E91

**Task performed:**

UNIT REMOVED FROM TRUCK AND WILL REPAIR  
UNIT AT SHOP.

Parts

Quantity

OPP-503LENS FOR OPA570

1

XMG SOP235-OPSGASKET FOR OPA570

1

**Workorder: V53969**

In Date: 11/24/2012  
Close Date: 12/26/2012

Meter Reading: 60,370.00

**Problem?**

A/C Compressor is leaking oil and the sight glass indicates no oil left. E 91

**Task performed:**

FOUND NO LEAK AT COMPRESSOR.

Parts

Quantity

NO PARTS USED

**Workorder: V54938**

In Date: 01/08/2013  
Close Date: 02/01/2013

Meter Reading: 60,690.00

**Problem?**

replace cable in light pole

**Task performed:**

1. REPLACE ELECTRICAL CORD IN SIDE OF POLE LIGHT NEW IN CHECK OUT OK.
2. INSTALLED NEW LIGHT.

Parts

Quantity

480CCCORDD ASSY COILED EXTENDABLE LIGHT

2

**Workorder: V55835**

In Date: 02/19/2013  
Close Date: 02/20/2013

Meter Reading: 61,657.90

**Problem?**

Emergency lights inop E-91

**Task performed:**

REWIRED RELAY FOR POWER TO EMERGENCY LIGHTS.

Parts

Quantity

NO PARTS USED



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V55529**

In Date: 02/04/2013

Meter Reading: 61,168.50

Close Date: 02/22/2013

**Problem?**

E91 foam tank indicator is blinking showing foam tank as empty. If you manually check foam level the tank is full. No a dire situation but would still like repaired when possible. E91

**Task performed:**

RECALABRATED GAUGE AND TESTED.

Parts

NO PARTS USED

Quantity

**Workorder: V56291**

In Date: 03/10/2013

Meter Reading: 62,052.00

Close Date: 03/22/2013

**Problem?**

Driver's side rear yellow emergency dome light, mount to truck broken, light is held in place by wiring and fractured plastic. Also several ground lights, 1 on drivers side, 2 on officers.

**Task performed:**

1. INSTALLED NEW LIGHT ON LEFT SIDE OF TRUCK
2. AIR LEAK REPAIRED AT MAIN TANK.
3. REPAIRED TANK TO PUMP VALVE THAT WAS LEAKING.

Parts

RB6PAPRB6PAP ROTATING BEACON AMBER

1

Quantity

**Workorder: V56494**

In Date: 03/18/2013

Meter Reading: 62,081.00

Close Date: 03/22/2013

**Problem?**

Left rear rotating light (amber) is broken and is only connected to the truck by the wires. The plastic base is broken

**Task performed:**

1. TRAVEL TO STATION REMOVED LIGHT AND CAPPED WIRES WILL INSTALL NEW LIGHT TOMORROW.
2. INSTALLED NEW LIGHT ON REAR.

Parts

NO PARTS USED

Quantity

**Workorder: V49406**

In Date: 05/16/2012

Meter Reading:

Close Date: 04/08/2013

**Problem?**

Right, Rear, rotating warning light not working.

**Task performed:**

Parts

NO PARTS USED

Quantity



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V50432**

In Date: 06/27/2012

Meter Reading:

Close Date: 04/08/2013

**Problem?**

Already requested from Steve @ shop via phone call for new chain and air filter. Chainsaw is a Stihl m290, chain 20", 50cm, 81 teeth. Thank you. E 91

Task performed:

Parts

Quantity

NO PARTS USED

**Workorder: V53864**

In Date: 11/19/2012

Meter Reading:

Close Date: 04/08/2013

**Problem?**

The roof mounted searchlight is stuck in the "up" position. E 91

Task performed:

Parts

Quantity

LGHGO-2020GOLIGHT MODEL 2020 SEARCH LIGHT

1

**Workorder: V56283**

In Date: 03/09/2013

Meter Reading: 62,052.00

Close Date: 04/10/2013

**Problem?**

The halyard on the 24' Extension ladder is deteriorating and needs to be replaced.

Task performed:

Parts

Quantity

REPAIRED LOWER END OF ROPE.

NO PARTS USED

**Workorder: V56819**

In Date: 04/03/2013

Meter Reading: 62,081.00

Close Date: 04/10/2013

**Problem?**

Tow to shop E-91

Task performed:

Parts

Quantity

TOW TO SHOP E-91

NO PARTS USED

Vendor?: WESTWAY TOWING, INC.





1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V51132**

In Date: 07/25/2012  
Close Date: 04/11/2013

Meter Reading:

**Problem?**

While in for PM, E91 cab and front axle need inspected due to a loud, un-nerving rattle when hitting bumps. This has been on going and needs attention. I believe this has already been put in IBEM once. E 91

Task performed:

Parts

Quantity

NO PARTS USED

**Workorder: V55538**

In Date: 02/04/2013  
Close Date: 04/18/2013

Meter Reading:

**Problem?**

We need approx 15 sq. ft. of "Dry Deck" for shelves on E91

Task performed:

Parts

Quantity

NO PARTS USED

**Workorder: V58154**

In Date: 06/03/2013  
Close Date: 06/04/2013

Meter Reading: 62,081.00

**Problem?**

replace front tires

Task performed:

Parts

Quantity

REPLACE FRONT TIRES.

186301BRIDGESTONE 315/80R22.5

2

ARD130511.250.190 300AMP

1

Vendor?: BOULEVARD TIRE CENTE

**Workorder: V57110**

In Date: 04/17/2013  
Close Date: 06/24/2013

Meter Reading: 62,081.00

**Problem?**

REPAIR ACCIDENT DAMAGE

Task performed:

Parts

Quantity

REPAIR ACCIDENT DAMAGE.

8T7826UBOLTS

4

Vendor?: DIRECT HIT



1/29/2024

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V57903**

**In Date:** 05/22/2013

**Close Date:** 07/05/2013

**Meter Reading:** 62,081.00

**Problem?**

B inspection E91

**Task performed:**

Parts

Quantity



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

## CONTENDER FIRE DEPARTMENT PUMPER NFPA

1. B SERVICE.
2. B SERVICE.
3. B SERVICE.
4. CHECK HEAD LIGHTS - REMOVED CENTER PANEL FOR FUSES AND RELAYS - TRACED HEAD LIGHT CIRCUIT - FOUND BREAKER BAD - R&R BREAKER - FOUND WIRING GROUNDED TRIPPING BREAKER - TROUBLESHOOT AND ISOLATE CIRCUIT WIRING.
5. CHECK HEAD LIGHTS CARTS FOUND LOW BEAM POWER WIRE GROUNDED - DISASSEMBLED PANELS HEADLIGHTS MOUNTS, AND TRIM - TROUBLESHOOT AND FOUND WIRE GROUNDED - REPAIRED WIRING CHECK CIRCUIT - WIRE CHECK OK.
6. CHECK REAR UPPER AND LOWER EMERGENCY LIGHTS INOP - TRACED AND TROUBLESHOOT WIRING - ISOLATED LOWER LIGHT CIRCUIT - REPAIR CONNECTIONS AT RELAY.
7. REPAIR REAR UPPER AND LOWER LIGHTS CONT: FINISH LOWER LIGHT REPAIR - ISOLATED, TROUBLESHOOT AND REPAIR POWER CIRCUIT TO REAR UPPER LIGHTS - REMOVED AND REWIRED ALL EMERGENCY LIGHT CONTROL SWITCHES.
8. REPAIR EMERGENCY LIGHTS CONT: REPLACED EMERGENCY LIGHT SWITCHES - REPAIR AND REPLACED MELTED WIRING IN FUSE PANEL - REASSEMBLED ALL PARTS.
9. FOUND REAR ROLL UP DOOR INOP: CLEANED AND LUBED TRACK - CHECK OK.
10. REPLAC CAB A/C FILTER - REMOVED AIR FILTER ASSEMBLY - CUT NEW FILTER AND REPLACED - INSTALLED.
11. FOUND WINDSHIELD WASHER INOP - BOTTLE EMPTY - REMOVED STEP LIGHT DRILLED ACCESS HOLE - FILLED BOTTLE - RAN WASHER FOUND HOSES OFF OF FITTINGS BEHIND DASH PANELS - REMOVED PANELS AND COMPUTER MT. - INSTALLED HOSES - CHECK OK - TIGHTENED WIPER CONTROL VALVES.
12. FOUND FRONT AIR GAUGE ONLY GOING TO 90 PSI - REMOVED DASH PANEL - TROUBLESHOOT GAUGE - GAUGE BAD - ORDERED GAUGE.
13. FOUND SNAPS AND STRAPS BROKEN ON HOSE BED COVER - REPLACED MISSING PAST MOUNTS - DRILLED AND REPLACED OTHER POSTS.
14. REPAIR HOSE BED COVER CONT: INSTALLED COVER - REPAIRED SNAPS - REPLACED REAR HOLD DOWNS AND STRAPS.
15. FOUND PUMP PANEL LIGHTS OUT - R&R BULBS - R&R L REAR DOOR WINDOW HANDLE.
16. REPAIR AIR GAUGE CONT: CUT AND MODIFY DASH TO FIT GAUGE R&R GAUGE RAN AND CHECK OK.

|   |   |
|---|---|
| 0501PAIGAUGE AIR                          | 1 |
| 1817677C91FUEL FILTER SCREEN ASSY         | 1 |
| 33403FUEL FILTER LW                       | 1 |
| 33411FILTER FUEL SERIES 40                | 1 |
| 511182WINDOW CRANK HANDL EONE             | 1 |
| EL35012EL35012 SWITCH ROCKER              | 7 |
| FREIGHTSHIPPING CHARGES                   | 2 |
| H4656USE CV TYPE HEAD LIGHT               | 1 |
| L PLACARDLARGE SIDE PLACARD               | 2 |
| L PLACARD INSERTLARGE PLACARD INSERT CARD | 2 |
| PH713851799 FILTER OIL                    | 1 |
| UCB20FUSE 20AMP                           | 1 |
| Q2BPFEDERAL Q Q2B SIREN WITH BRACKET      | 1 |



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

- 17. TORQUE AXLE U-BOLTS - FOUND REAR AXLE BOLTS WON'T TORQUE SPRAYED, LOOSENED AND CLEANED REAR U-BOLTS.
- 18. TORQUE U-BOLTS CONTS: COULD NOT TORQUE U-BOLTS - REMOVED U-BOLTS - HOLD NEW ONES MADE.
- 19. REPAIR LOOSE SPRING HANGER ON FRONT SPRING - REMOVED FRONT AXLE U-BOLTS, RAISED AND LOWERED FRONT AXLE.
- 20. REPAIR FRONT SPRING CONT: REMOVED L. FRONT SPRING PIN AND FOUND SPRING HANGER BOLTS LOOSE - REMOVED AND REPLACED DAMAGED BOLTS.
- 21. REPAIR SPRING HANGER BOLTS - TIGHTENED ALL BOLTS.
- 22. ASSISTED WITH SPRING PIN INSTALLATION.
- 23. REPLACE AXLE U-BOLTS - INSTALLED AND REPLACED CRONT AXLE BOLTS - CUT BOLTS TO LENGTH - MEASURE AND CUT REAR AXLE U-BOLTS
- 24. REPLACE AXLE U-BOLTS CONT: REPLACED REAR AXLE U-BOLTS - TORQUE ALL U-BOLTS - TEST DROVE.
- 25. Ck. steering pulling to the right - check and adjust toe - toed in 1/4" - adjusted to specs - test drove - repositioned steering wheel - check ok.
- 26. installed acorn nuts on exposed bolts at tail board-r&r l pogo stick light bulb tied up wires at bumper check ok.
- 27. Check foam system - hook up to hyd - filled tank ran system.
- 28. Removed old number plate holders - sticked large number plates installed new plastic holders.
- 29. Replace missing fed q siren - found cable cut and assembly missing - stated to remove cable.
- 30. Replace missing fed q. ordered siren - removed power cable - removed siren assembly from E-95.
- 31. Replace fed q.
- 32. Perform Q & A Inspection.

**Workorder: V59067**

**In Date:** 07/13/2013

**Meter Reading:** 62,081.00

**Close Date:** 07/19/2013

**Problem?**

**FOAM GAUGE NOT WORKING. ALSO NEED A PEDAL ON THE DRIVERS SIDE FOR THE FEDERAL Q E 91**

**Task performed:**

- 1. CHECK OUT FOAM GAUGE SENDER IS BAD WILL ORDER.
- 2. CHECK OUT Q HAS PUSH BUTTON ON DASH AND WORKS.

Parts

Quantity

NO PARTS USED



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V59150**

In Date: 07/16/2013      Meter Reading: 62,081.00

Close Date: 07/19/2013

**Problem?**

DRIVERSIDE LOW BEAM OUT E91

**Task performed:**

TRAVEL TO ST 91 R&R HEADLIGHT.

Parts

H4656USE CV TYPE HEAD LIGHT

Quantity

2

**Workorder: V59221**

In Date: 07/20/2013      Meter Reading: 62,701.70

Close Date: 07/30/2013

**Problem?**

Driver's window makes a "screeching" sound when rolled up or down. E91

**Task performed:**

PULL DOOR PANEL LUBE UP LINKAGE AND  
REGULATOR.

Parts

NO PARTS USED

Quantity

**Workorder: V59348**

In Date: 07/25/2013      Meter Reading: 62,701.70

Close Date: 07/30/2013

**Problem?**

Install hook and strap to mount K-12 blades in the rear compartment on Driver's side.

**Task performed:**

SPOKE TO CAPTAIN HE SAID DON'T MOUNT BAGS  
STRAPS WILL BRAKE.

Parts

NO PARTS USED

Quantity

**Workorder: V59408**

In Date: 07/29/2013      Meter Reading: 62,701.70

Close Date: 08/15/2013

**Problem?**

Truck mounted generator will not start. does nothing when start button is pushed. does not crank at all. E93

**Task performed:**

TRAVEL TO ST 91 CHECK OUT GEN FUEL PUMP ON  
NO POWER TO REMOT SWITCH PULL GEN COVER  
PLATE AND GEN POWER BOX FOUND SWITCH WIRE  
OFF REPLACE COVER FOR TEST OK.

Parts

NO PARTS USED

Quantity



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V59529**

In Date: 08/03/2013  
Close Date: 08/16/2013

Meter Reading: 62,977.00

**Problem?**

drivers side spot light out E91

**Task performed:**

CHECK OUT SPOTLIGHT ON E-91 BREAKER OK NO POWER TO LIGHT CHECK SWITCHS ETC. CHECK GEN. POWER FOUND BREAKER ON GENERATOR OUT RESET TEST OK.

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V60216**

In Date: 09/02/2013  
Close Date: 09/11/2013

Meter Reading: 63,458.30

**Problem?**

transmission temp gauge not working. also need drivers side foot pedal for federal Q E91

**Task performed:**

- CHECK OUT TRANS TEMP GUAGE SENDER IN LINE FITTING BAD ORDER NEW SENSOR V.D.O. GUAGE.
- Q. HAS SWITCHES ON DASH. ADD ON NEXT P.M. PUT IN DEFERRED BOX THANKS ED.

**Parts**

- 2081600SWITCH A/C HIGH PRESSURE
- 63-0690SENSOR TRANS TEMP PIERCE
- 82-2019-0250BOLTS TORQUE BOX
- 82-3011NUT TORQUE BOX
- FREIGHTSHIPPING CHARGES

**Quantity**

- 1
- 1
- 2
- 2
- 1

**Workorder: V60352**

In Date: 09/06/2013  
Close Date: 09/11/2013

Meter Reading: 63,458.30

**Problem?**

A/C IN TRUCK NOT WORKING E91

**Task performed:**

FRONT A/C INOP - CHECK FUSES/RELAY ALL GOOD COMPRESSOR PRESSURES GOOD POWER TO SWITCHES GOOD FAN INOP POWER TO FAN, FAN BAD - NONE ON TRUCK TO MATCH ASSEMBLY. PARTS TO ORDER.

**Parts**

NO PARTS USED

**Quantity**



1/29/2024

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V60384**

In Date: 09/09/2013

Meter Reading: 63,458.30

Close Date: 09/24/2013

**Problem?**

A/C IN TRUCK NOT WORKING E91

**Task performed:**

1. ORDER BLOWER M&R 9/9/13 FROM ON CALL .
2. TRAVEL TO ST 91 R&R BLOWER M&R HAD TO CUT OLD MOTOR SHAFTS TO GET BLOWER WHEELS OUT HEAD UP TO GET SET SCREWS LOOSE DRIVE SHAFTS OUT OF WHEELS AND INSTALL ON NEW MOTOR ADJUST WHEELS AND INSTALL ASSY IN ROOF UNIT TEST PUT BACK TOGETHER UNIT RETEST OK..

**Parts**

**Quantity**

NO PARTS USED

**Workorder: V61035**

In Date: 10/06/2013

Meter Reading:

Close Date: 10/10/2013

**Problem?**

Low coolant, Driver door handle inoperable.

**Task performed:**

1. TRAVEL TO ST-91 CHECK DOOR HANDLE INOP PULL DOOR PANEL CHECK OUT DOOR LATCH FOUND HANDLE BROKEN R&R HANDLE ON OUTSIDE.

**Parts**

**Quantity**

HND5947NONLY LOCKING AVAIL L/H HANDLE CHROME

1

**Workorder: V60803**

In Date: 09/26/2013

Meter Reading:

Close Date: 10/11/2013

**Problem?**

Turning signal/hazard lights are not working on E91

**Task performed:**

- TRAVEL TO ST-91 CHECK OUT TURN SIG OUT CHECK SWITCH COLUMN MOUNT CHECK FLASHER ORDER NEW FLASHER.

**Parts**

**Quantity**

NO PARTS USED



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V61027**

In Date: 10/05/2013  
Close Date: 10/11/2013

Meter Reading: 64,372.00

**Problem?**

E91 has 2 auxillary plugs (cigarette lighter) but, they are not "hot" when the truck is off. For the tablet, we need to have one wired so it is always on.

**Task performed:**

REWIRE PLUGS TO STAY HOT PULL DOG HOUSE COVER ON TRUCK TO GET TO WIRING REWIRE TO HOT STUD REINSTALL COVER.

Parts

NO PARTS USED

Quantity

**Workorder: V61049**

In Date: 10/07/2013  
Close Date: 10/11/2013

Meter Reading: 64,372.00

**Problem?**

auto eject inop

**Task performed:**

TRAVEL TO ST 91 CHECK OUT AUTO EJECT CHARGE INOP BAD 110V END R&R END ON LINE.

Parts

NO PARTS USED

Quantity

**Workorder: V61074**

In Date: 10/07/2013  
Close Date: 10/22/2013

Meter Reading: 64,372.00

**Problem?**

clearance light needs to be fixed

**Task performed:**

TRAVEL TO ST 91 REPLACE LENS ON POLE LIGHT AND BULB.

Parts

NO PARTS USED

Quantity

**Workorder: V61249**

In Date: 10/14/2013  
Close Date: 10/22/2013

Meter Reading: 64,458.60

**Problem?**

install back board on E91 outside cab by pump pannel

**Task performed:**

1. MOUNT BACK BOARD ON BACK OF CAB WITH STRAPS LIKE IT SAYS ABOVE.
2. CAB LIGHT OUT MARKER INOP CHECK POWER AND GROUND R&R BULB.

Parts

SAHSVS2510STRAP

Quantity

2





1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V61260**

In Date: 10/15/2013  
Close Date: 10/22/2013

Meter Reading: 64,458.60

**Problem?**

Amber marker/left turn indicator on the cab, just in front of the driver's door, is out.

**Task performed:**

1. TRAVEL TO ST 91 INSTALL FLASHER THAT WAS ORDERED FOR TRUCK. REWIRE NEW STYLE FLASHER.
2. CHECK TURN SIGNAL OUT CHECK POWER AND GROUND R&R LIGHT.

| Parts                    | Quantity |
|--------------------------|----------|
| 63-0584FLASHER SOUND OFF | 1        |
| 64-1219-0006CONNECTOR    | 1        |
| 64-1220-0006CONNECTOR    | 1        |
| 64-1222-0001CONNECTOR    | 5        |
| 64-1222-0002TERMINALS    | 5        |
| FREIGHTSHIPPING CHARGES  | 1        |

**Workorder: V61377**

In Date: 10/19/2013  
Close Date: 10/30/2013

Meter Reading:

**Problem?**

officer side headlight out. E91

**Task performed:**

REPAIR ON WO# 61393.

| Parts         | Quantity |
|---------------|----------|
| NO PARTS USED |          |

**Workorder: V61393**

In Date: 10/20/2013  
Close Date: 10/30/2013

Meter Reading:

**Problem?**

Right side Low/High headlight out. We replaced with one we had in supply. Model H656 Type 2A1. Problem solved E92

**Task performed:**

DROP OFF HEADLIGHT HEADLIGHT WAS CHANGED

| Parts                       | Quantity |
|-----------------------------|----------|
| H4656USE CV TYPE HEAD LIGHT | 1        |

**Workorder: V61394**

In Date: 10/20/2013  
Close Date: 10/30/2013

Meter Reading:

**Problem?**

E91 still does not have a power plug that is always hot to charge the TripTix Tablet. Existing plugs are only hot with battery turned on. Previously requested 10/5/13 iBEM #P61434

**Task performed:**

TRAVEL TO ST 91 CHECK POWER PLUG ON DASH W METER12.6 V PK W BATT SWITCH OFF PASS. FUSE IN TRIPTIX CORD BAD LET DR KNOW.

| Parts         | Quantity |
|---------------|----------|
| NO PARTS USED |          |



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V62390**

In Date: 12/02/2013  
Close Date: 12/03/2013

Meter Reading: 65,325.00

**Problem?**

E91 coolant leak

**Task performed:**

COOLANT HOSE LEAKING REPLACED HOSE RAN ENGINE. FOUND WATER PUMP FAULTY E91 SWAPPED INTO B3SE.

Parts

NO PARTS USED

Quantity

**Workorder: V62391**

In Date: 12/02/2013  
Close Date: 12/06/2013

Meter Reading: 65,325.00

**Problem?**

E91 water pump faulty

**Task performed:**

TRAVEL TO ST 91 R&R WATER PUMP BAD DRAIN COOLANT R&R WATER PUMP AND THERMOSTAT REFILL TEST FOR LEAKS OK.

Parts

1830256C93THERMOSTAT INT.

1830606C94WATER PUMP

ALA00350-50 EXTENDED LIFE COOLANT GAL

1

1

6

Quantity

**Workorder: V62869**

In Date: 12/21/2013  
Close Date: 12/27/2013

Meter Reading:

**Problem?**

Roof ladder damaged while training. possibly needs to be replaced. Thanks, E91

**Task performed:**

Wayne issued E91 a new 14' roof adder.

Parts

NO PARTS USED

Quantity

**Workorder: V62571**

In Date: 12/08/2013  
Close Date: 12/31/2013

Meter Reading:

**Problem?**

Shelf above Hurst tool generator is bending and has a crack in the middle. In addition, two small light covers appear to be broken on the roof in the front of the engine on the driver and passenger sides. e91

**Task performed:**

- CHECK REAR CHELF OVERLOADED WILL RETURN WITH BRAKE FOR SHELF.
- TRAVEL TO ST-91 FAB BAR TO HOLD UP SHELF IN REAR COMPT FOR HURST TOOLS.

Parts

NO PARTS USED

Quantity



1/29/2024

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V62785**

In Date: 12/17/2013

Meter Reading:

Close Date: 12/31/2013

**Problem?**

Roof ladder clamp broken on E91.

**Task performed:**

Parts

Quantity

CHECK BROKEN LADDER CLAMP STRAP W/VELCRO STRAP.

NO PARTS USED

**Workorder: V62878**

In Date: 12/22/2013

Meter Reading:

Close Date: 12/31/2013

**Problem?**

2 front lights out on E91. The officer side light for clearance off the front bumper is out. Also the amber running light is out on the same side.

**Task performed:**

Parts

Quantity

- CHECK OUT LIGHT OUT R&R BULB IN POLE LIGHT
- CHECK TOP MARKER OUT BAD GROUND ON LIGHT REMOVE AND CLEAN GROUND.

SAHSVS2510STRAP

2

UMVS111611STRAP

2

**Workorder: V62999**

In Date: 12/28/2013

Meter Reading:

Close Date: 12/31/2013

**Problem?**

Emergency light by Drivers door is out. Also officer side amber running light is out and the light bulb on the clearance bar is out. E91

**Task performed:**

Parts

Quantity

CHECK OUT STROBE OUT HAS POWER AND GROUND R&R BULB.

NO PARTS USED

**Workorder: V63175**

In Date: 01/06/2014

Meter Reading: 66,381.60

Close Date: 01/07/2014

**Problem?**

case of oil to 91

**Task performed:**

Parts

Quantity

PARTS ONLY NO LABOR.

15W40QSYN OIL QT

12



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V63661**

In Date: 01/24/2014  
Close Date: 02/03/2014

Meter Reading: 66,669.00

**Problem?**  
coolant leak

**Task performed:**

TRAVEL TO ST-91 COOLANT LEAK CHECK OUT COOLING SYST. FOUND LEAK ON MOTOR REMOVE ALT AND REPAIR HOSE END FILL AND TEST OK.

| Parts                      | Quantity |
|----------------------------|----------|
| ANTICOOLANT ANTIFREEZE GAL | 3        |

**Workorder: V63168**

In Date: 01/06/2014  
Close Date: 02/06/2014

Meter Reading:

**Problem?**  
Officer's seat cushion is torn and needs to be repaired. e91

**Task performed:**

SWAPPED OUT SEAT FROM SPARE.

| Parts         | Quantity |
|---------------|----------|
| NO PARTS USED |          |

**Workorder: V63960**

In Date: 02/04/2014  
Close Date: 02/07/2014

Meter Reading: 66,904.00

**Problem?**  
triptix antenna

**Task performed:**

- CHECK OUT TRIPTIX CHARGER INOPINSTALL 12V CHARGE PART ON DASH AND WIRE UP. TEST OK.
- REPLACE HURST POWER FOOT.

| Parts                    | Quantity |
|--------------------------|----------|
| 56415CIG. LIGHTER ACCES. | 1        |

**Workorder: V64364**

In Date: 02/19/2014  
Close Date: 02/24/2014

Meter Reading: 67,251.00

**Problem?**  
coolant leak

**Task performed:**

TRAVEL TO ST-91 CHECK COOLANT LEAK FOUND LOWER MOTOR COOLING HOSE LEAKING R&R HOSE REFILL PRESSURE TEST OK.

| Parts                      | Quantity |
|----------------------------|----------|
| ANTICOOLANT ANTIFREEZE GAL | 4        |



1/29/2024

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V64812**

In Date: 03/10/2014

Meter Reading:

Close Date: 03/13/2014

**Problem?**

The hose bed cover pin/snaps are worn and broken. E91

**Task performed:**

**Parts**

**Quantity**

1. TRAVEL TO ST-91 REPAIR AND REPLACE HOSE BED OVER SNAPS AND BUCKLES ON REAR.

NO PARTS USED

**Workorder: V63475**

In Date: 01/17/2014

Meter Reading:

Close Date: 03/20/2014

**Problem?**

Please have a mechanic check both outer rear tires. The treads are getting pretty shallow

**Task performed:**

**Parts**

**Quantity**

TIRES REPAIRED BY OUTSIDE VENDER ON W.O #63644 BY BOULEVARD TIRE.

NO PARTS USED

**Workorder: V64910**

In Date: 03/13/2014

Meter Reading:

Close Date: 03/20/2014

**Problem?**

coolant leak and drivers side rear amber becon light is burn out.

**Task performed:**

**Parts**

**Quantity**

TRAVEL TO ST-91 CHECK COOLANT LEAK ON TRUCK FILTER LEAKING CALL SHOP FOR PARTS GO TO T.P.B TO USE A FILTER FOR NOW RETURN TO ST-91 R&R FILTER REFILL TEST LINES LEAKING TIGHTEN HOSE CLAMPS RETEST TOP OFF COOLANT OK.

24071-1FUEL FILTER WPB

1

3804899SEAL FRONT COVER B

1

ALA00350-50 EXTENDED LIFE COOLANT GAL

3

ANTICOOLANT ANTIFREEZE GAL

3

H35SN12BULB

1

**Workorder: V65143**

In Date: 03/24/2014

Meter Reading: 67,827.00

Close Date: 03/26/2014

**Problem?**

Headlight switch

**Task performed:**

**Parts**

**Quantity**

TRAVEL TO ST-91 INSTALL NEW HEAD LIGHT AND SWITCH AND REPLACE AND REWIRE TEST OK.

64-1105-0006HEADLITE SW DPDT WHT

1

FREIGHTSHIPPING CHARGES

1



1/29/2024

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V65223**

In Date: 03/26/2014

Meter Reading:

Close Date: 04/03/2014

**Problem?**

Both headlights on drivers side go out when high beams are turned on. Changed bulbs, still doing it.

**Task performed:**

1. TRAVEL TO STATION CHECK OUT BOLT LIGHTS ON HIGH; OUT. CHECK OUT LIGHT, NO POWER TO LIGHT ON LEFT SIDE. CHECK HEAD LIGHT SWITCH OK. CHECK WIRING RELAYS ECT PASS BAD WIG WAG NEED WIRING.  
2. CHECK GROUND LT OUT CHECK FOR POWER AND GROUND OK. R&R LIGHTS.

**Parts**

**Quantity**

621714 IN LIGHT

1

70R00XRR700 SER LED STOP LIGHT

1

**Workorder: V64965**

In Date: 03/17/2014

Meter Reading: 67,752.00

Close Date: 04/04/2014

**Problem?**

No Headlights E91

**Task performed:**

TRACED OUT PROBLEM FOUND SHORT IN HEAD LIGHT SWITCH, REPAIRED AND TESTED.

**Parts**

**Quantity**

NO PARTS USED

**Workorder: V64007**

In Date: 02/05/2014

Meter Reading:

Close Date: 04/22/2014

**Problem?**

Both outside rear tires are worn to/past the wear bars.

**Task performed:**

REPAIRED BY OUTSIDE VENDER.

**Parts**

**Quantity**

NO PARTS USED

**Workorder: V65360**

In Date: 04/01/2014

Meter Reading:

Close Date: 05/13/2014

**Problem?**

Rear tires are to the wear indicators.

**Task performed:**

REAR TIRES REMOVE REAR TIRES FOR REPLACEMENT- REINSTALL NEW TIRES.

**Parts**

**Quantity**

NO PARTS USED



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V65382**

**In Date:** 04/01/2014

**Meter Reading:**

**Close Date:** 05/13/2014

**Problem?**

Leaks Alot of oil. Brakes squeek. Red line preconnect valve leaks water wont shut off all the way. Cover for generator is missing. Tele lights are funky and we would like some of the fancy LED kind please. Thanks

**Task performed:**

Parts

Quantity

1. OIL LEAKS SEVERAL AREAS OF OIL LEAKS. FIRST WASH OFF OIL RESIDUE FROM UNDER ENG, FRAME, HOSES ELECTRICAL WIRING ETC. REPLACE GASKETS AT BACK END OF AIR COMPRESSOR ENG OIL FILTER HOUSING LEAKING- RESEAL, P/STEERING ALSO LEAKING REPLACE HOSES AND GASKET AT PRESSURE PUMP.
2. BRAKE SQUEAL CHECK OUT BRAKES- ALL LININGS WERE WERE 80% OR BETTER SOME SQUEAL IS NORMAL ON THESE TYPE OF BRAKES.
3. PRECONNECT LEAKING WATER REMOVE AND ON BENCH REBUILT VALVE AND REINSTALL.
4. GEN SET COVER FIND A PIECE OF MATERIAL LARGE ENOUGH AND CUT TO SIZE- FIND SOME KIND OF LATCHES SYSTEM TO HOLD DOWN COVER- INSTALL SYSTEM.

NO PARTS USED

**Workorder: V66368**

**In Date:** 05/09/2014

**Meter Reading:** 68,000.00

**Close Date:** 05/13/2014

**Problem?**

replace rear tires

**Task performed:**

Parts

Quantity

replace rear tires

NO PARTS USED

**Vendor?:** BOULEVARD TIRE



1/29/2024

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V65376**

**In Date:** 04/01/2014

**Close Date:** 05/21/2014

**Meter Reading:** 68,116.00

**Problem?**

C inspection E91

**Task performed:**

Parts

Quantity





1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10180687

### CONTENDER FIRE DEPARTMENT PUMPER NFPA

1. C-INSP.
2. C-INSP.
3. CAB LIFT CYLINDERS CHECK OUT PROBLEM WITH LEAKING CYLINDERS- CYLINDERS- CYLINDERS ARE LEAKING SO BADLY ON BOTH SIDES THAT THEY WON'T LIFT CAB ENOUGH TO BLOCK OPEN, HAD TO CHANGE OUT CYLINDERS ON THE GROUND WITH CAB DOWN. THIS WAS POSSIBLE BUT WITH GREAT DIFFICULTY.
4. ALT POS BAT CABLE MAIN BAT CABLE AT ALTERNATOR WAS BAD COVER OVER CABLE ROTTED OF EXPOSING BARE WIRING- DISCONNECT BATTS AND PULL DOWN CABLE UNDER FRAME UNTIL I FOUND GOOD CABLE SPLICE IN A NEW CABLE AND RUN BACK UP SIDE OF ENG TO ALTERNATOR- REATTACH.
5. HANDLITE HOLER R/REAR CAB HANDLE CHARGING BASE BROKEN- SEARCH FOR A USED BASE- NG GET NEW BASE FROM FROM WAYNE IN STALL NEW BASE AND REWIRE.
6. CAB DOOR WINDOW R/REAR CAB DOOR WINDOW ROLL UP DOWN HANDLE BROKEN- REPACE HANDLE.
7. UNDER TRUCK LIGHTS, 3 UNDER TRUCK LIGHTS- INOP CHECK OUT PROBLEM TWO OF THE LIGHT ASSEMBLY REPLACE- INSTALL NEW PIG TAIL HARNESS.
8. REPLACE ALL ENG BELTS AND BELT TENSIONER.
9. CAB ROOF MARKER LIGHT REMOVE LENS TO CHANGE BULB AND FOUND HOUSING BROKEN- CHECK WITH PARTS TO REPLACE FIXTURE- NG NO LIGHT ASSEMBLY AVAILABLE- GLUE BROKEN PIECES TOGETHER TO HOLD BULB- REASSEMBLE.
10. CAB DOOR PANEL SCREWS. SEVERAL OF THE CAB DOORS PANEL SCREWS LOOSE OR MISSING TIGHTEN ALL THAT WOULD TIGHTEN SOME STRIPPED OUT- INSTALL OVER SIZE AND REPLACE THOSE THAT WERE MISSING.
11. ENG NOISE CHECK OUT PROBLEM- FOUND IDLER PULLY BAD REPLACE.
12. A/C FAN SPEED DEFROST/HEAT FAN SPEED CONTROL KNOB VERY LOOSE- ADJUST KNOB TO PROPER ALIGNMENT AND TIGHTEN SET SCREW TO SECURE.
13. HUB BEARING SEALS BOTH OUTER BEARING CAP SEALS LEAKING OIL- REPLACE BOTH CAP SEAL.
14. L/SIDE TAIL LIGHT L/REAR HAS ONLY 3 LED BUBS BURNING OUT OF ABOUT 40- REPLACE ENTIRE LT FIXTURE.
15. FUEL LEAK CHECK OUT FUEL LEAK FROM MIDDLE OF CHASSIS- FOUND FUEL RETURN HOSE FROM END FUEL RAIL TO TANK WAS VERY HARD AND BRITTLE- HOSE HAD CRACKED AT ONE OF IT

|   |   |
|---|---|
| 07080TURN SIGNAL WPB                      | 2 |
| 1549164988280 GASKET P/S PUMP TO AIR COMP | 1 |
| 16-31438915 VALVE CORE A/C 3544706C1      | 2 |
| 1817677C91FUEL FILTER SCREEN ASSY         | 1 |
| 1819391C2FAN BELT                         | 1 |
| 1830033C2TENSIONER                        | 1 |
| 1898277CAB CYLINDER-LAKEWORTH PIERCE      | 2 |
| 26390YMARKER LIGHT AMBER WPB              | 1 |
| 29526898 29548988 TRANS FILTER ALLISON    | 1 |
| 33403FUEL FILTER LW                       | 1 |
| 33411FILTER FUEL SERIES 40                | 1 |
| 359-5990PLUG - HUB OIL CAP                | 2 |
| 467293HOSE AND FITTING                    | 1 |
| 46748AIR FILTER PIERCE                    | 1 |
| 467549HOSE & FITTING ASSY                 | 1 |
| 5008414CARTRIDGE DC100                    | 1 |
| 51064OIL FILTER ONAN                      | 1 |
| 589603-3758 COMPRESSOR QUNIT              | 1 |
| 621714 IN LIGHT                           | 1 |
| 70R00XRR700 SER LED STOP LIGHT            | 1 |
| 74R258607-2613A RED DOT DRIER 7127        | 1 |
| 80-0247WINDOW CRANK HANDLE                | 1 |
| 8201L17-3428 ESTER OIL E7                 | 2 |
| 91-20WIPER BLADE 20 IN                    | 2 |
| 91378905 VALVE KIT 2 IN AKRON             | 1 |
| 94993PIGTAIL TRUCKLITE 3-WIRE             | 1 |
| 95809580 BELT                             | 5 |
| FRT 65376FREIGHT CHARGE                   | 1 |
| H4651USE CV TYPE SEALED BEAM              | 1 |
| H4656USE CV TYPE HEAD LIGHT               | 1 |
| LAF2745AFILTER AIR 46270 WIX GEN KUBOTA   | 1 |
| R950013TURBO CUT OFF VLV KIT              | 1 |
| R950014PURGE VALVE WABCO AIR DRYER        | 1 |
| UMVS056511STRAP                           | 5 |
| 71R4040KNOB                               | 1 |
| 7605-666764-0023 SWITCH FOOT SIREN        | 1 |
| 923182-2151 SWITCH MOMENTARY 24-372       | 1 |
| PH713851799 FILTER OIL                    | 1 |



1/29/2024

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

BENDS- REMOVE ENTIRE LENGTH OF HOSE ALONG CHASIS REPLACE WITH NEW AND BETTER TYOE OF HOSE.

16. AIR DRYER SERV AIR DRYER.

17. TRANS SERV TRANSMISSION.

18. FRT TIRES ROTATE FRONT TIRES.

19. HEAD LIGHTS L/SIDE HIGH AND LOW BEAM HEADLIGHTS- INOP- FIRST REPLACE BOTH BULBS- STIL INOP REMOVE ENTIRE HEADLIGHT ASSEMBLY FROM BODY. THIS TO GAIN ACCESS TO WIRING- AFTER TRACING BCK WIRING I FOUND THE GROUND WIRE BROKE- REPLACE ON WIRE- RECONNECT AND RECHECK NOW ALL WORKS GOOD- REASSEMBLY LIGHTS.

20. R/FRONT TURN SIGNAL R/ FRONT TURN SIGNAL WAS INOP AND L/SIDE WORKED BUT VERY DULL- REMOVE BOTH TURN LIGHT ASSEMBLIES FROM BODY- ALSO REMOVE SIDE MARKER TURN FIXTURES- THESE LIGHTS ARE TIED TOGETHER FOR R/SIDE FIXTURE ROTTED AWAY AND GROUNDING OUT AND THE L/SIDE HAD A BAD FEED BACK THROUGH - REPAIR L/SIDE AND REPLACE FIXING ON RIGHT SIDE NOW TEST BOTH CIRCUITS- ALL OK- REASSEMBLE LIGHTING.

21. A/C SYSTEM A/C BLOWS ONLY COOL AND COMPRESSOR IS LOOSING OIL OUT THE BOTTOM- EVACUATE SYSTEM - REMOVE COMPRESSOR AND FOUND BOTH OIL LEVEL SIGHT GLASSES WERE LEAKING BADLY- WASH OFF ALL OIL RESIDUE FROM BRACKETS AND SIDE OF ENG - DRAIN OIL OUT OF NEW COMPRESSOR AND REFILL TO PROPER LEVEL -INSTALL COMPRESSOR - VACUUM DOWN AND RECHARGE SYSTEM - AFTER RUNNING FOR AWHILE I NOTICED PRESSURES WERE NOT RIGHT AND COOLING WAS OVER OILED- REEVACUATE SYSEM AMD FOUND-RECOVERY BOTTLE SHOWED ALMOST 8OZ OF RECOVERED OIL- REPLACE DRYER IN ROOF UNTIL- RECHECK OIL LEVEL IN COMPRESSOR AND RECHARGE SYSTEM AGAIN- NOW PRESSURES ARE SHOWING GOOD AND COOLING GOOD.

22. SERV GEN SET. SERV GENERATOR- NOTE: BECAUSE OF FACTORY INSTALLATION WITH NO ACCESS TO IL FILTER IT WAS NECESSARY TO CUT OUT A TO X7 ACCESS OPENING IN WALL BEHIND PUMP PANEL, THIS WAS ALSO EXTREMELY DIFFICULT BECAUSE OF OBJECT IN THE WAY- REPLACE FILTERS AND FINISH SERV, MAKE A COVER PLATE FOR ACCESS OPENING AND INSTALI

23. WIPER BLADES REPLACE WIPER BLADES AND FIND PROBLEM WITH WASHERS- TRACE BACK HOSE TO BOTTLE AND FOUND HOSE KINKED CLOSE- REROUTE FOR STRAIGHTER CONNECT TO PUMP MOTOR.



1/29/2024

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V66587**

**In Date:** 05/19/2014

**Meter Reading:** 68,177.00

**Close Date:** 05/21/2014

**Problem?**

Electical short in OK to pump circuit.

**Task performed:**

1. DRIVE TO UNIT LOCATION CHECK UNIT FOUND ELECTRICAL. SHORT CIRCUIT ON WIRE HARNESS. BRING UNIT TO SHOP FOR REPAIRS. FOUND TROUBLE WITH ASSISTANCE FROM SHOOT PUT BACK TOGETHER IS GOOD NOW.
2. ASSIST IN ELECTRICAL DIAGNOSE.

**Parts**

**Quantity**

B-1103A1131 LENS (AMBER)

1

**Workorder: V66578**

**In Date:** 05/19/2014

**Meter Reading:**

**Close Date:** 05/22/2014

**Problem?**

e91 pump will not throttle up when pump is engaged

**Task performed:**

1. DRIVE TO UNIT LOCATION. CAR FUEL LEAKS IN FRONT LAKEWORTH. HIGH DIAGNOSIS, FOUND LOST TO WIRE HARNESS. WAS DONE AT SHOP.
2. TRAVEL TO ST-91 CHECK OUT GEN NO START FOUND SWITCH OFF ON UNIT RESET TEST OK.
3. CHECK OUT TRUCK STALL ON PUMP ENGINE COULNT GET TO FAIL UNFOUNDED.

**Parts**

**Quantity**

NO PARTS USED

**Workorder: V66861**

**In Date:** 05/30/2014

**Meter Reading:**

**Close Date:** 06/13/2014

**Problem?**

AIR LEAK FROM DASH AREA AFTER ENGAGING PUMP

**Task performed:**

travel to sta, 91 found hub switch bad leak at pump shifter removed switch and replaced with new ok.

**Parts**

**Quantity**

76072-15-DC76072-15-DC SWITCH SW76072

1



1/29/2024

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V67538**

In Date: 06/29/2014

Meter Reading:

Close Date: 07/11/2014

**Problem?**

The front bumper light pole one of the bolts broke off. The light pole was secured with another bolt however it was the wrong size. E91

**Task performed:**

Parts

Quantity

REPLACE BUMPER POLE BOLT ON PASS SIDE.

NO PARTS USED

**Workorder: V68012**

In Date: 07/18/2014

Meter Reading:

Close Date: 07/24/2014

**Problem?**

On board generator will start but nothing will work. Checked the breaker and re set them all with no changes. Un able to get spot lights or outlets to work.

**Task performed:**

Parts

Quantity

on board generator inop, reset breaker ck, ok

NO PARTS USED

**Workorder: V68149**

In Date: 07/24/2014

Meter Reading:

Close Date: 07/25/2014

**Problem?**

Gas cap on gas fan is not able to be tightened down, leaks gas. Please replace with new gas cap. In addition, a new gas/oil funnel is needed to replace the old, one big and one small if possible.

**Task performed:**

Parts

Quantity

LD delivered.

GX160HONDA FUEL CAP

1

**Workorder: V67398**

In Date: 06/23/2014

Meter Reading: 68,836.40

Close Date: 08/14/2014

**Problem?**

air leak

**Task performed:**

Parts

Quantity

repairs complete on w/o v66861 at other time.

NO PARTS USED



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10180687

### CONTENDER FIRE DEPARTMENT PUMPER NFPA

**Workorder: V67787**

**In Date:** 07/09/2014  
**Close Date:** 08/14/2014

**Meter Reading:** 69,852.00

**Problem?**

The bottom stand/bracket that holds the power unit off the ground is broken. Only 2 welds out of the 4 are still together. The 2 welds that are still together are weak.

**Task performed:**

CARL AT THE SHOP REMOVED UNIT FROM BRACKET AND REWELDED MONTS BACK IN SERVICE COMPLETE.

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V72268**

**In Date:** 01/28/2015  
**Close Date:** 02/04/2015

**Meter Reading:** 2,814.00

**Problem?**

Starter

**Task performed:**

1. Check starter operation. Found starter grinding when engaging. Removed cables, hoses, wires and starter.
2. Replaced starter. Replaced wire ends. Reassembled all parts. Check operation - ok.
3. Check for coolant leak. Pressurize system. Found water filter leaking. Removed filter and cleaned seal surface. Replaced filter, filled and checked for leaks. Check ok.
4. Driver's door ajar going off. Check compartment doors. R & R 5 compartment light bulbs. Troubleshoot system. Found magnetic sw bad. R & R rear door switch.
5. Door ajar repair: Tied up and reassembled wires. Check operation - ok.
6. Repair foam system: Found control solenoid missing on foam pipe. Drained tank and removed side panel.
7. Replaced control solenoid, air line and fittings. Ran foam system and check ok. Reinstalled all parts.
8. Replace cab a/c filter: Removed filter assembly. Cut and installed new filter. Check ok.

**Parts**

- 1142BULB
- 1431684AIR FOAM VALVE PIERCE WPB
- 52-624SWITCH DOOR
- 63-1298MAGNETIC SWITCH WPB
- 82000056808 38MT 12T STARTER
- FRT V27624FREIGHT CHARGE
- PR338324070 WIX FILTER WATER

**Quantity**

- 5
- 1
- 1
- 1
- 1
- 1
- 1



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V71155**

**In Date:** 11/24/2014

**Close Date:** 04/29/2015

**Meter Reading:** 2,814.00

**Problem?**

Install door locks

**Task performed:**

1. Began installing locking latches on all compartment doors.
2. Completed installing locking latches on compartment doors.

**Parts**

**Quantity**

279LSS1250D-RING HANDLE W/LOCK 101280008

8

FRT 66185FREIGHT CHARGE

1



1/29/2024

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180687

**CONTENDER FIRE DEPARTMENT PUMPER NFPA**

**Workorder: V72819**

**In Date:** 02/02/2015

**Meter Reading:** 70,642.00

**Close Date:** 05/01/2015

**Problem?**

B inspection old E91 used at training

**Task performed:**

1. Perform "B" Service.
2. Continued/Completed "B" Service.
3. Replaced wiper blades. Tighten loose bolt on wiper transmission on driver side (loose). Also cleaned debris from both windshield skirters.
4. Replaced light in tripple light assembly on tailboard. Had to pry straighten tail board away from light assembly to access. (Bent).
5. Began checking out frozen/seized tank pum valve. Drained water tank , removed access panel on right size of truck.
6. Continued tank to pump repair: also removed pump panel on left side of truck to access valve also and removed valve. Began rebuilding valve.
7. Completed valve rebuild and began reinstalling valve. Scapped and cleaned mating surfaces before reinstalling. During reinstall both inner and out O-ring broke. Will have to order parts.
8. Removed tank to pump valve and tank side flange to repair hose couplers and pipe from tank to valve, (to log). Removed couplers and cleaned. Cut piping down to proper length. Will reinstall when new to pump O-Rings arrive.
9. Rebuilt left cross lay valve and adjust linkage.
10. Replaced tank recircutor valve. Also installed new are lever (rusted). Also adjusted linkage for full open and close.
11. R&R right side cross lay valve, cleaned and adjusted linkage. Neede no internals.
12. Installed valve control handle knob (missing).
13. Received O-ring for tank to pump valve from parts dept. Installed tank to pump valve. Fabbbed pipe to go from tank to valve.
14. Filled truck with water, operated pump and check for leaks at perssure. No leaks found. Reinstalled left and right pump panels and all related parts.

| Parts  | Quantity |
|--|----------|
| 0567042LONG STRECHER BAR                     | 1        |
| 15200RRED MARKER LIGHT RECTANGULAR           | 1        |
| 279LSS1250D-RING HANDLE W/LOCK 101280008     | 3        |
| 3157TAIL LIGHT BULBS                         | 1        |
| 33403FUEL FILTER LW                          | 1        |
| 33411FILTER FUEL SERIES 40                   | 1        |
| 78158915 VALVE 1 1/2                         | 1        |
| 91-20WIPER BLADE 20 IN                       | 2        |
| 91378905 VALVE KIT 2 IN AKRON                | 1        |
| FRT V28260FREIGHT CHARGE                     | 1        |
| PH713851799 FILTER OIL                       | 1        |
| WAT-W37108-4ORING WATEROUS PUMP TANK TO PUMP | 4        |
| 52-0139KNOB CONTOL LEVER PIERCE              | 1        |



# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

Asset: (10180687) 2002 - PIERCE CONTENDER 1250 Gpm Pumper E772

10180687

**CSHOP-2015-982**

Comments: **OLD E91 AT TRAINING - NEEDS MANSVER BARS INSTALLED**

Date Opened: 6-4-2015      Date Finished: 7-23-2015      Meter 1 Reading: 70,642

**TASKS PERFORMED**

**Q      PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
EMERGENCY EQUIPMENT

2      20 IN MANSVER

**CSHOP-2016-3406**

Comments: **C-INSPECTION**

Date Opened: 7-14-2016      Date Finished: 8-19-2016      Meter 1 Reading: 70,885

**TASKS PERFORMED**

**Q      PARTS**

PM SERVICE C

30      FLUID; SYN OIL BULK QTS  
1      VALVE; TURBO CUT OFF VLV KIT  
1      FILTER; FUEL FILTER LW  
1      FILTER; FILTER FUEL SERIES 40  
1      FILTER; FILTER OIL 51799  
1      BRAKE; CARTRIDGE DC100  
1      VALVE; PURGE VALVE WABCO AIR DRYER

**CSHOP-2016-4129**

Comments: **REPAIRS FROM PM**

Date Opened: 8-22-2016      Date Finished: 8-26-2016      Meter 1 Reading: 70,891

**TASKS PERFORMED**

**Q      PARTS**

WATER TANK LEVEL LIGHTS  
TANK SUCTION VALVE FIRE PUMP  
INSTRUMENT PANEL LIGHTS  
TAIL LIGHTS  
PARK-CLEARANCE LIGHTS  
DOOR  
HOSES-LINES & FITTINGS  
HVAC SYSTEM

2      PIERCE; 2.5 IN 30-0-400 PSI  
2      BULB; BULB  
1      BULB; BULB 100W SPOT  
1      LIGHT; 4 IN LIGHT  
2      9IP; RED MARKER LIGHT RECTANGULAR  
1      BULB; LIGHT BULB 12CP  
2      LIGHT; 4 IN LIGHT  
2      9IP; BULB  
1      STRUT; GSS6298UH STRUTS 90#  
1      DRYER; 07-2613A RED DOT DRIER 7127



**Asset Work Order History 10180687**

**CSHOP-2016-4415**

Date Opened: 9-9-2016

Date Finished

11-8-2016

Meter 1 Reading:

70,919

**TASKS PERFORMED**

**Q PARTS**

|                                     |    |                                  |
|-------------------------------------|----|----------------------------------|
| PUMP PANEL                          | 2  | STRAINER; STRAINER 2.5 IN        |
| FIRE PUMP                           | 2  | STRAINER; STRAINER 6 IN          |
| WIPERS-WASHER                       | 1  | 9IP; WASHER NOZZEL               |
| OIL                                 | 1  | FLUID; GAL CONTAINER TRANS FLUID |
| PARK-CLEARANCE LIGHTS               | 12 | 9IP; SYN OIL QT                  |
| REPAIR FROM PM - DECALS/CLEANLINESS | 1  | LENS; B-1100 CLAMP TOP LENS      |
| LIGHT BAR                           | 10 | BULB; BULB                       |
| BODY EXTERIOR                       | 6  | BULB; BULB 12 VOLT               |
| QUALITY CHECK-REPAIRS               | 1  | LENS; 1131 LENS (AMBER)          |
|                                     | 1  | POWER SUPPLY; POWER SUPPLY 9M    |
|                                     | 2  | NEWPART; WHEEL AND TIRE ASSY     |
|                                     | 1  | BLOCK; BLOCK VACUMN              |

**Service Requests:**

09/08/2016 SERVICE REQUEST / 12: BROKEN / REPAIR  
SERVICE REQUEST NEED NEW STRAINER FOR PUMP

**CSHOP-2017-2623**

Date Opened: 5-4-2017

Date Finished

6-15-2017

Meter 1 Reading:

70,919

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
FIRE PUMP

**Service Requests:**

05/04/2017 SERVICE REQUEST / 11: BINDS/STICKS / INSPECT  
SERVICE REQUEST WILL NOT GO INTO PUMP. PUMP ENGAGE LIGHT AND OK TO PUMP LIGHT NOT COMING ON NO THROTTLE RESPONSE AT PUMP PANEL

**CSHOP-2017-3518**

Date Opened: 6-14-2017

Date Finished

8-10-2017

Meter 1 Reading:

70,919

**TASKS PERFORMED**

**Q PARTS**

|              |   |                           |
|--------------|---|---------------------------|
| PM SERVICE B | 1 | FIL; NAPAGOLD FUEL FILTER |
|              | 1 | FIL; NAPAGOLD OIL FILTER  |
|              | 5 | 9OC; SYN 15W40            |
|              | 1 | FIL; NAPAGOLD FUEL FILTER |
|              | 5 | FLUID; SYN OIL BULK QTS   |

**Asset Work Order History 10180687**

**CSHOP-2017-3543**

Comments: **REPAIRS FROM PM**

Date Opened: 6-15-2017

Date Finished

6-30-2017

Meter 1 Reading:

70,919

**TASKS PERFORMED**

**Q PARTS**

|                               |   |                             |
|-------------------------------|---|-----------------------------|
| FOAM SYSTEM                   | 1 | ECH; SWITCH                 |
| FIRE PUMP CONTROLS            | 1 | 5TN; SENDER                 |
| FIRE PUMP                     | 1 | 9IP; BULB 100W SPOT         |
| REPAIR FROM PM - GENERATOR    | 1 | 9IP; STEPWELL LIGHT         |
| ENGINE COOLANT TEMPERATURE SE | 1 | LIGHT; STEPWELL LIGHT       |
| LIGHTING SYSTEM               | 1 | 6KU; AUTO CHAGER AC2000 12V |
| BATTERY                       | 6 | 1AD; BATTERY 31 SERIES      |
| SHORELINE CHARGER             | 1 | 9IP; A/C VENT               |
| ABS COMPUTER CONTROLS         |   |                             |
| SIREN                         |   |                             |
| A/C BLOWER OPERATES           |   |                             |

**CSHOP-2017-5112**

Comments: **PARTS FROM MAKO FOR CASCADE TRAILER FOR PHILL**

Date Opened: 8-30-2017

Date Finished

9-20-2017

Meter 1 Reading:

70,919

**TASKS PERFORMED**

**Q PARTS**

|            |   |               |
|------------|---|---------------|
| AIR SYSTEM | 1 | 9HY; FITTINGS |
|            | 1 | 9HY; FITTINGS |

**CSHOP-2017-6069**

Comments: **TRAINING ENGINE ADDED A SERVICE REQUEST FOR TRAINING JOHN DEERE ALSO THANK YOU**

Date Opened: 10-20-2017

Date Finished

1-22-2018

Meter 1 Reading:

70,919

**TASKS PERFORMED**

**NO PARTS USED**

COMMERCIAL WORK - OUTSIDE AGENCY

**VENDOR?** REGANS SMALL ENGINE SERVICE

**Service Requests:**

|            |  |
|------------|--|
| 10/19/2017 | FUEL / 12: BROKEN / INSPECT<br>FUEL GAUGE NOT RESPONDING STAYS AT 3/4  |
| 12/20/2017 | STARTER / 12: BROKEN / REPAIR<br>VEHICLE WILL NOT START THIS IS NOT FOR APPARATUS. THIS IS FOR THE JOHN DEERE TALLER SIDE BY SIDE. ASSET # 10177200 . STARTER WAS REPLACED. BUT NOW NEEDS NEW BATTERY. |
| 10/20/2017 | STARTER / 12: BROKEN / INSPECT<br>VEHICLE WILL NOT START POSSIBLE STARTER ISSUE. TRIED STARTING HEARD CLICKING ONLY. USED HAMMER TO TAP STARTER AND STARTED RIGHT UP. JOHN DEERE ASSET # 10177200      |

**Asset Work Order History 10180687**

**CSHOP-2018-3978**

Comments: **ADDED A TIRE LINE FOR PHIL TO GET ATV TIRES**

Date Opened: 7-13-2018      Date Finished 8-28-2018      Meter 1 Reading: 70,919

**TASKS PERFORMED**

**Q      PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
LADDER RACK BODY  
TIRES ALL

1      9AP; TIRES  
1      NCB; THL24336ML

**Service Requests:**

07/13/2018      SERVICE REQUEST / 18: LEAKING / INSPECT  
HYDRAULIC OIL LEAKING FROM LADDER RACK INTO R-3 COMPARTMENT

**CSHOP-2018-4391**

Comments: **THIS BILL IS 2 INVOICES COMBINED AND IS FOR TRAINING EQUIPMENT THAT IS NOT IN ASSET WORKS**

Date Opened: 8-6-2018      Date Finished 8-6-2018      Meter 1 Reading: 70,919

**TASKS PERFORMED**

**NO PARTS USED**

VENDOR TIRE REPAIR/CHANGE

**VENDOR?**      DAN CALLAGHAN ENTERPRISES

**CSHOP-2018-5242**

Comments: **LADDER RACK**

Date Opened: 9-14-2018      Date Finished 3-7-2019      Meter 1 Reading: 71,939

**TASKS PERFORMED**

**Q      PARTS**

LADDER RACK BODY  
INTAKE GAUGE  
REPAIR FROM PM - TRANS/TRANSFER CASE  
LIGHTING SYSTEM  
ELECTRICAL  
REPAIR FROM PM - DIFFERENTIALS  
REPAIR FROM PM - CAB  
REPAIR FROM PM - DECALS/CLEANLINESS  
HVAC SYSTEM

2      BK; PTEX ULTRA BLACK 30Z  
1      2IH; TRANSYND  
1      9AP; ACTUATOR  
1      9HW; BOLTS  
2      5TN; CLASS1 VAC GAUGE  
1      ECH; SWITCH  
3      LIT; LENS  
2      9AP; BRAKE CLEAN  
12      9AP; BRAKE CLEAN  
2      1AN; WIPER BLADE  
12      NCB; CHAMPION 2 CYCLE OIL  
1      9AP; DETAIL  
2      SVP; CNDSTRFAN  
1      TEM; FILTER DRIER

**CSHOP-2018-5243**

Date Opened: 9-14-2018      Date Finished 3-7-2019      Meter 1 Reading: 70,919

**TASKS PERFORMED**

**Q      PARTS**

PM SERVICE C

1      FIL; NAPAGOLD FUEL FILTER  
1      FIL; NAPAGOLD OIL FILTER  
30      4PC; 15W40 PREMIUM BLUE OIL  
1      NCB; DEGREASER MULTI PURP  
1      FIL; NAPAGOLD FUEL FILTER

**Asset Work Order History 10180687**

**CSHOP-2018-799**

Date Opened: 2-8-2018

Date Finished

6-28-2018

Meter 1 Reading:

70,919

**TASKS PERFORMED**

**Q PARTS**

|                           |     |                               |
|---------------------------|-----|-------------------------------|
| FIRE FIGHTING EQUIPMENT   | 1   | 9HW; THREADED ROD             |
| FIRE PUMP CONTROLS        | 1   | 9HY; HOSE                     |
| LADDER RACK BODY          | 2   | 5TN; KITREPAIRDRAINVLV        |
| EXHAUST MANIFOLD          | 1   | 5AB; 1.5 BALL KIT             |
| COOLING SYSTEM            | 1   | 5TN; GOVERNOR                 |
| BATTERY                   | 2   | 5AB; 2.5 BALL KIT COMPOSITE   |
| CRANKING SYSTEM           | 1   | 5TN; SOLENOID VALVE           |
| VOLT METER                | 2   | 5AB; 2.5 BALL KIT COMPOSITE   |
| SIREN                     | 2   | 5TN; 2IN GAUGE -30/400        |
| TEMP GAUGE                | 1   | NONSTOCK; FREIGHT CHARGE      |
| INSTRUMENTS-GAUGES-METERS | 4   | 9HE; HURST5KBLUEFLUID         |
|                           | 1   | MMM; WTHRSTRP ADH-BLK 5OZ     |
|                           | 25  | NBH; SILICONE HTR HOSE        |
|                           | 1   | ECH; ELECTRICAL CONNECTOR     |
|                           | -40 | 9OC; COOLANT                  |
|                           | 40  | 9OC; COOLANT                  |
|                           | 10  | FLUID; COOLANT ANTIFREEZE GAL |
|                           | 1   | ECH; COOLANT TEM SENSOR       |
|                           | 1   | MMM; ATTACHMENT TAPE          |
|                           | 1   | 5TN; SENDER                   |

**Service Requests:**

02/07/2018 SERVICE REQUEST / 12: BROKEN / CORRECTED ON TASK 042  
SEE ATTACHED FILE

02/08/2018 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / ADJUST  
LADDER RACK NOT WORKING WILL NOT LOWER

**CSHOP-2019-1874**

Date Opened: 4-11-2019

Date Finished

5-10-2019

Meter 1 Reading:

72,288

**TASKS PERFORMED**

**NO PARTS USED**

LADDER RACK BODY  
REPAIR FROM PM - PUMP PANEL CONTROLS

**CSHOP-2019-3049**

Comments: **PARTS ONLY**

Date Opened: 6-12-2019

Date Finished

6-17-2019

Meter 1 Reading:

70,919

**TASKS PERFORMED**

**Q PARTS**

BODY EXTERIOR

|  |   |                    |
|--|---|--------------------|
|  | 3 | 6ZA; STRAP 25"-44" |
|--|---|--------------------|

**CSHOP-2019-4947**

Date Opened: 9-18-2019

Date Finished

9-21-2019

Meter 1 Reading:

0

**TASKS PERFORMED**

**Q PARTS**

HOSES-LINES & FITTINGS

|  |   |               |
|--|---|---------------|
|  | 1 | 9HD; TRAINING |
|--|---|---------------|

**Asset Work Order History 10180687**

**CSHOP-2019-937**

Date Opened: 2-19-2019      Date Finished      4-9-2019      Meter 1 Reading:      72,288

**TASKS PERFORMED**

**Q      PARTS**

---

|                         |    |                                  |
|-------------------------|----|----------------------------------|
| FIRE FIGHTING EQUIPMENT | 1  | 5CS; GOVERNOR 108                |
| PUMP PANEL              | 10 | BOLT                             |
| LADDER RACK BODY        | 1  | 9AP; ACTUATOR REBUILD            |
| HOSES-LINES & FITTINGS  | 2  | BK; PTEX ULTRA BLACK 30Z         |
| BATTERY                 | 2  | 5SC; CAB LATCH LOCK              |
| HVAC SYSTEM             | 1  | 9AM; REMOTE BATTERY TERMINALS PR |

---

**CSHOP-2020-2118**

Comments:      **INSPECT ONLY NO OIL/FILTERS**

Date Opened: 4-21-2020      Date Finished      5-18-2020      Meter 1 Reading:      72,273

**TASKS PERFORMED**

**NO PARTS USED**

---

PM SERVICE B

---

**CSHOP-2020-3222**

Date Opened: 6-19-2020      Date Finished      6-19-2020      Meter 1 Reading:      72,273

**TASKS PERFORMED**

**Q      PARTS**

---

|                     |    |                                |
|---------------------|----|--------------------------------|
| EMERGENCY EQUIPMENT | 10 | 9AP; HEAT SENSOR LADDER LABELS |
|---------------------|----|--------------------------------|

---

**CSHOP-2020-3895**

Date Opened: 7-28-2020      Date Finished      8-20-2020      Meter 1 Reading:      72,273

**TASKS PERFORMED**

**Q      PARTS**

---

|         |   |                        |
|---------|---|------------------------|
| BATTERY | 1 | 1AD; BATTERY 51 SERIES |
|---------|---|------------------------|

---

**CSHOP-2020-4587**

Date Opened: 9-3-2020      Date Finished      9-5-2020      Meter 1 Reading:      0

**TASKS PERFORMED**

**Q      PARTS**

---

|                         |   |                           |
|-------------------------|---|---------------------------|
| FIRE FIGHTING EQUIPMENT | 1 | 9GN; GENESIS FLUID GAL    |
|                         | 2 | 9HE; FLUID HURST BLUE 1QT |

---

**CSHOP-2021-2652**

Comments:      **INSPECT ONLY**

Date Opened: 5-12-2021      Date Finished      5-17-2021      Meter 1 Reading:      72,295

**TASKS PERFORMED**

**NO PARTS USED**

---

PM SERVICE C

---

**Asset Work Order History 10180687**

**CSHOP-2021-2653**

Comments: **ORDERED NEW GENESIS CUTTER INSERTS**

Date Opened: 5-12-2021      Date Finished 8-23-2021      Meter 1 Reading: 73,037

**TASKS PERFORMED**

**Q      PARTS**

FIRE FIGHTING EQUIPMENT  
FUEL SYSTEM  
ENGINE AND ACCESSORIES  
BATTERY  
CRANKING SYSTEM  
HVAC SYSTEM

1      5TN; DOOR JAM CONTACT 3WIRE BRUAN  
2      BK; AUTOMOTIVE GOOP  
4      5GR; C236 NXTGEN INSERT CUTTERS  
1      9HC; HOSE MAKO CUSTOM  
1      9AP; OIL SAMPLE TEST KIT PETRO CANADA  
30     4PC; 15W40 PREMIUM BLUE OIL  
1      FIL; NAPAGOLD FUEL FILTER  
1      FIL; NAPAGOLD OIL FILTER  
1      FIL; NAPAGOLD FUEL FILTER  
6      1AD; 1000 CCA 31 SERIES BATTERY

**CSHOP-2022-2305**

Comments: **E772 INSPECTION**

Date Opened: 4-27-2022      Date Finished 5-16-2022      Meter 1 Reading: 73,037

**TASKS PERFORMED**

**NO PARTS USED**

INSPECTION

**CSHOP-2022-3429**

Date Opened: 6-24-2022      Date Finished 10-6-2022      Meter 1 Reading: 73,037

**TASKS PERFORMED**

**Q      PARTS**

DIAGNOSE ELECTRICAL

10     8AM; TOOL MOULDING REMOVAL  
1      FREIGHT

**CSHOP-2022-5639**

Comments: **BREAKER**

Date Opened: 10-19-2022      Date Finished 10-21-2022      Meter 1 Reading: 0

**TASKS PERFORMED**

**Q      PARTS**

ELECTRICAL

1      BK; HI AMP FLUSH MOUNT

**CSHOP-2023-2699**

Date Opened: 5-19-2023      Date Finished 5-23-2023      Meter 1 Reading: 73,128

**TASKS PERFORMED**

**NO PARTS USED**

INSPECTION

**Asset Work Order History 10180687**

**RADIO-2018-1215**

Comments: **INSTALL NEW MDC MOUNT & CLEAN UP WIRING.**

Date Opened: 11-28-2018

Date Finished 11-28-2018

Meter 1 Reading: 0

**TASKS PERFORMED**

**NO PARTS USED**

---

PC RELATED

**Service Requests:**

---

11/28/2018

RADIO / /

INSTALL NEW MDC MOUNT

---