

2/1/2024
4:11:59 PM

Palm Beach County Fleet Management Asset Maintenance History
10198024 2015 JACOBSON GROOM MASTER II Ballfield Groomer

Total Hours: 84.50 Labor: 5,722.75 Parts: 2,730.69 Comm: 0.00 Charged: 8453.44

Work Order: 1502307 **Meter:** 1 **In Date:** 03/04/2015 **Closed:** 03/04/2015
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1602010 **Meter:** 270 **In Date:** 02/26/2016 **Closed:** 03/08/2016
Problem: P.M.SERVICE

Work Completed

- pm
- svc hyd sys rr filter correct fluid level inspect lines and hoses
- wash eq
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Napagold Fuel Filter	1.00
Napagold Oil Filter	1.00
15w40 Bulk South Reg	4.00
Napa Trans Filter	1.00
Aw68 Bulk Sr	2.00
Shop Supplies	1.00

Hours: 6.00 Comm: 0.00 Labor: 360.00 Parts: 43.15 Total: 403.15

Work Order: 1702795 **Meter:** 469 **In Date:** 03/20/2017 **Closed:** 03/30/2017
Problem: PM Service

Work Completed

- Pm Service.
- Service hyd system.inspect lines,hoses etc..replace filter.correct fluid level.
- Verify needs front tire.replace front tire.mount Add N2.
- Wash equipment.
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Napagold Fuel Filter	1.00
Napagold Oil Filter	1.00
15w40 Bulk South Reg	4.00
Wd40 Spr	1.00
Napa Trans Filter	1.00
20x11.0	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 7.50 Comm: 0.00 Labor: 450.00 Parts: 191.67 Total: 641.67

2/1/2024
4:11:59 PM

Palm Beach County Fleet Management Asset Maintenance History
10198024 2015 JACOBSON GROOM MASTER II Ballfield Groomer

Work Order: 1802671 **Meter:** 612 **In Date:** 03/12/2018 **Closed:** 03/30/2018
Problem: PM Service.Will not start.

Work Completed

Parts Issued

Quantity

- Pm Service.
- C/c wont start.verify rusted safety switches.inoperable.replace two switches and adjust.
- Verify needs two rear tires.replace two rear tires.mount and add N2
- Service hyd system.inspect.replace filter.correct fluid level.
- Wash equipment.
- Shop Supplies

Napagold Fuel Filter	1.00	
Napagold Air Filter	1.00	
Napagold Oil Filter	1.00	
Wd40 Spr	1.00	
15w40 Bulk South Reg	4.00	
Switch, Prox	3.00	
Napa Trans Filter	1.00	
Aw68 Bulk Sr	2.00	
20x11.00-10 4ply Carl Turf Tamer	2.00	
Shop Supplies	1.00	
Tire Disposal Fee	2.00	
Freight Charge	1.00	
Labor: 555.00	Parts: 617.32	Total: 1,172.32

Hours: 9.25

Comm: 0.00

Work Order: 1804981 **Meter:** 617 **In Date:** 05/14/2018 **Closed:** 07/12/2018
Problem: Brake pedal rubbing against machine.Engine willnot turn over.

Work Completed

Parts Issued

Quantity

- C/c wont turn over.replace ignition switch.
- Replace and adjust proximity switch.
- Verify brake components missing.install new pedal lock and hardware.
- Wash equipment.
- Shop Supplies

Keyswitch	1.00	
Switch, Prox	1.00	
Screws	2.00	
Parking Brake Lever	1.00	
Keyswitch	1.00	
Shaft Turn Assist	1.00	
Shop Supplies	1.00	
Freight Charge	1.00	
Freight Charge	1.00	
Labor: 240.00	Parts: 328.53	Total: 568.53

Hours: 4.00

Comm: 0.00

2/1/2024
4:11:59 PM

Palm Beach County Fleet Management Asset Maintenance History
10198024 2015 JACOBSON GROOM MASTER II Ballfield Groomer

Work Order: 2004838 **Meter:** 765 **In Date:** 05/13/2020 **Closed:** 05/29/2020
Problem: P.M.SERVICE

Work Completed

- Pm Service
- Service hyd. system.r/r filter,correct fluid.verify hyd.handles broken.replace levers.
- Verify engine belt need replaced.replace belt.
- Wash equipment for service and repair.
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Fuel Element	1.00
15w40 Bulk South Reg	4.00
Napagold Oil Filter	1.00
Aw68 Bulk Sr	2.00
Napa Trans Filter	1.00
Control Valve Handle	2.00
V Belt	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 8.75

Comm: 0.00

Labor: 638.75 Parts: 496.49 Total: 1,135.24

Work Order: 2007593 **Meter:** 1775 **In Date:** 08/03/2020 **Closed:** 08/17/2020
Problem: Lever for hydraulic control loose.

Work Completed

- Repair lever for Hyd.lift valve.reassemble.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 2.00

Comm: 0.00

Labor: 146.00 Parts: 4.00 Total: 150.00

Work Order: 2010298 **Meter:** 790 **In Date:** 10/13/2020 **Closed:** 10/29/2020
Problem: Broken hydraulic hose.

Work Completed

- Customers complaint unit has broken hydraulic hose. Verify multiple hydraulic hoses are worn through, remove and replace 3 hydraulic hoses, install pieces of heater hose as anti chafing gear to prevent further damage. Refill tank r/r filter.
- Wash hydraulic fluid and clay from unit to trouble shoot leaks and perform repairs.
- Shop Supplies

Parts Issued

Quantity

Mako Hoses	1.00
Aw68 Bulk Sr	20.00
Napa Trans Filter	1.00
Shop Supplies	1.00

Hours: 7.50

Comm: 0.00

Labor: 547.50 Parts: 277.89 Total: 825.39

2/1/2024
4:11:59 PM

Palm Beach County Fleet Management Asset Maintenance History
10198024 2015 JACOBSON GROOM MASTER II Ballfield Groomer

Work Order: 2105878 **Meter:** 829 **In Date:** 05/27/2021 **Closed:** 06/11/2021
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- wash - n clean radiator
- replace 4 ft of fuel line n run new filter system
- Shop Supplies

Parts Issued

Quantity

Napa Qt 15w40	4.00
Napagold Oil Filter	1.00
Fuel Element	1.00
Napagold Air Filter	1.00
Non-chlor Brake Clnr	1.00
Pm-22-a Additive Dies	1.00
Fuel Line Hose	4.00
Napagold Fuel Filter	1.00
Shop Supplies	1.00

Hours: 6.50

Comm: 0.00

Labor: 474.50 Parts: 66.22 Total: 540.72

Work Order: 2206341 **Meter:** 884 **In Date:** 06/15/2022 **Closed:** 07/01/2022
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Service hydraulic system, replace filter, correct fluid level, inspect all hoses and fittings.
- Customers complaint unit steers to the right. Remove and breakdown hydraulic cylinder and found damaged seal is causing internal bypass. install seal rebuild kit to cylinder, reinstall, reassemble and test drive.
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Napagold Air Filter	1.00
Fuel Element	1.00
15w40 Bulk South Reg	4.00
Napagold Oil Filter	1.00
Aw68 Bulk Sr	2.00
Napa Trans Filter	1.00
Seal Kit	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 9.00

Comm: 0.00

Labor: 657.00 Parts: 119.19 Total: 776.19

2/1/2024
4:11:59 PM

Palm Beach County Fleet Management Asset Maintenance History
10198024 2015 JACOBSON GROOM MASTER II Ballfield Groomer

Work Order: 2307062 **Meter:** 960 **In Date:** 07/18/2023 **Closed:** 07/27/2023
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Service hydraulic system, replace filter, correct fluid level and inspect all.
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Inner Air Filter Replaces 2845	1.00
15w40 Bulk South Reg	4.00
Napagold Oil Filter	1.00
Fuel Element	1.00
Aw68 Bulk Sr	2.00
Napa Trans Filter	1.00
Napagold Fuel Filter	1.00
Shop Supplies	1.00

Hours: 5.00 Comm: 0.00

Labor: 365.00 Parts: 76.53 Total: 441.53

Work Order: 2310526 **Meter:** 968 **In Date:** 10/18/2023 **Closed:** 10/25/2023
Problem: Front flat tire.

Work Completed

- C/c flat front tire. Verify leaking from dry rot. Replace front tire, correct Nitrogen level.
- C/c steering. Remove panel, replace hardware on tilt steering mechanism, reassemble and test drive.
- Shop Supplies

Parts Issued

Quantity

20x11-10 Tires	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 3.00 Comm: 0.00

Labor: 219.00 Parts: 108.88 Total: 327.88

Work Order: 2400269 **Meter:** 968 **In Date:** 01/09/2024 **Closed:** 01/09/2024
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00

Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 84.50

Total Labor: 5,722.75

Total Comm: 0.00

Total Parts: 2,730.69