Palm Beach County Fleet Management Asset Maintenance History
10201851 2016 JACOBSON GROOM MASTER II Ballfield Groomer

Total Hours: 99.75 Labor: 6,830.50 Parts: 4,201.55 Comm: 0.00 Charged: 11032.05

Work Order: 1604679 Meter: 1 In Date: 05/04/2016 Closed: 05/04/2016

Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1609698 Meter: 38 In Date: 09/16/2016 Closed: 10/18/2016

Problem: WONT START

Work Completed

- C/c wont start.set for warranty repairs.ean from Jacobson installed new

ignition under warranty.

Hours: 0.50 Comm: 0.00 Labor: 30.00 Parts: 0.00 Total: 30.00

Work Order: 1705229 Meter: 221 In Date: 05/26/2017 Closed: 06/12/2017

Problem: Pm Service .Three tires

Work Completed	Parts Issued	Quantity
- Pm Service	Napagold Air Filter	1.00
- C/c tires.r/r 3 tires.add N2	Napagold Fuel Filter	1.00
- Inspect and service hyd.system.r/r filter.correct fluid level.	Napagold Oil Filter	1.00
- Wash equipment.	15-40 Oil	3.00
- Shop Supplies	20x11.0	3.00
	Napa Trans Filter	1.00
	Aw68 Bulk Sr	3.00
	15w40 Bulk South Reg	3.00
	Shop Supplies	1.00
Hours: 8.50 Comm: 0.00	Labor: 510.00 Parts: 582.49	Total: 1,092.49

10201851

Palm Beach County Fleet Management Asset Maintenance History 2016 JACOBSON GROOM MASTER II Ballfield Groomer

Work Order: 1706174 Meter: 233 In Date: 06/22/2017 Closed: 06/26/2017

Problem: Loose steering wheel and check for hydraulic oil leak.

Work Completed Parts Issued Quantity

- C/c steering.verify bolt fell out of steering assm.remove covers and repair. Shop Supplies 1.00

- C/c hyd.leak.found fluid level too high.coming out of vent.drain fluid.clean area and test drive.

area and test drive.

- C/c starts intermittently.adjust sensor on traction pedal.

- Shop Supplies

Hours: 5.75 Comm: 0.00 Labor: 345.00 Parts: 2.00 Total: 347.00

Work Order: 1709470 Meter: 285 In Date: 09/28/2017 Closed: 09/29/2017

Problem: Wont stay running.

Work Completed

- C/c wont stay running verify gasolene was added to diesel tank drain

Shop Supplies

1.00

- C/c wont stay running.verify gasolene was added to diesel tank.drain

system flush and test run.

- Shop Supplies

Hours: 3.00 Comm: 0.00 Labor: 180.00 Parts: 2.00 Total: 182.00

Work Order: 1804882 Meter: 439 In Date: 05/10/2018 Closed: 06/26/2018

Problem: P.M.SERVICE, THREE NEW TIRES

Work Completed		Parts Issued	Quantity
- Pm Service.		Keyswitch	1.00
- C/c 3 tires.replace three tires.		Freight	1.00
- C/c Ignition.replace ignition switch.		15w40 Bulk South Reg	3.00
- Service hyd.system.		Napagold Oil Filter	1.00
- Wash equipment.		Napagold Air Filter	1.00
- Shop Supplies		Fuel Filter	1.00
		20x11.0	3.00
		Keyswitch	1.00
		Shop Supplies	1.00
		Freight Charge	1.00
Hours: 8.25	Comm: 0.00	Labor: 495.00 Parts: 661.63	Total: 1,156.63

10201851

Palm Beach County Fleet Management Asset Maintenance History 2016 JACOBSON GROOM MASTER II Ballfield Groomer

Work Order: 1809161 Meter: 526 In Date: 09/06/2018 Closed: 09/18/2018

Problem: Bad battery.

Work CompletedParts IssuedQuantity- C/c Dead battery.test battery bad.replace battery and ckeck charging systemBattery1.00Shop Supplies1.00

- Shop Supplies

Hours: 0.75 Comm: 0.00 Labor: 45.00 Parts: 118.64 Total: 163.64

Work Order: 1810026 Meter: 526 In Date: 09/27/2018 Closed: 09/27/2018

Problem: rake attachment needs weld repair

Work CompletedParts IssuedQuantity- repair and weld brackets on rake attachmentShop Supplies1.00- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1904992 Meter: 721 In Date: 05/08/2019 Closed: 05/30/2019

Problem: No reverse. Key borken in ignition.

Work CompletedParts IssuedQuantity- C/c Key broke off.replace ignition with key.Keyswitch1.00- C/c No Reverse.lubricate all linkages components adjust traction pedal at hyd motor.test run.Shop Supplies1.00- Verify park brake wont hold.adjust linkage.Freight Charge1.00

- Shop Supplies

Hours: 3.50 Comm: 0.00 Labor: 234.50 Parts: 48.46 Total: 282.96

10201851 Palm Beac

Hours: 4.00

Palm Beach County Fleet Management Asset Maintenance History 2016 JACOBSON GROOM MASTER II Ballfield Groomer

Work Order: 1907721 Meter: 735 In Date: 07/25/2019 **Closed:** 07/31/2019 Problem: PM Service. **Parts Issued** Quantity **Work Completed** Napagold Air Filter 1.00 - Pm Service. 1.00 Fuel Filter - Service and inspect hyd.system.replace hyd filter.correct fluid level. 15w40 Bulk South Reg 3.00 - C/c check brake.adjust parking brake. Napagold Oil Filter 1.00 - Wash equipment. Aw68 Bulk Sr 2.00 - Shop Supplies Napa Trans Filter 1.00 **Shop Supplies** 1.00 Hours: 7.25 Comm: 0.00 Parts: 56.64 Labor: 485.75 Total: 542.39 Work Order: 1912217 Meter: 810 In Date: 11/26/2019 Closed: 12/06/2019 Problem: engine smoking, possible over filled oil Quantity **Work Completed Parts Issued** 15-40 Oil 4.00 - change oil level to correct amount. test ran equipment **Shop Supplies** 1.00 - degrease engine compartment - Shop Supplies Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 17.32 Total: 163.32 Work Order: 2006063 Meter: 948 In Date: 06/18/2020 **Closed:** 07/31/2020 Problem: Trottle cabe/linkage. **Work Completed Parts Issued** Quantity Tire 20x11-10 1.00 - Replace front tire, mount and add N2 Throttle Cable Asm 1.00 - Replace trottle cable. Cush Knob 1.00 - Remove battery covers, wash and clean terminals. **Shop Supplies** 1.00 - Shop Supplies

Comm: 0.00

Freight Charge

Labor: 292.00

Parts: 537.31

1.00

Total: 829.31

10201851

Palm Beach County Fleet Management Asset Maintenance History 2016 JACOBSON GROOM MASTER II Ballfield Groomer

Work Order: 2007605 Meter: 948 In Date: 08/03/2020 Closed: 08/17/2020

Problem: PM Service and fuel cap

Work Completed		Parts Issued		Quantity
- Pm Service.		Wd40 Spr		1.00
Service Hyd. System. 71 med. correct hard level.		Fuel Element		1.00
		15w40 Bulk South	Reg	3.00
- Wash equipment.	Napagold Oil Filter Aw68 Bulk Sr		1.00	
- Remove alternator to repair threads on bolt into motor.reinstall and adjust.				
- Shop Supplies		Napa Trans Filter		1.00
		Diesel Fuel Cap		1.00
		Shop Supplies		1.00
		Freight Charge		1.00
Hours: 7.50	Comm: 0.00	Labor: 547.50	Parts: 74.64	Total: 622.14

Work Order: 2009290 Meter: 950 In Date: 09/16/2020 Closed: 09/28/2020

Problem: Will Not Start.

Nork Completed		Parts Issued		Quantity
- C/c will not start.found fuel pump not pumping fu	Napagold Fuel Filt	er	1.00	
pump install in line fuel filter.drain and refill contaminated fuel tank Shop Supplies		Pump Assmb;y Fuel Shop Supplies		1.00
				1.00
		Freight Charge		1.00
Hours: 4.00	Comm: 0.00	Labor: 292.00	Parts: 276.79	Total: 568.79

Palm Beach County Fleet Management Asset Maintenance History 2016 JACOBSON GROOM MASTER II Ballfield Groomer

Problem: PM Service.

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napagold Air Filter		1.00
- Service hydraulic system, replace filter, inspect all correct fluid level.	fluid level.	Napagold Air Filter		1.00
 Wash clay off unit to perform service and repairs. Replace 2 rear tires, mount, add 7 Psi of Nitrogen to all. 		Fuel Element Napagold Fuel Filter		1.00
				1.00
- Shop Supplies		15w40 Bulk South Reg Napagold Oil Filter		3.00
				1.00
		Aw68 Bulk Sr		1.00
		Napa Trans Filter 20x11-10 Tires		1.00
				2.00
		Shop Supplies		1.00
		Tire Disposal Fee		2.00
Hours: 7.50 C	comm: 0.00	Labor: 547.50	Parts: 256.79	Total: 804.29

Work Order: 2109717 Meter: 1175 In Date: 09/07/2021 Closed: 10/07/2021

Problem: Keeps shutting off when grooming. goes really slow, gas pedal may need to adjusted because its really stif

Work Completed		Parts Issued		Quantity
- Verify fuel tank is contaminated, Replace fuel lines and fuel pump, install		Spray Paint		1.00
in line fuel filter.	1 17			1.00
switch on traction pedal, adjust all linkages. Test drive for 1 hr to verify does not shut off		Napagold Fuel Filt	er	1.00
		Fuel Line Hose		3.00
		Fuel Pump		1.00
- Shop Supplies		Shop Supplies		1.00
		Freight Charge		1.00
Hours: 6.00 Cor	mm: 0.00	Labor: 438.00	Parts: 151.19	Total: 589.19

10201851

Palm Beach County Fleet Management Asset Maintenance History 2016 JACOBSON GROOM MASTER II Ballfield Groomer

Work Order: 2201523 Meter: 1300 In Date: 02/10/2022 Closed: 02/11/2022

Problem: Pedal plate bracket broken.

Work CompletedParts IssuedQuantity- Customers complaint bracket for rake is broken. Repair and fabricate rakeShop Supplies1.00

- Customers complaint bracket for rake is broken. Repair and fabricate rak assembly, paint and reassemble. Weld new brackets and re drill mounting holes.

- Shop Supplies

Hours: 3.00 Comm: 0.00 Labor: 219.00 Parts: 2.65 Total: 221.65

Work Order: 2208464 Meter: 1300 In Date: 08/16/2022 Closed: 08/23/2022

Problem: PM Service.

Work Completed	Parts Issued	Quantity
- Pm Service.	Napagold Air Filter	1.00
- Service hydraulic system, replace filter and correct fluid level, inspec	t all. Napagold Air Filter	1.00
- Verify proximity switch for traction pedal is out of adjustment, remo	ve Fuel Element	1.00
sensor, clean connections, reinstall and readjust.	15w40 Bulk South Reg	3.00
- Verify headlight switch is broken. Replace headlight switch.	Napagold Oil Filter	1.00
- Shop Supplies	Aw68 Bulk Sr	3.00
	Napa Trans Filter	1.00
	Rocker Switch On/off	1.00
	Shop Supplies	1.00
Hours: 7.25 Comm: 0.00	Labor: 529.25 Parts: 59.82	Total: 589.07

Work Order: 2303594 Meter: 1373 In Date: 04/11/2023 Closed: 04/20/2023

Problem: Gas pedal need to attached

Work Completed		Parts Issued		Quantity
- C/c gas petal. Verify ball joint fitting ends broke c	gas petal. Verify ball joint fitting ends broke off of traction petal.			2.00
Remove rods, replace two ball joint fittings, adjust linkage and creep. test		Shop Supplies		1.00
drive.		Freight Charge		1.00
- Shop Supplies				
Hours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 106.94	Total: 252.94

10201851

Palm Beach County Fleet Management Asset Maintenance History 2016 JACOBSON GROOM MASTER II Ballfield Groomer

Work Order: 2305012 Meter: 1373 In Date: 05/19/2023 Closed: 06/13/2023

Problem: HYD LEAK

Work Completed		Parts Issued		Quantity
 C/c leaking fluid. Verify lift cylinder is leaking, replace cylinder assembly, top off hydraulic fluid reservoir and test drive. Shop Supplies 		Aw68 Bulk Sr		5.00
		Hyd Cylinder		1.00
		Hyd Cylinder Asm Shop Supplies		1.00
				1.00
		Freight Charge		1.00
Hours: 3.00	Comm: 0.00	Labor: 219.00	Parts: 987.36	Total: 1,206.36

Work Order: 2308329 Meter: 1382 In Date: 08/21/2023 Closed: 08/29/2023

Problem: PM. Handle

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service	Napagold Air Filte	er	1.00	
- Service hydraulic system, replace filter, correct fl	Napagold Air Filte	er	1.00	
		Fuel Element 15w40 Bulk South Reg		1.00 3.00
	Aw68 Bulk Sr Napa Trans Filter Control Valve Handle		2.00	
			1.00	
			1.00	
		Shop Supplies		1.00
Hours: 6.00	Comm: 0.00	Labor: 438.00	Parts: 188.20	Total: 626.20

Work Order: 2309402 Meter: 1399 In Date: 09/15/2023 Closed: 10/04/2023

Problem: Steering not rotation when turning

Work Completed		Parts Issued		Quantity
- C/c steering. Trouble shoot hydraulic system, found cylinder is bypassing		Seal Kit		1.00
internally. Rebuild seal kit on steering cylinder. correct fluid level and test drive.		Shop Supplies		1.00
		Freight Charge		1.00
- Shop Supplies				
Hours: 5.00	Comm: 0.00	Labor: 365.00	Parts: 68.70	Total: 433.70

10201851

Palm Beach County Fleet Management Asset Maintenance History 2016 JACOBSON GROOM MASTER II Ballfield Groomer

Work Order: 2311663 Meter: 1399 In Date: 11/22/2023 Closed: 11/22/2023

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 99.75 Total Labor: 6,830.50 Total Comm: 0.00 Total Parts: 4,201.55