Palm Beach County Fleet Management Asset Maintenance History 2012 GMC SIERRA Pickup, 1/2 Ton, Ext Cab, 4X4 10187839

Total Hours: 168.70	Labor: 10,99	94.50	Parts: 6,379.80 Comm: 4,358.81		Charged: 21733.11			
Work Order: 1207 Problem: instal		Meter:	115		In Date:	08/10/2012	Closed:	08/17/2012
Work Complete	ork Completed			Parts Issued			Qı	uantity
- Parts only				2571 Receiver Lock 5	5/8"			1.00
•	Hours: 0.00		Comm: 0.00	Labor: 0.00	Parts: 10.	26	Total:	10.26
Work Order: 1207 Problem: 1061	-	Meter: spection	129		In Date:	08/10/2012	Closed:	08/10/2012
Work Complete	d							
- Pre Delivery Ins	pection							
·	Hours: 2.00		Comm: 0.00	Labor: 120.00	Parts: 0.0	0	Total:	120.00
Work Order: 1300 Problem: pm s		Meter:	4516		In Date:	01/14/2013	Closed:	01/24/2013
Work Complete	d			Parts Issued			Qı	uantity
- Pm				Filter				1.00
- rear brake serv	ce			Napa Quart 5w30				6.00
	Hours: 3.75		Comm: 0.00	Labor: 225.00	Parts: 27.	26	Total:	252.26
Work Order: 1306 Problem: pm s		Meter:	7855		In Date:	06/25/2013	Closed:	06/28/2013
Work Complete	d			Parts Issued			Qı	uantity
- Pm Service				Napa Quart 5w30				6.00
- Clean And Adj	Rear Brakes			Napagold Oil Filter				1.00
-				Wiper Blade				2.00
	Hours: 3.70		Comm: 0.00	Labor: 222.00	Parts: 34.	02	Total:	256.02
Wanta Ondana 4007	842	Meter:	8523		In Date:	08/06/2013	Closed:	08/06/2013
Work Order: 1307								

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 9.73 Labor: 0.00 Parts: 0.00 Total: 9.73

Palm Beach County Fleet Management Asset Maintenance History 10187839 2012 GMC SIERRA Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 1310831 Meter: 11699 In Date: 10/29/2013 Closed: 10/31/2013

Problem: pm service

 Work Completed
 Parts Issued
 Quantity

 - Pm Service
 Napagold Oil Filter
 1.00

 - Rear Brake Service
 Napa Quart 5w30
 6.00

 Hours: 3.75
 Comm: 0.00
 Labor: 225.00
 Parts: 25.53
 Total: 250.53

Work Order: 1312384 Meter: 12409 In Date: 12/12/2013 Closed: 12/13/2013

Problem: Left front tire flat.

Work Completed

- Repair flat left front tire.nitrogen fill and balance same.

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 0.00 Total: 60.00

Work Order: 1400613 Meter: 13443 In Date: 01/17/2014 Closed: 01/23/2014

Problem: L/R tire flat

Work CompletedParts IssuedQuantity- Mount and Balance 2 tires, nitro fill, reset tire monitor sensorsP265/70r17 Wrangler St2.00- Top off fuelTire Disposal Fee2.00Hours: 2.00Comm: 0.00Labor: 120.00Parts: 450.55Total: 570.55

Work Order: 1400846 Meter: 13443 In Date: 01/17/2014 Closed: 01/27/2014

Problem: flat tire on rear (will tow to fleet)

Work Completed

- Tow From: Se corner of Vista Garage

Hours: 0.00 Comm: 104.15 Labor: 0.00 Parts: 0.00 Total: 104.15

Hours: 5.25

Palm Beach County Fleet Management Asset Maintenance History 10187839 2012 GMC SIERRA Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: Problem:	1402822 pm service	Meter:	15374		In Date:	03/24/2014	Closed:	03/27/2014
Work Com	pleted			Parts Issued			Q	uantity
- Pm				Napagold Oil Filter				1.00
- rear brak	ke service			Napa Quart 5w30				6.00
- rotate, hi	igh speed balance and nitro 4 tires			Napagold Air Filter				1.00
				Accufit Beam				2.00
				Washer Fl				1.00
	Hours: 4.75		Comm: 0.00	Labor: 285.00	Parts: 62.	.58	Total:	347.58
Work Order: Problem:	1406969 PM SERVICE	Meter:	21120		In Date:	07/15/2014	Closed:	07/18/2014
Work Completed				Parts Issued			Q	uantity
- Pm Servi	ce			Napagold Oil Filter				1.00
- Rear Brak	ke Service`			Dexos 5w30 Oil				6.00
	Hours: 3.75		Comm: 0.00	Labor: 225.00	Parts: 39.	.93	Total:	264.93
Work Order: Problem:	1407951 3 - Wash ticket(s) issued	Meter:	22108		In Date:	08/12/2014	Closed:	08/12/2014
Work Com	pleted							
- 3 - Wash	ticket(s) issued							
	Hours: 0.00		Comm: 29.20	Labor: 0.00	Parts: 0.0	00	Total:	29.20
Work Order: Problem:	1412908 pm service	Meter:	25517		In Date:	12/30/2014	Closed:	01/12/2015
Work Com	pleted			Parts Issued			Q	uantity
- Pm Servi	ce			Dexos 5w30 Oil				6.00
- Replace 2	2 tires mount balance nitro			Napagold Oil Filter				1.00
- Service, A	Adjust rear brakes			Accufit Beam				2.00
	-			P265/70r17 Wrangle	er St			2.00
				Tire Disposal Fee				2.00

Comm: 0.00

Labor: 315.00

Parts: 539.56

Total: 854.56

Hours: 0.00

Palm Beach County Fleet Management Asset Maintenance History 10187839 2012 GMC SIERRA Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: Problem:	1505907 pm service	Meter:	28630		In Date:	06/15/2015	Closed:	06/17/2015
Work Com				Parts Issued			Qı	uantity
- Pm				10w30 Motor Oil				6.00
	d Readjust Rear Shoes			Napagold Oil Filter				1.00
Clearit	a Readjust Real Shoes			Wiper Blade				2.00
				Accufit Beam				2.00
	Hours: 3.75		Comm: 0.00	Labor: 225.00	Parts: 59.	37	Total:	284.37
Work Order: Problem:	1506034 1 - Detail Vehicle Wash Ticket(s) Is		28623		In Date:	06/16/2015	Closed:	06/16/2015
Work Com	pleted							
- 1 - Detail	Vehicle Wash Ticket(s) Issued							
	Hours: 0.00		Comm: 96.00	Labor: 0.00	Parts: 0.0	0	Total:	96.00
Work Order: Problem:		Meter:	30170		In Date:	08/12/2015	Closed:	08/18/2015
Work Com	pleted							
- Repair 2 t	ires and relearn sensors mount spa	re under v	ehicle					
·	Hours: 2.00		Comm: 0.00	Labor: 120.00	Parts: 0.0	0	Total:	120.00
	1508118 Flat tire on L/F	Meter:	30058		In Date:	08/11/2015	Closed:	08/12/2015
Work Com	pleted							
- Tire Servi	ce 6200 Lw Rd - Flat tire on L/f							

Comm: 66.34

Labor: 0.00

Parts: 0.00

Total: 66.34

Hours: 0.00

Palm Beach County Fleet Management Asset Maintenance History 10187839 2012 GMC SIERRA Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order:		Meter:	33140		In Date:	11/16/2015	Closed:	11/30/2015
Problem:	pm service							
Work Com	pleted			Parts Issued			Qı	ıantity
- Pm				10w30 Motor Oil				6.00
- Replace b	oth rear wheel brake cylinders bleed	d brake cy	linders. Bleed Brake	Napagold Oil Filter				1.00
sys readjust	drums Flush Master Cyidner-replac	e Fluid		Wheel Cyl 2.00				
- wash veh	cle			B Fluid Dot 3-32oz				1.00
				Brake Cleaner				2.00
	Hours: 5.75		Comm: 0.00	Labor: 345.00	Parts: 151	.19	Total:	496.19
Work Order: Problem:	1511930 1 - Wash ticket(s) issued	Meter:	33303		In Date:	11/23/2015	Closed:	11/23/2015
Work Com	pleted							
- 1 - Wash	ticket(s) issued							
	Hours: 0.00		Comm: 9.54	Labor: 0.00	Parts: 0.00	0	Total:	9.54
Work Order: Problem:	1602685 Left rear tire flat,spare on truck.	Meter:	36010		In Date:	03/14/2016	Closed:	03/17/2016
Work Com	pleted							
- Repair an	d balance left rear tire.							
	Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 0.00	0	Total:	60.00
Work Order: Problem:	1604485 3 - Wash ticket(s) issued	Meter:	37089		In Date:	04/28/2016	Closed:	04/28/2016
Work Com	pleted							

Comm: 28.62

Labor: 0.00

Parts: 0.00

Total: 28.62

Palm Beach County Fleet Management Asset Maintenance History 10187839 2012 GMC SIERRA Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: Problem:	1605098 pm service	Meter:	37795		In Date:	05/17/2016	Closed:	05/27/2016
Work Com	pleted			Parts Issued			Qı	uantity
- Pm				Napagold Oil Filter				1.00
- Repair tra	ailer plug socket			Napagold Oil Filter				1.00
- Clean and	d adjust rear brakes			Accufit Beam				2.00
				Female Conn Socket				1.00
				Brake Cleaner				1.00
				10w30 Motor Oil				6.00
				Dexos 5w30				6.00
	Hours: 5.25		Comm: 0.00	Labor: 315.00	Parts: 111	1.86	Total:	426.86
Work Order: Problem:	1608350 1 - Wash ticket(s) issued	Meter:	41483		In Date:	08/12/2016	Closed:	08/12/2016
Work Com	pleted							
- 1 - Wash	ticket(s) issued							
	Hours: 0.00		Comm: 9.54	Labor: 0.00	Parts: 0.0	0	Total:	9.54
Work Order: Problem:	1609637 pm service	Meter:	43328		In Date:	09/15/2016	Closed:	09/19/2016
Work Com	pleted			Parts Issued			Qı	uantity
- Pm				Napagold Oil Filter				1.00
- Rear brak	ke service			Napa Syn 5w30 Qt				6.00
				Accufit Beam				2.00
	Hours: 3.75		Comm: 0.00	Labor: 225.00	Parts: 66.	03	Total:	291.03
Work Order: Problem:	1611603 crack in left rear light	Meter:	44680		In Date:	11/10/2016	Closed:	11/29/2016
Work Com	pleted			Parts Issued			Qı	uantity
- Replace L	L/r Light Asm Replace strobe ligh	nt and Rewire		Left Rear Light Ass Y				1.00
·				Vtx609c Led Strobe C	21			1.00
	Hours: 1.50		Comm: 0.00	Labor: 90.00	Parts: 283	3.97	Total:	373.97

Palm Beach County Fleet Management Asset Maintenance History 10187839 2012 GMC SIERRA Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 1611793 Meter: 44673 In Date: 11/16/2016 Closed: 11/16/2016

Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 1612742 Meter: 45250 In Date: 12/13/2016 Closed: 12/14/2016

Problem: low tire light on

Work Completed

- Repair L/r Tire

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 0.00 Total: 60.00

Work Order: 1700560 Meter: 46183 In Date: 01/19/2017 Closed: 01/24/2017

Problem: replace hitch

Work CompletedParts IssuedQuantity- Install Hitch and Lock PinsHitch Pin Lock1.00Pintle Pin W/clip1.00

Hours: 0.50 Comm: 0.00 Labor: 30.00 Parts: 16.17 Total: 46.17

02/13/2017 **Closed:** 02/22/2017

In Date:

Problem: pm service

Work Order: 1701509

Work Completed Parts Issued Quantity

Meter: 47200

- Pm Napagold Oil Filter 1.00

- Service rear brakes

Napa Quart 5w30

Accufit Beam

2.00

Washer Fluid Concentr

1.00

Work Order: 1705189 Meter: 49292 In Date: 05/25/2017 Closed: 05/31/2017

Problem: tire light on

Work Completed

- Check over all tires inflate to proper tire pressure

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 0.00 Total: 60.00

Palm Beach County Fleet Management Asset Maintenance History 10187839 2012 GMC SIERRA Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 1705699 Meter: 49783 In Date: 06/08/2017 Closed: 06/13/2017

Problem: WIPER BLADES

 Work Completed
 Parts Issued
 Quantity

 - Wipers replaced
 Accufit Beam
 2.00

 Hours: 0.50
 Comm: 0.00
 Labor: 30.00
 Parts: 25.08
 Total: 55.08

Work Order: 1706494 Meter: 50740 In Date: 06/30/2017 Closed: 06/30/2017

Problem: flat tire

Work Completed

- Repair r/f tire install spare tire

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 0.00 Total: 60.00

Work Order: 1707735 Meter: 52192 In Date: 08/08/2017 Closed: 08/17/2017

Problem: pm service

Work Completed		Parts Issued		Quantity
- pm		P265/70r17sl		2.00
- load test and replace battry		Napa Quart 5w30		
- repalce front brake pads, rotors, and service calipers		Napagold Oil Filte	1.00	
- clean and adjust rear brake		Napagold Air Filte	1.00	
- replace 2 tires, nitro fill and balance 4 tires		Accufit Beam		2.00
		Battery	1.00	
		Disc Pad Brake Rotor Non-chlor Brake Clnr Tire Disposal Fee		1.00
				2.00
				1.00
				2.00
Hours: 10.25	Comm: 0.00	Labor: 615.00	Parts: 760.42	Total: 1,375.42

Palm Beach County Fleet Management Asset Maintenance History 10187839 2012 GMC SIERRA Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 1710514 Meter: 56679 In Date: 10/25/2017 Closed: 10/31/2017

Problem: pm service, headlight out, rear strobes not working

Work Completed		Parts Issued		Quantity
- Pm		Napagold Oil Filte	r	1.00
- Replace 2 tires, nito and balance		Napa Quart 5w30		6.00
- Replace r/side headlight bulb		Accufit Beam		2.00
- Replace r/rear strobe light		Napagold Air Filte	er	1.00
		179535492 Lt265-	70r17	2.00
		Halogen Bulb		1.00
		Vtx609c Led Strob	e Cl	1.00
		P265/70r17sl		2.00
		Tire Disposal Fee	2.00	
Hours: 6.25	Comm: 0.00	Labor: 375.00	Parts: 1,111.96	Total: 1,486.96

Work Order: 1803218 Meter: 59516 In Date: 03/27/2018 Closed: 04/11/2018

Problem: headlight out

Work Completed		Parts Issued		Quantity
- pm service		Napa Syn 5w30 Qt		6.00
- replace front left headlight bulb		Napagold Oil Filter	1.00	
- replace rear brake shoes, wheel cylinders and drums bleed	system and test	22in Exactfit-beam	2.00	
drive		Non-chlor Brake Clnr		
- replace pintle pin		Blister Pack Capsule	1.00	
		Reman Brake Shoes Brake Drum		1.00
				2.00
		Drum Brake Whl Cy	lind	2.00
		Pintle Pin W/clip	1.00	
Hours: 7.75 Co	mm: 0.00	Labor: 465.00	Parts: 279.80	Total: 744.80

Palm Beach County Fleet Management Asset Maintenance History 10187839 2012 GMC SIERRA Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 1806435 Meter: 62720 In Date: 06/25/2018 Closed: 06/27/2018

Problem: check brakes & engine stalls

 Work Completed
 Parts Issued
 Quantity

 - diesel in fuel, flush tank & lines, add fresh fuel
 Spark Plug Asm
 8.00

 - freplace spark plugs
 Startron 8oz Fuel Trt
 1.00

 Hours: 6.00
 Comm: 0.00
 Labor: 360.00
 Parts: 77.84
 Total: 437.84

Work Order: 1806629 Meter: 62761 In Date: 06/22/2018 Closed: 06/28/2018

Problem: brakes went out

Work Completed

- Tow From: military and northlake/marathon station To: 2601 vista

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 1807918 Meter: 63008 In Date: 08/02/2018 Closed: 08/06/2018

Problem: pm/ roaches

Quantity **Work Completed Parts Issued** Napagold Oil Filter 1.00 - pm service Napa Quart 5w30 6.00 - treat for roaches Non-chlor Brake Clnr 1.00 Hours: 3.25 Comm: 0.00 Labor: 195.00 Parts: 30.26 Total: 225.26

Work Order: 1900850 Meter: 66814 In Date: 01/23/2019 Closed: 01/25/2019

Problem: tire light on

Work Completed

- repair tire, reset light

Hours: 1.00 Comm: 0.00 Labor: 67.00 Parts: 0.00 Total: 67.00

Palm Beach County Fleet Management Asset Maintenance History 10187839 2012 GMC SIERRA Pickup, 1/2 Ton, Ext Cab, 4X4

	1900942 pm service	Meter:	66854		In Date:	01/25/2019	Closed:	02/14/2019
Work Com	pleted			Parts Issued			Qı	ıantity
- Pm Servi	ce			Napagold Oil Filter				1.00
- Head ligh	ht restore			Napa Quart 5w30				6.00
- Service re	ear brakes			22in Exactfit-beam				2.00
				Hdlght Clr Coat				1.00
	Hours: 5.25		Comm: 0.00	Labor: 351.75	Parts: 58.	74	Total:	410.49
Work Order: Problem:		Meter:	68026		In Date:	04/01/2019	Closed:	04/04/2019
Work Com	pleted							
- Removed	d and repaired R/f tire; relearned tire	pressures						
	Hours: 1.00		Comm: 0.00	Labor: 67.00	Parts: 0.00	0	Total:	67.00
Work Order:	1904408	Meter:	68175		In Date:	04/23/2019	Closed:	04/29/2019
Problem:	check engine ligt on							
	3 3 3 3							
Work Com				Parts Issued			Qı	ıantity
Work Com		m leak; cl	ean throttle body &				Qı	1.00
Work Com	npleted er scan- P0171 & P0174; repair vacuu	m leak; cl	ean throttle body & Comm: 0.00		Parts: 8.0	7		•
Work Com - Compute mass air flo Work Order:	npleted er scan- P0171 & P0174; repair vacuu ow sensor; clear light and road test Hours: 2.00	m leak; cl	Comm: 0.00	Air Flow Sensor Clnr	Parts: 8.0	7 08/14/2019	Total:	1.00
Work Com - Compute mass air flo Work Order:	er scan- P0171 & P0174; repair vacuu ow sensor; clear light and road test Hours: 2.00 1908496 pm service		Comm: 0.00	Air Flow Sensor Clnr			Total:	1.00
Work Com - Compute mass air flo Work Order: Problem:	er scan- P0171 & P0174; repair vacuu ow sensor; clear light and road test Hours: 2.00 1908496 pm service		Comm: 0.00	Air Flow Sensor Clnr Labor: 134.00			Total:	1.00 142.07 08/26/2019
Work Computer mass air floor Work Order: Problem: Work Com - Pm Service	er scan- P0171 & P0174; repair vacuu ow sensor; clear light and road test Hours: 2.00 1908496 pm service		Comm: 0.00	Air Flow Sensor Clnr Labor: 134.00 Parts Issued			Total:	1.00 142.07 08/26/2019
Work Computer mass air floor work Order: Problem: Work Com - Pm Service - Clean & a	er scan- P0171 & P0174; repair vacuu ow sensor; clear light and road test Hours: 2.00 1908496 pm service hpleted		Comm: 0.00	Air Flow Sensor Clnr Labor: 134.00 Parts Issued Napagold Oil Filter			Total:	1.00 142.07 08/26/2019 nantity 1.00
Work Com - Compute mass air flo Work Order: Problem: Work Com - Pm Servi - Clean & a - Rotate, h	er scan- P0171 & P0174; repair vacuu ow sensor; clear light and road test Hours: 2.00 1908496 pm service hpleted ce adjust rear brakes		Comm: 0.00	Air Flow Sensor Clnr Labor: 134.00 Parts Issued Napagold Oil Filter Napa Quart 5w30			Total:	1.00 142.07 08/26/2019 nantity 1.00 6.00
Work Com - Compute mass air flo Work Order: Problem: Work Com - Pm Servi - Clean & a - Rotate, h	er scan- P0171 & P0174; repair vacuu ow sensor; clear light and road test Hours: 2.00 1908496 pm service hpleted ce adjust rear brakes high speed balance & nitro fill tires pped harness for rear strobe lamps		Comm: 0.00	Air Flow Sensor Clnr Labor: 134.00 Parts Issued Napagold Oil Filter Napa Quart 5w30 22in Exactfit-beam			Total:	1.00 142.07 08/26/2019 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00

Palm Beach County Fleet Management Asset Maintenance History 10187839 2012 GMC SIERRA Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 1911296 Meter: 70143 In Date: 10/30/2019 Closed: 11/13/2019

Problem: had to jump start/ trailer may be draining battery?

Work CompletedParts IssuedQuantity- R/r battery, check for drawBattery1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 144.86 Total: 217.86

Work Order: 2001234 Meter: 71706 In Date: 02/04/2020 Closed: 02/24/2020

Problem: pm service

Work Completed	Work Completed			Quantity
- pm service	Napagold Oil Filte	1.00		
- replace both leaking wheel cylinders, service and bleed system		Napa Quart 5w30	6.00	
		22in Exactfit-beam Drum Brake Whl Cylind		2.00
				2.00
Hours: 5.25	Comm: 0.00	Labor: 383.25	Parts: 104.99	Total: 488.24

Work Order: 2006675 Meter: 76508 In Date: 07/07/2020 Closed: 07/10/2020

Problem: pm service

Work Completed		Parts Issued		Quantity
- pm service		Napagold Oil Filte	1.00	
- rear brake service		Napa Quart 5w30		6.00
- service trailer light on, traced found bad relay		22in Exactfit-beam	ı	2.00
,		Trailer Relay		1.00
Hours: 5.75	Comm: 0.00	Labor: 419.75	Parts: 99.12	Total: 518.87

Palm Beach County Fleet Management Asset Maintenance History 10187839 2012 GMC SIERRA Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 2100877	Meter: 78526	In Date:	01/26/2021 Closed:	02/04/2021
---------------------	--------------	----------	--------------------	------------

Problem: pm/ tire light/ add fuel 350001/ handle broke

Work Completed		Parts Issued		Quantity
 - Preventive Maint. Service - Repair left rear tire - Rotate, high speed balance, and nitro four tires 		Napa Quart 5w30		6.00
		Napagold Oil Filte	r	1.00
		Air Filter Pro Select		1.00
- Rear brake service		Washer Fluid Concentr		1.00
- Repair broken driver door handle and repair door panel		22in Exactfit-beam	2.00	
- Top off loaner		Non-chlor Brake Clnr		1.00
- Replace worn sway bar end links		Sway Bar Links		2.00
		Interior Door Hand	dle	1.00
Hours: 8.75	Comm: 0.00	Labor: 638.75	Parts: 269.12	Total: 907.87

Work Order: 2101335 Meter: 78526 In Date: 02/02/2021 Closed: 02/04/2021

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 2102556 Meter: 79361 In Date: 03/08/2021 Closed: 03/09/2021

Problem: new Fire X and bracket

Work Completed		Parts Issued		Quantity
- Replaced Expired Fire Extinguisher And Bracket		Used Fire X Refur	bished	1.00
		Fire Ext Mount St	rap Style	1.00
Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 27.45	Total: 100.45

Palm Beach County Fleet Management Asset Maintenance History 10187839 2012 GMC SIERRA Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 210775	Meter:	81405	In Date:	07/16/2021 Cl	osed:	08/19/2021
Problem: pm service/ N212328790 - Defect in the passenger-side frontal airbag inflator						
Work Completed		Parts Issued			Qua	antity

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napa Quart 5w30		6.00
- Replace 4 Tires, Nitro Fill, And Balance		Napagold Oil Filte	r	1.00
- Service Rear Brakes		Washer Fluid Con	centr	1.00
- to dealer for N212328790 - Defect in the passenger-s	dealer for N212328790 - Defect in the passenger-side frontal airbag			2.00
inflator		High Gloss Coatin	g	1.00
		P265/70r17 113t Han Dynapro Ht Rh12 Owl Rust Fix		4.00
				1.00
		Tire Disposal Fee		4.00
Hours: 7.75	Comm: 0.00	Labor: 565.75	Parts: 824.93	Total: 1,390.68

Work Order: 2200635 Meter: 84094 In Date: 01/20/2022 Closed: 01/26/2022

Problem: front right light out

Work CompletedParts IssuedQuantity- replace 2 low beams bulbsBlister Pack Capsules2.00Hours: 1.50Comm: 0.00Labor: 109.50Parts: 20.33Total: 129.83

Work Order: 2201308 Meter: 84121 In Date: 02/04/2022 Closed: 03/07/2022

Problem: PM SERVICE

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napa Quart 5w30		6.00
- Rear Brake Service		Napagold Oil Filte	er	1.00
- Roate, High Speed Balance, And Nitro Four Ti	es	Washer Fluid Con-	centr	1.00
- Replace Front Brake Pads, Turn Rotors, And Se	ervice Calipers	22in Exactfit-bean	n	2.00
	·	Used Fire X Refurb	bished	1.00
		Pintle Pin W/clip		1.00
		Brake Pads		1.00
Hours: 8.25	Comm: 0.00	Labor: 602.25	Parts: 158.63	Total: 760.88

Palm Beach County Fleet Management Asset Maintenance History 10187839 2012 GMC SIERRA Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 2202478 Meter: 84130 In Date: 03/04/2022 Closed: 03/07/2022

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 90.40 Labor: 0.00 Parts: 0.00 Total: 90.40

Work Order: 2203015 Meter: 84212 In Date: 03/18/2022 Closed: 03/28/2022

Problem: ABS and traction light on

Work Completed Parts Issued Quantity

- Scanned Dtcs C0050, Replaced Right Rear Speed Sensor

Sensor

1.00

Hours: 1.50 Comm: 0.00 Labor: 109.50 Parts: 42.80 Total: 152.30

Work Order: 2207986 Meter: 86104 In Date: 06/02/2022 Closed: 08/04/2022

Problem: Damage to right side of bed

Work CompletedParts IssuedQuantity- Damage to right side of bed4x4 Decal1.00

- Shop Supplies Shop Supplies 1.00

Hours: 0.00 Comm: 3,536.90 Labor: 0.00 Parts: 80.79 Total: 3,617.69

Work Order: 2208719 Meter: 86733 In Date: 08/19/2022 Closed: 08/19/2022

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued to: TOM LILLY

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued to: Tom Lilly

Hours: 0.00 Comm: 90.40 Labor: 0.00 Parts: 0.00 Total: 90.40

Work Order: 2208754 Meter: 86748 In Date: 08/22/2022 Closed: 08/31/2022

Problem: pm service

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	Napa Quart 5w30	6.00
- Performed Rear Brake Service	Napagold Oil Filter	1.00
- Replaced Corroded Trailer Plug	Washer Fluid Concentr	1.00
	22in Exactfit-beam	2.00
	trailer plug	1.00

Hours: 5.25 Comm: 0.00 Labor: 383.25 Parts: 59.48 Total: 442.73

Palm Beach County Fleet Management Asset Maintenance History 10187839 2012 GMC SIERRA Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 2209167 Meter: 86765 In Date: 08/31/2022 Closed: 09/02/2022

Problem: FUEL FILLER CAME LOOSE

Work Completed

- Re-installed Fuel Filler Neck

Hours: 0.50 Comm: 0.00 Labor: 36.50 Parts: 0.00 Total: 36.50

Work Order: 2305418 Meter: 90720 In Date: 06/01/2023 Closed: 06/06/2023

Problem: pm service

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service - service rear brakes - clean n readjust Napa Quart 5w30		r	1.00	
		Napa Quart 5w30		6.00
		Washer Fluid Concentr		1.00
		22in Exactfit-beam	ı	2.00
Hours: 3.75	Comm: 0.00	Labor: 273.75	Parts: 53.26	Total: 327.01

Work Order: 2307990 Meter: 91899 In Date: 08/10/2023 Closed: 08/16/2023

Problem: tail light bulb wire hanging/ ac inop

Work Completed		Parts Issued		Quantity
- Replaced Tag Light Housings And Bulbs		Boxed Miniatures		2.00
- Performed Evac And Recharge W/ Dye, Ran For 3	30 Mins, No Leaks Found	Ac Uv Dye 5 Shot		1.00
At This Time				1.00
		License Plate Lens		2.00
Hours: 2.50	Comm: 0.00	Labor: 182.50	Parts: 52.82	Total: 235.32

Palm Beach County Fleet Management Asset Maintenance History 10187839 2012 GMC SIERRA Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 2311484 Meter: 94650 In Date: 11/16/2023 Closed: 11/22/2023

Problem: pm service

Work Completed		Parts Issued	Quantity
- Preventive Maint. Service		Napa Quart 5w30	6.00
- Service Rear Brakes		Napagold Oil Filter	1.00
		Washer Fluid Concentr	1.00
		22" Wiper Blade	2.00
		Used Fire X Refurbished	1.00
		Repel Wiper Blade 22	2.00
Hours: 3.75	Comm: 0.00	Labor: 273.75 Parts: 83.82	Total: 357.57

Work Order: 2401281 Meter: 95307 In Date: 02/05/2024 Closed: 02/05/2024

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 168.70 Total Labor: 10,994.50 Total Comm: 4,358.81 Total Parts: 6,379.80