

3/2/2017
10:38:27AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10194210 2014 CLUB CAR CARRYALL 295 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Workorder: 1402090

Problem: install hitch ext

Meter Reading: 1 In Date: 03/04/2014	Close Date: 03/06/2014	Labor Hours	Description	Parts	Quantity
- Install Hitch Ext			RECEIVER EXTENSION		1.00
- Shop Supplies			PIN W/CLIP 5/8 FOR HITCH		2.00
			SHOP SUPPLIES		1.00
			BALL MOUNT 3/4"		1.00
Parts Charge: 96.00		Labor Charge: 0.00			

Workorder: 1402111

Problem: 1061 - Pre Delivery Inspection

Meter Reading: 1 In Date: 03/04/2014	Close Date: 03/04/2014	Labor Hours	Description	Parts	Quantity
- Pre Delivery Inspection		2.00			
Parts Charge: 0.00		Labor Charge: 120.00			

Workorder: 1410874

Problem: pm/ check clutch/ tail light/ parking brake/ see notes

Meter Reading: 683 In Date: 10/30/2014	Close Date: 12/09/2014	Labor Hours	Description	Parts	Quantity
- Pm		15.00	NAPAGOLD AIR FILTER		1.00
- Replace Left And Right Outer Cv Boots			NAPAGOLD OIL FILTER		1.00
- Replace 2 Tires			15-40 OIL		3.00
- Replace Frt Pads-Replace Rear Pads And Rotors-Replace R/Side Park Brake And Adj Straightened R/Side Caliper Support			BRAKE ROTOR		2.00
			TAIL LIGHT ASM		1.00
			FUEL FILTER		1.00
- Replace R/Tail Lamp Assembly			295 REAR BRAKE PAD KIT		2.00
- Shop Supplies			UNITRAC FLUID PINT QTY		2.00
			RH PARKING BRAKE CABLE		1.00
			L/F OUTER CV BOOT		2.00
			MOBIL 424 FLUID		2.00
			25X11.00-12 ALL TRAIL TIRE 4P		2.00
			SHOP SUPPLIES		1.00
			TIRE DISPOSAL FEE		2.00
Parts Charge: 942.17		Labor Charge: 900.00			

3/2/2017
10:38:27AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10194210 2014 CLUB CAR CARRYALL 295 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Workorder: 1412118 **Problem:** transmission slips

Meter Reading: 683		Labor	Parts
In Date: 12/03/2014	Close Date: 12/09/2014	Hours	

- To Hector Turf For Rear End Warranty			
	Parts Charge: 0.00	Labor Charge: 0.00	

Workorder: 1500659 **Problem:** install windshield kit

Meter Reading: 861		Labor	Parts
In Date: 01/20/2015	Close Date: 04/27/2015	Hours	

- Install Windshield Kit		1.00	SHOP SUPPLIES	1.00
- Shop Supplies			FOLD-DOWN WINDSHIELD KIT	1.00
	Parts Charge: 237.61	Labor Charge: 60.00		

Workorder: 1504013 **Problem:** pm service/ light out

Meter Reading: 864		Labor	Parts
In Date: 04/17/2015	Close Date: 05/11/2015	Hours	

- Pm		8.50	NAPAGOLD AIR FILTER	1.00
- Replace L/Outer Cv Boot			NAPAGOLD OIL FILTER	1.00
- Replace 2 Tires			FUEL FILTER	1.00
- Repair Rear Lights			MOBIL 424 FLUID	2.00
- Shop Supplies			L/F OUTER CV BOOT	1.00
			25 X 11.00 X 12 TIRE KENDA	2.00
			15-40 OIL	3.00
			TIRE DISPOSAL FEE	2.00
			SHOP SUPPLIES	1.00
	Parts Charge: 571.05	Labor Charge: 510.00		

Workorder: 1504101 **Problem:** rear end locks after warmed up/ steering problem

Meter Reading: 862		Labor	Parts
In Date: 04/21/2015	Close Date:	Hours	

-				
	Parts Charge: 0.00	Labor Charge: 0.00		

3/2/2017
10:38:27AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10194210 2014 CLUB CAR CARRYALL 295 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Workorder: 1508331

Problem: rear light out, drive shaft bad shape, park brake not holding, horn not working, strg wheel adjustme

Meter Reading: 864	Labor	Parts	
In Date: 08/19/2015	Hours	Description	Quantity
- Replace Coolant Pipes And Undercoat New Pipes And Fill With Coolant	14.00	SHOP SUPPLIES	1.00
		RUBBERIZED UNDERCOAT	1.00
- Replace Front And Rear Brakes And Adjust		PEAK GLOBAL	1.00
- Replace Both Front Outside Axle Boots		LOCKNUT	3.00
- Replace Rear Tail Light Bulb		HORN	1.00
- Diagnose Horn Not Working Replaced Horn		MOBIL 424 FLUID	4.00
- Replace Front Driveshaft		BRAKE ROTOR	4.00
- Drivetrain Service		295 REAR BRAKE PAD KIT	2.00
- Coat Underside With Ospho		L/F OUTER CV BOOT	2.00
- Shop Supplies		BULB	1.00
		BRAKE CLEANER	2.00
		COOLANT PIPES	1.00
		RUST CONDITIONER	1.00
		Freight Charge	1.00
		RONT DRIVE SHAFT	1.00
Parts Charge:	1,114.83	Labor Charge:	840.00

Workorder: 1509877

Problem: starter clicking, park brake not working, check coolant pipes for rust

Meter Reading: 1162	Labor	Parts	
In Date: 09/29/2015	Hours	Description	Quantity
- Adjust Parking Brakes	3.00	STARTER	1.00
- Test And Replace Starter		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	313.36	Labor Charge:	180.00

3/2/2017
10:38:27AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10194210 2014 CLUB CAR CARRYALL 295 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Workorder: 1601720

Problem: pm service, shift cable broken, tires worn, tail light broken

Meter Reading: 1411	Labor	Parts	
In Date: 02/18/2016	Hours	Description	Quantity
- Pm W/Drive Train Service	17.70	windshield clip	1.00
- Replace Front And Rear Brake Pad And Rotors. Lube Caliper And Cables		Freight Charge	1.00
- Replace Shifter Cable		SHOP SUPPLIES	1.00
- Replace 4 Tires		NAPAGOLD OIL FILTER	1.00
- Replace Front Drive Shaft		25 X 11.00 X 12 TIRE KENDA	4.00
- Check Electrical Sys Replace Battery		BRAKE ROTOR	4.00
- Replace Windshield Mount		propshaft	1.00
- Wash Vehicle And Apply Rubberized Undercoat		BRAKE CLEANER	1.00
- Fabricate And Install Rear Tail Light Brackets And New Lights		TAIL LIGHT ASM	2.00
- Shop Supplies		MOBIL 424 FLUID	4.00
		TIRE DISPOSAL FEE	4.00
		15-40 OIL	3.00
		TRANS SHIFT CABLE	1.00
		BATTERY	1.00
		FUEL FILTER	1.00
		RUBBERIZED UNDERCOAT	2.00
		295 REAR BRAKE PAD KIT	2.00
		RUST CONDITIONER	1.00
		NAPAGOLD AIR FILTER	1.00
Parts Charge:	1,978.80	Labor Charge:	1,062.00

3/2/2017
10:38:27AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10194210 2014 CLUB CAR CARRYALL 295 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Workorder: 1606205

Problem: RF noise/ E brake/ check rear end/ see notes

Meter Reading: 1635 In Date: 06/16/2016	Close Date: 07/11/2016	Labor Hours	Description	Parts	Quantity
- Power Train Service, Service Engine		21.50	SHOP SUPPLIES		1.00
- Replace Both Front Axles Repalce Front Differential Due To Corrosion			MOBIL 424 FLUID		4.00
			NAPAGOLD OIL FILTER		1.00
- R&R Both Rear Axle Housing To Disassemble And Replace Both Rear Wheel Bearings, 1 Axle Shaft And 1 Wheel Hub			FRONT HALFSHAFT AWD		2.00
			FUEL FILTER		1.00
			differential		1.00
- Adj Parking Brake			RING RETAINING		2.00
			BEARINGS		2.00
- Shop Supplies			WHEEL HUB		1.00
			RETAINING RING		2.00
			WASHER		1.00
			RH AXLE		1.00
			15-40 OIL		3.00
Parts Charge:		2,757.56	Labor Charge:		1,290.00

Workorder: 1700436

Problem: Transition Prep Charge

Meter Reading: 1635 In Date: 01/13/2017	Close Date: 01/13/2017	Labor Hours	Description	Parts	Quantity
- Transition Prep Charge		2.00			
Parts Charge:		0.00	Labor Charge:		120.00

Total Parts Charges:	8,011.38	Total Labor Charges:	5,082.00	Total Comm. Charges:	0.00
----------------------	-----------------	----------------------	-----------------	----------------------	-------------