- Shop Supplies

Hours: 7.00

Comm: 0.00

Palm Beach County Fleet Management Asset Maintenance History 10182382 2010 FELLING FT10DT TRAILER, DUMP, 12,980 GVWR, 2 AXLE

Total Hours: 124.50 Charged: 14377.30 Labor: 8,212.00 Parts: 5,891.66 Comm: 273.65 Work Order: 1010973 Meter: 0 10/05/2010 Closed: 10/05/2010 In Date: **Problem:** Pre Delivery Inspection **Work Completed** - Pre Delivery Inspection Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00 Work Order: 1111817 Meter: 0 11/02/2011 **Closed**: 11/03/2011 In Date: Problem: pm service Quantity **Work Completed Parts Issued** 1.00 Shop Supplies - P.m. 42385 Seal 4.00 - Nitro Tires 09997 Brake Clean 1.00 - R&r Brake away switch 004098 Breakaway Switch 1.00 - Shop Supplies Hours: 6.00 Comm: 0.00 Labor: 360.00 Total: 378.23 Parts: 18.23 Work Order: 1204464 05/02/2012 **Closed**: 05/10/2012 Meter: 0 In Date: Problem: rr flat **Work Completed** - Tire Service 12500 40th lox - rr flat Parts: 0.00 Hours: 0.00 Comm: 60.00 Labor: 0.00 Total: 60.00 Work Order: 1300891 Meter: 0 In Date: 01/25/2013 **Closed**: 01/31/2013 Problem: pm service **Parts Issued** Quantity **Work Completed Brake Cleaner** 1.00 - Pm Trailer 45896 Grease Cap 4.00 - Service hyd system Aw68 Hydro Fluid Hydr 10.00 - Charge and test battery 4086 Switch Cable 1.00 - Clean and readjust all four wheel drum brakes and repalce trailer brake away unit rewire **Shop Supplies** 1.00

Labor: 420.00

Parts: 43.79

Total: 463.79

Palm Beach County Fleet Management Asset Maintenance History 10182382 2010 FELLING FT10DT TRAILER, DUMP, 12,980 GVWR, 2 AXLE

Work Order: 1306955 Meter: 0 In Date: 07/12/2013 Closed: 07/15/2013

Problem: trailer pigtail

Work Completed		Parts Issued		Quantity
- Replace male connector to trailer		Trailer Conn Plug		1.00
- Shop Supplies		Shop Supplies		1.00
Hours: 1.50	Comm: 0.00	Labor: 90.00	Parts: 7.90	Total: 97.90

Work Order: 1312008 Meter: 0 In Date: 12/02/2013 Closed: 12/18/2013

Problem: dump inop/ wire harness burned

Work Completed		Parts Issued		Quantity
- Pm Service		42385 Seal		4.00
- Diagnose burned wires rewire trailer. replace	male trailer plug rewire trailer	Brake Cleaner		1.00
replace all burned wiring	, -	Bulk Trailer Wire		21.00
- Hydro service		Trailer Conn Plug		1.00
- Charge battery repalce hold down		Vinyl Electrical Tap	pe	1.00
- Clean readjust all drums and shoes replace br	ake away unit	Aw68 Hydro Fluid Hydr		5.00
- Shop Supplies		Tarp Fas		2.00
		Break Away		1.00
		Grease Cap		4.00
		Shop Supplies		1.00
Hours: 11.00	Comm: 0.00	Labor: 660.00	Parts: 97.63	Total: 757.63

Work Order: 1400389 Meter: 0 In Date: 01/13/2014 Closed: 01/23/2014

Problem: not working/ check battery

Work Completed		Parts Issued		Quantity
- Test Charge amd replace Battery		Group 31 Stud De	elco	1.00
- Shop Supplies		Shop Supplies		1.00
Hours: 1.00	Comm: 0.00	Labor: 60.00	Parts: 135.19	Total: 195.19

Palm Beach County Fleet Management Asset Maintenance History 10182382 2010 FELLING FT10DT TRAILER, DUMP, 12,980 GVWR, 2 AXLE

Work Order: 1412854 Problem: pm service/ brake cable needs r	Meter: 0 eplaced/ defective electric cabl	e	In Date:	12/29/2014	Closed:	01/12/2015
Work Completed		Parts Issued			Qı	uantity
- Pm		Seal 2.250x3.371x.375	5			4.00
- Replace trailer plug		Trailer Conn Plug				1.00
- Replaced breakaway switch and cable and	repair broken feed wire to	Breakaway Switch				1.00
breakaway switch		762173406 225-75r1	5			2.00
- Replace 2 tires and Nitro		Shop Supplies				1.00
- Shop Supplies		Tire Disposal Fee				2.00
Hours: 8.50	Comm: 0.00	Labor: 510.00	Parts: 329	9.43	Total:	839.43
Work Order: 1500281 Problem: tailgate bent/ wont close	Meter: 0		In Date:	01/08/2015	Closed:	02/19/2015
Work Completed		Parts Issued			Qı	uantity
- Replace bent tailgate and straighten traile	r box and fabricate lock pin	Tailgate Asm				1.00
- Repalce max load sticker		Shop Supplies				1.00
- Shop Supplies		Freight Charge				1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 814	4.87	Total:	994.87
Work Order: 1509572 Problem: slow lifting, possible battery	Meter: 0		In Date:	09/22/2015	Closed:	09/24/2015
Work Completed		Parts Issued			Qı	uantity
		Group 31 Stud Delco				1.00
 Test Batery and test charging sys replace t 	pattery					
 Test Batery and test charging sys replace be Shop Supplies 	pattery	Shop Supplies				1.00

Palm Beach County Fleet Management Asset Maintenance History 10182382 2010 FELLING FT10DT TRAILER, DUMP, 12,980 GVWR, 2 AXLE

Work Order: 1607696 Meter: 0 In Date: 07/27/2016 Closed: 08/09/2016

Problem: pm/ hydraulic hose leaking

Work Completed		Parts Issued		Quantity
- Pm		Seal 2.250x3.371x.3	375	4.00
- replace hyd pumpt reservoir and seal replace hyd hoses	sevice pump	Grease Cap		2.00
- replace (2) tires		762173406 225-75	5r15	2.00
- Replace trialer plug and trailer harness		Tr416 Valve Stem		2.00
- Replace brake away unit; Service all brakes		Trailer Conn Plug		1.00
- Shop Supplies		Breakaway Switch		1.00
		Hose Made		1.00
		Bulk Trailer Wire		7.00
		Aw68 Hydro Fluid I	Hydr	8.00
		Hyd Pump Resevio	r	1.00
		Breather W/dipstic	k	1.00
		Reseervoir O Ring		1.00
		Shop Supplies		1.00
		Tire Disposal Fee		2.00
		Freight Charge		1.00
Hours: 12.50	Comm: 0.00	Labor: 750.00	Parts: 602.26	Total: 1,352.26

Work Order: 1704722 Meter: 0 In Date: 05/11/2017 Closed: 05/22/2017

Problem: pm/ dump wont lift

Work Completed		Parts Issued	Quantity
- pm service		Seal 2.250x3.371x.375	4.00
- replace r/r marker light and gromet			1.00
- replace trailer plug		Grommet	
- replace I/r tire and nitro		Male Trailer Connector	1.00
- charged and test battery for dump bed - ok		762173406 225-75r15	1.00
- Shop Supplies		Tr416 Valve Stem	1.00
		Shop Supplies	1.00
		Tire Disposal Fee	1.00
Hours: 8.00	Comm: 0.00	Labor: 480.00 Parts: 176.19	Total: 656.19

Hours: 0.50

Palm Beach County Fleet Management Asset Maintenance History 10182382 2010 FELLING FT10DT TRAILER, DUMP, 12,980 GVWR, 2 AXLE

Work Order: 1803893 Meter: 0 04/13/2018 **Closed:** 04/23/2018 In Date: Problem: dump wont go up after charging battery all weekend Parts Issued Quantity **Work Completed** Group 31 Stud Delco 1.00 - test and replace battery, charger and check wiring to trailer plug 1.00 **Battery Charger** - Shop Supplies **Shop Supplies** 1.00 Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 185.75 Total: 305.75 Work Order: 1901912 Meter: 0 In Date: 02/20/2019 **Closed:** 02/28/2019 Problem: pm service Quantity **Parts Issued Work Completed** Seal 2.250x3.371x.375 4.00 - Pm Male Trailer Connector 1.00 - Replace Trailer plug St225/75r15 Carlisle Load-d 1.00 - Replace 1 Tire & Nitro Tr416 Valve Stem 1.00 - Replace Safety chains and repair foot on jack **Shop Supplies** 1.00 - Fabricate breakaway cable Tire Disposal Fee 1.00 - Shop Supplies Hours: 8.50 Comm: 0.00 Labor: 569.50 Parts: 150.07 Total: 719.57 Work Order: 1910470 Meter: 0 In Date: 10/07/2019 **Closed**: 10/09/2019 Problem: flat tire **Work Completed** - Tire Service Nroc 12500 40th st Rpb - flat tire Comm: 51.56 Labor: 0.00 Parts: 0.00 Hours: 0.00 Total: 51.56 Work Order: 1910588 Meter: 0 **In Date:** 10/15/2019 **Closed:** 10/18/2019 Problem: needs breakaway cable **Work Completed** - Replace breakaway cable

Comm: 0.00

Labor: 36.50

Parts: 0.00

Total: 36.50

Palm Beach County Fleet Management Asset Maintenance History 10182382 2010 FELLING FT10DT TRAILER, DUMP, 12,980 GVWR, 2 AXLE

Work Order: 2000145 Meter: 0 In Date: 01/03/2020 Closed: 01/06/2020

Problem: Flat tire on D/R

Work Completed

- Tire Service 12500 40th Street North - Flat tire on D/r

Hours: 0.00 Comm: 67.16 Labor: 0.00 Parts: 0.00 Total: 67.16

Work Order: 2000165 Meter: 0 In Date: 01/07/2020 Closed: 01/09/2020

Problem: 1 new tire

Work Completed		Parts Issued		Quantity
- parts only		St225/75r15 Nat	ional Road Max	1.00
- Shop Supplies		Shop Supplies		1.00
		Tire Disposal Fee	2	1.00
Hours: 0.00	Comm: 0.00	Labor: 0.00	Parts: 89.16	Total: 89.16

Work Order: 2009195 Meter: 0 In Date: 09/14/2020 Closed: 11/17/2020

Problem: pm/ tailgate/ battery box/ tires/ see notes

Work Completed		Parts Issued		Quantity
- preventive maintance service		Seal 2.250x3.371x.3	375	4.00
- replace damaged tailgate		St225/75r15 Carlisl	e Load-d	3.00
- repair battery box to lock latch. install registra	ation holder.	Tr416 Valve Stem		3.00
- replace 3 tires and nitro fill		Breakaway Switch		1.00
- service all brakes. replace brake away switch a	and rewire harness to battery	Non-chlor Brake Cl	nr	2.00
box.		Male Trailer Conne	ctor	1.00
- replace trailer plug and running lights.		Led S T T Kit		2.00
- replace side decals and max load		Document Holder		1.00
- Shop Supplies		Trailer Door		1.00
		Shop Supplies		1.00
		Tire Disposal Fee		3.00
Hours: 16.00	Comm: 0.00	Labor: 1,168.00	Parts: 2,168.31	Total: 3,336.31

Palm Beach County Fleet Management Asset Maintenance History 10182382 2010 FELLING FT10DT TRAILER, DUMP, 12,980 GVWR, 2 AXLE

Work Order: 2102666 Meter: 0 In Date: 03/09/2021 Closed: 04/02/2021

Problem: dump bed inop

Work CompletedParts IssuedQuantity- test battery - replace battery n clean connection - test hydro systemBattery1.00- Shop SuppliesShop Supplies1.00Hours: 1.50Comm: 0.00Labor: 109.50Parts: 189.43Total: 298.93

Work Order: 2104182 Meter: 0 In Date: 04/14/2021 Closed: 04/19/2021

Problem: wont raise

Work Completed Parts Issued Quantity Male Trailer Connector 1.00 - replace 12v charger - charge battery **Battery Charger** 1.00 - replace trailer plug 1.00 **Shop Supplies** - Shop Supplies Hours: 3.00 Comm: 0.00 Labor: 219.00 Parts: 64.62 Total: 283.62

Work Order: 2107946 Meter: 0 In Date: 07/22/2021 Closed: 07/28/2021

Problem: Hydraulic Cap Broken

Work Completed		Parts Issued		Quantity
- Replace hydraulic pump down valve dual action coil ,	cap and fill with	Aw68 Hydro Fluid	Hydr	4.00
fluid. test run ok.		Kti 10v Valve Sole	noid	1.00
- Shop Supplies		Kti Hydro Filler Ca	р	1.00
		Shop Supplies		1.00
		Freight Charge		1.00
Hours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 74.42	Total: 220.42

Palm Beach County Fleet Management Asset Maintenance History 10182382 2010 FELLING FT10DT TRAILER, DUMP, 12,980 GVWR, 2 AXLE

Vork Order: 211 Problem: Rep		Meter: 0 t close it. be replaced this year		In Date:	10/22/2021	Closed:	11/30/202
Work Complet	ed		Parts Issued			Qı	uantity
- Pm Service			Seal 2.250x3.371x.	375			4.00
- Straighten Oເ	ut Tail Gate So It Can Be Op	pened And Closed Properly	Non-chlor Brake C	Inr			1.00
- Replaced Cor	roded Trailer Plug, Replace	d 2 Faulty Led Side Marker Lights	Male Trailer Connector			1.00	
Load Test Trailer Battery FailedDegrease Inside Tool Box		Group 31 Stud De	lco			1.00	
		Led M C Gromme	t Kit			2.00	
_		n, Rewire Switch To Battery Box	Breakaway Switch				1.00
- Repaired 1 Ti		•	Shop Supplies				1.00
- Shop Supplie	S						
	Hours: 12.50	Comm: 0.00	Labor: 912.50	Parts: 181	1.96	Total:	1,094.46
Vork Order: 220 Problem: Tra		Meter: 0 eeds tailgate repair or replace		In Date:	03/07/2022	Closed:	04/06/202
Problem: Tra Work Complet - Diagnos Traile Cleaned Conne	iler will not come down / ne ed er Won't Come Down, Test ctions And Repaired Wire H		Parts Issued Shop Supplies	In Date:	03/07/2022		04/06/202 uantity 1.00
Problem: Tra Work Complet - Diagnos Traile Cleaned Connec Are Now Opera	iler will not come down / ne ed er Won't Come Down, Test ctions And Repaired Wire F ting Normally	eeds tailgate repair or replace All Wiring, Take Apart Controller, Harness, Test Dump Operations	1 41 45 15541541	In Date:	03/07/2022		uantity
Problem: Tra Work Complet - Diagnos Traile Cleaned Connec Are Now Opera - Repaired Taile	iler will not come down / ne ed er Won't Come Down, Test ctions And Repaired Wire F ting Normally gate To Allow It To Close Pi	eeds tailgate repair or replace All Wiring, Take Apart Controller, Harness, Test Dump Operations	1 41 45 15541541	In Date:	03/07/2022		uantity
Problem: Tra Work Complet - Diagnos Traile Cleaned Connec Are Now Opera	iler will not come down / ne ed er Won't Come Down, Test ctions And Repaired Wire F ting Normally gate To Allow It To Close Pi	eeds tailgate repair or replace All Wiring, Take Apart Controller, Harness, Test Dump Operations	1 41 45 15541541	In Date:		Qı	uantity
Problem: Tra Work Complet - Diagnos Traile Cleaned Connec Are Now Opera - Repaired Taile - Shop Supplie	ed er Won't Come Down, Test ctions And Repaired Wire H ting Normally gate To Allow It To Close Pr s Hours: 4.00	All Wiring, Take Apart Controller, Harness, Test Dump Operations roperly Comm: 0.00 Meter: 0	Shop Supplies			Q ı Total:	uantity 1.00
Problem: Tra Work Complet - Diagnos Traile Cleaned Connect Are Now Opera - Repaired Taile - Shop Supplie	ed er Won't Come Down, Test ctions And Repaired Wire F ting Normally gate To Allow It To Close Pi s Hours: 4.00	All Wiring, Take Apart Controller, Harness, Test Dump Operations roperly Comm: 0.00 Meter: 0	Shop Supplies	Parts: 2.6	5	Total:	1.00 294.65
Problem: Tra Work Complete - Diagnos Traile Cleaned Connect Are Now Opera - Repaired Taile - Shop Supplie Vork Order: 220 Problem: report	ed er Won't Come Down, Test ctions And Repaired Wire Hing Normally gate To Allow It To Close Proses Hours: 4.00 17938 lace RF tire set up for 7/27	All Wiring, Take Apart Controller, Harness, Test Dump Operations roperly Comm: 0.00 Meter: 0	Shop Supplies Labor: 292.00	Parts: 2.6 In Date:	5	Total:	1.00 294.65 08/02/202
Problem: Tra Work Complete - Diagnos Traile Cleaned Connect Are Now Opera - Repaired Taile - Shop Supplie Vork Order: 220 Problem: report	ed er Won't Come Down, Test ctions And Repaired Wire Hing Normally gate To Allow It To Close Proses Hours: 4.00 17938 lace RF tire set up for 7/27	All Wiring, Take Apart Controller, Harness, Test Dump Operations roperly Comm: 0.00 Meter: 0 am	Shop Supplies Labor: 292.00 Parts Issued	Parts: 2.6 In Date:	5	Total:	294.65 08/02/202
Problem: Tra Work Complete - Diagnos Traile Cleaned Connect Are Now Opera - Repaired Taile - Shop Supplie Vork Order: 220 Problem: rep Work Complete - Tire Service: 1	ed er Won't Come Down, Test ctions And Repaired Wire Hing Normally gate To Allow It To Close Proses Hours: 4.00 17938 lace RF tire set up for 7/27	All Wiring, Take Apart Controller, Harness, Test Dump Operations roperly Comm: 0.00 Meter: 0 am	Shop Supplies Labor: 292.00 Parts Issued Callaghan Tire #10	Parts: 2.6 In Date:	5	Total:	294.65 08/02/202
Problem: Tra Work Complete - Diagnos Traile Cleaned Connect Are Now Opera - Repaired Taile - Shop Supplie Vork Order: 220 Problem: repl Work Complete - Tire Service: 1 7/27 am	ed er Won't Come Down, Test ctions And Repaired Wire F ting Normally gate To Allow It To Close Pr s Hours: 4.00 17938 lace RF tire set up for 7/27 ed	All Wiring, Take Apart Controller, Harness, Test Dump Operations roperly Comm: 0.00 Meter: 0 am	Shop Supplies Labor: 292.00 Parts Issued Callaghan Tire #10	Parts: 2.6 In Date:	5	Total:	294.65 08/02/202

Palm Beach County Fleet Management Asset Maintenance History 10182382 2010 FELLING FT10DT TRAILER, DUMP, 12,980 GVWR, 2 AXLE

Work Order: 2208984 Meter: 0 In Date: 08/26/2022 Closed: 11/08/2022

Problem: Will not dump

Work Completed		Parts Issued		Quantity
Trydraume Furnip 25W 5TT Furd. Top Furd. 7 The Critical Furnity Control of Co		Aw68 Hydro Fluid Hydr		4.00
ring And Tank. Replace Tank With Seal		Reseervoir O Ring		1.00
- Replace Brake Away Cable.service Bra	kes	Hyd Pump Resevior		1.00
- Pm Service		Non-chlor Brake C	Clnr	2.00
- Replace Tire		Seal 2.250x3.371x.	.375	4.00
- Replace Trailer Plug		St225/75r15 Carlis	sle Load-d	1.00
- Shop Supplies		Tr416 Valve Stem		1.00
		Plug		1.00
		Grease Cap		4.00
		Shop Supplies		1.00
		Tire Disposal Fee		1.00
		Freight Charge		1.00
Hours: 11.00	Comm: 0.00	Labor: 803.00	Parts: 256.49	Total: 1,059.49

Work Order: 2400358 Meter: 0 In Date: 01/10/2024 Closed:

Problem: PM/ comments

Work Completed

- Preventive Maint. Service

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

Work Order: 2401092 Meter: 0 In Date: 01/30/2024 Closed: 01/30/2024

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 124.50 Total Labor: 8,212.00 Total Comm: 273.65 Total Parts: 5,891.66