

3/2/2017
10:39:37AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10195190 2014 CLUB CAR CARRYALL 295 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Workorder: 1403213

Problem: install hitch ext

Meter Reading: 1 In Date: 04/02/2014	Close Date: 04/08/2014	Labor Hours	Description	Parts	Quantity
- Install Hitch Ext			RECEIVER EXTENSION		1.00
- Shop Supplies			BALL MOUNT 3/4"		1.00
			PIN W/CLIP 5/8 FOR HITCH		2.00
			SHOP SUPPLIES		1.00
Parts Charge: 96.00		Labor Charge: 0.00			

Workorder: 1403305

Problem: 1061 - Pre Delivery Inspection

Meter Reading: 1 In Date: 04/04/2014	Close Date: 04/04/2014	Labor Hours	Description	Parts	Quantity
- Pre Delivery Inspection		2.00			
Parts Charge: 0.00		Labor Charge: 120.00			

Workorder: 1504220

Problem: pm service/ all fluids changed

Meter Reading: 1 In Date: 04/23/2015	Close Date:	Labor Hours	Description	Parts	Quantity
-					
Parts Charge: 0.00		Labor Charge: 0.00			

3/2/2017
10:39:37AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10195190 2014 CLUB CAR CARRYALL 295 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Workorder: 1504222

Problem: pm service/ change all fluids

Meter Reading: 1	Labor	Parts	
In Date: 04/23/2015	Hours	Description	
Close Date: 04/29/2015		Quantity	
- Pm	11.00	15-40 OIL	3.00
- R/R Rusted Brake Pads, Rotors Lube Calipers And Grease		NAPAGOLD OIL FILTER	1.00
		FUEL FILTER	1.00
- Diag. And R/R Faulty Horn		NAPAGOLD AIR FILTER	1.00
- Repair Wiring And Replace L/R Tail Light Bulb		295 REAR BRAKE PAD KIT	2.00
- Wash Vehicle Prep Under Carriage And Undercoat Spary		HORN	1.00
Protectant On Electronics And Cables		RUBBERIZED UNDERCOAT	2.00
- Shop Supplies		SHOP SUPPLIES	1.00
		MOBIL 424 FLUID	4.00
		BRAKE ROTOR	4.00
Parts Charge:	534.62	Labor Charge:	660.00

Workorder: 1509104

Problem: pm/ no start/ no lights/ no bed lift

Meter Reading: 141	Labor	Parts	
In Date: 09/10/2015	Hours	Description	
Close Date: 09/24/2015		Quantity	
- Pm	10.00	NAPAGOLD OIL FILTER	1.00
- Diagnose No Start Issue Found All Ground Wiring Corroded Cleaned Wiring		15-40 OIL	3.00
		BATTERY	1.00
- Check Charging Sys Battery Failed Load Test Replaced Battery		NAPAGOLD AIR FILTER	1.00
		FUEL FILTER	1.00
- Repalce Actuator Pump On Dump Bed		MOBIL 424 FLUID	4.00
- Treat Undercarriage With Rust Inhibitor		ACTUATOR BED LIFT	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	937.27	Labor Charge:	600.00

3/2/2017
10:39:37AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10195190 2014 CLUB CAR CARRYALL 295 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Workorder: 1512196

Problem: foot throttle sticking

Meter Reading: 141	Labor	Parts	Quantity
In Date: 12/03/2015	Hours	Description	Quantity
- Replace Coolant Pipes	10.00	SHOP SUPPLIES	1.00
- Replace All 4 Calipers Brakes And Rotors And Adjust Parking Brakes		BRAKE CLEANER	2.00
		PEAK GLOBAL	2.00
- Wash Eqpt Apply Rust Inhibitors And Apply Under Coating		1401 BRAKE FLUID BRA	1.00
		CALIPER REAR RH	1.00
- Remove And Clean Throttle Pedal And Lube		BRAKE ROTOR	4.00
- Shop Supplies		RUBBERIZED UNDERCOAT	3.00
		Freight Charge	1.00
		BRK FLUID DOT 4-12OZ	1.00
		COOLANT PIPES	1.00
		LEFT REAR CALIPER	1.00
		CALIPER BRAKE FRONT	2.00
		295 REAR BRAKE PAD KIT	1.00
Parts Charge:	1,294.52	Labor Charge:	600.00

Workorder: 1512984

Problem: steering hard, especially on beach

Meter Reading: 169	Labor	Parts	Quantity
In Date: 12/28/2015	Hours	Description	Quantity
- Remove And Replace Steering Column	6.00	RUBBERIZED UNDERCOAT	2.00
- Wash Frame Am Apply Rust Inhabitor And Undercoat		STEERING COLUMN	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	362.03	Labor Charge:	360.00

3/2/2017
10:39:37AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10195190 2014 CLUB CAR CARRYALL 295 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Workorder: 1603632

Problem: throttle sticking, park brake not working

Meter Reading: 191 In Date: 04/06/2016	Close Date: 05/26/2016	Labor Hours	Description	Parts	Quantity
-	Replace Rear Parking Brake Cable Assembly W/Calipers. Adjust And Bleed	9.00	MICRO SWITCH		1.00
-	Remove Accelerator Pedal. Replace Accelerator Pedal Pivot And Bushings. Lube Throttle Cable.		LEFT REAR CALIPER		1.00
-	Pressure Wash Club Car Apply Rubberized Undercoat		Freight Charge		1.00
-	Replace Brake Light Switch And Brake Bulbs		CALIPER REAR RH		1.00
-	Replace Parking Brake Mircor Swich		WASHER		4.00
-	Shop Supplies		BOLT		4.00
			BOLT		2.00
			LEFT PARKING BRAKE CABLE		1.00
			RH PARKING BRAKE CABLE		1.00
			CABLE MAIN PK BRK		1.00
			LIGHT SWITCH		1.00
			Freight Charge		1.00
			RUBBERIZED UNDERCOAT		2.00
			BOLT		1.00
			BULB		2.00
			MACH SCREW		2.00
			Freight Charge		1.00
			SHOP SUPPLIES		1.00
			BUSHING, NYLINER		2.00
			BRAKE FL		1.00
	Parts Charge: 903.78	Labor Charge: 540.00			

Workorder: 1610764

Problem: pm service

Meter Reading: 191 In Date: 10/18/2016	Close Date: 10/24/2016	Labor Hours	Description	Parts	Quantity
-	Pm	6.50	SHOP SUPPLIES		1.00
-	Wash And Apply Rubberized Undercoat		MOBIL 424 FLUID		4.00
-	Shop Supplies		NAPAGOLD AIR FILTER		1.00
			15-40 OIL		3.00
			FUEL FILTER		1.00
			NAPAGOLD OIL FILTER		1.00
			RUBBERIZED UNDERCOAT		1.00
	Parts Charge: 92.92	Labor Charge: 390.00			

3/2/2017
10:39:37AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10195190 2014 CLUB CAR CARRYALL 295 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Workorder: 1701003

Problem: Transition Prep Charge

Meter Reading: 191

Labor

Parts

In Date: 01/31/2017

Close Date: 01/31/2017

Hours

Description

Quantity

- Transition Prep Charge

2.00

Parts Charge: 0.00

Labor Charge: 120.00

Total Parts Charges: **4,221.14**

Total Labor Charges: **3,390.00**

Total Comm. Charges: **0.00**