10203144

Hours: 9.50

# Palm Beach County Fleet Management Asset Maintenance History 2017 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Total Hours: 75.50 La	bor: 5,191.25	Parts: 1,293.28	Comm: 0.00		Charged	d: 6484.53	
Work Order: 1700050 Problem: install hitch	Mete	r: 1		In Date:	01/03/2017	Closed:	01/12/2017
Work Completed			Parts Issued			Qı	ıantity
- install Hitch Extension	n and ball		Receiver Extension				1.00
- Shop Supplies			Ball Mount 3/4"				1.00
			Pin W/clip 5/8 For Hi	tch			2.00
			Shop Supplies				1.00
Ho	ours: 0.00	Comm: 0.00	Labor: 0.00	Parts: 96.	00	Total:	96.00
Work Completed - Pre Delivery Inspection Ho	on ours: 2.00	Comm: 0.00	Labor: 120.00	Parts: 0.0	0	Total:	120.00
Work Order: 1707013 Problem: Wrong fuel		r: 31 tank		In Date:	07/18/2017	Closed:	08/21/2017
Work Completed			Parts Issued			Qı	ıantity
- C/c wrong fuel pumped into tank.remove tank to clean,flush fuel							
- C/C wrong ruel pump	ed into tank.remo	ove tank to clean,flush fuel	Napagold Fuel Filter				1.00
9		ove tank to clean,flush fuel I filter.reassemble and test run.	Napagold Fuel Filter Clean-r-carb 20oz				1.00
lines,pump,remove carl	o.and clean.r/r fue						
lines,pump,remove carl - Remove spark plugs spark plugs.	o.and clean.r/r fue to clean unburn d	I filter.reassemble and test run. iesel fuel from cylinders.install new	Clean-r-carb 20oz				1.00
lines,pump,remove carl	o.and clean.r/r fue to clean unburn d	I filter.reassemble and test run. iesel fuel from cylinders.install new	Clean-r-carb 20oz Spark Plug				1.00

Labor: 570.00

Parts: 15.53

Total: 585.53

Comm: 0.00

10203144

## Palm Beach County Fleet Management Asset Maintenance History 2017 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Work Order: 1801867 Meter: 102 In Date: 02/16/2018 Closed: 02/28/2018

Problem: P.M.SERVICE

Work Completed		Parts Issued	Quantity
- Pm Service		Napagold Air Filter	1.00
- Wash equipment.		Napagold Fuel Filter	1.00
- Drive train service.		Napagold Oil Filter	1.00
- Shop Supplies		15w40 Bulk South Reg	2.00
		Shop Supplies	1.00
Hours: 6.75	Comm: 0.00	Labor: 405.00 Parts: 61.73	Total: 466.73

Work Order: 1808903 Meter: 122 In Date: 08/28/2018 Closed: 09/18/2018

Problem: Oil leaks

Work Completed	Parts Issued	Quantity
- C/c oil leak.verify external oil filter hose fell off.reinstall,correct oil level.test	15w40 Bulk South Reg	2.00
run.	Shop Supplies	1.00
- Shop Supplies		
Hours: 2.00 Comm: 0.00	Labor: 120.00 Parts: 8.18	Total: 128.18

Work Order: 1902226 Meter: 164 In Date: 02/28/2019 Closed: 03/11/2019

Problem: PM Service. Check gear or shifting concern.

Work Completed		Parts Issued		Quantity
- Pm Service.		Napagold Air Filter		1.00
- Verify E.brake inop.replace E brake caliper and adjust linkag	e.	Napagold Fuel Filte	er	1.00
- C/c check shifter cable, found shifts hard due to high idle.ad	just idle down.	15w40 Bulk South	Reg	2.00
e, e eneck sinter custo, round sints hard due to high raicidajust raic down.		Napagold Oil Filter		1.00
- Wash equipment.		Caliper Mech Park	Brake	1.00
- Shop Supplies		Clean-r-carb 20oz		1.00
		Locking Diff Fluid Cc Only		1.00
		Shop Supplies		1.00
Hours: 9.50 Cor	mm: 0.00	Labor: 636.50	Parts: 246.09	Total: 882.59

10203144

## Palm Beach County Fleet Management Asset Maintenance History 2017 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Work Order: 2002950 Meter: 164 In Date: 03/24/2020 Closed: 03/30/2020

**Problem:** PM Service Check ticking noise.

Work Completed		Parts Issued		Quantity
- Drive train servicetransfer case .front and rear diffs.		Napagold Air Filter		1.00
		Napagold Fuel Filt	er	1.00
		10w30 Bulk Sr		2.00
caliper.reinstall front diff. and drive shaft.		Napagold Oil Filte	r	1.00
- Verify leaking oil from filter hose.replace two hose clamps.c	clean oil from	Locking Diff Fluid Cc Only  Rotor Park Brake  Caliper Mech Park Brake  Hose Clamp		3.00 1.00 1.00 10.00
area.				
- Wash equipment.				
- Shop Supplies	Hose			
		Shop Supplies		1.00
Hours: 11.25 Con	mm: 0.00	Labor: 821.25	Parts: 274.21	Total: 1,095.46

Work Order: 2102544 Meter: 532 In Date: 03/05/2021 Closed: 03/24/2021

**Problem:** PM Service. Check for something burning, Also driver rear tire flat.

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	Napagold Oil Filter	1.00
- Repair left rear tire, replace valve stem, and correct all Nitrogen leve	els. 10w30 Bulk Sr	2.00
- Customers complaint vehicle started fire. found damaged wiring on	oil Napagold Fuel Filter	1.00
sensor, debris in engine compartment, and fuel sending unit gasket b	roken. Napagold Air Filter	1.00
replace gasket, sensor, and repair wiring.	Locking Diff Fluid Cc Only	1.00
- Replace all fluids in drive train, front/rear differential and transaxle.	Gasket Rubber	1.00
- Wash equipment for service and repairs	Oil Pressure Fh Switch	1.00
- Shop Supplies	Shop Supplies	1.00
Hours: 10.00 Comm: 0.0	0 Labor: 730.00 Parts: 105.15	Total: 835.15

10203144

#### **Palm Beach County Fleet Management Asset Maintenance History** 2017 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

**Shop Supplies** 

1.00

1.00

Work Order: 2103832 Meter: 533 04/05/2021 **Closed:** 04/14/2021 In Date:

**Problem:** Sounds like something is clanging around in what sounds like the drive shaft. or somethings wrong with the transmission.

**Parts Issued** Quantity **Work Completed** 

- Customers complaint making noise. Verify 4x4 switch is on, turn off 4x4 and test drive multiple times. inspect drive train and fluids. Unable to verify complaint at this time. Instruct operator to only operate 4x4 off road, not on pavement.

- Shop Supplies

Total: 77.00 Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 4.00

**Parts Issued** 

Work Order: 2200479 **Meter:** 670 In Date: 01/14/2022 **Closed:** 01/20/2022

Problem: Stalling and oil light came on

Quantity **Work Completed** Clean-r-carb 20oz 1.00 - Verify the unit is stalling. Drain fuel tank, replace all fuel lines and filter. Fuel Injection Hose 20.00 - Customers complaint lights on dah, verify parking brake light stays on. 1.00

Replace bolt securing switch indicator on parking brake lever. Napagold Fuel Filter - Check engine oil level due to customers complaint of oil light coming on. **Shop Supplies** Verify light coming on due to unit continuously stalling. Test run after

repairs, verify all functions are now normal.

- Shop Supplies

Hours: 4.50 Comm: 0.00 Labor: 328.50 Parts: 66.00 Total: 394.50

Work Order: 2203342 Meter: 696 03/29/2022 **Closed**: 04/07/2022 In Date:

Problem: PM Service.

Work Completed		<b>Parts Issued</b>		Quantity
- Preventive Maint. Service		Napagold Air Filter		1.00
- Service front and rear differential and check fluid	in transaxle.	Napagold Fuel Filt	ter	1.00
- Shop Supplies		10w30 Bulk Sr		2.00
		Napagold Oil Filte	r	1.00
		Shop Supplies		1.00
Hours: 5.00	Comm: 0.00	Labor: 365.00	Parts: 23.15	Total: 388.15

10203144

## Palm Beach County Fleet Management Asset Maintenance History 2017 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Work Order: 2212131 Meter: 825 In Date: 12/01/2022 Closed: 12/14/2022

**Problem: STEERING** 

Work Completed		<b>Parts Issued</b>		Quantity
- Customers complaint steering. Verify all front bushing	g are worn. Replace	Lower Arm Bushin	g	4.00
front upper and lower suspension bushings.		Lower Arm Sleeve		2.00
- Shop Supplies		Upper Sleeve		4.00
		Arm Bushing		8.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 219.00	Parts: 83.52	Total: 302.52

Work Order: 2300425 Meter: 833 In Date: 01/13/2023 Closed: 01/19/2023

Problem: bad batery and parking brake

Work Completed	Parts Issued	Quantity
- Customers complaint dead battery. Battery failed load test, replaced	Battery	1.00
battery.	Caliper Mech Park Brake	1.00
- Parking brake not holding. Pads wore thin. Replace parking brake caliper	Wd40 Spr	1.00
assembly	Shop Supplies	1.00
- Repair left rear tire, correct all Nitrogen levels to 18 Psi		
- Shop Supplies		

Hours: 3.00 Comm: 0.00 Labor: 219.00 Parts: 253.09 Total: 472.09

Work Order: 2303349 Meter: 885 In Date: 04/04/2023 Closed: 04/12/2023

Problem: PM Service.

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		air filter		1.00
- Customers complaint rear bushings. Verify complai	int replace bushings and	Napagold Fuel Fil	ter	1.00
hardware on rear sway bars.		10w30 Bulk Sr		2.00
- Shop Supplies		Napagold Oil Filte	er	1.00
		Arm Bushing		8.00
		Shop Supplies		1.00
Hours: 6.00	Comm: 0.00	Labor: 438.00	Parts: 56.64	Total: 494.64

10203144

Palm Beach County Fleet Management Asset Maintenance History

2017 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Work Order: 2401531 Meter: 885 In Date: 02/12/2024 Closed: 02/12/2024

Problem: Transition Prep Charge

**Work Completed** 

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 75.50 Total Labor: 5,191.25 Total Comm: 0.00 Total Parts: 1,293.28