

4/1/2024
2:43:38 PM

Palm Beach County Fleet Management Asset Maintenance History
10199060 2015 FORD F150 Pickup, 1/2 Ton

Total Hours: 112.50 Labor: 7,629.00 Parts: 3,697.10 Comm: 2,865.31 Charged: 14191.41

Work Order: 1509479 **Meter:** 345 **In Date:** 09/18/2015 **Closed:** 09/18/2015
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1602594 **Meter:** 4670 **In Date:** 03/11/2016 **Closed:** 03/30/2016
Problem: Pm service.Advance trac message on dash interm.

Work Completed

- Pm service.
- Rotate and balance all four tires.
- Transport vehicle to and from dealer for repairing oil leak in rear of engine.no problem found with with traction control.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Used Fire X Refurbished	1.00
Stg Wheel Cov - Ford	1.00
Shop Supplies	1.00
Labor: 300.00 Parts: 53.87 Total: 353.87	

Hours: 5.00 Comm: 0.00

Work Order: 1609261 **Meter:** 10078 **In Date:** 09/06/2016 **Closed:** 09/30/2016
Problem: P.M. service and install strobe lights and no power around curves and check engine light.

Work Completed

- P.m. Service.
- Install four corner strobe light.fabricate and install wiring and switch.
- Rotate and balance all tires.
- Transport vehicle to dealer for loss of power complain.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Vtx609c Led Strobe Cl	2.00
Vtx609a Led Strobe Am	2.00
Fuse Holder	1.00
Rocker Led Blk Ambe	1.00
Clr Rtv Silcn Sealant	1.00
Fab Loom-split Poly	20.00
Shop Supplies	1.00
Labor: 780.00 Parts: 499.28 Total: 1,279.28	

Hours: 13.00 Comm: 0.00

4/1/2024
2:43:38 PM

Palm Beach County Fleet Management Asset Maintenance History
10199060 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1703334 **Meter:** 15602 **In Date:** 04/04/2017 **Closed:** 04/27/2017
Problem: P.M. service and power on turns.

Work Completed

- P.m. Service.
- Diagnose no power complain.transport vehicle to dealer for misfire codes.
- Rotate and balance tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours: 5.00 Comm: 0.00 Labor: 300.00 Parts: 44.83 Total: 344.83

Work Order: 1707500 **Meter:** 17352 **In Date:** 07/25/2017 **Closed:** 07/31/2017
Problem: accident

Work Completed

- Tow From: Nw corner of Lyons/lantana To: vista

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 1708428 **Meter:** 17352 **In Date:** 07/26/2017 **Closed:** 08/25/2017
Problem: Damage to right front tire & rim, light, front bumper, right front fender & possible steering.

Work Completed

- Damage to right front tire & rim, light, front bumper, right front fender & possible steering.

Hours: 0.00 Comm: 2,769.31 Labor: 0.00 Parts: 0.00 Total: 2,769.31

4/1/2024
2:43:38 PM

Palm Beach County Fleet Management Asset Maintenance History
10199060 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1711134 **Meter:** 17746 **In Date:** 11/09/2017 **Closed:** 11/29/2017
Problem: PM Service, Battery discharged had to be jumped.

Work Completed

- P.m. service.
- Rotate and high speed balance all four tires .repair right front tire.left rear tire pressure sensor failed replace with new.
- Test battery and charging system .battery failed load test after charge.r&r with new.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
22" Wiper Blade	2.00
Mac Wite Lithium Gres	1.00
Battry Motorcraft	1.00
Tpms Sens Kit	1.00
Shop Supplies	1.00

Hours: 5.00

Comm: 0.00

Labor: 300.00 Parts: 287.05 Total: 587.05

Work Order: 1805122 **Meter:** 21281 **In Date:** 05/17/2018 **Closed:** 05/24/2018
Problem: P.M. service.

Work Completed

- P.m. service.
- Rotate and high speed balance all four wheels. Nitrofill.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Drain Plug	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Mac Wite Lithium Gres	1.00
Drain Plug	1.00
Shop Supplies	1.00

Hours: 3.00

Comm: 0.00

Labor: 180.00 Parts: 41.53 Total: 221.53

4/1/2024
2:43:38 PM

Palm Beach County Fleet Management Asset Maintenance History
10199060 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1905827 **Meter:** 28407 **In Date:** 06/03/2019 **Closed:** 06/13/2019
Problem: P.M. service and recall18S27 .

Work Completed

Parts Issued

Quantity

- P.m. service.
- Resurface rear brake rotors and service calipers . Replace pads . Flush and bleed brake system . Test drive.
- Rotate and high speed balance all four tires . Nitrofill all.
- Transport to and from dealer for recall 18s27 .
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Napagold Air Filter	1.00
Brk Fluid Dot 4-12oz	1.00
Non-chlor Brake Clnr	1.00
Fron Brake Pad	1.00
Shop Supplies	1.00

Hours: 8.50

Comm: 0.00

Labor: 569.50

Parts: 113.19

Total: 682.69

Work Order: 1911330 **Meter:** 31787 **In Date:** 10/31/2019 **Closed:** 11/06/2019
Problem: Right rear tire going flat .

Work Completed

Parts Issued

Quantity

- Repair right rear tire and balance . Nitrofill all.
- Test battery after fully charging . Battery failed load test . R&r defective battery . Reset Bms .
- Shop Supplies

Battry Motorcraft	1.00
Shop Supplies	1.00

Hours: 2.50

Comm: 0.00

Labor: 182.50

Parts: 180.69

Total: 363.19

Work Order: 1912306 **Meter:** 32285 **In Date:** 12/02/2019 **Closed:** 01/24/2020
Problem: P.M. service.

Work Completed

Parts Issued

Quantity

- P.m. service.
- Replace two tires . Rotate and balance all four tires . Nitrofill all.
- Perform complete front end alignment and road test .
- Transport to and from dealer for rear main seal leaking .
- Shop Supplies

22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
245/70/17 Tire Mich	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 8.50

Comm: 0.00

Labor: 620.50

Parts: 499.76

Total: 1,120.26

4/1/2024
2:43:38 PM

Palm Beach County Fleet Management Asset Maintenance History
10199060 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 2101315 **Meter:** 39645 **In Date:** 02/04/2021 **Closed:** 02/19/2021
Problem: P.M. Service. Toolbox does not lock , check power inverter .

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Inspect and repair utility tool box
- Check electrical ckt.r & I radio panel necessary to access switch. r & I new switch repair wiring connector to switch loose, Check and replace both inverter power inverter intermittent operation
- Inspect and repair Lr tire, rotate and speed balance all four, nitro fill
- Shop Supplies

Used Fire X Refurbished	1.00
5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Steering Wheel Cover Large	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
400w Inverter Cobra	1.00
Rocker Led Blk Ambe	1.00
400w Inverter Cobra	1.00
Shop Supplies	1.00

Hours: 5.80

Comm: 0.00

Labor: 423.40 Parts: 238.93 Total: 662.33

Work Order: 2106722 **Meter:** 42125 **In Date:** 06/21/2021 **Closed:** 06/22/2021
Problem: Right rear tire going flat .

Work Completed

Parts Issued

Quantity

- Repair right rear tire and balance . Nitro fill all.
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 73.00 Parts: 4.00 Total: 77.00

4/1/2024
2:43:38 PM

Palm Beach County Fleet Management Asset Maintenance History
10199060 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 2111360 **Meter:** 44241 **In Date:** 10/21/2021 **Closed:** 10/28/2021
Problem: P.M. Service . Pulls left ,Hears cluck in front at slow speeds turning . Check no power when passing .

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Inspect Tires Rotate And Balance All Tires With Nitro Fill
- Test Drove Vehicle Steering Wheel Is Off To The Left, Perform Front End Alignment Retest
- Test Drove Vehicle For Noise And Poor Acceleration, No Noise Found, Cut Floormat Back For Poo Acceleration
- Shop Supplies

Drain Plug	1.00
5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Napagold Air Filter	1.00
Qd Electronic Cleaner	1.00
Shop Supplies	1.00

Hours: 6.00

Comm: 0.00

Labor: 438.00

Parts: 46.42

Total: 484.42

Work Order: 2112717 **Meter:** 44595 **In Date:** 12/01/2021 **Closed:** 12/02/2021
Problem: check battery - had to jump start several times recently

Work Completed

Parts Issued

Quantity

- Charge battery fully . Test battery and charging system . Battery failed load test . R&r defective battery . Hook up Ids to reset Bsm .
- Shop Supplies

Battry Motorcraft	1.00
Shop Supplies	1.00

Hours: 1.50

Comm: 0.00

Labor: 109.50

Parts: 139.86

Total: 249.36

Work Order: 2201818 **Meter:** 45688 **In Date:** 02/17/2022 **Closed:** 02/22/2022
Problem: screw in left rear tire

Work Completed

Parts Issued

Quantity

- Replace both rear tires and balance . Due to too many repairs on same tire
- Shop Supplies

245/70/17 Tire Mich	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 413.34

Total: 486.34

4/1/2024
2:43:38 PM

Palm Beach County Fleet Management Asset Maintenance History
10199060 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 2304788 **Meter:** 52856 **In Date:** 05/12/2023 **Closed:** 05/18/2023
Problem: P.M. Service. Check engine light on

Work Completed

- Preventive Maint. Service
- rotate and balance all 4 tires nitro fill all
- perform fuel injector service and air intake decarb and cleaning .
- Computer diagnose customer states check engine light using Ids codes P0302 and P0303 . Perform tune up Replace all 6 spark plugs Retest and clear codes
- Shop Supplies

Hours: 9.20 Comm: 0.00

Parts Issued

Quantity

Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Intake Cleaner Kit	1.00
Motor Tune-up 16oz	1.00
Spark Plug	6.00
White Shepherd Stp Lk	1.00
Shop Supplies	1.00

Labor: 671.60 Parts: 133.72 Total: 805.32

Work Order: 2311135 **Meter:** 56400 **In Date:** 11/03/2023 **Closed:** 11/14/2023
Problem: PM Service

Work Completed

- Perform Pm Service
- Rotate, balance and nitro service.
- Scan diagnose Cel, Codes P0300, P0303, P0304. Perform cranking compression test, Pass, remove intake, read plugs 3 and 4 Ok, replace coils, clear codes and test drive.
- Shop Supplies

Hours: 5.50 Comm: 0.00

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Ignition Coil	2.00
Shop Supplies	1.00

Labor: 401.50 Parts: 231.51 Total: 633.01

Work Order: 2402539 **Meter:** 58742 **In Date:** 03/11/2024 **Closed:** 03/15/2024
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 4.00 Comm: 0.00

Labor: 292.00 Parts: 0.00 Total: 292.00

Total Hours: 112.50

Total Labor: 7,629.00

Total Comm: 2,865.31

Total Parts: 3,697.10