



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V26793

In Date: 10/09/2009
Close Date: 10/16/2009

Meter Reading: 16,803.00

Problem?

Sorry wrong asset # none assigned for E93. E93 rear FF seat is not secured down and slides around while riding. Needs to be secured down

Task performed:

1. C/O; fnd that it needs bolts installed on base to stop it frm sliding arnd E-93; rep _____ headset at base.
2. Drive to Stn91; rep it; seal light & rep one emergency light on top light bar. j

Parts	Quantity
795 BULB	2

Workorder: V26687

In Date: 10/06/2009
Close Date: 11/17/2009

Meter Reading: 16,803.00

Problem?

repair headlight E93

Task performed:

Lake Worth - 10180687

1. Installed new headlight.
2. Mntd tools in L-1 compt.
4. Rep left side compt light. j

Parts	Quantity
F30T8-CWUSE F25T8 4V439 BULB	7

Workorder: V27856

In Date: 11/23/2009
Close Date: 11/30/2009

Meter Reading:

Problem?

on call coolant leak. E93

Task performed:

Rep coolant leak. j

Parts	Quantity
NO PARTS USED	

Workorder: V27469

In Date: 11/06/2009
Close Date: 12/09/2009

Meter Reading: 16,803.00

Problem?

E93 officer's side rear brake light 10-7. Replaced previously and it shorts out.

Task performed:

Rear T-signal out on left side; rep grnd wire. j

Parts	Quantity
NO PARTS USED	



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V27502

In Date: 11/08/2009

Meter Reading:

Close Date: 12/09/2009

Problem?

The R Rear brakelight is out/intermittent. E93

Task performed:

Parts

Quantity

Traced out problem w/lights & fnd bad connection on brake light; rep. j

NO PARTS USED

Workorder: V27198

In Date: 10/27/2009

Meter Reading: 16,803.00

Close Date: 12/21/2009

Problem?

2 running board/ground lights out on both driver and officer side of E93

Task performed:

Parts

Quantity

Short in light; traced out problem & will have rep at B-inspection. j

NO PARTS USED

Workorder: V27843

In Date: 11/21/2009

Meter Reading:

Close Date: 01/13/2010

Problem?

Captain side (right) brake light not working. E93

Task performed:

Parts

Quantity

1. Fnd short in right rear brake light socket; will order new one.

NO PARTS USED

2. Replcd rear brake lights with LED lights. j

Workorder: V27918

In Date: 11/24/2009

Meter Reading:

Close Date: 01/13/2010

Problem?

E93 Right rear brake light out. Also, running light goes out when brake pedal is pressed.

Task performed:

Parts

Quantity

1. Replcd w/LED brake lights.

NO PARTS USED

2. Air leak; fnd/rep. j



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V27369

In Date: 11/02/2009

Meter Reading:

Close Date: 01/14/2010

Problem?

Both interior jumpseat lights not working. Mount New York pry bar on rear of cab. e93

Task performed:

1. Interior lights inop; fnd bad grd on one light.
2. Move hose bed divider over; will be done at shop.
3. Remnt tools in L-1. j

Parts

Quantity

5269LPVM-5 SM MOUNT

10



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V27991

In Date: 11/30/2009

Meter Reading: 123,340.00

Close Date: 01/14/2010

Problem?

C INSPECTION AND REPAIRS AS NEEDED E 93

Task performed:

Parts

Quantity



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

C-Inspection	101305009SS0001 CPI SHELF BRACKET ONE HOLE 2005	4
2. R/R btrys; rem D8's; install & rewire.	1142BULB	1
3. Shim out door hold opens; replc hardware.	114650-12591AIR FILTER YANMAR LW93	1
4. R/R wiper blades; rep washer; tubes block up; cln out & fill tank.	1304031A/C VENT	2
5. Set up trck for tire guy; put away; assist him	1817677C91FUEL FILTER SCREEN ASSY	1
6. R/R air compress gov.	1902769-0020SEAT BELT LW	1
7. Svc rear; swap to syn ube; add to fix; lube pump slow	20A-400CLAMP 4" 33969	2
8. Svc T-case.	349298HOSE	1
9. Svc trans.	3576REAR BRAKE DRUMS	2
10. Svc P/S sys; rep leak on window of tank; rep _____ hoses.	4020362171 GRO LAMP DOME 4 IN	1
11. R/R leaking fuel line; replcd line gas leaks on fuel pump on motor.	42-1436SWITCH LOW COOLANT	1
12. R/R exh clamps leaking & move mnt over.	60351STEPWELL LIGHT	1
13. R/R pole lights on frnt bumper.	65166BDRUM	2
14. C/O ladders; replc heat sensors; clean up.	75W90GEAR OIL SYN QT	18
15. Find out why cab lights are out; chkd brkn etc.; replc brkn wiring shorted out; pull paneling, etc; chase down wiring, pull swtchs, light lens; rep brkn _____; fnd water bad in light head over new light.	76062-15-NCSWITCH PRESS	1
16. C/O grnd light ckt; fnd brkn open; R/R brkr; R/R light out.	91-20WIPER BLADE 20 IN	2
17. Rebuild dryer; C/O all oil in unit; cln air tanks.	95809580 BELT	2
18. Rep cab clearance light; replc one fixture; replc (4) bulbs & (4) lens.	9ULENSCCLEAR LENS FREEDOM BAR	1
19. Assist ken with frnt light bar set up.	BG54-8854215 LIGHT GUIDE BUMPER	1
20. R/R headliners frt/rear; rem (3) cab light bars & wiring; rework mnts to fit; upgraded light bar; drill/tap set screws; set center light Baron roof.	DOR570016PLUG	1
21. Work on light bar; install; rework light bar set up; wire up unit; mnt down; seal up wiring on frnt bar.	FG83284DFG/HF6238 PS/HDY FILTER	1
22. Rep wiring on tag light & on pump panel lights.	1319AMARKER LAMP PIERCE LW	1
23. R/R exh mast gksts; reinstall all, etc.	22230-000-30BREAKER CIRCUIT 30A	1
24. Rep seat pad ripped on Benett seat rear wall.	8943AMARKER LAMP LENS PIERCE LW	4
25. R/R A/C filter; made rear A/C filter holder; R/R A/C vents.	BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	6
26. Svc cooling sys; rep leaks; order parts.	14-7014HGR-1 HELMET HOOK	2
27. R/R brakes/drums.	1501450007750USE 0775145	3
28. R/R frnt bearing hubs/gskts; fill w/syn lube.	15W40BSYN OIL BULK QTS	30
29. R/R belts.	2506656C124316 WIX CAB A/C FILTER	1
30. Get ready to go for springs in frnt.	33403FUEL FILTER LW	1
31. Work on shelf for compt; cut/weld shelf to fit.	33411FILTER FUEL SERIES 40	1
32. R/R cab A/C Dist panel; R/R (2) outlet vent controls.	46748AIR FILTER PIERCE	1
33. Prepare veh to go to spring shoop; rem all hardware on floor, cvr open holes in roof; take veh off hoists, etc.	51799OIL FILTER 40 SERIES	1
34. Cut/mod mntng brkts on hard suction hose trays.	1812348C1FUEL LINE SLEEVE INT	6
35. Mnt hard suction trays to veh; had to cut shorter to fit hose.	1818727C1GASKET	1
36. Finish hard suction tray; install L/S.	1825436C1GASKET EXH MANIFOLD	1
37. R/R frnt seat belt; wrng one; rem & install.	284358GOVERNOR D-2	1
38. Tighten SCBA bottle holders.	5008414CARTRIDGE DC100	1
39. Mnt shelves & wll brkts; mnt ext. brkts; wire up handlight; mov divider for blitz line;; coat hooks; complete	29526898 29548988 TRANS FILTER ALLISON	1
	31782POWER OUTLET	1
	340-4009CAP OIL HUB	2
	FG-Q59278P/S GASKET	1
	5004614XAIR COMPRESSOR	1
	63-1583SENSOR PIERCE	1
	66-04928080-0000-13 LIGHT DOME RED/CLR LENS WPB	1



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

list frm Stn93.

40. Assist John w/foam flush & fill; flowed foam to test sys - Levy.

41. Flush foam sys & tank ok; old 3-6%; flush sy & piping; fill w/new foam; rerun sys w/new foam; calibrate sys to new foam; refill tank w/new.

42. R/R coolant temp sensor & upper hose plugged.

43. C/O ceiling light problme; chk wiring, ckt; R/R ___; order new light; fnd short in light asy; reinstall body panels & roof panels.

44. R/R trans temp light on guage.

45. C/O gen start problem; its working; svc gen.

46. Quality check.

47. Replc bulb & rep bad grnd on compt light.

48. Rem steering wheel; set straight; retest, drive.

j

874592C91PROBE	1
9MMEDGEPRRFLMINI EDGE 4 STRB	2
E7895LE7895L NUT INNER LEFT	10
E7895RNUT INNER R/H	10
HP-31DBATTERY 950CCA HP-31D	6
JEIBC207M3BWJEIBC207M3BWS CABLE BATT	2
JEIBC207M3RWCABLE BATT	2
K080726BELT	1
KSR4034715QPSHOE KIT	2
PR338324070 WIX FILTER WATER	1
R950014PURGE VALVE WABCO AIR DRYER	1
UCB15FUSE 15 AMP NEW #BR315	1
UMVS162511STRAP	3
XK4034707QPMHD SHOE KIT 3/8 BEAM	2
LZ77LS1CARB WISCONSON	1

Workorder: V28040

In Date: 12/01/2009

Meter Reading: 16,803.00

Close Date: 01/15/2010

Problem?

replace 2 front tires E93 (outside agency-callaghan tire)

Task performed:

Replc (2) front tires E93 - Callaghan j

Parts _____ Quantity

NO PARTS USED

Vendor?: CALAGHAN

Workorder: V28460

In Date: 12/17/2009

Meter Reading: 16,803.00

Close Date: 01/20/2010

Problem?

REPAIR FRONT SUSP. TOTAL TRUCK

Task performed:

Repair front susp. - Total Truck j

Parts _____ Quantity

NO PARTS USED

Vendor?: TOTAL TRUCK



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V28461

In Date: 12/17/2009 Meter Reading: 16,803.00
Close Date: 01/20/2010

Problem?
REPAIR HOSE BED COVER E93

Task performed:	Parts	Quantity
Repair hose bed cover E93 - Central Auto j	NO PARTS USED	

Vendor?: CENTRAL AUTO

Workorder: V29121

In Date: 01/14/2010 Meter Reading: 16,803.00
Close Date: 02/01/2010

Problem?
move hose bed divider e93

Task performed:	Parts	Quantity
Cut & moved hose bed divider. j	NO PARTS USED	

Workorder: V29313

In Date: 01/21/2010 Meter Reading: 16,803.00
Close Date: 02/10/2010

Problem?
wont start E 93

Task performed:	Parts	Quantity
Went to Stn93 from Stn21; rem fuel filters; tightened all fuel lines; rem/bled lines to eng; started/ran; pumped water; ck ok; put back in svc. j	NO PARTS USED	

Workorder: V29274

In Date: 01/20/2010 Meter Reading: 16,803.00
Close Date: 02/17/2010

Problem?
INSTALL STORAGE BOX E93

Task performed:	Parts	Quantity
Installed storage box in unit. j	NO PARTS USED	



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V29337

In Date: 01/21/2010

Close Date: 03/02/2010

Meter Reading:

Problem?

mini lightbar that was just installed, drivers side, middle , rear section of light bar inop. front side operational

Task performed:

installed/mntd equipment.

j

Parts

5269LPVM-5 SM MOUNT

LPVM-7LG MOUNT

Quantity

15

10

Workorder: V29708

In Date: 02/04/2010

Close Date: 03/02/2010

Meter Reading: 12,334.40

Problem?

2 red strobe lights out on top of cab (driver side) E93

Task performed:

Rep L/side light bar.

j

Parts

NO PARTS USED

Quantity

Workorder: V29709

In Date: 02/04/2010

Close Date: 03/02/2010

Meter Reading: 12,334.40

Problem?

foam indicating lights shows 1/2 full although tank is full. note also when primer is activated, 3/4 full indicating light turns on then goes out when primer released. E93

Task performed:

Recalibrated foam gauge & tested.

j

Parts

NO PARTS USED

Quantity

Workorder: V29712

In Date: 02/04/2010

Close Date: 03/02/2010

Meter Reading: 12,334.40

Problem?

hurst ram tool has a hydraulic hose leak. took ram off engine and tagged it where leak is and placed it under work bench on apparatus floor. no asset# on tool. asset # on power unit is invalid when entered. E93

Task performed:

Rep ram that was leaking.

j

Parts

NO PARTS USED

Quantity



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V29177

In Date: 01/15/2010
Close Date: 03/19/2010

Meter Reading: 16,803.00

Problem?

Install S.O.P. dome light lens E93

Task performed:

Installed new light/lens. j

Parts

Quantity

66-04928080-0000-13 LIGHT DOME RED/CLR LENS WPB

1

Workorder: V30095

In Date: 02/19/2010
Close Date: 03/19/2010

Meter Reading: 12,356.30

Problem?

No1 speedlay foam preconnect unable to discharge @a high psi. flowed water from other discharges with no problem. back flush pump. E93

Task performed:

No pump press; fnd nozzle no good; replc nozzle. j

Parts

Quantity

NO PARTS USED

Workorder: V30268

In Date: 02/25/2010
Close Date: 03/26/2010

Meter Reading: 12,388.70

Problem?

Hurst ram leaks fluid. This truck only has one ram and it's out of service. E93

Task performed:

Replcd two hoses on ram & tested. j

Parts

Quantity

NO PARTS USED

Workorder: V30516

In Date: 03/07/2010
Close Date: 03/26/2010

Meter Reading: 12,388.70

Problem?

horn dvice came off steering wheel, could not get back on E93

Task performed:

Reinstalled horn bottom. j

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V27250

In Date: 10/28/2009
Close Date: 04/14/2010

Meter Reading: 16,803.00

Problem?

install graphics e93

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V27323

In Date: 11/01/2009
Close Date: 04/14/2010

Meter Reading: 16,803.00

Problem?

ON CALL ALT 10-7. E93

Task performed:

Parts

Quantity

on call replaced alt

A1-607C630 NEW A1-608 290AMP ALT. NIEHOFF

1

Workorder: V27736

In Date: 11/17/2009
Close Date: 04/14/2010

Meter Reading:

Problem?

Extension cord plug missing ground wire. Needs replacement. E93

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V30799

In Date: 03/17/2010
Close Date: 04/21/2010

Meter Reading: 12,388.70

Problem?

rear right yellow emergency light out, found burnt wire terminal from bulb e93

Task performed:

Parts

Quantity

Replcd rear light. j

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V30800

In Date: 03/17/2010

Meter Reading: 12,388.70

Close Date: 04/21/2010

Problem?

Request reflective decals for rear of truck. Visability on I-95 is a huge concern. R93 has reflective decals and has made a big difference on vehicle accidents. Station 93 covers I95 from Lantana to WPB. install extra rar lighting E93

Task performed:

Installed (5) LED lights in rear of truck. j

Parts

Quantity

60R00FRR600 SERIES RED LED W/O FLANGE

4

90R00FRR900 SERIES LED W/O FLANGE - RED

2

9EFLANGEFLANGE CHROME

2

Workorder: V31480

In Date: 04/13/2010

Meter Reading: 124,682.00

Close Date: 04/29/2010

Problem?

ON CALL LADDER RACK 10-7 E 93

Task performed:

Eng ladder rack 10-7; bypass sys temp wire sys; unit to be properly rep during normal work week as per Ed Ehrke. j

Parts

Quantity

NO PARTS USED

Workorder: V31254

In Date: 04/03/2010

Meter Reading: 124,682.00

Close Date: 05/01/2010

Problem?

Need to hard wire TIC so it charges when the battery is off E93

Task performed:

Rewired tic charger to btry. j

Parts

Quantity

NO PARTS USED

Workorder: V31355

In Date: 04/08/2010

Meter Reading: 124,682.00

Close Date: 05/05/2010

Problem?

INSTALL SIGNS ON UNIT E 93

Task performed:

1. Installed campaign signs.
2. Air leaks; traced air leak/rep. j

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V31396

In Date: 04/09/2010
Close Date: 05/11/2010

Meter Reading: 16,803.00

Problem?

repair gas fans (outside agency-regan's small engine service)

Task performed:

Repair gas fans - Regan j

Parts

NO PARTS USED

Quantity

Vendor?: REGAN

Workorder: V31429

In Date: 04/10/2010
Close Date: 05/11/2010

Meter Reading: 124,682.00

Problem?

repair electric ladder rack E93

Task performed:

Rep electric ladder rack that had bad grnd. j

Parts

NO PARTS USED

Quantity

Workorder: V31822

In Date: 04/27/2010
Close Date: 05/25/2010

Meter Reading: 124,682.00

Problem?

Small air leak at pump engage switch when in pump gear..E93

Task performed:

Turbo hose has hole; rem/replcd. j

Parts

NO PARTS USED

Quantity

Workorder: V31857

In Date: 04/28/2010
Close Date: 06/04/2010

Meter Reading: 12,523.30

Problem?

repair needed to exhaust fitting pass side to front radiator hole in hose temporary duct taped E93

Task performed:

Rep turbo hose w/new hose. j

Parts

357737-2HUMP HOSE FLF/FRE1020-0001

Quantity

1



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V31960

In Date: 05/04/2010
Close Date: 06/04/2010

Meter Reading: 12,523.30

Problem?

fuel leak E93

Task performed:

Rep fuel leak at fuel filter. j

Parts

Quantity

NO PARTS USED

Workorder: V31978

In Date: 05/04/2010
Close Date: 06/04/2010

Meter Reading: 12,523.30

Problem?

written up prior, feb/2010 foam indicator 3/4, and full not working. E19

Task performed:

Recalibrated foam gauge. j

Parts

Quantity

NO PARTS USED

Workorder: V32254

In Date: 05/17/2010
Close Date: 06/09/2010

Meter Reading: 125,453.00

Problem?

Requesting 12 (one shot) two cycle oil for one gallon gas cans. sta 93

Task performed:

Dropped off oil. j

Parts

Quantity

NO PARTS USED

Workorder: V32861

In Date: 06/14/2010
Close Date: 06/21/2010

Meter Reading: 125,902.00

Problem?

ON CALL AIR LEAKS E93

Task performed:

Traced out air leaks & repaired. j

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V32697

In Date: 06/07/2010

Meter Reading: 125,902.00

Close Date: 06/28/2010

Problem?

Officer's side red emergency flasher out. e93

Task performed:

Parts

Quantity

Rep grnd wire for spotlight. j

NO PARTS USED

Workorder: V32755

In Date: 06/08/2010

Meter Reading: 125,902.00

Close Date: 06/28/2010

Problem?

Flashing Right side strobe out - wiring/bulb out and at station (no number) on part -also reminder - air leak at PTO and Foam tan gauge light e93

Task performed:

Parts

Quantity

Replcd strobe bulb in R/front. j

NO PARTS USED

Workorder: V32966

In Date: 06/17/2010

Meter Reading: 125,902.00

Close Date: 07/01/2010

Problem?

GROUND LIGHT - UN-PLUGGED AND OTHER 2 ALSO NOT WORKING ..E93

Task performed:

Parts

Quantity

R/R light bulbs; rep plug wiring. j

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V32989

In Date: 06/18/2010

Meter Reading: 125,902.00

Close Date: 08/02/2010

Problem?

engine overheating E93

Task performed:

1. Eng overheats; relay not getting signal frm ECM; wired 205 of alarm stdt; also replcd gauge.
2. Was not reading properly; installed new gauge/sender; fan comes on at approx 212 now; also cld not get shop ECM to communicate properly.
3. Coolant leaks - bypass hose bad & air purge hose/fitting bad; replcd hose/fittings as needed.
4. A/C belt loose; tightened A/C belt.
5. Assist w/radiator - Vasko.
6. Replcd wtr pump.
7. Replce eng t-stat.
8. Replcd heater valve - rusted/seized.
9. Assist w/radiator - levy.
10. Replcd hoses/clamps as needed.
11. Steering wheel off centered; center. ja

Parts

Quantity

1814320C1TEMP. SENDING UNIT	1
286404BE13250 SWITCH BRK-LGT	1
359816HOSE AND FITTING	2
3605ALARMSTST 195F	1
44-1089TEMP SENDER	1
63-4844TEMP GAUGE PIERCE	1
FREIGHTSHIPPING CHARGES	30
3607ALARMSTAT 205F/96C	1



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V33227

In Date: 06/29/2010

Meter Reading: 126,253.00

Close Date: 08/04/2010

Problem?

B INSPECTION E 93

Task performed:

- B-inspection
- 2. C/O air leak in dash in pump gear; chk shift cyl seals-ok; chk shift lever valve-ok; fnd ok to pump; switch leak; R/R switch - ok now.
- 4. Grnd lights out; replc bulbs; no power to P/P grnd light; chk wiring ____ etc; fmd shorted wire in frame rail; rep; ok.
- 5. R/R wipers.
- 6. Reseal P/S hose to pump; tighten line on fittings.
- 7. Retest gauge; R/R gauge; rewire; R/R temp sender; replc dash lights out.
- 8. Chk sys; add freon to unit - reading low; still evac sys; refill hi-side Shrader.
- 9. Pull apart units; R/R H-block; rem cores; R/R dryer; reinstall all body panels, etc.; vac fill test; test drive.
- 10. Assist with A/C work.
- 11. R/R tensioner, tighten up A/C belts.
- 12. R/R radiator. ja

Parts

Quantity

15W40BSYN OIL BULK QTS	30
16-31438915 VALVE CORE A/C 3544706C1	1
160012-2012A EXPANSION VALVE 71R8301	2
1817677C91FUEL FILTER SCREEN ASSY	1
1830033C2TENSIONER	1
194-ABULB	10
33403FUEL FILTER LW	1
33411FILTER FUEL SERIES 40	1
4020362171 GRO LAMP DOME 4 IN	4
51799OIL FILTER 40 SERIES	1
59-0638HEATER SHUT OFF VALVE	1
74R258607-2613A RED DOT DRIER 7127	1
91-20WIPER BLADE 20 IN	2
FREIGHTSHIPPING CHARGES	31
1830256C93THERMOSTAT INT.	1
1830606C94WATER PUMP	1
21194HOSE LOWER RADIATOR	1
42-1436SWITCH LOW COOLANT	1
994966BEARING KIT HORTON CLUTCH	1

Workorder: V34243

In Date: 08/13/2010

Meter Reading: 125,902.00

Close Date: 08/13/2010

Problem?

David Clark system cuts off and on E93

Task performed:

REPOTED TO RADIO SHOP 08/13/10

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V33746

In Date: 07/23/2010
Close Date: 08/16/2010

Meter Reading: 125,902.00

Problem?

Primer inop E93

Task performed:

Fnd primer NG; rem/replcd; tested unit tested ok. ja

Parts

Quantity

2000071102000072100 SOLENOID HALE PRIMER 1

501-3090-00PRIMER PUMP MOTOR 1

Workorder: V33945

In Date: 08/02/2010
Close Date: 09/08/2010

Meter Reading: 125,902.00

Problem?

DASH LIGHTS STARTED GOING OFF AND THEN BACK ON - WHEN OFF - TAPPING TOP OF DASH - LIGHTS BLINK - E93

Task performed:

Traced out problem w/light going off; rem cvr over eng; fnd shorted wires; rep wires/tested. j

Parts

Quantity

NO PARTS USED

Workorder: V34066

In Date: 08/06/2010
Close Date: 09/09/2010

Meter Reading: 125,902.00

Problem?

while responding and onscene of a call emergency lights turned off intermitently, and would come back on. turned load manager c and high idle. E93

Task performed:

1. Traced out problem; fnd bad connection on relay; rep/retested.
2. Air leak; chk; fnd none at this time. j

Parts

Quantity

NO PARTS USED

Workorder: V33985

In Date: 08/02/2010
Close Date: 09/17/2010

Meter Reading: 125,902.00

Problem?

unit I.D. placard for front and back E93

Task performed:

installed number on frnt of eng. j

Parts

Quantity

S PLACARDFRONT AND BACK PLACARD 8



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V34338

In Date: 08/17/2010
Close Date: 09/17/2010

Meter Reading: 125,902.00

Problem?

top indicator green light stays lit when in road position. e93

Task performed:

Replcd pump shifter switch. j

Parts

Quantity

NO PARTS USED

Workorder: V34415

In Date: 08/20/2010
Close Date: 09/29/2010

Meter Reading: 125,902.00

Problem?

Rescue saw not receiving spark to plug, changed plug with same result. E93

Task performed:

Worked on saw, sent to shop. j

Parts

Quantity

NO PARTS USED

Workorder: V35211

In Date: 09/27/2010
Close Date: 10/18/2010

Meter Reading: 127,548.00

Problem?

AIR LEAKS E93

Task performed:

1. check for air leaks, inspected truck for air leaks and repaired. jab

Parts

Quantity

NO PARTS USED

Workorder: V34469

In Date: 08/23/2010
Close Date: 10/21/2010

Meter Reading: 125,902.00

Problem?

front top emergency lights cut off and on intermittently r93

Task performed:

1. light shutting off, repaired bad connection in circuit board. jab

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V35368

In Date: 10/04/2010

Meter Reading: 127,548.00

Close Date: 10/25/2010

Problem?

ON CALL LIGHT BAR 10-7 E 93

Task performed:

Parts

Quantity

1. road call, check light bar, checked light bar found bad connection at breaker, repaired connection. j ab

NO PARTS USED

Workorder: V35537

In Date: 10/10/2010

Meter Reading: 127,548.00

Close Date: 10/28/2010

Problem?

STARTER ON ENGINE 93 MAKES A GRINDING NOISE UPON STARTING. DOES NOT HAPPEN AFTER EVERY START. HAPPENED TWICE OUT OF FOUR STARTS TODAY.E93

Task performed:

Parts

Quantity

1. C/O starter problem; rem starter frm veh; on bench cC/O; fnd Bendix drive brkn; get reman frm parts; before install, reclock frnt hsng & chk condition of fly wheel; install starter asy.

10461277USE 10461089

1

R134AFREON LB

30

2. Assist Larson w/fly wheel C/O - Murray. j

Workorder: V36267

In Date: 11/08/2010

Meter Reading: 128,081.00

Close Date: 11/18/2010

Problem?

ON CALL E 93 NO PUMP GEAR

Task performed:

Parts

Quantity

No pump light; readj switch & tested. j

NO PARTS USED

Workorder: V36015

In Date: 10/28/2010

Meter Reading: 128,081.00

Close Date: 12/07/2010

Problem?

Mount halagan on running board. Officer side. Tommy has looked at the location requested. E93

Task performed:

Parts

Quantity

Installed halagan on running board. j

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V36051

In Date: 10/31/2010
Close Date: 12/07/2010

Meter Reading: 128,081.00

Problem?

emergency flasher on passenger side of cab out E93

Task performed:

Parts

Quantity

- 1. Replaced bulb in right side flasher.
- 2. Chk A/C temp & C/O ok; blowing at 56. j

NO PARTS USED

Workorder: V36041

In Date: 10/29/2010
Close Date: 12/16/2010

Meter Reading: 128,081.00

Problem?

Primer was not working, but driver was able to get it back in service---mechanic already came out to evaluate it and related part ordered---only notification Sta 93

Task performed:

Parts

Quantity

- (1) TRAVELED TO ST93 TO REPAIR PRIMER PROBLEM ON E93. CHECKED OUT PRIMER LUBE LEVEL.OK. FOUND BAD PRIMER SWITCH. WILL HAVE TO ORDER PRIMER SWITCH.
- (3) INSTALLED NEW PRIMER SWITCH THAT HAD BEEN ON ORDER. OK.

51779SWITCH WATEROUS

1

J.W.

Workorder: V36529

In Date: 11/17/2010
Close Date: 12/16/2010

Meter Reading: 128,081.00

Problem?

E-93 top and D/E side emergency light bars not working . Side strobes on chassis also need to be checked only activating sometimes. E93

Task performed:

Parts

Quantity

- (1) TRAVELED TO ST93 TO REPAIR EMERGENCY LIGHT BARS THAT ISN'T WORKING ON E93. FOUND ALL WIRES MELTED ON RELAY. REWIRED LIGHT BAR CIRCUIT. ALL TESTED OK.

NO PARTS USED

Workorder: V33005

In Date: 06/19/2010
Close Date: 12/22/2010

Meter Reading: 125,902.00

Problem?

E93 is at the shop at this time. Please tint windows.

Task performed:

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V34950

In Date: 09/14/2010
Close Date: 12/22/2010

Meter Reading: 125,902.00

Problem?

E93 (drivers side left rear comp.) electric extension cord reel works intermittently. Extension cord only works when reel is in a certain position.

Task performed:

Parts

Quantity

(1) ELECTRIC CORD REEL WORKS INTERM. NOT FIXED. TRY TO ORDER NEW ONE.

NO PARTS USED

J.W.

Workorder: V35041

In Date: 09/19/2010
Close Date: 12/22/2010

Meter Reading: 127,453.00

Problem?

foam tank is full and indicator reads empty E93

Task performed:

Parts

Quantity

(1) FOAM TANK GAGE NOT WORKING CORRECTLY. RECALIBRATED GAGE AND TESTED OK FOR CORRECT READING OF FOAM IN TANK. J.W.

NO PARTS USED

Workorder: V35342

In Date: 10/02/2010
Close Date: 12/22/2010

Meter Reading: 127,548.00

Problem?

K12 INOPERABLE AGAIN. UNSURE IF FUEL MIXTURE IS BAD OR CARB. IT IS LOCATED ON WORKBENCH E93

Task performed:

Parts

Quantity

(1) TRAVELED TO ST 93 TO REPAIR K12 FROM E93. NO REPAIR LISTED ON WORK ORDER SHEET. J.W.

NO PARTS USED

Workorder: V36711

In Date: 11/29/2010
Close Date: 12/22/2010

Meter Reading: 128,081.00

Problem?

Truck pulls to the left when braking and drifts to the right when driving. Hurst power unit due for annual PM 10/11. unable to locate asset number. e93

Task performed:

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V37050

In Date: 12/09/2010

Meter Reading: 128,081.00

Close Date: 12/22/2010

Problem?

A inspection and test drive for pull to left. headlight out

Task performed:

A-inspection - chk over outside; repair frnt end suspension.

2. Replc left hi-lo headlight.

3. Tire press improperly inflated; fill all tires to proper inflation press.

4. Steering wheel off center to the left; lift steering wheel & repos.

5. Cab grd light R/rear inop; replc brkn light fixture.

6. Cab L/turn side marker light inop; rem complete light fixture; fnd grd brkt broke; rep frkt; also wire harness was off fixture & fell inside body panel; to relocate it was ness to rem complete headlight asy; reach inside & retrieve wiring; rep wires & reassem.

7. Replc rear Lic plate light bulb; rep grn as light was dim after replc brkn bulb.

8. Replc brkn bulb in pump panel light; drill drain hole in lens to let water out.

9. Inside pump compt lite inop; lite fixture rusted; rem frm veh & order parts; mntng screws brkn off; relocate lite, drill/tap new holes; install new screws; mod wiring.

10. C/O fuel leak under veh; fnd fuel lines leaking frm fitting on fuel pipes frm filter hsng to new recently installed fuel pump; diss all fuel tubes; fnd that none of special pipe rubber seals were replcd; this is a must on this type of piping; ordered all new seals; install new pipe seals & reinstall piping to pump & filter hsng; start/chk for leaks; all ok.

11. Cab R/rear interior lite inop; rem lens to chk bulbs; fnd printed ckt inside fixture burnt up; order parts; install new fixture; C/O lite & fnd new fixture also burnt up ckt board;

NOTE: orngl fixture doenst use a ckt board fixture; rem fixture frm other side & C/O wiring at that fixture; both sides wired the same; using both burnt out fixtures, I made my own fixture w/o using a ckt board; use just straight wiring as orngl was; solder all ckts & install in veh; retest; now all works properly; explained situation to parts on these fixtures & it seems like there is an older style but will chk on availability; newer style will not work w/the veh wiring as is; will short out the printed ckt board.

j

Parts	Quantity
1157BULB	1
1812348C1FUEL LINE SLEEVE INT	6
4020362171 GRO LAMP DOME 4 IN	1
60351STEPWELL LIGHT	1
66-04928080-0000-13 LIGHT DOME RED/CLR LENS WPB	1
921LIGHT BULB	2
H4656USE CV TYPE HEAD LIGHT	1
80350DOME LIGHT	1



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V36775

In Date: 12/01/2010
Close Date: 01/10/2011

Meter Reading: 128,081.00

Problem?

steering pulls to left when braking, drifts to right when driving E 93

Task performed:

1. Chkd brakes; fnd LR brake chamber hanging up & not returning; R/R both rear chambers; problem still existis; chkd frnt brakes; slack adjuster throw & adj ok; rem wheels/drums; all brake hardware ok; chkd brake spydeer bolts ok; reinstalled drums/wheels; road testd again to get temp of drums; LF drum 75 degrees hotter than all the rest; chkd/retorqued u-bolts; chkd toe in all-ok; ran air press test; fnd both frnt wheels have same press; swapped unit out to spare truck for further inspection.
2. Chk ABS electronic control units; diss/inspect; no fault fnd; reassemble/install; chk air tank; fnd excess oil in filter; replc filter; drain air tank, further inspection; fnd left frnt spring chassis mnt bolts nut msng; springs shifting; unit going to ____ truck. j
3. Adj brakes; truck still pulls to left; sent to shop. j

Parts

Quantity

5008414CARTRIDGE DC100	1
91523933 GAUGE VAC/PRESS.	1
MA15445NT3030 STD CHAMBER 30/30	2
R950014PURGE VALVE WABCO AIR DRYER	1

Workorder: V37096

In Date: 12/12/2010
Close Date: 01/10/2011

Meter Reading: 128,081.00

Problem?

roof mounted spot light, for finding addresses at night spare at 93

Task performed:

- C/O light bar mtng; this light bar at one time already had a spotlight on top of it; sev screw holes had to be filled in & sealed as wtr was getting inside; mnt new spotlight to light bar; lift light bar from its mnts & bore hole in bottom & in roof for remote power/opn cable; pull down headline inside cab & side wall panel;
- Also electric panel cvr & dash; run wire cable frm light bar;, thru hood, across the wall to electric panel & dash cntrl mode; after hookup, reinstall all - removed items & seal cable holes in roof & light bar. j

Parts

Quantity

091-3YWCOVER KUSSMAUL AUTO EJECT	1
0915520120AUTO EJECT 20 AERO OTL3925	1
LGHGO-2020GOLIGHT MODEL 2020 SEARCH LIGHT	1



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V36827

In Date: 12/02/2010
Close Date: 01/11/2011

Meter Reading: 128,081.00

Problem?

repair springs total truck

Task performed:

Repair springs - Total Truck j

Parts

Quantity

40-5244SPRING HANGER

1

FREIGHTSHIPPING CHARGES

125

Vendor?: TOTAL TRUCK

Workorder: V37266

In Date: 12/19/2010
Close Date: 01/11/2011

Meter Reading: 128,081.00

Problem?

E93 pulls to the right when brakes applied

Task performed:

Unit sent to shop for rears. j

Parts

Quantity

NO PARTS USED

Workorder: V37405

In Date: 12/25/2010
Close Date: 02/04/2011

Meter Reading: 128,081.00

Problem?

E93 tank to pump handle threads are stripped/cross threaded. On call mechanic Steve wrapped handle with teflon tape and temporarily fixed problem.

Task performed:

Pump handle threads stripped on tank to pump valve needs new base & handle. j

Parts

Quantity

NO PARTS USED

Workorder: V38503

In Date: 02/14/2011
Close Date: 02/16/2011

Meter Reading: 129,435.00

Problem?

repair rotating light E93

Task performed:

Rep rear rotator. j

Parts

Quantity

H50SN12BULB

2



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V37995

In Date: 01/23/2011

Meter Reading: 129,435.00

Close Date: 03/08/2011

Problem?

Air horn and siren foot controls on officer's side not working E93

Task performed:

Parts

Quantity

Tested pedals & all work at this time. j

NO PARTS USED

Workorder: V38066

In Date: 01/26/2011

Meter Reading: 129,567.00

Close Date: 03/08/2011

Problem?

lights on dashboard go off and on, may have loose connection E 93

Task performed:

Parts

Quantity

Fnd bad connection for dash lights. j

NO PARTS USED

Workorder: V38136

In Date: 01/29/2011

Meter Reading: 129,567.00

Close Date: 03/08/2011

Problem?

Tank to tump lever threads are stripped off to the point of near failure to hold in female socket that works tank to pump linkage. E93

Task performed:

Parts

Quantity

Replcd handle & tested. j

52-0455CONTROL HANDLE PIERCE

1

52-0462ROD CONTROL

1

FREIGHTSHIPPING CHARGES

9

Workorder: V38465

In Date: 02/13/2011

Meter Reading: 129,710.00

Close Date: 03/09/2011

Problem?

Rear OIC side Emergency light is out.E93

Task performed:

Parts

Quantity

Rep bad connection on relay for side emergency lights. j

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V38469

In Date: 02/13/2011
Close Date: 03/09/2011

Meter Reading: 129,710.00

Problem?

no back up alarm on E93.

Task performed:

replc backup alarm. j

Parts

Quantity

090-0278STRECHER BAR NEW

1

575BACKUP ALARM ECCO 107 DEC

1

Workorder: V38636

In Date: 02/19/2011
Close Date: 03/15/2011

Meter Reading: 130,067.00

Problem?

E93 chainsaw has no spark. Also needs new air filter. Located on Workbench at St. 93 with tag.

Task performed:

Old saw not county saw; DC will get new saw. j

Parts

Quantity

NO PARTS USED

Workorder: V39294

In Date: 03/19/2011
Close Date: 03/24/2011

Meter Reading: 130,247.00

Problem?

E93 on board generator wont start

Task performed:

Operate gen; unit rns approx (3) sec & shuts down; tried unit on unit; ran under load, didn't shut down; cld not find fault. j

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V38937

In Date: 03/03/2011

Meter Reading: 130,518.00

Close Date: 04/04/2011

Problem?

C INSPECTION AND REPAIRS AS NEEDED E93

Task performed:

1. C-Inspection
2. R/R all btrys.
3. Paint fuel cap.
4. Change oil in T-case.
5. Fnd wtr in rear end drain & flush w/brake cleaner; started wheel, drain, axles & hub off to cln wtr out of reservoir; finish cln rear end & flush w/diesel fuel to get wtr out; rem hubs & ___ in tires; cln/inspect; replc seal & install hubs.
6. Fnd coolant lever sender leaking & no date for coolant so I drained coolant & change coolant filter & rem sender & ordered new sender; replcd new sender & top off radiator.
7. Mike needs # off frnt/rear axles; clnd plate on frnt/rear axles & wrote them down.
8. R/R air filter.
9. Rep tank over full.
10. Svc Hurst tool; replcd (4) hose & tested.
11. Chk windshield washer; fnd hose too short in dahs; it pulled off nipple on throttle fire wall fitting; had to get longer hose & tighten fitting under dash; had to rem ABS ___ to get to it.
12. Tom said (1) condensor fan was not working & get me a fan frm his trk; I started truck up; both fans were working; AMP test both fans were 12 AMPs - worked good; turn on/off to see if one wldn't start after it warmed up; both work good.
13. The center of dash which is the warning light display fell outbecause holddown bolt was glued to the dash; took out & cln them up; super glued them back & bolted the dash back tog.
14. Dash light was flashing & backup light & alarm were not working; open up doghouse to get to fuse panel.
15. Install nut zert in back of cab for axe holder.
16. Look for backup light & alarm fuse; took doghouse cvr off; fnd ___.
17. had to replc velcro on doghouse cvr; pop rivet it down to lid; replc velcro on holders.
18. Fnd A/C filter loose in brkt; put two bolts w/wingnut .
19. Went to hyd to fill tank test foam; made foam work & flush sys - ok; pump drain wld not seal; rem drain & clnd; replc o-ring; drain stop leaking.
20. Fnd wtr under truck this morning; fnd compression sleeve bad; R/R compression slee; stopped leak.

j

Parts	Quantity
05-17223-000CAP RADIATOR 10 LB	1
114650-12591AIR FILTER YANMAR LW93	1
1229F4634SKIT RING/LOCK WASHER	2
1280008CONNECTOR SET	2
15W40BSYN OIL BULK QTS	30
1817677C91FUEL FILTER SCREEN ASSY	1
194BULB	1
33403FUEL FILTER LW	1
33411FILTER FUEL SERIES 40	1
353R023HURST HOSE W/O SWIVEL	4
380003ASEAL	2
401581GASKET AXLE FL80 R002435	2
42-1436SWITCH LOW COOLANT	1
46748AIR FILTER PIERCE	1
95809580 BELT	1
PH713851799 FILTER OIL	1
PR338324070 WIX FILTER WATER	1
S3240WIX 33582 FUEL FILTER SPARE BRUSH TRUCK	1
K080726BELT	1
135R009WARNING DECAL	4
250R001250R001 STICKER	1
250R004TAG DIRECTIONAL	1
250R014250R014 DECAL	2
19570 AMP RELAY	2
UCB10BR310 FUSE 10 AMP	1
60351STEPWELL LIGHT	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	6
HP-31DBATTERY 950CCA HP-31D	6



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V40005

In Date: 04/19/2011
Close Date: 04/27/2011

Meter Reading: 131,025.00

Problem?

ENGINE-93 FRONT RIGHT SIDE FLASHING STROBE NOT WORKING --- STATION 93 GAS BLOWER LEAKING AND NOT RUNNING Sta 93.

Task performed:

Light bar inop - low voltage; load manager drops when truck not running. j

Parts

Quantity

NO PARTS USED

Workorder: V41395

In Date: 06/16/2011
Close Date: 06/23/2011

Meter Reading: 132,258.00

Problem?

A/C is blowing ambient air temp. AT-13 contacted and he repaired leak and recharged system. May need more freon in the near future. Sta 93.

Task performed:

Connected light/buzzer on alarm. j

Parts

Quantity

NO PARTS USED

Workorder: V41497

In Date: 06/21/2011
Close Date: 06/24/2011

Meter Reading: 132,258.00

Problem?

E93 alarm gong off

Task performed:

Alarm going off - dash lights all on; cld not dupe; Storz leaking; open hand valve & inner gasket parts came out w/wtr; leaks worse now; came to shop for new Storz. j

Parts

Quantity

NO PARTS USED

Workorder: V40180

In Date: 04/26/2011
Close Date: 06/28/2011

Meter Reading: 131,261.00

Problem?

Failed dry vacuum test, Sta 93.

Task performed:

vacum tested pump and passed test ak

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V41391

In Date: 06/16/2011

Meter Reading: 132,258.00

Close Date: 07/08/2011

Problem?

A/C inop.

Task performed:

work completed on wo 41395 ak

Parts

Quantity

NO PARTS USED

Workorder: V41281

In Date: 06/12/2011

Meter Reading: 132,258.00

Close Date: 07/11/2011

Problem?

Dash lights are not working.... e93

Task performed:

1. Rep dimmer switch
2. Adj tools inr rear compt. j

Parts

Quantity

NO PARTS USED

Workorder: V41360

In Date: 06/15/2011

Meter Reading: 132,258.00

Close Date: 07/11/2011

Problem?

Spare 18 inch chain saw blade, Sta 93.

Task performed:

DC will drop off chain. j

Parts

Quantity

NO PARTS USED

Workorder: V41427

In Date: 06/18/2011

Meter Reading: 132,258.00

Close Date: 07/11/2011

Problem?

5 INCH JAFFERY VALVE LEAKING E93

Task performed:

PU valve & will send out for repair. j

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V41396

In Date: 06/16/2011
Close Date: 07/19/2011

Meter Reading: 132,258.00

Problem?

Air horn floor switch not working. AT-13 cleaned the switch and it now works intermittantly. Switch needs to be replaced.

Task performed:

REPLACED AIR HORN FOOT SWITCH AK

Parts

7605-666764-0023 SWITCH FOOT SIREN

Quantity

1

Workorder: V41580

In Date: 06/24/2011
Close Date: 07/19/2011

Meter Reading: 132,258.00

Problem?

FOAM PRE-CONNECT - LEAKING WITH VALVE CLOSED - MIGHT BE FOAM FUSH IS LEAKING BY -SWITCH IS OFF Sta 93.

Task performed:

RAN FOAM SYSTEM AND TESTED OK FOUND NO
LEAKS

Parts

NO PARTS USED

Quantity

ROAD TESTED FOR NOISE IN FRONT END FOUND
NO NOISE AK

Workorder: V41755

In Date: 07/02/2011
Close Date: 07/19/2011

Meter Reading: 132,488.00

Problem?

The truck seems to pull to the right. E34

Task performed:

ROAD TESTED TRUCK AND TESTED OK AK

Parts

NO PARTS USED

Quantity

Workorder: V41646

In Date: 06/28/2011
Close Date: 08/08/2011

Meter Reading: 132,488.00

Problem?

both circle D lights are not working. they are 500 watt circle d bulbs. could we please have an extra bulb for backup storage. Sta 9

Task performed:

dropped off bulb for lights

Parts

NO PARTS USED

Quantity



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V41871

In Date: 07/08/2011 Meter Reading: 132,658.00
Close Date: 08/08/2011

Problem?

Circle D light male receptacle has snapped off. Will be located on work bench at St. 93.

Task performed:

unit sent to shop and gave spare to put on engine

Parts

NO PARTS USED

Quantity

Workorder: V42034

In Date: 07/14/2011 Meter Reading: 132,795.00
Close Date: 08/25/2011

Problem?

Drivers side rear beacon is out. Sta 93.

Task performed:

replaced light in rear

Parts

RB6DRPRB6PRP RED ROTATING BEACON

Quantity

1

Workorder: V42695

In Date: 08/09/2011 Meter Reading: 133,314.00
Close Date: 09/12/2011

Problem?

officer's side door leaking water with window shut. weather stripping around door not sealing properly. E 93

Task performed:

repaired side door that was leaking

Parts

NO PARTS USED

Quantity

repaired hurst unit that was running rough

Workorder: V43171

In Date: 08/30/2011 Meter Reading: 133,731.00
Close Date: 09/12/2011

Problem?

Replace four tires across the rear.

Task performed:

Replace (4) tires across the rear - Tiresoles j

Parts

NO PARTS USED

Quantity

Vendor?: TIRESOLE



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V42934

In Date: 08/20/2011

Meter Reading: 133,448.00

Close Date: 09/16/2011

Problem?

right side flasher out E93

Task performed:

replaced bulb in light

Parts

Quantity

DPSTDPST SW-ROCKER

2

H35SN12BULB

2

air leak repair air leaks

Workorder: V43064

In Date: 08/25/2011

Meter Reading: 133,639.00

Close Date: 09/19/2011

Problem?

pump panel work area lights will not turn on, Sta 93.

Task performed:

replaced switch for lights

Parts

Quantity

NO PARTS USED

repaired door handle for drivers window

Workorder: V43430

In Date: 09/05/2011

Meter Reading: 133,900.00

Close Date: 09/21/2011

Problem?

Rear driver side ground light out -under tail-board..... E93

Task performed:

Replc grd light on rear of truck.

Parts

Quantity

4020362171 GRO LAMP DOME 4 IN

1

Workorder: V43879

In Date: 09/23/2011

Meter Reading: 134,242.00

Close Date: 10/07/2011

Problem?

need cam sensor. Sta 93

Task performed:

check engine light on replaced cam sealer

Parts

Quantity

1885812C91CAM SENSOR OLD DT 1807339C92

1

repaired rear door handle



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V43900

In Date: 09/24/2011
Close Date: 10/14/2011

Meter Reading: 134,242.00

Problem?

Top pre-connect leaks and charges line when in pump gear and tank to pump is opened E93

Task performed:

Parts

Quantity

READJUSTED PRECONNECT VALVE AND TESTED

NO PARTS USED

REPAIRED FUEL LINE ON GENERATOR THAT WAS LEAKING

Workorder: V44363

In Date: 10/13/2011
Close Date: 10/21/2011

Meter Reading:

Problem?

primer pump not working - smell of burnt wire or motor - stop working after pulling a prime.... Sta 93.

Task performed:

Parts

Quantity

replaced primer motor and repaired wires

501-3090-00PRIMER PUMP MOTOR

1

Workorder: V44483

In Date: 10/18/2011
Close Date: 10/28/2011

Meter Reading:

Problem?

E93 On board generator will not start. Sta 93.

Task performed:

Parts

Quantity

1. Rep gen, rep fuel pump & ran unit.
2. air leak; rep leak at pump panel. j

NO PARTS USED

Workorder: V44484

In Date: 10/18/2011
Close Date: 10/28/2011

Meter Reading:

Problem?

Found a small oil leak on floor from E93. Added 1 qt of oil to engine, Sta 93.

Task performed:

Parts

Quantity

Rep oil filter that was leaking. j

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V43906

In Date: 09/25/2011
Close Date: 11/07/2011

Meter Reading: 134,242.00

Problem?

#1 Foam pre-connect gate valve - leaking and charging hose bed.....E93

Task performed:

Will need to be done at B-Inspection; will mk note.
j

Parts	Quantity
1045711BALL VALVE ASSY	1
91378905 VALVE KIT 2 IN AKRON	1
91388906 VALVE KIT 2.5 IN AKRON	1
91398907 VALVE KIT 3 IN AKRON	1

Workorder: V44607

In Date: 10/22/2011
Close Date: 11/07/2011

Meter Reading:

Problem?

chain saw hard to start - K-12 did not start - spark plug not firing - check another spark plug and it was firing - install that plug and started - need 2 spare plugs and both saws checked..... E93

Task performed:

Ran/tested all saws. j

Parts	Quantity
NO PARTS USED	

Workorder: V45132

In Date: 11/13/2011
Close Date: 11/21/2011

Meter Reading:

Problem?

right side front high/low bead headlight out E 93

Task performed:

Replc headlight. j

Parts	Quantity
NO PARTS USED	

Workorder: V45138

In Date: 11/13/2011
Close Date: 11/21/2011

Meter Reading:

Problem?

replaced halogen on E93 with light from St 91. Need H4656 replacements for future use at both St 91 and St 93.

Task performed:

Dropped off bulbs at stn. j

Parts	Quantity
NO PARTS USED	



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V45405

In Date: 11/24/2011

Meter Reading:

Close Date: 11/30/2011

Problem?

Hurst power unit - re-coil starting pull cord catching and smashing hand - not running and cord housing making a loose metal sound when pulling cord E93

Task performed:

Parts

Quantity

hurst power tool not running and recoil broken swapped with spare unit

NO PARTS USED

Workorder: V44815

In Date: 10/31/2011

Meter Reading:

Close Date: 12/02/2011

Problem?

K-12 Saw - still hard to starting - had to clean old spark plug- wet with gas - prior to starting -- also air cleaner housing broken/cracked, Sta 93.

Task performed:

Parts

Quantity

CLEANED CARB AND TESTED

NO PARTS USED

Workorder: V45088

In Date: 11/10/2011

Meter Reading:

Close Date: 12/02/2011

Problem?

On board generator is not producing enough power/watts/amps to sufficiently operate tools or lights. e91

Task performed:

Parts

Quantity

will have repaired at b inspection

NO PARTS USED

unit will have to be removed from truck

Workorder: V45144

In Date: 11/14/2011

Meter Reading: 135,183.00

Close Date: 12/05/2011

Problem?

water pump leaking from fitting

Task performed:

Parts

Quantity

FOUND FITTING ON PUMP LEAKING - REPAIRED AND TESTED.

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V45692

In Date: 12/06/2011
Close Date: 01/03/2012

Meter Reading:

Problem?

right-side amber emergency flashing light out - seal-beam, Sta 93

Task performed:

Parts

Quantity

air leak, traces out air leak and repaired leak

NO PARTS USED

repaired rear flashing light

Workorder: V45797

In Date: 12/12/2011
Close Date: 01/03/2012

Meter Reading:

Problem?

FRONT EMERGENCY LIGHT BAR NOT WORKING.....1 ROCKER SWITCH IS NOT TURNING ON..... Sta 93

Task performed:

Parts

Quantity

removed access cover and repaired all melted wires for light bar

NO PARTS USED

Workorder: V46195

In Date: 12/31/2011
Close Date: 01/13/2012

Meter Reading: 136,074.00

Problem?

SLOW OIL LEAK NEAR ENGINE/ TRANSMISSION, POSSIBLE REAR SEAL AIR

Task performed:

Parts

Quantity

CHECKED OIL LEAK, WILL REPAIR AT B-INSPECTION

1420408SWITCH SEAT HGT ADJ

1



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V46336

In Date: 01/05/2012

Meter Reading: 136,074.00

Close Date: 01/13/2012

Problem?

B INSPECTION AND REAIRS E 93

Task performed:

1. B-INSPECTION.
2. ADJUST A/C FANBELTS.
3. REMOVE EXCESS OIL FROM P.S RESERVIOR UNTIL FULL COLD LEVEL ON STICK.
4. R&R LENS R&R BULB ON CAB ROOF MARKER LIGHT.
5. REPAIR W/WASHER SYSTEM - FILL RESERVOIR CLEAN OUT NOZZLES. TRIED TO REPLACE DRIVERSIDE - DON'T STOCK THIS TYPE OF NOZZLE. CLEAR HOSES ON WIPER ARMS.
6. R&R LENS R&R BULB ON TAG LIGHT.
7. R&R LENS ON L/R UPPER MARKER LIGHT.
8. R&R R/F SCHRADER VALVE IN TIRE TO 105 PSI.
9. R&R CAB A/C FILTER - HAD TO CUT TO SIZE - ORIGINAL FILTER DIFFERENT - STIFFER - HAD TO ADD SUPPORT RODS TO KEEP NEW FILTER IN PLACE.
10. R&R BATTERY CHARGE INDICATOR ON L/S PUMP PANEL - TEST UNIT - WORKS OK. TRACE WIRING TO FIND PROBLEM. FOUND CRUSHED CABLE. REPAIRED DAMAGED SECTION.
11. EXHAUST PIPE HITTING BODY SUPPORT ON CHASSIS - MOVE EXHAUST PIPE TIGHTEN ALL CLAMPS. REPLACE BOLTS ON CHASSIS HANGERS FOR MUFFLER.
12. DIAGNOSE WHY PRIMER DOESN'T WORK. REMOVE PRIMER - BENCH TEST NO GOOD - INSTALLED NEW PRIMER ASSY.

Parts

Quantity

1817677C91FUEL FILTER SCREEN ASSY	1
33403FUEL FILTER LW	1
33411FILTER FUEL SERIES 40	1
404-100 VALVE CORE	1
501-3090-00PRIMER PUMP MOTOR	1
906LIGHT BULB 12CP	1
91-20WIPER BLADE 20 IN	2
PH713851799 FILTER OIL	1

Workorder: V46757

In Date: 01/22/2012

Meter Reading: 136,074.00

Close Date: 02/03/2012

Problem?

E93 RIGHT CLEARANCE LIGHT HOUSING ON CAB HAS A CRACK NEEDS REPLACING. Sta 93

Task performed:

REPAIRED LIGHT AND REPAIRED WIRES.

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V46778

In Date: 01/23/2012
Close Date: 02/03/2012

Meter Reading: 136,074.00

Problem?

K-12 SAW - BROKEN AIR CLEANER COVER AND VERY VERY VERY HARD TO START - CALL D/O JIM SHOOK AT 561-758-0084 FOR ANY OTHER DETAILS... Sta 93

Task performed:

REPAIRED SAW AND TESTED.

Parts

NO PARTS USED

Quantity

Workorder: V47100

In Date: 02/05/2012
Close Date: 02/10/2012

Meter Reading: 136,575.00

Problem?

AC unit not blowing cold air. Might need a charge. Sta 93

Task performed:

FOUND A/C FANS NOT WORKING - REMOVE AND REPLACED FANS.
2. AIR LEAK. FOUND NO AIR LEAK.

Parts

3568MP06-3568M 16 IN FAN
S30TLBULB

Quantity

2
1

Workorder: V47395

In Date: 02/17/2012
Close Date: 03/06/2012

Meter Reading: 136,781.00

Problem?

Stihl K12 saw on E 93 needs air intake replaced at is is hanging on by one screw. The rest of the brackets have broke off, Sta 93

Task performed:

1. REPAIRED K-12 SAW AND TESTED.
2. REPAIRED CHAIN SAW THAT WOULD NOT RUN.

Parts

NO PARTS USED

Quantity

Workorder: V47396

In Date: 02/17/2012
Close Date: 03/06/2012

Meter Reading: 136,781.00

Problem?

Hurst unit flywheel was repaired but still engages occasionally when starting, yanking arm back towards unit. Sta 93

Task performed:

1. AIR LEAK IN DASH - REPAIRED LEAK ON AIR GAUGE.
2. HURST UNIT WAS SWAPPED OUT AND SENT TO SHOP.

Parts

NO PARTS USED

Quantity



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V45600

In Date: 12/03/2011
Close Date: 03/12/2012

Meter Reading:

Problem?

AMBER CLEARANCE LIGHT COVER MISSING - CAB ROOFE E93

Task performed:

Parts

Quantity

8943AMARKER LAMP LENS PIERCE LW

1

Workorder: V47447

In Date: 02/21/2012
Close Date: 03/13/2012

Meter Reading: 136,781.00

Problem?

The TIC charger does not appear to be hard wired to the battery. It is not charging while E93 is sitting idle. Could we get the TIC charger hard wired so it will charge with shore line. Thanks

Task performed:

Parts

Quantity

1. REWIRED SL-40 HANDLIGHTS AND TESTED.
2. REPAIRED PUMP LEAK AND TESTED FOR WATER LEAKS.

NO PARTS USED

Workorder: V47657

In Date: 03/01/2012
Close Date: 03/13/2012

Meter Reading: 137,068.00

Problem?

Hurst inop. Sta 93

Task performed:

Parts

Quantity

1. WORKED ON CARB AND RAN UNIT AND TESTED.
2. AIR LEAK REPAIRED LEAK AT AIR HORN SOLENOID.

15W40BSYN OIL BULK QTS

12

Workorder: V47955

In Date: 03/14/2012
Close Date: 03/30/2012

Meter Reading: 13,735.40

Problem?

DRIVER SEAT AIR CONTROL LEAKING - PIERCE GOVERNOR CENTER / MESSAGE CENTER SCREEN FADED/WORN. E93

Task performed:

Parts

Quantity

REPAIRED ALL AIR LEAKS AND REPAIRED VALVE ON DRIVER'S SEAT.

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V48193

In Date: 03/26/2012

Meter Reading: 137,725.00

Close Date: 04/02/2012

Problem?

Small oil leak -left side - front engine - just started.. Sta 93

Task performed:

Parts

Quantity

1. CLEANED OFF ENGINE AND REPAIRED OIL LEAK
2. READJUSTED LINKAGE TO DECK-GUN VALVE THAT WAS LEAKING.

NO PARTS USED

Workorder: V48292

In Date: 03/29/2012

Meter Reading: 137,725.00

Close Date: 04/16/2012

Problem?

PUMP PANEL LIGHT TOGGLE SWICTH STUCK IN ON POSITION..... E93

Task performed:

Parts

Quantity

1. REPLACED SWITCH ON PUMP PANEL.
2. REPLACE BULB IN SPOT LIGHT.

EL35115 SW ROCKER A/C 360000088

1

H35SN12BULB

2

Workorder: V48661

In Date: 04/14/2012

Meter Reading: 138,177.00

Close Date: 05/11/2012

Problem?

Generator on the engine is not putting out enough power to the outlets to properly power tools/fans. This has apparently been an issue in the past.

Task performed:

Parts

Quantity

RAN GENERATOR AND TESTED OK.

NO PARTS USED

Workorder: V48578

In Date: 04/11/2012

Meter Reading: 137,826.00

Close Date: 05/14/2012

Problem?

request for engine oil. no oil in station. need 2 today. E93

Task performed:

Parts

Quantity

DROPPED OFF OIL.

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V49247

In Date: 05/10/2012
Close Date: 05/30/2012

Meter Reading: 138,889.00

Problem?

GAS SMOKE FAN /EJECTOR RUNNING ROUGH AT HIGH SPEED - CHECK FUEL BOWL AND FILTER -- CLEAN E93

Task performed:

REPAIRED FAN AND TESTED.

Parts

NO PARTS USED

Quantity

Workorder: V48888

In Date: 04/25/2012
Close Date: 06/01/2012

Meter Reading: 138,406.00

Problem?

RIGHTSIDE TOP/CAP CLEARANCE LIGHT HOUSING BROKEN - LENS OK E93

Task performed:

1. REPLACED LIGHT AND REWIRED.
2. READJUSTED DOOR LATCH ON RIGHT SIDE.

Parts

1319AMARKER LAMP PIERCE LW

1

Quantity

Workorder: V49751

In Date: 05/31/2012
Close Date: 06/01/2012

Meter Reading: 139,320.00

Problem?

headlight out on drivers side

Task performed:

REPLACED HEADLIGHT ON E93.

Parts

H4656USE CV TYPE HEAD LIGHT

2

Quantity

Workorder: V49769

In Date: 05/31/2012
Close Date: 06/01/2012

Meter Reading: 139,320.00

Problem?

HURST POWER UNIT - ENGINE MOTOR MOUNTS - RUBBER - TORN NOT SECURE E 93

Task performed:

INSTALLED NEW MOUNTS.

Parts

HR149460107MOUNT VIBRATION (NEWER POWER UNITS
L PLACARD INSERTLARGE PLACARD INSERT CARD

4

2

Quantity



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V48662

In Date: 04/14/2012
Close Date: 06/08/2012

Meter Reading: 138,177.00

Problem?

The gate valve on pump panel marked "FRONT" is not remaining shut when engine pressure is brought to approx above 100PSI. Gated wye is currently in place on front bumper to stop water flow and allow use of trash line.

Task performed:

READJUSTED VALVE LINKAGE - TO STOP LEAK

Parts

NO PARTS USED

Quantity

Workorder: V50078

In Date: 06/12/2012
Close Date: 06/13/2012

Meter Reading: 139,691.00

Problem?

replace sparkplugs for K-12. E93

Task performed:

SWAP SAWS OUT AND CHANGE BLADES.

Parts

NO PARTS USED

Quantity

Workorder: V49687

In Date: 05/29/2012
Close Date: 06/18/2012

Meter Reading: 139,320.00

Problem?

rewire tic charger E93

Task performed:

1. REWIRED TIC CHARGER AND HAND LIGHTS TO BATTERY POWER.
2. AIR LEAK CHECKED AND REPAIRED AIR LEAK AT MAIN AIR TANK.

Parts

NO PARTS USED

Quantity

Workorder: V50261

In Date: 06/20/2012
Close Date: 06/21/2012

Meter Reading: 13,993.00

Problem?

federal q inop

Task performed:

FED Q INOP NO POWER - SWITCH WORK SOLENOID. TOOK CENTER CONSOLE APART. SOLENOID JUMPED. sIREN STILL INOP. TESTED SOLENOID AND FOUND BAD GROUND UNDER FRONT OF TRUCK.

Parts

NO PARTS USED

Quantity



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V50149

In Date: 06/15/2012
Close Date: 06/25/2012

Meter Reading: 139,691.00

Problem?

Primer inoperable during morning truck check.

Task performed:

RAN PUMP AND TESTED PRIMER, ALL TESTED OK.

Parts

NO PARTS USED

Quantity

Workorder: V50481

In Date: 06/29/2012
Close Date: 06/29/2012

Meter Reading: 140,175.00

Problem?

WONT START E 93

Task performed:

TRAVEL TO STATION 93 TEST BATTERIES FOUND 2 BAD. REPLACED 4 OUT OF 6 BATTERIES TEST STARTER OK AT THIS TIME.

Parts

BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER BATTERY
HP-31D BATTERY 950CCA HP-31D

4

4

Workorder: V50609

In Date: 07/05/2012
Close Date: 07/13/2012

Meter Reading: 140,275.00

Problem?

Pump panel lights not working. E93

Task performed:

REPAIRED BAD CONNECTION ON PUMP PANEL.

Parts

NO PARTS USED

Quantity

Workorder: V50406

In Date: 06/26/2012
Close Date: 07/25/2012

Meter Reading: 14,002.70

Problem?

E93 ROOF (top of cab) 1 STROBE FLASHER ABOVE CAPT SEAT IS OUT

Task performed:

FOUND NO LIGHTS OUT.

Parts

NO PARTS USED

Quantity



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V50555

In Date: 07/02/2012
Close Date: 07/25/2012

Meter Reading: 140,275.00

Problem?

strobe light out on Officer's side of light bar E93

Task performed:

REPLACED LIGHT ON FRONT DRIVER'S SIDE.

Parts

NO PARTS USED

Quantity

Workorder: V50694

In Date: 07/09/2012
Close Date: 07/25/2012

Meter Reading: 140,375.00

Problem?

Pump panel lights/switch not working.... E93

Task performed:

1. REWIRED AND REPLACED LIGHT SWITCH ON PUMP PANEL.
2. REPAIRED WATER LEAK AT DRAIN VALVE.

Parts

NO PARTS USED

Quantity

Workorder: V50752

In Date: 07/11/2012
Close Date: 07/25/2012

Meter Reading: 14,506.00

Problem?

E 93 front discharge valve has been leaking for some time and has been reported, however, now water continuously leaks from a automatic drain valve.

Task performed:

INSTALLED PLUG IN REPLACE OF DRAIN VALVE.

Parts

NO PARTS USED

Quantity

Workorder: V51259

In Date: 08/01/2012
Close Date: 08/09/2012

Meter Reading: 140,888.00

Problem?

oil leak (under engine) reported in past is getting worse. need oil delivered to station. e93

Task performed:

INSTALLED NEW FILTER AND FILLED OIL TO CORRECT LEVEL.

Parts

15W40QSYN OIL QT
PH713851799 FILTER OIL

Quantity

24
1



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V51758

In Date: 08/21/2012

Meter Reading:

Close Date: 09/13/2012

Problem?

right rear upper compartment door needs gas support shocks replaced. will not go up with ease or stay up. truck at hq today (am training) E93.....

Task performed:

- 1. REPAIRED BRACKET FOR DOOR POSITION ANS REPLACED DOOR POSITION.

Parts	Quantity
101281012GSS6298UH STRUTS 90#	2
EAA-8350-30UGSS1783UQ STRUT-LIFT	2
GSS1801UN30LB SHOCK SIDE DOOR HORTON	2
HLD39941143UB GAS STRUT	2

Workorder: V51953

In Date: 08/28/2012

Meter Reading:

Close Date: 09/13/2012

Problem?

PUMP PANEL LIGHTS TOGGLE SWITCH WORKS INTERMITTENTLY E93

Task performed:

- 1. REPAIRED CONNECTION AND RAN NEW WIRES.
- 2. REPAIRED NEW PUMP LEAK AT PUMP FITTING.

Parts	Quantity
NO PARTS USED	

Workorder: V52324

In Date: 09/12/2012

Meter Reading:

Close Date: 09/25/2012

Problem?

handle/lever for front bumper trash line, the black knob on the top of the handle broke off. E93

Task performed:

- REPAIRED HANDLE ON PUMP PANEL THAT WAS BROKEN.

Parts	Quantity
NO PARTS USED	

Workorder: V52461

In Date: 09/17/2012

Meter Reading:

Close Date: 10/16/2012

Problem?

pump panel lights dont work. electrical connections appear burnt at back of switch. e93

Task performed:

- REWIRED PUMP PANEL LIGHTS AND TESTED. COOLANT LEAK- REPAIRED LEAK AT LOWER COOLANT HOSE.

Parts	Quantity
NO PARTS USED	



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V52696

In Date: 09/28/2012

Meter Reading: 142,195.00

Close Date: 10/17/2012

Problem?

C INSPECTION AND NEEDED REPAIRS... E93

Task performed:

Parts

Quantity



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

1. C-Inspection	05-17223-000CAP RADIATOR 10 LB	1
2. Replaced 2 batteries on driver's side checked history of vehicle other 4 replaced 6-12 clean cables and terminals.	1141BULB	2
3. C-Inspection.	1156BULB	2
4. Service trans filters and take sample. Top of Trans fluid.	12E6ULB1SOLENOID ISUZU PONY MOTOR BRUSH TRUCI	1
5. Service t-case.	15W40BSYN OIL BULK QTS	38
6. C-Inspection.	1807369C2OIL PRESSURE SW	1
7. Remove tilt cab reservoir cover and fill reservoir. Reinstall cover.	1817677C91FUEL FILTER SCREEN ASSY	1
8. Repair front valve stem cores and air tires.	29526898 29548988 TRANS FILTER ALLISON	1
9. Vacuum debris from radiator core.	33403FUEL FILTER LW	1
10. Make Air filter for rear a/c. Install in made up frame.	33411FILTER FUEL SERIES 40	1
11. Pressure check cooling system. Diagnose various leaks. Tighten hose clamps.	33582FILTER FUEL YANMAR LW93	1
12. Service generator. R&R cover.	34BVVALVE DRAIN CLASS1	1
13. C-Inspection.	5008414CARTRIDGE DC100	1
14. Install truck height sticker.	621714 IN LIGHT	2
15. Diagnose oil leaks. Oil leaks at switch above air compressor.	67BULB 12 VOLT	4
16. Radiator coolant leak. Pressure test system - secure loose hose clamp - retorque coolant tank bolter at top and side of tank. Sight glass leaking. Remove to replace with new part - sensor leaking remove clean and apply sealant. Fill radiator. Radiator cap. Secure radiator support bracket.	828001002SIGHT GLASS SAME AS 17KP655	1
17. Left cap lift cylinder see page not quite a class 1.	906LIGHT BULB 12CP	3
18. front sump line drain valve malfunction - remove and install new drain valve.	91-20WIPER BLADE 20 IN	2
19. clean engine operate looking for oil leaks no leak found from turbo, normal blow by through. Crank case vent clean power steering pump no leak found . Engine pressure switch leaking clean area - remove switch and instll new switch.	B-1103A1131 LENS (AMBER)	1
20. Rear ground lights inop - remove both tailboard under carriage lights and install new ones; tag light assembly inop. Repair loose ground. pump panel light loose bulb socket correct fault.	BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	2
21. Air dryer - drain oil out of front and rear air tank - replace air dryer and purge valve new.	PH713851799 FILTER OIL	1
22. Right rear cab step light. Replace blown bulb and repair positive wire connector.	PR338324070 WIX FILTER WATER	1
23. Diagnosing generator intermitting start - found shut off selonoid. Would not using age. Replace selonoid - start unit - found wire harness to controll terminate repair as per Ed Ehrke.	R950014PURGE VALVE WABCO AIR DRYER	1
24. Air leak - diagnosing air slow air leak. Secure loose air line and fittings.	TRANSYNDALLISON TRANS FLUID GAL	4
25. L-2 tool holder tray, hook and door strut inop - remove tool holder tray retap to 1/4-20 install tray - remove hook retap support hole install, door strut remove and replace support nut and washer secure hold down pin and reinstall strut.	WAT61403STRAINER 6 IN	1
	HP-31DBATTERY 950CCA HP-31D	2
	34-57434-574 SWITCH	1
	46748AIR FILTER PIERCE	1



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

- 26. Windshield wiper blades - remove defective washer spray nozzle clean tip and reinstall. (parts not in stock)
- 27. Road test after repairs.
- 28. RR inner tire valve stem core loose - secure shander valve to air tire to specs.
- 29. Unit drift to right - check alignment out by 1/16 swap tires road test no difference. Not an aggressive drift.
- 30. Q.A. Inspection - check ok.
- 31. Fill water tank.

Workorder: V53141

In Date: 10/17/2012 Meter Reading:
Close Date: 11/09/2012

Problem?

right front tire, outside edge, rubber worn down as to see first layer breaking thru to second layer. E93

Task performed:

CHK TIRE, FOUND TIRE OK, DOES NOT NEED TO BE CHANGED.

Parts	Quantity
NO PARTS USED	

Workorder: V53209

In Date: 10/19/2012 Meter Reading:
Close Date: 11/09/2012

Problem?

E93 Back up alarm is not working. E93

Task performed:

REPLACED ALARM, AND TESTED- REPAIRED GROUND WIRE. AIR LEAK, REPAIRED AIR LEAKS.

Parts	Quantity
6010760-107 BACK-UP ALARM OE	1

Workorder: V53384

In Date: 10/30/2012 Meter Reading: 142,561.00
Close Date: 11/16/2012

Problem?

INSTALL FILTER ORDERED FOR GENERATOR E 93

Task performed:

INSTALLED FILTER AND RAN GENERATOR.

Parts	Quantity
114650-12591AIR FILTER YANMAR LW93	1



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V53765

In Date: 11/14/2012
Close Date: 12/14/2012

Meter Reading: 142,787.00

Problem?

INSTALL 20 INCH BAR AND CHAIN ON SAW SEE WAYNE FOR PARTS E93

Task performed:

INSTALLED NEW 20 INCH BAR AND CHAIN ON SAW.

Parts

NO PARTS USED

Quantity

Workorder: V54077

In Date: 11/29/2012
Close Date: 12/19/2012

Meter Reading: 143,197.00

Problem?

REPAIR TIRE

Task performed:

REPAIR TIRE.

Parts

NO PARTS USED

Quantity

Vendor?: BOULEVARD TIRE

Workorder: V54305

In Date: 12/08/2012
Close Date: 01/03/2013

Meter Reading:

Problem?

2 lights are out on the pump panel E 93

Task performed:

REPAIRED SHORT IN PUMP PANEL LIGHTS.

Parts

NO PARTS USED

Quantity

Workorder: V56055

In Date: 02/27/2013
Close Date: 04/05/2013

Meter Reading: 143,621.00

Problem?

Smells like a clutch burning smell and alternator not charging reading 10volts running. Did not have time to look and see if a/c locked up or the cause. e95

Task performed:

1. REPLACED STARTER SOLENOID AND TESTED.
2. REMOVED ALL NUMBER SIGNS.

Parts

NO PARTS USED

Quantity



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V48326

In Date: 04/01/2012

Meter Reading:

Close Date: 04/08/2013

Problem?

HYDRAULIC SLAVE CYLINDER FOR RAISING CAB LEAKING FLUID - OIL LEVEL LOW -ALSO SUPPLIES LADDER LIFT - NE HYDRAULIC AND MOTOR OIL.... E93

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V49579

In Date: 05/23/2012

Meter Reading:

Close Date: 04/08/2013

Problem?

Requesting a speaker for the rear cab of the Engine. Firefighter CAN NOT hear fire main with diesel engine noise while engine is running. THANK YOU!! :)

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V55487

In Date: 02/01/2013

Meter Reading:

Close Date: 04/18/2013

Problem?

THE MDC IS NOT GETTING POWER THE LAPTOP WILL NOT TUEN ON AND THE DOCKING STATION IS ALSO NO GETTING POWER NO LIGHTS, NO POWER TO DOCKING STATION. MDC 10-7 UNTILL REPAIRED. CANNOT GET CALLS OR INFO, MAPPING NO MDC.

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V56194

In Date: 03/06/2013

Meter Reading:

Close Date: 05/03/2013

Problem?

Need 7(seven) D handles with locks installed @ TRAINING

Task performed:

Parts

Quantity

INSTALLED HANDLES.

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V57104

In Date: 04/17/2013

Meter Reading:

Close Date: 05/29/2013

Problem?

Engine runs rough when started. A lot of smoke comes out exhaust. Sounds like the engine has a miss. After a while the miss clears up and engine runs smooth. E95

Task performed:

REPAIR ON NEXT PM.

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V58338

In Date: 06/11/2013

Meter Reading: 143,621.00

Close Date: 07/19/2013

Problem?

B inspection E95

Task performed:

1. B-INSPECTION.
2. FEDERAL QUE INSTALL - MOUNT UNIT ON FRONT BUMPER AND REWIRE AND SECURE.
3. LADDER RACK HYDAULIC TANK ATENA OILY - CLEAN ALL ASSOCIATED PARTS, OPERATE SYSTEM AND LOOK FOR LEAKS NONE FOUND RESOUIOR 3/4 FULL.
4. RIGHT FRONT TIRE HAS SCREW - REMOVE TIRE LEAKING - SLOW LEAK. TIRE REPAIR AT SHOP VIA TIRE SHOP.
5. EXHAUST SYSTEM LEAKING - REMOVE FLEXPipe, PIPE EXTENSION, HANGERS, SUPPORT RODS DAMAGE LOOSEN MUFFLER, CUT NEW FLEX PIPE AND 4 INCH EXTENSION - REASSEMBLE, INSTALLNEW CLAMPS SECURE.
6. TURBO OIL LINE LEAKING AT FLANGE - CLEAN AND RETORQUE FLANGE BOLTS.
7. PUMP PRIMER OPERATING INTERMITTING - DIAGNOSE FAULT - FOUND MANUEL ELECTRIC PRIMER VALVE STICKING - CLEAN PRIMER, DRI LUBE CABE ASSEMBLEY AND OPERATE, CHECK CABLE ROUTING FOR KINKS AND READJUST CABLI
8. PUMP PANEL LIGHT AND TAILBOARD LIGHT INOP- REPLACE BLOWN BULBS AND CLEAN CORRODED GROUND AND SHORT TO GROUND.
9. AULT OUT PART 14.8V? REMOVE ALL CONNECTIONS, CLEAN AND INSPECT REMOVE REGULATOR CLEAN CONTACTS AND REASSEMBLE. ?????? AT HI AND LO IDLE TEST ALTERNATOR OUT PUT LOADED AND NO WIRE 13.7 - 14.3 REGULATOR DISCONN 12.2 CONNECTED SYSTEM OPERATE TO SPECS.
10. POWER STEERING FILTER AND OIL SERVICE.
11. PULLS TO RIGHT - TIRES IN GOOD CONDITION - SWAP TIRES LEFT AND RIGHT - ROAD TEST PULL - PULL AT A MINIMUM. CHECK ALL STEERING LINKAGE AT POINT GOOD.
12. Q & A.

Parts

Quantity

0714023GASKET 3.5 IN	2
1141BULB	1
1817677C91FUEL FILTER SCREEN ASSY	1
20A-400CLAMP 4" 33969	2
33403FUEL FILTER LW	1
33411FILTER FUEL SERIES 40	1
357884 IN CLAMP	2
40022STAINLESS FLEX PIPE 4"	5
621714 IN LIGHT	1
92541676VAC TEST GAUGE 0-30	1
94993PIGTAIL TRUCKLITE 3-WIRE	1
ACX-84534LUG NUT COVER PK10	1
FG83284DFG/HF6238 PS/HDY FILTER	1
PH713851799 FILTER OIL	1
UMVS111611STRAP	10
35103HANGAR EXHAUST	1



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V60692

In Date: 09/23/2013

Meter Reading:

Close Date: 11/25/2013

Problem?

2 Pump Panel lights not working Left rear ground light(white) not working On board generator starter hangs up

Task performed:

Parts

Quantity

1. TESTED GENERATOR AND REPAIRED GROUND WIRE AND RETESTED.
2. REPAIRED PUMP PANEL LIGHTS.

NO PARTS USED

Workorder: V61170

In Date: 12/04/2013

Meter Reading:

Close Date: 12/31/2013

Problem?

Pressure gauge inop

Task performed:

Parts

Quantity

TRACED OUT PRESSURE GAUGE FOUND UNIT NEEDS TO BE REPLACED- WILL ORDER.

NO PARTS USED

Workorder: V63356

In Date: 01/13/2014

Meter Reading: 144,261.00

Close Date: 02/03/2014

Problem?

replace pump control

Task performed:

Parts

Quantity

1. FOUND TRUCK IN P LOT. RAN EXTENSION CORDS TO VEH TO CHARGE BATTS WITH ON BOARD CHARGER.
2. BATTS STILL DEAD. HOOK UP SHOP BATTERY CHARGER TO SEE IF BATTS WILL CHARGE. JUMP START VEH. ROLLUP CORDS AND PUT CHARGER AWAY BRING VEH INTO SHOP.
3. INSTALL NEW CLASS 1 PUMP CONTROL. DOESNT WORK- WONT CALIBRATE OR GO INTO PRESSURE MODE. DIAGNOSE PROBLEM. R&R TRANSENDER. ENTER CALIBRATION MODE. SET IDLE SPEED ETC.
4. DIANGNOSE ON BOARD BATTERY CHARGER. FIND CHARGER TRACE WIRING FROM CHARGER TO BATTS. INSPECT ALL CONNECTIONS. CHECK FOR RESISTANCE.
5. CONTINUE REPAIRS & DIAGNOSE BATTERY CHARGER. REPLACE ALL TY WRADS CUT FROM HARNESS TO TRACE WIRING. R&R DISPLAY PANEL. RETEST VOLTAGE AT BATTERIES.

091-56-INDREMOTE DISPLAY

1

100581TRANSDUCER COMMAND MASTER 300 PSI

1

FREIGHTSHIPPING CHARGES

1



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V64927

In Date: 03/14/2014
Close Date: 03/14/2014

Meter Reading: 144,261.00

Problem?

Spot light bulbs

Task performed:

PARTS ONLY.

Parts	Quantity
4007BULB NIGHT FIGHTER	1
4419BULB	1

Workorder: V59679

In Date: 03/19/2014
Close Date: 03/19/2014

Meter Reading:

Problem?

Parts for training engine

Task performed:

PARTS ONLY NO LABOR.

Parts	Quantity
201L-404G200 PSI GAUGE	3
5582-10 82-2111 GROTE ON-OFF WEATHERPROOF	2

Workorder: V57850

In Date: 05/20/2013
Close Date: 04/07/2014

Meter Reading:

Problem?

Class One control on pump panel needs replaced.Can not read all the digital numbers.

Task performed:

REPAIRED ON WORK ORDER # 58338

Parts	Quantity
NO PARTS USED	

Workorder: V62059

In Date: 11/15/2013
Close Date: 04/17/2014

Meter Reading:

Problem?

2 pump panel lights out scene flood lights not working E95

Task performed:

REPAIRED ON V63356.

Parts	Quantity
63-1949GOVERNOR CAPTAIN	1
FREIGHTSHIPPING CHARGES	1



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V69607

In Date: 09/23/2014
Close Date: 09/23/2014

Meter Reading: 144,635.00

Problem?

2 air gauges to training

Task performed:

Air gauges to training.

Parts

Quantity

S986AIR GAUGE 160 PSI

1

Workorder: V68136

In Date: 07/24/2014
Close Date: 12/22/2014

Meter Reading:

Problem?

1. Tank to pump handle broken 2. Tank to pump not closing all the way 3. Front discharge not closing 4. Front discharge knob missing 5. Headlights not working 6. 2 pump panel lights out

Task performed:

repairs were completed

Parts

Quantity

NO PARTS USED

Workorder: V68137

In Date: 07/24/2014
Close Date: 12/22/2014

Meter Reading:

Problem?

7. Top speedlay valve not opening all the way.

Task performed:

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10180688

CONTENDER FIRE DEPARTMENT PUMPER NFPA

Workorder: V72012

In Date: 01/02/2015

Meter Reading: 145,223.00

Close Date: 01/20/2015

Problem?

C inspection E94

Task performed:

1. Perform C inspection
2. Continue/completed C inspection
3. Checked out alternator output at batteries and at alt output is good. Also load tested system all outputs are good, gauge on dash is slightly off.
4. Replaced wiper blades, cleaned debris from squirters ad repaired hoses going to squirters.
5. Replaced right high beam bulb (cracked)
6. Replaced left rear upper marker light bulb
7. Checked out bumper pole lights inop-found bumper poles were never wired
8. Repalced left side cab latch assembly(leaking). Replaced o-rings in fittings and topped off reservoir. Purged air from system and rechecked-no further leaks found.
9. Serviced p/s
10. Serviced air brake dryer
11. Serviced T case
12. R/R air filter to check-filter was still clean
13. Replaced pump panel light bulb

Parts

Quantity

1141BULB	1
1817677C91FUEL FILTER SCREEN ASSY	1
33403FUEL FILTER LW	1
33411FILTER FUEL SERIES 40	1
5008414CARTRIDGE DC100	1
53-4470LATCH CAB HYDRAULIC WPB	1
67BULB 12 VOLT	1
91-22WIPER BLADE	2
FG83284DFG/HF6238 PS/HDY FILTER	1
H4651USE CV TYPE SEALED BEAM	1
PH713851799 FILTER OIL	1
R950014PURGE VALVE WABCO AIR DRYER	1



Palm Beach County Fire Rescue Fleet Maintenance Asset History

Asset: (10180688) 2004 - PIERCE CONTENDER 1250 Gpm Pumper E773

10180688

CSHOP-2015-3055

Comments: BRAKE VALVE LEAKS. TOMMY HAS CHECKED IT. TRAINING

Date Opened 9-23-2015 Date Finished 10-20-2015 Meter 1 Reading: 144,635

TASKS PERFORMED

Q PARTS

AIR SYSTEM
INSTRUMENTS-GAUGES-METERS

1 VALVE; 802745 VALVE QUICK REL.

CSHOP-2015-983

Comments: E94 INSTALL MANSAVERS

Date Opened 6-4-2015 Date Finished 7-23-2015 Meter 1 Reading: 144,635

TASKS PERFORMED

Q PARTS

EMERGENCY EQUIPMENT

2 20 IN MAN SAVER

CSHOP-2016-1013

Comments: REPAIR FLAT ON TRAINING FORKLIFT ASSET#10175754

Date Opened 3-2-2016 Date Finished 3-2-2016 Meter 1 Reading: 144,635

TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2016-152

Comments: E774 REPAIR AIR LEAK

Date Opened 1-12-2016 Date Finished 1-12-2016 Meter 1 Reading: 144,635

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM

CSHOP-2016-2047

Date Opened 4-29-2016 Date Finished 4-29-2016 Meter 1 Reading: 144,635

TASKS PERFORMED

Q PARTS

BATTERY

6 BATTERY; BATTERY 950CCA HP-31D
6 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY

Service Requests:

04/29/2016 SERVICE REQUEST / 43: WEAK / EXCHANGE - NEW

Asset Work Order History 10180688

CSHOP-2016-2191

Date Opened 5-5-2016 Date Finished 6-8-2016 Meter 1 Reading: 146,463

BOBCAT LOADER HAS HYD. LEAK

TASKS PERFORMED

Q PARTS

HYDRAULIC SYSTEM

1 NEWPART; SWITCH STOP LIGHT PRESSURE

CSHOP-2016-2441

Comments: E91 FED Q INOP

Date Opened 5-20-2016 Date Finished 5-20-2016 Meter 1 Reading: 146,174

TASKS PERFORMED

Q PARTS

SIREN

1 MOTOR; SIREN MOTOR FED.Q

Asset Work Order History 10180688

CSHOP-2016-2462

Date Opened 5-23-2016

Date Finished

1-9-2017

Meter 1 Reading:

146,882

TASKS PERFORMED

TRAVEL TO BE CHARGED TO WORK ORDER
CONTROL VALVE FIRE PUMP
FIRE APPARATUS
WIPERS-WASHER
FAULT CODE
LIGHTING SYSTEM
ELECTRICAL
TIRES & WHEELS
REPAIR FROM PM - DECALS/CLEANLINESS
AIR SYSTEM
SIREN
HOOD LATCH

Q PARTS

2	VALVE; 8905 VALVE KIT 2 IN AKRON
1	HANDLE; CONTROL HANDLE PIERCE
1	BULB; BULB
1	SENSOR; OIL LEVEL SENSOR
1	NEWPART; PAN GASKET
1	NEWPART; PAN GASKET
2	WIPER; WIPER BLADE 20 IN
1	LIGHT; STEPWELL LIGHT
2	BULB; BULB
3	9IP; RED MARKER LIGHT RECTANGULAR
-1	9IP; AKRON LONG ARM RC-4
1	9IP; AKRON LONG ARM RC-4
2	INSERT; LARGE PLACARD INSERT CARD
58	9IP; 9IP
2	INSERT; FRONT AND BACK INSERT CARD
2	EMBLEM; LARGE SIDE PLACARD
2	EMBLEM; FRONT AND BACK PLACARD
6	COUPLING; COUPLING NIPPLE
1	VALVE; PURGE VALVE WABCO AIR DRYER
1	BRAKE; CARTRIDGE DC100
1	VALVE; TURBO CUT OFF VLV KIT
1	SIREN; SIREN
2	LATCH; LATCH CAB HYDRAULIC WPB

Service Requests:

05/23/2016	ENGINE / 12: BROKEN / REPAIR TANK TO PUMP HANDLE NEEDS TO BE REPLACED ITS STRIPPED OUT, FRONT DISCHARGE LEAKES AND CAP HAS TO REMAIN ON TO PREVENT HOSE FROM FILLING WHEN NOT IN USE
05/23/2016	TIRES / 12: BROKEN / REPAIR TIRES NEED REPLACED ON FRONT, ENGINE IS LOCATED AT STATION 91 NOT TRAINING IT IS BEING USED AS AN IN SERVICE UNIT
05/23/2016	SERVICE REQUEST / 12: BROKEN / REPAIR SAFETY PAD WILL NO CHARGE WHEN TRUCK IS NOT RUNNING, TIC MOUNT IS ALSO NOT CHARGING, VELCRO STRAPS TO BE MOUNTED TO SECURE HOSES. TRUCK IS LOCATED AT STATION 91 NOT TRAINING IT IS BEING USED AS AN IN SERVICE UNIT

CSHOP-2016-2686

Date Opened 6-6-2016

Date Finished

7-12-2016

Meter 1 Reading:

146,882

TASKS PERFORMED

HVAC SYSTEM

Q PARTS

3	A/C; FREON LB
---	---------------

Service Requests:

06/06/2016	ENGINE / 19: LOOSE / REPAIR LAST NIGHT NOTICE ANTI FREEZE ON FLOOR OF BAY. RAISED CAB, THERE APPEARS TO BE VERY SMALL LEAK(I BELIEVE A PIN HOLE IN CORE). ALSO ADDED 1 GALLON OF WATER.
------------	--

Asset Work Order History 10180688

CSHOP-2016-3811

Comments: **B-INSPECTION**

Date Opened 8-5-2016 Date Finished 8-5-2016 Meter 1 Reading: 147,366

TASKS PERFORMED

Q PARTS

PM SERVICE B

- 1 FILTER; FUEL FILTER SCREEN ASSY
- 1 FILTER; FILTER OIL 51799
- 1 FILTER; FILTER FUEL SERIES 40
- 1 FILTER; FUEL FILTER LW

CSHOP-2016-4119

Date Opened 8-22-2016 Date Finished 8-22-2016 Meter 1 Reading: 146,882

TASKS PERFORMED

NO PARTS USED

FIRE FIGHTING EQUIPMENT

VENDOR? REGANS SMALL ENGINE SERVICE

CSHOP-2016-4139

Date Opened 8-22-2016 Date Finished 8-22-2016 Meter 1 Reading: 146,882

TASKS PERFORMED

NO PARTS USED

TIRES ALL

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2017-2752

Date Opened 5-10-2017 Date Finished 8-10-2017 Meter 1 Reading: 147,720

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
COMMERCIAL WORK - OUTSIDE AGENCY
CONTROL VALVE

- 1 5AB; 2" BALL KIT COMPOSITE

Service Requests:

05/10/2017 SERVICE REQUEST / 11: BINDS/STICKS / REPAIR
SERVICE REQUEST NUMBER 1 SPEED LAY DISCHARGE VALVE NOT OPENING ALL THE WAY.

Asset Work Order History 10180688

CSHOP-2017-3232

Comments: **TRAINING**

Date Opened 6-2-2017

Date Finished

7-1-2017

Meter 1 Reading:

147,639

TASKS PERFORMED

Q PARTS

HYDRAULIC CYLINDER EXTENSION
PUMP PANEL
LADDER RACK BODY
HOSES-LINES & FITTINGS
COOLING SYSTEM
LIGHTING SYSTEM
BATTERY
SHORELINE CHARGER
CHARGING SYSTEM
FILTER
AIR SYSTEM
REPAIR FROM PM - DASH
FUEL GAUGE
HVAC SYSTEM

1 NONSTOCK; FREIGHT CHARGE
1 9IP; ATF DETRAN 3
2 5TN; CYLINDER
1 9IP; CAB LIFT CYL
-1 9IP; CAB LIFT CYL
1 9HY; 3/8 HOSE
3 FLUID; ALLISON TRANS FLUID GAL
14 FLUID; ALLISON TRANS FLUID GAL
1 9IP; CAP RADIATOR 10 LB
1 9IP; 4ELTUBE REFLECTOR ASSY.
2 9IP; 4 IN LIGHT
2 9IP; LIGHT BULB
6 1AD; BATTERY 31 SERIES
1 6KU; AUTO CHAGER AC2000 12V
1 FIL; NAPA TRANS FILTER
17 9OC; BULK TRANS SYN
1 TWD; C-1COCK DRAIN
2 BK; SPRAYER
1 5TN; SENDER
1 TEM; FILTER DRIER
7 9XX; 134A 10194654
2 TEM; EXPANSION VALVE
2 MAC; NON-CHLOR BRAKE CLNR
2 TEM; PAG 100 OIL

Service Requests:

06/01/2017 ENGINE / 12: BROKEN / EXCHANGE - NEW
ENGINE WILL NOT START. ENGINE CRANKS WILL TO RUN. .MAY HAVE BEEN RAN OUT OF FUEL. FUEL TANK EMBLEM WAS FLASHING ON DASH.

06/02/2017 SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW
SERVICE REQUEST FUEL GAUGE NOT READING PROPER AMOUNT OF FUEL. GAUGE ON DASH MOVES BUT READS WRONG AMOUNT OF FUEL

CSHOP-2017-3494

Date Opened 6-12-2017

Date Finished

6-14-2017

Meter 1 Reading:

147,621

TASKS PERFORMED

Q PARTS

PM SERVICE C

30 9OC; SYN 15W40
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPAGOLD OIL FILTER
30 FLUID; SYN OIL BULK QTS
1 FIL; NAPAGOLD FUEL FILTER

Asset Work Order History 10180688

CSHOP-2017-3901

Date Opened 7-1-2017 Date Finished 8-10-2017 Meter 1 Reading: 147,720

TASKS PERFORMED

NO PARTS USED

FIRE FIGHTING EQUIPMENT

VENDOR? REGANS SMALL ENGINE SERVICE

CSHOP-2017-682

Comments: **TRAINING**

Date Opened 2-1-2017 Date Finished 3-22-2017 Meter 1 Reading: 146,882

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
ENGINE AND ACCESSORIES

Service Requests:

01/31/2017 ENGINE / 33: REGISTERS WRONG / INSPECT
ENGINE CHECK ENGINE LIGHT ON

CSHOP-2018-3783

Comments: **INSPECT ONLY NO OIL/FILTERS**

Date Opened 7-5-2018 Date Finished 7-24-2018 Meter 1 Reading: 148,011

TASKS PERFORMED

NO PARTS USED

PM SERVICE B

CSHOP-2018-4440

Date Opened 8-8-2018 Date Finished 8-13-2018 Meter 1 Reading: 148,020

TASKS PERFORMED

NO PARTS USED

COMMERCIAL WORK - OUTSIDE AGENCY

VENDOR? DAN CALLAGHAN ENTERPRISES

Service Requests:

08/08/2018 TIRES / 18: LEAKING / CLEAN
BAD TIRES LEFT REAR INNER TIRE FLAT GOODYEAR 12R22.5 G287 MSA

Asset Work Order History 10180688

CSHOP-2018-816

Date Opened 2-8-2018

Date Finished

7-30-2018

Meter 1 Reading:

148,020

TASKS PERFORMED

	<u>Q</u>	<u>PARTS</u>
WATER TANK LEVEL LIGHTS	2	5SC; 12CHAIN
SCBA BRACKETS	2	LMP; LAMP
FIRE PUMP CONTROLS	1	5TN; 35INWATERFLANGE
PUMP PANEL	1	9ME; LANYARD LATCH
FIRE PUMP	1	9IP; XE-IO3100PT3-S0B 600 TRANSDUCER INT
LADDER RACK BODY	1	MAC; MACS CHAIN CABLE LUBE
DISCHARGE GAUGE	1	9AP; SWITCH,SPST,ON/OFF ROCKER W/RED
UL REPAIRS	1	5TN; ROD CONTROL TOP MNT
PARK BRAKE	1	5TN; CLEVIS 50 ZINC
STROBE LIGHTS	1	5TN; CONTROL HANDLE TOP MT MACH
GRILLE	1	5AB; 2" BALL KIT COMPOSITE
BODY EXTERIOR	1	5AB; 3- 3.5 BALL KIT COMPOSITE
CAB-INTERIOR ACCESSORIES	1	9IP; STRAINER 6 IN
DOOR ALARM OR OTHER WARNING	1	5AB; 2" BALL KIT COMPOSITE
	1	5TN; KNOB LOCK BLACK
	3	5AB; 2.5 BALL KIT COMPOSITE
	1	5AB; 2.5 BALL KIT COMPOSITE
	2	5TN; BALL VALVE 2 1/2
	1	5AB; 1.5 BALL KIT
	1	5TN; 2IN GAUGE -30/400
	1	FRT
	1	9HD; RELAYVALVEDBLCHK
	1	2FL; BENDIXR14VALVE
	1	8GR; BULB, HALOGEN, TWISTLOCK
	1	8GR; BULB, HALOGEN, TWISTLOCK
	1	9IP; WINDOW CRANK HANDLE
	1	9HY; HOSEMADE

Service Requests:

02/07/2018 SERVICE REQUEST / 12: BROKEN / REMOVE AND INSTALL NEW CONTROL
SEE ATTACHED FILE

CSHOP-2019-1259

Comments: **PARTS ONLY**

Date Opened 3-8-2019

Date Finished

3-9-2019

Meter 1 Reading:

0

TASKS PERFORMED

	<u>Q</u>	<u>PARTS</u>
MOUNT	9	9ME; STRAP 25"-44"
DOOR	2	5AH; GAS SPRING, 20", 65 LB

Service Requests:

03/08/2019 BODY / 44: WORN / EXCHANGE - NEW
NEED HYDRAULIC SUPPORT FOR R-2 COMPARTMENT DOOR I WILL BRING OLD ONE TO MATCH UP NEW PART

Asset Work Order History 10180688

CSHOP-2019-2665

Date Opened 5-24-2019 Date Finished 7-25-2019 Meter 1 Reading: 148,877

TASKS PERFORMED

	<u>Q</u>	<u>PARTS</u>
TRAVEL TO BE CHARGED TO WORK ORDER	7	9HC; FITTING10
LADDER RACK BODY	6	5PF; 5PF
DISCHARGE GAUGE	2	9LA; ASSY
HOSES-LINES & FITTINGS	1	WD; WD40 12OZ SPRAY
LIGHTING SYSTEM	1	MMM; SUPERWTHRSTRPADHV
AIR GAUGE	1	5PF; 2INGAUGE30400
HVAC SYSTEM	1	4PC; 15W40PREMIUMBLUEOIL
	1	LIT; LENS
	1	LIT; MARKER L
	3	5TN; 2INGAUGE30400
	1	9GP; COMPRESSOR
	8	9XX; AC FREON 10174676
	1	9HC; CUSTOM HOSE
	3	TEM; PAG 100 OIL
	7	9HC; FITTING10
	1	TEM; FILTER DRIER

Service Requests:

05/23/2019 SERVICE REQUEST / 18: LEAKING / REPAIR
BOTH LADDER RACK MOTORS LEAKING MOST OF THE PUMP PANEL GAUGES NOT WORKING

CSHOP-2019-320

Comments: **DETAIL**
Date Opened 1-17-2019 Date Finished 1-26-2019 Meter 1 Reading: 0

TASKS PERFORMED

	<u>Q</u>	<u>PARTS</u>
REPAIR FROM PM - DECALS/CLEANLINESS	1	9AP; DETAIL

CSHOP-2019-5305

Date Opened 10-8-2019 Date Finished 10-10-2019 Meter 1 Reading: 148,923

TASKS PERFORMED

	<u>Q</u>	<u>PARTS</u>
PM SERVICE C	-1	FIL; NAPAGOLD AIR FILTER
	1	FIL; NAPAGOLD AIR FILTER
	1	FIL; FIL
	30	4PC; 15W40 PREMIUM BLUE OIL
	1	FIL; NAPAGOLD FUEL FILTER
	1	FIL; NAPAGOLD OIL FILTER
	1	FIL; NAPAGOLD FUEL FILTER

Asset Work Order History 10180688

CSHOP-2019-5332

Date Opened 10-9-2019 Date Finished 10-22-2019 Meter 1 Reading: 148,923

TASKS PERFORMED

Q PARTS

FIRE FIGHTING EQUIPMENT	2	9AP; PIGTAIL 10K PSI
PRIMING PUMP FIRE PUMP	1	5HP; EPS PRIMER PUMP
PARK-CLEARANCE LIGHTS	1	LMP; LAMP
HEADLIGHTS LOW BEAM	1	GRO; STEPWELL LICENSE LAMP
LIGHTING SYSTEM	1	LMP; LAMP RE ORDER BLISTER PK
HUB CAP	1	LMP; LAMP, RO BLISTER PK
STEERING WHEEL	1	9IP; PLUG HUB OIL CAP
STEERING	1	FIL; NAPA HYDRAULIC FILTER
UPHOLSTERY	3	9OC; BULK TRANS SYN

CSHOP-2020-4139

Date Opened 8-11-2020 Date Finished 3-3-2021 Meter 1 Reading: 0

TASKS PERFORMED

Q PARTS

FIRE APPARATUS	1	5CS; GOVERNOR 10 8
----------------	---	--------------------

Service Requests:

08/11/2020 SERVICE REQUEST / 18: LEAKING / REPAIR
TRUCK WILL GO INTO PUMP GEAR, HOWEVER YOU CAN NOT THROTTLE UP ON THE PUMP PANEL. CHECKED WITH
CREW OPERATING CORRECTLY

CSHOP-2020-4756

Comments: **INSPECT ONLY NO OIL/FILTERS**

Date Opened 9-12-2020 Date Finished 9-16-2020 Meter 1 Reading: 149,147

TASKS PERFORMED

NO PARTS USED

PM SERVICE B

CSHOP-2020-4800

Date Opened 9-14-2020 Date Finished 9-16-2020 Meter 1 Reading: 149,147

TASKS PERFORMED

NO PARTS USED

DIAGNOSE ELECTRICAL
EMERGENCY EQUIPMENT

CSHOP-2020-5780

Date Opened 11-2-2020 Date Finished 11-10-2020 Meter 1 Reading: 149,224

TASKS PERFORMED

Q PARTS

PRIMING PUMP FIRE PUMP	1	5HP; EPS PRIMER PUMP
------------------------	---	----------------------

Asset Work Order History 10180688

CSHOP-2021-1140

Date Opened 3-1-2021 Date Finished 3-2-2021 Meter 1 Reading: 149,224

TASKS PERFORMED

NO PARTS USED

DIAGNOSE ELECTRICAL

CSHOP-2021-1558

Date Opened 3-23-2021 Date Finished 4-8-2021 Meter 1 Reading: 149,487

TASKS PERFORMED

NO PARTS USED

DOOR LATCH

CSHOP-2021-4786

Date Opened 8-23-2021 Date Finished 8-25-2021 Meter 1 Reading: 149,784

TASKS PERFORMED

Q PARTS

SAFETY INSPECTION

1 9AP; OIL SAMPLE TEST KIT PETRO CANADA
30 4PC; 15W40 PREMIUM BLUE OIL
1 1FG; FUEL FILTER 3404
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPAGOLD OIL FILTER

CSHOP-2021-4788

Comments: **REPAIR LIST ON RELATED FILES**

Date Opened 8-23-2021 Date Finished 8-25-2021 Meter 1 Reading: 149,784

TASKS PERFORMED

Q PARTS

FIRE APPARATUS
WIPER BLADES
COOLING SYSTEM
REPAIR FROM PM - TILT CAB
OIL
ENGINE AND ACCESSORIES
LIGHTING SYSTEM
DOOR

2 1AN; 22 WIPER BLADE
2 2IH; 50 50 COOLANT FLEETGUARD
1 2IH; SENSOR
2 GRO; BHIVE LMP MRKR W FIX

CSHOP-2021-5113

Date Opened 9-10-2021 Date Finished 9-13-2021 Meter 1 Reading: 149,786

HEAD LIGHT OUT

TASKS PERFORMED

Q PARTS

HEADLIGHTS LOW BEAM

1 LMP; LAMP

Asset Work Order History 10180688

CSHOP-2021-5191

Comments: **INSPECT ONLY**

Date Opened 9-15-2021 Date Finished 9-15-2021 Meter 1 Reading: 149,786

TASKS PERFORMED

NO PARTS USED

INSPECTION

CSHOP-2022-4959

Comments: **TRAINING 773 INSPECTION ONLY**

Date Opened 9-14-2022 Date Finished 9-14-2022 Meter 1 Reading: 14,041

TASKS PERFORMED

NO PARTS USED

INSPECTION

RADIO-2018-1216

Comments: **INSTALL NEW MDC MOUNT & CLEAN UP WIRING.**

Date Opened 11-28-2018 Date Finished 11-28-2018 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

PC RELATED

Service Requests:

11/28/2018 RADIO / /
INSTALL NEW MDC MOUNT
