



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V1504

In Date: 02/14/2006
Close Date: 03/10/2006

Meter Reading:

Problem?

SET UP NEW VECHICLE, Q-15

Task performed:

See B Inspection pre-printed form

Parts	Quantity
14-7014HGR-1 HELMET HOOK	2
3085-195-000HORIZ.MOUNT	2
3095-155-0003095-155-000 BOLT CUTTER	1
373-2.5E-Z LOK BRACKET	2
5025TERMINAL BOX	1
5269LPVM-5 SM MOUNT	5
AWMBAWMB AXE WALL BRACKET	2
CYBS24268011CYBS-2426-80-11 STRAP	1
CYBS27299011 STRAP 36IN	1
LPVM-7LG MOUNT	6
PAPCAXE COVER PLASTIC W/CHAIN	1
SAHSVS2510STRAP	2
TH2QUIC-MOUNT TOOL HOLDER	1
TH92JHS60 DEGREE JL RAM HOLDER	6
UMVS056511STRAP	1
UMVS111611STRAP	2
UMVS162511STRAP	1

Workorder: V1638

In Date: 02/27/2006
Close Date: 03/16/2006

Meter Reading:

Problem?

CHECK FRONT STEERING, Q-15

Task performed:

Parts	Quantity
NO PARTS USED	

Vendor?: TIRESOLES



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V1814

In Date: 03/10/2006

Meter Reading:

Close Date: 03/27/2006

Problem?

P/SIDE HANDLIGHT LENS MELTED, Q-15

Task performed:

Parts

Quantity

A1211593054HOSE DISCHG

1

Workorder: V1973

In Date: 03/27/2006

Meter Reading:

Close Date: 03/29/2006

Problem?

CHECK FUEL GAUGE, Q-15

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1862

In Date: 03/16/2006

Meter Reading:

Close Date: 04/03/2006

Problem?

OFFICER SIDE RPM INOP, DOOR ALARM GOES OFF, D/SIDE MIRROR NEED ADJUST, CHECK POWER STEERING CAP, Q-15

Task performed:

Parts

Quantity

14-7014HGR-1 HELMET HOOK

4

CYBS21237011CYBS21237011 STRAP

1

CYBS27299011 STRAP 36IN

1

UMVS254411STRAP 46 IN

1

Workorder: V2047

In Date: 03/31/2006

Meter Reading:

Close Date: 04/03/2006

Problem?

HYDRANT WRENCH FROZEN, Q-15

Task performed:

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V2141

In Date: 04/07/2006

Meter Reading:

Close Date: 04/11/2006

Problem?

PICK UP COVER AT STA, 15

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1610

In Date: 02/23/2006

Meter Reading:

Close Date: 05/11/2006

Problem?

SIREN/HORN HANDS FREE INOP, HAND LIGHT INOP, Q-15

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V2841

In Date: 06/05/2006

Meter Reading:

Close Date: 06/07/2006

Problem?

WATER LEAK ON L/SIDE A/C FAN, Q-15

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V3052

In Date: 06/20/2006

Meter Reading:

Close Date: 06/23/2006

Problem?

GREASE LADDER, Q-15

Task performed:

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V3113

In Date: 06/02/2006

Meter Reading:

Close Date: 06/23/2006

Problem?

oil leak from engine (outside agency-Fla Detroit/Allison) Q15

Task performed:

Parts

Quantity

NO PARTS USED

Vendor?: FLOR0311B

Workorder: V3189

In Date: 07/03/2006

Meter Reading:

Close Date: 07/06/2006

Problem?

REPAIR DOOR OPEN CIRCUIT

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V3230

In Date: 06/30/2006

Meter Reading:

Close Date: 07/10/2006

Problem?

ON CALL DOOR OPEN CIRCUIT STAYS ON Q15

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V3070

In Date: 06/21/2006

Meter Reading:

Close Date: 07/24/2006

Problem?

water tower flow meter is not working and the foam metering knob will not turn, Q-15

Task performed:

Parts

Quantity

HR149460107MOUNT VIBRATION (NEWER POWER UNITS

8



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V3275

In Date: 07/03/2006

Meter Reading:

Close Date: 07/24/2006

Problem?

Back-up alarm not working. Q15

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V3250

In Date: 07/01/2006

Meter Reading:

Close Date: 07/28/2006

Problem?

backup alarm 10/7 Q15

Task performed:

Parts

Quantity

575BACKUP ALARM ECCO 107 DEC 2

FSC17492134NC SW PARK BK SPADE TYPE CONNECTOR 1

K080570BELT 1

VCC/36000006A/C FILTER CAB M2 1

Workorder: V3683

In Date: 07/28/2006

Meter Reading:

Close Date: 07/31/2006

Problem?

hyd line dumping oil on ground possible from turn table Q15

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V3752

In Date: 08/03/2006

Meter Reading:

Close Date: 08/10/2006

Problem?

headlight on left front low beam 10/7 Q 15

Task performed:

Parts

Quantity

4912-14912-1 FOG LAMP 2



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V3860

In Date: 08/09/2006

Meter Reading:

Close Date: 08/18/2006

Problem?

cab a/c vent not blowing air/ driver side 10/7 Q15

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1917

In Date: 03/21/2006

Meter Reading:

Close Date: 10/03/2006

Problem?

110 VOLT RECEPTACLES INOPERATIVE Q15

Task performed:

Parts

Quantity

A39012-004PS DIP STICK NEW QUINT TRW

1

Workorder: V4415

In Date: 09/13/2006

Meter Reading:

627.00

Close Date: 10/03/2006

Problem?

B INSPECTION AND REPAIRS AS NEEDED Q 15

Task performed:

REPAIR FUEL GAUGE, AC BELT , LADDER BED LT GOES OFF WHILE DRIVING, INSTALL FLOW METER, HORN BUTTON FOR SIREN , MOUNT GLOVE BOXES CHECKED FRT A/C. PRESSURE BAD. EVACUATE & CHARGE & RECHECK PRESSURE. NO GOOD. REMOVE 1 1/2 LBS FREON & OIL RECHECK FRT A/C NOW IN GOOD WORKING ORDER. TROUBLE SHOOT SIREN NOT RECIEVING SIGNAL FROM HORN SWITCH.

Parts

Quantity

29526898 29548988 TRANS FILTER ALLISON

1

33063FUEL FILTER ONAN

1

353R023HURST HOSE W/O SWIVEL

1

4025130FUEL PRESS SENSOR

1

50-24WIPER BLADE - KME

2

51064OIL FILTER ONAN

1

5155SPARK PLUG NGK FR4 REPLACES RC12YC

1

524740830-805 A/F HONDA 17210-ZE1-505

1

LF18TS-LEDMAP LIGHT LED 18 IN

1

P1147GFUEL FILTER 33120 WIX DELCO TP916

1

PH47 51758 L/F PH725 OIL FILTERL

1

PH7405 51971 OIL FILTER WIX

2

PS683033442 FUEL FILTER

1



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V4682

In Date: 10/02/2006
Close Date: 10/10/2006

Meter Reading: 627.00

Problem?

ON CALL LADDER QUIT OPERATING Q15

Task performed:

1. TRAVELED TO STN 15 FOUND LADDER INOP. FOUND BROKEN WIRING BED LADDER WITH EMERGENCY SYSTEM.

Parts

NO PARTS USED

Quantity

Workorder: V4695

In Date: 10/02/2006
Close Date: 10/26/2006

Meter Reading: 627.00

Problem?

repair wiring on turn table q15

Task performed:

1. REPAIRED 32 WIRES ON TURN TABLE AND TESTED LADDER. LADDER IN GOOD WORKING ORDER.

Parts

NTE5812DIODE

Quantity

1

Workorder: V4739

In Date: 10/04/2006
Close Date: 10/26/2006

Meter Reading: 538.00

Problem?

LADDER IS STUCK IN MASTER STREAM MODE AND WILL NOT CHANGE TO RESCUE MODE WITH SWITCH

Task performed:

1. TRAVELED TO STN 15. FOUND BAD CONNECTION IN WIRING FOR LADDER RESCUE MODE SWITCH. TEST/ LADDER NOW IN GOOD WORKING ORDER.

Parts

NO PARTS USED

Quantity

Workorder: V5127

In Date: 10/28/2006
Close Date: 11/14/2006

Meter Reading: 549.00

Problem?

door ajar alarm sounding continually.

Task performed:

1 repair door ajar alarm

Parts

NO PARTS USED

Quantity



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V5148

In Date: 10/30/2006
Close Date: 12/04/2006

Meter Reading: 667.00

Problem?

REINSTALL REMOTE FOR LADDER Q15

Task performed:

Parts

Quantity

- 1. repair done on wo #3023

NO PARTS USED

Workorder: V5667

In Date: 12/04/2006
Close Date: 12/04/2006

Meter Reading: 7,578.00

Problem?

REINSTALL REMOTE CONTROL UNIT FOR ARIEL Q15

Task performed:

Parts

Quantity

- 1. drive to sta. install circuit braker

NO PARTS USED

Workorder: V6503

In Date: 01/27/2007
Close Date: 01/31/2007

Meter Reading: 7,838.00

Problem?

throttle sticking on hurst power unit Q15

Task performed:

Parts

Quantity

- 1. TRAVELED TO STN 15. WORK ON HURST UNIT CARB, CLEAN UP, TEST/ OK.

NO PARTS USED

Workorder: V6640

In Date: 02/06/2007
Close Date: 03/08/2007

Meter Reading: 653.00

Problem?

air bag light remains on during operation q15

Task performed:

Parts

Quantity

- 1. Drive to station and checked the wiring ok. Need program to look at system.
- 2. Talk with Ed about program to find problem with air bags.
- 3. Drive to station with Ferrara warranty person and assisted with repair

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V7007

In Date: 03/01/2007

Meter Reading: 757.00

Close Date: 03/14/2007

Problem?

rightside out rigger is leaking q15

Task performed:

Parts

Quantity

1. Remove cover found ram leaking at cylinder call Scott and reported
2. Repaired by Ferrara

NO PARTS USED

Workorder: V7169

In Date: 03/12/2007

Meter Reading: 757.00

Close Date: 03/19/2007

Problem?

left front tire is worn on inside q15

Task performed:

Parts

Quantity

1. Drive to station. Check tire called ED E. to have replaced and aligned

NO PARTS USED

Workorder: V7218

In Date: 03/15/2007

Meter Reading: 757.00

Close Date: 03/21/2007

Problem?

driverside wiper blade is coming apart Q15

Task performed:

Parts

Quantity

1. Drive to station. Repair wipers, nuts loose. Did not have new wiper on truck
2. Drive to station. Installed new wipers

50-24WIPER BLADE - KME

2

Workorder: V7232

In Date: 03/16/2007

Meter Reading: 8,722.00

Close Date: 03/23/2007

Problem?

REPLACE TIRES AT STA 15 CALLAGHAN ENT Q15

Task performed:

Parts

Quantity

1. Replace Tires at Sta 15 Callaghan Ent

NO PARTS USED

Vendor?: CALLAGHAN ENT



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V7587

In Date: 04/09/2007 Meter Reading: 757.00

Close Date: 04/11/2007

Problem?

right out rigger is leaking fluid Q15

Task performed:

Lowered right outrigger and found leak at cylinder.
Contacted Ed and reported to him

Parts

NO PARTS USED

Quantity

Workorder: V7832

In Date: 04/20/2007 Meter Reading: 8,722.00

Close Date: 04/26/2007

Problem?

repair per aerial inspection Q15

Task performed:

Cradle pads missing or loose. Drilled out broken screws
& installed new pads.
Lubricated left/right outriggers.
Replaced bulb in operators light.
Repaired micro switch arm.
Adjusted ladder cables.
Installed trinary switches for cab A/C.
Ferrara rem/replc r/side stabilizer eye.
Installed pad for ladder

Parts

752-0001NYLA WEAR PADS
FREIGHTSHIPPING CHARGES

Quantity

2
1

Workorder: V7233

In Date: 03/16/2007 Meter Reading: 8,722.00

Close Date: 04/30/2007

Problem?

FRONT END ALIGN TIRESOLES Q15

Task performed:

Elpex Front end alignment

Parts

NO PARTS USED

Quantity

Vendor?: ELPEX



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V7919

In Date: 04/25/2007

Meter Reading: 757.00

Close Date: 05/08/2007

Problem?

direct tank fill/garden hose attachment does not work. We just got a coupling for it and tried it for the first time and it does not work q15

Task performed:

Parts

Quantity

Take valve apart-chk line; order new valve.
Ferrara will repair

NO PARTS USED

Workorder: V6150

In Date: 01/08/2007

Meter Reading: 7,838.00

Close Date: 05/15/2007

Problem?

U L TEST UNIT NATIONAL TESTING Q15

Task performed:

Parts

Quantity

Aerial Testing

NO PARTS USED

Vendor?: CONAM

Workorder: V7685

In Date: 04/13/2007

Meter Reading: 757.00

Close Date: 05/15/2007

Problem?

front cab a/c blowing hot air, rear a/c ok. Q15

Task performed:

Parts

Quantity

Check freon & wiring; fill

NO PARTS USED

Workorder: V8549

In Date: 06/02/2007

Meter Reading: 932.00

Close Date: 06/06/2007

Problem?

ladder/outtrigger alarm won't shut off. mech came in sat. and disconnected. still have alarm in cab, but not as loud as before.

Task performed:

Parts

Quantity

1. Drive to Sta 15, check alarm system - could not fix.
Disconnected Alarm buzzer

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V8341

In Date: 05/21/2007 Meter Reading: 10,361.00
Close Date: 06/11/2007

Problem?

on call door ajar It going off q15

Task performed:

Parts

Quantity

1. Travel, found door ajar alarm on but no low air alarm 7 Driver said air was 130psi when alarm was on & said came on when driving through water. Checked screen which indicated step switch, checked connection, checked power and ground, checked operation of switch OK. ried ypass of switch. Clean and dry connetions in wiring harness could not locate problem. Will re-check in morning later after truck has dried. Travel home

NO PARTS USED

Workorder: V8595

In Date: 06/05/2007 Meter Reading: 10,587.00
Close Date: 06/20/2007

Problem?

outrigger alarm going off Q15

Task performed:

Parts

Quantity

1. Drive to station Y bad at node replaced test ok

NO PARTS USED

0

Workorder: V8966

In Date: 06/22/2007 Meter Reading: 10,587.00
Close Date: 07/02/2007

Problem?

replace tires at sta 15 callaghan ent

Task performed:

Parts

Quantity

1. replace tires

NO PARTS USED

Vendor?: CALLAGHAN TIRE

Workorder: V8964

In Date: 06/22/2007 Meter Reading: 932.00
Close Date: 07/03/2007

Problem?

OUTSIDE REAR TIRES ARE WORN q15

Task performed:

Parts

Quantity

Drive to stn; chk tire ; Called Ed to have (4) new tires installed

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V9059

In Date: 06/28/2007

Meter Reading: 932.00

Close Date: 07/03/2007

Problem?

fix right rear (above the wheel) compartment door and latch. Q15

Task performed:

1. DRIVE TO STATION. REMOVE DOOR. BRING TO SHOP FOR REPLACEMENT.

Parts

NO PARTS USED

Quantity

Workorder: V9062

In Date: 06/28/2007

Meter Reading: 10,587.00

Close Date: 07/03/2007

Problem?

repair blower and vent saw Q15 (outside agency-regan's small engine service)

Task performed:

Repair blower & vent saw - Regan's Small Engine

Parts

NO PARTS USED

Quantity

Vendor?: REGANS SMALL

Workorder: V9099

In Date: 07/02/2007

Meter Reading: 932.00

Close Date: 07/06/2007

Problem?

bulb out, driver side top rear marker light Q15

Task performed:

1. Drive to sta. R&R bulb and install back up alarm.
Test OK

Parts

575BACKUP ALARM ECCO 107 DEC

1

Workorder: V9701

In Date: 08/02/2007

Meter Reading: 11,060.00

Close Date: 08/08/2007

Problem?

heavy water leaking from quint after each call.possible from a/c. q15

Task performed:

clean out drain

Parts

78R536078R5360M 2PK FILTER AIR COND

2



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V10309

In Date: 09/07/2007

Meter Reading: 1,044.00

Close Date: 09/20/2007

Problem?

hurst tool throttle sticking q15

Task performed:

Drive to Stn; rem filter; cl n throttle valve; test-ok

Parts

NO PARTS USED

Quantity

Workorder: V10214

In Date: 09/03/2007

Meter Reading: 1,160.00

Close Date: 09/26/2007

Problem?

rubber supopr leg on the gas powered fan needs to be replaced Q15

Task performed:

1. DRIVE TO STATION, R/R FEET, TEST O.K.

Parts

FZ51368FEET RUBBER RAM-FAN

Quantity

4

Workorder: V10213

In Date: 09/02/2007

Meter Reading: 1,044.00

Close Date: 09/27/2007

Problem?

rear sliding door needs repair does not stay open Q15

Task performed:

1. DRIVE TO STATION, WORK ON DOOR, NEED TO ORDER PARTS WOODLAND IS WORKING ON IT.

2. REMOVE AND REPAIR REAR DOOR.

3. ASST. REPAIR ON REAR DOOR.

Parts

NO PARTS USED

Quantity



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V10453

In Date: 09/14/2007

Meter Reading: 1,160.00

Close Date: 10/04/2007

Problem?

b inspection and repairs as needed q15

Task performed:

1. "B" INSPECTION
2. "B" INSPECTION
3. SERVICE AIR DRYER AND PURGE VALVE
4. SERVICE T-CASE
5. SERVICE REAR END
6. R/R BATTERIES AND REPAIR BATTERY BOX WHERE CABLE WAS RUBBING
7. R/R BELTS ON FAN AND A/C, ORDER ALT. BELT
8. R/R AIR FILTER
9. SERVICE P/S
10. SERVICE GENERATOR REMOVE SIDE COVER AROUND GENERATOR AND TOP OF GENERATOR. FOUND OIL AND FUEL FILTERS, CALLED FERRARA TO FIND AIR FILTER, FOUND FILTER AIR INTAKE DUCT, HAD TO REMOVE ALL INTAKE DUCT WORK TO CHECK FILTER, REINSTALLED DUCT WORK
11. FABRICATED DOOR TO ACCESS FILTER FOR LADDER
12. FABRICATED DOOR TO ACCESS AIR FILTER FOR GENERATOR
13. ROTATED FRONT TIRES TO HELP (E. EHRKE) TEST DRIVE O.K.
14. CHECK BATTERY IN REMOTE, FOUND LOW, REPLACED BATTERY
15. FOUND CODE 6340 CHECKED CONNECTION AND CLEARED THE CODE
16. REPAIRED BRACKET FOR HURST TOOL...
17. ASSIST SHEEDY WITH MODIFACATION TO AIR INTAKE SYSTEM FOR GENERATOR SET

Parts

Quantity

Parts	Quantity
01-0381498LIGHT USE COMPLETE UNIT PRMISCC	1
0100030000SCREEN 6 IN	1
0769027STRAINER 2.5 IN	1
1212BTURTLE TILE 12X12 BLACK	2
16-31438915 VALVE CORE A/C 3544706C1	1
194BULB	10
2000071102000072100 SOLENOID HALE PRIMER	2
24211ROM STRAPS	2
5008414CARTRIDGE DC100	1
58525852 COUPLING	1
6-68-74PLUG	1
716907-0610A DRYER	1
800404USE K022105 PURGE KIT AD-IP-IS	1
91388906 VALVE KIT 2.5 IN AKRON	1
91398907 VALVE KIT 3 IN AKRON	2
9420BELT	1
9435BELT	3
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	6
CA7230WA10116 AIR FILTER 46893 WIX	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FREIGHTSHIPPING CHARGES	1
HP-31DBATTERY 950CCA HP-31D	6
K080570BELT	1
P1147GFUEL FILTER 33120 WIX DELCO TP916	1
PH47 51758 L/F PH725 OIL FILTERL	1
PH7405 51971 OIL FILTER WIX	2
PRMISCCNLA PIERCER 2 DUAL STROBE	1
PS683033442 FUEL FILTER	1
R00038DRIP SEAL ROM	1
R00072SLAT ASSEMBLY	2
RD571290 01-2616 MOTOR 12V 73R-0542 3512	1
REDG6S14023 GASKET 6 IN	2
V893276P16CHAMBER	2



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V9706

In Date: 08/03/2007 Meter Reading: 11,060.00
Close Date: 10/04/2007

Problem?

replace damaged compartment door Q15

Task performed:	Parts	Quantity
1. INSTALL COMPARTMENT DOORS	H3023-R4R4 DOOR	1

Workorder: V10925

In Date: 10/09/2007 Meter Reading: 1,044.00
Close Date: 10/23/2007

Problem?

Small fan mounted near drivers sun visor won't turn off. Also we would like to have a mount for hydrant clamp, outside on rear of truck installed if possible Q15

Task performed:	Parts	Quantity
drove to stn; rep sfw on fan; test ok	NO PARTS USED	

Workorder: V11390

In Date: 11/02/2007 Meter Reading: 1,044.00
Close Date: 11/21/2007

Problem?

the shock for the driver door compartment came apart Q-15

Task performed:	Parts	Quantity
Rework shock on door; installed new holder. j	NO PARTS USED	

Workorder: V11979

In Date: 12/08/2007 Meter Reading: 1,178.00
Close Date: 12/19/2007

Problem?

pump panel light 10-7. there is adequate lighting to operate, with the other lights on Q-15

Task performed:	Parts	Quantity
1. Travel to 15. 2. Repair ground for P/Panel light replace lense on another.	68-3963453-30LENS CLEAR FOR STRIP LIGHT	1



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V12091

In Date: 12/16/2007

Meter Reading: 1,178.00

Close Date: 12/20/2007

Problem?

LEFT REAR CAB DOOR WILL NOT OPEN FROM OUTSIDE Q-15

Task performed:

Parts

Quantity

1. Travel to 15, remove LR cab door panel and replaced linkage.

NO PARTS USED

Workorder: V12505

In Date: 01/10/2008

Meter Reading: 13,062.00

Close Date: 01/24/2008

Problem?

chainsaw on Q15 missing bolt from chainbrake-----prosaw/univent.

Task performed:

Parts

Quantity

1. Shop Meeting with Ed, Ed, Scott and Robby

NO PARTS USED

Workorder: V12597

In Date: 01/15/2008

Meter Reading: 1,178.00

Close Date: 02/04/2008

Problem?

two lights out on the pump panel q15

Task performed:

Parts

Quantity

1. Chk (2) uppere pump panel LED lights; need to order; not on service truck.

01-06635060-C90PSC0CDCR STRIP LIGHT STEADY WHITE

2

2. Drive to stn; R/R lights; test ok

j

5269LPVM-5 SM MOUNT

1

Workorder: V12790

In Date: 01/24/2008

Meter Reading: 13,062.00

Close Date: 02/04/2008

Problem?

HANDRAIL ON TURNTABLE OF Q15 IS BENT AND MISSING A SCREW.

Task performed:

Parts

Quantity

- Drive to Stn; tap screws out; tighten bolts; test ok.

j

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V12791

In Date: 01/24/2008

Meter Reading: 13,062.00

Close Date: 02/04/2008

Problem?

HYDRAULIC HOSE IS CLOGGED. TOOLS NOT WORKING q15

Task performed:

Drive to Stn;; replc line; run unit; fill w/hyd oil; test ok.
j

Parts

Quantity

180R002HURST HYD. FLUID QT

1

3530016HOSE HURST 16 ORANGE

1

Workorder: V12761

In Date: 01/23/2008

Meter Reading: 13,062.00

Close Date: 02/05/2008

Problem?

2nd entry to service chainsaw, bolt missing from brake. Also need new blades. One for saw and one for backup. 16in. provent. q1
REGANS

Task performed:

Svc chainsaw, bolt missing from brake; Needs new
blades-Regans Small Eng j

Parts

Quantity

NO PARTS USED

Vendor?: REGANS SMALL ENG

Workorder: V2835

In Date: 06/02/2006

Meter Reading:

Close Date: 02/07/2008

Problem?

WATER LEAKING INTO CAB ON L/SIDE THROUGH CEILING FAN, Q-15

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V3672

In Date: 07/28/2006

Meter Reading:

Close Date: 02/07/2008

Problem?

repair flow meter Q15

Task performed:

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V13118

In Date: 02/07/2008

Meter Reading: 13,945.00

Close Date: 02/14/2008

Problem?

remote control antenna for ladder broken off of remote.Q15

Task performed:

Parts

Quantity

1. Drive to station, pickup, take apart, needs to be soldered, gave to radio shop, they repaired and sent back.

NO PARTS USED

Workorder: V13241

In Date: 02/14/2008

Meter Reading: 1,407.00

Close Date: 02/15/2008

Problem?

right front headlight out. Q15

Task performed:

Parts

Quantity

1. Drive to station, R & R headlite, test OK

H4656USE CV TYPE HEAD LIGHT

1

Workorder: V13427

In Date: 02/22/2008

Meter Reading: 14,121.00

Close Date: 03/05/2008

Problem?

COMP DOOR 10-7 Q15

Task performed:

Parts

Quantity

1. Drive to station, rework latches on compartment doors, test OK

NO PARTS USED

Workorder: V13465

In Date: 02/25/2008

Meter Reading: 1,289.00

Close Date: 03/05/2008

Problem?

HAND RAIL TO CLIMB TO LADDER TURRET LOOSE. PASSENGER SIDE. SCREWS STRIPPED. q15

Task performed:

Parts

Quantity

1. Drive to station, inspection on ladder fly and flow water after hitting door, redrill hand rail, test OK

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V13626

In Date: 03/01/2008

Meter Reading: 1,294.00

Close Date: 03/07/2008

Problem?

headlight out low beam driver side Q15

Task performed:

Parts

Quantity

1. Drive to station, R & R headlight, test OK

NO PARTS USED

Workorder: V13766

In Date: 03/09/2008

Meter Reading: 1,317.00

Close Date: 03/12/2008

Problem?

tire wear on both front tires inside. Q15

Task performed:

Parts

Quantity

1. Drive to station, check tires, one tire has 3/32, tires are still good, called Ed. unit will be coming in for B inspection and tires 2 will be changed then.

NO PARTS USED

Workorder: V13889

In Date: 03/13/2008

Meter Reading: 1,317.00

Close Date: 03/18/2008

Problem?

Q15 mobile radio mounting problem, radio loose, needs to be remounted. one side came loose. radio is hanging by one side. possibly comm. shop job ??? If this is a comm. shop job please pass on.

Task performed:

Parts

Quantity

1. drive to station, take upper console apart, repair radio, test OK.

NO PARTS USED

Workorder: V13913

In Date: 03/17/2008

Meter Reading: 14,621.00

Close Date: 03/18/2008

Problem?

MASTER SWITCH FOR PRIMER SHUTS OFF WHEN PULLING PRIMER Q15 DRAIN HOSE NEEDS TO BE TIED UP

Task performed:

Parts

Quantity

1. Drive to station, tighten wires, test OK, tied up drain lines.

75908SWITCH BATTERY MASTER 300A

1

H3LIGHT BULB BP1255/H3 H

1



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V13991

In Date: 03/19/2008

Meter Reading: 1,317.00

Close Date: 03/24/2008

Problem?

primer not working Q15

Task performed:

Parts

Quantity

1. found cable loose at frame. ground test ok.

NO PARTS USED

Workorder: V13997

In Date: 03/19/2008

Meter Reading: 1,317.00

Close Date: 03/24/2008

Problem?

mount the hose clamp mount to the out side of Q15. done

Task performed:

Parts

Quantity

1. mount hose clamp.

NO PARTS USED

Workorder: V13998

In Date: 03/19/2008

Meter Reading: 1,317.00

Close Date: 03/24/2008

Problem?

D/O door step is broken. Trip and fall hazard. Q15

Task performed:

Parts

Quantity

1. repair door step.

NO PARTS USED

Workorder: V14000

In Date: 03/19/2008

Meter Reading: 1,317.00

Close Date: 03/24/2008

Problem?

water level lights on cab do not work correctly.

Task performed:

Parts

Quantity

1. trace wires check grounds.

2. found conection under truck rusted cleaned tested ok.

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V14001

In Date: 03/19/2008

Meter Reading: 1,317.00

Close Date: 03/24/2008

Problem?

water and foam level on command center screen not working correctly Q15

Task performed:

Parts

Quantity

1. see work order 14000.

NO PARTS USED

Workorder: V14002

In Date: 03/19/2008

Meter Reading: 1,317.00

Close Date: 03/24/2008

Problem?

we have no extra buckets of FOAM. Foam level is ok on Q15 currently.

Task performed:

Parts

Quantity

1. take foam to sta 15.

NO PARTS USED

Workorder: V14192

In Date: 03/31/2008

Meter Reading: 149,640.00

Close Date: 04/18/2008

Problem?

replace front tires at sta 15 q 15 callaghan

Task performed:

Parts

Quantity

Replace front tire at Stn15, Q15 - Callaghan

j

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V14489

In Date: 04/15/2008

Meter Reading: 14,977.00

Close Date: 04/30/2008

Problem?

front end alignment q 15

Task performed:

Parts

Quantity

Front end alignment Q15 - Callaghan

j

NO PARTS USED

Vendor?: CALLAGHAN



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V14636

In Date: 04/23/2008

Meter Reading: 1,378.80

Close Date: 05/02/2008

Problem?

cover plate missing bolts q15

Task performed:

Parts

Quantity

1. Drive to station 15, drill tap and installed new bolts

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V14194

In Date: 03/31/2008

Meter Reading: 149,640.00

Close Date: 05/06/2008

Problem?

C inspection and repairs as needed Q15

Task performed:

Parts

Quantity



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

1. C-Inspection	12105QUICK DRAIN	2
2. Clean and lubricate ladder slides and cables	15W40BSYN OIL BULK QTS	40
3. C-Inspection	16-31438915 VALVE CORE A/C 3544706C1	1
4. Clean & lube ladder adj. cables	16302RETAINER CLIP	12
5. Repair wire for L-3 compartment light	33063FUEL FILTER ONAN	2
6. Repair glove box slides	353R023HURST HOSE W/O SWIVEL	3
7. Replace all compartment hold opens	50-24WIPER BLADE - KME	2
8. Clean and lube outriggers	5008414CARTRIDGE DC100	1
9. Replace broken light bar lens	51064OIL FILTER ONAN	1
10. Clean and tighten wires on solenoid behind batteries	6256RJN6256RJN NUT-OUTER/RIGHT	3
11. Service air dryer	6535SPARK PLUG CR5HSB	2
12. Install new fittings on Engine cooler, check for leaks	680-10LAMERICAN FLAG W UV CLEAR LEFT	1
13. Tighten all radiator top tank bolts and bottom tank bolts	680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
14. Replace fitting on small tank line	74R258607-2613A RED DOT DRIER 7127	1
15. Adjust ladder cables	78241USE 8550A250A	1
16. Service generator, had to remove starter	78R536078R5360M 2PK FILTER AIR COND	1
17. Fuel filter leaking on generator, had to remove starter again & replace filter	800404USE K022105 PURGE KIT AD-IP-IS	1
18. Service transfer case	827009-003CAB LIFT CLY QUINTS 3 STAGE	2
19. Replace bolt in Right side ladder cradle	9UCAPCC9UCAPCC END CAP CLEAR	1
20. Clean & lubricate valve for foam system	EAA-8350-90UGSS6558UK STRUT-LIFT	6
21. Assist Rob with siren	H1422TSX STUD	2
22. Check in books, readjusted test, ok	H27SN12BULB	1
23. Assist Rob with Right Side cab lift cylinder	P1147GFUEL FILTER 33120 WIX DELCO TP916	1
24. R & R e-core for a/c, R & R a/c	PH47 51758 L/F PH725 OIL FILTERL	1
25. Serviced Hurst tool power unit, replaced plugs and oil. Replaced bad tool noses and filtered oil	PH7405 51971 OIL FILTER WIX	2
26. Replaced coolant hose from water manifold to air manifold to air compressor on front of engine	PS683033442 FUEL FILTER	1
27. Replaced clamp on upper radiator hose and serviced cooling system	SHIPPING CHARGESSHIPPING CHARGES	1
28. Replaced wiper blades and hoses for washer nozzle	71R755011-2624 TRINARY SWITCH A/C 1560	1
29. Checked engine and transmission codes		
30. Adjusted sensor for outrigger on left side, alarm was going off intermittently		
31. Checked garden hose fillport on pump panel for clog, ok		
32. Checked transmission and temp gauges on pump panel, no problems		
33. Checked foam system for not working, found clogged valve, cleaned and lubed		
34. Interlock for ladder down out of adjustment, called Smeel and adjusted per instructions		
35. Adjusted load minder and tested		
36. Installed flag decals		
37. Secured loose door hinges on doors for stabilizer controls		
38. Assist Bill with trans mount		
39. Traced wiring for water level gauges, found 3 way connector wiring faulty.		



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

- Recrimped all wires, ok
- 40. Hands free siren inoperative on wheel, traced faulty wire on Q-Switch
- 41. Evacuated front A/C and recharged. Evacuated rear A/C, found low and leaking, ordered E-Core
- 42. Removed drivers step (caracked) welded crack, reinforced step, reinstalled
- 43. Cab lift cylinder leaking R & R cylinders
- 44. Assist Bill with E-core installation
- 45. Fab and weld new hubcap bolt

Workorder: V14710

In Date: 04/27/2008 Meter Reading: 1,378.80
Close Date: 05/06/2008

Problem?

5" front swivil intake locking screw is stuck. This makes the swivil a little tight, but it is still moveable. Q15

Task performed:	<u>Parts</u>	<u>Quantity</u>
1. FREE UP LOCKING SCREW-TESTED OK	NO PARTS USED	

Workorder: V14767

In Date: 04/29/2008 Meter Reading: 1,393.00
Close Date: 05/06/2008

Problem?

one lug nut cover is missing on left front wheel q47

Task performed:	<u>Parts</u>	<u>Quantity</u>
1. INSTALL COVER	NO PARTS USED	

Workorder: V14893

In Date: 05/06/2008 Meter Reading: 1,399.00
Close Date: 05/23/2008

Problem?

work request to add a Double Female holder bracket on the OIC side pump panel. q15

Task performed:	<u>Parts</u>	<u>Quantity</u>
1. Drive to station , install holder	373-2.5E-Z LOK BRACKET	1



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V15243

In Date: 05/21/2008
Close Date: 06/06/2008

Meter Reading: 1,431.00

Problem?

The chain saw on Q15 is leaking oil all over the rear ladder compartment. A chain saw with a case may solve this problem and we could move the chain saw up in the storage bin next to the generator. Thanks

Task performed:

Drive to Stn; test run new chain saw with them & drop off. j

Parts

NO PARTS USED

Quantity

Workorder: V15352

In Date: 05/27/2008
Close Date: 06/09/2008

Meter Reading: 1,445.00

Problem?

the end of the 77' ladder (the yellow break away part) is bent. q15

Task performed:

Drive to Stn; chkd; need new part; talked w/Ed O. about ordering. j

Parts

NO PARTS USED

Quantity

Workorder: V13992

In Date: 03/19/2008
Close Date: 06/17/2008

Meter Reading: 1,317.00

Problem?

ladder tip broken off. 35 FT. ladder. need new tip. Q15

Task performed:

no parts in stock parts on order

Parts

NO PARTS USED

Quantity

Workorder: V14677

In Date: 04/24/2008
Close Date: 06/17/2008

Meter Reading: 1,378.80

Problem?

work request to have 2x tubes added to rear compartment (were the pike polls are) of Q15 to stow the new Roof Hook & Piercing Nozzle.

Task performed:

1. build tubes at shop went to sta. they had to go to training
2. drive to sta. remove ladder installed

Parts

R134AFREON LB

Quantity

3



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V14892

In Date: 05/06/2008

Meter Reading: 1,399.00

Close Date: 06/17/2008

Problem?

Circle D light female hook up cord is torn exposing wires, possible shock hazard. The light still works. Just need new wire for back of the Circle D light. Thanks q15

Task performed:

1. drive to station rework cord test ok

Parts

R134AFREON LB

Quantity

3

Workorder: V15548

In Date: 06/05/2008

Meter Reading: 16,001.00

Close Date: 06/19/2008

Problem?

INSTALL GRAPHICS ON DOOR Q-15

Task performed:

Install graphics on door Q-15 - Graphic Designs

Parts

NO PARTS USED

Quantity

Vendor?: GRAPHIC DESIGNS

Workorder: V15014

In Date: 05/12/2008

Meter Reading: 1,415.00

Close Date: 06/26/2008

Problem?

one of the ladder tip lights appears to have been hit by something and it has been angled up. The light is not in any threat of falling off. The attachment bracket appears to be cracked, however. q15

Task performed:

1. Diss entire ladder tip light & rem asy from veh; on bench rebuild light asy including some bad wiring & reinstall on veh.

2. Rem center dash panel & install new ignition switch; Note: (old switch would intermittently not shut off). j

Parts

SWT54915SWIT-251240 SW ROCKER SPST ON/OFF GREE

Quantity

1

Workorder: V15353

In Date: 05/27/2008

Meter Reading: 1,445.00

Close Date: 07/01/2008

Problem?

work request to hang Hurst hoses on Hurst compartment door.

Task performed:

1. drive to station installed hose holders

Parts

UMVS-0811-11STRAP ZICO

Quantity

2



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V15526

In Date: 06/04/2008

Meter Reading: 16,001.00

Close Date: 07/01/2008

Problem?

Check eng lt on q 15

Task performed:

Parts

Quantity

1. drive to station. coolant and speed sensor bad. called shop.

NO PARTS USED

Workorder: V15730

In Date: 06/13/2008

Meter Reading: 16,001.00

Close Date: 07/01/2008

Problem?

take unit to ft pierce for repair

Task performed:

Parts

Quantity

1. drop truck at fdda in ft. pierce

NO PARTS USED

Workorder: V15557

In Date: 06/05/2008

Meter Reading: 1,464.00

Close Date: 07/03/2008

Problem?

Q15 needs Hydraulic Fluid for Ladder and Outriggers, dip stick shows ADD

Task performed:

Parts

Quantity

1. Chk hydraulic for ladder.
2. Chk coolant level; added 3/4 gal; chk eng oil-added (1) qt.
3. Gen inop; wouldn't start; rem Onan gen cover & side wall; chk wiring ckts & rep loose connector; start gen several times-now ok; reinstall cover & wall.
4. Cab lift inop; won't lower; checkout wiring for remote; fnd connector pulled apart in harness; mk connector repair; now ok. j

1212BTURTLE TILE 12X12 BLACK

36

25-37125-371 TOGGLE BOOT

1

47153582-2116 TOGGLE SW ON/OFF

1

FC504-U-2BRACKET WPB

1



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V16012

In Date: 06/26/2008
Close Date: 07/03/2008

Meter Reading: 16,201.00

Problem?

repair coolant leak fla detroit diesel q15

Task performed:

Repair coolant leak - Florida Detroit Diesel j

Parts

Quantity

NO PARTS USED

Vendor?: FLORIDA DET DIESEL

Workorder: V15564

In Date: 06/06/2008
Close Date: 07/09/2008

Meter Reading: 1,464.00

Problem?

yesterday Aerial remote control worked then didn't then did during some trianing. B-shift driver sts it didn't work at all last shift duri training. may want to have mech check it when he comes back for sensor. Q15

Task performed:

Check out aerial remote device; change out bat in device; retest; NG; no response; give to foreman to send out for repair. j

Parts

Quantity

NO PARTS USED

Workorder: V16098

In Date: 07/01/2008
Close Date: 07/10/2008

Meter Reading: 1,485.00

Problem?

"Aerial not stowed" light & buzzer keeps coming on. Warning light for the RPM comes on on officer's side when RPM is normal Q-15

Task performed:

1. drive to station adjusted sender for aerial stowed test = ok need program to reset control for RPM wont delay truck from respnding.

Parts

Quantity

NO PARTS USED

Workorder: V16221

In Date: 07/08/2008
Close Date: 07/18/2008

Meter Reading: 1,496.00

Problem?

we have a bad flash light, it is tagged and located in the office. Thanks q15

Task performed:

Drop off light. j

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V16256

In Date: 07/09/2008

Meter Reading: 16,406.00

Close Date: 07/21/2008

Problem?

FAN BELT SLIPPING ON Q15,WILL BE AT HQ ALL DAY TOMORROW FOR QUINT CLASS. Q15

Task performed:

1. Drive to Stn; get numbers off belts.
2. R/R fan belt; test ok. j

Parts

K080570BELT

Quantity

1

Workorder: V16304

In Date: 07/11/2008

Meter Reading: 16,563.00

Close Date: 07/21/2008

Problem?

ladder bed light always on q15

Task performed:

- Drive to Stn; adj sender. j

Parts

NO PARTS USED

Quantity

Workorder: V16421

In Date: 07/17/2008

Meter Reading: 1,534.10

Close Date: 07/28/2008

Problem?

request to mount high rise pack on top driver side of truck, like Q29. Next Wed 7/23 C-shift would be a good time before 1:30pm training. q15

Task performed:

- Drive to Stn; installed high rise pack. j

Parts

UMVS254411STRAP 46 IN

Quantity

2

Workorder: V16424

In Date: 07/17/2008

Meter Reading: 1,534.10

Close Date: 08/01/2008

Problem?

Request to have TIC charger moved to the front next to the OIC seat. q15

Task performed:

1. drive to station. move tic. wired up and tested all ok

Parts

NO PARTS USED

Quantity



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V16528

In Date: 07/22/2008

Meter Reading: 1,544.00

Close Date: 08/01/2008

Problem?

a/c belt is loose and water in front right side floor of cab Q15

Task performed:

Parts

Quantity

1. drive to station rework A/C line. drain test=ok. also checked A/C belt and found no problem

NO PARTS USED

Workorder: V16329

In Date: 07/11/2008

Meter Reading: 1,514.00

Close Date: 08/07/2008

Problem?

Sensor on the left outrigger keeps going off. Q15

Task performed:

Parts

Quantity

1. drive to station installed sender test - ok

360000161PROXIMITY SWITCH

1

Workorder: V16551

In Date: 07/23/2008

Meter Reading: 1,544.00

Close Date: 08/11/2008

Problem?

need new rubber strap for TIC charger to hold TIC in place, the current one is torn. Q-15

Task performed:

Parts

Quantity

1. installed rubber strap test - ok

NO PARTS USED

Workorder: V16690

In Date: 07/29/2008

Meter Reading: 1,560.40

Close Date: 08/11/2008

Problem?

driver side outrigger sank down onto pin today during training. Q-15

Task performed:

Parts

Quantity

1. drive to station couldnt make outrigger to drop no problem found

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V16976

In Date: 08/12/2008
Close Date: 08/13/2008

Meter Reading: 17,316.00

Problem?

AIR HURST UNIT Q15

Task performed:

Drive to Stn; cln carb throttle; test ok. j

Parts

NO PARTS USED

Quantity

Workorder: V17074

In Date: 08/15/2008
Close Date: 08/18/2008

Meter Reading: 1,596.00

Problem?

a/c belt is squeaking Q-15

Task performed:

contacted fleet maint. for repair

Parts

4080570BELT SAME AS K080570

Quantity

1

Workorder: V17282

In Date: 08/25/2008
Close Date: 08/25/2008

Meter Reading: 17,578.00

Problem?

ON CALL Q 15 WATER LEAKING FROM PRIMER

Task performed:

1. DRIVE TO ST.15 C/O REPLACED PRIMARY VALVE/SWITCH
2. ADJUST DRIVERS DOOR

Parts

538028052VALVE PRIMER PUMP W/HARDWARE

Quantity

1

Workorder: V17112

In Date: 08/18/2008
Close Date: 08/28/2008

Meter Reading: 1,596.00

Problem?

computer on pump panel intermittent problem rpm and idle coming on at the same time Q-15

Task performed:

Drive to Stn; clean all plugs; run pump; test ok. j

Parts

NO PARTS USED

Quantity



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V17194

In Date: 08/21/2008

Meter Reading: 17,412.00

Close Date: 08/28/2008

Problem?

BURNING SMELL COMING FROM PUMP PANEL Q15

Task performed:

Drive to Stn; replc primer relay & bad ground at pump panel; test ok. j

Parts

2000071102000072100 SOLENOID HALE PRIMER

Quantity

1

Workorder: V16691

In Date: 07/29/2008

Meter Reading: 1,560.40

Close Date: 09/22/2008

Problem?

Air Restriction red light is still going on and off when accelerating. I believe you are aware of this just wanted to make sure. Q-15

Task performed:

Drive to Stn; installed air sender for light; test ok. j

Parts

23527565TENSORER

846010002AIR RESTRICTOR SENSOR 770050

FREIGHTSHIPPING CHARGES

Quantity

1

1

1

Workorder: V17033

In Date: 08/13/2008

Meter Reading: 1,585.00

Close Date: 09/22/2008

Problem?

Noticed that OIC side rear inside compartment area wall paneling is missing bolts that secure the plastic paneling to the wall. Q15

Task performed:

Drive to Stn; R/R bolts in c ab; test ok. j

Parts

NO PARTS USED

Quantity

Workorder: V17362

In Date: 08/27/2008

Meter Reading: 1,613.00

Close Date: 09/22/2008

Problem?

new fan belt squeaks also Q15

Task performed:

Adj A/C belt & tested. j

Parts

NO PARTS USED

Quantity



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V17716

In Date: 09/15/2008
Close Date: 09/29/2008

Meter Reading: 1,637.00

Problem?

Governor lights not working- pump engage light, ok to pump light, no light on psi, non of presets not working. q15

Task performed:

1. drive to sta replace bad t case switch test pump npf

Parts

200-2450-00NC SWITCH OK TO PUMP

Quantity

1

Workorder: V17350

In Date: 08/27/2008
Close Date: 10/01/2008

Meter Reading: 1,613.00

Problem?

hose under the front of quint is hanging down q15

Task performed:

1. Drive to Sta-15 to R/R hose holder under truck/test.

Parts

NO PARTS USED

Quantity

(R.T.)

Workorder: V17691

In Date: 09/13/2008
Close Date: 10/09/2008

Meter Reading: 1,637.00

Problem?

HANDLE TO OIL DIP STICK CAP BROKEN. CAP STILL FITS AND TIGHTENS TO NECK. Q15

Task performed:

1. Drive to Sta. installed new dip stick, check for leaks.
Test (OK).

Parts

834020-002TRANS DIPSTICK TUBE

FREIGHTSHIPPING CHARGES

Quantity

1

1

(R.T.)

Workorder: V18085

In Date: 10/02/2008
Close Date: 10/09/2008

Meter Reading: 1,665.00

Problem?

brake air compressor blow off valve making differant noise q15

Task performed:

1. Drive to Sta-15. R/R valve for air dryer. test (OK).

Parts

800404USE K022105 PURGE KIT AD-IP-IS

Quantity

1

(R.T.)



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V18008

In Date: 09/29/2008
Close Date: 10/14/2008

Meter Reading: 1,658.00

Problem?

marker light front center of cab, check front tire wear inside edge q15

Task performed:

Parts

Quantity

1-Drive to sta need tire replaced on driver side, order lights.
2-Drive to sta R/R lite, find bad ground. repaired and tested. ok.

NO PARTS USED

Workorder: V13861

In Date: 03/12/2008
Close Date: 10/17/2008

Meter Reading: 1,317.00

Problem?

Install Piercing Nozzle on Quints. Wayne chambers e-mail me to state new Piercing nozzles are in and each Quint need to have one installed. Q15

Task performed:

Parts

Quantity

installed new nozzle in ladder compt.

NO PARTS USED

Workorder: V18198

In Date: 10/07/2008
Close Date: 10/20/2008

Meter Reading: 18,112.00

Problem?

Q15 CHAINSAW,UNABLE TO START.

Task performed:

Parts

Quantity

Drive to stn; R/R spark plug; cln carb; test ok. j

BPMR4A6028 SPARK PLUG

1

Workorder: V13999

In Date: 03/19/2008
Close Date: 10/22/2008

Meter Reading: 1,317.00

Problem?

HF (hands free) on steering wheel dose not work. Q15

Task performed:

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V16450

In Date: 07/19/2008
Close Date: 10/22/2008

Meter Reading: 16,829.00

Problem?

ADJUST BODY COLLISION FOR LADDER Q15

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V18449

In Date: 10/20/2008
Close Date: 10/24/2008

Meter Reading: 18,421.00

Problem?

check front tire low q15

Task performed:

Parts

Quantity

Drive to Stn; fill tire; fnd valve stem leaking; repaired; test ok. j

S506USE 501 GAUGE AIR

1

S986AIR GAUGE 160 PSI

1

Workorder: V18595

In Date: 10/25/2008
Close Date: 11/17/2008

Meter Reading: 1,699.00

Problem?

scene lights on the tip of Q-15 intermitantly working.

Task performed:

Parts

Quantity

Drive to Stn; fnd wire at STW loose; rework; test ok. j

NO PARTS USED

Workorder: V18981

In Date: 11/10/2008
Close Date: 11/19/2008

Meter Reading: 18,656.00

Problem?

please put in helmet hook on officer side of q15

Task performed:

Parts

Quantity

1. Drive to Stn; chk rear tires; call Ed O. to hav replaced.
2. Drive to Stn; installed latch. j

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V18086

In Date: 10/02/2008
Close Date: 12/05/2008

Meter Reading: 18,112.00

Problem?

re[place left front tire q15

Task performed:

replace left front tire q15

Parts

NO PARTS USED

Quantity

Vendor?: CALLAGHAN

Workorder: V18878

In Date: 11/05/2008
Close Date: 12/09/2008

Meter Reading: 18,656.00

Problem?

replace rear tires at sta 15 callaghan

Task performed:

Replace rear tirest at Stn15 - Callaghan j

Parts

NO PARTS USED

Quantity

Vendor?: CALALGHAN

Workorder: V18616

In Date: 10/27/2008
Close Date: 01/02/2009

Meter Reading: 18,621.00

Problem?

front 1.5 discharge gauge is leaking oil Q15

Task performed:

drive test; crawlin pump panel area; replcd (2) gauges.

Parts

91553941GAUGE
91553943GUAGE

Quantity

1
2

Workorder: V20028

In Date: 12/30/2008
Close Date: 01/06/2009

Meter Reading: 19,374.00

Problem?

primer sticking q15

Task performed:

drive to Stn; tighten cables & lube primer; test ok. j

Parts

NO PARTS USED

Quantity



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V20018

In Date: 12/29/2008
Close Date: 01/13/2009

Meter Reading: 1,785.00

Problem?

MOUNT FOR DOOR PISTON BROKEN L1 q15

Task performed:

Drive to Stn; repl cd holder & shocks; test ok. j

Parts

Quantity

16301BALL STUD	4
16302RETAINER CLIP	6
EAA-8350-90UGSS6558UK STRUT-LIFT	2

Workorder: V20275

In Date: 01/10/2009
Close Date: 02/04/2009

Meter Reading: 1,808.70

Problem?

DO compartment door pneumatic door arm stopper brake is broken Q15

Task performed:

1- Found mount for door shock absorber to be broken, part not on truck.
2- Drive to station, replace door shock. test ok,

Parts

Quantity

16301BALL STUD	8
EAA-8350-90UGSS6558UK STRUT-LIFT	1

Workorder: V20356

In Date: 01/14/2009
Close Date: 02/04/2009

Meter Reading: 19,700.00

Problem?

NEED EXTRA GREEN CHAIN FOR CHAINSAW ON Q15.

Task performed:

1- Drive to station, installed new chain, test ok.

Parts

Quantity

BM6AUSE 5921 SPARK PLUG	2
-------------------------	---

Workorder: V20207

In Date: 01/07/2009
Close Date: 02/05/2009

Meter Reading: 1,808.70

Problem?

Airpack seat behind the driver is broken, it will not hold the airpack. q15

Task performed:

Installed ring to allow airpack to be released. j

Parts

Quantity

NO PARTS USED	
---------------	--



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V17722

In Date: 09/15/2008

Meter Reading: 1,637.00

Close Date: 02/20/2009

Problem?

2 1/2 discharge on tip hard to open and close. Also, reminder to check on part, Yellow ladder tip break away extension. q15

Task performed:

Repaired on C-Inspection 2/17/09. j

Parts

Quantity

101111066HANDLE R-1

1

47263CAN USE 47253 LED MAKER LIGHT YELLOW

1

740-0121END FRAME LADDER

1

FREIGHTSHIPPING CHARGES

1

Workorder: V21341

In Date: 02/25/2009

Meter Reading: 19,971.00

Close Date: 02/27/2009

Problem?

HURST TOOL LEAKING GAS WHEN GAS LINE TURNED ON. Q-15

Task performed:

Swapout power unit. j

Parts

Quantity

NO PARTS USED

Workorder: V21048

In Date: 02/11/2009

Meter Reading: 19,971.00

Close Date: 02/28/2009

Problem?

replace front tires q15

Task performed:

Replace front tires Q15 - Callaghan j

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V19323

In Date: 11/25/2008

Meter Reading: 18,891.00

Close Date: 03/02/2009

Problem?

repair load minder q15

Task performed:

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V20173

In Date: 01/07/2009

Meter Reading:

Close Date: 03/02/2009

Problem?

reprogram node 6 & 7 to bring ground lights On when in reverse.

Task performed:

Drive to Stn; rem cover for node 6 & 7; hook laptop one-to-one on node; no change in sys; talke with Ed O. about getting another program.

2. Tried to reprogram nodes 6-7; cld not work; called Kevin ward to chk program; he sent a new copy-NG; had Ed O. try-NG; chkd nodes wiring; all ok.

3. Ed E. got with U-mux & fnd file name wrong; changed file names & reprogrammed nodes 1,5,67 so all under body lights work in reverse. j

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V20610

In Date: 01/26/2009

Meter Reading: 19,700.00

Close Date: 03/03/2009

Problem?

C INSPECTION AND REPAIRS AS NEEDED Q15

Task performed:

Parts

Quantity



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

C-Inspection	02-0363769255D400 LED SPLIT RED RED	1
2. Dia/rep R-rear brake application problem; make/install brake hose.	05-17223-000CAP RADIATOR 10 LB	1
3. Replc btrys.	15W40BSYN OIL BULK QTS	24
4. Safety wired PTo shaft lock bolts.	20X2040WHEEL STUD	20
5. Rem PTo shaft & frnt pump seal; PTO shaft was too long & pushing on seal; had shaft shortened; replcd frt seal in pump & installed shaft.	276567XVALVE DASH PP1	1
6. Svc T-Case.	3157TAIL LIGHT BULBS	2
7. Rem frt wheels to double chk brake lining; lining on both sides ok.	3202099SEAL WITH RACE QUINT	2
8. Replcd rear brake shoes & drums; also replcd wheel seals.	3219F4972BRAKE DRUM QUINT	2
9. Svc transmission.	35200-RLIGHT MARKER LED RED	2
10. Svc air dryer.	35200-YLIGHT MARKER LEDAMBER	4
11. Replcd rad cap.	43LENSLENS RED 43 SERIES	1
12. Replc parking brake valve & both brake swtchs.	504870C1BUSHING	2
13. Adj top base ca bles on ladder.	740-WWS75WATERWAY SEAL KIT	1
14. Showed extension cyl leak to Scott; was to told to let go to next inspection only a class 1 leak.	76062-15-NCSWITCH PRESS	2
15. Che ckd left outrigger ok; no drift.	78R536078R5360M 2PK FILTER AIR COND	1
16. Installed quick release valve that was rem by an on-call tech.	EST-1THERMAL TREATMENT	4
17. Got inside pump panel & lubed all valve linkage; operated linkage & lubed again.	EST-2DDIAMOND TREATMENT	2
18. Adj fan & A/C belts.	FREIGHTSHIPPING CHARGES	4
19. Lube outriggers.	FT4471BDQUINT REAR BRAKE SHOES	4
20. Traced & pre leak in gov line gauge to compressor; fnd leak in left frame rail.	KIT9081BRAKE HARDWARE KIT	2
21. Replcd A/C filter.	KN20901KN20901 KNOB PARKING BRAK	1
22. Replcd btry for aerial remote & tested.	KN32041DOUBLE CHECK VALVE	1
23. Rep gauge on panel #2 discharge.	N9553SFD/L END	1
24. Chkd garden hose tank fill; NPF.	P1147GFUEL FILTER 33120 WIX DELCO TP916	1
25. Lube & adj latch on frt compt; lube all latches.	PH7405 51971 OIL FILTER WIX	2
26. Rem seat belt & installed new-too long; ordered by build number; still wrong; 3rd set ordered; finally good.	PS683033442 FUEL FILTER	1
27. Trans code 6340; replcd both swtchs on parking brake ckt.	E-600013-3052 NUT	20
28. Charged/tested rear A/C.	29526898 29548988 TRANS FILTER ALLISON	1
29. R/R wipers & replcd brkn hose to washers inside cab.	401581GASKET AXLE FL80 R002435	2
30. Sec tool holders in all compts.	768-0006LADDER BAR	1
31. Told Ed E. to schedule alignment.	40X62X7SEAL	1
32. Rep marker & turn signal lights.	LABORHOURLY LABOR CHARGE	8
33. Rep emergency lights.	440-5 VALVE EXT.	2
34. Tried to reprogram nodes 617 for under body lights; See W/O V20173.	50-24WIPER BLADE - KME	2
35. Sec holdopens all compts.	5008414CARTRIDGE DC100	1
36. Exended ladder & resealed waterway tubes.	800404USE K022105 PURGE KIT AD-IP-IS	1
37. Rem 2-1/2" valve & flange from ladder; installed new flange; waiting on valve.	BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	6
38. Replcd bent safety reel on turntable.	HP-31DBATTERY 950CCA HP-31D	6
39. Cind/lubed ladder slides.	854003-005SEAT BELT	2
40. Replcd bent ladder tip.	88252.5 VLV W SS BALL	1
	94553941 USE 91553941 3.5 IN	1
	CA7230WA10116 AIR FILTER 46893 WIX	1



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

- 41. Lube/ajd flow valve for foam.
- 42. Mov waterway & heard loud noises; had inner tube (1) hole off; adj/ran ok.
- 43. Wiped down cables & waterways with oil.
- 44. Replcd foam fill swtch asy & tested.
- 45. Flow tested foam sys. j

Workorder: V21758

In Date: 03/12/2009 **Meter Reading:** 19,971.00
Close Date: 03/17/2009

Problem?

install valve on/ ladder repair a/c / ladder bed alm going off Q15

Task performed:

- 1. Installed valve on end of ladder.
- 2. Front A/C inop; fnd no charge on frnt sys; loose press sensor; rep & charged sys.
- 3. Aerial alarm & light went off on test ddrive; adj sensor on ladder bed.
- 4. Fnd small hyd leak at base of ladder; plastic plug broken; made bolt to fit hole & clnd area of fluid.
- 5. Traced & rep loose connection for level gauges; fnd connector on PDM msgng pin holder; replcd pin holder & chkd ok.
- 6. Flowed water thru water way for test after seal replacement.
- 7. Secured outrigger rod to prevent ladder ____ light from coming on.
- 8. Assist in above repairs. j

Parts

Quantity

NO PARTS USED

Workorder: V22225

In Date: 03/31/2009 **Meter Reading:** 20,363.00
Close Date: 04/06/2009

Problem?

repair coolant leak q15

Task performed:

- 1. Drive to Stn; drain coolant; make new hose; replc clamps; still leaking; drain; rework pressure; test ok; sent to shop.
- 2. Drain cooling sys; refill; press test; run truck.
- 3. Rep L-1 compt shelf. j

Parts

Quantity

ALA00350-50 EXTENDED LIFE COOLANT GAL

2



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V21535

In Date: 03/04/2009

Meter Reading: 19,971.00

Close Date: 04/14/2009

Problem?

replace rear springs total truck

Task performed:

Parts

Quantity

Replace rear springs - Total Truck

j

NO PARTS USED

Vendor?: TOTAL TRUCK

Workorder: V22483

In Date: 04/12/2009

Meter Reading: 1,900.00

Close Date: 04/23/2009

Problem?

Check engine light on in cab& panel. on pump panel display, idle and rpm lights blinking, will not allow pump rpm's to increase wh pump in gear. Resolved after several attempts. q 15

Task performed:

Parts

Quantity

1. Eng light on; low coolant; cleared code ok.
2. Pump gov not working right; cln plugs & press gov valve; working ok. j

NO PARTS USED

Workorder: V23246

In Date: 05/13/2009

Meter Reading: 21,157.00

Close Date: 05/13/2009

Problem?

repair hurst power unit Q15 (outside agency-regan's small engine service)

Task performed:

Parts

Quantity

NO PARTS USED

Vendor?: REGANS

Workorder: V23117

In Date: 05/06/2009

Meter Reading: 1,945.00

Close Date: 05/19/2009

Problem?

a/c is not cold in the front of the cab Q-15

Task performed:

Parts

Quantity

drive to Stn; fnd wire going to hi-pressure valve bad; reworked; test ok. j

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V23234

In Date: 05/12/2009
Close Date: 05/20/2009

Meter Reading: 21,157.00

Problem?

hurst power pack not idling up stays on low almost stalls out when put under load Q15

Task performed:

Send spare power unit to Stn15. j

Parts

Quantity

NO PARTS USED

Workorder: V23312

In Date: 05/16/2009
Close Date: 05/21/2009

Meter Reading: 1,956.00

Problem?

a/c blowing hot air on q15, Lehan charged freon may 7th. thanks

Task performed:

Charged A/C again; looks like hi-side line at compressor leaking. j

Parts

Quantity

NO PARTS USED

Workorder: V23400

In Date: 05/19/2009
Close Date: 05/26/2009

Meter Reading: 1,956.00

Problem?

driver's side head light /singular low beam bulb is 10/7 q15

Task performed:

Replcd headlight; ck ok; went to Stn23. j

Parts

Quantity

H4656USE CV TYPE HEAD LIGHT

1

Workorder: V23548

In Date: 05/26/2009
Close Date: 06/15/2009

Meter Reading: 21,445.00

Problem?

FRONT A/C BLOWING WARM AIR. q15

Task performed:

Drive to Stn; fill A/C; look for leaks; need to go to shop for repair. j

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V23921

In Date: 06/08/2009 Meter Reading: 21,734.00
Close Date: 06/18/2009

Problem?

Rebuild gate valve- Q15 (parts direct charged)

Task performed:

Drive to Stn; rebuild valve; test. j

Parts

Quantity

NO PARTS USED

Workorder: V23654

In Date: 05/29/2009 Meter Reading: 21,445.00
Close Date: 06/23/2009

Problem?

FRONT A/C IN Q15 BLOWING WARM AGAIN.

Task performed:

drive to Stn; talk w/Ed E. need to come to shop for repair. j

2. C/O A/C sys; fnd line leaking on compressor; R/R lines; compressor thrds stripped; need compressor; didn't have; try to make one work; couldn't get; order new one; get fittings for hoses; seal off hoses for now; order parts.

3. R/R A/C; comp rear cover back ; ok unit for new style one; R/R A/C lines/fittings; replc fittings on hoses; R/R dryer; reinstall vac sys; chk for leaks; ok. j

Parts

Quantity

4411S08-6962BS 90 DEGREE SB1322

1

5638G03-6540G COMPRESSOR HEAD

1

570703-3418 COMPRESSOR 4666

1

71R755011-2624 TRINARY SWITCH A/C 1560

1

74R258607-2613A RED DOT DRIER 7127

1

Workorder: V23670

In Date: 05/30/2009 Meter Reading: 1,974.00
Close Date: 06/23/2009

Problem?

3 inch y on rear of q15. rt. side gate hard to work

Task performed:

Drive to Stn; call Chief Wells to order parts; talk to _____; call Chief Wells; part on order. j

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V23739

In Date: 06/02/2009

Meter Reading: 1,988.00

Close Date: 06/23/2009

Problem?

cab latch light is on Q15

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V24130

In Date: 06/16/2009

Meter Reading: 21,734.00

Close Date: 07/02/2009

Problem?

gas powered vent fan throttle 10-7. q15

Task performed:

Parts

Quantity

Drive to Stn; cln carb & adj; test ok. j

NO PARTS USED

Workorder: V24420

In Date: 06/29/2009

Meter Reading: 2,013.00

Close Date: 07/16/2009

Problem?

rear a/c not working Q15

Task performed:

Parts

Quantity

1. drive to Stn; T-shoot sys; ck nodes; trinary swtch & T-stat need eqmt to finish job.

600000003NODE HERCULES V-MUX

1

2. Drive to Stn; no power to clutch; replcd node, stw & bypass T-stat; chk press; test ok.

71R755011-2624 TRINARY SWITCH A/C 1560

2

3. T-shoot rear cab A/C; fnd no powr on clutch ckt frm node #2; replcd/reprogrammed node; replcd foam clutch swtch & fnd T-stat to be intermittent. j



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V24886

In Date: 07/20/2009

Meter Reading: 22,368.00

Close Date: 07/24/2009

Problem?

REPAIR A/C AND COMPLETE REPAIRS FROM UL LIST Q15

Task performed:

1. Dia A/C sys; fnd minimal charge in frnt/rear; evac/charg; look for leaks; no leaks; R/R rear A/C T-stat; frnt A/C hi-press; chk H-block; fnd debris; R/R blocks/dryer.
2. Rem waterway relief valve; took apart/clnd; put back on waterway; started to press test.
3. Finished testing/adj waterway relief valve at base stn.
4. Fnd clutch fan wires chaffing on frnt right of eng block; rep wires; most likely why A/C has been intermittent.
5. tightened loose waterway mntng bolts.
6. Clnd/lube ladder stn slide surfaces.
7. Chkd intercom sys; cld not find problem
8. Lube/clnd undersides of horizontal stabilizers.
9. Researched how to recalibrate load minder called Class One; adj min/max load at tip of ladder.
10. Adj extension/retraction cables.
11. Chk max output of hyd pump; under spec by 100 PSI; called ladder man; fnd info on adjusting pump press; adj press up to 1950 at high idle.
12. Chkd/adj rear waterway/rear discharge relief valve; set to 250 PSi.
13. Assist Steve w/cable/relief valve adjustment - Levy.
14. Did final chk on A/C during test driv e; sys working good. j

Parts

Quantity

12-0612AUSE 1600 VALVE EXPANSION RED DOT HOSELIN	1
71R31001331 THERMOSTAT A/C	1
74R258607-2613A RED DOT DRIER 7127	1
78R536078R5360M 2PK FILTER AIR COND	1
ADPDATA PLATE QUINTS	1
FREIGHTSHIPPING CHARGES	1

Workorder: V25278

In Date: 08/04/2009

Meter Reading: 2,090.00

Close Date: 08/17/2009

Problem?

reservior tank cap is coming a part at the threads

Task performed:

1. Drive to Stn; tape cap; order part
- .2. Drive to Stn; replcd hose for coolant & cap.

Parts

Quantity

101331605QUINT COOLANT RES CAP	1
--------------------------------	---



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V25525

In Date: 08/14/2009
Close Date: 08/17/2009

Meter Reading: 22,660.00

Problem?

NO THROTTLE RESPONSE. LINKAGE MISSING BETWEEN LEVER AND CARB. ABLE TO MANUALLY THROTTLE UP AND DOWN. HURST UNIT ON Q-15

Task performed:

Drive to Stn; cln carb & adj; replcd spark plug; test ok.
j

Parts

6535SPARK PLUG CR5HSB

Quantity

3

Workorder: V25668

In Date: 08/20/2009
Close Date: 08/20/2009

Meter Reading: 2,090.00

Problem?

Q15 hurst tool power unit fuel leak at base of carburator. spoke with Ehrke, he is sending us a spare.

Task performed:

had light duty take spare to sta to swap unit for repair. no labor

Parts

NO PARTS USED

Quantity

Workorder: V25849

In Date: 08/28/2009
Close Date: 09/16/2009

Meter Reading: 23,026.00

Problem?

Install UL Plate Q15

Task performed:

Drive to Stn; installed UL plate. j

Parts

NO PARTS USED

Quantity

Workorder: V27701

In Date: 11/16/2009
Close Date: 11/30/2009

Meter Reading: 24,285.00

Problem?

oil level low Q15

Task performed:

Svc call to Stn15; ck oil level - low; added oil; ck for leak;s ck ok; went to Stn1. j

Parts

NO PARTS USED

Quantity



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V27965

In Date: 11/28/2009
Close Date: 12/04/2009

Meter Reading: 2,259.00

Problem?

Hurst tool generator won't run. Q15

Task performed:

1. Travel to Stn15 from Stn24. Chk hurst unit; crank case full of fuel; drain crankcase; fill w/oil; cln carb; cln spark plug; ; run unit-ok; needs air filter.
2. R/R air filter on Hurst power unit; test run unit. j

Parts

17211-2L8-02330-347 HURST UNITS 06 HONDA

Quantity

1

Workorder: V28167

In Date: 12/07/2009
Close Date: 12/17/2009

Meter Reading: 24,681.00

Problem?

STOP AND CHECK ENGINE LIGHT ON. q15

Task performed:

1. Drive to Stn15; chk eng code; Fnd low coolant.
2. Drive to Kevin's house to get laptop.
3. Travel to Stn15.
4. Chk eng code; fnd code for low coolant; chk eng code; fnd code for low coolant; driver added coolant; erased inactive code. j

Parts

NO PARTS USED

Quantity

Workorder: V28254

In Date: 12/10/2009
Close Date: 12/21/2009

Meter Reading: 24,681.00

Problem?

hurst tool choke sticking,will run but have to hold choke lever,Q15.

Task performed:

1. Travel to Stn15.
2. Rem carb frm Hurst motor; diss & clean; reinsdtall; test run ok. j

Parts

NO PARTS USED

Quantity



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V28331

In Date: 12/14/2009
Close Date: 12/22/2009

Meter Reading: 24,751.00

Problem?

CHECK BRAKES ON UNIT Q15

Task performed:

Parts

Quantity

- 1. Travel
- 2. Chk brakes on quint; rear brakes ok; frt brakes cld not fully chk w/o mirror or removing wheels. j

NO PARTS USED

Workorder: V28350

In Date: 12/15/2009
Close Date: 12/22/2009

Meter Reading: 24,751.00

Problem?

winch out unit q 15 stuck

Task performed:

Parts

Quantity

- Travel to Universe Blvd for Q15 stuck at FPL; w/for tow truck; C/O truck after tow; travel home. j

NO PARTS USED

Workorder: V28501

In Date: 12/21/2009
Close Date: 01/05/2010

Meter Reading: 24,815.00

Problem?

ON CALL CHECK ENG LT ON Q15

Task performed:

Parts

Quantity

- Went to Stn15; raised ladder/cab; fnd low coolant alarm code; added coolant; press tested; R/R top rad hose clamp; added (2) qt oil; ran ck ok. j

NO PARTS USED

Workorder: V28159

In Date: 12/07/2009
Close Date: 01/15/2010

Meter Reading: 24,681.00

Problem?

Replace Front Tires q15

Task performed:

Parts

Quantity

- Replace front tires Q15 - Callaghan j

NO PARTS USED

Vendor?: CALLAGHAN



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V28349

In Date: 12/15/2009
Close Date: 01/15/2010

Meter Reading: 24,751.00

Problem?

winch out unit q 15

Task performed:

Parts

Quantity

Winch out unit Q15 - Sisters j

NO PARTS USED

Vendor?: SISTERS

Workorder: V28751

In Date: 01/03/2010
Close Date: 01/26/2010

Meter Reading: 25,038.00

Problem?

HURST TOOL NOT RUNNING PROPERLY. Q15

Task performed:

Parts

Quantity

Hurst tool running poorly; took spare unit to them. j

NO PARTS USED

Workorder: V27564

In Date: 11/10/2009
Close Date: 01/27/2010

Meter Reading: 24,217.00

Problem?

Instruct aerial operators about lubrication information Q15

Task performed:

Parts

Quantity

Drop off lube manual for quint. j

NO PARTS USED

Workorder: V29275

In Date: 01/20/2010
Close Date: 02/08/2010

Meter Reading: 2,332.00

Problem?

fan belt on q-15 is spueaking

Task performed:

Parts

Quantity

Went to Stn15; Fnd belts new; must must run trk to seat in belts; does this everytime; belts are changed. j

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V28849

In Date: 01/06/2010

Meter Reading: 25,038.00

Close Date: 02/12/2010

Problem?

C INSPECTION AND REPAIRS AS NEEDED Q15

Task performed:

- 1. C-inspection
- 2. Resecure drivers side crosslay
- 3. Chk for coolant leak; tighten all coolant hoses.
- 4. R/R air dryer & purge valve.
- 5. Toque turn table bolts.
- 6. Tighten all compt door brkts/hinges.
- 7. R/R eng belts.
- 8. Take remote for aerial apart & chk swtchs; send out for repair.
- 9. R/R grd ladder's heat sensors.
- 10. R/R wiper blades & spray nozzles.
- 11. R/R SCBA brkts.
- 12. Q.C. w/Mike; replc L/R upper marker light; tighten grd for marker lights. j

Parts

Quantity

15W40BSYN OIL BULK QTS	40
15W40QSYN OIL QT	4
33063FUEL FILTER ONAN	1
35200-RLIGHT MARKER LED RED	1
50-24WIPER BLADE - KME	2
5008414CARTRIDGE DC100	1
67BULB 12 VOLT	1
9420BELT	1
CA7230WA10116 AIR FILTER 46893 WIX	1
K022105PURGE VALVE AD-IP-IS	1
K080570BELT	1
P1147GFUEL FILTER 33120 WIX DELCO TP916	1
PH47 51758 L/F PH725 OIL FILTERL	1
PH7405 51971 OIL FILTER WIX	2
PS683033442 FUEL FILTER	1
9435BELT	3

Workorder: V28860

In Date: 01/06/2010

Meter Reading: 25,038.00

Close Date: 02/25/2010

Problem?

Repair hurst power unit Q15 (outside agency-regan's small engine service)

Task performed:

Rep Hurst power unit Q15 - Regan j

Parts

Quantity

NO PARTS USED

Vendor?: REGAN SMALL ENG



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V29603

In Date: 02/01/2010
Close Date: 03/02/2010

Meter Reading: 25,517.00

Problem?

q15 belt still slipping and screaming every time you accelerate and getting worse. was told it needed time to break in or seat. but that can't be feasible at this point.Q15

Task performed:

Went to shop for part; went to Stn15; test drove w/driver; raised ladder/cab; R/R serp belt/tensioner; tightened fan belts; tightened A/C belt; fnd P/S gskt seeping oil & dripping on A/C comp pulley; tightened P/S pump clnd oil; test drove; ck ok. j

Parts

Quantity

23527565TENSORER

1

K080570BELT

1

Workorder: V29728

In Date: 02/04/2010
Close Date: 03/02/2010

Meter Reading: 25,517.00

Problem?

belt still slipping badly on acceleration. getting worse Q15

Task performed:

Rep done on W.O. 29603 j

Parts

Quantity

NO PARTS USED

Workorder: V29437

In Date: 01/26/2010
Close Date: 04/02/2010

Meter Reading: 25,305.00

Problem?

remove wireless modual for repair q15

Task performed:

1. Fnd module inside panel of control tower; marked/taped all wires; rem module; reinstalled side panel.
2. Travel to Stn15; replc module; install btry in remote; remote didn;t work; rem panel; chk power frm remote; power switch old; chk wiring/relays-ok; remote started working; installed cvr. j

Parts

Quantity

901596CONTROL BOARD WIL BURT S0 31

1



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V30433

In Date: 03/04/2010 Meter Reading: 26,046.00
Close Date: 04/09/2010

Problem?

back up alarm and camera 10/7. Q15

Task performed:

Went to Stn15; fnd baackup alarm inop; R/R alm; ran/ck ok. j

Parts

575BACKUP ALARM ECCO 107 DEC

Quantity

1

Workorder: V30294

In Date: 02/27/2010 Meter Reading: 26,046.00
Close Date: 04/20/2010

Problem?

back up camera 10-7 Q15

Task performed:

1. Fnd rear camera inop; need to order camera.
 2. Install backup camera; reseal camera shield; travel to Stn15 from Stn16.
 3. Install helmet hook on eng cvr at pass side cab seat.
- j

Parts

NO PARTS USED

Quantity

Workorder: V31050

In Date: 03/26/2010 Meter Reading: 26,543.00
Close Date: 04/20/2010

Problem?

WONT PASS VACCUM TEST Q15

Task performed:

Went to Stn15; ran vac test; passed; talked w/driver that pump tested trck; fnd master gauge was leaking when they did test. j

Parts

NO PARTS USED

Quantity

Workorder: V31384

In Date: 04/09/2010 Meter Reading: 26,766.00
Close Date: 04/27/2010

Problem?

Q15 front a/c 10/7

Task performed:

A/C leak; leaking at clamp; low press side charging part connection; change unit as per E.Ehrke; unit in svc; need to go to shop for appropriate repair.

Parts

NO PARTS USED

Quantity



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V31447

In Date: 04/12/2010
Close Date: 04/27/2010

Meter Reading: 26,766.00

Problem?

Hurst power unit not running right Q15 (on-call)

Task performed:

Parts

Quantity

1. R/R hurst pump not running right; go to shop; get spare; take to Stn15.
2. Return to shop; drop off eqmpt & restock svc truck & fuel up truck; paper work. j

NO PARTS USED

Workorder: V31192

In Date: 03/31/2010
Close Date: 04/28/2010

Meter Reading: 26,766.00

Problem?

FRONT A/C BLOWING WARM ON Q15.

Task performed:

Parts

Quantity

Went to 15; fnd freon level low; filled A/C sys; ck opn; ck ok. j

NO PARTS USED

Workorder: V31333

In Date: 04/07/2010
Close Date: 04/28/2010

Meter Reading: 26,766.00

Problem?

check the tire wear on q-15

Task performed:

Parts

Quantity

Fnd all tires wearing choppy; aggressive tire tread. j

NO PARTS USED

Workorder: V31514

In Date: 04/14/2010
Close Date: 04/29/2010

Meter Reading: 27,084.00

Problem?

front ac is not working q15

Task performed:

Parts

Quantity

Went to Stn15; fnd scraeder valve leaking; rep valve; topped off A/C sys; ran/ck ok. j

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V31489

In Date: 04/13/2010
Close Date: 04/30/2010

Meter Reading: 27,084.00

Problem?

left rear botom marker light burned out q15

Task performed:

1. Went to Stn15; fnd rear lites out; rem L/rear scrub rail; R/R marker lite; R/R (2) rear tailboard lights; ck ok.
 2. Ck rear spot lites; fnd R/lite out; rep wire to lite; ck ok.
- j

Parts

Quantity

35200-RLIGHT MARKER LED RED

4

Workorder: V31992

In Date: 05/04/2010
Close Date: 05/20/2010

Meter Reading: 27,525.00

Problem?

Q15 NEEDS NEW SAFETY NETS FOR THE CROSSLAYS

Task performed:

- Went to 15; rem both safety nets; replc nets; R/I roller asys; ck ok. j

Parts

Quantity

NO PARTS USED

Workorder: V32108

In Date: 05/10/2010
Close Date: 06/03/2010

Meter Reading: 27,685.00

Problem?

Relocate stabilizer pin for left rear stalilizer. Q15

Task performed:

- Remount outrigger pin on left rear outrigger cut off old holder & drill & mk new one on top.

Parts

Quantity

NO PARTS USED

Workorder: V32257

In Date: 05/18/2010
Close Date: 06/03/2010

Meter Reading: 27,741.00

Problem?

OFFICERS DOOR STEP BROKEN. NEEDS WELDED. Q15

Task performed:

- Rem step on R/frnt; mnt brkn off of button; mk new brckt & weld on to step; remnt on truck.

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V32298

In Date: 05/19/2010

Meter Reading: 27,741.00

Close Date: 06/08/2010

Problem?

repair a/c q15

Task performed:

- A/C inop; refrigerant leaded out both sys; rep leaks; replcd (4) splices & both dryers.
- Cab lift inop; L/S lock inop & lift pump manual level brkn; replc cab locks & rep pump.
- Assisted w/cab lift inop & A/C - Reines j
- Went to 15; fnd cab A/C empty; R/R discharge Schrader valve - vac/charge sys; ck opn; ck ok.
- Ck federal Q - siren sometimes doesn't work; fnd pedal switch worn; went to Stn15; R/R siren button w/used one; wired switch.
- Move/remntd remote controller hooks, clamps; installed strap for fire ext; remntd other fire ext; mntd (2) hose packs on right deck. j

Parts

Quantity

16-31438915 VALVE CORE A/C 3544706C1	4
35200-RLIGHT MARKER LED RED	1
4579S08-3422BS SPLICE	2
5269LPVM-5 SM MOUNT	4
53-4470LATCH CAB HYDRAULIC WPB	1
74R258607-2613A RED DOT DRIER 7127	2
827011-001CAB LIFT LOCK	1
94862PIGTAIL LED MARKER LIGHTS	1
SAHSVS2510STRAP	1
UMVS254411STRAP 46 IN	2

Workorder: V32422

In Date: 05/25/2010

Meter Reading: 27,741.00

Close Date: 06/11/2010

Problem?

replace rear tires boulevard

Task performed:

Replace rear tires - Boulevard j

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD TIRE



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V32434

In Date: 05/25/2010

Meter Reading: 27,741.00

Close Date: 06/11/2010

Problem?

cab lock warning going off q15

Task performed:

1. Went to Stn 15; t-shoot cab locks & switcheds; need locks.
2. ordered parts; went to shop for locks; went to 15 from 21; raised ladder/cab; R/R locks; ck opn; ck ok; return home.
3. Fnd drivers rear step brkn; rem step; rep; went to 15; installed/drilled step; ck ok; fnd Fed Q. switch inop; R/R switch; ck ok.
4. Cut/grnd & rep step - welded.

Parts

Quantity

827011-001CAB LIFT LOCK	2
FREIGHTSHIPPING CHARGES	75

Workorder: V32686

In Date: 06/06/2010

Meter Reading: 28,040.00

Close Date: 06/18/2010

Problem?

tip of ladder hit tree breaking welded area at tip of yellow section. Q15

Task performed:

- Phone call w/ DC Chief about ladder; call Jerry out; spare ladder; call back DC to call FOO.

Parts

Quantity

NO PARTS USED

Workorder: V32711

In Date: 06/07/2010

Meter Reading: 28,040.00

Close Date: 06/21/2010

Problem?

tip of ladder hit tree breaking welded area at tip of yellow section. Q15

Task performed:

1. Rem brkts & fix rest on ladder tip for welder, then replace them & yellow tip; order new light.
2. Assist in replc tip on end of ladder. Reines j
3. Fnd brkt on end of ladder bent; tried to straighten it-not lock; so rem it & try box & wire; order new brkt. j

Parts

Quantity

0757073NOZZLE O-RING	1
7001-40ESEAL 4 IN	2
740-1686ENDD FRAME QUINT	1
FREIGHTSHIPPING CHARGES	200



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V32607

In Date: 06/02/2010

Meter Reading: 27,871.00

Close Date: 06/30/2010

Problem?

repair flat q15 boulevard

Task performed:

Parts

Quantity

Repair flat Q15 - Boulevard j

NO PARTS USED

Vendor?: BOULEVARD TIRE

Workorder: V32792

In Date: 06/10/2010

Meter Reading: 28,137.00

Close Date: 06/30/2010

Problem?

labor for welding on ladder van linda

Task performed:

Parts

Quantity

Labor for welding on ladder - Van Linda j

NO PARTS USED

Vendor?: VAN LINDA IRON WORKS

Workorder: V33452

In Date: 07/11/2010

Meter Reading: 28,619.00

Close Date: 07/26/2010

Problem?

Q15 foam pump 10/7

Task performed:

Parts

Quantity

went to 15; fnd foam fill pump inop; rem hose; rep kink in hose; needs swtch returned to 15; R/R switch panel; fnd switching valves stuck; freed valve; filled foam tank. j

111602SPS PANEL

1

S153BLOW GUN

1

S777COUPLING NIPPLE

1

Workorder: V33510

In Date: 07/13/2010

Meter Reading: 28,619.00

Close Date: 07/26/2010

Problem?

Q15 foam tank primer pump 10/7. gas power fan needs pull cord repaired,

Task performed:

Parts

Quantity

Fnd ram fan rope brkn; rem recoil asy; replc rope; reinstalled; ck opnh; ck ok. j

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V33608

In Date: 07/18/2010
Close Date: 07/26/2010

Meter Reading: 2,887.00

Problem?

Axe mount on tip of quint ladder missing strap tie down. rubber strap at axe handle broken off or missing. Tempoary repair by firefighter by using velcro strap until it can be repaired. q15 Thanks

Task performed:

travel to 15; Replcd axe mnt (parts) DNI j

Parts

NO PARTS USED

Quantity

Workorder: V33130

In Date: 06/25/2010
Close Date: 07/29/2010

Meter Reading: 28,137.00

Problem?

install light on ladder 15

Task performed:

1. Went to 15; Mntd/wired spot light; ran/ck opn; ck ok.
2. Went to 15; drilled/mntd nozzle remote holder, helmet hooks; mov/mntd nozzle holders.
3. Made, drilled & mntd plates & holders for N.Y. ___ on ladder; ck ok. j

Parts

OPA570SCENE LIGHT

Quantity

1

Workorder: V33345

In Date: 07/06/2010
Close Date: 08/02/2010

Meter Reading: 28,520.00

Problem?

DO YOU HAVE ANY STABLE WE CAN GET FOR OUR VARIOUS GAS CANS ON THE TRUCKS? IF NOT, DO YOU KNOW IF I HAVE TO ORDER IT? q15

Task performed:

Went to 15; dropped off nozzle fuel stabilizer for quint/brush truck. j

Parts

NO PARTS USED

Quantity



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V34351

In Date: 08/18/2010
Close Date: 09/01/2010

Meter Reading: 29,349.00

Problem?

both front and back a/c not working q15

Task performed:

1. Chk track; fnd both compressors not working; chk wiring; fnd trinary switch on frt sys bad; R/R switch; made compressor run; fnd sys overcharged; took 3/4 lb. out of frnt; worked good.
2. Chk rear sys; fnd compressor not working; chk wiring; fnd temp switch bad; R/R temp switch & compressor works; fnd sys a little low; added 8 oz. air on rear sys.
js

Parts	Quantity
71R31001331 THERMOSTAT A/C	1
71R755011-2624 TRINARY SWITCH A/C 1560	1
78R536078R5360M 2PK FILTER AIR COND	1
H4656USE CV TYPE HEAD LIGHT	1

Workorder: V34330

In Date: 08/17/2010
Close Date: 09/03/2010

Meter Reading: 29,349.00

Problem?

I-2 compartment door. pin on the door piston is broken Q15

Task performed:

Went to Stn15; fnd door close cyl end brkn off; rem brkn end; replc; ck opn-ck ok. js

Parts	Quantity
NO PARTS USED	

Workorder: V34535

In Date: 08/26/2010
Close Date: 09/03/2010

Meter Reading: 29,349.00

Problem?

door piston for I-1 driver side is 10-7 Q15

Task performed:

Went to 15; fnd piston msng & brkt damaged; rep brkts, shock ___ & replc shock; ck ok. js

Parts	Quantity
EAA-8350-60UGSS6557UP STRUT-LIFT	1

Workorder: V34625

In Date: 08/30/2010
Close Date: 09/03/2010

Meter Reading: 27,741.00

Problem?

needs front tires (callout repair)

Task performed:

Called stn & tire co. for replacement. js

Parts	Quantity
NO PARTS USED	



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V34060

In Date: 08/05/2010
Close Date: 09/07/2010

Meter Reading: 29,109.00

Problem?

rear a/c not cooling q15

Task performed:

Parts

Quantity

1. Went to 15; Fnd frnt A/C inop; raised ladder/cab; t-shoot & rep connection at trinary switch; ran/chk ok.
2. Ck rear A/C - inop; fnd no power; out of node 2; reprogrammed node 1 & 2; no charge. j

NO PARTS USED

Workorder: V34623

In Date: 08/30/2010
Close Date: 09/29/2010

Meter Reading: 27,741.00

Problem?

replace front tires (outside agency- boulevard)

Task performed:

Parts

Quantity

Replc front tires - Boulevard j

NO PARTS USED

Vendor?: BOULEVARD TIRE

Workorder: V32714

In Date: 06/07/2010
Close Date: 10/19/2010

Meter Reading: 27,741.00

Problem?

Replace wheel rim Q15

Task performed:

Parts

Quantity

Completed

NO PARTS USED

Workorder: V35444

In Date: 10/06/2010
Close Date: 10/25/2010

Meter Reading: 29,848.00

Problem?

repair flat tire boulevard

Task performed:

Parts

Quantity

Repair flat tire - Boulevard j

NO PARTS USED

Vendor?: BOULEVARD TIRE



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V35231

In Date: 09/27/2010

Meter Reading: 30,135.00

Close Date: 10/28/2010

Problem?

C inspection and repairs as needed q 15

Task performed:

Parts

Quantity



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

1. Eng warn "stop eng light" on. Tighten loose fuse clamps.
2. C-Inspection.
3. Cross nozzle holder full of wtr; made drain holes.
4. Rear axle flange bolts loose; tightened.
5. Svc ladder & ladder inspection.
6. Foam sys inop; hose frm tank pinched; rep foam sys.
7. Rem frnt wheels & cvrs; chk brake & torque lug nuts; inspected frnt brakes & retorqued lug nuts.
8. Replc wiper blades - worn.
9. Chk tires; have to rem wheel cvrs; R/R I valve stem brkn; rotated rea tires; fnd problem w/valve stem ext leaking; installed braided extensions to stop inside tire leak.
10. Svc gen.
11. Svc air dryer & purge valve.
12. P/S leak; fitting on pump boss o-ring; rem seized fitting & cld area.
13. L/R cab door hard to open; linkage binding inside door; diss door & rep linkabe.
14. Door panels loose & msng screws; svc all cab doors; replc msng stripped screws.
15. Williams fnd dial arrow not legible; rep arrow.
16. Q. sire inop - poor grnd; rep grnd; cldd corrosion frm mntng plate & installed grnd cable.
17. A/C inop - discharge fitting @ L/S compressor leaking; locate leak rep fitting rerouted discharge line.
18. Svc ram fan.
19. Ram fan pull rope sticking; also stalls @ low speed; reworked pull rope; cld not get working properly; replc pull rope asy; also cldd carb jets; installed fresh fuel/stabilizer.
20. Washers inop; nozzle clogged; replc left nozzle & cldd R/S.
21. Left intake cap chain brkn; replc chain.
22. Ladder decals expired; rem old & installed new decals on 14 ft x 2 & ___ ladder.
23. R/F brake line rubbing tire; made new aero equip line & installed.
24. (2) velcro strap worn; replcd.
25. Cab door flashing red lights - loose mntng; rep light mntng.
26. Cvr for aerial hyd switch loose; stripped & msng screws; rep hyd cvr.
27. 110V tip light cable frayed; rep RK rip light witin
28. Trans code (63-40 255 counts inactive); chkd wiring, cldd connectors; cleared code; road tested ok.
29. Intake press gauge reading press with no wtr; t-shoot faulty intake press sensor; R/R sensor; test gauge - all ok.

102161	TRANSDUCER 500 PSI	1
108-12	FBEADED CHAIN W/CONN 12	1
15W40	BSYN OIL BULK QTS	40
31-052	RREBUILT REWIND ASSBLY	1
440-5	VALVE EXT.	2
8201L17-3428	ESTER OIL E7	1
AMH-1	AMH-1 VALVE EXTENSION	1
HA24063	HOOK WHEELED COACH	1
P1147G	FUEL FILTER 33120 WIX DELCO TP916	1
PH7405 51971	OIL FILTER WIX	2
PS683033442	FUEL FILTER	1
UMVS162511	STRAP	3
33063	FUEL FILTER ONAN	1
50-24	WIPER BLADE - KME	2
5008414	CARTRIDGE DC100	1
K022105	PURGE VALVE AD-IP-IS	1
PH47 51758 L/F	PH725 OIL FILTERL	1
4411S08-6962	BS 90 DEGREE SB1322	1
51064	OIL FILTER ONAN	1
UMVS254411	STRAP 46 IN	2

1. Cab door flashing red light - loose mntng; rep light



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

mnt.

- 2. Cvr for aerial hyd switch loose; stripped & msng sirens; rep hyd cvr.
- 3. 110V tip light cable frayed; rep wiring.
- 4. Trans

Workorder: V35973

In Date: 10/28/2010 Meter Reading: 29,848.00
Close Date: 11/03/2010

Problem?

REPAIR RUNG ALIGNMENT Q15

Task performed:

Travel to stn; Rung alignment light inop; switch arm bad; rep switch arm. j

Parts	Quantity
035605MICRO SWITCH GRAINGER #4B811	1
102162TANK LEVEL TRANSDUCER PRES	1

Workorder: V34660

In Date: 09/01/2010 Meter Reading: 29,349.00
Close Date: 11/17/2010

Problem?

perform ladder certification test (outside agency-Mistras Group Inc.)

Task performed:

Perform ladder certification test - Mistras Group j

Parts	Quantity
NO PARTS USED	

Vendor?: MISTRAS GROUP

Workorder: V36167

In Date: 11/03/2010 Meter Reading: 29,848.00
Close Date: 11/17/2010

Problem?

REPAIR RUNG ALIGNMENT Q15 and reported repairs

Task performed:

Parts only - replc rung alignment switch. j

Parts	Quantity
EL-10366MICRO SWITCH XCKL1041	1

Workorder: V36347

In Date: 11/10/2010 Meter Reading: 30,601.00
Close Date: 11/19/2010

Problem?

right side nozzle buckel fell off for pre connect q15

Task performed:

1. r/s crosslay nozzle holder is off truck, reinstall crosslay holder. jab

Parts	Quantity
NO PARTS USED	



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V37036

In Date: 12/09/2010
Close Date: 12/30/2010

Meter Reading: 30,976.00

Problem?

OIL DIP STICK TEE HANDLE BROKE OFF Q15

Task performed:

(1) TRAVELED TO ST15 TO CHECK OUT OIL DIP STICK THAT HAD BROKEN OFF ON Q15, REPLACED WITH NEW ONE.
(2) INSTALLED LOW WATER WARNING LABLE.
J.W

Parts

Quantity

23532156OIL DIP STICK DETROIT 60

1

Workorder: V37401

In Date: 12/25/2010
Close Date: 01/13/2011

Meter Reading: 31,071.00

Problem?

A/C LINE LEAKING GOING INTO CONDENSER IN FRONT OF RADIATOR. Q15

Task performed:

1. A/C inop - line leaking at condensor; needs to go to shop.
2. Belts squeels - fan belts loose; adj fan belts.
3. Rep leak at condensor; crimp bad; recrimp line & recharge. j

Parts

Quantity

NO PARTS USED

Workorder: V37676

In Date: 01/07/2011
Close Date: 01/18/2011

Meter Reading: 31,421.00

Problem?

PPV FAN,NEEDS HOOK UP ON MUFFLER FOR EHAUST PIPE. Q15

Task performed:

Travel to 15; exh adapter msng; install new adapter.
j

Parts

Quantity

NO PARTS USED

Workorder: V38349

In Date: 02/08/2011
Close Date: 02/15/2011

Meter Reading: 32,137.00

Problem?

MOVE AND REWIRE HAND LIGHT Q15

Task performed:

Travel to Stn15; move & remount handlight on motor box; rewire ight; R/R fuse. j

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V38507

In Date: 02/14/2011 Meter Reading: 3,225.60
Close Date: 02/25/2011

Problem?

Q15 dome lights out, front and rear red dome lights.

Task performed:

1. Travel to stn; dome lights inop; installed new bulbs.
2. L/R cab light inop - LED brkn; replcd light. j

Parts	Quantity
37000003722-44816-001 DOME LIGHT RECT	1

ref to wo 39589

Workorder: V38878

In Date: 03/01/2011 Meter Reading: 3,225.60
Close Date: 03/03/2011

Problem?

Q15 Check engine light on (callout repair)

Task performed:

1. Travel to Stn15; fnd active code for VSG; chkd connections - ok; swap out veh to eng. j

Parts	Quantity
NO PARTS USED	

Workorder: V38880

In Date: 03/01/2011 Meter Reading: 3,225.60
Close Date: 03/22/2011

Problem?

Q15 Check engine light on

Task performed:

1. Travel to HQ for calibration specs off Q47 to be used on Q15; install new command master gov; test - NG; rem side panel in L-1 compt & replc gov module - ok; erase eng codes.
2. Assist in removal & install of pump control command master - McIntosh.

Parts	Quantity
NO PARTS USED	

Workorder: V40111

In Date: 04/25/2011 Meter Reading: 33,853.00
Close Date: 04/27/2011

Problem?

REPLACE BATTERY Q 15

Task performed:

1. Travel to 15; R/R btrys. j

Parts	Quantity
BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER BATTERY	2
HP-31D BATTERY 950CCA HP-31D	2



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V40113

In Date: 04/25/2011 Meter Reading: 33,853.00
Close Date: 04/27/2011

Problem?

ON CALL BATTERY DEAD Q 15

Task performed:

Travel to Stn15; test btrys - (4) bad; replc btrys; need (2) more replcd; add 2 qts oil & 1 qt trans eynd; travel home.
j

Parts	Quantity
15W40QSYN OIL QT	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
HP-31DBATTERY 950CCA HP-31D	4
TRANSYNDALLISON TRANS FLUID GAL	1

Workorder: V40217

In Date: 04/28/2011 Meter Reading: 33,880.00
Close Date: 05/03/2011

Problem?

Q15 still turning over slow when starting.

Task performed:

Travel to Stn15; replcd starter & tested ok. j

Parts	Quantity
19939826356 QUINT 42MT STARTER	1

Workorder: V40309

In Date: 05/02/2011 Meter Reading: 33,952.00
Close Date: 05/18/2011

Problem?

left front tire is wear on the inside edge Q15

Task performed:

Left front tire is worn on the inside edge Q15 - Elpex
j

Parts	Quantity
NO PARTS USED	

Vendor?: ELPEX

Workorder: V40545

In Date: 05/11/2011 Meter Reading: 34,097.00
Close Date: 06/13/2011

Problem?

red light on the inside of the officers door . ring that holds the light in is broken, Sta15.

Task performed:

1. PU parts from stn to get correct one frm parts room.
2. Replc light ring on officers door. j

Parts	Quantity
2FLANGEBLIGHT FLANGE	1



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V41163

In Date: 06/07/2011 Meter Reading: 34,428.00
Close Date: 06/13/2011

Problem?

q-15 the r-2 door piston is broken, Sta 15.

Task performed:

Travel to 15; rep door hold open. j

Parts

Quantity

NO PARTS USED

Workorder: V41234

In Date: 06/09/2011 Meter Reading: 34,428.00
Close Date: 06/14/2011

Problem?

Q15 CHAINSAW WON;T START

Task performed:

Cldn carb & air filter started up fine. j

Parts

Quantity

NO PARTS USED

Workorder: V41274

In Date: 06/11/2011 Meter Reading: 34,428.00
Close Date: 06/14/2011

Problem?

hurst power unit leaking gas. will not run. Q15

Task performed:

travel to stn15; fnd crank case full of fuel; drained case & replc oil. j

Parts

Quantity

NO PARTS USED

Workorder: V41461

In Date: 06/20/2011 Meter Reading: 34,628.00
Close Date: 06/28/2011

Problem?

Q15 hurst power unit needs to be looked at again. We turned on the fuel to start it this morning and fuel is leaking heavily from ca

Task performed:

Travel to 15; cldn float bowl & needle in carb. j

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V41645

In Date: 06/28/2011
Close Date: 06/30/2011

Meter Reading: 34,882.00

Problem?

Hurst crank case full of gas AGAIN. We will be at HQ from 1 to 5, Sta 15.

Task performed:

Travel to 15; drained oil frm Hurst unit & refilled; ran unit - ok. j

Parts

NO PARTS USED

Quantity

Workorder: V41742

In Date: 07/01/2011
Close Date: 07/07/2011

Meter Reading: 34,914.00

Problem?

check engine light came on when first started in the morning. then goes out in about ten sec. Sta 15.

Task performed:

travel to 15 checked codes found coolant leve code - sensor ak

Parts

23520380SENSOR COOLANT

23520381DETROIT COOLANT LEVEL SENSOR

1

1

travel to 15 pepaired loose connection to coolant level sensor ak

Workorder: V42033

In Date: 07/14/2011
Close Date: 07/18/2011

Meter Reading: 35,225.00

Problem?

yellow and red engine warning dash lights coming on again. all temp gauges within normal levels. q 15

Task performed:

CHECK OUT TRUCK FOUND COOLANT WAS LOW 3/4 GALLON ADD
CHEK FOR LEAKS OK
HAD CODE FOR COOLANT LOW AND CODE 49
TURBO OVER HEAT AND LOW TEMP ALSO. AK

Parts

NO PARTS USED

Quantity



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V42080

In Date: 07/18/2011
Close Date: 07/18/2011

Meter Reading: 35,225.00

Problem?

Coolant leak.

Task performed:

TRAVEL TO ST 15 DIAGNOSE COOLANT LEAK
FOUND LOWER HOSE BLOWN DROP TUBE AND
REMOVE HOSE TRAVEL TO SHOP FOR PARTS AND
TO CHECK CAPTAIN 10 SIREN

TRAVEL FROM SHOP TO ST 15 INSTALL HOSE AND
TUBE RETHREAD CLAMP FOR TUBE FILL WITH
COOLANT PRESSURE CHECK OK

CODES IN ENGINE LADDER BED ALARM AK

Parts

Quantity

ALA00350-50 EXTENDED LIFE COOLANT GAL

6

ANTICOOLANT ANTIFREEZE GAL

6

Workorder: V42140

In Date: 07/20/2011
Close Date: 07/21/2011

Meter Reading: 35,270.00

Problem?

COOLANT LEAK.

Task performed:

travel to 15 added coolant and checked for leaks ok ak

Parts

Quantity

NO PARTS USED

Workorder: V39589

In Date: 03/31/2011
Close Date: 08/01/2011

Meter Reading: 33,425.00

Problem?

Driverside rear passenger compartments red dome lights out x2. q15

Task performed:

refer to wo 38507

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V40394

In Date: 05/04/2011

Meter Reading: 33,952.00

Close Date: 08/04/2011

Problem?

repair spots in glass

Task performed:

Parts

Quantity

travel to 15 checked glass and reported to mike

NO PARTS USED

Workorder: V42782

In Date: 08/13/2011

Meter Reading: 35,701.00

Close Date: 08/16/2011

Problem?

could you please track down our hurst power unit and get it back to us. it's been over a month. thanks. Sta 15

Task performed:

Parts

Quantity

unit out for repair with hurst

NO PARTS USED

Workorder: V42972

In Date: 08/22/2011

Meter Reading: 35,861.00

Close Date: 09/08/2011

Problem?

Replace rear tires.

Task performed:

Parts

Quantity

Replace rear tires - Tiresoles j

NO PARTS USED

Vendor?: TIRESOLES

Workorder: V43884

In Date: 09/23/2011

Meter Reading: 36,012.00

Close Date: 10/03/2011

Problem?

REBUILD HYD. CYL.

Task performed:

Parts

Quantity

Rebuild hyd cyl - Construction Hyd j

NO PARTS USED

Vendor?: CONSTRUCTION HYD



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V43005

In Date: 08/23/2011

Meter Reading: 35,861.00

Close Date: 10/20/2011

Problem?

right rear lug nut Replace.

Task performed:

r/r lug nut, seized, removed lug nut and repaired threads and ordered new studs, will bring back in the pm for repair

Parts

Quantity

20X2040WHEEL STUD

20

E-600013-3052 NUT

1

FREIGHTSHIPPING CHARGES

126

Workorder: V43646

In Date: 09/13/2011

Meter Reading: 36,012.00

Close Date: 10/28/2011

Problem?

UL TEST UNIT Q 15

Task performed:

UL test unit Q15 - Mistras j

Parts

Quantity

NO PARTS USED

Vendor?: MISTRAS

Workorder: V41363

In Date: 06/15/2011

Meter Reading: 34,628.00

Close Date: 11/01/2011

Problem?

ladder creeps down when raised Q 15

Task performed:

see work order 43085

Parts

Quantity

FREIGHTSHIPPING CHARGES

13

HY10382SV3 CARTRIDGE SMEAL

2



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V43085

In Date: 08/26/2011

Close Date: 11/01/2011

Meter Reading: 36,112.00

Problem?

C inspection.

Task performed:

Parts

Quantity



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

C INSPECTION x 4 DAYS wo 41363	1229F4634SKIT RING/LOCK WASHER	1
SERVICE T CASE	13047CLEVIS D-RING 3/4	1
R&R BATTERIES AND MADE TWO LONG POS. CABLES	140-2897AIR FILTER ONAN 49697	1
ASSIST WITH C SERVICE (BILL H.)	14714-1-5COOLER NEW QUINTS	1
ASSIST WITH C INSPECTION (SCOTT MCWHITE)	15W40BSYN OIL BULK QTS	36
R&R STUB ON BOTH REAR HUBS	1619296P/S RESERVOIR SEAL	1
BRING HYDRAULIC CYLINDERS FROM HYD. SUPPL`	29526898 29548988 TRANS FILTER ALLISON	1
REMOVE EXTENSION CYLINDERS TO SEND TO BE REPAIRED	3202099SEAL WITH RACE QUINT	2
ASSIST WITH REMOVAL OF CYLINDERS (REINES)	33063FUEL FILTER ONAN	1
START PULLING WHEELS AND BRAKE TO CLARN AND REPACK BEARINGS, FOUND THE SPENDLE -- NEEDED A SPECIAL TOOL AND WE DID NOT HAVE ONE SO STAN AND JERRY MADE A TOOL TO REMOVE NUT AND HUB ASS.	392932HOSE AND FITTING	1
FIND MATERIALS CUT AND WELD PIECES TO MAKE A SPECIAL TOOL FOR REMOVAL AND INSTALL OF BEARING HUB NUTS	39769F0062GUIDE AND SEAL KIT	2
CHECK STEP LIGHT FOUND LIGHT GOOD AND PUT BACK ON STEP MOUNT	401581GASKET AXLE FL80 R002435	2
R&R LENS ON BOTH PUMP PANLE LIGHT ON PASSENGER SIDE	5008414CARTRIDGE DC100	1
REMOVE HAND RAILS ON LADDER PLATFORM, ORDER THEM AND CLEAN UP RUST IN HOLES FOR NEW HAND RAILS	51064OIL FILTER ONAN	1
ASSIST WITH HAND RAILS (STAN)	68-3963453-30LENS CLEAR FOR STRIP LIGHT	2
STARTED TO REMOVE BELTS, FOUND POWER STEERIN LEAK SO CLEANED UP PUMP AND TIGHTEN FITTING ON PUMP, REMOVE A/C BELT, FOUND OIL GROUND COMPRESSER PULLY CLEAN ALL OIL AROUND COMPRESSER	75W90GEAR OIL SYN QT	26
CHECK FOR AC LEAK AT COMPRESSOR WITH LEAK TESTER, I WOULD ---OFF SO RECOVER FREON AND FOUND IT HAD FALL--CHARGE 3 LB 4 OZ SO CHARGED BACK UP AND INSTALLED BELTS AND FAN ON FAN CLUTCH	768-0007HAND RAIL	1
	768-0008LADDER BAR SIDE	1
	773092 TRUNNION	1
	78R536078R5360M 2PK FILTER AIR COND	1
	91368904 VALVE KIT 1 1/2 IN	1
	ANTICOOLANT ANTIFREEZE GAL	5
	AW32-5G5 GAL AW32 HDY OIL	4
	BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	6
	BTH-0022AC00060 WHEEL BRG	2
	C00066INTERNAL CIRCLIP	2
	C00074LODKING WASHER	2
	C00077M22 WHEEL STUD STEEL	20
	E-600013-3052 NUT	40
	FA10170SNAP RING EXT CYL LADDER	8
	FA11901PIN EXT CYL LADDER	4
	FG87904MFG3937557S FILTER P/S NEW STYLE	1
	HP-31DBATTERY 950CCA HP-31D	6
	K010604CALIPER BOLT SEAL KIT	2
	K022105PURGE VALVE AD-IP-IS	1
	P1147GFUEL FILTER 33120 WIX DELCO TP916	1
	PH7405 51971 OIL FILTER WIX	2
	PS683033442 FUEL FILTER	1
	S1815COUPLER MILTON	1
	TRANSYNDALLISON TRANS FLUID GAL	10
	H3522TSX22 MM STUD EXT	2
	9420BELT	1
	9435BELT	3
	K080570BELT	1
	FREIGHTSHIPPING CHARGES	113



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

SERVICE POWER STEERING FILTER

STARTED SERVICING GEN ALL FILTERS WERE VERY HARD TO GET TO, AIR FILTER IS IN DUCT WORK IN PUMP COMPARTMENT UNDER GEN. SO I PUT STICK FOR NEXT TECH AND ORDER FILTER

SERVICE AIR DRYER

REMOVE FRONT WATER INLET PIPE AND CLEAN UP TO BE WELD, WELD AND PAINT PIPE AND INSTALL PIPE

GET AIR FILTER AND INSTALL IT, BLEED FUEL AND STARTED WIRING --ENGINE AND CHECK FLUIDS RAN GOOD ADDED ANOTHER STICKER TO TELL TECH ACCESS IS EHIND DUCT

REMOVE PADS FOR ALDDER TO BED ON FOUND LOTS OF RUST, SANDED TO SEE HOW BAD PITTING WAS, FINISH SANDING AD TREATED WITH RUST ENCAPSULATOR AN TAP---TINS INSTALLED PADS

DID VACUM TEST FOUND NO DISCHARGE VALVE LEAKING SO PUT TANK RE---LATOR VALVE R&R VALVE AND PASS VACUM TEST

CLEAN AND GREASE STABLIZER CHANNLES

INSTALL HAND RAILS ON LADDER PLATE FORM

ASSIST WITH HAND RAILS (SCOTT)

INSTALL EXTENSION CYLINDER

ASSIST WITH EXTENSION CYLINDER (SCOTT)

REMOVE TANS COOLER AND COOLER LINE TO SEND TO MAKO

SERVICE TRANS AND ASSIST WITH COOLER LINE (SCOTT)

REMOVED TRANS COOLER LINES WENT TO MAKO HAD NEW LINES MADE, REINSTALLED

FINISHED INSTALLING NEW TRANS COOLER AND FLUIDS

CLEANED PREPPED LADDER FOR INSPECTION FINISHED CYLINDERS

INSTALLED LIFT CYLENDER HOLDING VALVES AND CHECKED FLUIDS



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

INSTALLED HUB AND CALIPER AND WHELL SO LADDER CAN BE UL TESTED

CLEAN LADDER TOP OFF ALL FLUID

CHECK EXTENSION CABLES FOUND THEM LOOSE SO READJUSTED THEM

ASSISTE WITH CABLE ADJUSTMENT (SCOTT)

CHECKED REAR WATERWAY PRESSURE GAUGE LOW ON STABILIZER OIL REMOVE GAUGE AND FILL IT WITH OIL AND INSTALL GAUGE

CHECK TRANSMISSION COOLER LINES AND ELECTRIC HYD. PUMP LINES AFTER SETTING OVER NIGHT AN NO LEAKS FOUND STARTED TRUCK AND AN EPUMP STILL NO LEAKS

CHECK THIRD SECTION 4TH RA WHERE THE ELECT. WIRE ARE GOING IN TO MAIN RAIL AND SEALED IT WITH BLOCK SILICONE

CHECK FOR AIR LEAK AT PUMP PANEL NO LEAK FOUND

CHECK MAGNETIC SWITCHES ON JACK FEET AND BASE SECTION RETRACTION AND TIGHTENED THE CHECK AERIAL REMOTE CALLED S--EAL AND TALK TO TECH, HE EXPLAINED OPERATION OF THE REMOTE AND IT WORKED GOOD NO PROBLEM WITH REMOTE OR MONITOR LEFT AND RIGHT ROTATION

CLEAN UP TRANSMISSION COOLER LINES AND ELECT HYD. PUMP LINE FOUND NO LEAK SO LET SIT OVER NIGHT

FINISH LIST FOR UL TEST FOUND PUMP PANEL WATERWAY FLOOR WINDOWS--UNDER PL--- IN AND TEST IS ALL NUMBER COME UP

REMOVE BOTH FRONT HUBS AND R&R BEARING ASSIST WITH FRONT BEARING

WENTTO TTP WITH HUBS FOR NEW STUDES, THEY COULDNT MATCH THEM HAD TO ORDER NEW, CLEANING ALL THE PARTS AND FOUND A LOT OF OLD LOCK TIGHT IN ALL THE HOLES HAD TO GRIND IT OUT TO CLEAN HOLES AND HAD ALL BOLTS AND HOLES TO CLEAN , WASH ALL THE OTHER PARTS UP THEN CLEAN UP AROUND TRACK



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V41526

In Date: 06/22/2011

Meter Reading: 34,475.90

Close Date: 11/02/2011

Problem?

lense cover is off on left rear steps. can be repaired at pm. q15

Task performed:

Parts

Quantity

ref to wo 43085

NO PARTS USED

Workorder: V44544

In Date: 10/20/2011

Meter Reading: 36,012.00

Close Date: 11/02/2011

Problem?

replace front wheel bearings and lug studs.

Task performed:

Parts

Quantity

1. installed new wheel studs bearing & lug nuts.
2. Test drove unit; filled w/fuel/wtr. j

NO PARTS USED

Workorder: V44992

In Date: 11/05/2011

Meter Reading:

Close Date: 11/09/2011

Problem?

the lighting on the Command Master Smart Pump screen is unreadable. To dim to read.Q15

Task performed:

Parts

Quantity

Work completed on WO 45011. j

NO PARTS USED

Workorder: V45011

In Date: 11/07/2011

Meter Reading: 36,253.00

Close Date: 11/10/2011

Problem?

Auto eject. Sta 15.

Task performed:

Parts

Quantity

1. Auto-eject not working; rem frm truck; fnd that plunger needed lubrication; reinstalled - chkd ok.
2. Command master not working; rem frm truck; installed new unit; programmed to truck; chkd on - ok.
3. Chk eng light on - chkd codes; fnd to be low coolant; filled - chkd ok. j

111085COMMAND MASTER CLASS 1

1



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V44974

In Date: 11/04/2011

Meter Reading:

Close Date: 11/23/2011

Problem?

charger outlet not releasing cord when the q15 is started, sta 15.

Task performed:

Parts

Quantity

removed from truck found pin on eject solinoid dry and dirty cleaned -- checked ok

NO PARTS USED

Workorder: V45406

In Date: 11/24/2011

Meter Reading:

Close Date: 12/07/2011

Problem?

the pump screen system is reading false pump dischare and for the three checkoff ok box on screen to pump is only one working. but the truck pump water ok. i just go by individual gauge discharge.Q15

Task performed:

Parts

Quantity

adjusted governor to match gauges

NO PARTS USED

Workorder: V45609

In Date: 12/04/2011

Meter Reading:

Close Date: 12/07/2011

Problem?

pump control panel is set in (KPA) instead of (PSI) unable to determine proper discharge pressures. Unable to reset control panel proper settings Q15

Task performed:

Parts

Quantity

travel to 15 repogrammed pressure govonor

NO PARTS USED

Workorder: V45794

In Date: 12/12/2011

Meter Reading: 36,925.00

Close Date: 12/13/2011

Problem?

Q15 no start.

Task performed:

Parts

Quantity

travel to st 15, vehicle cranks but wont start, check fuel bowl on fuel fitler and drain fuel to check for quality ok, check for engine codes, none, check ecm connectors and fuses ok, laptop lost communication from ecm, swap into spare at station

NO PARTS USED

travel to shop to issue spare engine for charity event that was supposed to be used bat 1 spare engine, travel home



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V45795

In Date: 12/12/2011

Meter Reading: 36,925.00

Close Date: 12/20/2011

Problem?

Q15 cranks, won't start.

Task performed:

TRAVEL TO 15 DIAGNOSE PROBLEM TO WIRING ISSUE HAD TRUCK TOWED TO SHOP FOR FURTHER

ASSIST WITH WIRING.

Parts

Quantity

102162TANK LEVEL TRANSDUCER PRES

1

350000028ABS ECU

1

599908STARTER SOLENOID EONE

1

6400000006444-0000-00 VDR RVCAN

1

DT043PP007DEUTSCH RECEPTACLE

2

Workorder: V46028

In Date: 12/15/2011

Meter Reading: 36,925.00

Close Date: 12/27/2011

Problem?

throttle loss

Task performed:

ELECTRONIC PROBLEM WITH TRUCK CHARGE DATA BUS, ABS ECM, CAM SENSOR - CHECK WIRING PROGRAMMING AND HARNESSSES.

ASSIST WITH TROUBLE SHOOT.

Parts

Quantity

23527338SRS SENSOR

1

23527339TIMING REF SENSOR TRS

1

VF445F11FSO140A RELAY A/C DIODE SUP

3

Workorder: V46087

In Date: 12/27/2011

Meter Reading: 37,273.00

Close Date: 01/03/2012

Problem?

No idle, no power to ladder.

Task performed:

installed ne componets rebuilt hyd. pump installed crank sensor

assisted trouble shoot, delievered truck to station 15

Parts

Quantity

194BULB

8

350000054THROTTLE PEDAL

1

76054-60-NOSWITCH PRESSURE

1

76577-4-NC76577-4-NC SWITCH

2

KN20021DASH VALVE

1



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V45834

In Date: 12/13/2011
Close Date: 01/10/2012

Meter Reading: 36,925.00

Problem?

repair unit wont run

Task performed:

REMOVED BAD STARTER AND INSTALLED NEW ONE. CHECKED OK.

Parts

19939826356 QUINT 42MT STARTER

Quantity

1

Workorder: V46202

In Date: 01/01/2012
Close Date: 01/10/2012

Meter Reading: 37,273.00

Problem?

PTO FROM ROAD TO PUMP AIR LEAK. DID NOT ALWAYS SEAL SHUT DURING TRANFER OF SWITCH POSITION. ALSO OI OCATION, THE STARTER MOTOR NOT START/CONNECT WHEN PUSHING THE TOGGLE SWITCH TO START. q15

Task performed:

1. REBUILD UPS SHIFTER IN T-CASE.
2. ASSISTED ELECTRICAL TROUBLE SHOOTING.
3. WORKED ON ELECTRICAL ISSUE WITH DETRIOT DIESEL MECHANIC.

Parts

1212BTURTLE TILE 12X12 BLACK
5460370530VPS SHIFT KIT 546-0370-53-0

Quantity

6

1

Workorder: V46251

In Date: 01/03/2012
Close Date: 01/10/2012

Meter Reading: 37,273.00

Problem?

CHECK ENG LIGHT COMES ON Q15

Task performed:

Work completed on V46202

Parts

NO PARTS USED

Quantity

Workorder: V46324

In Date: 01/05/2012
Close Date: 01/10/2012

Meter Reading: 37,273.00

Problem?

Install Genesis tool brackets.

Task performed:

MOUNTED GENESIS TOOLS

Parts

NO PARTS USED

Quantity



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V46394

In Date: 01/07/2012
Close Date: 01/11/2012

Meter Reading: 37,444.00

Problem?

when batteries are on, the foam indicator top light blinks on and off and the pump panel displays states foam is "off line" on the Command Master panel. it does not re set when PTO pump is engaged. Q15

Task performed:

Parts

Quantity

TRAVEL TO 15 REPROGRAM GOVENER AND TEST.
OK

NO PARTS USED

Workorder: V46465

In Date: 01/10/2012
Close Date: 01/13/2012

Meter Reading: 37,444.00

Problem?

when you hit rpm on the pump panel pressure goes directly to preset A needs command master programming. Q15 will be at HQ 11 AM Q15

Task performed:

Parts

Quantity

RAN SYSTEM AND ADJUSTED. OK.

NO PARTS USED

Workorder: V46499

In Date: 01/11/2012
Close Date: 01/13/2012

Meter Reading: 37,444.00

Problem?

#3 discharge gauge stuck on 60 psi, Sta 15

Task performed:

Parts

Quantity

TRAVEL TO 15 DRAINED SYSTEM AND CLOSED VALVE.

NO PARTS USED

Workorder: V46566

In Date: 01/13/2012
Close Date: 01/18/2012

Meter Reading: 37,566.00

Problem?

small water leak on front steamer pipe underneat the front pumper, Sta 15

Task performed:

Parts

Quantity

FOUND VERY SMALL LEAK IN WELD ON PIPE. WILL HAVE WELDED ON NEXT SERVICE.

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V47089

In Date: 02/04/2012

Meter Reading: 37,988.00

Close Date: 02/28/2012

Problem?

Flasher out rear, top right; spot light out aerial base left side.Sta 15

Task performed:

1. INSTALL NEW FLASHER ON REAR OF TRUCK.
2. INSTALL NEW BULB IN SPOT LIGHTS.

Parts

Quantity

4007BULB NIGHT FIGHTER

1

50R03ZCRLIGHT LED RED TIR 6

1

Q500T3CLBULB HALOGEN 120V 500WATT 4 11/16 LONG

1

Workorder: V47298

In Date: 02/14/2012

Meter Reading: 38,130.00

Close Date: 02/29/2012

Problem?

need a new bracket for the pry bar. q15

Task performed:

REPLACED BRACKET.

Parts

Quantity

5269LPVM-5 SM MOUNT

1

Workorder: V47540

In Date: 02/24/2012

Meter Reading: 3,833.00

Close Date: 02/29/2012

Problem?

Headlight out

Task performed:

1. TRAVEL TO ST 15 CHECK VEHICLE HEADLIGHT OUT SCREWS FROZEN AND HEADS DAMAGED, HAD TO CUT TRIM FRAME OFF VEHICLE TO R&R HEADLIGHT.
2. ORDER PARTS NEEDED AND FILLOUT PARTS ORDER REQUEST ON COMPUTER.

Parts

Quantity

H4656USE CV TYPE HEAD LIGHT

1

Workorder: V44496

In Date: 10/19/2011

Meter Reading: 36,012.00

Close Date: 03/09/2012

Problem?

REPLACE STUD IN HUB

Task performed:

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V47726

In Date: 03/03/2012
Close Date: 03/19/2012

Meter Reading: 38,514.00

Problem?

tires starting to wear on the inside edge. need a mechanic to check. Q15

Task performed:

CHECKED TIRES INSIDE TREAD WORN DUE TO FRONT END WILL CHECK AGAIN.

Parts

NO PARTS USED

Quantity

Workorder: V47710

In Date: 03/02/2012
Close Date: 03/20/2012

Meter Reading: 3,842,300.00

Problem?

Q15 CHAINSAW WORKS BUT WONT IDLE. sta 15

Task performed:

CHECK CHAIN SAW - STARTED AND ADJUSTED - CHECK OK.

Parts

BPR5ESSPARK PLUG 7734

Quantity

4

Workorder: V47798

In Date: 03/07/2012
Close Date: 04/02/2012

Meter Reading: 38,587.00

Problem?

warning strobe light on rt.side for over load is 10/7. warning light comes on to early. truck was used for quint training. Sta 15

Task performed:

TRAVEL TO ST 15 CHECK OUT OVERLOAD LIGHT FOUND LIGHT BAD ORDER NEW LIGHT.

Parts

NO PARTS USED

Quantity

Workorder: V48109

In Date: 03/22/2012
Close Date: 04/02/2012

Meter Reading: 38,962.00

Problem?

flash light charger in the frontof cab not charging both flash lights not working, Sta 15

Task performed:

TRAVEL TO ST 15 CHECK OUT HAND LIGHT CHARGERS FOUND CHARGERS WORKING LIGHTS BAD R&R LIGHTS.

Parts

NO PARTS USED

Quantity



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V48839

In Date: 04/23/2012
Close Date: 04/25/2012

Meter Reading: 39,528.00

Problem?

check front tires

Task performed:

TRAVEL TO 15 INSPECTED FRONT TIRES AND ORDERED NEW SET FOR FRONT AXLE.

Parts

Quantity

NO PARTS USED

Workorder: V48806

In Date: 04/22/2012
Close Date: 05/03/2012

Meter Reading: 39,528.00

Problem?

flat tire passenger side, rear outside Q15

Task performed:

TRAVEL TO C/S TO GET PARTS FOR TIRE TECH (BOULEVARD TIRE) TO REPAIR Q-15. TIRE TECH CALLED - NEEDED TIRE PARTS AT CENTRAL SHOP.

Parts

Quantity

NO PARTS USED

FLAT TIRE PASSENGER SIDE, REAR OUTSIDE Q15.

Vendor?: BOULEVARD TIRE CENTE

Workorder: V49053

In Date: 05/02/2012
Close Date: 05/08/2012

Meter Reading: 39,679.00

Problem?

fan belt is slipping, left turn light on the inside dash, tool box on turn table cable for latch is broken.

Task performed:

1. TRAVEL TO 15 ADJUSTED FAN BELTS.
2. REPAIRED CABLE ON TOOL BOX LATCH.
3. REPAIRED DASH LIGHT.

Parts

Quantity

NO PARTS USED

Workorder: V49055

In Date: 05/02/2012
Close Date: 05/08/2012

Meter Reading: 39,679.00

Problem?

a/c not cold

Task performed:

CHECKED A/C FOUND NO PROBLEM.

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V49192

In Date: 05/08/2012

Meter Reading: 39,778.00

Close Date: 05/10/2012

Problem?

fan belt loosec q15

Task performed:

Parts

Quantity

TRAVEL BACK TO 15 ADJUSTED FAN BELTS ON QUINT.

NO PARTS USED

Workorder: V49201

In Date: 05/08/2012

Meter Reading: 39,838.00

Close Date: 05/10/2012

Problem?

The fan belt that is connected to the AC is still making noise. Mechanic was out earlier and fixed it but it is still making noise with the ac.

Task performed:

Parts

Quantity

TRAVEL TO 15 FOUND LOWER COMPRESSOR ADJUSTED BOLT MISSING INSTALLED BOLT AND ADJUSTED BELT RAN TRUCK OK.

NO PARTS USED

Workorder: V49255

In Date: 05/10/2012

Meter Reading: 39,838.00

Close Date: 05/15/2012

Problem?

REPLCE FRON TIRES

Task performed:

Parts

Quantity

REPLACE FRONT TIRES.

NO PARTS USED

Vendor?: ELPEX

Workorder: V49374

In Date: 05/15/2012

Meter Reading: 39,948.00

Close Date: 05/17/2012

Problem?

command master inop

Task performed:

Parts

Quantity

1. FOUND PSI ON COMMAND CONTROL INOP - R&R CONTROL PANEL - RAN PUMP- PUMP DROPS OUT ON PSI - FOUND INTAKE PRESSURE NEGATIVE. R&R TRANSLUCENT - RAN PUMP - CHECK OK.
2. ASSIST KEVIN WITH REPAIRS.

100581TRANSDUCER COMMAND MASTER 300 PSI

1

111085COMMAND MASTER CLASS 1

1



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V49438

In Date: 05/17/2012 Meter Reading: 40,079.00
Close Date: 05/18/2012

Problem?

Stihl chainsaw. Problems starting. Once started not running in idle. When run and turn off, unable to start again. Q47

Task performed:

ADJUSTED CARB AND REPLACED SPARK PLUG.
GAVE CREW AN EXTRA PLUG FOR EMERGENCY USE.

Parts

5921SPARK PLUG REPLACES BM6A

Quantity

2

Workorder: V49367

In Date: 05/15/2012 Meter Reading: 39,948.00
Close Date: 05/25/2012

Problem?

On the Command Master Panel- pre-set A and B will not operate in PRM Mode. Pre-set A and B will engage but then dis-engage i PSI Mode, (as rpms increase, but then goes back to idle). Pre-set A and B were set to 100/150 Q15

Task performed:

TRAVEL TO ST 15 CHECK OUT COMMAND MASTER
PRESET FALL OUT WHE SET R&R TRANS DUCER ON
PRESSURE SIDE SET PRESETS WORKING OK
WENT OUT AGAIN NEEDS NEW CONTROLL HEAD
SEND TO SHOP.

Parts

100581TRANSDUCER COMMAND MASTER 300 PSI

Quantity

1

Workorder: V48933

In Date: 04/26/2012 Meter Reading: 39,605.00
Close Date: 05/29/2012

Problem?

FRONT END ALIGNMENT

Task performed:

FRONT END ALIGNMENT.

Parts

NO PARTS USED

Quantity

Vendor?: CALLAGHAN TIRE

Workorder: V49007

In Date: 05/01/2012 Meter Reading: 39,679.00
Close Date: 05/29/2012

Problem?

Station leaf blowers not running.

Task performed:

PICKED UP LEAF BLOWERS AND BROUGHT TO SHOP

Parts

NO PARTS USED

Quantity



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V49294

In Date: 05/12/2012

Meter Reading: 39,948.00

Close Date: 05/29/2012

Problem?

ON CALL RERA TIRE FLAT Q 15.

Task performed:

CALLED BY DISPATCH, FLAT ON QUINT 15 AT FIRE SCENE. RESPONDED TO SCENE GOT TIRE SIZE CAME TO SHOP TO GET TIRE FOR THE COMPANY. THERE'S GOT TO BE A BETTER WAY. NOTE NO TUBES FOR UNMOUNTED TIRES!!!!TRAVEL TO APACHEE AND 97TH GOT TIRE SIZE ON UNIT AND CAME TO SHOP FOR TIRE AND WAITED FOR TIRE COMPANY.

Vendor?: BOULEVARD TIRE CENTE

Parts

Quantity

1100/1200R24/25TIRE TUBE

1

138655715 12R241200R24 TIRE

1

Workorder: V49490

In Date: 05/20/2012

Meter Reading: 40,079.00

Close Date: 05/29/2012

Problem?

K12 will not start. Quint possibly low on hydraulic fluid b/c must go to high idle when raising ladder from below zero degrees & stabilizers are slow to respond. Sta 15

Task performed:

1. TRAVEL TO 15 PICKED UP K12 TO BRING TO SHOPFUEL IS VARNISHED.
2. CHECKED HYD SYSTEM ON TRUCK NO PROBLEM FOUND.

Parts

Quantity

NO PARTS USED

Workorder: V49491

In Date: 05/20/2012

Meter Reading: 40,079.00

Close Date: 05/29/2012

Problem?

Difficulty engaging PTO. Q15

Task performed:

CHECKED PTO ENGAUGEMENT NO PROBLEM FOUND.

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V49607

In Date: 05/24/2012 Meter Reading: 40,305.00
Close Date: 05/31/2012

Problem?

CHECK LADDER CABLES Q 15

Task performed:

Parts

Quantity

CHECKED LADDER CABLES FOR TENSION OK AT THIS TIME.

NO PARTS USED

Workorder: V49611

In Date: 05/24/2012 Meter Reading: 40,305.00
Close Date: 05/31/2012

Problem?

PRESSURE GAUGES ON Q15 ARE LOW AND MISSING FLUIDS INSIDE GAUGES.

Task performed:

Parts

Quantity

CHECKED GAUGES STILL PLENTY OF OIL IN GAUGES AND ALL GAUGES WORK.

NO PARTS USED

Workorder: V49578

In Date: 05/23/2012 Meter Reading: 40,201.00
Close Date: 06/04/2012

Problem?

AERIAL VERY SLOW AT IDLE, ONLY WORKS WITH HIGH IDLE ON. Q15

Task performed:

Parts

Quantity

1. TRAVEL TO 15 OPERATE UNIT FOUND SYSTEM PRESSURE LOW AND DIFFERENT OF UPPER C/LOWER.
2. DID SEVERAL TESTS ON AERIAL PUMP ALL CHECK GOOD PRESSURE STILL LOW AT IDLE.
3. CHECKED SYSTEM COULD FIND NO PROBLEM.

PH47 51758 L/F PH725 OIL FILTERL

1



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V49778

In Date: 05/31/2012
Close Date: 06/04/2012

Meter Reading: 40,400.00

Problem?

The fire pump PTO is very difficult to engage. Q15

Task performed:

1. TRAVEL TO 15 FOUND NO AIR AT PUMP SHIFT PRIORITY VALVE SET TO HIGH 105 PSI TRUCK COMING TO SHOP IN A.M. NO VALVE ON TRUCK WILL REPAIR AT SHOP.
2. TRACED DOWN AIR LINE FOR PUMP SWITCH LINE FEEDS OFF PRESSURE PROTECTED AIR DRYER SYSTEM WORKS RIGHT.

Parts

Quantity

277148VALVE BRAKE

1

Workorder: V49780

In Date: 05/31/2012
Close Date: 06/04/2012

Meter Reading: 40,400.00

Problem?

REPAIR FLAT Q15

Task performed:

REPAIR FLAT Q15.

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD TIRE CENTE

Workorder: V50029

In Date: 06/11/2012
Close Date: 06/12/2012

Meter Reading: 40,551.00

Problem?

K12 saw inop

Task performed:

TOOK Q-15 SPARE K12 SAW.

Parts

Quantity

NO PARTS USED

Workorder: V49696

In Date: 05/29/2012
Close Date: 06/15/2012

Meter Reading: 40,400.00

Problem?

Need a new foam insert in the top of the Partner K950 K12 above the air cleaner

Task performed:

REPLACED FOAM INSERT IN K12 SAW.

Parts

Quantity

605-257AIR FILTER K950

1



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V50130

In Date: 06/14/2012
Close Date: 06/15/2012

Meter Reading: 40,551.00

Problem?

K12 ON QUINT 15 WILL NOT START

Task performed:

TRAVEL TO 15 STARTED K12 SAW. REPLACED FUEL IN CAN ADDED ADDITIVE TO UNIT OK.

Parts

NO PARTS USED

Quantity

Workorder: V50146

In Date: 06/15/2012
Close Date: 06/15/2012

Meter Reading:

Problem?

K12 SAW STILL NOT STARTING. NO ASSET# ON THE SAW, THATS WHY ENTERED UNDER UNIT.

Task performed:

delivered spare k12

Parts

NO PARTS USED

Quantity

Workorder: V50351

In Date: 06/24/2012
Close Date: 06/26/2012

Meter Reading: 40,831.00

Problem?

Q15 aerial when extended and fully lowered off rear off truck will not raise in low idle. Q15

Task performed:

CHECKED TRUCK OVER SEVERAL TIMES NO PROBLEM FOUND.

Parts

0/2-311-610-372SDUEL AIR GAUGE M2

Quantity

1

Workorder: V50493

In Date: 06/29/2012
Close Date: 07/03/2012

Meter Reading: 40,917.00

Problem?

top right running light not working

Task performed:

TRAVEL TO 15 REPLACED SHORTED CLEARANCE LIGHT.

Parts

47263CAN USE 47253 LED MAKER LIGHT YELLOW

Quantity

1



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V50444

In Date: 06/28/2012
Close Date: 07/06/2012

Meter Reading: 40,917.00

Problem?

drivers window crank will not move the window Q15

Task performed:

1. TRAVEL TO 15 CHECKED WINDOW REGULATOR 10-7 PARTS ON ORDER.
2. ORDERED CLEARANCE LIGHT FOR CAB ALSO.
3. TRAVEL TO 15 REPLACED WINDOW REGULATOR

Parts

Quantity

70-01-016WINDOW REG LEFT HAND SPEC OPS QUINTS

1

Workorder: V50562

In Date: 07/02/2012
Close Date: 07/06/2012

Meter Reading: 40,917.00

Problem?

driver window froze half way open. it will not shut q 15

Task performed:

SEE R/O V50444 REPAIR COMPLETE.

Parts

Quantity

NO PARTS USED

Workorder: V50592

In Date: 07/04/2012
Close Date: 07/06/2012

Meter Reading: 41,199.00

Problem?

light on control panel on turn table out. Q15

Task performed:

REPAIRED LIGHT ON CONTROL PANEL.

Parts

Quantity

NO PARTS USED

Workorder: V50748

In Date: 07/10/2012
Close Date: 07/12/2012

Meter Reading: 41,199.00

Problem?

left front headlight burned out Q15

Task performed:

TRAVEL TO 15 R&R HEADLIGHT.

Parts

Quantity

H4656USE CV TYPE HEAD LIGHT

1



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V50786

In Date: 07/13/2012
Close Date: 07/18/2012

Meter Reading: 41,199.00

Problem?

check to see if 25 hour check sheet and monthly inspection sheet have been placed neat aerial hour meter/controls. Also see if 20 ft pike pole has been installed. Report back to Lehan

Task performed:

Parts

Quantity

1. INSTALLED INSPECTION SHEET IN CENTRAL BOX BY HOUR METER.
2. COULD FIND NO WHERE TO MOUNT 20' FOOT PIKE POLE.

NO PARTS USED

Workorder: V50834

In Date: 07/13/2012
Close Date: 07/18/2012

Meter Reading: 41,199.00

Problem?

Right rear outside dual tire has bulge on sidewall. Needs to be checked out for safety reasons..... Q15

Task performed:

Parts

Quantity

1. TRAVEL TO 15 CHECKED TIRES ALL OK.
2. WHILE ON SCENE DRIVER COMPLAINED OF COOLANT LEAK FOUND LOOSE CLAMP ON HOSE. SECURED CLAMP ADDED COOLENT.

NO PARTS USED

Workorder: V50944

In Date: 07/18/2012
Close Date: 07/19/2012

Meter Reading: 41,383.00

Problem?

Q15 electrical problem

Task performed:

Parts

Quantity

TRAVEL TO STA 15 - VEHICLE OPERATING NORMAL. READ TEST EMERGENCY LIGHTS CAME ON, COULD NOT TURN ON HEADLIGHTS. CHECKED NODES. NO REPLY NODE 4 CHECK CONNECTIONS. NODE 4 STARTED WORKING. ROAD TEST VEHICLE AGAIN. COULD NOT GET IT TO FAIL. BUTTONS ON BOTTOM OF VISTA SCREEN NEED TO BE REPLACED. EMERGENCY MASTER BUTTON OFF ALIGNMENT. TRAVEL HOME. DID NOT HAVE CORRECT NODE SHEETS FOR H3023.

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V51003

In Date: 07/20/2012

Meter Reading: 41,383.00

Close Date: 07/24/2012

Problem?

warning lights do not turn off sometimes. the switch may be worn out on the computer. Q15

Task performed:

TRAVEL TO 15 FOUND BUTTONS ON ???? SCREEN
WORN OUT CAME TO SHOP FOR PARTS RETURNED
TO 15 INSTALLED ALL NEW BUTTONS.

Parts

Quantity

0K00-1957-00KEY PAD 4 POSITION

2

0K00-1958-00KEY PAD 7 POSITION

1

Workorder: V50847

In Date: 07/13/2012

Meter Reading: 41,199.00

Close Date: 07/25/2012

Problem?

water leak in the motor Rob already repaired. Q15

Task performed:

TRAVEL TO 15 REPAIRED COOLANT LEAK.

Parts

Quantity

NO PARTS USED

Workorder: V51178

In Date: 07/28/2012

Meter Reading: 41,459.00

Close Date: 07/30/2012

Problem?

pump command change to metric Q 15

Task performed:

WENT TO SHOP FOR PARTS - WENT TO 14 FOUND
PUMP PANEL CONTROL SCREEN IN METRIC -
CHANGED TO ENGLISH - RAN PUMP CHECK OK
RETURN HOME.

Parts

Quantity

NO PARTS USED

Workorder: V51424

In Date: 08/07/2012

Meter Reading: 41,681.00

Close Date: 08/07/2012

Problem?

INSTALL 16 FT PIKE POLE Q 15

Task performed:

INSTALL 16' PIPE POLE AND LABLES.

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V51806

In Date: 08/22/2012

Meter Reading: 61,774.00

Close Date: 09/13/2012

Problem?

repair rear end total truck

Task performed:

Parts

Quantity

REPAIR REAR END TOTAL TRUCK

NO PARTS USED

Vendor?: TOTAL TRUCK PARTS

Workorder: V48302

In Date: 03/30/2012

Meter Reading: 39,180.00

Close Date: 09/17/2012

Problem?

REPLACE HEADLIGHT BEZEL Q 15

Task performed:

Parts

Quantity

CHKD BEZEL FOUND NO PROB.

470S-1280-ASTROBE

1

850008-003BEZEL MTG LONG

20

Workorder: V51495

In Date: 08/09/2012

Meter Reading:

Close Date: 09/17/2012

Problem?

the to warning lights on the side of the cab. Q15

Task performed:

Parts

Quantity

TRVL TO 15 CHK WARNING LIGHTS FOUND BROKEN WIRE TO FT BUMPER LIGHTS REPAIRED OK.

NO PARTS USED

Workorder: V52168

In Date: 09/05/2012

Meter Reading:

Close Date: 09/24/2012

Problem?

Foam showing off line on pump panel with no foam level

Task performed:

Parts

Quantity

TRVL TO 15 ADJUSTED PROGRAM FOR FOAM LEVEL GAUGE.

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V48580

In Date: 04/11/2012

Meter Reading:

Close Date: 09/27/2012

Problem?

q-15 was at quint class and instructor said the motor for the nozzle was moving to slow and smelled. Q15

Task performed:

PARTS ONLY NO LABOR.

Parts

Quantity

35780011AKRON MOTOR GEAR AND CONN NOZZLE

2

Workorder: V50507

In Date: 06/30/2012

Meter Reading:

Close Date: 09/27/2012

Problem?

Red Genesis hydraulic hose is chaffed. Q 15

Task performed:

TRVEL TO 15 I HAVE WRONG HOSES WILL RETURN.

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V51731

In Date: 08/20/2012

Meter Reading: 61,774.00

Close Date: 09/27/2012

Problem?

C INSPECTION Q 15

Task performed:

1. C INSP
2. C INSP
3. C INSP
4. C INSP
5. C INSP
6. FOUND METAL IN OIL IN REAR END SO I REMOVED BOTH AXLE SHAFTS PUT SEFAC ON TRUCK AND LIFT TRUCK SET UP JACK FOR DIFF AND REMOVE IT LOAD IN TRUCK OF TRUCK TO GO TO T PARTS WHEN CLEAN UP HOUSING.
7. INSTALLED NEW DIFF, PUT AXLES BACK IN AND ROAD TEST AND TOP GEAR OIL IN DIFF.
8. CHK IN GEN, FOUND OVER FALL SO DRAINED OIL AND TOOK SAMPLE CHARGE FILTER AND PUT 3 QUARTZ OF OIL BACK IN MOTOR.
9. WENT TO ST 5 TO DO REPAIR ON C-INSPECTION (LFT SIDE #2 COMPT SHOCK ACHER BAD 4 MARKER LIGHT OUT, AIR DRYER OUT OF DATE, EMERG PUMP LIGHT, WATER WAY RELIEF VALVE.
10. ASSIST W/ Q/5.

Parts

Quantity

05-17223-000CAP RADIATOR 10 LB	1
15W40BSYN OIL BULK QTS	38
2436A432436A43 MUD FLAP 24X36	1
35200-RLIGHT MARKER LED RED	2
35200-YLIGHT MARKER LEDAMBER	2
381 838 02 19DASH VENT	1
5-2815-281X U-OINT	1
5008414CARTRIDGE DC100	1
51064OIL FILTER ONAN	1
529008000529-0080-10-0 1 1/4 ANODE KIT	1
6256RJN6256RJN NUT-OUTER/RIGHT	1
75W90GEAR OIL SYN QT	26
H1422TSX STUD	1
P1147GFUEL FILTER 33120 WIX DELCO TP916	1
PH7405 51971 OIL FILTER WIX	2
PL-11005 WATERWAY RELIEF VALVE	1
PS683033442 FUEL FILTER	1
SS-25SC5025 SUCTION SCREEN	1
TRANSYNDALLISON TRANS FLUID GAL	2
4626BPMR7A SPARK PLUG	1

Workorder: V52677

In Date: 09/27/2012

Meter Reading: 42,216.00

Close Date: 10/04/2012

Problem?

right rear brake light 10/7. q15

Task performed:

CHECKED BRAKE LIGHTS ALL OK.

Parts

Quantity

60R00XRRBRAKE/TAILLIGHT LED	1
-----------------------------	---



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V53081

In Date: 10/15/2012

Meter Reading: 42,471.00

Close Date: 10/16/2012

Problem?

on call wont start q 15

Task performed:

WENT TO SHOP FOR PARTS - WENT TO ST 15 - FOUND STARTER BAD - PULLED QUINT OUT OF STATION - R&R STARTER - CHECK OK - RETURN HOME.

Parts

19939826356 QUINT 42MT STARTER

Quantity

1

Workorder: V53156

In Date: 10/17/2012

Meter Reading: 42,516.00

Close Date: 10/24/2012

Problem?

tic is not charging in the charger. headlights not bright when driving at night Q15

Task performed:

1. TRAVEL TO 15 CHECK OUT TIC NO POWER BASE LADDER TILT CAB CHASE WIRE TO BACK COMPT. CHECK CONNECTION REWIRE AND FORE TIC.
2. CHECK HEAD LIGHT AND VOLTAGE IS OK ON BOTH LIGHTS OK.

Parts

NO PARTS USED

Quantity

Workorder: V53185

In Date: 10/18/2012

Meter Reading: 42,516.00

Close Date: 10/24/2012

Problem?

amber light activated stating "Ladder Raised" when in drive mode. Ladder is bedded properly. q15

Task performed:

TRAVEL TO ST 15 CHECK OUT LADDER UP LIGHTS CHECK SWITCHES CALL FERRARA FOR WIRING HELP CHECK WIRING CONNECTION ETC. CAN'T FIND WATER IN PLUGS WILL SENT TO SHOP.

Parts

NO PARTS USED

Quantity

Workorder: V52931

In Date: 10/09/2012

Meter Reading: 42,381.00

Close Date: 10/29/2012

Problem?

tail light works sum times on the right side. tic is not charging in the charger. Q 15

Task performed:

REPAIRED ON ANOTHER WORK ORDER.

Parts

NO PARTS USED

Quantity



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V53397

In Date: 10/30/2012

Meter Reading: 42,711.00

Close Date: 10/31/2012

Problem?

right brake tail light is out, medical door compartment top broket broke from the hydraulic piston bar Q15

Task performed:

1. TRAVEL TO 15 REPLACED RR TAIL LIGHT.
2. ORDERED PARTS FOR DOOR 6.

Parts

60R00XRRBRAKE/TAILLIGHT LED

Quantity

1

Workorder: V52796

In Date: 10/02/2012

Meter Reading: 42,306.00

Close Date: 11/01/2012

Problem?

door piston off at the door Q15

Task performed:

TRAVEL TO 15 SECURED PISTON TO DOOR AND REDRILLED BRACKET.

Parts

101305001BRACKET LEFT DH0008-5

101305002DH0007-5 BRACKET RIGHT

Quantity

1

1

Workorder: V53369

In Date: 10/29/2012

Meter Reading:

Close Date: 11/08/2012

Problem?

r-2 door for medical equip. door bracket is broken R15

Task performed:

TRAVEL TO 15 REPLACED BRACKET FOR HOLD.

Parts

101305001BRACKET LEFT DH0008-5

101305002DH0007-5 BRACKET RIGHT

Quantity

1

1

Workorder: V53731

In Date: 11/13/2012

Meter Reading:

Close Date: 11/20/2012

Problem?

left out rigger rear warning light is not working Q 15

Task performed:

TRAVEL TO ST 15 CHECK OUT LIGHT TEST CHECK, FOUND BAD LIGHT R/R LIGHT AND REWIRE.

Parts

50R03ZCRLIGHT LED RED TIR 6

Quantity

1



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V53810

In Date: 11/16/2012

Meter Reading: 42,985.00

Close Date: 11/20/2012

Problem?

REPAIR FLAT Q 15

Task performed:

REPAIR FLAT Q 15

Parts

NO PARTS USED

Quantity

Vendor?: ELPEX

Workorder: V53709

In Date: 11/12/2012

Meter Reading:

Close Date: 12/04/2012

Problem?

Clearance light out in front, officers seat leaks air at the valve

Task performed:

TRAVEL TO ST 15 R&R CLEARANCE LIGHT. CHECK OUT AIR LEAK ON SEAT FOUND SWITCH LEAKING R&R SEAT SWITCH REPLACE LINES.

Parts

47263CAN USE 47253 LED MAKER LIGHT YELLOW

BOS6222136002622207-001 W AIR SEAT

1

1

Quantity

Workorder: V52697

In Date: 09/28/2012

Meter Reading: 42,216.00

Close Date: 12/12/2012

Problem?

repair auto lube

Task performed:

DRAIN AUTO LUBE AND FOUND NO WATER SO I REFILLED AUTO LUBE.

Parts

046-0220-00-0GASKET FRONT COVER

046-5170-00-0DIAPHRAGM

077-1871-20-0RETAINING RING

250-9100-00-0BEARING SLEEVE

2962080000296-2080-00-0 SEAL

3

1

1

1

1

Quantity

Workorder: V54040

In Date: 11/28/2012

Meter Reading:

Close Date: 12/12/2012

Problem?

The load gauge on the platform is not working. It shows as if the aerial is at its max load, even when it is bedded. Q15

Task performed:

REPAIRED ON WO#53412.

Parts

NO PARTS USED

Quantity



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V53412

In Date: 10/30/2012

Meter Reading: 42,711.00

Close Date: 12/13/2012

Problem?

Check items on UL test

Task performed:

1. CALL TOM SMEAL TO HELP TROUBLESHOOT AND HE SAID TO CHECK SOLENOID VALVE OPERATION AND I FOUND SOLENOID WORKING SO TOM SAID TO CHECK RELIEF VALVE BY PLUG VALVE HOSE SO I PLUG VALVE HOSE OF THE PRESSURE CAME UP AT IDLE SO I NEED TO REPLACE VALVE SO I GOT PART # FROM TOM ORDER PART AND ORDER PARTS. GOT PARTS FROM SMEAL INSTALLED THEM AND LADDER WORKS GOOD.
2. FOUND PUMP SHIFT LEAKING AIR REMOVE COVER PUMP SHIFT AND FOUND O-RINGS BAD R&R O-RINGS AND SHAFT SEAL AND STOP PAD LEAK.
3. FOUND COOLANT LEAK AT BOTTOM RODATOR HOSE TIGHTEN 2 CLAMPS AND STOP LEAK.
4. REMOVE AND CLEAN BALL BEARING IN MONITOR, INSTALLED AND LUBED BALL BEARING TO MAKE MONITOR MOVE SIDE TO SIDE BETTER.
5. SET LADDER UP FOR UL CHECK REAR WARNING LIGHT ON LEFT JACK FOUND LIGHT WORKING, CHECK AERIAL 3RD SECTION THE PUTTY AROUND THE WIRING ENTERING THE LEFT MAIN RAIL BEND REPAIR WITH SILICONE.
6. CALIBRATED LOAD MINDER.
7. CLEAN AND HUB WATERWAY AND LADDER.
8. TALK TO TOM SMEAL ABOUT JOYSTICK FOR MONITOR HE SAID CHECK ARKON BRASS WEB PAGE SO WE WENT ON WEB PAGE AND PRINTED JOY STICK OPERATION ND MODE FOR LABELS FOR OPERATOR.

Parts

Quantity

037-1341-50-0VPS SHIFT KIT 2 PIECE	1
HY-1009212V COIL	1
HY-10164SOLND VALVE	1
HY-10607RELIEF VLV	1

Workorder: V54455

In Date: 12/16/2012

Meter Reading:

Close Date: 12/17/2012

Problem?

Q15 would not start, checked battery connections and then it started. After hours mechanic checked batteries and tightened terminals, load tested and checked charging system.

Task performed:

NO START, CHECK ALL BATTERY AND CABLES, BATTERY CHARGE LOAD TEST ALL BATTERY, TIGHTEN ALL BATTERY END CHECK CHARGING SYSTEM; WORK AT THIS TIME.

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V54569

In Date: 12/22/2012
Close Date: 12/28/2012

Meter Reading: 43,475.00

Problem?

LR Brake light is out. Q15

Task performed:

TRAVEL TO 15 LIGHTS FINE.

Parts

NO PARTS USED

Quantity

Workorder: V54805

In Date: 01/04/2013
Close Date: 01/04/2013

Meter Reading: 43,623.00

Problem?

check tires

Task performed:

TRAVEL TO ST 15 CHECKED REAR TIRES.

Parts

NO PARTS USED

Quantity

Workorder: V55114

In Date: 01/17/2013
Close Date: 01/23/2013

Meter Reading: 43,756.00

Problem?

low voltage alarm

Task performed:

DIAGNOSE ELECTRICAL PROBLEM REPLACED BATTERIES.

Parts

BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER BATTERY
HP-31D BATTERY 950CCA HP-31D

Quantity

6
6

Workorder: V55122

In Date: 01/17/2013
Close Date: 01/23/2013

Meter Reading: 43,756.00

Problem?

low voltage alarm

Task performed:

CHANGED ALTERNATOR AND INSTALLED NEW CAB TILT SOLINOID.

Parts

2000071102000072100 SOLENOID HALE PRIMER
4962PAUSE 4949PA UPGRADE ALT. 320A LEECE

Quantity

1
1



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V55296

In Date: 01/25/2013
Close Date: 01/28/2013

Meter Reading: 44,127.00

Problem?

stop engine light on

Task performed:

- TRAVEL TO ST 15 CHECK OUT TRUCK CODER FOUND COOLANT LOW FILL COOLANT TEST OK. FOUND BRAKE HOSE WITH CUT IN IT WILL COM BACK.
- TRAVEL TO ST 15 AGAIN AFTER GOING TO SHOP FOR BRAKE HOSE RAISE LADDER TILT CAB R&R BRAKE HOSE MAKE UP NEW HOSE AND INSTALL TEST OK. NO LEAKS RETURN TO SHOP.

Parts

Quantity

NO PARTS USED

Workorder: V54553

In Date: 12/21/2012
Close Date: 01/29/2013

Meter Reading:

Problem?

unable to get the cab up.

Task performed:

REPLACED LOOSE CONNECTOR IN PLUG IN.

Parts

Quantity

NO PARTS USED

Workorder: V54824

In Date: 01/04/2013
Close Date: 02/12/2013

Meter Reading: 43,623.00

Problem?

master discharge gauge is not accurate. reads about 50 psi low. Can open unused Discharge and use that instead. q15

Task performed:

CHECKED PUMP PRESSURES OK.

Parts

Quantity

NO PARTS USED

Workorder: V54903

In Date: 01/07/2013
Close Date: 02/12/2013

Meter Reading: 43,684.00

Problem?

Master Discharge gauge is not working properly on the Pump Master Computer. Digital gauge reads 50-100psi lower than real pressure. Q15

Task performed:

- TRAVEL TO 15 CHECKED SYSTEM AND SWITCH.
- REPLACED DISCHARGE SENDING UNIT ON PUM

Parts

Quantity

100581TRANSDUCER COMMAND MASTER 300 PSI

1

102161TRANSDUCER 500 PSI

1



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V55274

In Date: 01/24/2013

Meter Reading: 44,127.00

Close Date: 02/12/2013

Problem?

coolant leak q 15

Task performed:

COOLANT LEAK - REPAIRED HOSE - AND TESTED.

Parts

ALA00350-50 EXTENDED LIFE COOLANT GAL

Quantity

12

Workorder: V55352

In Date: 01/28/2013

Meter Reading: 44,189.00

Close Date: 02/12/2013

Problem?

Red cab lights are not working in the back cab of the Quint

Task performed:

REPLACED DOME LIGHTS IN REAR OF CAB.

Parts

2507385C1CAB AIR LEVEL VALVE INT

37000003722-44816-001 DOME LIGHT RECT

Quantity

1

2

Workorder: V55751

In Date: 02/13/2013

Meter Reading: 2,657.00

Close Date: 02/20/2013

Problem?

Replace L/R tires

Task performed:

REPLACE L/R TIRES.

Parts

138655715 12R241200R24 TIRE

Quantity

2

Vendor?: ELPEX

Workorder: V56269

In Date: 03/08/2013

Meter Reading: 45,056.00

Close Date: 03/12/2013

Problem?

Need a 2.5" (male) intake cap and safety chain. Noticed it was missing while back flushing the pump this morning.

Task performed:

TRAVEL TO 15 REPLACED PLUG AND SAFETY CHAIN ON INTAKE.

Parts

108-12FBEADED CHAIN W/CONN 12

Quantity

1



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V56188

In Date: 03/06/2013

Meter Reading: 44,856.00

Close Date: 03/21/2013

Problem?

Mount surfboard Q-15

Task performed:

TRAVEL TO ST 15 MOUNTED RESCUE BOARD ON TOP OF Q15 E VELCRO STRAPS.

Parts

UMVS254411STRAP 46 IN

Quantity

6

Workorder: V56614

In Date: 03/25/2013

Meter Reading: 45,331.00

Close Date: 03/25/2013

Problem?

on call coolant leak q 15

Task performed:

TRAVEL TO Q15 BROKE DOWN ON ROAD FOUND BLOWN RADIATOR HOSE TRAVEL TO SHOP FOR PARTS RETURN TO Q15 REPLACED HOSE AND ANTIFREEZE.

Parts

ALA00350-50 EXTENDED LIFE COOLANT GAL

ANTICOOLANT ANTIFREEZE GAL

Quantity

6

2

Workorder: V56723

In Date: 03/29/2013

Meter Reading: 45,545.00

Close Date: 04/05/2013

Problem?

need a new federal Q button on the officer side floor. Fed Q got stuck wide open and would not turn off, had to pull the button out hand to shut it off.Q-15

Task performed:

TRAVEL TO 15 REPLACED SIREN SWITCH ON OFFICERS SIDE.

Parts

7605-666764-0023 SWITCH FOOT SIREN

Quantity

1

Workorder: V54660

In Date: 12/27/2012

Meter Reading:

Close Date: 04/08/2013

Problem?

GENERATOR WONT START

Task performed:

Parts

NO PARTS USED

Quantity



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V57264

In Date: 04/25/2013

Meter Reading: 46,140.00

Close Date: 04/26/2013

Problem?

Turntable sensor is damaged and needs to be adjusted or replaced Q15 has to be over ridden to bed ladder. Q15 still in service but needs to have the sensor replaced or repaired.

Task performed:

Parts

Quantity

TRAVEL TO 15 PROXIMITY SWITCH BRACKET, BENT, REMOVED BRACKET AND REPAIRED REINSTALLED AND ADJUSTED.

NO PARTS USED

Workorder: V57251

In Date: 04/24/2013

Meter Reading:

Close Date: 04/30/2013

Problem?

left rear side marker light 10-7 Q-15

Task performed:

Parts

Quantity

CHECKED LIGHTS FOUND NO PROBLEM.

NO PARTS USED

Workorder: V57314

In Date: 04/28/2013

Meter Reading:

Close Date: 04/30/2013

Problem?

the 2 metal plates that the ladder rests on the screws are coming loose and or stripped and the plate is coming loose.

Task performed:

Parts

Quantity

TRAVEL TO 15 REPAIRED LOOSE SCREWS ON UPPER PLATE.

NO PARTS USED

Workorder: V57315

In Date: 04/28/2013

Meter Reading:

Close Date: 05/08/2013

Problem?

sensor for the ladder in the Bed Zone (Blue Light) was found knocked loose and was not lined up correctly. We were able to adjust it, but a mechanic should take a look at it to make sure it is adjusted properly.

Task performed:

Parts

Quantity

1. ORDERED NEW SENSOR FOR LADDER.
2. REPLACED LADDER SENSOR.

EL-12041PROXIMITY SWITCH

1

FREIGHTSHIPPING CHARGES

35



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V57509

In Date: 05/06/2013

Meter Reading:

Close Date: 05/08/2013

Problem?

air horn activates when the battery is turned on Q15

Task performed:

1. TRAVEL TO 15 REPLACED AIR HORN SWITCH AND SOLENOID PROBLEM STILL EXIST MUST HAVE PROBLEM WITH MULTI PLEX SYSTEM WILL GET COMPLETE TO CHECK.
2. TRAVEL TO 15 REPROGRAMMED NODE PROBLEM STILL THERE. STARTED TRAVELING, WIRES FOUND PLUG SHORTED AND WET. REWIRED PLUG AND SEALED OK.

Parts

Quantity

600000003NODE HERCULES V-MUX

1

Workorder: V57611

In Date: 05/09/2013

Meter Reading: 46,382.00

Close Date: 05/20/2013

Problem?

Replace steer tires Q15

Task performed:

REPLACE STEER TIRES Q15.

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD TIRES

Workorder: V57718

In Date: 05/14/2013

Meter Reading:

Close Date: 05/20/2013

Problem?

CHOKE ON GENESIS POWER UNIT ON Q15 STICKING RUNS ON HALF CHOKE.#10186759

Task performed:

TRAVEL TO 15 CLEANED CARB ON GENESIS UNIT AND RAN OK.

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V57607

In Date: 05/09/2013
Close Date: 06/05/2013

Meter Reading: 46,382.00

Problem?

auto eject outlet on q15, one of the prongs is to short. the end is broken off.

Task performed:

TRAVEL TO 15 REMOVED INNER FENDER AND REPLACED KUSSMAUL AUTO EJECT REINSTALLED AND TESTED OK.

Parts

Quantity

091-20WP-120AUTO EJECT	1
091-3YWCOVER KUSSMAUL AUTO EJECT	1
0915520120AUTO EJECT 20 AERO OTL3925	1

Workorder: V58101

In Date: 05/31/2013
Close Date: 06/05/2013

Meter Reading: 46,724.00

Problem?

female shoreline plug on Q15 is in need of repair or replaced.

Task performed:

CHECKED PLUG OK. REPLACED.

Parts

Quantity

NO PARTS USED

Workorder: V58264

In Date: 06/08/2013
Close Date: 06/12/2013

Meter Reading: 4,685.00

Problem?

the shoreline connection is faulty. Most hold in certain spot for truck to charge. Q15

Task performed:

TRAVEL TO 15 REPLACED PLUG IN STATION FOR QUINT'S AUTO EJECT.

Parts

Quantity

NO PARTS USED

Workorder: V58375

In Date: 06/12/2013
Close Date: 06/25/2013

Meter Reading: 4,685.00

Problem?

We had a fire today and when I ingaged the pump it would not hold pressure. I restarted Q15, which fixed the problem. Back at 15 had a different issue I've had before where PSI button would not work & had to restart.

Task performed:

RAN PUMP SEVERAL TIMES NO PROBLEM FOUND.

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V58647

In Date: 06/24/2013
Close Date: 06/25/2013

Meter Reading: 47,122.00

Problem?

night light on aerial ladder control panel not working.

Task performed:

REPAIRED PANAL LIGHTS.

Parts

1141BULB

Quantity

10

Workorder: V58358

In Date: 06/12/2013
Close Date: 06/26/2013

Meter Reading: 46,998.00

Problem?

nozzle/master stream on Q15 will not rotate left or right. Q15

Task performed:

- TRAVEL TO ST 15 DROP OFF 3" HOSE CHECK OUT ROTATION MOTOR R&R MOTOR LUBE UNIT TEST.
- CHECKED NOZZLE WORKS FINE.

Parts

35780011AKRON MOTOR GEAR AND CONN NOZZLE

Quantity

1

Workorder: V58645

In Date: 06/24/2013
Close Date: 07/02/2013

Meter Reading: 47,122.00

Problem?

Q15 cab lift motor is burned up won't lift cab. I can still hear the motor running even though the battery is off. lift motor is hot to tou and sounds like it's still running.

Task performed:

REPLACED CAB LIFT PUMP AND TESTED.

Parts

827008-004CAB LIFT MOTOR SO

Quantity

1

Workorder: V58872

In Date: 07/05/2013
Close Date: 07/08/2013

Meter Reading: 47,474.00

Problem?

charging at 12.4 not at normal 13.5 Q15

Task performed:

TRAVEL TO 15 CHECKED CHARGING SYSTEM. NO PROBLEMS FOUND.

Parts

NO PARTS USED

Quantity



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V58826

In Date: 07/02/2013
Close Date: 07/23/2013

Meter Reading: 47,474.00

Problem?

Flat tire R/R/I

Task performed:

FLAT TIRE R/R/I

Parts

NO PARTS USED

Quantity

Vendor?: ELPEX

Workorder: V59302

In Date: 07/23/2013
Close Date: 07/30/2013

Meter Reading: 47,847.00

Problem?

Replace R/R/O tire [install used mounted tire here] and install new one on rim for spare

Task performed:

REPLACE R/R/O TIRE [INSTALL USED MOUNTED TIRE HERE] AND INSTALL NEW ONE ON RIM FOR SPARE.

Parts

NO PARTS USED

Quantity

Vendor?: BOULEVARD TIRE CENTE

Workorder: V58646

In Date: 06/24/2013
Close Date: 07/31/2013

Meter Reading: 47,122.00

Problem?

rear scene lights not working.

Task performed:

CHECKED SCENE LIGHTS ON REAR OK.

Parts

NO PARTS USED

Quantity

Workorder: V58666

In Date: 06/25/2013
Close Date: 07/31/2013

Meter Reading: 47,288.00

Problem?

back seat driver side flashlight charger is broken. The holder clip wont hold the flashlight in place correctly to charge the flashlight

Task performed:

REPLACED BOX LIGHT BASE.

Parts

NO PARTS USED

Quantity



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V59949

In Date: 08/21/2013
Close Date: 08/22/2013

Meter Reading: 48,471.00

Problem?

shoreline power plug does not appear to be working. Indicator lights do not come on when it is plugged in. Q15

Task performed:

Parts

Quantity

TRAVEL TO 15 RESET BREAKER IN STATION FOR CHARGER OK.

NO PARTS USED

Workorder: V60141

In Date: 08/28/2013
Close Date: 08/30/2013

Meter Reading: 48,542.00

Problem?

Repair auto eject

Task performed:

Parts

Quantity

TRAVEL TO 15 REPAIRED 110 VOLT CABLE.

NO PARTS USED

Workorder: V57404

In Date: 05/01/2013
Close Date: 09/05/2013

Meter Reading: 48,648.00

Problem?

front tires showing steel belts, need new tires. Expecting bad weather today and would be nice to have them replaced. Thanks

Task performed:

Parts

Quantity

REPAIRED ON W.O. #57611.

NO PARTS USED

Workorder: V59284

In Date: 07/23/2013
Close Date: 09/10/2013

Meter Reading: 48,648.00

Problem?

rt. rear outside tire close to the wear bars

Task performed:

Parts

Quantity

REPAIRED ON W.O. #V59302

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V60683

In Date: 09/23/2013

Meter Reading: 48,973.00

Close Date: 09/27/2013

Problem?

driverside outside head lamp is out.

Task performed:

travel to st 15 check out headlight out r&r bulb.

Parts

H4656USE CV TYPE HEAD LIGHT

Quantity

1

Workorder: V61050

In Date: 10/07/2013

Meter Reading: 49,136.00

Close Date: 10/09/2013

Problem?

no start

Task performed:

1. TRACED OUT PROBLEM WITH NO START FOUND
NO PROBLEM AT THIS TIME.

Parts

NO PARTS USED

Quantity

Workorder: V61059

In Date: 10/07/2013

Meter Reading: 49,136.00

Close Date: 10/10/2013

Problem?

R/R/I flat

Task performed:

R/R/I FLAT

Parts

NO PARTS USED

Quantity

Vendor?: ELPEX

Workorder: V61010

In Date: 10/04/2013

Meter Reading: 49,136.00

Close Date: 10/21/2013

Problem?

hydraulic system gauges on tower and base inop also base lights out

Task performed:

1. check out guages on ladder stuck don't order guages.
check out light broken will get also.
2. travel to st 15 r&r upper and lower hyd. pressure
guages had to cut panels to fit new style guage and
replump.

Parts

9152331491523314 GAUGE 0-5000 PSI

Quantity

2



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V61097

In Date: 10/08/2013
Close Date: 10/21/2013

Meter Reading: 49,211.00

Problem?

We need out cigarette lighter Hot wired to charge the trip tix. Can we also have the radio hot wired so we can switch it on without turning on the battery? Thanks

Task performed:

Parts

Quantity

1. TRAVEL TO ST 15 NOT THERE AT ST 29 GOT TO ST 29.
2. PULL WASH AND FIND WIRING TO 12 V PLUG TAP INTO BATT POWER UNDER DASH AND REWIRE PLUG.

NO PARTS USED

Workorder: V61127

In Date: 10/09/2013
Close Date: 10/21/2013

Meter Reading: 49,271.00

Problem?

start button on console intermittent

Task performed:

Parts

Quantity

check starting system inop. check truck for loose wires etc. test starter and button. state 308 ampi ok under load hot batts ok 110v charge and alt ok unfounded.

NO PARTS USED

Workorder: V61373

In Date: 10/19/2013
Close Date: 10/22/2013

Meter Reading: 49,478.00

Problem?

rear passenger side hub cap is missing a lug to hold the hub cap on. Q15

Task performed:

Parts

Quantity

CALLED ST 15 HAD DRIVER REMOVE HUB CAP.

NO PARTS USED

Workorder: V61631

In Date: 10/29/2013
Close Date: 11/07/2013

Meter Reading: 49,618.00

Problem?

replace left side rear tires

Task performed:

Parts

Quantity

REPLACE LEFT SIDE REAR TIRES.

NO PARTS USED

Vendor?: ELPEX



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V61806

In Date: 11/05/2013

Meter Reading: 49,855.00

Close Date: 11/07/2013

Problem?

Wheel studs or lug nuts stripped l/f

Task performed:

Parts

Quantity

1. TRAVEL TO ST-15 TO CHECK LUGS TIRE GUY HAVING PROBLEMS GETTING LOOSE ON STRIP OUT CHECK OUT LUGS STUCK ON SET UP TRUCK TO GO TO SHOP IN AM.

NO PARTS USED

Workorder: V61523

In Date: 10/25/2013

Meter Reading:

Close Date: 11/14/2013

Problem?

air leak in passenger side rear outside tire. Pressure was 50psi. Putting air in it now. Need someone to look at it and fix please Q 15

Task performed:

Parts

Quantity

1. TRAVEL TO ST-18 CHECK OUT TIRE CHECK VALVE STEM SYST AND TIRE LOOKS NEW FOUND NO PROBLEM MISSING HUB CAP NUT WILL GET NEW ONE.

NO PARTS USED

2. TRAVEL TO ST-15 REPLACE MISSING LUG ON REAR WHEEL COVER.

3. TRAVEL TO ST-15 CHECK FRONT TIRE WAIT FOR TRUCK ORDER NEW TIRE.

Workorder: V61827

In Date: 11/06/2013

Meter Reading: 49,855.00

Close Date: 11/25/2013

Problem?

Can't remove L/F tire

Task performed:

Parts

Quantity

REMOVE FROZEN LUG NUTS FROM LEFT FRONT WHEEL AND GET TIRE OUT OF BLDG #3 TO BE INSTALLED.

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V61944

In Date: 11/12/2013
Close Date: 11/25/2013

Meter Reading: 50,147.00

Problem?
REPLACE TIRE

Task performed:

REPLACE TIRES

Parts

NO PARTS USED

Quantity

Vendor?: ELPEX

Workorder: V62121

In Date: 11/19/2013
Close Date: 11/25/2013

Meter Reading:

Problem?
OIC side LoadMinder Strobe on the ladder is out

Task performed:

INSTALL NEW STROBE LIGHT ON LADDER MAN
LOAD, WARNING LIGHT.

Parts

470S-1280-ASTROBE

Quantity

1

Workorder: V62392

In Date: 12/02/2013
Close Date: 12/03/2013

Meter Reading: 50,713.00

Problem?
Q15 air leak

Task performed:

REPAIRED OIL LEAK AT FILTER.
AIR LEAK FOUND WATERWAY SOLENOID VALVE
LEAKING WILL ORDER NEW PART.

Parts

NO PARTS USED

Quantity

Workorder: V62405

In Date: 12/02/2013
Close Date: 12/03/2013

Meter Reading: 50,713.00

Problem?
coolant leak

Task performed:

WATER LEAK/COOLANT LEAK - FOUND HOSE FOR
ENGINE COOLER WAS BROKEN REINSTALLED
NEWHOSE AND TESTED.

Parts

NO PARTS USED

Quantity



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V62329

In Date: 11/28/2013

Meter Reading: 50,713.00

Close Date: 12/04/2013

Problem?

Q15 R4 door is damaged and needs replacement per mechanic. Q15

Task performed:

Parts

Quantity

TRAVEL TO ST 15 TRUCK AT 1264 LAKE WORTH LANE NORTH PALM GAS LEAK CHECK OUT DOOR ORDER PARTS TO FIX DOOR.

NO PARTS USED

Workorder: V62423

In Date: 12/02/2013

Meter Reading: 50,713.00

Close Date: 12/18/2013

Problem?

mount genesis tools

Task performed:

Parts

Quantity

TRAVEL TO ST-15 MOUNT GENESIS TOOLS AND EQ

NO PARTS USED

Workorder: V62899

In Date: 12/23/2013

Meter Reading: 51,281.00

Close Date: 01/02/2014

Problem?

genesis hose for Q15

Task performed:

Parts

Quantity

LD DELIVERED TO 15.

ART330SC-BEXT HOSE GENESIS UNITS WITH OSC COUPL

1

Workorder: V62982

In Date: 12/27/2013

Meter Reading:

Close Date: 01/03/2014

Problem?

Aerial nozzle will not turn to the left when flowing water. Will move left while not flowing water. Q 15

Task performed:

Parts

Quantity

1. WENT TO ST-15- TRUCK NOT THERE- CALL DISPATCH- TRUCK ONE CALL- RETURN TO SHOP.
2. TRAVEL TO ST-15 SET UP LADDER TAKE APART NOZZLE AND LUBE BEARINGS IN SWIVEL TEST STILL NOT WORKING WILL HAVE TO REBUILD WILL ORDER KIT.

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V62983

In Date: 12/27/2013

Meter Reading:

Close Date: 01/03/2014

Problem?

would like to mount straps in Compartments R2, L3, and hang 2nd Genesis hose in R5. Request mechanic for this on A-shift. Thank you Q15

Task performed:

Parts

Quantity

TRAVEL TO ST-15 TO MOUNT STRAPS, DRIVER SAID TO WAIT UNTIL P.M AND DRIVE TANK MOUNT TO SEE WHAT WILL BE NEEDED.

NO PARTS USED

Workorder: V63267

In Date: 01/09/2014

Meter Reading:

Close Date: 01/13/2014

Problem?

Ddoor alarm is going non stop with all doors closed. Cab is also leaking.

Task performed:

Parts

Quantity

TRAVEL TO 15 DRIVER COMPLAINT DOOR AJAR GOING OFF CONSTANTLY. CHECKED SYSTEM FOUND SIGNAL TO NODE ALL OF TIME REPROGRAMMED MODE NO CODE TRIED NODE NO GOOD GOT WHILE ON INPUT SIDE MODE OK.

NO PARTS USED

Workorder: V63171

In Date: 01/06/2014

Meter Reading:

Close Date: 01/17/2014

Problem?

Reprogram door locks

Task performed:

Parts

Quantity

DRIVER COMPLAINT DOOR LOCKS.

NO PARTS USED

Workorder: V63440

In Date: 01/16/2014

Meter Reading:

Close Date: 01/17/2014

Problem?

Put Q15 in waterway mode and when attempting to put it back in rescue mode the hydraulic arms would not come down

Task performed:

Parts

Quantity

DRIVER COMPLAINT WATER WAY STUCK IN TOWER MODE PULLED APART CONSOLE TO FIND RELAYS AND BRAKERS POWER AND GROUND AT SWITCH WILL SEND TO SHOP.

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V63302

In Date: 01/10/2014
Close Date: 01/21/2014

Meter Reading: 51,842.00

Problem?

Cant air tires

Task performed:

CANT AIR TIRES.

Parts

NO PARTS USED

Quantity

Vendor?: GOOD YEAR

Workorder: V63375

In Date: 01/14/2014
Close Date: 01/23/2014

Meter Reading: 51,890.00

Problem?

Still have same air leak that you can hear from the rear compartment. DC1 heard it today and direct me to write it up again. q15

Task performed:

TRAVEL TO ST 15 CHECK OUT SPARE QUINT TEST DRIVE TO PUT BACK IN SERVICE OK CHECK AIR LEAK VALVE IN LADDER BAY LEAKING GOING TO SHOP.

Parts

NO PARTS USED

Quantity

Workorder: V63718

In Date: 01/26/2014
Close Date: 01/31/2014

Meter Reading:

Problem?

request Synthetic oil for trucks.

Task performed:

PARTS ONLY NO LABOR.

Parts

15W40QSYN OIL QT

Quantity

12

Workorder: V63719

In Date: 01/26/2014
Close Date: 01/31/2014

Meter Reading:

Problem?

Check Engine & Stop Engine lights on dash. Contacted on call mechanic who repaired.

Task performed:

FOUND LOW ON COOLANT.

Parts

NO PARTS USED

Quantity



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V62544

In Date: 12/07/2013

Meter Reading:

Close Date: 02/07/2014

Problem?

OIC side Aereal tip hallogen light is out. Q15

Task performed:

TRAVEL TO ST-15 CHECK OUT TIP LIGHT OUT TEST POWER AND GROUND OK R&R BULB.

Parts

Quantity

Q500T3CLBULB HALOGEN 120V 500WATT 4 11/16 LONG

1

Workorder: V63594

In Date: 01/21/2014

Meter Reading:

Close Date: 02/10/2014

Problem?

chainsaw 2634926687 will not start and chainsaw 251185920 was sparying fuel they are being sent back to the shop with Q15

Task performed:

BILL REGAN REPAIRED.

Parts

Quantity

NO PARTS USED

Workorder: V63717

In Date: 01/26/2014

Meter Reading:

Close Date: 02/12/2014

Problem?

OIC side front wheel hub needs oil.

Task performed:

1. REPLACE BELTS, AND ROAD TESTED TRUCK.
2. REPAIRED REAR CAB DOOR WINDOW REGULATOR THAT WAS NOT WORKING.

Parts

Quantity

K080485BELT

1

Workorder: V61845

In Date: 11/06/2013

Meter Reading:

49,855.00

Close Date: 02/25/2014

Problem?

front end align

Task performed:

FRONT END ALIGN.

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD TIRE



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V63771

In Date: 01/28/2014

Meter Reading:

Close Date: 02/25/2014

Problem?

back window will not roll up Q15

Task performed:

Parts

Quantity

REPAIRED REAR WINDOW THAT WAS NOT ROLLING UP.

NO PARTS USED

Workorder: V64499

In Date: 02/24/2014

Meter Reading: 52,038.00

Close Date: 02/26/2014

Problem?

REPAIR FLAT

Task performed:

Parts

Quantity

REPAIR FLAT.

NO PARTS USED

Vendor?: ELPEX

Workorder: V61965

In Date: 11/12/2013

Meter Reading: 50,037.00

Close Date: 03/11/2014

Problem?

REPAIRS FROM UL TEST Q15

Task performed:

Parts

Quantity

- TRAVEL TO ST-15 ADJUST LOOSE OUTRIGGER SWITCHES AND TIGHTEN #4 ON LIST.
- REPLACED TORN WEATHER BOOTS ON SWITCHES #5 ON LIST REINSTALL PANEL.
- STEP LIGHT OUT AND BROKEN R&R LIGHT REWIRE AND REMOUNT LIGHT #7 ON LIST.
- STEP LOOSE TIGHTEN BOLTS ON SIDE STEP TEST OK #8 ON LIST.
- LADDER WATER WAY DRY, LUBE TUBE WITH TRANS FLUID #9 ON LIST.
- R&R WATERWAY RELIEF VALVE.
- CHECK LOAD MINDER FOUND AND WORKED IT, WAS SET TO HIGH SO ADJUSTED IT TO GO OFF OVER 500LB.
- TIGHTEN UP SCREW ON CRADLE SWITCH.
- REMOVE INLET PIPE CLEAN UP AND GOT LUIS TO WELD IT, CLEANED UP AND PAINTED THE WELDS AND INSTALLED PIPE.
- WELD PIPE WATER WAY.
- GREASE BULL GEAR ON LADDER.

50R03ZCRLIGHT LED RED TIR 6

1

60351STEPWELL LIGHT

1

8126482-2106 TOGGLE GUARD

3

FREIGHTSHIPPING CHARGES

1

PL-11005 WATERWAY RELIEF VALVE

1



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V63153

In Date: 01/06/2014

Meter Reading:

Close Date: 03/11/2014

Problem?

I was told at pass down that Q15 air leak had been repaired, but can still hear the air leak from the back of the truck. It's not fixed.

Task performed:

WENT TO ST-15 CHECK AIR LEAK ON Q15 REMOVE LADDER AND WHEN UNDER TURNTABLE AND FOUND AIR VALVE LEAKING, TOOK PICS AND GOT # OFF VALVE.

Parts

Quantity

FREIGHTSHIPPING CHARGES

1

HY-10124ARO A212SS-12D VALVE

1

Workorder: V63489

In Date: 01/17/2014

Meter Reading:

Close Date: 03/11/2014

Problem?

Hydraulic door hinge spring on compartment door L2 is broken.

Task performed:

R&R PIN FOR HYD SHOCK W.O 63782.

Parts

Quantity

NO PARTS USED

Workorder: V64432

In Date: 02/21/2014

Meter Reading: 52,038.00

Close Date: 03/11/2014

Problem?

Mount SCUBA equipment in Q15

Task performed:

MOUNT SCBA EQUIPMENT, HAD TO REMOVE DOOR ON BOTH SIDES CABINETS ON BACK WALL TIE UP WI4RES ON RIGHT SIDE CABINETS REMOVE SCBA BRACKET AND INSTALL SCBA IN JUMP SEAT BEHIND DRIVER SEAT.

Parts

Quantity

ULLH-EZOAIR BRACKETS

4

Workorder: V62393

In Date: 12/02/2013

Meter Reading:

Close Date: 03/19/2014

Problem?

spot light on the tip of the ladder right side needs bulb

Task performed:

REPAIRED ON C-INSPECTION BY KEN FLERX ON W.O #62417.

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V64874

In Date: 03/12/2014
Close Date: 03/20/2014

Meter Reading: 52,139.00

Problem?

mount straps and brackets

Task performed:

1. TRAVEL TO ST-15 MOUNT EQ AND MOVE SHELF IN TRUCK.
2. TRAVEL TO ST-15 FINISH MOUNTING AND STRAPS AND MOVING SHELF ON Q-15.

Parts

Quantity

LPVM-7LG MOUNT
SAHSVS2510STRAP
UMVS056511STRAP

2
6
3

Workorder: V64937

In Date: 03/14/2014
Close Date: 03/20/2014

Meter Reading:

Problem?

computerized throttle, is not working properly. can you remove it and install a manual throttle and relief valve

Task performed:

TRAVEL TO ST-15 CHECK GOVERNOR NOT GETTING PRESET PRESSURES, CHECK OUT SYST CHECK PRESSURE TRANS OVER ECT AIR GETTING IN PUMP FOUND FRONT INTAKE OPEN AIR PUMP.

Parts

Quantity

S1145REGULATOR MINI HVY DUTY

1

Workorder: V61786

In Date: 11/05/2013
Close Date: 03/24/2014

Meter Reading:

Problem?

left front tire wear on the inside edge

Task performed:

REPAIRED ON ANOTHER WORK ORDER BY VENDOR #61845.

Parts

Quantity

NO PARTS USED

Workorder: V63167

In Date: 01/06/2014
Close Date: 03/24/2014

Meter Reading:

Problem?

Low tire pressures.

Task performed:

REPAIRED BY BOULEVARD TIRE ON WORK ORDER #63302.

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V65134

In Date: 03/23/2014

Meter Reading:

Close Date: 03/26/2014

Problem?

THERMAL IMAGING CAMERA ZOOM FUNCTION NOT WORKING. Q15

Task performed:

TRAVEL TO ST-15 CHECK OUT TIC, CALLED WAYNE TO GET NEW TIC D/C GHAS TO GET NEW TIC.

Parts

NO PARTS USED

Quantity

Workorder: V65284

In Date: 03/28/2014

Meter Reading:

Close Date: 04/02/2014

Problem?

Drivers seat needs upholstery job foam exposed/worn out.

Task performed:

TRAVEL TO ST-15 CHECK SEAT R/P JUST CAME BACK FROM P.M WILL HAVE REPAIRED NEXT P.M.

Parts

NO PARTS USED

Quantity

Workorder: V65392

In Date: 04/02/2014

Meter Reading:

Close Date: 04/09/2014

Problem?

36' ladder is missing a ladder tip piece. q15

Task performed:

1. TRAVEL TO ST-15 R&R LADDER TIPS ON END OF 36' LADDER OLD ONES BROKEN.
2. REAR SPOT LT OUT CHECK FOR POWER AND GROUND AT LIGHT OK R&R BULB.

Parts

03910030SWITCH COMPARTMENT DOORS

4435HEADLIGHT

91823SWITCH SWT5499 MED MASTER

Quantity

2

1

1

Workorder: V65694

In Date: 04/14/2014

Meter Reading:

Close Date: 04/16/2014

Problem?

need new windshield wipers

Task performed:

REPLACE WIPER BLADES AND REPAIR SPRAYERS.

Parts

50-24WIPER BLADE - KME

Quantity

2



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V65566

In Date: 04/08/2014

Meter Reading:

Close Date: 04/17/2014

Problem?

Q15 D-Light adapter frayed, need a new pig tail. Will send DC1 and e mail with picture.

Task performed:

Parts

Quantity

REPAIR D.LIGHT ADAOTER BOARD.

NO PARTS USED

Workorder: V65693

In Date: 04/14/2014

Meter Reading:

Close Date: 04/17/2014

Problem?

Pressure governer has been malfunctioning. Buttons periodically will not work. Keep having to shut truck down and restart to fix. Need a mechanic to take a look.

Task performed:

Parts

Quantity

CHARGED PRESSURE GOV.

NO PARTS USED

Workorder: V65690

In Date: 04/14/2014

Meter Reading:

Close Date: 04/18/2014

Problem?

request to have water rescue life guard bouys mounted with velcro straps. Will need probably 4 velcro straps and 8 footmans loop

Task performed:

Parts

Quantity

INSTALL VELCRO STRAPS OM REAR OF BUNKER FOR BOUYS.

14-7014HGR-1 HELMET HOOK

6

SAHSVS2510STRAP

4

Workorder: V65788

In Date: 04/17/2014

Meter Reading:

Close Date: 04/24/2014

Problem?

Sensor in hurst tool door on Q15 keeps buzzing

Task performed:

Parts

Quantity

TRAVEL TO 15 DRIVER COMPLAINT DOOR AJAR BUZZER FOUND MAGNET FOR ROLL UP DOOR BROKEN. REPLACED MAGNET OK.

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V66105

In Date: 04/30/2014

Meter Reading:

Close Date: 05/01/2014

Problem?

Q15 WOULD NOT START, LATER IT DID START

Task performed:

TRAVEL TO 15 CHECKED NO START NO PROBLEM FOUND.

Parts

NO PARTS USED

Quantity

Workorder: V66045

In Date: 04/28/2014

Meter Reading:

Close Date: 05/06/2014

Problem?

Cab lock warning light (on dash) comes on while driving.

Task performed:

DRIVE TO STA-15 CHECK CAB LOCK SENSORS ADJUST TO SPECS TEST DRIVE FOR OPERATION IS OK NOW.

Parts

NO PARTS USED

Quantity

Workorder: V66306

In Date: 05/07/2014

Meter Reading:

Close Date: 05/08/2014

Problem?

AERIAL LADDER WILL NOT WORK UNLESS SYSTEM IS SWITCHED IN OVER RIDE Q15

Task performed:

DRIVER COMPLAINT AERIAL INOP. DRIVER ERROR PUT TRUCK LEVEL AND UNIT WORKED FINE.

Parts

NO PARTS USED

Quantity



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V63782

In Date: 01/28/2014

Meter Reading: 52,038.00

Close Date: 05/21/2014

Problem?

1. Nozzle does not move correctly
2. ladder stuck in waterway mode
3. broken r4 door
4. broken door shock L2
5. air leak towards rear
6. drivers seat air seat inop

Task performed:

Parts

Quantity



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

1. SLACK ADJUSTERS-REAR BRAKES. INSTALL NEW SLACKS- SET UP TRAVEL TAND ADJUSTER STRAP- ADJUST BRAKES.
2. AIR LEAKS AFTER SLACK REPAIR- NOTICED VEHICLE WAS STILL LOOSING AIR PRESSURE- START CHECKING FROM ONE END TO THE OTHER FOR LEAKS FLUID SEVERAL AND SOME VERY HARD TO ACCESS REPAIR AND RECHECK AS I WENT.
3. PRIMER SYSTEM- PRIMER MOTOR LEAKING ON FLOOR- CHECK OUT PROBLEM . REMOVE PRIMER,PULL VALVE FROM PUMP PANEL- NOTE GREAT DIFFICULTY TO ACCESS VALVE ON BENCH. REBUILD VALVE- REINSTALL- WORK VALVE SEVERAL TIMES- REPAIR MOTOR QUITE LEEAKING BUT STEM OF VALVE IS NOW LEAKING- REMOVE AGAIN AND INSTALL NEW VALVE- NOW ALL OK.
4. FOUND CAB TILT DID NOT WORK, CHECK ALL WIRING DID NOT FIND ANY PROBLEM, PUT MOTOR DOWN AND HOOKED UP A GROUND WIRE TO THE FRAME AND IT WOULDNT WORK, SO I CLEANED FRAME AT BOLT AND GROUND AND INSTALL FOUR NEW BOLTS IN MOUNTING BRACKET AND CHECKED OK.
5. R&R LIGHT BULB.
6. FOUND HYD HOSES LEAKING AT LIFT CYLINDER ON LADDER REMOVE BOTH HOSE AND SEND TO MAKO TO MAKE NEW HOSES. GOT HOSES AND INSTLLED THEM.
7. FOUND COOLANT LEAK ON BOTTOM RAD. HOSE TIGHTEN CLAMP.
FOUND HYD HOSE LEAKING ON CAB TILT REMOVE HOSE SEND TO MAKO GOR NEW AND INSTALLED IT
8. CHECK AIR RIDE SEAT NO PROBLEM FOUND.
9. R&R PIN FOR DOOR SHOCK ON L-2.
10. REPAIRED AIR LEAK ON W.O#63515. CHECK ON DOOR ED. W SAID IT SHOULD BE THERE THIS WEEK.
11. REMOVE NOZZLE AND MONITOR, GOT PARTS; STARTED PUTTING MONITOR BACK TOGETHER FOUND GEAR BROKEN INPLANNTERY GEARS. ORDR NEW PLANATERY BAT PAT SEALS AND BALLS IN BOTH JOINT PAT OTHER PAT TOGETHER AND TESTED IT.
12. TAKE MONITOR APART CLEAN UP AND FIND BAD PARTS.
13. REMOVE OLD DOOR AND CLEAN UP TAPE UNDER HINGE, SAND TAPE OFF REPAINT UNDER HINGE.
14. TIED STRAUGHTEN LACK FOR WATERWAY, RESCUE AND BROKE IT SO TOOK IT OFF CLEAN UP FOR CARL .R TO WELD. CHECK ACTUATOR, FOUND IT BAD SO ORDER NEW ACYATOR INSTALLE NEW ACTUATOR MOTOR.

042-0091-00SPRING PRIMER	1
073-0010-00PISTON RELIEF VALVE HALE	1
1229F4634SKIT RING/LOCK WASHER	2
1429L3 FAB DOOR	1
1891BULB	1
3202099SEAL WITH RACE QUINT	2
35780365PLANRTARY GEAR 5:1	1
401581GASKET AXLE FL80 R002435	2
462733HOSE & FITTINGS	1
463202HOSE & FILTER	1
657843STRIKER EGS-FM-E500-106-ZN MT EONE	1
66617AKRON 3578 PARTS	1
78R536078R5360M 2PK FILTER AIR COND	1
A3275S1059SLACK ADJ	2
AMH-1AMH-1 VALVE EXTENSION	1
DS-EL-12524ACTUATOR WATERWAY RESCUE SMEAL FEF	1
E-600013-3052 NUT	3
FREIGHTSHIPPING CHARGES	32
FT4471BDQUINT REAR BRAKE SHOES	4
KIT9081BRAKE HARDWARE KIT	2
MJTV5 VALVE AIR CONTROL	1
NBG818GM60A0360000161 PROXIMIITY SWITCH	1
PVG-KITORING KIT	1



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

- 15. WELD BRACKET TO WATER WAY BROKEN OFF, REPAIRED REWELD END.
- 16. PAINTED LOCK AND INSTALL IT.
- 17. INSTALL NEW DOOR ON PASSENGER SIDE FOUND DOOR ALARM SWITCH BAD, HAD TO R&R DOOR ALARM SWITCH HAD TO TAKE BOTTLE HOLDER PUT TO GET TO SWITCH INSTALL PLUG ON NEW SWITCH TRY WIRE UP AND INSTALL BOTTLE HOLDER AND PUT STRIKE ON DOOR.
- 18. REMOVE ACCREDITATION DECALS AND BUFF OUT SIDES.
- 19. TRUCK WOULDNT START SO LOAD TESTED BATTERY AND BATTERY TESTED GOOD CLEANED TERMINALS HOOKED BATTERY BACK UP.
- 20. COMPARTMENT DOOR .
- 21. GET SEFAC AND PICKED UP TRUCK TO REMOVE JACK STAND.
- 22. ASSIST JERRY WITH ABOVE BRAKE REPAIR.

Workorder: V66501

In Date: 05/23/2014 **Meter Reading:** 53,728.00
Close Date: 05/23/2014

Problem?

Mirror broken Pull cord rope broken

Task performed:

REPAIRED ON W.O #66558.

Parts	Quantity
506258102PARTNER STARTER PULLEY	1
506258901SPRING ASSY	1

Workorder: V66557

In Date: 05/17/2014 **Meter Reading:**
Close Date: 05/23/2014

Problem?

driver side mirror shakes when backing up. It is very difficult to see when trying to use the rear view mirror to back up. Possible safety concern. Q15

Task performed:

TIGHTEN UP MIRROR ON DR SIDE.

Parts	Quantity
NO PARTS USED	



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V66558

In Date: 05/17/2014

Meter Reading:

Close Date: 05/23/2014

Problem?

driver's hanging fan is not working. Q15

Task performed:

Parts

Quantity

CHECK OUT FAN, REMOVE UNIT-CHECK FOR POWER REPAIR GROUND AND REINSTALL UNIT.

NO PARTS USED

Workorder: V66559

In Date: 05/17/2014

Meter Reading:

Close Date: 05/23/2014

Problem?

driver side outside tire. The tread in the middle is down to the middle wear bar. Still plenty of tread on outside wear bars. Q15

Task performed:

Parts

Quantity

1. TRAVEL TO ST-15 CHECK TIRES CALL HOP TO ORDER TIRES.
2. INSTALL MARKING THREAD TAPE ON BACK OF TURN TABLE TO GUIDE EGRESS OF F.F.

NO PARTS USED

Workorder: V66715

In Date: 05/24/2014

Meter Reading: 54,296.00

Close Date: 06/12/2014

Problem?

Replace l/r tires

Task performed:

Parts

Quantity

Replace LR

NO PARTS USED

Vendor?: ELPEX

Workorder: V66516

In Date: 05/15/2014

Meter Reading:

Close Date: 06/17/2014

Problem?

2 discharge pressure gauge sticking

Task performed:

Parts

Quantity

1. CHECK OUT GUAGE WILL ORDER NEW GUAGE.
2. R&R #2 GUAGE AND REPLUMB.

91553941GAUGE

1



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V66752

In Date: 05/26/2014

Meter Reading:

Close Date: 06/17/2014

Problem?

OIC side low mid body small orange light is out.

Task performed:

REMOVE RAIL AND R&R LIGHT.

Parts

35200-YLIGHT MARKER LEDAMBER

Quantity

1

Workorder: V67056

In Date: 06/07/2014

Meter Reading:

Close Date: 06/17/2014

Problem?

Truck motor making odd noises. Possibly sounds like a bad belt. Mechanic should check it out and the belts. So far running fine, but truck just doesn't sound normal.

Task performed:

RUN TRUCK NO ODD NOISES UNFOUNDED CHECK BELTS PER D.O REQUEST BELTS OK AND TIGHT.

Parts

NO PARTS USED

Quantity

Workorder: V67057

In Date: 06/07/2014

Meter Reading:

Close Date: 06/17/2014

Problem?

driver side rear Firefighter seat pull cord for SCBA needs adjustment. Firefighter states it's not working properly.

Task performed:

CHECK OUT SCBA SEAT CORD IS INOP TAKE CORD OFF DIVE TANK AND INSTALL NEW STYLE ON THERE, USE CORD OFF DIVE TANK ON SCBA SEAT ADJUST TEST OK.

Parts

101-124-000CRASH RESTRAINT STRAPS

Quantity

1

Workorder: V67058

In Date: 06/07/2014

Meter Reading:

Close Date: 06/17/2014

Problem?

Multi color light cover on driver side showing Water Tank level is broken and looks like might be missing one of 2 screws.

Task performed:

CHECK OUT TANK LEVEL GUAGE LENS HAS CRACK, WILL ORDER NEW LENS.

Parts

68-3963453-30LENS CLEAR FOR STRIP LIGHT

Quantity

1



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V67059

In Date: 06/07/2014
Close Date: 06/17/2014

Meter Reading:

Problem?

Halogen Light on Areal tip driver side is loose looks like it is missing several Alan head screws or they are stripped out, that hold it tight in place.

Task performed:

TRAVEL TO ST-15 CHECK OUT DR SIDE LIGHT
TIGHTEN UP SET SCREWS ON LIGHT BASE.

Parts

Quantity

NO PARTS USED

Workorder: V67190

In Date: 06/13/2014
Close Date: 06/23/2014

Meter Reading:

Problem?

2 Halogen Aerial Lights out. Both on OIC side. Tip light and base of turn table light.

Task performed:

1. TRAVEL TO ST-15 CHECK OUT LIGHTS INOP DIDNT FIND PROBLEM UNFOUNDED.
2. REPAIR HANDLT NOT CHARGING FOUND OPEN WIRE REPAIR OPEN TEST OK.
3. MOVE MIC CLIP.

Parts

Quantity

NO PARTS USED

Workorder: V67379

In Date: 06/23/2014
Close Date: 06/24/2014

Meter Reading:

Problem?

Had mechanic come out to truck on 6/22 after having difficulty with the truck starting system. Q 15

Task performed:

WENT TO ST-15 FROM ST-26- CHK STARTING SYSTEM CHK ALL VOLTAGES AND CHARGING SYSTEM. CHK OK- REMOVED BATT CABLES LOAD TEST ALL BELTS- CHK OK- CLEANED CABLES AND TERM- CHK OK NO PROBLEM FOUND.

Parts

Quantity

NO PARTS USED

Workorder: V67397

In Date: 06/23/2014
Close Date: 06/30/2014

Meter Reading:

Problem?

charger for tic is not working. no system or charging lights coming on while seated in.

Task performed:

TRAVEL TO ST- 15 CHECK OUT TIC INOP R&R BAD FUSE ON UNIT.

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V65283

In Date: 03/28/2014

Meter Reading:

Close Date: 07/02/2014

Problem?

wipers will not turn off.

Task performed:

Parts

Quantity

TRAVEL TO ST-15 CHECK OUT WIPES INOP CHECK SYSTEM.

NO PARTS USED

Workorder: V65900

In Date: 04/23/2014

Meter Reading:

Close Date: 07/17/2014

Problem?

rear compartment door alarm will not turn off. Please come fix it. It's driving us crazy.

Task performed:

Parts

Quantity

REPAIRS COMPLETE ON TICKET V65788.

NO PARTS USED

Workorder: V67996

In Date: 07/18/2014

Meter Reading:

Close Date: 07/21/2014

Problem?

quint 15 high idle is activating, and unable to turn off

Task performed:

Parts

Quantity

Travel to 15. Driver complaint that idle on all the time. Checked charging system and ran truck all ok. Showed how to bypass system to work.

4867JB320 UPGRADE ALTERNATOR

1

Workorder: V68070

In Date: 07/21/2014

Meter Reading:

Close Date: 07/21/2014

Problem?

Genesis power unit runs rough. q15

Task performed:

Parts

Quantity

Called Billreban for repair.

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V67963

In Date: 07/16/2014

Meter Reading:

Close Date: 07/23/2014

Problem?

R15 advised us after following Q15 today that breaklight on Driver side is bearily noticable. The driver side break light appears to halve half the number of LED bulbs as OIC side. Not sure if this is a safty issue?

Task performed:

Parts

Quantity

Replaced rear taillights.

60R00XRRBRAKE/TAILLIGHT LED

2

Workorder: V67966

In Date: 07/16/2014

Meter Reading:

Close Date: 07/23/2014

Problem?

There appears to be grease leaking from the bottom of the Aerial master stream nozzle and a new scratch in the same area. Nozz is operational. found 7/13. Should have a mechanic check it out. Q15

Task performed:

Parts

Quantity

Checked master stream ok.

NO PARTS USED

Workorder: V68035

In Date: 07/19/2014

Meter Reading:

Close Date: 07/23/2014

Problem?

Q15 high idle problem, cancel work request. Switch left on at turntable. No longer a problem, no follow up service nesscessary. Q

Task performed:

Parts

Quantity

Checked high idle ok.

NO PARTS USED

Workorder: V68045

In Date: 07/19/2014

Meter Reading:

Close Date: 07/23/2014

Problem?

Rear door alarm was reported as repaired and it is still activating intermintantly during driving. Q15

Task performed:

Parts

Quantity

Adjusted door alarm switch.

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V68049

In Date: 07/20/2014

Meter Reading:

Close Date: 07/23/2014

Problem?

install lifepak bracket in cab per diagram provided

Task performed:

Parts

Quantity

Crew decided to put life pack in R3 compartment.

NO PARTS USED

Workorder: V66658

In Date: 05/21/2014

Meter Reading: 54,095.00

Close Date: 07/25/2014

Problem?

B inspection Q15

Task performed:

Parts

Quantity

- 1.Travel to station 15 start "B" inspection on the shop will finish.
- 2.Travel to station 15. R and R rail and R and R marker light. Test ok.
- 3.Remove rear switch control panel. Replace lights out in rigger. High idle repair bad wire end on upper control light.
- 4.Rear compartment light out . Pull lens bulb bell out. Replace bulb and lens ok.
- 5.Travel to station 15. Remove and replaced bad seat belt. Wrong seat belts will ahve parts under the right parts.
- 6.Remove and replace wiper blades.

35200-RLIGHT MARKER LED RED

1

50-24WIPER BLADE - KME

2

Workorder: V67682

In Date: 07/04/2014

Meter Reading:

Close Date: 07/28/2014

Problem?

noticed over past few weeks an increase in oil leakage on the floor from the truck that we havn't had before. Oil level is good. Q15

Task performed:

Parts

Quantity

Check out oil leak. Found filter or housing leaking tighten filter.

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V67686

In Date: 07/05/2014

Meter Reading:

Close Date: 07/28/2014

Problem?

electrical shoreline ejector is not working for Q15. Also Rubber boot overdriver side wheel fender is sticking out a bit, It's under the shoreline ejector. Q15

Task performed:

CK, OUT AUTO EJECT FOUND BAD UNIT REPLACED
AUTO EJECT UNIT WITH NEW ONE TESTED OK.

Parts

091-20WP-120AUTO EJECT

Quantity

1

Workorder: V67741

In Date: 07/07/2014

Meter Reading:

Close Date: 07/28/2014

Problem?

Fuel gauge reads higher than fuel in tank really is. D/O's are using the excuse that fuel is greater than 3/4 tank and not fueling the truck, when tank is >30gals low on 100gal tank. Gauge may need to be calabrated.

Task performed:

Check out fuel gauge tank unit. Bad. Will order part .
Truck has to go to shop for tank drop repair.

Parts

35100090351000908 FUEL SENDING UNIT
FRT V67741FREIGHT CHARGE

Quantity

1

1

Workorder: V67744

In Date: 07/08/2014

Meter Reading:

Close Date: 07/28/2014

Problem?

rear compartment door alarm is intermitently going off.

Task performed:

REPAIRS COMPLETE ON WORK ORDER V67888

Parts

NO PARTS USED

Quantity

Workorder: V67888

In Date: 07/14/2014

Meter Reading:

Close Date: 07/28/2014

Problem?

roll up back door alarm sounds q15

Task performed:

TRAVEL TO STA15 CK, OUT DOOR SYSTEM FOUND
MAGNET MISSING INSTALLED NEW AND GLUE IN
PLACE CK,AND TESTED OK.

Parts

NO PARTS USED

Quantity



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V68397

In Date: 08/04/2014

Meter Reading: 55,774.00

Close Date: 08/08/2014

Problem?

Make up new shoreline cable

Task performed:

Travel to staition 15. Tilt cab. Check for oil leaks. Found front end lower A frame mount. Broken on both sides or truck out or service unsafe call for tow. biuld new shore line cable.

Parts

Quantity

15W40QSYN OIL QT

12

5-20PH1PGK4 CONNECTOR 120V 20A FEMALE

3

PH7405 51971 OIL FILTER WIX

2

Workorder: V68320

In Date: 07/31/2014

Meter Reading:

Close Date: 08/20/2014

Problem?

Battery switch needs replaced and truck is not charging

Task performed:

TRAVEL TO STA,-15 CK,OUT TRUCK NOT CHARGING FOUND PLUG IN CEILING OUT GET LADDER PLUG IN CORD TESTED OK. ORDER NEW BATT, SW FOR TRUCK.

Parts

Quantity

9703PERKO SWITCH

1

Workorder: V69610

In Date: 09/23/2014

Meter Reading: 55,774.00

Close Date: 09/23/2014

Problem?

need 2 cycle oil. none in station.

Task performed:

Parts only

Parts

Quantity

NO PARTS USED

Workorder: V70028

In Date: 10/09/2014

Meter Reading: 55,774.00

Close Date: 10/10/2014

Problem?

Replace front tires

Task performed:

WORK REPAIRS REQUESTED

Parts

Quantity

NO PARTS USED

Vendor?: ELPEX



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V69160

In Date: 09/04/2014
Close Date: 11/04/2014

Meter Reading: 55,774.00

Problem?

repair front suspension

Task performed:

WORK REPAIRS REQUESTED.

Parts

Quantity

NO PARTS USED

Vendor?: TOTAL TRUCK PARTS

Workorder: V70120

In Date: 10/14/2014
Close Date: 11/26/2014

Meter Reading: 55,774.00

Problem?

Rear ladder compartment. Add 3 more pike pole tube holders. 2 will fit above and 1 will fit below the existing tubes.

Task performed:

1. - 4. Start removing ladders and fabricate pipepoll brackets and brackets for little giant ladder.

Parts

Quantity

NO PARTS USED

Workorder: V70123

In Date: 10/14/2014
Close Date: 11/26/2014

Meter Reading: 55,774.00

Problem?

Rear ladder compartment. Little Giant ladder needs a Rack (like other ladders) to store it while it is in full extension position (at it's thinnest, to take up length in the compartment and not width)

Task performed:

REPAIRED ON WORK ORDER #70120.

Parts

Quantity

NO PARTS USED

Workorder: V70124

In Date: 10/14/2014
Close Date: 11/26/2014

Meter Reading: 55,774.00

Problem?

Request Trip-Tix holder in back seat area on bulk head by flashlights.

Task performed:

NOT DONE AT THIS TIME PER BC - 11/26/14.

Parts

Quantity

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V70015

In Date: 10/20/2014

Close Date: 12/02/2014

Meter Reading: 55,774.00

Problem?

C inspection Q15

Task performed:

Parts

Quantity



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

1. 1 1/2" jumpline, #3 crosslay, 33 discharge and waterway (rear) compound gauges leaking, R/R failed gauges.
2. R/R map inop. R/l rear headliner to gain access to lamp and harness. Lamp LED failed, replaced failed lamp.
3. Turntable control panel lamp inop control panel lid props weak-traced open ground to corroded connector. Repaired open circuit-replaced failed props.
4. Front suspension grease fittings not accessible and not taking grease. Replaced all grease fittings on independant front suspension.
5. Prefomed transfer case and auto lube services
6. Prefomed air system drier service
7. Replaced intake system air filter and failed below 5
8. Set tire pressures, 20 PSI low
9. Right side tip lamp bulb dim, bulb failed and replaced bulb.
10. R2 door hold open bracket loose-replaced fastners and secured.
11. Repaired loose connection at tilt cab pump. Slotted mounting brackets for cab locks for proper fit-adjusted and secured.
12. Aerial waterway valve handle drags, difficult to operate removed handle and linkage. Cleaned, lubricated and reinstalled.
13. Install belts
14. R/R coolant tank on gen
15. Calibration load minder
16. R/R hood had to remove assy to install headlight
17. R/R wiperblades and washer nozzles
18. Install drivers side front and seat
19. R/R turbo return tube part new o-rings to stop oil leaks
20. Clean up E pump and check for leaks-check after lunch, found wet at fitting so i R/R o-ring o fittings.
21. Remove trans cooler line to send to Mako-install new cooler line and turn cooler ran track. Check for leaks and top off fluids.
22. R/R brake line on driver side front wheel
23. Set up truck and put petot gauge on nozzle on ladder to calibrate flow meter.

046-0040-000GASKET CAP PLATE	1
101781007BUSHING CAB TILT	2
1141BULB	1
115-0670-00-0CAP PLATE	1
140-2897AIR FILTER ONAN 49697	1
15W40BSYN OIL BULK QTS	40
33063FUEL FILTER ONAN	1
5008414CARTRIDGE DC100	1
51064OIL FILTER ONAN	1
5117362OIL FILL PLUG 60 SERIES	1
6231-0010-11VISTA III SREEN WELDON	1
75W90GEAR OIL SYN QT	23
827007-001PIN CAB TILT FERRARA	2
827009-002CAB LIFT CYL	2
846007-001BOOT AIR CLEANER FERRARA	1
91553943GUAGE	4
99-3008 L/H NOZZLE WINDSHIELD WASHER	1
1619296P/S RESERVOIR SEAL	1
485171HOSE & FITTINGS	1
78R536078R5360M 2PK FILTER AIR COND	1
1654-8FERRULE .718	4
37000003722-44816-001 DOME LIGHT RECT	1
35200-YLIGHT MARKER LEDAMBER	1
50-24WIPER BLADE - KME	2
9420BELT	1
9435BELT	3
99-3009NOZZLE WINDSHIELD WASHER R/H	1
AVMSE300A40PGSS1728UA STRUT S/O	2
CA7230WA10116 AIR FILTER 46893 WIX	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FGQ59267COVER GASKET STEERING	1
FRT V28720FREIGHT CHARGE	1
FRT V28856FREIGHT CHARGE	1
H4656USE CV TYPE HEAD LIGHT	1
K022105PURGE VALVE AD-IP-IS	1
K080570BELT	1
P1147GFUEL FILTER 33120 WIX DELCO TP916	1
PH47 51758 L/F PH725 OIL FILTERL	1
PH7405 51971 OIL FILTER WIX	2
PS683033442 FUEL FILTER	1
Q500T3CLBULB HALOGEN 120V 500WATT 4 11/16 LONG	1
S775COUPLER	4
S777COUPLING NIPPLE	5
SAHSVS2510STRAP	1
UMVS111611STRAP	1



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

TRANSYNDALLISON TRANS FLUID GAL	3
EL12767UTILITY LIGHT QUINTS	2
FRT V28579FREIGHT CHARGE	1

Workorder: V71249

In Date: 11/28/2014 Meter Reading:
Close Date: 12/10/2014

Problem?

Foam system Flush switch is broken off.

Task performed:

Check out flush switch inop order new switch for panel

Parts	Quantity
NO PARTS USED	

Workorder: V71457

In Date: 12/06/2014 Meter Reading:
Close Date: 12/10/2014

Problem?

windshield wipers are on intermitent while in the off position. just started tonight

Task performed:

Check out wipers inop, found intermitent switch on

Parts	Quantity
NO PARTS USED	

Workorder: V71463

In Date: 12/07/2014 Meter Reading: 56,229.00
Close Date: 12/10/2014

Problem?

rear compartment door alarm is intermitent. The alarm goes off for no reason then stops then comes back on, then goes off then back on again.

Task performed:

Travel to station 15-check out dow light going off, R/R rear door track and R/R rpm switch. Rewire test ok.

Parts	Quantity
R00781R01078 SWITCH ROM ROLL UP DOOR	1

Workorder: V71432

In Date: 12/05/2014 Meter Reading:
Close Date: 12/11/2014

Problem?

door alarm issue ongoing since unit placed back in service.

Task performed:

COMPLETED ON WO#71463

Parts	Quantity
NO PARTS USED	



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V71458

In Date: 12/06/2014

Meter Reading:

Close Date: 12/11/2014

Problem?

"door open" buzzer going off most of the day. alerted to different doors open during the day. alarm would stop when the brakes were applied and restart with acceleration or standing still.

Task performed:

Parts

Quantity

Ali converted on WO#71463

NO PARTS USED

Workorder: V71248

In Date: 11/28/2014

Meter Reading:

Close Date: 12/12/2014

Problem?

ABS Light on dash is on.

Task performed:

Parts

Quantity

Check out ABS light on-check for codes, R/R wheel sensor inop-check wiring and plugs sensor bad, shop will repair on next PM

NO PARTS USED

Workorder: V68398

In Date: 08/04/2014

Meter Reading:

Close Date: 12/18/2014

Problem?

The quint is leaking oil when the engine is running. On a call oil had leaked out on the roadway from the quint.

Task performed:

Parts

Quantity

Repaired on another WO#

NO PARTS USED

Workorder: V71250

In Date: 11/28/2014

Meter Reading:

Close Date: 12/18/2014

Problem?

need a few tool mounts moved. Will call Monday on A-shift to arrange.

Task performed:

Parts

Quantity

1. Travel to station 15, mount brackets and move eq and mounts on Q-15 will return.
2. Vasko finish up mounting brackets and eq on truck

5269LPVM-5 SM MOUNT

3

UMVS111611STRAP

5



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V71574

In Date: 12/11/2014

Meter Reading:

Close Date: 12/18/2014

Problem?

Halogen light at base of Aerial on passenger side appears to be out. Switch was checked and had no effect. q15

Task performed:

Travel to station 15-check out light out, check power and ground, R/R bulb

Parts

Q500T3CLBULB HALOGEN 120V 500WATT 4 11/16 LONG

Quantity

1

Workorder: V71636

In Date: 12/14/2014

Meter Reading:

Close Date: 12/22/2014

Problem?

Ongoing issue with door alarm activation every shift now.Q15

Task performed:

Worked with Ed. and crew removing items and mounting equipment for weight problem.

Parts

SAHSVS2510STRAP

UMVS-0811-11STRAP ZICO

UMVS162511STRAP

UMVS254411STRAP 46 IN

Quantity

1

1

1

1

Workorder: V72095

In Date: 01/07/2015

Meter Reading:

Close Date: 01/16/2015

Problem?

OIC side Outrigger flasher is out.

Task performed:

Travel to ST 15. Check outrigger light out. R/R TIR 6 bulb and rewire.

Parts

50R03ZCRLIGHT LED RED TIR 6

Quantity

1

Workorder: V72096

In Date: 01/07/2015

Meter Reading:

Close Date: 01/16/2015

Problem?

Driver side Outrigger randomly is dropping on it's own and triggers an alarm. Happened on TPK half way home from HQ today.

Task performed:

Repaired on W/O #71874.

Parts

NO PARTS USED

Quantity



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V71874

In Date: 12/26/2014

Meter Reading:

Close Date: 01/20/2015

Problem?

OPEN DOOR ALARM CONTINUES TO SOUND IN CAB OF TRUCK Q15

Task performed:

1. Travel to ST 15. Check DOW inoperable. Found passenger side sensor needed adjustment. Test - ok.
2. R & R outrigger holding valve on driver's side outrigger
3. Mount hammer on door and Eq. straps. Mount Stokes basket on tank cover.

Parts	Quantity
14143-P5 IN STORZ PRESSURE GASKET	1
EAA-8350-90UGSS6558UK STRUT-LIFT	1
FRT V27642FREIGHT CHARGE	1
HY-10184PILOT CHECK VALVE	1
LPVM-7LG MOUNT	1
UMVS-0811-11STRAP ZICO	2
UMVS254411STRAP 46 IN	2

Workorder: V72179

In Date: 01/09/2015

Meter Reading:

Close Date: 01/23/2015

Problem?

Drivers air fan is not working. Q15

Task performed:

- R & R driver fan inoperable and rewire.

Parts	Quantity
0130503855 FAN BE29012 - CAB	1

Workorder: V72603

In Date: 01/26/2015

Meter Reading: 57,407.00

Close Date: 01/29/2015

Problem?

Coolant leak

Task performed:

1. Travel from home to scene. Found large coolant leak. Added coolant to get to station. Pressure tested to find leak. Leak found at cooler hose. Replaced leaking hose. Adjoining hose soft and chaffed. Replaced second hose. Added coolant and purged air from system. Test drove.
2. Fan belt squealing under load. Adjusted fan belt.
3. Check engine and stop engine lamp on. Found coolant below sensor in radiator. Air pocket purged. Topped coolant and test drove. Verified correct level.
4. Pump cooler fittings leaking water. Replaced 90 degree quick disconnect fittings.

Parts	Quantity
ANTICOOLANT ANTIFREEZE GAL	13



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V72701

In Date: 01/28/2015

Meter Reading:

Close Date: 02/06/2015

Problem?

shore cord is not working when plugged into truck Q15

Task performed:

Parts

Quantity

Travel to ST 15. Check out shore line inop. Found station breaker needed to be reset. Test unit. Charging ok.

NO PARTS USED

Workorder: V71896

In Date: 12/28/2014

Meter Reading:

Close Date: 02/09/2015

Problem?

Genesis extrication cutters, the handle is broken. Needs repaired. Q15

Task performed:

Parts

Quantity

Travel to ST 15. Check out cutter handle. Needs new handle. One ordered.

NO PARTS USED

Workorder: V73237

In Date: 02/17/2015

Meter Reading:

Close Date: 02/19/2015

Problem?

request chain saw bar chain oil. Station is out of bar chain oil.

Task performed:

Parts

Quantity

Delivered to station

NO PARTS USED

Workorder: V73238

In Date: 02/17/2015

Meter Reading:

Close Date: 02/24/2015

Problem?

Q15 a/c does not seem to be blowing cold. Can we have it checked?

Task performed:

Parts

Quantity

Travel to ST 15. Check out striping on side door. Get picture and measure for replacement.

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V71572

In Date: 12/11/2014

Meter Reading:

Close Date: 02/27/2015

Problem?

rear driver side outrigger appears to be dropping slowly or not seating properly when being put back. I noticed twice and D/O last shift noticed issue. Spoke to Mechanic about it. q15

Task performed:

Parts

Quantity

Call Tom Smeal. Order part for outriggers.

NO PARTS USED

Workorder: V73504

In Date: 02/27/2015

Meter Reading: 58,100.00

Close Date: 03/09/2015

Problem?

A/C inop

Task performed:

Parts

Quantity

1. A/C INOP. ADDED FREON TO CHECK FOR LEAKS
COULDN'T FIND LEAK. CHECKED
OUT REAR A/C ALSO.

NO PARTS USED

Workorder: V73523

In Date: 02/28/2015

Meter Reading:

Close Date: 03/09/2015

Problem?

Q15 generator wont start.

Task performed:

Parts

Quantity

1. CHECK OUT GEN NO START. CHECKED FUEL
SYS. STARTED SYS. NO PROBLEM FOUND
GEN OK

NO PARTS USED

Workorder: V74430

In Date: 04/05/2015

Meter Reading:

Close Date: 04/20/2015

Problem?

Load minder not functioning correctly. It flashes and beeps like a full load even when just out of bed. Q15

Task performed:

Parts

Quantity

Received call from station 15 reference ladder load
minder alarm going off when ladder is raised. Officer said
it was entered into IBEM and he was ok with running the
truck until it could be brought to the shop.

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V74837

In Date: 04/21/2015

Meter Reading:

Close Date: 04/21/2015

Problem?

Water Extinguisher strap clip has a bad spring and strap disconnects from the can. Request a new strap or repair/replace of clip.

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V73774

In Date: 03/10/2015

Meter Reading:

Close Date: 04/27/2015

Problem?

Rear driver side Firefighter cab door has a broken inside door light that needs repaired.

Task performed:

Parts

Quantity

- 1. Travel to staion 15. Check door light, inop. Lin min. Replace light, rewire and mount light.

2FLANGECWH200 SERIES CHROME FLANGE

1

2FR00ZCR200 SER TRI LED RED

1

Workorder: V74348

In Date: 03/31/2015

Meter Reading:

Close Date: 04/27/2015

Problem?

While hose testing, found that both pig tail hoses on both crosslays need replaced. We were unable to remove them from the swivles as they were coroded stuck and there is no room to use a spanner wrench. Q15

Task performed:

Parts

Quantity

- 1. Travel to station 15. R&R crosslays on tk. Connection rusted on.

NO PARTS USED

Workorder: V73975

In Date: 03/18/2015

Meter Reading:

Close Date: 04/30/2015

Problem?

Genesis power unit not running.starts will not continue to run. q15

Task performed:

Parts

Quantity

- 1. Check out power unit. Test run, no problem found.

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V74105

In Date: 03/23/2015

Meter Reading:

Close Date: 04/30/2015

Problem?

officer side outside rear tire has low tread.

Task performed:

Parts

Quantity

1. Check out tire. Still has 7 3/2 left on tread. Will watch for now.

NO PARTS USED

Workorder: V74171

In Date: 03/25/2015

Meter Reading:

Close Date: 04/30/2015

Problem?

OIC seat sun visor is broken off.

Task performed:

Parts

Quantity

1. Check visor off. Drill and tap head liner. Install new bolts and adjust visor. Travel to ST15.

NO PARTS USED

Workorder: V74174

In Date: 03/25/2015

Meter Reading:

Close Date: 04/30/2015

Problem?

Panel light on Aerial turn table is out.

Task performed:

Parts

Quantity

1. Travel to ST15. Check out P/P light out. Check for power ok. R&R bulb.

NO PARTS USED

Workorder: V74175

In Date: 03/25/2015

Meter Reading:

Close Date: 04/30/2015

Problem?

Aerial Tip light on driver side is loose. tightening screws are stripped out or missing. I was told by mechanic we need a new light.

Task performed:

Parts

Quantity

1. Check out It inop. Drill and pin light fro new. Will order new It.

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V74349

In Date: 03/31/2015

Meter Reading:

Close Date: 05/04/2015

Problem?

shoreline ejector appears to not be ejecting the shoreline when L15 is started.

Task performed:

Parts

Quantity

1. Travel to ST-15, R&R auto eject. and rewire.

091-20WP-120AUTO EJECT

1

Workorder: V74274

In Date: 03/29/2015

Meter Reading:

Close Date: 05/08/2015

Problem?

Rear handle on K12 saw located on L15 is broken at the back of the handle. Found on morning checks.

Task performed:

Parts

Quantity

1. Check out K-12 saw. Handle is part of main body. Will see if we have parts.

NO PARTS USED

Workorder: V73773

In Date: 03/10/2015

Meter Reading:

Close Date: 05/11/2015

Problem?

Loadminder on aerial is malfunctioning/not working properly.

Task performed:

Parts

Quantity

1. Reset ladder load sensor on upper stand.

NO PARTS USED

Workorder: V74394

In Date: 04/03/2015

Meter Reading:

Close Date: 05/11/2015

Problem?

headlight on captains side is out

Task performed:

Parts

Quantity

1. Travel to ST-15, R&R headlight.

H4656CVH4656CVC1 LOW BEAM CRYSTAL VISION

1



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V74435

In Date: 04/05/2015

Meter Reading:

Close Date: 05/11/2015

Problem?

Middle running light on the front of the cab is burned out and needs a new bulb. Q15

Task performed:

Parts

Quantity

1. Travel to ST-15. Check out marker light. Repair ground.
2. Rescue/water way mode stuck in between. Finally get mode to work. Lock bars need replaced. Get working for now. Will order.

NO PARTS USED

Workorder: V74458

In Date: 04/06/2015

Meter Reading:

Close Date: 05/11/2015

Problem?

outrigger flashing hazard lights are all out on both sides

Task performed:

Parts

Quantity

1. Repair bad wiring on flashers of truck.

NO PARTS USED

Workorder: V74473

In Date: 04/06/2015

Meter Reading:

Close Date: 05/11/2015

Problem?

Need mechanic to check A/C, it is not blowing cold. q15

Task performed:

Parts

Quantity

1. Travel to ST-15. Check out A/C inop. Found pressure inop. Replace, ok.

71R755011-2624 TRINARY SWITCH A/C 1560

1

740-1032LOCKING ARN LH SMEAL

1

740-1075LOCKING ARM RH SMEAL

1

Workorder: V74387

In Date: 04/02/2015

Meter Reading:

Close Date: 06/24/2015

Problem?

air bag light has come on dash. light is yellow in color and will not go off.

Task performed:

Parts

Quantity

1. Found inactive code dn boby controller. Cleared code and air bad light went out.

NO PARTS USED



3/28/2024

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10160569

FERRARA HD-77 2005 QUINT AERIAL

Workorder: V72426

In Date: 01/18/2015

Meter Reading:

Close Date: 06/30/2015

Problem?

driver side outrigger still dropping occasionally and triggering sensor alarm. Let Mechanic John know.

Task performed:

Parts

Quantity

NO PARTS USED



Palm Beach County Fire Rescue Fleet Maintenance Asset History

Asset: (10160569) 2005 - FERRARA HD77 Training Ladder

10160569

10182875-2015-2

Comments: L15 FLOOD LIGHT AT TIP OF LADDER IS BURNED OUT CRACK LF STEERING BOX AREA LEFT OUTRIGGER DRIFTS DOWN

Date Opened 7-13-2015 Date Finished 7-20-2015 Meter 1 Reading: 60,100

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
STEERING

CSHOP-2015-1060

Comments: Q 15 FRONT JUMP LINE LEAKS / PRIMER 10-7 AXE BRACKET NEEDS REPAIR

Date Opened 6-8-2015 Date Finished 6-11-2015 Meter 1 Reading: 60,100

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
PRIMING PUMP FIRE PUMP
FIRE PUMP

1 VALVE; VALVE PRIMER PUMP W/HARDWARE
1 SOLENOID; 2000072100 SOLENOID HALE PRIMER

CSHOP-2015-1102

Comments: REPLACE REAR TIRES LADDER15

Date Opened 6-9-2015 Date Finished 6-9-2015 Meter 1 Reading: 60,036

TASKS PERFORMED

NO PARTS USED

REAR TIRES

VENDOR? TIRE CENTERS LLC TCI

CSHOP-2015-1441

Comments: CHECK FRONT TIRES ON L15

Date Opened 6-29-2015 Date Finished 6-30-2015 Meter 1 Reading: 60,100

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

CSHOP-2015-1504

Comments: CHAINSAW WONT START L15

Date Opened 7-1-2015 Date Finished 7-1-2015 Meter 1 Reading: 60,100

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE FIGHTING EQUIPMENT

Asset Work Order History 10160569

CSHOP-2015-1563

Comments: **L15 FLOOD LIGHT AT TIP OF LADDER IS BURNED OUT**

Date Opened 7-6-2015

Date Finished 7-13-2015

Meter 1 Reading: 60,100

TASKS PERFORMED

NO PARTS USED

LIGHTING SYSTEM

CSHOP-2015-2040

Comments: **QC BACK FROM TOTAL TRUCK & REPAIRS FOR C-SER**

Date Opened 7-30-2015

Date Finished 10-8-2015

Meter 1 Reading: 60,327

QC ON QUINT

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER	1	HYD CLY REPAIR WITH SHAFT
WATERWAY AERIAL LADDER	1	HYD CLY REPAIR
HYDRAULIC CYLINDER EXTENSION	1	LIGHT; LED PANEL LIGHT
EGRESS TIP AERIAL LADDER FLY	1	FOAM VALVE
AERIAL LADDER EQUIPMENT	1	9IP; BL SQ SEAL RING
INTERCOM SYSTEM - EMERGENCY V	1	VALVE; EZ-FILL MOTOR/VALVE
FIRE FIGHTING EQUIPMENT	1	HOSE & FITTINGS
RELIEF VALVE FIRE PUMP	1	CHAIN; BEADED CHAIN W/CONN 12
FIRE PUMP	1	GASKET; 14023 GASKET 6 IN
LADDER RACK BODY	4	DECAL; LADDER OUT OF SERVICE STICKER
DISCHARGE GAUGE	1	9IP; WATERWAY RELIEF VALVE
HOSE BED BODY	1	HYD CLY REPAIR
CAB	1	FLUID; GAL CONTAINER TRANS FLUID
FAN BELT	1	BELT; BELT
OIL PAN-GASKET	3	BELT; BELT
TIMING CHAIN COVER	1	BELT; BELT
LENS	5	ASSEMBLY; INSULATOR ASSY
PARK-CLEARANCE LIGHTS	5	9IP; BOLT KIT WITH INSULATOR AND SPACER
LIGHTING SYSTEM	1	O-RING
BATTERY	1	9IP; GASKET OIL PAN 60 SERIES
TERMINAL BLOCK	1	O-RING
FILTER	1	COMPRESSOR; COMPRESSOR TO PS HOUSING
REAR TIRES	1	LIGHT; MAP LIGHT LED 18 IN
RESERVOIR	1	9IP; CLEARANCE LITE LED
ABS CODES	1	LIGHT; LED GROUND LITE CLEAR
FRONT BRAKE PADS-SHOES	6	BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY
AIR DRIER	6	BATTERY; BATTERY 950CCA HP-31D
SEAT BELTS	1	FILTER; 29548988 TRANS FILTER ALLISON
A/C FILTER	1	9IP; P/S GASKET
QUALITY CHECK-REPAIRS	1	FILTER; FG3939557S FILTER P/S NEW STYLE
	1	ABS HARNESS
	1	NONSTOCK; FREIGHT CHARGE
	1	BRAKE; BRAKE PADS WPB
	1	BRAKE; CARTRIDGE DC100
	1	VALVE; PURGE VALVE AD-IP-IS
	2	BELT; SEAT BELT
	1	FILTER; 78R5360M 2PK FILTER AIR COND
	2	FILTER; 78R5360M 2PK FILTER AIR COND

Asset Work Order History 10160569

CSHOP-2015-2069

Comments: **C-INSPECTION L15**

Date Opened 8-3-2015

Date Finished 8-20-2015

Meter 1 Reading: 60,260

C-SER.

TASKS PERFORMED

Q PARTS

PM SERVICE C

9 GEAR; GEAR OIL SYN QT
-1 FILTER; AIR FILTER GENERATOR LAF8388 ONAN
-1 FILTER; OIL FILTER ONAN
1 FILTER; AIR FILTER GENERATOR LAF8388 ONAN
1 FILTER; OIL FILTER ONAN
1 FILTER; OIL FILTER ONAN
1 FILTER; OIL FILTER ONAN
1 FILTER; FUEL FILTER ONAN
-1 FILTER; FUEL FILTER ONAN
1 FILTER; 33442 FUEL FILTER
1 FILTER; FUEL FILTER 33120 WIX DELCO TP916
2 FILTER; 51971 OIL FILTER WIX
1 FILTER; 51758 L/F PH725 OIL FILTERL
1 FILTER; FUEL FILTER ONAN
40 FLUID; SYN OIL BULK QTS
1 FILTER; AIR FILTER ONAN 49697
10 FLUID; ALLISON TRANS FLUID GAL

CSHOP-2015-2073

Comments: **REPLACED FRONT TIRES**

Date Opened 8-3-2015

Date Finished 8-3-2015

Meter 1 Reading: 60,110

TASKS PERFORMED

NO PARTS USED

FRONT TIRES

VENDOR? ELPEX TIRE TIRESOLES

CSHOP-2015-2617

Comments: **UL REPAIRS L15**

Date Opened 8-31-2015

Date Finished 9-28-2015

Meter 1 Reading: 60,268

TASKS PERFORMED

NO PARTS USED

CRADLE AERIAL LADDER
WATERWAY AERIAL LADDER
HYDRAULIC CYLINDER EXTENSION
EGRESS TIP AERIAL LADDER FLY
AERIAL LADDER EQUIPMENT
AERIAL EQUIPMENT FIRE APPARATUS
UL AERIAL TESTING

CSHOP-2015-3092

Comments: **WHITE SMOKE FROM EXHAUST T15**

Date Opened 9-25-2015

Date Finished 10-2-2015

Meter 1 Reading: 60,269

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

Asset Work Order History 10160569

CSHOP-2015-3217

Comments: **L15 AIR LEAK THAT AFFECTS THINGS LIKE SEATS.**

Date Opened 10-5-2015 Date Finished 10-13-2015 Meter 1 Reading: 60,366

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM

CSHOP-2015-3243

Comments: **Q15**

Date Opened 10-5-2015 Date Finished 10-14-2015 Meter 1 Reading: 60,366

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
ENGINE AND ACCESSORIES
SEAT FRONT

1 9IP; 6222207-001 W AIR SEAT

Service Requests:

10/05/2015 SERVICE REQUEST / 12: BROKEN / REPAIR
1. AIR LEAK THAT IS CAUSING DRIVERS SEAT TO NOT BE ADJUSTABLE. 2. FLOW METER GAUGE FOR AERIAL WATERWAY IS NOT DISPLAYING GPM'S. 3. DIAL FOR FOAM SETTING MISSING ON PUMP PANEL.

CSHOP-2015-3367

Comments: **AUDIBLE ALARM FOR EXCESSIVE IDLE Q 15 LADDER TIP LIGHT OUT**

Date Opened 10-13-2015 Date Finished 10-27-2015 Meter 1 Reading: 61,437

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
ENGINE AND ACCESSORIES
QUARTZ LIGHT

1 BULB; BULB HALOGEN 120V 500WATT 4 11/16 LONG

Service Requests:

10/12/2015 ALARMS / 12: BROKEN / REPAIR
INDICATOR PANEL BY CAPT SEAT SHOWS EXCESSIVE IDLE ON SCREEN, HAVE A AUDIBLE ALARM ON

10/17/2015 LIGHTS / 12: BROKEN / REPAIR
LADDER TIP LIGHT ON THE DRIVER SIDE IS BURN OUT.

CSHOP-2015-367

Comments: **RRO TIRE DOWN TO WEAR BAR Q15 CALL HERE IF IT NEEDS TIRES THANK YOU**

Date Opened 4-30-2015 Date Finished 4-30-2015 Meter 1 Reading: 59,264

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
TIRES & WHEELS

Asset Work Order History 10160569

CSHOP-2015-400

Comments: **CHECK ENGINE LIGHT ON L15 REPLACED COOLANT SIGHT GLASS AND TOPPED OFF COOLANT**

Date Opened 5-1-2015 Date Finished 5-4-2015 Meter 1 Reading: 59,275

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
RADIATOR
HVAC SYSTEM

2 FLUID; 50-50 EXTENDED LIFE COOLANT GAL
1 FREIGHTLINER; SIGHT GLASS SAME AS 17KP655

CSHOP-2015-4209

Comments: **L15 MIRROR BROKEN**

Date Opened 11-30-2015 Date Finished 12-18-2015 Meter 1 Reading: 60,774

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
MIRRORS

1 NEWPART; MIRROR ASSY L/H

Service Requests:

11/29/2015 MIRROR / 12: BROKEN / REPAIR
DRIVER SIDE TOP MIRROR BROKEN OFF. BOTTOM MIRROR MAY HAVE MINOR DAMAGE, BUT IS OPERATIONAL.

CSHOP-2015-4434

Comments: **PRIMER STUCK DURING PUMP TESTING L15**

Date Opened 12-11-2015 Date Finished 12-15-2015 Meter 1 Reading: 60,757

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE APPARATUS
LIGHTING SYSTEM

1 BULB; BULB HALOGEN 120V 500WATT 4 11/16 LONG

Service Requests:

12/12/2015 SERVICE REQUEST / 12: BROKEN / REPAIR
PRIMER HANDLE STICKS IN ON PULLED POSITION

12/13/2015 LIGHTS / 12: BROKEN / REPAIR
L15 TIP CAPTAIN SIDE HALOGEN SPOT LIGHT NOT TURNING ON. BULB LOOKS BURNT OUT.

12/13/2015 LIGHTS / 12: BROKEN / REPAIR
L15 TIP CAPTAINS SIDE HALOGEN LIGHT NOT TURNING ON. BULB LOOKS BURNT OUT.

CSHOP-2015-447

Comments: **L15 RIGHT TIP LIGHT ON THE LADDER AND THE ONE BEHIND IT ON THE SAME SIDE NOT WORKING**

Date Opened 5-5-2015 Date Finished 5-8-2015 Meter 1 Reading: 59,849

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM

1 BULB; BULB HALOGEN 120V 500WATT 4 11/16 LONG

Asset Work Order History 10160569

CSHOP-2015-448

Comments: **RIGHT TIP LIGHT AND THE ONE BEHIND IT ARE INOP L15**

Date Opened 5-5-2015 Date Finished 5-11-2015 Meter 1 Reading: 59,849

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM

1 BULB; BULB HALOGEN 120V 500WATT 4 11/16 LONG

CSHOP-2015-4561

Comments: **L15**

Date Opened 12-21-2015 Date Finished 1-19-2016 Meter 1 Reading: 61,049

TASKS PERFORMED

Q PARTS

QUARTZ LIGHT
MIRRORS

2 BULB; BULB HALOGEN 120V 500WATT 4 11/16 LONG

Service Requests:

01/06/2016 LIGHTS / 12: BROKEN / EXCHANGE - NEW
CAPTAINS SIDE FLOOD LIGHT ON THE BASE OF LADDER TURNTABLE IS OUT.

CSHOP-2015-471

Comments: **T-15 SCENE LIGHTS OUT ON LADDER.**

Date Opened 5-6-2015 Date Finished 5-11-2015 Meter 1 Reading: 59,849

TASKS PERFORMED

Q PARTS

SPOT LIGHTS

1 BULB; BULB HALOGEN 120V 500WATT 4 11/16 LONG

CSHOP-2015-571

Comments: **RRO TIRE LOW TREAD WATERWAY DISPLAY NOT DISPLAYING NUMBERS OUTRIGGER CONTROL SWITCH LIGHT
DRIVERS SIDE DAMAGED L15**

Date Opened 5-11-2015 Date Finished 6-11-2015 Meter 1 Reading: 60,036

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
INSTRUMENT CLUSTER
INSTRUMENTS-GAUGES-METERS

1 LAMP; LAMP
1 FRC GAUGE

CSHOP-2015-778

Comments: **HANDLE ON GENESIS CUTTER BROKEN Q 15**

Date Opened 5-26-2015 Date Finished 5-28-2015 Meter 1 Reading: 60,000

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
HURST TOOL SPREADERS

Asset Work Order History 10160569

CSHOP-2016-1102

Comments: **L15**

Date Opened 3-8-2016 Date Finished 3-21-2016 Meter 1 Reading: 61,367

TASKS PERFORMED

NO PARTS USED

SERPENTINE BELT
HVAC SYSTEM

-1 BELT; BELT
1 BELT; BELT

Service Requests:

03/08/2016 A/C / 12: BROKEN / REPAIR
A/C BELT IS SQUEALING REALLY BAD. WE NEED A MECHANIC TO TAKE A LOOK AT IT, IT MAY NEED A NEW BELT.

CSHOP-2016-1278

Comments: **WILL COME IN TO SHOP THURSDAY MORNING IF ALL GOES WELL**

Date Opened 3-16-2016 Date Finished 3-17-2016 Meter 1 Reading: 61,336

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

Service Requests:

03/16/2016 A/C / 12: BROKEN / ADJUST
A/C NOT WORKING. SOUNDS LIKE THE BELT IS BAD. REMOVED BRACKET. TO BE REPAIRED AT NEXT SERVICE

CSHOP-2016-1281

Comments: **L15 ALIGNMENT**

Date Opened 3-17-2016 Date Finished 3-17-2016 Meter 1 Reading: 61,336

TASKS PERFORMED

NO PARTS USED

ALIGNMENT

VENDOR? ELPEX TIRE TIRESOLES

CSHOP-2016-1388

Comments: **LOW VOLTAGE**

Date Opened 3-23-2016 Date Finished 3-23-2016 Meter 1 Reading: 61,389

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
ELECTRICAL

Asset Work Order History 10160569

CSHOP-2016-1625

Date Opened 4-6-2016

Date Finished

4-18-2016

Meter 1 Reading:

61,440

TASKS PERFORMED

PM SERVICE C

<u>Q</u>	<u>PARTS</u>
2	FILTER; 51971 OIL FILTER WIX
1	FILTER; 51758 L/F PH725 OIL FILTERL
1	ANODE; ANODE ONLY
1	CAP; CAP RADIATOR 10 LB
1	FILTER; 33442 FUEL FILTER
1	FILTER; OIL FILTER ONAN
1	FILTER; FUEL FILTER 33120 WIX DELCO TP916
1	FILTER; FUEL FILTER ONAN

CSHOP-2016-1731

Comments: **REPAIRS FROM PM MOUNT NUMBER PANELS BACK ON LADDER 15**

Date Opened 4-12-2016

Date Finished

10-21-2016

Meter 1 Reading:

61,450

CAB AC INOP. BRACKET BROKEN

TASKS PERFORMED

AERIAL LADDER NAMEPLATES
HYDRAULIC CYLINDER EXTENSION
TURNABLE CONTROL CONSOLE AER
AERIAL EQUIPMENT FIRE APPARATUS
FOAM SYSTEM
FIRE PUMP CONTROLS
PRIMING PUMP FIRE PUMP
WIPER BLADES
FUEL TANK
CAP
LICENSE PLATE LIGHTS
PARK-CLEARANCE LIGHTS
BATTERY
SWITCH-ELECTRICAL
MOUNT
REAR TIRES
FRONT TIRES
GRILLE
DOOR ALARM OR OTHER WARNING
A/C FILTER
A/C HOSES/FITTINGS

<u>Q</u>	<u>PARTS</u>
1	CLASS 1; LOADMINDER LMS KIT
1	NEWPART; TRANSDUCER
2	NEWPART; FITTING SWAGELOK
1	9IP; BL SQ SEAL RING
1	PANEL; SPS PANEL
1	CLASS 1; TRANSDUCER COMMAND MASTER 300 PSI
1	VALVE; VALVE PRIMER PUMP W/HARDWARE
2	WIPER; WIPER BLADE - KME
1	LIGHT; STEPWELL LIGHT
1	LIGHT; LIGHT MARKER LED RED
2	FILTER; A/C FILTER WPB
1	COMPRESSOR; 03-3470 COMPRESSOR A/C
1	COMPRESSOR; 03-3470 COMPRESSOR A/C
1	9IP; 11-2624 TRINARY SWITCH A/C 1560
1	9IP; 12-2012A EXPANSION VALVE 71R8301
1	9IP; 11-3084 THERMOSTAT A/C 1331
1	NEWPART; FITTING
1	A/C; 17-3428 ESTER OIL E7
1	A/C; 17-3428 ESTER OIL E7
2	VALVE; 8915 VALVE CORE A/C 3544706C1
1	NEWPART; HOSE
1	NEWPART; BELT
1	FILTER; FUEL FILTER 33120 WIX DELCO TP916
1	NEWPART; HOSE & FITTING
1	9IP; 12-2012A EXPANSION VALVE 71R8301
1	DRYER; 07-2613A RED DOT DRIER 7127
1	FILTER; 78R5360M 2PK FILTER AIR COND
1	9IP; 03-6540G COMPRESSOR HEAD
2	DRYER; 07-2613A RED DOT DRIER 7127
1	DRYER; 07-2613A RED DOT DRIER 7127

Asset Work Order History 10160569

CSHOP-2016-240

Comments: **L15**

Date Opened 1-19-2016

Date Finished

2-4-2016

Meter 1 Reading:

61,141

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

Service Requests:

12/20/2015 SERVICE REQUEST / 12: BROKEN / REPAIR
FRONT BUMPER DISCHARGE VALVE IS STILL LEAKING. FOUND BUMPER LINE FULL OF WATER AGAIN.

01/19/2016 ENGINE / 12: BROKEN / REPAIR
WHILE DRIVING IT SOUND LIKE A BELT IS SLIPPING AND CAUSING A LOUD SQUEALING SOUND.

CSHOP-2016-3657

Comments: **STEERIN BOX BRACKET L15**

Date Opened 8-1-2016

Date Finished

8-5-2016

Meter 1 Reading:

61,418

TASKS PERFORMED

NO PARTS USED

STEERING

CSHOP-2016-485

Comments: **L-15 LOW BEAM HEADLIGHTS NOT VERY BRIGHT**

Date Opened 2-1-2016

Date Finished

2-4-2016

Meter 1 Reading:

61,141

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM
AIR SYSTEM

2 LAMP; HEAD LAMP LOW BEAM CRYSTAL VISION

Service Requests:

01/31/2016 LIGHTS / 17: INSUFFICIENT LUBRICANT / REPAIR
REQUEST BRIGHTER HALOGEN HEADLIGHTS FOR L15. LOW BEAMS PERFORM POORLY AND I END UP HAVING TO
DRIVE WITH HIGH BEAMS ON.

CSHOP-2016-595

Date Opened 2-8-2016

Date Finished

2-12-2016

Meter 1 Reading:

61,238

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
ALIGNMENT

Service Requests:

02/06/2016 STEERING / 13: CHIPPED / REPAIR
L15 COULD USE AN ALIGNMENT. STEERING WHEEL HAS BECOME OFF CENTER AND INSIDE OF TIRE WEAR IS
GETTING BAD.

Asset Work Order History 10160569

CSHOP-2016-945

Comments: **L15**

Date Opened 2-29-2016

Date Finished

3-7-2016

Meter 1 Reading:

61,307

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
DOOR

Service Requests:

02/27/2016

DOOR / 12: BROKEN / REPAIR

DRIVER SIDE COMPARTMENT DOOR #2. DOOR STRUT IS BROKEN OFF. THE SCREW THAT THE STRUT ATTACHES TO THE BODY IS BROKEN OFF. THE STRUT IS ACTUALLY FUNCTIONAL.

CSHOP-2017-1168

Comments: **REPAIRS FROM UL TEST**

Date Opened 2-24-2017

Date Finished

2-25-2017

Meter 1 Reading:

61,559

UL TEST REPAIRS

TASKS PERFORMED

NO PARTS USED

UL AERIAL TESTING

CSHOP-2017-1308

Date Opened 3-3-2017

Date Finished

3-20-2017

Meter 1 Reading:

61,767

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES
QUARTZ LIGHT
HVAC SYSTEM

1

BULB; BULB HALOGEN 120V 500WATT 4 11/16 LONG

Service Requests:

02/27/2017

A/C / 12: BROKEN / REPAIR

A/C ISSUE, FRONT CAB PASSENGER BLOWING WARM AIR. ALSO DRIVER SIDE TRACKING BASE LIGHT ON THE LADDER IS OUT.

03/02/2017

A/C / 12: BROKEN / REPAIR

A/C ISSUE, BOTH A/C FRONT CAB AND BACK SEAT BLOWING HOT AIR

03/05/2017

LIGHTS / 12: BROKEN / REPAIR

VEHICLE LIGHTS NOT WORKING, HALOGEN BASE LIGHT ON AERIAL (DRIVER SIDE) HAS A BURNED OUT BULB.

CSHOP-2017-1762

Comments: **PRIMER INOP**

Date Opened 3-23-2017

Date Finished

3-30-2017

Meter 1 Reading:

61,858

TASKS PERFORMED

Q PARTS

PRIMING PUMP FIRE PUMP

1

PUMP; PRIMER PUMP MOTOR

Asset Work Order History 10160569

CSHOP-2017-1875

Date Opened 3-28-2017 Date Finished 5-25-2017 Meter 1 Reading: 62,350

TASKS PERFORMED

Q PARTS

FIRE APPARATUS
DOOR

1 1DB; PUMP

Service Requests:

03/28/2017 SERVICE REQUEST / 12: BROKEN / REPAIR
L15 PRIMER SWITCH ON PUMP PANEL NOT WORKING..

03/31/2017 DOOR / 12: BROKEN / REPAIR
L15 DRIVER OPERATOR DOOR PISTON BROKEN.

CSHOP-2017-2081

Comments: **L15**

Date Opened 4-10-2017 Date Finished 5-1-2017 Meter 1 Reading: 62,077

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
AERIAL EQUIPMENT FIRE APPARATUS

1 5EF; 5EF
1 NONSTOCK; FREIGHT CHARGE

Service Requests:

04/10/2017 SERVICE REQUEST / 12: BROKEN / REPAIR
EXTEND - RETRACT LEVER ON TURN TABLE THREADS ARE STRIPPED WONT TIGHTEN.

04/14/2017 BODY / 12: BROKEN / REPAIR
BODY ISSUE/ PISTON TO DRIVER COMPARTMENT 10-7

CSHOP-2017-2532

Date Opened 5-1-2017 Date Finished 5-25-2017 Meter 1 Reading: 62,350

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
ABS COMPUTER CONTROLS

Service Requests:

04/28/2017 SERVICE REQUEST / 12: BROKEN / REPAIR
SERVICE REQUEST: ABS LIGHT ON DASH IS ON

CSHOP-2017-2699

Date Opened 5-8-2017 Date Finished 5-8-2017 Meter 1 Reading: 62,261

TASKS PERFORMED

NO PARTS USED

COMMERCIAL WORK - OUTSIDE AGENCY

VENDOR? DAN CALLAGHAN ENTERPRISES

Asset Work Order History 10160569

CSHOP-2017-3913

Date Opened 7-3-2017 Date Finished 8-10-2017 Meter 1 Reading: 63,026

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
ENGINE AND ACCESSORIES
QUARTZ LIGHT

1 9IP; BRACKET WPB
3 9IP; BULB HALOGEN 120V 500WATT 4 11/16 LONG

Service Requests:

07/01/2017 ENGINE / 12: BROKEN / REPAIR
ENGINE: ENGINE LIGHT CAME ON TODAY THEN EVENTUALLY WENT OUT.

07/02/2017 TIRES / 12: BROKEN / REPAIR
BAD TIRES L15 NEEDS REAR TIRES. TIP LIGHT ON LADDER IS BROKE.

CSHOP-2017-4155

Date Opened 7-17-2017 Date Finished 7-17-2017 Meter 1 Reading: 62,600

TASKS PERFORMED

NO PARTS USED

COMMERCIAL WORK - OUTSIDE AGENCY

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2017-4361

Date Opened 7-27-2017 Date Finished 8-11-2017 Meter 1 Reading: 63,026

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AUTO-EJECT

Service Requests:

07/27/2017 SERVICE REQUEST / 12: BROKEN / REPAIR
SERVICE REQUEST: SHORELINE FUSE FOR LAD15 MIGHT BE BLOWN. BECAUSE IS POWER ON SHORELINE
EXTENSION CORD

Asset Work Order History 10160569

CSHOP-2017-4615

Date Opened 8-9-2017 Date Finished 11-6-2017 Meter 1 Reading: 63,859

AC INOP.

TASKS PERFORMED

Q PARTS

REPAIR FROM PM - TILT CAB	1	9HY; HOSE FITTINGS
QUARTZ LIGHT	1	9IP; BULB HALOGEN 120V 500WATT 4 11/16 LONG
HEADLIGHTS LOW BEAM	2	LMP; BRITE LITE LAMP
HVAC SYSTEM	1	NTE; VAC PUMP OIL 32 OZ
	1	9IP; 03-6540G COMPRESSOR HEAD
	2	2CU; WATER PUMP
	-2	2CU; WATER PUMP
	1	9IP; 03-0607 A/C COMPRESSOR U4482 USE 7169 D
	-1	9IP; 03-0607 A/C COMPRESSOR U4482 USE 7169 D

Service Requests:

08/09/2017 A/C / 18: LEAKING / REPAIR
A/C ISSUE NOT WORKING AT ALL IN THE FRONT

09/06/2017 A/C / 18: LEAKING / REPAIR
A/C ISSUE, NO A/C AT ALL. WILL NOT TURN ON

09/06/2017 TIRES / 13: CHIPPED / EXCHANGE - NEW
BAD TIRES, INSIDE RIGHT TIRE WEAR

09/06/2017 LIGHTS / 12: BROKEN / EXCHANGE - NEW
TOWER LIGHTS NOT WORKING

CSHOP-2017-4742

Comments: **QUALITY CHECK GET READY TO SEND TO ST73 MAKE SURE IT HAS A HEIGHT DECAL AND THAT IS READS WILL NOT FIT IN ST73**

Date Opened 8-14-2017 Date Finished 10-23-2017 Meter 1 Reading: 63,555

TASKS PERFORMED

Q PARTS

HOLDING VALVES	2	5EF; CAB LOCK
ENGINE AND ACCESSORIES	1	9HY; HOSE
STEERING		
HVAC SYSTEM		

Service Requests:

09/04/2017 A/C / 12: BROKEN / EXCHANGE - NEW
A/C ISSUE A/C NOT WORKING. NO COLD. NO AIR EVEN BLOWING ON DRIVER SIDE. USED ELECTRONIC SWITCHES ON KEY PAD. STILL NOT WORKING. HOT!!!

CSHOP-2017-5307

Comments: **WOULD NOT BED**

Date Opened 9-12-2017 Date Finished 9-14-2017 Meter 1 Reading: 63,460

TASKS PERFORMED

NO PARTS USED

CRADLE AERIAL LADDER

Asset Work Order History 10160569

CSHOP-2017-5365

Comments: **SHORELINE CHARGER INOP SPARE LADDER AT ST29**

Date Opened 9-14-2017 Date Finished 9-14-2017 Meter 1 Reading: 63,460

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AUTO-EJECT

CSHOP-2017-5396

Date Opened 9-17-2017 Date Finished 9-18-2017 Meter 1 Reading: 63,536

TASKS PERFORMED

NO PARTS USED

CAB

CSHOP-2017-5446

Date Opened 9-19-2017 Date Finished 9-20-2017 Meter 1 Reading: 63,555

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
HOSES-LINES & FITTINGS

2 2IH; POWER STEERING FLUID 32OZ

Service Requests:

09/18/2017 SERVICE REQUEST / 18: LEAKING / INSPECT
SERVICE REQUEST LADDER 29 NEEDS STEERING AND DEF FLUID. BOTH WERE FILL TODAY. POSSIBLE SLOW LEAK.
THERE IS NO RESERVES FLUID AT THE STATION. SPARE QUINT.

CSHOP-2017-5646

Comments: **SPARE LADDER AT 29**

Date Opened 9-28-2017 Date Finished 9-29-2017 Meter 1 Reading: 63,555

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
HEADLIGHTS LOW BEAM

Service Requests:

09/28/2017 LIGHTS / 12: BROKEN / EXCHANGE - NEW
VEHICLE LIGHTS NOT WORKING RIGHT SIDE LOW BEAM HEADLIGHT GOES OFF WHEN HIGH BEAM IS TURNED ON.

CSHOP-2017-578

Comments: **C-INSPECTION**

Date Opened 1-26-2017 Date Finished 2-22-2017 Meter 1 Reading: 61,553

C-SER.

TASKS PERFORMED

Q PARTS

PM SERVICE C

20 9IP; 9IP

Asset Work Order History 10160569

CSHOP-2017-6280

Comments: **COOLENT WAS DROPPED OFF AT STATION**

Date Opened 10-31-2017 Date Finished 11-1-2017 Meter 1 Reading: 63,555

TASKS PERFORMED

Q PARTS

COOLING SYSTEM
FUEL GAUGE
INSTRUMENTS-GAUGES-METERS

18 PAF; ANTIFRZ

Service Requests:

10/30/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
SERVICE REQUEST - CHECK ENGINE LIGHT COMES ON THROUGHOUT THE DAY - STOP ENGINE LIGHT COMES ON INTERMITTENTLY - 'BARO LOW' COMES UP ON OFFICER'S SIDE DISPLAY - IDLE TOO LONG DISPLAYED - LOW COOLANT 0% AFTER TOPPING OFF COOLANT

10/31/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
SERVICE REQUEST FUEL GAUGE READING IS INACCURATE, READS FULL ALL THE TIME

10/31/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
SERVICE REQUEST- PLEASE SEND 2 CASES OF COOLANT FOR LADDER TRUCK- 10160569

CSHOP-2017-6363

Comments: **LEAKING FLUID UNDER TURN TABLE**

Date Opened 11-3-2017 Date Finished 11-3-2017 Meter 1 Reading: 63,555

TASKS PERFORMED

NO PARTS USED

HYDRAULIC SYSTEM

CSHOP-2017-6367

Comments: **LOW POWER/BLACK SMOKE**

Date Opened 11-3-2017 Date Finished 11-17-2017 Meter 1 Reading: 64,197

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES
DIAGNOSE ELECTRICAL

1 2FL; ACTUATOR

Asset Work Order History 10160569

CSHOP-2017-6406

Date Opened 11-6-2017 Date Finished 11-6-2017 Meter 1 Reading: 63,555

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FOAM SYSTEM
FIRE APPARATUS
COOLING SYSTEM

Service Requests:

- 11/04/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
SERVICE REQUEST- PRESSURE GOVERNOR NOT WORKING CORRECTLY. WILL NOT MAINTAIN A CONSTANT PRESSURE , OCCASIONALLY WILL NOT RESPOND AT ALL.
- 11/04/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
SERVICE REQUEST- WATP SYSTEM WILL NOT WORK AT ALL, FOAM IS DUMPING ON THE GROUND WHEN SYSTEM IS ACTIVATED
- 11/04/2017 ALARMS / 18: LEAKING / REPAIR
ALARM SIGNALS- STOP ENGINE LIGHT ON, LOW COOLANT LIGHT ON, CHECK ENGINE LIGHT ON, CAB LATCH LIGHT ON

CSHOP-2017-642

Comments: **PM REPAIRS.**

Date Opened 1-30-2017 Date Finished 3-27-2017 Meter 1 Reading: 61,858

CAB LATCH INOP.

TASKS PERFORMED

Q PARTS

WATERWAY AERIAL LADDER	1	5EF; WATER WAY ELBOW SEAL KIT
EGRESS TIP AERIAL LADDER FLY	1	5EF; WATER WAY SEAL KIT
AERIAL LADDER EQUIPMENT	2	WIPER; WIPER BLADE - KME
SWIVEL AERIAL LADDER	1	LAMP; HEAD LAMP HIGH BEAM CRYSTAL VISION
WIPER BLADES	6	1AD; BATTERY 31 SERIES
DRAIN COCK	1	9IP; AUTO EJECT
FLASHER	1	9AP; TRANS DIPSTICK
HEADLIGHTS HIGH BEAM	1	BRAKE; CARTRIDGE DC100
BATTERY	1	9HY; 9HY
AUTO-EJECT	2	5EF; CAB LOCK
DIPSTICK AND TUBE	1	NONSTOCK; FREIGHT CHARGE
AIR DRIER	1	5FF; CAB LATCH SWITCH
BODY EXTERIOR		

CSHOP-2017-6715

Date Opened 11-21-2017 Date Finished 11-21-2017 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR? DAN CALLAGHAN ENTERPRISES

Asset Work Order History 10160569

CSHOP-2017-6757

Date Opened 11-27-2017 Date Finished 11-27-2017 Meter 1 Reading: 64,297

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM

CSHOP-2017-6864

Date Opened 12-1-2017 Date Finished 12-1-2017 Meter 1 Reading: 64,354

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
INSTRUMENTS-GAUGES-METERS

Service Requests:

12/01/2017 ENGINE / 18: LEAKING / REPAIR
ENGINE- OCCASIONALLY, TRUCK IS LOSING POWER AND BLACK OR WHITE SMOKE IS POURING FROM THE EXHAUST.

CSHOP-2017-7059

Date Opened 12-11-2017 Date Finished 12-11-2017 Meter 1 Reading: 64,445

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2017-7083

Date Opened 12-12-2017 Date Finished 12-21-2017 Meter 1 Reading: 64,451

CHECK ENGINE LT & SMOKE AT EXHAUST

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
FAULT CODE

4	2FL; WASHER
3	NBH; SIL SDI COOLANT HOSE
1	2FL; SELA RING
4	5SC; NUT
1	2FL; HOSE
1	2FL; HOSE
3	9AP; BRAKE CLEANER
1	9IP; WA10116 AIR 46893
1	2FL; GASKET
1	2FL; EGR
1	2FL; SEAL RING
2	2FL; O RING
1	2FL; HOSE
3	2FL; NUT
1	2FL; HOSE

Asset Work Order History 10160569

CSHOP-2018-231

Date Opened 1-10-2018 Date Finished 1-10-2018 Meter 1 Reading: 64,630

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

CSHOP-2018-6187

Comments: **USE FOR PM FOLLOW UPS OIL PRESSURE GAUGE INOP CAB LATCH LIGHT ON FRONT TIRE VALVE STEM HIT BRAKE CALIPER AND GETS DAMAGED**

Date Opened 10-30-2018 Date Finished 1-30-2019 Meter 1 Reading: 64,767

TASKS PERFORMED

Q PARTS

AERIAL LADDER EQUIPMENT	1	BK; MPACT BLK GRAY XL
CONTROL VALVE FIRE PUMP	1	NONSTOCK; FREIGHT CHARGE
SENSING VALVE FIRE PUMP	3	CRC; CHAINWIRE ROPE LUBE
HYD PUMP-PTO	3	CRC; CHAINWIRE ROPE LUBE
WIPERS-WASHER	98	5EF; WRUNG COVER
REPAIR FROM PM - GENERATOR	22	5EF; RUNG COVER
ENGINE AND ACCESSORIES	1	8HD; BRAIDED NYLON
QUARTZ LIGHT	2	8AM; CABLE
BATTERY	1	5EF; SMEAL PARTSLADDER CABLES
SHORELINE CHARGER	1	9AP; TIE STRAP
FRONT BEARING-RACE	1	5AB; 3- 3.5 BALL KIT COMPOSITE
HVAC SYSTEM	1	5TN; CONVERSION KIT SS BALL 15
	6	5EF; RUBBER RUNG COVER
	2	1AN; WIPER BLADE
	1	9AP; SORBENT PAD
	2	5FR; LIGHT HEAD
	1	NONSTOCK; FREIGHT CHARGE
	2	5FR; LIGHT HEAD
	6	1AD; BATTERY 31 SERIES
	1	6KU; AC2000 12V PLC TEN8
	1	6KU; AUTO EJECT
	1	5SC; RELAY 40A/30A 5PIN
	2	NOS; HD TRUCK SCOTSEAL
	7	9XX; 134A 10194654
	1	MMM; ELECTRICAL TAPE
	2	CRC; FOAMING COIL CLEANER
	2	TEM; FILTER DRIER
	1	TEM; BLOW/MOT
	1	TEM; EXPANSION VALVE

CSHOP-2018-6188

Date Opened 10-30-2018 Date Finished 12-3-2018 Meter 1 Reading: 64,767

TASKS PERFORMED

Q PARTS

PM SERVICE C	1	FIL; NAPAGOLD OIL FILTER
	1	FIL; NAPAGOLD AIR FILTER
	1	FIL; NAPAGOLD FUEL FILTER

Asset Work Order History 10160569

CSHOP-2018-619

Comments: **UL REPAIRS**

Date Opened 1-29-2018 Date Finished 8-2-2018 Meter 1 Reading: 64,657

QUARTZ LT AT LEFT SIDE TIP OF 3RD SECTION IS DAMAGED

TASKS PERFORMED

Q PARTS

OUTRIGGERS/STABILIZERS	2	9IP; PROXIMITY SWITCH
AERIAL EQUIPMENT FIRE APPARATUS	1	NONSTOCK; FREIGHT CHARGE
TANK-RESERVOIR	1	9AP; BREATHER CAP 3/4 PIPE
MOTOR	1	FIL; OIL ANALYSIS KIT
CONTROL VALVE	1	5TN; GUAGE
HYDRAULIC SYSTEM		
ENGINE AND ACCESSORIES		
QUARTZ LIGHT		

CSHOP-2018-6326

Date Opened 11-6-2018 Date Finished 11-6-2018 Meter 1 Reading: 64,711

TASKS PERFORMED

NO PARTS USED

TIRES ALL

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2018-677

Date Opened 2-1-2018 Date Finished 5-25-2018 Meter 1 Reading: 64,657

SHORELINE CHARGER INOP.

TASKS PERFORMED

Q PARTS

FUEL INJECTOR	1	FIL; NAPAGOLD FUEL FILTER
SHORELINE CHARGER	1	2DD; INJECTOR
	1	2DD; SEAL
	1	2DD; INJECTOR HARNESS
	1	9HY; 9HY
	6	2DD; BOLT
	1	FIL; NAPAGOLD FUEL FILTER
	1	2DD; INJECTORS 6 PAK
	1	NONSTOCK; FREIGHT CHARGE

Asset Work Order History 10160569

CSHOP-2018-6918

Date Opened 12-5-2018

Date Finished

4-25-2019

Meter 1 Reading:

64,771

TASKS PERFORMED

Q PARTS

WATERWAY AERIAL LADDER
AERIAL LADDER EQUIPMENT
SWIVEL AERIAL LADDER
FIRE PUMP
SENSOR
FUEL GAUGE

1 5EF; SEAL KIT WWAY
2 BK; CLR RTV SILCN SEALANT
1 5EF; WWAYMID75
-1 5EF; WWAYMID75
1 5EF; WWAYMID75
-1 5EF; WWAYMID75
1 5EF; WWAYMID75
1 5EF; WWAYFLY75
-1 5EF; WWAYFLY75
1 5EF; WWAYFLY75
-1 5EF; WWAYFLY75
1 9AP; CYLINDER REBUILD
1 5EF; WWAYFLNGESEAL
1 5EF; WWAYFLY75
1 5EF; SEAL KIT WWAY
1 5EF; FLANGEWAY
1 5EF; RELIFE VALVE
1 FRT
1 5EF; LOADMINDER W DISPLAY
1 5EF; LOADMINDER W DISPLAY
-1 5EF; LOADMINDER W DISPLAY
1 BK; SNAP RING KIT
1 NW; FUSE HOLDER
2 5EF; FUEL SENDING UNIT

CSHOP-2019-1263

Comments: **QC INSPECTION**

Date Opened 3-9-2019

Date Finished

3-11-2019

Meter 1 Reading:

64,767

TASKS PERFORMED

NO PARTS USED

QUALITY CHECK-REPAIRS

CSHOP-2019-1684

Date Opened 4-1-2019

Date Finished

5-23-2019

Meter 1 Reading:

64,771

TASKS PERFORMED

Q PARTS

WATERWAY AERIAL LADDER

1 BK; CLR RTV SILCN SEALANT
1 5AB; 2.5" BALL VALVE KIT SS

CSHOP-2019-293

Comments: **ANNUAL UL AERIAL AND GROUND LADDER TEST**

Date Opened 1-15-2019

Date Finished

1-26-2019

Meter 1 Reading:

64,767

TASKS PERFORMED

NO PARTS USED

UL AERIAL TESTING

VENDOR? MISTRAS GROUP INC

Asset Work Order History 10160569

CSHOP-2019-3133

Comments: **PRE TRIP AND TEST WATERWAY RELIEF VALVE**

Date Opened 6-18-2019 Date Finished 6-25-2019 Meter 1 Reading: 64,817

CHECK RELIEF ON WATER WAY

TASKS PERFORMED

Q PARTS

WATERWAY AERIAL LADDER

1 8HD; CARABINER 14X38 SS

CSHOP-2019-3150

Comments: **ALSO HAD TROUBLE BEDDING LADDER HAD TO USE MANUAL OVERRIDE WE NEED THIS LOOKED AT AS SOON AS YOU CAN PLEASE**

Date Opened 6-18-2019 Date Finished 7-3-2019 Meter 1 Reading: 64,817

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
LADDER RACK BODY
DOME LIGHTS
REAR WINDOW
CAB-INTERIOR ACCESSORIES
HVAC SYSTEM

3 GRO; STEPWELL LICENSE LAMP
1 9AP; RED LED
1 2IH; REGULATOR
1 TWD; TRINSWI
1 2RD; FILTER, 17.5X5.5, MASTER PK (2)

CSHOP-2019-3286

Comments: **CAB A/C WARM**

Date Opened 6-24-2019 Date Finished 6-24-2019 Meter 1 Reading: 64,817

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

CSHOP-2019-341

Comments: **UL TEST INCLUDING GROUND LADDERS**

Date Opened 1-19-2019 Date Finished 1-19-2019 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

UL AERIAL TESTING

VENDOR? MISTRAS GROUP INC

CSHOP-2019-3469

Date Opened 7-3-2019 Date Finished 8-22-2019 Meter 1 Reading: 65,057

UL DRIFT TEST FOUND OIL ON OUTRIGGER PAD

TASKS PERFORMED

NO PARTS USED

OUTRIGGERS/STABILIZERS

Asset Work Order History 10160569

CSHOP-2019-3550

Date Opened 7-9-2019 Date Finished 8-12-2019 Meter 1 Reading: 65,057

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
LADDER RACK BODY
HEADLIGHTS HIGH BEAM
QUARTZ LIGHT

1 5SC; LDR HNDL ZIA 3096005910 13.75
1 9ME; LAS975HANDLEASSY
2 9AP; HALOGENLAMP
1 9AP; SWITCH - ROCKER FOR UNITY LIGHT
1 LMP; LAMP
1 9AP; BULB, 750W 120V HALOGEN

Service Requests:

- 07/08/2019 LIGHTS / 12: BROKEN / REPAIR
VEHICLE LIGHTS NOT WORKING- 1.DRIVER SIDE HIGH BEAM LIGHT NOT WORKING, 2. OIC SIDE TELE-LIGHT AND 3. AERIAL BASE LIGHTS NOT WORKING 2. & 3. RUNS ON GENERATOR, AND 4. DRIVER SIDE REAR SCENE LIGHT NOT WORKING.
- 07/08/2019 SERVICE REQUEST / 12: BROKEN / REPAIR
THERE IS NO WAY TO SECURE ROOF LADDER IN BRACKET ON THE AERIAL. THERE USE TO BE A SPRING ACTUATING GUARD, BUT IT IS NOT THERE ANY MORE.
- 07/08/2019 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / INSPECT
WE HAD TO BORROW THE 15 SIGNS OF B15 OUR BRUSH TRUCK, CAN WE REQUEST 2 NEW 15 SIGNS FOR WHEN L15 IS IN A SPARE?

CSHOP-2019-358

Date Opened 1-21-2019 Date Finished 3-11-2019 Meter 1 Reading: 64,767

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AERIAL EQUIPMENT FIRE APPARATUS

Service Requests:

- 01/19/2019 SERVICE REQUEST / 12: BROKEN / REPAIR
JACK ON THE OFFICERS SIDE IS "STICKING". AS I TRY TO EXTEND THE ARM, IT JERKS AND STOPS AT ABOUT A FOOT. IT WILL NO LONGER GO OUT OR BACK IN UNTIL I LOWER THE JACK TO THE GROUND TO THE POINT OF RAISING THE TRUCK SLIGHTLY. AT THAT POINT, AND NOT EVERY TIME, I CAN RAISE THE JACK AND IT WILL START MOVING. HOWEVER IT WILL NOT ALWAYS CONTINUE TO EXTEND, ONLY RETRACT. ALSO, HYDRAULIC FLUID LIGHT IS IN THE YELLOW "OK", NOT THE GREEN "FULL".

CSHOP-2019-3647

Date Opened 7-14-2019 Date Finished 8-8-2019 Meter 1 Reading: 65,057

TASKS PERFORMED

Q PARTS

HVAC SYSTEM

1 5EO; BLOWERMOTOROFFICERSSIDEDASH
1 9AM; DUCT
1 TEM; RESISTER
1 9HC; COILCLEANER128OZ
1 5SC; BRILLOSTYLEFILTERAC
1 TEM; EXPANSION VALVE

Asset Work Order History 10160569

CSHOP-2019-3772

Comments: **SPARE LADDER AT STATION 15**

Date Opened 7-22-2019 Date Finished 8-12-2019 Meter 1 Reading: 65,057

TASKS PERFORMED

Q PARTS

OUTRIGGERS/STABILIZERS
DOOR LATCH
FUEL TANK
QUARTZ LIGHT
UPHOLSTERY

1 9HY; OUTRIGGERREUBILDS
2 9HW; TYWRAP38200PK
10 9HY; FITTING
170 9HY; HOSEHYD6
12 9AP; BRAKECLEAN
4 9HY; FITTING90
2 9HY; FITTING90DEG
1 9AP; BULB750W120VHALOGEN
1 9AP; BULB
1 2FR; GASKET
1 2FR; POWERCORDFRCOPTIMUM

Service Requests:

- 07/21/2019 SERVICE REQUEST / 18: LEAKING / REPAIR
WHEN THE TRUCK IS FUELED IT WILL OVERFLOW FROM SOMEWHERE UNDER THE TRUCK IN THE BACK AND DUMPS DIESEL ON THE GROUND. WE CAN PROBABLY LIVE WITH THIS UNTIL WE GET OUR REGULAR TRUCK BACK, BUT NEEDS ADDRESSED.
- 07/21/2019 SERVICE REQUEST / 18: LEAKING / EXCHANGE - REBUILT
NOTICED A SMALL HYDRAULIC LEAK ON TURN TABLE ON TOP CENTER COVER.
- 07/21/2019 SERVICE REQUEST / 19: LOOSE / REPAIR
FIREFIGHTER'S DOOR IS BROKEN AGAIN AND THE FIRE FIGHTER CAN NOT OPEN THE DOOR FROM INSIDE THE TRUCK.
- 07/21/2019 SERVICE REQUEST / 35: RUSTED/CORRODED / INSPECT
NOTICED RUSTY AERIAL LADDER COMPONENTS, THAT NEED REPORTED
- 07/21/2019 SERVICE REQUEST / 40: STRIPPED / EXCHANGE - NEW
PASSENGER SIDE TELE-LIGHT NOT WORKING. ONLY LIGHT NOT WORKING ON GENERATOR.

CSHOP-2019-3821

Date Opened 7-23-2019 Date Finished 7-29-2019 Meter 1 Reading: 65,057

TASKS PERFORMED

NO PARTS USED

DOOR LATCH

Service Requests:

- 07/23/2019 SERVICE REQUEST / 19: LOOSE / REPAIR
FIREFIGHTER DOOR BEHIND DRIVER WILL NOT OPEN FROM THE INSIDE AND IS DIFFICULT TO OPEN FROM THE OUTSIDE

CSHOP-2019-4406

Comments: **PASSED UL TEST 8-19-19 WAITING ON INVOICE**

Date Opened 8-20-2019 Date Finished 8-23-2019 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

UL AERIAL TESTING

VENDOR? MISTRAS GROUP INC

Asset Work Order History 10160569

CSHOP-2019-4582

Date Opened 8-27-2019 Date Finished 9-21-2019 Meter 1 Reading: 0

TASKS PERFORMED

Q PARTS

REPAIR FROM PM - DECALS/CLEANLINESS

1 9EM; SIGNAGE 10160569

CSHOP-2019-4638

Date Opened 8-30-2019 Date Finished 10-31-2019 Meter 1 Reading: 65,057

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
WATER TANK LEVEL LIGHTS
CAB TILT PUMP
DIAGNOSE ELECTRICAL
BRAKES
AIR DRIER

1 1WL; LIGHT 18 LED STRIP
1 1WL; LIGHT, 18 LED STRIP
-2 1WL; LIGHT, STRIP TANK STATUS
2 1WL; LIGHT, STRIP TANK STATUS
1 2DD; DELTA P SENSOR
-1 2CU; SENSOR DFN PRESSURE
1 2CU; SENSOR DFN PRESSURE
2 1AM; CALIPERS MERITOR
1 9HD; HOSE FITTINGS
1 FIL; NAPAGOLD AIR FILTER
1 TWD; VALVE KT
-1 TWD; VALVE KT
1 TWD; PURGE VALVE ASSY KIT
2 9HD; WHEELS SOLID HAND TRK
-1 TWD; PURGE VALVE KIT
1 TWD; PURGE VALVE KIT

CSHOP-2019-5096

Date Opened 9-27-2019 Date Finished 10-31-2019 Meter 1 Reading: 65,057

TASKS PERFORMED

NO PARTS USED

PM SERVICE C

CSHOP-2020-1034

Date Opened 2-23-2020 Date Finished 2-24-2020 Meter 1 Reading: 65,350

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE PUMP

Asset Work Order History 10160569

CSHOP-2020-1044

Date Opened 2-24-2020 Date Finished 4-8-2020 Meter 1 Reading: 65,588

TASKS PERFORMED

	Q	PARTS
AERIAL LADDER EQUIPMENT	1	6ZA; STRAP 16 25
BODY - WORK COMPARTMENT EMER	1	5AH; D RING LATCH
FIRE PUMP	1	MBI; DASH FAN
ELECTRIC FAN		
DOOR		
FUEL GAUGE		

Service Requests:

- 02/03/2020 SERVICE REQUEST / 19: LOOSE / INSPECTED CHECKED TERMINALS TESTED NO ISSUES FOUND FUEL GAGE NOT WORKING
- 02/14/2020 BODY / 12: BROKEN / EXCHANGE - NEW REPLACED HANDLE ASSEMBLY BODY ISSUE, BROKEN HANDLE AND LATCH TO FRONT BUMPER HOSE COMPARTMENT. LITERALLY BROKE COMPLETELY OFF. COMPARTMENT LID ONLY HELD DOWN BY ITS OWN WEIGHT.
- 02/18/2020 SERVICE REQUEST / 10: BENT / REPAIRED BENT DOOR LATCH ROD DRIVERS SIDE PASSENGER DOOR CAN NOT BE OPENED/EXTREMELY DIFFICULT FROM OUTSIDE.
- 02/23/2020 SERVICE REQUEST / 19: LOOSE / INSPECTED TESTED COULDNT DUPLICATE DIFFICULT TIME GETTING LADDER TRUCK INTO PUMP. COULD NOT DECREASE THE PRESSURE, ONLY BY HITTING IDOL.

CSHOP-2020-1355

Comments: **WILL GET WITH NORRIS FOR MORE INFO / DANNY IS GOING TO WORK ON THIS NOW SEVERAL OPEN WORK ORDERS 3-25-2020**

Date Opened 3-7-2020 Date Finished 3-25-2020 Meter 1 Reading: 0

TASKS PERFORMED

	Q	PARTS
FIRE PUMP	1	5CS; CAPTAIN GOV KIT
	1	5HP; 5HP
	1	5CS; 5CS
	1	9IP; 9IP
	1	5HP; 5HP

CSHOP-2020-1405

Date Opened 3-9-2020 Date Finished 3-12-2020 Meter 1 Reading: 0

TASKS PERFORMED

	Q	PARTS
TRAVEL TO BE CHARGED TO WORK ORDER ANTIFREEZE	6	NBH; V BELT

Asset Work Order History 10160569

CSHOP-2020-1409

Comments: **SPARE LADDER AT 29**

Date Opened 3-10-2020

Date Finished 4-27-2020

Meter 1 Reading: 65,695

TASKS PERFORMED

NO PARTS USED

EGRESS TIP AERIAL LADDER FLY
VENDOR TIRE REPAIR/CHANGE

Service Requests:

03/09/2020 SERVICE REQUEST / 12: BROKEN / INSPECT
NOZZLE ON THE LADDER WILL NOT GO UP AND DOWN.

03/10/2020 SERVICE REQUEST / 12: BROKEN / INSPECT
FAN INSIDE CAB HANGING FROM WIRE BRACKET APPEARS TO BE RUSTED.

CSHOP-2020-1964

Comments: **SPARE LADDER AT 15 CHECK FRONT END AFTER RETURN FROM ST15 SEEMS TO BE A PROBLEM WITH FRONT SPRINGS**

Date Opened 4-13-2020

Date Finished 4-29-2020

Meter 1 Reading: 65,695

FRONT END BOUNCES

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
QUALITY CHECK-REPAIRS
AERIAL EQUIPMENT PEDESTAL FIR
FRONT SPRING

1 8AM; STROBE

Service Requests:

04/12/2020 ALARMS / 12: BROKEN / REPAIR
ALARM SIGNALS- DRIVER SIDE LOADMINDER WARNING LIGHT ON AERIAL IS BROKEN NEEDS REPLACED.

CSHOP-2020-222

Comments: **SPARE LADDER AT 29**

Date Opened 1-14-2020

Date Finished 1-24-2020

Meter 1 Reading: 65,115

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
ELECTRICAL
TIRE

1 BK; PWR OUTL
1 NCB; BLASTER PENETRANT
1 9IP; 13 3052 NUT
2 9IP; AMH 1 VALVE EXTENSION
12 1CH; BRAKE CLEANER MOPAR

Service Requests:

01/14/2020 SERVICE REQUEST / 23: NOT CONNECTED / EXCHANGE - NEW
NO POWER POINT TO CHARGE EQUIPMENT / SAFETY PAD

Asset Work Order History 10160569

CSHOP-2020-2396

Comments: **ORDERED WHEEL FOR STOCK WHEEL IS HERE WILL SEND TO CALLAGHAN TO MOUNT SPARE**

Date Opened 5-5-2020 Date Finished 5-14-2020 Meter 1 Reading: 0

TASKS PERFORMED

Q PARTS

TIRES & WHEELS

1 5EF; 3PC WHEEL STEEL 24X8 5 10 HOLE

CSHOP-2020-2652

Comments: **SPARE LADDER AT 57----AC WAS REPAIRED AT SOUTH SHOP**

Date Opened 5-19-2020 Date Finished 6-10-2020 Meter 1 Reading: 65,817

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE
HVAC SYSTEM

VENDOR? DAN CALLAGHAN ENTERPRISES

Service Requests:

- 05/19/2020 A/C / 18: LEAKING / REPAIR
A/C ISSUE- A/C NOT BLOWING COLD. CAUSING WINDSHIELD TO FOG DURING RAIN STORM
- 05/27/2020 A/C / 18: LEAKING / REPAIR
A/C ISSUE- FRONT A/C BLOWING HOT
- 05/30/2020 A/C / 18: LEAKING / REPAIR
A/C ISN'T COOLING FRONT CAB.

CSHOP-2020-300

Comments: **ON CALL REPAIR CK WATERWAY CONTROL INOP**

Date Opened 1-19-2020 Date Finished 1-27-2020 Meter 1 Reading: 65,096

TASKS PERFORMED

NO PARTS USED

FIRE PUMP CONTROLS

CSHOP-2020-3150

Comments: **AIR CONDITIONING LEAKS OUT VERY QUICKLY**

Date Opened 6-15-2020 Date Finished 7-1-2020 Meter 1 Reading: 65,837

AC INOP.

TASKS PERFORMED

Q PARTS

- QUALITY CHECK-REPAIRS 1 9AP; HAND SOAP PUM TOTAL TRK
- FREON REORDER 16 9HD; 1X1X3 4 TURTLE
- STORAGE CABINET EMERGENCY VEH 1 9ES; BULB 750W 120AC EIKO
- CAB TILT PUMP 1 CRC; FOAMING COIL CLEANER
- COOLING SYSTEM 1 5AH; 10MM BALL STUD
- LIGHTING SYSTEM 1 5SC; ROM DOOR SWITCH 5WIRE
- GRILLE 1 TWD; TRINSWI
- DOOR 1 TWD; AC DRIER
- DOOR ALARM OR OTHER WARNING
- A/C FILTER
- HVAC SYSTEM

Asset Work Order History 10160569

CSHOP-2020-3801

Date Opened 7-22-2020 Date Finished 7-22-2020 Meter 1 Reading: 65,838

NEEDS A QC

TASKS PERFORMED

NO PARTS USED

QUALITY CHECK-REPAIRS

CSHOP-2020-4328

Date Opened 8-20-2020 Date Finished 11-10-2020 Meter 1 Reading: 65,838

HEAD LIGHT INOP.

TASKS PERFORMED

Q PARTS

HYDRAULIC CYLINDER EXTENSION
MOTOR
SPOT LIGHTS
HEADLIGHTS HIGH BEAM

1 9HD; 9HD
1 9HD; 9HD
1 9HD; 9HD
1 9HD; 9HD
1 5EF; MOTOR ROSS
1 5EO; KIT SEAL ORING BRAKE
1 8HD; 4 PACK 2032 BATTERY
-1 5EO; KIT SEAL ORING BRAKE
1 9HD; TAPE BLUE 1 5
1 LMP; LAMP

CSHOP-2020-452

Date Opened 1-28-2020 Date Finished 2-24-2020 Meter 1 Reading: 65,350

TASKS PERFORMED

NO PARTS USED

HYDRAULIC SYSTEM

Service Requests:

01/28/2020 SERVICE REQUEST / 18: LEAKING / REPAIR
LADDER HYDROLIC LEAK

CSHOP-2020-470

Comments: **ORDERED FROM NAPA**

Date Opened 1-29-2020 Date Finished 4-6-2020 Meter 1 Reading: 0

TASKS PERFORMED

Q PARTS

REGULATOR

1 9HY; MAKO FITTINGS

CSHOP-2020-5352

Comments: **UNIT WILL COME BACK FOR PM FOLLOW UP AND AT A LATER DATE**

Date Opened 10-10-2020 Date Finished 11-18-2020 Meter 1 Reading: 65,838

TASKS PERFORMED

NO PARTS USED

PM SERVICE C AERIAL

Asset Work Order History 10160569

CSHOP-2020-6297

Date Opened 12-3-2020 Date Finished 12-16-2020 Meter 1 Reading: 65,842

TASKS PERFORMED

Q PARTS

LADDER INSPECTION
WIPERS-WASHER
LIGHTING SYSTEM
BRAKES
CAB FANS

2 1AN; WIPER BLADE
2 5SC; WIPER NOZZLE
1 9IP; CLEARANCE LITE LED
1 1WL; 600 SERIES LED LOOSE LEAD
3 GRO; LED
5 LIT; LED M C LAMP
-4 LIT; LED M C LAMP
2 PTX; PERMATEX
1 9IP; 9IP
-2 NOS; OIL SEAL
-20 TWD; NUT
1 FREIGHT
2 NOS; OIL SEAL
20 TWD; NUT
2 MBI; DASH FAN

CSHOP-2020-6486

Date Opened 12-11-2020 Date Finished 12-14-2020 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE APPARATUS

Service Requests:

12/11/2020 SERVICE REQUEST / 12: BROKEN / REPAIR
SPARE LAD15 HAD AN OIL LEAK COME FROM SOMEWHERE BY THE FIRE PUMP, ALSO NO LIGHT ON WATER LEVEL
PUMP PANEL

CSHOP-2020-65

Date Opened 1-6-2020 Date Finished 1-13-2020 Meter 1 Reading: 65,077

STEERING IS NOT STRAIGHT WHEN DRIVING & HORN INOP.

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
FIRE PUMP PLUMBING
STEERING WHEEL

1 9AP; HAND SOAP PUM TOTAL TRK

Asset Work Order History 10160569

CSHOP-2020-688

Comments: @ST 29

Date Opened 2-6-2020

Date Finished 2-13-2020

Meter 1 Reading: 65,286

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
AUTO-EJECT

1 6KU; AUTO EJECT

Service Requests:

02/06/2020

SERVICE REQUEST / 12: BROKEN / REPLACED

AUTO EJECT PLUG IN FOR LADDER NOT EJECTING UPON START UP.

CSHOP-2020-769

Comments: SPARE LADDER AT 29

Date Opened 2-10-2020

Date Finished 2-18-2020

Meter 1 Reading: 65,316

TASKS PERFORMED

Q PARTS

AERIAL EQUIPMENT FIRE APPARATUS

1 9ES; SWITCH E STOP PUSH BUTTON

Service Requests:

02/10/2020

SERVICE REQUEST / 12: BROKEN / REPLACED

HYDRAULIC SYSTEM LOCK PULL SWITCH BROKEN ON UPPER AERIAL CONTROLS, RED PLASTIC PULL SWITCH BROKEN OFF FROM INSIDE OF SWITCH. NOT ABLE TO ENGAGE AERIAL POWER TO THE LADDER PROPERLY

CSHOP-2020-885

Date Opened 2-15-2020

Date Finished 3-9-2020

Meter 1 Reading: 65,480

TASKS PERFORMED

Q PARTS

STARTER

1 2PR; STARTER SOLENOID EONE PRESTOLITE
1 1AD; STARTER NEW 12 TOOTH 38MT 12V
1 TWD; STARTER, 39MT 12V
1 2PR; STARTER SOLENOID EONE PRESTOLITE

CSHOP-2021-1019

Date Opened 2-23-2021

Date Finished 2-24-2021

Meter 1 Reading: 65,843

TASKS PERFORMED

NO PARTS USED

PRIMING PUMP FIRE PUMP

Service Requests:

02/23/2021

SERVICE REQUEST / 12: BROKEN / OVERHAUL

PRIMER IS NOT WORKING. UNABLE TO PUMP TEST.

Asset Work Order History 10160569

CSHOP-2021-1543

Comments: CHECK FOR BRAKE ISSUE. IT WAS REPORTED THAT THE BRAKES DO NOT STOP PROPERLY NEED TO PUMP TEST AFTER BRAKE REPAIR

Date Opened 3-22-2021 Date Finished 5-6-2021 Meter 1 Reading: 65,858

AIR BAG LIGHT ON

TASKS PERFORMED

Q PARTS

BRAKES
INSTRUMENT CLUSTER

2 9HD; CABLE ADAPTER
1 6LP; HOSES CUSTOM MAKO
-2 TWD; BRK CHAM
2 TWD; BRK CHAM
1 FREIGHT
1 9HD; VALVE ABS 3
2 MBI; MBI
2 2IH; ADJUSTER SLACK MERITIR A3275S1059
3 2FL; MINI BULB ASSEMBLY

CSHOP-2021-1772

Comments: DON`T THINK THIS HAD THE OIL AND FILTERS DONE ALSO, CHECK WHEN IT HAD IT`S LAST LADDER INSPECTION

Date Opened 4-5-2021 Date Finished 4-9-2021 Meter 1 Reading: 65,858

AIR DRIER NEEDS TOBE SER.

TASKS PERFORMED

Q PARTS

FILTER
OIL FILTER
BATTERY
FLUID
AIR DRIER

1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPAGOLD FUEL FILTER
2 FIL; NAPAGOLD OIL FILTER
40 4PC; 15W40 PREMIUM BLUE OIL
1 9AP; OIL SAMPLE TEST KIT PETRO CANADA
6 1AD; 1000 CCA 31 SERIES BATTERY
1 FIL; NAPAGOLD AIR FILTER
1 TWD; PURGE VALVE ASSY KIT

CSHOP-2021-4481

Date Opened 8-9-2021 Date Finished 8-10-2021 Meter 1 Reading: 65,858

TASKS PERFORMED

NO PARTS USED

DIAGNOSE ELECTRICAL

CSHOP-2021-4570

Date Opened 8-13-2021 Date Finished 8-13-2021 Meter 1 Reading: 65,858

TASKS PERFORMED

NO PARTS USED

BATTERY

Asset Work Order History 10160569

CSHOP-2021-5195

Date Opened 9-15-2021 Date Finished 9-15-2021 Meter 1 Reading: 65,858

TASKS PERFORMED

NO PARTS USED

AERIAL LADDER EQUIPMENT

CSHOP-2021-5845

Comments: **AIR LEAK**

Date Opened 10-18-2021 Date Finished 11-18-2021 Meter 1 Reading: 65,868

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES
VENDOR TIRE REPAIR/CHANGE
AIR SYSTEM

1 FIL; NAPAGOLD AIR FILTER
1 9HD; SWITCH 745 275083
1 9EM; VALVE 1 4 SINGLE SOLENOID
1 FREIGHT
1 MBI; PURG VLV
1 TWD; E 6VALVE BRAKE
1 5HP; KIT VPS KPS PWR SHIFT AMP CNTRL

Service Requests:

10/18/2021 TIRES / 48: LOW PRESSURE / EXCHANGE - NEW
BAD TIRES. REAR TIRES NEED TO BE REPLACED.

10/18/2021 SERVICE REQUEST / 18: LEAKING / REPAIRED
QUINT HAS AN AIR LEAK AND MAY BE THE POSSIBLE CAUSE FOR THE PUMP NOT ENGAGING. PUMP NOT ENGAGING.

CSHOP-2022-1072

Date Opened 2-24-2022 Date Finished 2-25-2022 Meter 1 Reading: 65,869

TASKS PERFORMED

Q PARTS

DIAGNOSE ELECTRICAL

20 6ZA; STRAP 16 25

CSHOP-2022-1728

Date Opened 3-28-2022 Date Finished 7-13-2022 Meter 1 Reading: 65,877

TASKS PERFORMED

Q PARTS

HYDRAULIC SYSTEM
COOLING SYSTEM
ELECTRICAL

5 LIT; LED MDL 33 M C GMT KT

Asset Work Order History 10160569

CSHOP-2022-205

Date Opened 1-12-2022 Date Finished 1-18-2022 Meter 1 Reading: 65,858

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM
EMERGENCY EQUIPMENT

Service Requests:

01/12/2022 SERVICE REQUEST / 18: LEAKING / REPAIR
LEVERS TO CONTROL THE AERIAL ARE LOOSE ON THE TURN TABLE.

CSHOP-2022-350

Comments: TRAINING LADDER WON`T START

Date Opened 1-20-2022 Date Finished 1-20-2022 Meter 1 Reading: 65,869

TASKS PERFORMED

NO PARTS USED

BATTERY

CSHOP-2022-3633

Date Opened 7-7-2022 Date Finished 7-8-2022 Meter 1 Reading: 65,877

TASKS PERFORMED

NO PARTS USED

EMERGENCY EQUIPMENT
BODY EXTERIOR

CSHOP-2022-3958

Date Opened 7-26-2022 Date Finished 7-26-2022 Meter 1 Reading: 65,877

TASKS PERFORMED

NO PARTS USED

EMERGENCY EQUIPMENT

CSHOP-2022-4441

Date Opened 8-25-2022 Date Finished 8-26-2022 Meter 1 Reading: 65,877

TASKS PERFORMED

NO PARTS USED

EMERGENCY EQUIPMENT

CSHOP-2022-5214

Date Opened 9-26-2022 Date Finished 9-27-2022 Meter 1 Reading: 65,877

TASKS PERFORMED

NO PARTS USED

EMERGENCY EQUIPMENT

Asset Work Order History 10160569

CSHOP-2022-5893

Date Opened 11-2-2022 Date Finished 11-3-2022 Meter 1 Reading: 65,887

TASKS PERFORMED

NO PARTS USED

INSPECTION

CSHOP-2022-5903

Comments: **PM REPAIRS**

Date Opened 11-3-2022 Date Finished 1-13-2023 Meter 1 Reading: 65,887

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS	1	9IP; AKRON MOTOR GEAR AND CONN NOZZLE
WATERWAY AERIAL LADDER	1	MAC; SILICONE SPRAY 100Z
HYDRAULIC SYSTEM	2	1AD; ENGINE SEALANT
ENGINE AND ACCESSORIES	3	9AP; AW 32
LIGHTING SYSTEM	1	9HY; METRIC OIL DUST SEAL
EMERGENCY EQUIPMENT	12	CRC; BRAKE KLEEN
BODY EXTERIOR	1	9AP; CYLINDER REBUILD
	1	8HY; 5 GAL AW32
	3	NHF; PREM AW 32 HYD FL 5G
	1	FIL; NAPAGOLD FUEL FILTER
	1	FIL; NAPAGOLD FUEL FILTER
	4	LIT; LED M C LAMP
	3	LIT; LED M C LAMP
	1	PTX; PERMATEX
	1	9AP; CLEARANCE LITE LED
	1	LIT; LED FITN FORGET PLG
	1	BK; BACK UP ALARM
	1	NTH; GAUGE

CSHOP-2023-2977

Comments: **NO AIR PRESSURE**

Date Opened 6-1-2023 Date Finished 6-2-2023 Meter 1 Reading: 65,887

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM

CSHOP-2023-3223

Date Opened 6-14-2023 Date Finished 3-27-2024 Meter 1 Reading: 65,906

TASKS PERFORMED

Q PARTS

EMERGENCY EQUIPMENT	1	8AM; CG COLOR ORDORLESS CLEANER
	1	8AM; CG HEAVY DUTY SPRAY BOTTLE
	1	9AP; CARPET CLEANER
	1	8AM; CG SILK SHINE 1G

Asset Work Order History 10160569

CSHOP-2023-5161

Comments: **NO START**

Date Opened 10-4-2023

Date Finished

3-27-2024

Meter 1 Reading:

65,906

TASKS PERFORMED

Q PARTS

FIRE APPARATUS
DIAGNOSE ELECTRICAL

2 9ES; 38 1600 REPLACEMENT CABLE HARNESS 416E

CSHOP-2023-5637

Date Opened 11-1-2023

Date Finished

11-14-2023

Meter 1 Reading:

65,906

TASKS PERFORMED

NO PARTS USED

INSPECTION

Asset Work Order History 10160569

CSHOP-2023-5646

Date Opened 11-1-2023

Date Finished

2-2-2024

Meter 1 Reading:

65,906

AC inop.

TASKS PERFORMED

	<u>Q</u>	<u>PARTS</u>
EGRESS TIP AERIAL LADDER FLY	3	8GR; MOMENT ON OFF MOMEN ON 3 WIRE TOGGLE SWI
AERIAL LADDER EQUIPMENT	2	1WL; LIGHT STRIP TANK STATUS
TURNTABLE AERIAL LADDER	4	5CS; GAUGE 3 5 30 400
WATER TANK LEVEL LIGHTS	2	8AM; VDO 73 10 OHMS FUEL GAUGE
FIRE PUMP CONTROLS	1	9AP; DATCON SMART FUEL GAUGE 240 33 5 OHMS
DISCHARGE GAUGE	2	1AN; WIPER BLADE
GUIDE RAILS	1	1AN; WASHER TUBING 3 32 AND 7 64
HYDRAULIC SYSTEM	-2	5SC; WIPER NOZZLE
WIPERS-WASHER	2	5SC; WIPER NOZZLE
FILTER	2	8AM; SPARGUE DEVICES GW103 NOZZLE
REPAIR FROM PM - GENERATOR	1	FIL; NAPAGOLD FUEL FILTER
OIL FILTER	1	FIL; NAPAGOLD FUEL FILTER
MULITFUNCTION SWITCH	1	FIL; NAPAGOLD FUEL FILTER
HEADLIGHTS LOW BEAM	1	FIL; NAPA HYDRAULIC FILTER
LIGHTING SYSTEM	1	FIL; NAPAGOLD AIR FILTER
BATTERY	2	8HD; 1 GANG BLANK COVER SILVER
AUTO-EJECT	1	FIL; NAPAGOLD FUEL FILTER
FLUID	2	8HD; L150 3 4 STRAIGHT NM FITTING
FILTER	1	FIL; NAPAGOLD OIL FILTER
DIFFERENTIAL	2	8HD; BOX 1 GANG 4 HOLE 3 4
SUSPENSION	2	8HD; L120 3 4 90 FITTING
RESERVOIR	2	FIL; NAPAGOLD OIL FILTER
CAB & BODY MOUNT	36	4PC; 15W40 PREMIUM BLUE OIL
AIR DRIER	1	9AP; OIL ANALYSIS TEST
STROBE LIGHTS	1	5EO; FERRARA STEERING WHEEL
SIREN	2	8AM; H4656BL SYLVANIA LIGHT
CAB-INTERIOR ACCESSORIES	2	8AM; H4651 SYLVANIA LIGHT
BACK UP CAMERA-MONITOR	2	LIT; LAMP
HVAC SYSTEM	8	6WL; LIGHT CLR LED PUMP PNL
	10	GRO; LAMP
	1	9AP; LED LIGHT
	2	LIT; GROMMET
	-2	LIT; GROMMET
	10	LIT; GROMMET
	6	1AD; 1000 CCA 31 SERIES BATTERY
	1	6KU; AUTO EJECT W STD YEL CVR
	35	9OC; BULK TRANS SYN
	1	2DD; FILTER KIT TRANS SUMP 4
	4	9OC; BULK TRANS SYN
	1	FIL; NAPA HYDRAULIC FILTER
	1	TWD; PURGE VALVE ASSY KIT
	1	2TP; KIT PURGE VALVE
	1	1FG; FILTER AIR BRAKE 4374
	-1	2TP; KIT PURGE VALVE
	3	1WL; WHELEN 600 SERIES
	1	8GR; FOOT SWITCH HORN SIREN
	3	1WL; LIGHT 18 LED STRIP
	1	5FF; PASS SEAT BELT
	1	BK; BACK UP ALARM

Asset Work Order History 10160569

CSHOP-2023-5743

Comments: **ANNUAL LADDER INSPECTION**

Date Opened 11-7-2023 Date Finished 1-10-2024 Meter 1 Reading: 65,906

need annual ladder inspection

TASKS PERFORMED

Q PARTS

INSPECTION

4 CRC; CHAIN WIRE ROPE LUBE
2 CRC; CHAIN WIRE ROPE LUBE
2 CRC; CHAIN WIRE ROPE LUBE
1 MAC; SILICONE SPRAY 100Z

CSHOP-2024-1166

Date Opened 3-2-2024 Date Finished 3-2-2024 Meter 1 Reading: 65,906

TASKS PERFORMED

NO PARTS USED

SURPLUS PREP

RADIO-2016-382

Comments: **PROGRAMMED, TESTED, AND DELIVERED A REPLACEMENT PAGER TO ST15.**

Date Opened 6-27-2016 Date Finished 7-5-2016 Meter 1 Reading: 61,418

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
RADIO

Service Requests:

06/25/2016 PAGER ISSUE / /
L-15 DRIVERS PAGER SCREEN IS NOT SHOWING ANYTHING. IT LIGHTS UP BUT DOESN'T SHOW ANY OTHER
FUNCTIONS

RADIO-2018-848

Comments: **REMOVE 10141661, INSTALL 10204815 INTO SPARE LADDER 2 PARTS UH-51 X2**

Date Opened 7-26-2018 Date Finished 7-27-2018 Meter 1 Reading: 0

TASKS PERFORMED

Q PARTS

MOBILE RELATED

2 UH51; UH51

Service Requests:

07/26/2018 RADIO / /
REMOVE AND INSTALL MOBILE RADIO IN SPARE LADDER 2

Asset Work Order History 10160569

RADIO-2020-48

Comments: PARTS REQUESTED: 1 EA. 9ES UH51 HEADSET REPLACED OIC POSITION HEADSET. INSPECTED AND TESTED THE DO AND FF HEADSETS. BOTH WERE IN GOOD SHAPE AND FUNCTIONING NORMALLY.

Date Opened 1-15-2020 Date Finished 1-15-2020 Meter 1 Reading: 0

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER INTERCOM SYSTEM - EMERGENCY V

1 9ES; HEADSET WIRED FIRECOM CONTROL COMM

Service Requests:

01/15/2020 RADIO / /
RADIO ISSUES CAPTAIN'S HEADSET IS FALLING APART. BARE WIRE IS ALL THAT IS LEFT AND UNLESS MIC IS INSIDE YOUR MOUTH GUYS CANT HEAR ME .ALL INSULATION AND SHEATHING GONE ON THE WIRE TO THE HEADSET.

SSHOP-2020-171

Date Opened 6-2-2020 Date Finished 6-9-2020 Meter 1 Reading: 65,811

TASKS PERFORMED

Q PARTS

COOLING SYSTEM

3 FLUID; COOLANT ANTIFREEZE GAL
3 PAF; ANTIFRZ
3 9OC; BULK COOLANT SOUTH SHOP
-3 9OC; BULK COOLANT SOUTH SHOP

SSHOP-2020-174

Date Opened 6-4-2020 Date Finished 6-4-2020 Meter 1 Reading: 65,797

TASKS PERFORMED

NO PARTS USED

HURST TOOL CUTTERS
