10200922

Palm Beach County Fleet Management Asset Maintenance History 2016 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Total Hours: 89.50 Labor: 6,221.00 Parts: 2,554.21 Comm: 0.00 Charged: 8775.21 Work Order: 1603261 Meter: 1 03/29/2016 **Closed:** 03/31/2016 In Date: Problem: install hitch ext **Work Completed Parts Issued** Quantity Ball Mount 3/4" 1.00 - Install hitch & extention 1.00 Receiver Extension - Shop Supplies Pin W/clip 5/8 For Hitch 2.00 **Shop Supplies** 1.00 Hours: 0.50 Comm: 0.00 Labor: 30.00 Parts: 119.50 Total: 149.50 Work Order: 1603292 Meter: 1 In Date: 03/29/2016 **Closed**: 03/29/2016 Problem: 1061 - Pre Delivery Inspection **Work Completed** - Pre Delivery Inspection Hours: 2.00 Total: 120.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Work Order: 1702657 Meter: 404 In Date: 03/15/2017 **Closed:** 05/15/2017 Problem: P.M.SERVICE

| Work Completed | | Parts Issued | | Quantity |
|--|------------|--------------------|---------------|---------------|
| - Pm Service. | | Napagold Air Filte | er | 1.00 |
| Service all drive trainrear and front diff and transfer case. | | Fuel Filter | | 1.00 |
| - Wash equipment. | | Napagold Oil Filte | r | 1.00 |
| - Return to Hector for warranty repair on rear differential locker assmfound | | 15w40 Bulk South | Reg | 4.00 |
| bad rear upon inspection. | | Mobil 424 Fluid | | 4.00 |
| - Shop Supplies | | Locking Diff Fluid | Cc Only | 4.00 |
| | | Shop Supplies | | 1.00 |
| Hours: 8.00 | Comm: 0.00 | Labor: 480.00 | Parts: 187.64 | Total: 667.64 |

10200922

Palm Beach County Fleet Management Asset Maintenance History 2016 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Work Order: 1806520 Meter: 938 In Date: 06/26/2018 Closed: 07/03/2018

Problem: pm service

| Work Completed | | Parts Issued | | Quantity |
|--------------------------------------|------------|---------------------|---------------|---------------|
| - pm with drive train service | | 15-40 Oil | | 4.00 |
| - replace rear lateral link bushings | | Napagold Oil Filter | | 1.00 |
| - wash equipment | | Napagold Air Filter | | 1.00 |
| - Shop Supplies | | Napa Fuel Filter | | 1.00 |
| | | Mobil 424 Fluid | | 4.00 |
| | | Upper Sleeve | | 2.00 |
| | | Arm Bushing | | 4.00 |
| | | Arm Bushing | | 4.00 |
| | | Inner Sleeve | | 4.00 |
| | | Shop Supplies | | 1.00 |
| Hours: 8.00 | Comm: 0.00 | Labor: 480.00 | Parts: 102.20 | Total: 582.20 |

Work Order: 1901425 Meter: 1202 In Date: 02/06/2019 Closed: 03/06/2019

Problem: stalls out like its getting no fuel

| Work Completed | Parts Issued | Quantity |
|---|---------------|----------|
| - Test fuel, tank, filter & solenoid for contamination; test run multiple times | Shop Supplies | 1.00 |
| - N.p.fi | | |

- N,p,II - Shop Supplies

Hours: 3.00 Comm: 0.00 Labor: 201.00 Parts: 3.00 Total: 204.00

10200922

Palm Beach County Fleet Management Asset Maintenance History 2016 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Work Order: 1907895 Meter: 1202 In Date: 07/31/2019 Closed: 08/19/2019

Problem: PM Service. Shifter cable broken.

| Work Completed | | Parts Issued | | Quantity |
|--|--|---------------------|---------------|---------------|
| - Pm Service. | Napagold Air Filter | | 1.00 | |
| - Replace shifter cable and lever on transaxle.tighten bra | Napa Fuel Filter 15w40 Bulk South Reg Napagold Oil Filter Trans Shift Cable | | 1.00 | |
| Service cooling system.flush system.add coolant and clean reservoir. Service drive train.change fluid in transaxle front and rear diffs. Wash equipment. | | | 4.00 | |
| | | | 1.00 | |
| | | | 1.00 | |
| - Shop Supplies | | 1gal Rtu Antifreeze | | 2.00 |
| | | Bell Crank | | 1.00 |
| | | Shop Supplies | | 1.00 |
| Hours: 9.00 | Comm: 0.00 | Labor: 603.00 | Parts: 170.33 | Total: 773.33 |

Work Order: 2009273 Meter: 1996 In Date: 09/16/2020 Closed: 09/30/2020

Problem: PM Service.

| Work Completed | | Parts Issued | Quantity |
|---|------------|-----------------------------|---------------|
| - Pm Service. | | Napagold Air Filter | 1.00 |
| - Drive train service front and rear differentials. | | Napa Fuel Filter | 1.00 |
| - Replace E-brake caliper assembly. | | 15w40 Bulk South Reg | 4.00 |
| - Replace battery.install proper brackets. | | Napagold Oil Filter | 1.00 |
| - Wash equipment. | | Caliper Mech Park Brake | 1.00 |
| - Shop Supplies | | 3/8 Ss Split Washer | 2.00 |
| | | 3/8-16 Ss Screw | 2.00 |
| | | 5/16-18 Locknut | 1.00 |
| | | 5/16-18 Hex Cap Screw | 1.00 |
| | | Battery Clamp | 1.00 |
| | | Battery | 1.00 |
| | | Shop Supplies | 1.00 |
| Hours: 8.75 | Comm: 0.00 | Labor: 638.75 Parts: 309.52 | Total: 948.27 |

10200922

Palm Beach County Fleet Management Asset Maintenance History 2016 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Work Order: 2100926 **Meter:** 1996 01/26/2021 **Closed:** 02/08/2021 In Date:

Problem: Drive shaft broken

| Work Completed | | Parts Issued | | Quantity |
|--|------------|-------------------|---------------|---------------|
| - Customers complaint drive shaft broken. Replace rear drive shaft assembly. | | Rear Propshaft | | 1.00 |
| - Replace parking brake caliper assembly. | | Caliper Mech Park | Brake | 1.00 |
| - Shop Supplies | | Shop Supplies | | 1.00 |
| Hours: 3.75 | Comm: 0.00 | Labor: 273.75 | Parts: 370.99 | Total: 644.74 |
| | | | | |

Work Order: 2106290 06/09/2021 **Closed:** 06/15/2021 **Meter:** 2195 In Date:

Problem: Check and repair broken axle boots and leaking.

| Work Completed | | Parts Issued | | Qu | antity |
|---|-----------|---------------|---------------|--------|--------|
| Customers complaint front cv axle boots are bad. Remove front cv axles, grease, install new boots, reassemble front end. test drive. Shop Supplies | | Cv Boot | | | 2.00 |
| | | Cv Boot | | | 2.00 |
| | | Shop Supplies | | | 1.00 |
| Hours: 4.00 Co | omm: 0.00 | Labor: 292.00 | Parts: 175.69 | Total: | 467.69 |

Work Order: 2110128 Meter: 2258 09/17/2021 **Closed**: 09/28/2021 In Date:

Problem: PM Service.Battery dead. Suspension bushings.

| Work Completed | Parts Issued | Quantity |
|---|----------------------|----------|
| - Preventive Maint. Service | Napagold Air Filter | 1.00 |
| - Customers complaint unit will not start. recharge and test battery, failed | Fuel Filter | 1.00 |
| load test. After battery replacement, verify unit is not charging, found broken wire on alternator, repair wire. - Remove coolant lines, flush cooling system, engine, add coolant, purge air from system, test drive. | 15w40 Bulk South Reg | 4.00 |
| | Napagold Oil Filter | 1.00 |
| | Battery | 1.00 |
| - Wash equipment for service and repair. | 1gal Rtu Antifreeze | 2.00 |
| - Service front, rear diff and transaxle fluid. Remove front diff and drive shaft to access transaxle. | Shop Supplies | 1.00 |
| - Shop Supplies | | |

Hours: 10.00 Comm: 0.00 Labor: 730.00 Parts: 177.78 Total: 907.78

10200922

Palm Beach County Fleet Management Asset Maintenance History 2016 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

In Date:

10/21/2022 **Closed**: 11/16/2022

Work Order: 2113032 Meter: 2300 In Date: 12/09/2021 Closed: 12/17/2021

Problem: check driver side front wheel

Work CompletedParts IssuedQuantity- Customers complaint front end. Replace front lower suspension bushings.Lower Arm Bushing4.00- Shop SuppliesLower Arm Sleeve2.00Shop Supplies1.00

Hours: 3.00 Comm: 0.00 Labor: 219.00 Parts: 49.64 Total: 268.64

Meter: 2510

Problem: PM Service.

Work Order: 2210799

| Work Completed | | Parts Issued | | Quantity |
|---|-----------------------------|-------------------------|---------------|-----------------|
| - Preventive Maint. Service | - Preventive Maint. Service | | er | 1.00 |
| - Customers complaint Steering needs adjustment. Verify Front upper control arm and rear ladder bar bushings are bad. Replace bushings. | 15w40 Bulk South Reg | | 4.00 | |
| | bushings. | Napagold Oil Filte | r | 1.00 |
| Replace parking brake caliper assembly. Adjust parking brake.secure lines dragging. | | Fuel Filter | Fuel Filter | |
| | | Upper Sleeve | | 4.00 |
| - Shop Supplies | | Arm Bushing bushing | | 8.00 |
| | | | | 8.00 |
| | | Inner Sleeve | | 4.00 |
| | | Caliper Mech Park Brake | | 1.00 |
| | | Cabl/tie | | 1.00 |
| | | Shop Supplies | | 1.00 |
| Hours: 10.00 | Comm: 0.00 | Labor: 730.00 | Parts: 308.33 | Total: 1,038.33 |

Work Order: 2307130 Meter: 2510 In Date: 07/19/2023 Closed: 07/19/2023

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

10200922

Palm Beach County Fleet Management Asset Maintenance History 2016 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Work Order: 2307135 Meter: 2645 In Date: 07/19/2023 Closed: 07/24/2023

Problem: prepare for transfer

| Work Completed | | Parts Issued | | Quantity |
|---|------------|-------------------|---------------|---------------|
| - replace parking brake and rear brake pads | | Caliper Mech Park | Brake | 1.00 |
| - transfer tires | | 295 Rear Brake Pa | d Kit | 1.00 |
| - replace axle boot- | | L/f Inner Cv Boot | | 1.00 |
| - Shop Supplies | | L/f Outer Cv Boot | | 1.00 |
| | | Non-chlor Brake C | Inr | 2.00 |
| | | Shop Supplies | | 1.00 |
| Hours: 5.00 | Comm: 0.00 | Labor: 365.00 | Parts: 307.68 | Total: 672.68 |

Work Order: 2312012 Meter: 2674 In Date: 12/01/2023 Closed: 12/27/2023

Problem: PM Service.

| Work Completed | | Parts Issued | | Quantity |
|---|------------|--------------------------------------|---------------|---------------|
| - Preventive Maint. Service - Replaced Cracked Parking Brake Rotor | | Napa Qt 15w40 Napagold Oil Filter | | 4.00 |
| | | | | 1.00 |
| - Replaced Alternator Belt | | Fuel Filter | | 1.00 |
| - Shop Supplies | | Napagold Air Filte | er | 1.00 |
| | | Mobil 424 Fluid | | 4.00 |
| | | Rotor Park Brake | | 1.00 |
| | | V-belt | | 1.00 |
| | | Shop Supplies | | 1.00 |
| Hours: 7.50 | Comm: 0.00 | Labor: 547.50 | Parts: 113.42 | Total: 660.92 |

Work Order: 2401979 Meter: 2645 In Date: 02/23/2024 Closed: 03/07/2024

Problem: starter doesnt always engage. starter soleniod will just click sometimes and will not start. Gas pedal sticky

| Work Completed | Parts Issued | Quantity |
|--|---------------|----------|
| - Load Test Battery, Replace Bad Battery | Battery | 1.00 |
| - Replace Rear Upper Link Bushings | Arm Bushing | 8.00 |
| - Clean And Lube Pedal Group | Shop Supplies | 1.00 |
| - Shop Supplies | | |

Hours: 3.00 Comm: 0.00 Labor: 219.00 Parts: 155.85 Total: 374.85

10200922

Palm Beach County Fleet Management Asset Maintenance History 2016 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Work Order: 2402886 Meter: 2645 In Date: 03/21/2024 Closed: 03/26/2024

Problem: Transition Prep Charge

Work CompletedParts IssuedQuantity- Transition Prep ChargeShop Supplies1.00

- Shop Supplies

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 2.65 Total: 148.65

Total Hours: 89.50 Total Labor: 6,221.00 Total Comm: 0.00 Total Parts: 2,554.21