Total Hours:	193.45 Lab	oor: 13,405.00	Parts: 9,614.08	Comm: 305.10		Charged	Charged: 23324.18		
Work Order: Problem:		Meter: elivery Inspection			In Date:	07/30/2013	Closed:	07/30/2013	
Work Com	pleted								
- Pre Deliv	ery Inspectior	ı							
	Ηοι	urs: 2.00	Comm: 0.00	Labor: 120.00	Parts: 0.0	0	Total:	120.00	
Work Order: Problem:		Meter: and install four co	1630 prner strobe lights.		In Date:	03/31/2014	Closed:	04/15/2014	
Work Com	pleted			Parts Issued			Qı	antity	
- Perform	pm service.			5w20 Engine Oil				5.00	
- Fabricate	e and install fo	our corner Led stro	be lamps into head lamps and tail	Napagold Oil Filter				1.00	
lamps.mak	e up and insta	ll wiring harness v	vith fusable link and switch.	Washer Fl				1.00	
- Rotate a	nd balance all	four tires.		Vtx609a Led Strobe A	۸m			2.00	
- Shop Su	pplies			Vtx609c Led Strobe C				2.00	
				Fuse Holder				1.00	
				Switch				1.00	
				Clr Rtv Silcn Sealant				1.00	
				Shop Supplies				1.00	
	Ηοι	urs: 11.75	Comm: 0.00	Labor: 705.00	Parts: 508	8.10	Total:	1,213.10	
Work Order: Problem:		Meter: and safety recalls.	3131		In Date:	03/31/2015	Closed:	04/14/2015	
Work Com	npleted			Parts Issued			Qı	antity	
- Pm servi	ce.			5w20 Engine Oil				5.00	
- Rotate a	nd balance all	four tires.		Napagold Oil Filter				1.00	
- Transpor	rt vehicle to ar	nd from dealer for	safety recalls#14s03 and 14s04	Washer Fluid Concen	ıtr			1.00	
- Shop Su	pplies			Shop Supplies				1.00	
	Ηοι	urs: 5.75	Comm: 0.00	Labor: 345.00	Parts: 19.	.93	Total:	364.93	

Vork Order: 1600059 Problem: Pm service.Recall	Meter: 4060		In Date:	01/04/2016	Closed:	01/19/2016
Work Completed		Parts Issued			Qu	uantity
- Pm service.		5w20 Engine Oil				5.00
- Rotate and balance all four tires.		Napagold Oil Filter				1.00
- Transport vehicle to and from dealer for safety	v recall #14s21	Washer Fluid Conce	ntr			1.00
- Shop Supplies		Shop Supplies				1.00
Hours: 5.75	Comm: 0.00	Labor: 345.00	Parts: 17.	.65	Total:	362.65
<i>Iork Order:</i> 1607614 <b>Problem:</b> P.M. service and antenna broken off	<b>Meter:</b> 4801		In Date:	07/26/2016	Closed:	08/18/2010
Work Completed		Parts Issued			Q	uantity
- P.m. Service.		5w20 Engine Oil				5.00
- R&r headliner ane replace broken antennea ba	ase.	Napagold Oil Filter				1.00
- Rotate and balance all tires.		Washer Fluid Conce	ntr			1.00
- Shop Supplies		Accufit Beam				2.00
		Aerial Wit				1.00
		Stanchion				1.00
		Shop Supplies				1.00
Hours: 5.25	Comm: 0.00	Labor: 315.00	Parts: 148	8.61	Total:	463.61
<i>Iork Order:</i> 1701258 <b>Problem:</b> P.M. service.	Meter: 5355		In Date:	02/07/2017	Closed:	02/22/201
Work Completed		Parts Issued			Qı	uantity
- P,m. Service.		5w20 Engine Oil				5.00
- Rotate and balance tires.		Napagold Oil Filter				1.00
- Shop Supplies		Wiper Blade				1.00
		Wiper Blade				1.00
		Wpr/blde				1.00
		Shop Supplies				1.00
Hours: 3.75	Comm: 0.00	Labor: 225.00	Parts: 60.	.89	Total:	285.89

Nork Order: 1711106 Problem: P.M. service.	Meter:	6144		In Date:	11/08/2017	Closed:	11/29/2017
Work Completed			Parts Issued			Qı	uantity
- P.m. service.			5w20 Engine Oil				5.00
- Load test battery and failed due to bad cell.replace battery with new.			Napagold Oil Filter				1.00
- Replace faulty horn assembly, in operatio	nal, with new.		Washer Fluid Conce	entr			1.00
- Rotate and balance four tires.			Battery				1.00
- Shop Supplies			Horn Assembly				1.00
			Shop Supplies				1.00
Hours: 5.75		Comm: 0.00	Labor: 345.00	Parts: 213	3.40	Total:	558.40
Vork Order: 1803769 Problem: Left front tire going flat.	Meter:	10349		In Date:	04/11/2018	Closed:	04/11/201
Work Completed			Parts Issued			Qı	uantity
- Repair left front tire .balance tire and nit	rofill all tires.		Shop Supplies				1.00
- Shop Supplies							
Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 2.0	0	Total:	62.00
Vork Order: 1804695 Problem: P.M. service and recall 17S09	Meter:	11279		In Date:	05/04/2018	Closed:	05/21/2018
Work Completed			Parts Issued			Qı	uantity
- P.m. service.			5w20 Engine Oil				5.00
- Rotate and balance all four tires. Nitroge	en fill all tires.		Napagold Oil Filter				1.00
- Transport to and from dealer for recalls	16s30 and 17s0	9.	Wiper Blade				1.00
- Shop Supplies			Wiper Blade				1.00
			Blade				1.00
			Washer Fluid Conce	entr			1.00
			Shop Supplies				1.00
			Labor: 345.00	Parts: 74.			419.00

Vork Order:		Meter:	13554		In Date:	07/23/2018	Closed:	07/25/2018
Problem:	Low coolant light on .							
Work Com	pleted							
	test cooling system . refill cool		ks found . low due					
to recall 17	s09 being performed at dealer							
	Hours: 0.20		Comm: 0.00	Labor: 12.00	Parts: 0.0	0	Total:	12.00
Vork Order: Problem:	1810527 P.M. service.	Meter:	16369		In Date:	10/12/2018	Closed:	10/18/2018
Work Com	pleted			Parts Issued			Qı	uantity
- P.m. serv	ice.			Napagold Oil Filter				1.00
- Mount ar	nd balance four new tires . Nitr	ogen fill all tires.		5w20 Engine Oil				5.00
- Pressure	test cooling system . Replace le	eaking hose clan	np at T connector .	Washer Fluid Conce	ntr			1.00
Top off coc	plant and retest.	-		Blade				1.00
- Perform	four wheel alignment. Road tes	st.		Wiper Blade				1.00
- Shop Sup	oplies			Wiper Blade				1.00
				Tire235/55/17 Mic				4.00
				Hose Clamp				1.00
				Shop Supplies				1.00
				Tire Disposal Fee				4.00
	Hours: 8.25		Comm: 0.00	Labor: 552.75	Parts: 839	9.08	Total:	1,391.83
Vork Order: Problem:	1901724 Low coolant light on.	Meter:	20330		In Date:	02/13/2019	Closed:	02/19/2019
Work Com	pleted							
- Diagnose plastic cool	e for low coolant light on dash. ant jug.	pressure test no	leaks found.top off	:				
	Hours: 0.50		Comm: 0.00	Labor: 33.50	Parts: 0.0	0	Totalı	33.50

Work Order: 1903045 Problem: PM Service	Meter:	21563		In Date:	03/20/2019	Closed:	04/01/2019
Work Completed			Parts Issued			Q	uantity
- P.m. service.			5w20 Engine Oil				5.00
- Rotate and balance all four tires	. Nitrofill all and reset	Tpms.	Napagold Oil Filter				1.00
- Shop Supplies			Washer Fluid Concent	tr			1.00
			Blade				1.00
			Wiper Blade				1.00
			Wiper Blade				1.00
			Battery				1.00
			Shop Supplies				1.00
Hours: 3.75		Comm: 0.00	Labor: 251.25	Parts: 106	6.62	Total:	357.87
Nork Order: 1907803 Problem: PM Service	Meter:	26958		In Date:	07/29/2019	Closed:	08/01/2019
Work Completed			Parts Issued			Q	uantity
- P.m. Service.			Napagold Oil Filter				1.00
- Test battery and charging system	n.replace bad battery.		5w20 Engine Oil				5.00
- Rotate and balance tires.			Blade				1.00
- Shop Supplies			Wiper Blade				1.00
			Wiper Blade				1.00
			Napa Cabin Air Filter				1.00
							1.00
			Battery				1.00
			Battery Shop Supplies				1.00
Hours: 4.75		Comm: 0.00		Parts: 264	4.90	Total:	
		Comm: 0.00 27449	Shop Supplies	Parts: 264	4.90 08/06/2019		1.00 583.15
Nork Order: 1908105			Shop Supplies			Closed:	1.00 583.15
Nork Order: 1908105 Problem: Splash shield hanging			Shop Supplies Labor: 318.25			Closed:	1.00 583.15 08/13/2019
Work Order: 1908105 Problem: Splash shield hanging Work Completed			Shop Supplies Labor: 318.25 Parts Issued			Closed:	1.00 583.15 08/13/2019

Vork Order: 1911907 Problem: P.M. service.	Meter:	32305		In Date:	11/18/2019	Closed:	11/26/201
Work Completed			Parts Issued			Qu	uantity
- P.m. service.			Napagold Oil Filter				1.00
- Rotate and balance all four ti	res . Nitrofill all.		5w20 Engine Oil				5.00
- Shop Supplies			Washer Fluid Concer	ntr			1.00
			Ford Triton Pvc Swc				1.00
			Shop Supplies				1.00
Hours: 3.7	75	Comm: 0.00	Labor: 273.75	Parts: 41.	.98	Total:	315.73
Vork Order: 2001752 Problem: ABS light on .	Meter:	36128		In Date:	02/20/2020	Closed:	02/27/202
Work Completed			Parts Issued			Qı	uantity
- Computer diagnose Abs light	t , code C0037 . Perform p	inpoint test . R&r	Sensor Asy				1.00
	•		Shop Supplies				1.00
defective left rear Abs wheel sp	eed sensor . Clear code ar	lu letest.	Shop Supplies				1.00
defective left rear Abs wheel sp - Shop Supplies	eed sensor . Clear code ar	la letest.	Shop Supplies				1.00
		Comm: 0.00	Labor: 146.00	Parts: 35.	56	Total:	181.56
- Shop Supplies Hours: 2.0	00 Meter:			Parts: 35. In Date:	56 04/22/2020		181.56
- Shop Supplies Hours: 2.0 Vork Order: 2004001	00 Meter:	Comm: 0.00				Closed:	181.56
- Shop Supplies Hours: 2.0 Vork Order: 2004001 Problem: P.M. service and re	00 Meter:	Comm: 0.00	Labor: 146.00			Closed:	181.56 05/05/202
- Shop Supplies Hours: 2.0 Vork Order: 2004001 Problem: P.M. service and re Work Completed	00 Meter: ecall 18S20.	Comm: 0.00	Labor: 146.00 Parts Issued			Closed:	181.56 05/05/202 Jantity
- Shop Supplies Hours: 2.0 Vork Order: 2004001 Problem: P.M. service and re Work Completed - P.m. service.	00 Meter: ecall 18S20.	Comm: 0.00 38210	Labor: 146.00 Parts Issued Napagold Oil Filter			Closed:	181.56 05/05/202 uantity 1.00
- Shop Supplies Hours: 2.0 Vork Order: 2004001 Problem: P.M. service and re Work Completed - P.m. service. - R&r both leaking rear shocks	00 Meter: ecall 18S20.	Comm: 0.00 38210	Labor: 146.00 Parts Issued Napagold Oil Filter 5w20 Engine Oil			Closed:	181.56 05/05/202 aantity 1.00 5.00
- Shop Supplies Hours: 2.0 Vork Order: 2004001 Problem: P.M. service and re Work Completed - P.m. service. - R&r both leaking rear shocks - Replace both rear brake roto	00 Meter: ecall 18S20.	Comm: 0.00 38210	Labor: 146.00 Parts Issued Napagold Oil Filter 5w20 Engine Oil Blade			Closed:	181.56 05/05/202 antity 1.00 5.00 1.00
<ul> <li>Shop Supplies Hours: 2.0</li> <li>Vork Order: 2004001 Problem: P.M. service and re</li> <li>Work Completed</li> <li>P.m. service.</li> <li>R&amp;r both leaking rear shocks</li> <li>Replace both rear brake roto bleed brake system . Road test</li> </ul>	00 Meter: ecall 18S20. s. rs and pads . Service calipo proken antenna base .	Comm: 0.00 38210	Labor: 146.00 Parts Issued Napagold Oil Filter 5w20 Engine Oil Blade Wiper Blade	In Date:		Closed:	181.56 05/05/202 aantity 1.00 5.00 1.00 1.00
<ul> <li>Shop Supplies Hours: 2.0</li> <li>Vork Order: 2004001 Problem: P.M. service and re</li> <li>Work Completed</li> <li>P.m. service.</li> <li>R&amp;r both leaking rear shocks</li> <li>Replace both rear brake roto bleed brake system . Road test</li> <li>Access headliner to replace b</li> </ul>	00 Meter: ecall 18S20. 5. rs and pads . Service calipe proken antenna base . res . Nitrofill all.	Comm: 0.00 38210	Labor: 146.00 Parts Issued Napagold Oil Filter 5w20 Engine Oil Blade Wiper Blade Wiper Blade	In Date:		Closed:	181.56 05/05/202 antity 1.00 5.00 1.00 1.00 1.00
<ul> <li>Shop Supplies Hours: 2.0</li> <li>York Order: 2004001 Problem: P.M. service and rest</li> <li>Work Completed</li> <li>P.m. service.</li> <li>R&amp;r both leaking rear shocks</li> <li>Replace both rear brake roto bleed brake system . Road test</li> <li>Access headliner to replace be Balance and rotate all four tire</li> </ul>	00 Meter: ecall 18S20. 5. rs and pads . Service calipe proken antenna base . res . Nitrofill all.	Comm: 0.00 38210	Labor: 146.00 Parts Issued Napagold Oil Filter 5w20 Engine Oil Blade Wiper Blade Wiper Blade Real Shock Motorcra	In Date:		Closed:	181.56 05/05/202 <b>Jantity</b> 1.00 5.00 1.00 1.00 1.00 2.00
<ul> <li>Shop Supplies Hours: 2.0</li> <li>York Order: 2004001 Problem: P.M. service and rest</li> <li>Work Completed</li> <li>P.m. service.</li> <li>R&amp;r both leaking rear shocks</li> <li>Replace both rear brake roto bleed brake system . Road test</li> <li>Access headliner to replace be</li> <li>Balance and rotate all four times</li> <li>Transport to and from dealer</li> </ul>	00 Meter: ecall 18S20. 5. rs and pads . Service calipe proken antenna base . res . Nitrofill all.	Comm: 0.00 38210	Labor: 146.00 Parts Issued Napagold Oil Filter Sw20 Engine Oil Blade Wiper Blade Wiper Blade Real Shock Motorcra Brake Pad Real	In Date:		Closed:	181.56 05/05/202 antity 1.00 5.00 1.00 1.00 2.00 1.00
<ul> <li>Shop Supplies Hours: 2.0</li> <li>Vork Order: 2004001 Problem: P.M. service and rest</li> <li>Work Completed</li> <li>P.m. service.</li> <li>R&amp;r both leaking rear shocks</li> <li>Replace both rear brake roto bleed brake system . Road test</li> <li>Access headliner to replace bot</li> <li>Balance and rotate all four tire</li> <li>Transport to and from dealer</li> </ul>	00 Meter: ecall 18S20. 5. rs and pads . Service calipe proken antenna base . res . Nitrofill all.	Comm: 0.00 38210	Labor: 146.00 Parts Issued Napagold Oil Filter 5w20 Engine Oil Blade Wiper Blade Wiper Blade Real Shock Motorcra Brake Pad Real Front Brake Rotor	In Date:		Closed:	181.56 05/05/202 antity 1.00 5.00 1.00 1.00 2.00 1.00 2.00

#### Work Order: 2011383 11/13/2020 Closed: 11/25/2020 Meter: 44290 In Date: Problem: PM Service, Safety Recall 20S30/20V-331 Parts Issued Quantity **Work Completed** Napagold Oil Filter 1.00 - Preventive Maint, Service 5w20 Engine Oil 5.00 - Rotate and balance all four wheels and tires. nitrogen fill all tires and rest tpms. Wiper Blade 1.00 - Replace cabin Ac filter. Clean fresh air intake . Wiper Blade 1.00 - Recall 20530 Performed and entered into ford latch recall. to verify. Blade 1.00 - Shop Supplies Napagold Air Filter 1.00 Napa Cabin Air Filter 1.00 Shop Supplies 1.00 Comm: 0.00 Parts: 102.88 Total: 442.33 Hours: 4.65 Labor: 339.45 Work Order: 2101478 Meter: 46456 In Date: 02/09/2021 Closed: 02/16/2021 Problem: A/C does not work . **Parts Issued** Quantity **Work Completed** Gasket Kit 1.00 - A/c performance test , found stuck closed expansion valve . Recover and evacuate system, R&r defective expansion valve. Vacuum and fully charge Freon Lv Shop 2 2.00 system . Retest . A/c Seal 1.00 - Shop Supplies A/c O Ring 1.00 Valva Asy A/c 1.00 1.00 Shop Supplies Hours: 4.00 Comm: 0.00 Labor: 292.00 Parts: 114.03 Total: 406.03

**Meter:** 48942

# Work Order:2107482Problem:PM Service.

## In Date: 07/12/2021 Closed: 07/15/2021

Work Completed		Parts Issued		Qı	antity	
- Preventive Maint. Service		Washer Fluid Con		1.00		
- Rotated and balanced all 4 tires. Nitroger	n filled all tires.	Blade	1.00			
- Replaced old worn out, faded and cracke	d asset numbers.	Wiper Blade		1.00		
- Shop Supplies		Wiper Blade			1.00	
		Napagold Oil Filte	1.00			
		5w20 Engine Oil		5.00		
		Shop Supplies			1.00	
Hours: 4.55	Comm: 0.00	Labor: 332.15	Parts: 64.45	Total:	396.60	
<b>Ork Order:</b> 2108179 <b>Problem:</b> Send for Detail. engine light on	Meter: 49316 due to low coolant		In Date: 07/29/202	1 Closed:	08/05/202	
<b>Problem:</b> Send for Detail. engine light on		<b>-</b>	In Date: 07/29/202			
Problem: Send for Detail. engine light on Work Completed	due to low coolant	Parts Issued	In Date: 07/29/202		antity	
<ul><li>Problem: Send for Detail. engine light on</li><li>Work Completed</li><li>Scan diagnose code P2560, Pin point test</li></ul>	due to low coolant t and identify cracked level sensor	Hose	In Date: 07/29/202		iantity 1.00	
<ul> <li>Problem: Send for Detail. engine light on</li> <li>Work Completed</li> <li>Scan diagnose code P2560, Pin point test pipe and chewed water outlet hose. Replace</li> </ul>	due to low coolant t and identify cracked level sensor e sensor and hose. Vacuum	Hose Pipe Asm	<b>In Date:</b> 07/29/202		antity	
<ul> <li>Problem: Send for Detail. engine light on</li> <li>Work Completed</li> <li>Scan diagnose code P2560, Pin point test pipe and chewed water outlet hose. Replace bleed/fill cooling system, pressure test and</li> </ul>	due to low coolant t and identify cracked level sensor e sensor and hose. Vacuum	Hose	<b>In Date:</b> 07/29/202		iantity 1.00	
<ul> <li>Problem: Send for Detail. engine light on</li> <li>Work Completed</li> <li>Scan diagnose code P2560, Pin point test pipe and chewed water outlet hose. Replace</li> </ul>	due to low coolant t and identify cracked level sensor e sensor and hose. Vacuum	Hose Pipe Asm	In Date: 07/29/202 Parts: 362.74	Qı	1.00	
Problem: Send for Detail. engine light on Work Completed - Scan diagnose code P2560, Pin point test pipe and chewed water outlet hose. Replace bleed/fill cooling system, pressure test and - Shop Supplies Hours: 4.00	due to low coolant t and identify cracked level sensor e sensor and hose. Vacuum clear codes	Hose Pipe Asm Shop Supplies	Parts: 362.74	Qı	1.00 1.00 1.00	
Problem: Send for Detail. engine light on Work Completed - Scan diagnose code P2560, Pin point test pipe and chewed water outlet hose. Replace bleed/fill cooling system, pressure test and - Shop Supplies Hours: 4.00	due to low coolant t and identify cracked level sensor e sensor and hose. Vacuum clear codes Comm: 0.00 Meter: 49316	Hose Pipe Asm Shop Supplies	Parts: 362.74	Qu Total:	1.00 1.00 1.00 1.00 654.74	
Problem: Send for Detail. engine light on Work Completed - Scan diagnose code P2560, Pin point test pipe and chewed water outlet hose. Replace bleed/fill cooling system, pressure test and - Shop Supplies Hours: 4.00 ork Order: 2108465	due to low coolant t and identify cracked level sensor e sensor and hose. Vacuum clear codes Comm: 0.00 Meter: 49316	Hose Pipe Asm Shop Supplies	Parts: 362.74	Qu Total:	1.00 1.00 1.00 1.00 654.74	
Work Completed - Scan diagnose code P2560, Pin point test pipe and chewed water outlet hose. Replace bleed/fill cooling system, pressure test and - Shop Supplies Hours: 4.00 Tork Order: 2108465 Problem: 1 - Detail Vehicle Wash Ticket(	due to low coolant t and identify cracked level sensor e sensor and hose. Vacuum clear codes Comm: 0.00 Meter: 49316	Hose Pipe Asm Shop Supplies	Parts: 362.74	Qu Total:	1.00 1.00 1.00 1.00 654.74	

keypad . Clear code and retest .

### Palm Beach County Fleet Management Asset Maintenance History 10192529 2013 FORD ESCAPE Suv, Mid Size, 4X4

## Work Order: 2109979 Problem: ABS sensor light on

#### 09/15/2021 Closed: 09/30/2021 In Date:

Total: 1,878.74

Work Completed	Parts Issued	Quantity
- Computer diagnose Abs light . Code U3000 . Perform pin point test . Clear	Actuator	1.00
code and retest code came back . R&r defective Hcu and Abs module .p.m.i	Abs Control Unit Assy	1.00
module program , reset Vid and all sensors . Flush and bleed brake system . Clear codes and retest .	Brk Fluid Dot 4-32oz	1.00
	Non-chlor Brake Clnr	1.00
- Computer diagnose keypad inop and damaged . code B121a . perform pinpoint test . Remove left front door panel to replace b-pillar molding with	Shop Supplies	1.00

- Shop Supplies

	Hours: 6.00	Comm: 0.00	Labor: 438.00	Parts: 974	4.50	Total:	1,412.50
Work Order:	2201594	Meter: 55194		In Date:	02/11/2022	Closed:	02/17/2022
Broblom	DM Service front percentage light not	working too coloctor not	working and as is not a	otting oold m	act of the t		

**Problem:** PM Service. front passenger light not working :ac selector not working and ac is not getting cold most of the t

Meter: 50136

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	Blade	1.00
- Replaced 2 tires. Rotated and balanced all 4 tires. Nitrogen filled all tires.	Wiper Blade	1.00
- Diagnose Ac not cooling. Found to have leaking Ac line, replaced leaking	Wiper Blade	1.00
line filled Freon to factory spec and checked full function of Ac. All working	Napagold Oil Filter	1.00
as it should.	5w20 Engine Oil	5.00
- Replaced Rf head light bulb and connector assembly. Replaced Lf faulty	Tire235/55/17 Mic	2.00
strobe light.	Freon Lv Shop 2	2.00
- Battery tested bad. Charged battery fully and retested bad. Replaced bad battery. Use scan tool to reset Bms.	Mnt Conc Led Clear	1.00
- Resurfaced front brake rotors. Replaced front pads and serviced calipers.	Headlamp Socket H11	1.00
Flush and bleed brake system . Road test .	Blister Pack Capsules	1.00
- Shop Supplies	Battery	1.00
	Brake Pads	1.00
	A/c Hose	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00

Labor: 1,127.85

Parts: 750.89

Comm: 0.00

Vork Order: Problem:	2205033 FLAT TIRE left front	Meter:	58328		In Date:	05/10/2022	Closed:	05/11/202
Work Com	npleted			Parts Issued			Q	uantity
- Repair le	eft front tire and balance and	replace damaged	lua nuts	Lug Nuts				5.00
- Shop Su		1 5	5	Shop Supplies				1.00
	Hours: 1.00		Comm: 0.00	Labor: 73.00	Parts: 24	.71	Total:	97.71
Vork Order: Problem:	2206691 PM Service. and A/C blows	Meter: warm	60428		In Date:	06/24/2022	Closed:	06/30/202
Work Com	npleted			Parts Issued			Qı	uantity
- Preventiv	ve Maint. Service			Napagold Oil Filter				1.00
- Replaced	d 2 tires. Rotated and balance	d all 4 tires. Nitro	gen filled all tires.	5w20 Engine Oil				5.00
•	amaged lug nuts		-	Washer Fluid Concent	tr			1.00
0	e A/c not cooling. Found to h			Blade				1.00
•	or, condenser, and expansion vector to factory spec. Retest	valve. Flushed A/c	system. Evacuate	Wiper Blade				1.00
- Shop Su	<b>3</b> 1			Wiper Blade				1.00
- Shop Su	ppnes			Lug Nuts				7.00
				Tire235/55/17 Mic				2.00
				V Belt				1.00
				E8 A/c Oil Univ W Dye	e			1.00
				O Ring Kit A/c				1.00
				A/c O Ring				1.00
				Flush Solvent				1.00
				Valva Asy A/c				1.00
				A/c Condenser				1.00
				A/c Compressor				1.00
				Freon Lv Shop 2				2.00
				Shop Supplies				1.00
				Tire Disposal Fee				2.00
	Hours: 15.65		Comm: 0.00	Labor: 1,142.45	Parts: 1,1	65.02	Total:	2,307.47

## Work Order: 2210280 Meter: 63606 Problem: front passenger light is out and noise from front wheels while driving

#### 10/06/2022 **Closed:** 10/18/2022 In Date:

Work Completed		Parts Issued		Quantity
- Test drive . Replace front motor mount , tra	ans mount and antiroll mount	Housing		1.00
Road test .		Housing		1.00
- Replace leaking left front drive axle . Repla	Engine Monut	Engine Monut		
oad test		Left Front Axle		1.00
- Test and replace right side low beam bulb retest .	- Test and replace right side low beam bulb and melted pig tail connector .			1.00
<ul> <li>Replace corroded negative battery cable as</li> </ul>	ssembly	Bearing		1.00
<ul> <li>Perform complete four wheel alignment ar</li> </ul>	<i>y</i>	Wire Assy		1.00
- Shop Supplies	iu iudu lest .	Bulb		1.00
- Shop Supplies		Bat Cable		1.00
		Shop Supplies		1.00
Hours: 12.70	Comm: 0.00	Labor: 927.10	Parts: 469.81	Total: 1,396.9
rk Order: 2300622	Meter: 67483		In Date: 01/23/2023	Closed: 01/30/20

Problem: PM Service.

## **Work Completed**

- Preventive Maint. Service
- Check and replace cabin filter and clean fresh air intake

- Check circuit to front and rear strobe light inop, R & I front bumper & headlight, necessary to replace front strobe, R & I left rear tail lamp & inner trim, necessary to replace rear strobe

- Rotate and speed balance, nitro fill
- Shop Supplies

Parts Issued	Quantity		
Napagold Oil Filter		1.00	
5w20 Engine Oil		5.00	
Washer Fluid Concer	ntr	1.00	
Blade		1.00	
Wiper Blade		1.00	
Wiper Blade		1.00	
Napa Cabin Air Filter	-	1.00	
Wrn Ambr		1.00	
Mnt Conc Led Clear		1.00	
Shop Supplies		1.00	
Labor: 529.25	Parts: 275.74	Total: 804.99	

Hours: 7.25

Comm: 0.00

#### Work Order: 2303414 Meter: 72179 04/05/2023 Closed: 04/11/2023 In Date: Problem: PM Service. front driver low beam out Parts Issued **Work Completed** Quantity Napagold Oil Filter 1.00 - Preventive Maint, Service 5w20 Engine Oil 6.00 - Rotate and speed balance, nitro fill Washer Fluid Concentr 1.00 - Check circuit to left headlight, inop. R & I new low beam light bulb Blade 1.00 - Shop Supplies Wiper Blade 1.00 Wiper Blade 1.00 Bulb 1.00 1.00 Shop Supplies Hours: 3.50 Comm: 0.00 Labor: 255.50 Parts: 93.98 Total: 349.48 Work Order: 2303775 **Meter:** 72602 In Date: 04/17/2023 Closed: 04/18/2023 **Problem:** front driver side light out **Work Completed** Parts Issued Quantity **Blister Pack Capsules** 1.00 - Test and replace left front low beam headlight bulb . Hours: 0.50 Comm: 0.00 Labor: 36.50 Parts: 10.68 Total: 47.18 Work Order: 2308495 Meter: 79664 In Date: 08/24/2023 Closed: 09/06/2023 Problem: PM Service and front tires noisy Parts Issued **Work Completed** Quantity Napagold Oil Filter 1.00 - Preventive Maint. Service 5w20 Engine Oil 5.00 - Rotated and balanced all 4 tires. Nitrogen filled all tires. Blade 1.00 - Performed transmission flush. Wiper Blade 1.00 - Diagnose humming noise when driving. Found Lf bearing to have play and Rf bearing to be noisy. R&r both front wheel bearings. Test drove to confirm Wiper Blade 1.00 fix. 12.00 oil auto - Shop Supplies 2.00 Bearing Shop Supplies 1.00 Hours: 10.15 Comm: 0.00 Labor: 740.95 Parts: 335.84 Total: 1,076.79

## Work Order: 2311538 **Meter:** 83914 Problem: PM Service check engine light on Send for Detail.

## In Date: 11/17/2023 Closed: 12/05/2023

Work Completed		Parts Issued		Quantity					
- Performed Pm service		Napagold Oil Filter		1.00					
- Rotated and balanced all 4 tires. Nitrogen filled all tires.		5w20 Engine Oil	5.00						
<ul> <li>wastegate solenoid. Replaced faulty solenoid and cleared all lines to it from debris. Also diagnosed code U0284- Found to have faulty grill shutter actuator. R&amp;r faulty actuator.</li> <li>Diagnose battery light on. Tested starting and charging system and found to have bad battery and alternator. R&amp;r bad alternator and battery. Use scan</li> </ul>		Blade	1.00						
		Wiper Blade		1.00					
		Wiper Blade	1.00						
		Battery		1.00					
		Alternator	lternator						
		Valve Regulating	1.00						
- Pressure tested cooling system and found to	Coolent	2.00							
coolant overflow hose at block. and both heater	Seal		1.00						
- Shop Supplies		Actuator Big G Degreaser 1 Gal Heater Hose32.54		1.00 1.00 1.00					
							Heater Hose		1.00
							Shop Supplies		1.00
Hours: 16.25	Comm: 0.00	Labor: 1,186.25	Parts: 1,098.84	Total: 2,285.09					
ork Order: 2312131	Meter: 83914		In Date: 12/05/2023	3 Closed: 12/06/20					

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued WO: 2311538 for: edgar longoria

## **Work Completed**

- 1 - Detail Vehicle Wash Ticket(s) Issued Wo: 2311538 for: edgar longoria

Hours: 0.00

Comm: 90.40

Labor: 0.00 Parts: 0.00 Total: 90.40

Work Order: Problem:	2400010 ABS light on	<b>Meter:</b> 84858		In Date:	01/02/2024	Closed:	01/04/2024
Work Com	pleted		Parts Issued			Q	uantity
- Computer diagnose Abs light/traction light , code C003a . perform			Non-chlor Brake Cln	r			1.00
pinpoint test . R&r defective right rear Abs wheel speed sensor . Clear code		Sensor				1.00	
and retest.			Shop Supplies				1.00
- Shop Sup		• • • • •					
	Hours: 1.50	Comm: 0.00	Labor: 109.50	Parts: 30.			139.55
Vork Order: Problem:	2401797 broken down, located on S sid	Meter: 87264 de of admin parking lot		In Date:	02/16/2024	Closed:	03/04/2024
Work Com	pleted		Parts Issued			Q	uantity
- Pm Canc	el		Coolent				2.00
- Pressure	test and inspect cooling syster	n . Replace leaking engine coolant	Coolant Hose Assy				1.00
reservoir hose and clamps . Flush cooling system and refill and retest .computer diagnose check engine light , P1299 ,p2560 . Clear codes and			Hose Assy				1.00
			Hose Clamp				1.00
retest after		Hose Clamp				2.00	
- Shop Sup	opnes		Hose Assy				1.00
			Hose Assy				1.00
			Shop Supplies				1.00
	Hours: 2.50	Comm: 0.00	Labor: 182.50	Parts: 573	3.70	Total:	756.20
Work Order: Problem:	2401894 broken down, located on S sid	<b>Meter:</b> 87083 de of admin parking lot		In Date:	02/16/2024	Closed:	02/21/2024
Work Com	pleted						
- Tow Fror	n: 8100 Foresthill, water utilitie	s To: fleet vista Lv shop					
	Hours: 0.00	Comm: 124.30	Labor: 0.00	Parts: 0.0	0	Total:	124.30
Nork Order:	2404627 Transition Prep Charge	Meter: 89917		In Date:	05/09/2024	Closed:	05/13/2024

- Transition Prep Charge

6/3/2024 2:52:13 PM	Palm Beach County Fleet Management Asset Maintenance History 10192529 2013 FORD ESCAPE Suv, Mid Size, 4X4					
	Hours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 0.00	Total: 146.00	
Total Hours: 193.45	Total Labo	r: 13,405.00	Total Comm: 305.1	0 Total Pa	urts: 9,614.08	