

10/17/2016  
11:24:23AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162778 2006 GMC 1500 Pickup, 1/2 Ton, 4X4, W/Winch, 8 Ft. Bed

**Workorder:** 641857                      **Problem:** PRE-DELIVERY INSPECTION

| Meter Reading: 0          | Labor                       | Parts       |
|---------------------------|-----------------------------|-------------|
| In Date: 07/05/2006       | Hours                       | Description |
| Close Date: 07/05/2006    |                             | Quantity    |
| - Pre-Delivery Inspection | <b>2.00</b>                 |             |
| <b>Parts Charge:</b> 0.00 | <b>Labor Charge:</b> 100.00 |             |

**Workorder:** 641907                      **Problem:** MINOR WELD REPAIR OR MACHINING.

| Meter Reading: 0                  | Labor                      | Parts       |
|-----------------------------------|----------------------------|-------------|
| In Date: 07/06/2006               | Hours                      | Description |
| Close Date: 07/06/2006            |                            | Quantity    |
| - Minor Weld Repair Or Machining. | <b>1.00</b>                |             |
| <b>Parts Charge:</b> 0.00         | <b>Labor Charge:</b> 50.00 |             |

**Workorder:** 644419                      **Problem:** ENGINE LIGHT ON

| Meter Reading: 423   | Labor                      | Parts              |
|--|----------------------------|--------------------|
| In Date: 08/21/2006  | Hours                      | Description        |
| Close Date: 08/22/2006   |                            | Quantity           |
| - Computer Sys Diagnosis (Evap Code)Found Fuel Cap Loose. Clear Code.Test Drive. | <b>1.00</b>                | SHOP SUPPLIES 1.00 |
| - Shop Supplies  |                            |                    |
| <b>Parts Charge:</b> 2.00  | <b>Labor Charge:</b> 50.00 |                    |

**Workorder:** 732951                      **Problem:** P.M SERVICE

| Meter Reading: 4758        | Labor                      | Parts                                      |
|----------------------------|----------------------------|--|
| In Date: 01/18/2007        | Hours                      | Description                                |
| Close Date: 01/25/2007     |                            | Quantity                                   |
| - Perform Pm Service       | <b>3.75</b>                | 10W30 MOTOR OIL 5.00                       |
| - Nitrogen Fill All Tires. |                            | PH3387A OIL FILTER LBF PH47 WIX 51040 1.00 |
| - Shop Supplies            |                            | 31-22 WIPER BLADES 22" WIPER BLADE 2.00    |
|                            |                            | SHOP SUPPLIES 1.00                         |
| <b>Parts Charge:</b> 28.10 | <b>Labor Charge:</b> 55.00 |  |

10/17/2016  
11:24:23AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162778 2006 GMC 1500 Pickup, 1/2 Ton, 4X4, W/Winch, 8 Ft. Bed

**Workorder:** 736042

**Problem:** FLAT TIRE

| Meter Reading: 6310  |  | Labor  |  | Parts    |      |
|----------------------|--|--------|--|----------|------|
| In Date: 03/22/2007  | Close Date: 03/26/2007   | Hours  | Description  | Quantity |      |
| -                    | Right Frt Tire Damage Beyond Repair.Repl With New Tire From Spare Wheel Then Install New Tire To Spare And Secure,High Speed Balance Both. | 1.50   | TIRE DISPOSAL FEE                                    |          | 1.00 |
| -                    | Shop Supplies  |        | 748469189 245/70R17 WRG SILENT ARMOR E SHOP SUPPLIES |          | 1.00 |
| <b>Parts Charge:</b> |  | 190.45 | <b>Labor Charge:</b>                                 | 82.50    |      |

**Workorder:** 737159

**Problem:** FLAT TIRE

| Meter Reading: 6754  |                        | Labor |                      | Parts    |      |
|----------------------|------------------------|-------|----------------------|----------|------|
| In Date: 04/13/2007  | Close Date: 04/18/2007 | Hours | Description          | Quantity |      |
| -                    | Repair Flat Tire       | 1.00  | SHOP SUPPLIES        |          | 1.00 |
| -                    | Shop Supplies          |       |                      |          |      |
| <b>Parts Charge:</b> |                        | 2.00  | <b>Labor Charge:</b> | 55.00    |      |

**Workorder:** 741766

**Problem:** PM SERVICE

| Meter Reading: 10206 |  | Labor |                                       | Parts    |      |
|----------------------|--|-------|---------------------------------------|----------|------|
| In Date: 07/20/2007  | Close Date: 07/24/2007                           | Hours | Description                           | Quantity |      |
| -                    | Pm Service                                       | 7.25  | PH3387A OIL FILTER LBF PH47 WIX 51040 |          | 1.00 |
| -                    | Clean And Readjust Rear Brakes And Drum          |       | USED FIREX REFURBED FIRE EXTINGSHERS  |          | 1.00 |
| -                    | Clean Mud Out Of Wheels And Balancce All 4 Tires |       | 10020 INJECTOR CLEANER DON'T REORDER  |          | 1.00 |
| -                    | Adjust Tension Bars And Align Front End.         |       | 10W30 MOTOR OIL                       |          | 5.00 |
| -                    | Shop Supplies                                    |       | 6678 AIR FILTER FRM CA8755A WIX 46678 |          | 1.00 |
|                      |  |       | SHOP SUPPLIES                         |          | 1.00 |
|                      |  |       | 31-22 WIPER BLADES 22" WIPER BLADE    |          | 2.00 |
| <b>Parts Charge:</b> |  | 51.32 | <b>Labor Charge:</b>                  | 137.50   |      |

**Workorder:** 742739

**Problem:** GUARANTEED BUMPER & SUPPLIERS

| Meter Reading: 0     |                               | Labor |                      | Parts    |                                    |
|----------------------|-------------------------------|-------|----------------------|----------|------------------------------------|
| In Date: 07/30/2007  | Close Date: 08/13/2007        | Hours | Description          | Quantity |                                    |
| -                    | Guaranteed Bumper & Suppliers |       |                      |          |                                    |
| <b>Parts Charge:</b> |                               | 0.00  | <b>Labor Charge:</b> | 0.00     | <b>Commercial Charge:</b> 1,879.80 |

10/17/2016  
11:24:23AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162778 2006 GMC 1500 Pickup, 1/2 Ton, 4X4, W/Winch, 8 Ft. Bed

**Workorder:** 832508

**Problem:** P.M SERVICE,CHECK VIBRATION

| Meter Reading: 14241  |                        | Labor                |                                       | Parts                     |        |
|---|------------------------|----------------------|---------------------------------------|---------------------------|--------|
| In Date: 01/09/2008   | Close Date: 01/22/2008 | Hours                | Description                           | Quantity                  |        |
| - Pm Service  |                        | 7.55                 | 6678 AIR FILTER FRM CA8755A WIX 46678 | 1.00                      |        |
| - Service Vehicle Winch And Replace Cable                     |                        |                      | PH3387A OIL FILTER LBF PH47 WIX 51040 | 1.00                      |        |
| - Service Rear Brakes   |                        |                      | 10020 INJECTOR CLEANER DON'T REORDER  | 1.00                      |        |
| - Complaint:Shake Over 60Mph Wash Mud Fr All Rims And Balance |                        |                      | 31-22 WIPER BLADES 22" WIPER BLADE    | 2.00                      |        |
| - Shop Supplies   |                        |                      | SHOP SUPPLIES                         | 1.00                      |        |
|   |                        |                      | 10W30 MOTOR OIL                       | 6.00                      |        |
| <b>Parts Charge:</b> 44.76                                    |                        | <b>Labor Charge:</b> | 108.00                                | <b>Commercial Charge:</b> | 115.20 |

**Workorder:** 838192

**Problem:** INSPECT FRONTEND/BRAKE NOISE

| Meter Reading: 17614   |                        | Labor                |                              | Parts    |  |
|--|------------------------|----------------------|------------------------------|----------|--|
| In Date: 05/07/2008  | Close Date: 05/15/2008 | Hours                | Description                  | Quantity |  |
| - Noise Fr Frt Suspension.Test Drive Diag Frt Hubs Bearing Remv & Repl Both Front Hubs Bearing W/New Test Drive Ok |                        | 6.00                 | FRONT BRAKE PAD SET          | 1.00     |  |
|  |                        |                      | SHOP SUPPLIES                | 1.00     |  |
|  |                        |                      | ANTISEIZE 405540005          | 1.00     |  |
| - Inspect Frt Brks-Brakes Worn Below Spec.Repl Pads Machine Rotors Libe Calipers Pins Bleed Brakes Test Drive.     |                        |                      | PD784 FRONT PADS             | 1.00     |  |
|  |                        |                      | WAGPD785 REAR PADS           | -1.00    |  |
|  |                        |                      | FRT BEARING HUB ASSY         | 2.00     |  |
|  |                        |                      | WAGPD785 REAR PADS           | 1.00     |  |
| - Shop Supplies  |                        |                      | 09997 BRAKE CLEAN            | 1.00     |  |
|  |                        |                      | 1401 BRAKE FLUID BRAKE FLUID | 1.00     |  |
|  |                        |                      | PD784 FRONT PADS             | -1.00    |  |
| <b>Parts Charge:</b> 713.98  |                        | <b>Labor Charge:</b> | 210.00                       |          |  |

**Workorder:** 840851

**Problem:** INSPECT WINCH & CABLE

| Meter Reading: 18949   |                        | Labor                |               | Parts                     |       |
|--|------------------------|----------------------|---------------|---------------------------|-------|
| In Date: 07/02/2008  | Close Date: 07/10/2008 | Hours                | Description   | Quantity                  |       |
| - Inspect Winch & Cable.Cable Frayed R&R W/New.Reinstall,Lube Rollers. |                        | 1.50                 | SHOP SUPPLIES | 1.00                      |       |
| - Shop Supplies  |                        |                      |               |                           |       |
| <b>Parts Charge:</b> 2.00  |                        | <b>Labor Charge:</b> | 90.00         | <b>Commercial Charge:</b> | 90.00 |

10/17/2016  
11:24:23AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162778 2006 GMC 1500 Pickup, 1/2 Ton, 4X4, W/Winch, 8 Ft. Bed

Workorder: 842154

Problem: P.M. SERVICE.

| Meter Reading: 19537  | Labor  | Parts                                 |          |
|---|--------|---------------------------------------|----------|
| In Date: 07/30/2008   | Hours  | Description                           | Quantity |
| - Pm Service  | 13.25  | 31-22 WIPER BLADES 22" WIPER BLADE    | 2.00     |
| - Replace Trailer Hitch Safety Chain.   |        | 18410 PINTLE PIN                      | 1.00     |
| - Service Transmission.Flush.   |        | PH3387A OIL FILTER LBF PH47 WIX 51040 | 1.00     |
| - Replace Frozen Wheel Cylinders,Rear Brake Shoes & Resurface Drums. Bleed Out And Flush System.Test Drive. |        | USED FIREX REFURBED FIRE EXTINGSHERS  | 1.00     |
| - Front End Alignment. Complete.  |        | 09997 BRAKE CLEAN                     | 1.00     |
| - Service Vehicle Winch.  |        | 1401 BRAKE FLUID BRAKE FLUID          | 1.00     |
| - Complaint:Steering Noise.R&R Steering Column Intermediate Shaft And Lubricate To Stop Noise.              |        | SYN/ATF TRANS FLUID SYNTHETIC         | 12.00    |
| - Shop Supplies   |        | WHEEL CYLINDER                        | 2.00     |
|   |        | 10W30 MOTOR OIL                       | 5.00     |
|   |        | SHOP SUPPLIES                         | 1.00     |
|   |        | REAR BRAKE SHOE SET                   | 1.00     |
| <b>Parts Charge:</b>  | 272.04 | <b>Labor Charge:</b>                  | 60.00    |

Workorder: 934564

Problem: P.M SERVICE

| Meter Reading: 22469                                    | Labor | Parts                                 |          |
|---|-------|---------------------------------------|----------|
| In Date: 02/27/2009                                     | Hours | Description                           | Quantity |
| - Pm Service  | 5.75  | 10W30 MOTOR OIL                       | 5.00     |
| - Service Winch.  |       | 6678 AIR FILTER FRM CA8755A WIX 46678 | 1.00     |
| - Service Rear Brakes.                                  |       | PH3387A OIL FILTER LBF PH47 WIX 51040 | 1.00     |
| - Rotate And Hi Speed Balance 4 Tires, Nitrofill Tires. |       | 31-22 WIPER BLADES 22" WIPER BLADE    | 2.00     |
| - Shop Supplies   |       | SHOP SUPPLIES                         | 1.00     |
| <b>Parts Charge:</b>                                    | 38.31 | <b>Labor Charge:</b>                  | 345.00   |

10/17/2016  
11:24:23AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162778 2006 GMC 1500 Pickup, 1/2 Ton, 4X4, W/Winch, 8 Ft. Bed

**Workorder:** 946596

**Problem:** P.M service, pulls right, brakes pulsate, noise in steering

| Meter Reading: 27141<br>In Date: 12/02/2009  | Close Date: 12/16/2009 | Labor<br>Hours | Description                           | Parts | Quantity |
|--|------------------------|----------------|---------------------------------------|-------|----------|
| - P.M Service.   |                        | <b>14.75</b>   | BRAKE DRUMS 81-126267                 |       | 2.00     |
| - Test Starting & Charging System, Charge & Test Battery,<br>Fail Load Test.Replace Defective Battery.                                     |                        |                | SHOP SUPPLIES                         |       | 1.00     |
| - Diagnose Noise In Steering, Replace Intermediate<br>Steering Shaft.  |                        |                | PH3387A OIL FILTER LBF PH47 WIX 51040 |       | 1.00     |
| - Machine Both Front Brake Rotors, Replace Both Rear<br>Drums, Service Front Caliper Assemblies, Service Rear<br>Drum Brakes & Test Drive. |                        |                | 31-22 WIPER BLADES 22" WIPER BLADE    |       | 2.00     |
| - Alignment.   |                        |                | STEERING SHAFT 19153614               |       | 1.00     |
| - Inspect & Service Winch.   |                        |                | GROUP 78 BATTERY (ACD 78PS)           |       | 1.00     |
| - Repair R/R Tire, Rotate & Balance All Four Tires.  |                        |                | 10W30 MOTOR OIL                       |       | 5.00     |
| - Shop Supplies  |                        |                | USED FIREX REFURBED FIRE EXTINGSHERS  |       | 1.00     |
| <b>Parts Charge:</b>   |                        | 343.80         | <b>Labor Charge:</b>                  |       | 1,770.00 |

**Workorder:** 1004011

**Problem:** Right front tire flat.

| Meter Reading: 28637<br>In Date: 04/19/2010 | Close Date: 04/21/2010 | Labor<br>Hours | Description          | Parts | Quantity |
|---|------------------------|----------------|----------------------|-------|----------|
| - Repair R/F Tire.                          |                        | <b>1.00</b>    | SHOP SUPPLIES        |       | 1.00     |
| - Shop Supplies                             |                        |                |                      |       |          |
| <b>Parts Charge:</b>                        |                        | 2.00           | <b>Labor Charge:</b> |       | 60.00    |

10/17/2016  
11:24:23AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162778 2006 GMC 1500 Pickup, 1/2 Ton, 4X4, W/Winch, 8 Ft. Bed

**Workorder:** 1007458

**Problem:** P.M. Service.

| Meter Reading: 30483<br>In Date: 07/14/2010  | Close Date: 07/30/2010 | Labor<br>Hours | Description                              | Parts | Quantity |
|--|------------------------|----------------|--|-------|----------|
| - Perform Pm Service.  |                        | 10.25          | 15-81683 BLOWER MOTOR (ACD)              |       | 1.00     |
| - Service Power Winch And Replace Failed Fair Lead Roller Assembly With New.                                 |                        |                | 22807123 RESISTOR BLOWER MOTOR (ACD)     |       | 1.00     |
|  |                        |                | PT2195 PIGTAIL BLOWER MOTOR (ACD)        |       | 1.00     |
| - Pressure Test And Inspect Cooling System.Reverse Flush And Renew Coolant.                                  |                        |                | SHOP SUPPLIES                            |       | 1.00     |
|  |                        |                | PH3387A OIL FILTER LBF PH47 WIX 51040    |       | 1.00     |
| - Diagnose Ac Blower Inop.On Fifth Speed.Test And Replace Failed Blower Motor,Resistor And Harness With New. |                        |                | 31-22 WIPER BLADES 22" WIPER BLADE       |       | 2.00     |
|  |                        |                | ANTIFREEZE EXT/LIFE ALL MAKES (PEAK 407) |       | 2.00     |
|  |                        |                | PRF116 COOLANT FLUSH                     |       | 1.00     |
| - Rotate And Balance All Four Tires.   |                        |                | 6678 AIR FILTER FRM CA8755A WIX 46678    |       | 1.00     |
|  |                        |                | 10W30 MOTOR OIL                          |       | 5.00     |
| - Perform Rear Drum Brakes Service And Adjust Brake Shoes.   |                        |                | FAIRLEAD ROLLER WARN WINCH               |       | 1.00     |
| - Shop Supplies  |                        |                |  |       |          |
| <b>Parts Charge:</b>   |                        | 537.33         | <b>Labor Charge:</b>                     |       | 615.00   |

**Workorder:** 1012527

**Problem:** Pm service.

| Meter Reading: 33274<br>In Date: 11/08/2010                      | Close Date: 11/17/2010 | Labor<br>Hours | Description                                    | Parts | Quantity |
|--|------------------------|----------------|--|-------|----------|
| - Perform Pm Service.  |                        | 6.75           | 10W30 MOTOR OIL                                |       | 5.00     |
| - Inspect And Replace Both Failed Rear Shock Absorbers With New. |                        |                | L0135-063 LUBRIPLATE CHAIN&CABLE LUBE,03050CRC |       | 1.00     |
|  |                        |                | SYN/ATF TRANS FLUID SYNTHETIC                  |       | 1.00     |
| - Inspect And Service Power Winch.                               |                        |                | SHOP SUPPLIES                                  |       | 1.00     |
| - Perform Rear Drum Brakes Service And Adjust Brake Shoes.       |                        |                | REAR SHOCK ABSORBER                            |       | 2.00     |
|  |                        |                | PH3387A OIL FILTER LBF PH47 WIX 51040          |       | 1.00     |
| - Rotate And Balance All Four Tires.                             |                        |                | USED FIREX REFURBED FIRE EXTINGSHERS           |       | 1.00     |
| - Shop Supplies  |                        |                |  |       |          |
| <b>Parts Charge:</b>   |                        | 167.80         | <b>Labor Charge:</b>                           |       | 405.00   |

10/17/2016  
11:24:23AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162778 2006 GMC 1500 Pickup, 1/2 Ton, 4X4, W/Winch, 8 Ft. Bed

**Workorder:** 1105226

**Problem:** P.M. service.

| Meter Reading: 37672<br>In Date: 05/17/2011              | Close Date: 05/26/2011 | Labor<br>Hours | Description                           | Parts | Quantity |
|--|------------------------|----------------|---------------------------------------|-------|----------|
| - Perform Pm Service.                                    |                        | 7.75           | PH3387A OIL FILTER LBF PH47 WIX 51040 |       | 1.00     |
| - Test Starting And Charging System.Battery Failed Load  |                        |                | USED FIREX REFURBED FIRE EXTINGSHERS  |       | 1.00     |
| - Test After Recharge.Replace Failed Battery With New.   |                        |                | 10W30 MOTOR OIL                       |       | 5.00     |
| - Remove New Spare Tire From Black Wheel And Muont       |                        |                | GROUP 78 BATTERY (ACD 78PS)           |       | 1.00     |
| - On To Regular Wheel.Install Second Tire From Shop Rack |                        |                | 31-22 WIPER BLADES 22" WIPER BLADE    |       | 2.00     |
| - To Match New Tire.Nitrogen Fill And Balance All .      |                        |                | SHOP SUPPLIES                         |       | 1.00     |
| - Inspect And Service Power Winch.                       |                        |                | 6678 AIR FILTER FRM CA8755A WIX 46678 |       | 1.00     |
| - Perform Rear Drum Brakes Service And Adjust Brake      |                        |                |                                       |       |          |
| - Shoes.   |                        |                |                                       |       |          |
| - Shop Supplies  |                        |                |                                       |       |          |
| <b>Parts Charge:</b>                                     |                        | 159.70         | <b>Labor Charge:</b>                  |       | 465.00   |

**Workorder:** 1106745

**Problem:** damage to rgt side of bed, tail gate & bed rail covers

| Meter Reading: 37991<br>In Date: 06/13/2011              | Close Date: 06/27/2011 | Labor<br>Hours | Description               | Parts | Quantity |
|--|------------------------|----------------|---------------------------|-------|----------|
| - Damage To Rgt Side Of Bed, Tail Gate & Bed Rail Covers |                        |                |                           |       |          |
| <b>Parts Charge:</b>                                     |                        | 0.00           | <b>Labor Charge:</b>      |       | 0.00     |
|  |                        |                | <b>Commercial Charge:</b> |       | 1,221.80 |

**Workorder:** 1108208

**Problem:** Trailer lights are inop from connector.

| Meter Reading: 39082<br>In Date: 08/04/2011             | Close Date: 08/09/2011 | Labor<br>Hours | Description                             | Parts | Quantity |
|---|------------------------|----------------|---|-------|----------|
| - Replace Trailer Plug And Repair Harness.Replace Blown |                        | 1.50           | 5404 FEMALE CONNECTOR                   |       | 1.00     |
| - Fuse.   |                        |                | 06133 3M ELECTRIC TAPE STOCK #832260101 |       | 1.00     |
| - Shop Supplies   |                        |                | SHOP SUPPLIES                           |       | 1.00     |
| <b>Parts Charge:</b>                                    |                        | 16.00          | <b>Labor Charge:</b>                    |       | 90.00    |

**Workorder:** 1109463

**Problem:** flat tire repair

| Meter Reading: 39819<br>In Date: 08/25/2011 | Close Date: 09/02/2011 | Labor<br>Hours | Description               | Parts | Quantity |
|---|------------------------|----------------|---------------------------|-------|----------|
| - Okee W Of 441-Go North-On West Side       |                        |                |                           |       |          |
| <b>Parts Charge:</b>                        |                        | 0.00           | <b>Labor Charge:</b>      |       | 0.00     |
|   |                        |                | <b>Commercial Charge:</b> |       | 175.73   |

10/17/2016  
11:24:23AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162778 2006 GMC 1500 Pickup, 1/2 Ton, 4X4, W/Winch, 8 Ft. Bed

**Workorder:** 1109464                      **Problem:** service

| Meter Reading: 39819      | Labor                     | Parts                           |
|---------------------------|---------------------------|---------------------------------|
| In Date: 08/30/2011       | Hours                     | Description                     |
| Close Date: 09/02/2011    |                           | Quantity                        |
| - 441 N Of Okeechobee     |                           |                                 |
| <b>Parts Charge:</b> 0.00 | <b>Labor Charge:</b> 0.00 | <b>Commercial Charge:</b> 54.00 |

**Workorder:** 1112081                      **Problem:** P.M. service .

| Meter Reading: 41685                                      | Labor                       | Parts                                      |
|---|-----------------------------|--|
| In Date: 11/10/2011                                       | Hours                       | Description                                |
| Close Date: 11/21/2011                                    |                             | Quantity                                   |
| - Perform Pm Service.                                     | 9.25                        | SHOP SUPPLIES 1.00                         |
| - Install Two New Tires To The Front Wheels.Nitrogen Fill |                             | TR416 VALVE STEM 2.00                      |
| And Balance All Four.                                     |                             | 31-22 WIPER BLADES 22" WIPER BLADE 2.00    |
| - Perform Wheel Alignment Complete.                       |                             | PH3387A OIL FILTER LBF PH47 WIX 51040 1.00 |
| - Inspect And Service Power Winch.                        |                             | 10W30 MOTOR OIL 5.00                       |
| - Perform Rear Drum Brake Service And Adjust Brake        |                             | 179469492 LT245/70R17 WRANGLER SR-A E 2.00 |
| Shoes.  |                             | TIRE DISPOSAL FEE 2.00                     |
| - Shop Supplies   |                             |  |
| <b>Parts Charge:</b> 367.58                               | <b>Labor Charge:</b> 555.00 |  |

**Workorder:** 1200959                      **Problem:** Flat tire.Repair bed rail.

| Meter Reading: 43737                 | Labor                      | Parts              |
|--------------------------------------|----------------------------|--------------------|
| In Date: 01/30/2012                  | Hours                      | Description        |
| Close Date: 02/08/2012               |                            | Quantity           |
| - Repair And Balance Left Rear Tire. | 1.50                       | SHOP SUPPLIES 1.00 |
| - Reglue Bed Rail Proptectors.       |                            |                    |
| - Shop Supplies                      |                            |                    |
| <b>Parts Charge:</b> 2.00            | <b>Labor Charge:</b> 90.00 |                    |

**Workorder:** 1200962                      **Problem:** repair or put on spare

| Meter Reading: 43505  | Labor                     | Parts                           |
|---|---------------------------|---------------------------------|
| In Date: 01/30/2012   | Hours                     | Description                     |
| Close Date: 01/30/2012  |                           | Quantity                        |
| - Tire Service Vista Garage/ 5Th Floor - Repair Or Put On Spare |                           |                                 |
| <b>Parts Charge:</b> 0.00                                       | <b>Labor Charge:</b> 0.00 | <b>Commercial Charge:</b> 62.70 |



10/17/2016  
11:24:23AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162778 2006 GMC 1500 Pickup, 1/2 Ton, 4X4, W/Winch, 8 Ft. Bed

**Workorder:** 1204312

**Problem:** P.M. Service.

| Meter Reading: 46322              | Labor | Parts                                 |          |  |
|-----------------------------------|-------|---------------------------------------|----------|--|
| In Date: 05/07/2012               | Hours | Description                           | Quantity |  |
| - P.M. Service.                   | 4.75  | PH3387A OIL FILTER LBF PH47 WIX 51040 | 1.00     |  |
| - Inspect And Service Winch.      |       | 10W30 MOTOR OIL                       | 5.00     |  |
| - Service And Adjust Rear Brakes. |       | 31-22 WIPER BLADES 22" WIPER BLADE    | 2.00     |  |
| - Shop Supplies                   |       | SHOP SUPPLIES                         | 1.00     |  |
| <b>Parts Charge:</b> 26.46        |       | <b>Labor Charge:</b> 285.00           |          |  |

**Workorder:** 1206956

**Problem:** Dome light stay on all the time.

| Meter Reading: 48112  | Labor | Parts                                |          |  |
|---|-------|--------------------------------------|----------|--|
| In Date: 07/26/2012   | Hours | Description                          | Quantity |  |
| - Computer Diagnose For Dome Light On All The Time.Pin Point Test And Replace Failed Body Control Unit With New.Had To Reprogram Passlock And Configure Air Bag System With Tech 2 Pass Thru. | 7.50  | 22807123 RESISTOR BLOWER MOTOR (ACD) | 1.00     |  |
|   |       | BODY CONTROL MODULE                  | 1.00     |  |
|   |       | SHOP SUPPLIES                        | 1.00     |  |
| - Diagnose Blower Motor #3 Speed Inop.Test And Replace Failed Blower Motor Resistor With New.   |       |                                      |          |  |
| - Perform Wheel Alignment Complete To Correct Strong Left Pull When Driving On A Level Road Way.  |       |                                      |          |  |
| - Shop Supplies   |       |                                      |          |  |
| <b>Parts Charge:</b> 289.18   |       | <b>Labor Charge:</b> 450.00          |          |  |

**Workorder:** 1210154

**Problem:** damage to rear cab panel & window

| Meter Reading: 49198                | Labor | Parts                     |          |                                  |
|-------------------------------------|-------|---------------------------|----------|----------------------------------|
| In Date: 10/01/2012                 | Hours | Description               | Quantity |                                  |
| - Damage To Rear Cab Panel & Window |       |                           |          |                                  |
| <b>Parts Charge:</b> 0.00           |       | <b>Labor Charge:</b> 0.00 |          | <b>Commercial Charge:</b> 769.38 |

10/17/2016  
11:24:23AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162778 2006 GMC 1500 Pickup, 1/2 Ton, 4X4, W/Winch, 8 Ft. Bed

**Workorder:** 1210899

**Problem:** Pm service.

| Meter Reading: 49526                                   | Labor        | Parts                 |          |
|--|--------------|-----------------------|----------|
| In Date: 11/07/2012                                    | Hours        | Description           | Quantity |
| - Perform Pm Service.                                  | <b>16.00</b> | USED FIREX REFURBED F | 1.00     |
| - Install New Front Brake Pads,Rotors, Both New Front  |              | 10W30 MOTOR OIL       | 5.00     |
| Wheel Bearing Hub Assemblies,New Rear Shoe,Drums       |              | 3157 TAIL LIGHT BULBS | 2.00     |
| And Wheel Cylinders.Service Calipers.Flush Brake Fluid |              | FRONT ROTOR           | 2.00     |
| And Bleed Hydraulic System.                            |              | 2232 BRAKE FLUID QUAR | 1.00     |
| - Test And Replace Failed Right Reverse Lamp Bulb With |              | SHOP SUPPLIES         | 1.00     |
| New.   |              | BRAKE PADS            | 1.00     |
| - Inspect And Service Power Winch.                     |              | OIL FILTER            | 1.00     |
| - Rotate And Balance All Four Tires.                   |              | FRONT ROTORS          | 2.00     |
| - Make Up And Replace Unreadable Front Asset Numbers   |              | HUB ASSEMBLY          | 2.00     |
| And Missing Decals.                                    |              | REAR SHOES            | 1.00     |
| - Shop Supplies  |              | WHEEL CYLINDER        | 2.00     |
|  |              | FRONT PADS            | 1.00     |
|  |              | REAR DRUMS            | 2.00     |
|  |              | 05088 BRAKE CLEAN     | 1.00     |
|  |              | 31-22 WIPER BLADES 22 | 2.00     |
| <b>Parts Charge:</b>                                   | 867.38       | <b>Labor Charge:</b>  | 960.00   |

**Workorder:** 1301204

**Problem:** Check engine light on.

| Meter Reading: 50202                                   | Labor       | Parts                |          |
|--|-------------|----------------------|----------|
| In Date: 02/01/2013                                    | Hours       | Description          | Quantity |
| - Computer Diagnose For Check Engine Light On.Test And | <b>3.00</b> | SHOP SUPPLIES        | 1.00     |
| Replace Failed Thermostat With New.Reverse Flush And   |             | PEAK GLOBAL ANTIFRZ  | 1.00     |
| Renew Engine Coolant.Clear Codes With Scan Tool And    |             | THERMOSTAT           | 1.00     |
| Road Test.   |             |                      |          |
| - Shop Supplies  |             |                      |          |
| <b>Parts Charge:</b>                                   | 30.25       | <b>Labor Charge:</b> | 180.00   |

10/17/2016  
11:24:23AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162778 2006 GMC 1500 Pickup, 1/2 Ton, 4X4, W/Winch, 8 Ft. Bed

**Workorder:** 1306429

**Problem:** Pm service.

| Meter Reading: 53242        |                                 | Labor                       |                     | Parts |          |
|-----------------------------|---------------------------------|-----------------------------|---------------------|-------|----------|
| In Date: 06/26/2013         | Close Date: 07/17/2013          | Hours                       | Description         |       | Quantity |
| -                           | P.M. Service.                   | 6.25                        | 10W30 MOTOR OIL     |       | 5.00     |
| -                           | Install New Bed Caps.           |                             | PROTECTOR           |       | 1.00     |
| -                           | Rotate And Balance All Tires.   |                             | SHOP SUPPLIES       |       | 1.00     |
| -                           | Service And Adjust Rear Brakes. |                             | WIPER BLADE         |       | 2.00     |
| -                           | Inspect And Service Winch.      |                             | NAPAGOLD OIL FILTER |       | 1.00     |
| -                           | Shop Supplies                   |                             | NAPAGOLD AIR FILTER |       | 1.00     |
| <b>Parts Charge:</b> 218.27 |                                 | <b>Labor Charge:</b> 375.00 |                     |       |          |

**Workorder:** 1307870

**Problem:** Tow in,front brakes locking up.

| Meter Reading: 54298        |  | Labor                       |                       | Parts |          |
|-----------------------------|--|-----------------------------|-----------------------|-------|----------|
| In Date: 08/06/2013         | Close Date: 08/30/2013   | Hours                       | Description           |       | Quantity |
| -                           | Replace Both Front Calipers,Brake Hoses And Pads.Resurface Front Rotors.Flush And Bleed System And Test Drive. | 5.50                        | SHOP SUPPLIES         |       | 1.00     |
| -                           | Shop Supplies  |                             | REMAN BRAKE CALIPER   |       | 1.00     |
|                             |  |                             | REMAN BRAKE CALIPER   |       | 1.00     |
|                             |  |                             | BRAKE HOSE            |       | 10.00    |
|                             |  |                             | BRAKE HOSE            |       | 1.00     |
|                             |  |                             | BRAKE CLEANER         |       | 1.00     |
|                             |  |                             | CAP                   |       | 1.00     |
|                             |  |                             | 2232 BRAKE FLUID QUAR |       | 1.00     |
| <b>Parts Charge:</b> 389.86 |  | <b>Labor Charge:</b> 330.00 |                       |       |          |

**Workorder:** 1307913

**Problem:** Brakes not working, smoking from RF tire

| Meter Reading: 53936      |  | Labor                     |             | Parts                            |          |
|---------------------------|--|---------------------------|-------------|----------------------------------|----------|
| In Date: 08/06/2013       | Close Date: 08/07/2013                                       | Hours                     | Description |                                  | Quantity |
| -                         | Tow From: Jupiter Inlet/Lighthouse, Us1 & Beach Rd To: Vista |                           |             |                                  |          |
| <b>Parts Charge:</b> 0.00 |  | <b>Labor Charge:</b> 0.00 |             | <b>Commercial Charge:</b> 104.15 |          |

10/17/2016  
11:24:23AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162778 2006 GMC 1500 Pickup, 1/2 Ton, 4X4, W/Winch, 8 Ft. Bed

**Workorder:** 1400555

**Problem:** Pm service and check over RPM gauge.

| Meter Reading: 58338                                    | Labor  | Parts                   |          |
|---|--------|-------------------------|----------|
| In Date: 01/16/2014                                     | Hours  | Description             | Quantity |
| - P.M. Service.   | 8.75   | 10W30 MOTOR OIL         | 5.00     |
| - Test Battery And Charging System.Replace Bad Battery. |        | WIPER BLADE             | 2.00     |
| - Diagnose Erractic Engine Rpm.Replace Defective Idle   |        | GROUP 78 BATTERY        | 1.00     |
| - Control Solenoid.Repair Damage Engine Wiring Harness. |        | BP193 EXTENSION BOLT    | 1.00     |
| - Inspect And Service Winch.                            |        | BAT TERM PROTECTOR      | 1.00     |
| - Service And Adjust Rear Brakes.                       |        | NAPAGOLD OIL FILTER     | 1.00     |
| - Shop Supplies   |        | VINYL ELECTRICAL TAPE   | 1.00     |
|   |        | VALVE - IDLE AIR CTRL   | 1.00     |
|   |        | USED FIRE X REFURBISHED | 1.00     |
|   |        | SHOP SUPPLIES           | 1.00     |
| <b>Parts Charge:</b>                                    | 234.31 | <b>Labor Charge:</b>    | 525.00   |

**Workorder:** 1407626

**Problem:** Pm service.

| Meter Reading: 62233                    | Labor  | Parts                 |          |
|---|--------|-----------------------|----------|
| In Date: 08/01/2014                     | Hours  | Description           | Quantity |
| - Perform Pm Service.                   | 7.75   | 10W30 MOTOR OIL       | 5.00     |
| - Service Front Differential.           |        | NAPAGOLD OIL FILTER   | 1.00     |
| - Service Rear Differential.            |        | 1QT SYNGEAR OIL 75-90 | 3.00     |
| - Inspect And Service Power Winch.      |        | 1QT SYNGEAR OIL 75-90 | 3.00     |
| - Inspect And Service Rear Drum Brakes. |        | WIPER BLADE           | 2.00     |
| - Rotate And Balance All Four Tires.    |        | SHOP SUPPLIES         | 1.00     |
| - Shop Supplies                         |        |                       |          |
| <b>Parts Charge:</b>                    | 121.02 | <b>Labor Charge:</b>  | 465.00   |

**Workorder:** 1411865

**Problem:** Cannot open tail gate

| Meter Reading: 64587                                   | Labor | Parts                |          |
|--|-------|----------------------|----------|
| In Date: 11/24/2014                                    | Hours | Description          | Quantity |
| - Diagnose For Tail Gate Lock Inop.Remove Trim.Replace | 1.00  | SHOP SUPPLIES        | 1.00     |
| - Both Broken Handle Rod Clips And Adjust Linkage To   |       | DOOR CLIP            | 2.00     |
| - Open Tail Gate.                                      |       |                      |          |
| - Shop Supplies  |       |                      |          |
| <b>Parts Charge:</b>                                   | 11.54 | <b>Labor Charge:</b> | 60.00    |

10/17/2016  
11:24:23AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162778 2006 GMC 1500 Pickup, 1/2 Ton, 4X4, W/Winch, 8 Ft. Bed

**Workorder:** 1501939

**Problem:** Pm service.

| Meter Reading: 66002<br>In Date: 02/24/2015                                     | Close Date: 03/09/2015        | Labor<br>Hours              | Description             | Parts | Quantity |
|---|-------------------------------|-----------------------------|-------------------------|-------|----------|
| - Pm Service.   |                               | 12.75                       | 10W30 MOTOR OIL         |       | 5.00     |
| - Replace Rear Brake Shoes,Both Wheel Cylinders And<br>Two Brake Drums          |                               |                             | WIPER BLADE             |       | 2.00     |
|   |                               |                             | USED FIRE X REFURBISHED |       | 1.00     |
| - Inspect For Noise And Replace Defective Left Front Wheel<br>Bearing Assembly. |                               |                             | WHEEL CYLINDER          |       | 2.00     |
|   |                               |                             | BRAKE CLEANER           |       | 2.00     |
| - Replace Two Tires.Rotate And Balance All Four.                                |                               |                             | TR416 VALVE STEM        |       | 2.00     |
|   |                               |                             | NAPAGOLD OIL FILTER     |       | 1.00     |
| - Complete Front End Alignment.   |                               |                             | TIRE DISPOSAL FEE       |       | 2.00     |
|   |                               |                             | REMAN BRAKE SHOES       |       | 1.00     |
| - Shop Supplies   |                               |                             | NAPAGOLD AIR FILTER     |       | 1.00     |
|   |                               |                             | HUB BEARING ASSEMBLY    |       | 1.00     |
|   |                               |                             | 179469492 LT245-70R17   |       | 2.00     |
|   |                               |                             | BRAKE DRUM              |       | 2.00     |
|   |                               |                             | 245 70R17 AT ADVENTURE  |       | 2.00     |
|   |                               |                             | SHOP SUPPLIES           |       | 1.00     |
|   |                               |                             | 1401 BRAKE FLUID BRA    |       | 2.00     |
|   | <b>Parts Charge:</b> 1,045.24 | <b>Labor Charge:</b> 765.00 |                         |       |          |

**Workorder:** 1502059

**Problem:** 11 - Wash ticket(s) issued

| Meter Reading: 65933<br>In Date: 02/26/2015 | Close Date: 02/26/2015    | Labor<br>Hours            | Description                      | Parts | Quantity |
|---|---------------------------|---------------------------|----------------------------------|-------|----------|
| - 11 - Wash Ticket(S) Issued                |                           |                           |                                  |       |          |
|   | <b>Parts Charge:</b> 0.00 | <b>Labor Charge:</b> 0.00 | <b>Commercial Charge:</b> 104.94 |       |          |

10/17/2016  
11:24:23AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162778 2006 GMC 1500 Pickup, 1/2 Ton, 4X4, W/Winch, 8 Ft. Bed

**Workorder:** 1509251

**Problem:** Pm service

| Meter Reading: 70240                                       |                        | Labor  | Parts                 |          |
|--|------------------------|--------|-----------------------|----------|
| In Date: 09/15/2015  | Close Date: 09/28/2015 | Hours  | Description           | Quantity |
| - Pm Service.  |                        | 15.25  | IGNITION CAP          | 1.00     |
| - Replace Cracked Serpentine Belt.                         |                        |        | SET IGNITION WIRES    | 1.00     |
| - Flush Transfer Case And Replace Fluid.                   |                        |        | 10W30 MOTOR OIL       | 5.00     |
| - Check Starting And Charging System.Battery Failed        |                        |        | ROTOR                 | 1.00     |
| - Loadtest After Recharge.Replace Defective Battery.       |                        |        | NAPAGOLD OIL FILTER   | 1.00     |
| - Perform Tune Up.Replace Six Spark Plugs,Ignition         |                        |        | CONTROL ARM ASSEMBLY  | 1.00     |
| - Wires,Distributor Cap And Rotor.                         |                        |        | WIPER BLADE           | 2.00     |
| - Left Side Upper Ball Joint Failed.Replace Defective Left |                        |        | BP193 EXTENSION BOLT  | 1.00     |
| - Upper Control Arm Assembly.                              |                        |        | SERPENTINE BELT       | 1.00     |
| - Inspect And Service Winch.                               |                        |        | SHOP SUPPLIES         | 1.00     |
| - Inspect And Service Rear Brakes.                         |                        |        | SYN-ATF TRANS FLUID S | 2.00     |
| - Rotate And Balance All Four Tires.                       |                        |        | GROUP 78 BATTERY      | 1.00     |
| - Complete Front End Alignment.                            |                        |        | SPARK PLUG ASM        | 6.00     |
| - Shop Supplies  |                        |        |                       |          |
| <b>Parts Charge:</b>                                       |                        | 405.77 | <b>Labor Charge:</b>  | 915.00   |

**Workorder:** 1512342

**Problem:** Right rear turn signal inop.

| Meter Reading: 71685                                    |                        | Labor | Parts                |          |
|---|------------------------|-------|----------------------|----------|
| In Date: 12/07/2015                                     | Close Date: 12/09/2015 | Hours | Description          | Quantity |
| - Test And Replace Defective Right Rear Turnsignal Lamp |                        | 0.50  | BULB                 | 1.00     |
| - Bulb.   |                        |       |                      |          |
| <b>Parts Charge:</b>                                    |                        | 0.75  | <b>Labor Charge:</b> | 30.00    |

**Workorder:** 1600085

**Problem:** Right rear tire fat.

| Meter Reading: 72806                  |                        | Labor | Parts                |          |
|---------------------------------------|------------------------|-------|----------------------|----------|
| In Date: 01/05/2016                   | Close Date: 01/05/2016 | Hours | Description          | Quantity |
| - Repair And Balance Right Rear Tire. |                        | 1.00  | SHOP SUPPLIES        | 1.00     |
| - Shop Supplies                       |                        |       |                      |          |
| <b>Parts Charge:</b>                  |                        | 2.00  | <b>Labor Charge:</b> | 60.00    |

10/17/2016  
11:24:23AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162778 2006 GMC 1500 Pickup, 1/2 Ton, 4X4, W/Winch, 8 Ft. Bed

**Workorder:** 1600972                      **Problem:** replace cracked windsheild

| Meter Reading: 72976         | Labor | Parts         |                           |  |        |
|------------------------------|-------|---------------|---------------------------|--|--------|
| In Date: 01/28/2016          | Hours | Description   | Quantity                  |  |        |
| - Set Up Repairs And Reasset | 1.00  | SHOP SUPPLIES | 1.00                      |  |        |
| - Shop Supplies              |       |               |                           |  |        |
| <b>Parts Charge:</b>         |       | 2.00          | <b>Labor Charge:</b>      |  | 60.00  |
|                              |       |               | <b>Commercial Charge:</b> |  | 179.71 |

**Workorder:** 1603133                      **Problem:** Pm service.Left rear tire flat.

| Meter Reading: 73333                                 | Labor | Parts               |                      |  |        |
|--|-------|---------------------|----------------------|--|--------|
| In Date: 03/24/2016                                  | Hours | Description         | Quantity             |  |        |
| - Pm Service.  | 6.75  | 10W30 MOTOR OIL     | 5.00                 |  |        |
| - Repair Left Rear Tire.Rotate And Balance All Four. |       | NAPAGOLD OIL FILTER | 1.00                 |  |        |
| - Service Rear Brakes.                               |       | 22" WIPER BLADE     | 2.00                 |  |        |
| - Inspect And Service Winch.                         |       | SHOP SUPPLIES       | 1.00                 |  |        |
| - Shop Supplies                                      |       |                     |                      |  |        |
| <b>Parts Charge:</b>                                 |       | 24.47               | <b>Labor Charge:</b> |  | 405.00 |

**Workorder:** 1604069                      **Problem:** ABS light stays on

| Meter Reading: 73362                        | Labor | Parts                |                      |  |        |
|---|-------|----------------------|----------------------|--|--------|
| In Date: 04/18/2016                         | Hours | Description          | Quantity             |  |        |
| - Diagnose Abs Light.C0040-Shorted Speed    | 2.50  | SHOP SUPPLIES        | 1.00                 |  |        |
| Sensor.Replace Right Front Hub/Speed Sensor |       | HUB BEARING ASSEMBLY | 1.00                 |  |        |
| Assemble.Clead Code.                        |       |                      |                      |  |        |
| - Shop Supplies                             |       |                      |                      |  |        |
| <b>Parts Charge:</b>                        |       | 197.84               | <b>Labor Charge:</b> |  | 150.00 |

**Workorder:** 1604228                      **Problem:** damage to frt bumper & hood

| Meter Reading: 73357          | Labor | Parts       |                           |  |          |
|-------------------------------|-------|-------------|---------------------------|--|----------|
| In Date: 04/01/2016           | Hours | Description | Quantity                  |  |          |
| - Damage To Frt Bumper & Hood |       |             |                           |  |          |
| <b>Parts Charge:</b>          |       | 0.00        | <b>Labor Charge:</b>      |  | 0.00     |
|                               |       |             | <b>Commercial Charge:</b> |  | 1,197.60 |

10/17/2016  
11:24:23AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10162778 2006 GMC 1500 Pickup, 1/2 Ton, 4X4, W/Winch, 8 Ft. Bed

**Workorder:** 1609052

**Problem:** cut off hitch, install new lock

| <b>Meter Reading:</b> 76367      | <b>Labor</b>               | <b>Parts</b>       |                 |
|----------------------------------|----------------------------|--------------------|-----------------|
| <b>In Date:</b> 08/31/2016       | <b>Hours</b>               | <b>Description</b> | <b>Quantity</b> |
| - Cut Off Hitch Pin. Replce Lock | <b>0.50</b>                | HITCH PIN LOCK     | 1.00            |
| <b>Parts Charge:</b> 13.56       | <b>Labor Charge:</b> 30.00 |                    |                 |

**Workorder:** 1609202

**Problem:** Transition Prep Charge

| <b>Meter Reading:</b> 76367 | <b>Labor</b>              | <b>Parts</b>       |                 |
|-----------------------------|---------------------------|--------------------|-----------------|
| <b>In Date:</b> 09/02/2016  | <b>Hours</b>              | <b>Description</b> | <b>Quantity</b> |
| - Transition Prep Charge    | <b>2.00</b>               |                    |                 |
| <b>Parts Charge:</b> 0.00   | <b>Labor Charge:</b> 0.00 |                    |                 |

|                      |                 |                      |                  |                      |                 |
|----------------------|-----------------|----------------------|------------------|----------------------|-----------------|
| Total Parts Charges: | <b>6,821.07</b> | Total Labor Charges: | <b>11,438.00</b> | Total Comm. Charges: | <b>5,955.01</b> |
|----------------------|-----------------|----------------------|------------------|----------------------|-----------------|