Total Hours: 149.00 Labor: 9,996.00	Parts: 7,909.64	Comm: 8,220.92	Charged: 26	126.56
Work Order: 1410553 Me Problem: have windows tented	er: 324		In Date: 10/22/2014 Cic	osed: 10/31/2014
Work Completed		Parts Issued		Quantity
- Set up window tinting-deliver and pie	:k up	Floor Mat Kit		1.00
- Shop Supplies		Shop Supplies		1.00
Hours: 1.00	Comm: 138.00	Labor: 60.00	Parts: 116.12	Total: 314.12
Work Order: 1410697 Me Problem: 1061 - Pre Delivery Inspect	er: 324 ion		In Date: 10/27/2014 Cic	osed: 10/27/2014
Work Completed				
- Pre Delivery Inspection				
Hours: 2.00	Comm: 0.00	Labor: 120.00	Parts: 0.00	Total: 120.00
Work Order: 1412064 Me Problem: 1 - Wash ticket(s) issued	er: 2498		In Date: 12/02/2014 Clo	osed: 12/02/2014
Work Completed				
- 1 - Wash ticket(s) issued				
Hours: 0.00	Comm: 8.51	Labor: 0.00	Parts: 0.00	Total: 8.51
Work Order: 1412067 Me Problem: 10 - Wash ticket(s) issued	er: 2498		In Date: 12/02/2014 Clo	osed: 12/02/2014
Work Completed				
- 10 - Wash ticket(s) issued				
Hours: 0.00	Comm: 85.08	Labor: 0.00	Parts: 0.00	Total: 85.08
Work Order: 1502077 Me Problem: P.M. Service.Detail.	er: 6033		In Date: 02/26/2015 Clo	osed: 02/28/2015
Work Completed		Parts Issued		Quantity
- Pm service.		Napa Quart 5w30		6.00
- Rotate and balance all four tires.		Napagold Oil Filter		1.00
- Shop Supplies		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 27.53	Total: 207.53

Work Order: 1502344 Problem: 1 - Detail Vehicle Wash Ticket(s) Is:	Meter: sued	6166		In Date:	03/04/2015	Closed:	03/04/2015
Work Completed							
- 1 - Detail Vehicle Wash Ticket(s) Issued							
Hours: 0.00		Comm: 90.00	Labor: 0.00	Parts: 0.0	0	Total:	90.00
Work Order: 1503263	Meter:	8097		In Date:	03/30/2015	Closed:	03/31/2015
Problem: Right front tire flat							
Work Completed			Parts Issued			Qı	uantity
- Repair flat and balance right front tire.			Shop Supplies				1.00
- Shop Supplies							
Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 2.0	0	Total:	62.00
Work Order: 1505878 Problem: Pm service.TPMS warning light on.	Meter:	11709		In Date:	06/12/2015	Closed:	06/16/2015
Work Completed			Parts Issued			Qı	uantity
- Pm service.			Oil Syn Motorcraft				6.00
- Rotate and balance all four tires.			Napagold Oil Filter				1.00
- Shop Supplies			Shop Supplies				1.00
Hours: 3.00		Comm: 0.00	Labor: 180.00	Parts: 63.	08	Total:	243.08
Work Order: 1506240 Problem: 10 - Wash ticket(s) issued	Meter:	12435		In Date:	06/22/2015	Closed:	06/22/2015
Work Completed							
- 10 - Wash ticket(s) issued							
Hours: 0.00		Comm: 83.40	Labor: 0.00	Parts: 0.0	0	Total:	83.40
Work Order: 1507062 Problem: Rear tires has screws.	Meter:	13487		In Date:	07/15/2015	Closed:	07/21/2015
Work Completed			Parts Issued			Qı	uantity
- Repair and balance both rear tires.			Shop Supplies				1.00
- Shop Supplies							
Hours: 2.00		Comm: 0.00	Labor: 120.00	Parts: 2.0	0	Total:	122.00

Work Order: Problem:	1509623 Pm service.	Meter:	17486		In Date:	09/23/2015	Closed:	09/28/2015
Work Com	pleted			Parts Issued			Qı	uantity
- Pm servio	ce.			Oil Syn Motorcraft				6.00
- Rotate ar	nd balance all four tires.			Napagold Oil Filter				1.00
- Shop Sup	oplies			Washer Fluid Concer	ntr			1.00
				Shop Supplies				1.00
	Hours: 3.00		Comm: 0.00	Labor: 180.00	Parts: 64.	81	Total:	244.81
Nork Order: Problem:	1509711 1 - Detail Vehicle Wash Ticke	Meter: t(s) Issued	17265		In Date:	09/25/2015	Closed:	09/25/201
Work Com	pleted							
- 1 - Detai	Vehicle Wash Ticket(s) Issued							
	Hours: 0.00		Comm: 90.00	Labor: 0.00	Parts: 0.0	0	Total:	90.00
Nork Order: Problem:	1511607 Tire Pressure Light On.	Meter:	20324		In Date:	11/12/2015	Closed:	11/16/201
Work Com	pleted			Parts Issued			Qu	uantity
- Replace a	and balance both rear tires.(na	l in inside sidew	alls)	Tire				2.00
- Shop Sup	oplies			Shop Supplies				1.00
				Tire Disposal Fee				2.00
	Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 558	3.03	Total:	618.03
Work Order: Problem:	1600150 P.M. Service.Detail	Meter:	23842		In Date:	01/06/2016	Closed:	01/19/2016
Work Com	pleted			Parts Issued			Qı	uantity
- Pm servio	ce.			Napa Syn 5w30 Qt				6.00
- Rotate ar	nd balance all four tires.			Napagold Oil Filter				1.00
- Shop Sup	oplies			Blades				1.00
				Blades				1.00
				Shop Supplies				1.00
							Total:	

Nork Order: Problem:	1600222 1 - Detail Vehicle Wash Tick	Meter: et(s) Issued	23312		In Date:	01/07/2016	Closed:	01/07/2016
Work Com								
	· I Vehicle Wash Ticket(s) Issued	4						
	Hours: 0.00	•	Comm: 90.00	Labor: 0.00	Parts: 0.00)	Total:	90.00
Work Order: Problem:	1605795 P.M. Service.Detail	Meter:	31239		In Date:	06/06/2016	Closed:	06/17/2016
Work Com	pleted			Parts Issued			Qı	antity
- P.m. Serv	vice.			Napa Quart 5w30				6.00
- Test battery and charging system.recharge and retest battery,fail load		attery,fail load	Washer Fluid Conc	entr			1.00	
	e defective battery.	5		Napagold Oil Filter				1.00
- Replace t	two damaged tires,rotate and	balance all four.		Wiper Blade				2.00
- Shop Sup	oplies			Battery 65				1.00
				Tire				2.00
				Accufit Beam				1.00
				Shop Supplies				1.00
				Tire Disposal Fee				2.00
	Hours: 5.00		Comm: 0.00	Labor: 300.00	Parts: 779	.73	Total:	1,079.73
Work Order: Problem:	1606475 1 - Wash ticket(s) issued	Meter:	31885		In Date:	06/24/2016	Closed:	06/24/2016
Work Com	pleted							
- 1 - Wash	ticket(s) issued							
	Hours: 0.00		Comm: 8.34	Labor: 0.00	Parts: 0.00)	Total:	8.34

Work Order: 1609496 Problem: P.M. Service.	Meter:	36462		In Date:	09/13/2016	Closed:	09/27/2016
Work Completed			Parts Issued			Qı	uantity
- P.m. Service.			Napa Quart 5w30				6.00
- Replace both leaking rear shocks.			Napagold Oil Filter				1.00
- Rotate and balance all tires.			Wiper Blade				1.00
- Shop Supplies			Accufit Beam				1.00
			Shock Absorber Real				2.00
			Shop Supplies				1.00
Hours: 4.00		Comm: 0.00	Labor: 240.00	Parts: 271	.43	Total:	511.43
Work Order: 1609975 Problem: 1 - Wash ticket(s) issued	Meter:	36462		In Date:	09/23/2016	Closed:	09/23/2016
Work Completed							
- 1 - Wash ticket(s) issued							
Hours: 0.00		Comm: 8.51	Labor: 0.00	Parts: 0.0	0	Total:	8.51
Work Order: 1611270 Problem: Transition Prep Charge	Meter:	38024		In Date:	11/01/2016	Closed:	11/01/2016
Work Completed							
- Transition Prep Charge							
Hours: 2.00		Comm: 0.00	Labor: 120.00	Parts: 0.0	0	Total:	120.00
Work Order: 1612525 Problem: 1 - Detail Vehicle Wash Ticket(s) I	Meter: ssued	38454		In Date:	12/07/2016	Closed:	12/07/2016
Work Completed							
- 1 - Detail Vehicle Wash Ticket(s) Issued							
Hours: 0.00		Comm: 90.00	Labor: 0.00	Parts: 0.0	0	Total:	90.00

Work Order: 1612636 Problem: replace wipers	Meter:	38456		In Date:	12/09/2016	Closed:	12/14/2016
Work Completed			Parts Issued			Qı	uantity
- Ck Over Install wiper blades			Wiper Blade				1.00
			Accufit Beam				1.00
Hours: 0.50		Comm: 0.00	Labor: 30.00	Parts: 33.	18	Total:	63.18
Work Order: 1701441 Problem: P.M. service.	Meter:	42404		In Date:	02/10/2017	Closed:	02/28/2017
Work Completed			Parts Issued			Qı	uantity
- P.m. Service.			Napa Syn 5w30 Qt				6.00
- Replace two tires, rotate and balance all four.			Napagold Oil Filter				1.00
- Complete wheel alignment.test drive.			Tire				2.00
- Shop Supplies			Shop Supplies				1.00
			Tire Disposal Fee				2.00
Hours: 6.50		Comm: 0.00	Labor: 390.00	Parts: 592	2.46	Total:	982.46
Work Order: 1701730 Problem: 3 - Wash ticket(s) issued	Meter:	41040		In Date:	02/16/2017	Closed:	02/16/2017
Work Completed							
- 3 - Wash ticket(s) issued							
Hours: 0.00		Comm: 25.52	Labor: 0.00	Parts: 0.0	0	Total:	25.52

	1706087 P.M. Service	Meter:	48320		In Date:	06/20/2017	Closed:	06/30/2017
Work Con	npleted			Parts Issued			Qı	antity
- P.m. Serv	vice.			Napagold Oil Filter				1.00
- Pressure	e test and inspect cooling syster	m.flush and refill	l system.	Napa Quart 5w30		6.00		
- Repair o	ne tire, rotate and balance all fo	our.		Washer Fluid Concen	ntr			1.00
- Shop Su	pplies			Accufit Beam				1.00
				Wiper Blade				1.00
				Anti Freeze Motorcra	ıft			2.00
				Shop Supplies				1.00
	Hours: 6.00		Comm: 0.00	Labor: 360.00	Parts: 113	3.83	Total:	473.83
Work Con	Damage to left rear fender &							
	-							
	to left rear fender & rear bum	per on both side						
- Damage	to left rear fender & rear bum Hours: 0.00		Comm: 1,110.05	Labor: 0.00	Parts: 0.0			1,110.05
- Damage Work Order:	to left rear fender & rear bum Hours: 0.00	Meter:	Comm: 1,110.05 53128	Labor: 0.00	Parts: 0.0	0 10/16/2017		
- Damage Work Order:	to left rear fender & rear bump Hours: 0.00 1710136 P.M. service and tirepressure	Meter:	Comm: 1,110.05 53128	Labor: 0.00 Parts Issued			Closed:	
- Damage Work Order: Problem: Work Con	to left rear fender & rear bump Hours: 0.00 1710136 P.M. service and tirepressure	Meter: light on and rer	Comm: 1,110.05 53128				Closed:	10/19/201
- Damage Work Order: Problem: Work Con - P.m. serv	to left rear fender & rear bump Hours: 0.00 1710136 P.M. service and tirepressure	Meter: e light on and rer and retest.	Comm: 1,110.05 53128 mote inop at times.	Parts Issued			Closed:	10/19/201
- Damage Work Order: Problem: Work Con - P.m. serv - Resurfac	to left rear fender & rear bump Hours: 0.00 1710136 P.M. service and tirepressure npleted vice .replace battery in key fob a	Meter: e light on and rer and retest.	Comm: 1,110.05 53128 mote inop at times.	Parts Issued Napagold Oil Filter			Closed:	10/19/201 aantity 1.00
- Damage Work Order: Problem: Work Con - P.m. serv - Resurfac and bleed	to left rear fender & rear bump Hours: 0.00 1710136 P.M. service and tirepressure npleted vice .replace battery in key fob a se both front rotors.service fron	Meter: e light on and rer and retest. t calipers and re	Comm: 1,110.05 53128 mote inop at times. eplace pads .flush	Parts Issued Napagold Oil Filter Napa Quart 5w30	In Date:		Closed:	10/19/201 antity 1.00 6.00
- Damage Work Order: Problem: Work Con - P.m. serv - Resurfac and bleed	to left rear fender & rear bump Hours: 0.00 1710136 P.M. service and tirepressure npleted vice .replace battery in key fob a ce both front rotors.service fron brake system.test drive.	Meter: e light on and rer and retest. t calipers and re	Comm: 1,110.05 53128 mote inop at times. eplace pads .flush	Parts Issued Napagold Oil Filter Napa Quart 5w30 Napagold Air Filter	In Date:		Closed:	10/19/201 antity 1.00 6.00 1.00
- Damage Nork Order: Problem: Work Con - P.m. serv - Resurfac and bleed - Repair le	to left rear fender & rear bump Hours: 0.00 1710136 P.M. service and tirepressure npleted vice .replace battery in key fob a ce both front rotors.service fron brake system.test drive.	Meter: e light on and rer and retest. t calipers and re	Comm: 1,110.05 53128 mote inop at times. eplace pads .flush	Parts Issued Napagold Oil Filter Napa Quart 5w30 Napagold Air Filter Napa Cabin Air Filter	In Date:		Closed:	10/19/201 antity 1.00 6.00 1.00 1.00
- Damage Work Order: Problem: Work Con - P.m. serv - Resurfac and bleed - Repair le	to left rear fender & rear bump Hours: 0.00 1710136 P.M. service and tirepressure npleted vice .replace battery in key fob a ce both front rotors.service fron brake system.test drive.	Meter: e light on and rer and retest. t calipers and re	Comm: 1,110.05 53128 mote inop at times. eplace pads .flush	Parts Issued Napagold Oil Filter Napa Quart 5w30 Napagold Air Filter Napa Cabin Air Filter Accufit Beam	In Date:		Closed:	10/19/201 aantity 1.00 6.00 1.00 1.00 1.00
- Damage Work Order: Problem: Work Con - P.m. serv - Resurfac and bleed - Repair le	to left rear fender & rear bump Hours: 0.00 1710136 P.M. service and tirepressure npleted vice .replace battery in key fob a ce both front rotors.service fron brake system.test drive.	Meter: e light on and rer and retest. t calipers and re	Comm: 1,110.05 53128 mote inop at times. eplace pads .flush	Parts Issued Napagold Oil Filter Napa Quart 5w30 Napagold Air Filter Napa Cabin Air Filter Accufit Beam Wiper Blade	In Date:		Closed:	10/19/201 iantity 1.00 6.00 1.00 1.00 1.00 1.00 1.00
- Damage Work Order: Problem: Work Con - P.m. serv - Resurfac and bleed - Repair le	to left rear fender & rear bump Hours: 0.00 1710136 P.M. service and tirepressure npleted vice .replace battery in key fob a ce both front rotors.service fron brake system.test drive.	Meter: e light on and rer and retest. t calipers and re	Comm: 1,110.05 53128 mote inop at times. eplace pads .flush	Parts Issued Napagold Oil Filter Napa Quart 5w30 Napagold Air Filter Napa Cabin Air Filter Accufit Beam Wiper Blade Washer Fluid Concer	In Date:		Closed:	10/19/2013 antity 1.00 6.00 1.00 1.00 1.00 1.00 1.00 1.00

Work Order: 1800847 Meter: 58668 In Date: 01/24/2018 Closed: 01/29/2018 Problem: P.M .service and had to jump start. Parts Issued Quantity **Work Completed** Napa Quart 5w30 5.00 - P.m. service. Napagold Oil Filter 1.00 - Replace rear brake pads and resurface rear rotors and service calipers .test drive. 26in Exactfit-beam 1.00 - Test battery and charging system .battery failed load test.r&r with new 20in Exactfit-beam 1.00 battery. Washer Fluid Concentr 1.00 - Rotate and high speed balance all four tires. Rear Brake Pad 1.00 - Shop Supplies Battery 65 1.00 Shop Supplies 1.00 Hours: 7.00 Comm: 0.00 Parts: 277.03 Total: 697.03 Labor: 420.00 Work Order: 1808239 08/10/2018 Closed: 08/15/2018 Meter: 68598 In Date: Problem: PM Service Quantity **Work Completed** Parts Issued Napagold Oil Filter 1.00 - P.m. service. Napa Quart 5w30 6.00 - Rotate and high speed balance all four tires. Nitrofill. 20in Exactfit-beam 1.00 - Shop Supplies 26in Exactfit-beam 1.00 Shop Supplies 1.00 Hours: 3.00 Comm: 0.00 Labor: 180.00 Parts: 56.00 Total: 236.00 Work Order: 1808889 Meter: 68891 In Date: 08/28/2018 **Closed:** 08/28/2018 **Problem:** Transition Prep Charge Work Completed - Transition Prep Charge Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: Problem:	1808953 1 - Detail Vehicle Wash Ticket(s) Iss	Meter: sued	68942		In Date:	08/29/2018	Closed:	08/29/2018
Work Com	pleted							
- 1 - Detail	Vehicle Wash Ticket(s) Issued							
	Hours: 0.00		Comm: 90.00	Labor: 0.00	Parts: 0.0	0	Total:	90.00
Work Order: Problem:	1900928 pm service	Meter:	69553		In Date:	01/24/2019	Closed:	02/04/2019
Work Com	pleted			Parts Issued			Qı	antity
- Pm Servio	ce			Napagold Oil Filter				1.00
				Napa Quart 5w30				6.00
				Washer Fluid Concer	ntr			1.00
				26in Exactfit-beam				1.00
				20in Exactfit-beam				1.00
	Hours: 2.00		Comm: 0.00	Labor: 134.00	Parts: 57.	35	Total:	191.35
Work Order: Problem:	1905081 1 - Wash ticket(s) issued	Meter:	70123		In Date:	05/09/2019	Closed:	05/09/2019
Work Com	pleted							
- 1 - Wash	ticket(s) issued							
	Hours: 0.00		Comm: 8.34	Labor: 0.00	Parts: 0.0	0	Total:	8.34
Work Order: Problem:	1905387 1 - Detail Vehicle Wash Ticket(s) Iss	Meter: sued	70193		In Date:	05/17/2019	Closed:	05/17/2019
Work Com	pleted							
	Vehicle Wash Ticket(s) Issued							
- 1 - Detail	VEHICLE VVASIT FICKEL(S) ISSUEU							

Work Order: 1907259 Problem: pm service	Meter:	71126		In Date:	07/16/2019	Closed:	07/19/2019
Work Completed			Parts Issued			Qı	antity
- Pm Service			Napa Quart 5w30				6.00
			Napagold Oil Filter				1.00
			20in Exactfit-beam				1.00
			26in Exactfit-beam				1.00
Hours: 2.00		Comm: 0.00	Labor: 134.00	Parts: 55.	14	Total:	189.14
Nork Order: 1908224 Problem: transmission/ Dealer	Meter:	71601		In Date:	08/08/2019	Closed:	08/28/2019
Work Completed			Parts Issued			Qu	antity
- Diag. transmission; to dealer for trans replace	ement		oil auto				5.00
- Car wash							
- Top off fuel							
Hours: 8.50		Comm: 4,330.36	Labor: 569.50	Parts: 41.	33	Total:	4,941.18
Work Order: 1908657 Problem: transmission problem	Meter:	71544		In Date:	08/14/2019	Closed:	08/19/2019
Work Completed							
- Tow From: 2601 vista To: al packer trail							
Hours: 0.00		Comm: 96.00	Labor: 0.00	Parts: 0.0	0	Total:	96.00
Work Order: 1909009 Problem: 1 - Wash ticket(s) issued	Meter:	71601		In Date:	08/28/2019	Closed:	08/28/2019
Work Completed							
- 1 - Wash ticket(s) issued							
Hours: 0.00		Comm: 9.54	Labor: 0.00	Parts: 0.0	0	Total:	9.54
Nork Order: 1910730 Problem: driver side mirror	Meter:	72169		In Date:	10/18/2019	Closed:	10/28/2019
Work Completed			Parts Issued			Qu	antity
- Repl. left side mirror			Side Mirror				1.00
Hours: 1.00		Comm: 0.00	Labor: 73.00	Parts: 279	9.87	Total:	352.87

Work Order: Problem:	1912632 check key fob battery	Meter:	72564		In Date:	12/10/2019	Closed:	12/12/2019
Work Com								
- test and	replace key fob battery							
	Hours: 0.50		Comm: 0.00	Labor: 36.50	Parts: 0.0	0	Total:	36.50
Nork Order: Problem:	2000097 pm service	Meter:	72758		In Date:	01/03/2020	Closed:	01/28/2020
Work Com	pleted			Parts Issued			Qı	uantity
- pm servi	се			Napagold Oil Filter				1.00
•	ipper radiator hose, degas bot	tle, heater hose	service port line.	Napa Quart 5w30				6.00
refill test ru		,		Washer Fluid Conce	entr			1.00
- replace a	III 4 tires			26in Exactfit-beam				1.00
				20in Exactfit-beam				1.00
				Napagold Air Filter				1.00
				Anti Freeze Motorc	raft			2.00
				255/45r19 100v Mid	c Primacy Mx	m4		4.00
				Hose	-			1.00
				Rad Hose				1.00
				Rad Hose				1.00
				Tire Disposal Fee				4.00
	Hours: 8.00		Comm: 0.00	Labor: 584.00	Parts: 1,8	17.51	Total:	2,401.51
Work Order: Problem:	2003628 1 - Detail Vehicle Wash Ticke	Meter: et(s) Issued	73744		In Date:	04/10/2020	Closed:	04/10/2020
Work Com	pleted							
- 1 - Detai	l Vehicle Wash Ticket(s) Issued							
	Hours: 0.00		Comm: 90.00	Labor: 0.00	Parts: 0.0	0	Total:	90.00

1/13/2025	
9:22:17 AM	

Work Order:		Meter:	74452		In Date:	05/07/2020	Closed:	05/22/2020
Problem:	check eng light on							
Work Com	pleted							
- check for	r codes, no problem found							
	Hours: 0.50		Comm: 0.00	Labor: 36.50	Parts: 0.0	0	Total:	36.50
Work Order:		Meter:	75816		In Date:	06/29/2020	Closed:	06/29/2020
Problem:	1 - Wash ticket(s) issued							
Work Com	pleted							
- 1 - Wash	ticket(s) issued							
	Hours: 0.00		Comm: 9.54	Labor: 0.00	Parts: 0.0	0	Total:	9.54
Work Order: Problem:	2006795 pm service	Meter:	75820		In Date:	07/13/2020	Closed:	07/28/2020
Work Com	pleted			Parts Issued			Qı	antity
- pm servio	ce			Napa Quart 5w30				6.00
- rotate an	nd balance all 4 tires			Napagold Oil Filter				1.00
				20in Exactfit-beam				1.00
				26in Exactfit-beam				1.00
				Napagold Air Filter				1.00
	Hours: 3.00		Comm: 0.00	Labor: 219.00	Parts: 62.	60	Total:	281.60
Work Order: Problem:	2012156 1 - Detail Vehicle Wash Ticket(s	Meter: s) Issued	79042		In Date:	12/07/2020	Closed:	12/07/2020
Work Com	pleted							
- 1 - Detail	l Vehicle Wash Ticket(s) Issued							

Nork Order: 2100 Problem: pm s		Meter:	79314		In Date:	01/11/2021	Closed:	01/26/202
Work Complete	d			Parts Issued			Qı	antity
- Preventive Ma	int. Service			Napa Quart 5w30				6.00
- Rotate and hig	h speed balance four tires. Nitro	o fill all.		Napagold Oil Filter				1.00
- Repair front ai	r dam and secure driver front ur	nper		20in Exactfit-beam				1.00
- top off loaner				26in Exactfit-beam				1.00
				Washer Fluid Concer	ntr			1.00
	Hours: 5.00		Comm: 0.00	Labor: 365.00	Parts: 57.	72	Total:	422.72
Nork Order: 2102 Problem: had	2048 to jump start several times	Meter:	79984		In Date:	02/23/2021	Closed:	03/09/202
Work Complete	d			Parts Issued			Qı	antity
- Check Had To System	Jump Start, Load Test And Repla	ace Batter	y, Check Charging	Battery				1.00
5	Hours: 1.00		Comm: 0.00	Labor: 73.00	Parts: 188	3.82	Total:	261.82
Nork Order: 2107 Problem: pm/	7499 Safety Recall 20S63/20V-692 -	Meter: Support B		ive Axle Half Shaft	In Date:	07/12/2021	Closed:	08/20/202
Work Complete	d			Parts Issued			Qı	antity
- Preventive Ma	int. Service			Napa Quart 5w30				6.00
	afety Recall 20s63/20v-692 - Suj	pport Brac	ket for Front Drive	Napagold Oil Filter				1.00
Axle Half Shaft								
Axle Half Shaft				Washer Fluid Concer	ntr			1.00
Axle Half Shaft				Washer Fluid Concer 26in Exactfit-beam	ntr			1.00 1.00
Axle Half Shaft					ıtr			
Axle Half Shaft				26in Exactfit-beam	ntr			1.00
Axle Half Shaft	Hours: 4.00		Comm: 0.00	26in Exactfit-beam 20in Exactfit-beam	ntr Parts: 51.	05	Total:	1.00 1.00
	642	Meter:		26in Exactfit-beam 20in Exactfit-beam Wd40 Spr		05 10/28/2021		1.00 1.00 1.00 343.05
Work Order: 2111	642 er headlight out			26in Exactfit-beam 20in Exactfit-beam Wd40 Spr	Parts: 51.		Closed:	1.00 1.00 1.00 343.05
Work Order: 2111 Problem: drive Work Complete	642 er headlight out			26in Exactfit-beam 20in Exactfit-beam Wd40 Spr Labor: 292.00	Parts: 51.		Closed:	1.00 1.00 1.00 343.05 10/29/202
Work Order: 2111 Problem: drive Work Complete	642 er headlight out d	Meter:		26in Exactfit-beam 20in Exactfit-beam Wd40 Spr Labor: 292.00 Parts Issued	Parts: 51.	10/28/2021	Closed: Qu	1.00 1.00 343.05 10/29/202*

Work Order: 2200040 Problem: making a loud noise/ pm	Meter:	82760		In Date:	01/03/2022	Closed:	01/07/2022
Work Completed			Parts Issued			Qı	uantity
- Preventive Maint. Service			Napa Quart 5w30				6.00
- Diag "noise", Replace Engine Both Mounts			Napagold Oil Filter				1.00
			Washer Fluid Concer	ntr			1.00
			26in Exactfit-beam				1.00
			20in Exactfit-beam				1.00
			Housing				1.00
			Bracket				1.00
Hours: 6.00		Comm: 0.00	Labor: 438.00	Parts: 188	3.28	Total:	626.28
Work Order: 2204723 Problem: 1 - Detail Vehicle Wash Ticket(s) Iss	Meter: sued	84593		In Date:	04/29/2022	Closed:	04/29/2022
Work Completed							
- 1 - Detail Vehicle Wash Ticket(s) Issued							
Hours: 0.00		Comm: 84.75	Labor: 0.00	Parts: 0.0	0	Total:	84.75
Work Order: 2205629 Problem: 1 - Detail Vehicle Wash Ticket(s) Iss	Meter: sued	84984		In Date:	05/25/2022	Closed:	05/26/2022
Work Completed							
- 1 - Detail Vehicle Wash Ticket(s) Issued							
Hours: 0.00		Comm: 84.75	Labor: 0.00	Parts: 0.0	0	Total	84.75

Work Order: 2206615 Problem: pm service	Meter:	85243		In Date:	06/24/2022	Closed:	07/15/2022
Work Completed			Parts Issued			Qı	uantity
- Preventive Maint. Service			Napa Quart 5w30				6.00
- Rotate, High Speed Balance,	And Nitro Four Ties		Napagold Oil Filter				1.00
- Repair Front And Rear Bump	per Valance		Napagold Air Filter				1.00
			Washer Fluid Concer	ntr			1.00
			26in Exactfit-beam				1.00
			20in Exactfit-beam				1.00
Hours: 4.	00	Comm: 0.00	Labor: 292.00	Parts: 60.	09	Total:	352.09
Work Order: 2210898 Problem: check engine light	Meter:	86530		In Date:	10/25/2022	Closed:	11/08/2022
Work Completed							
- Computer Scan, P219a. Ck C	over And Road Test. Npf						
Hours: 1.	00	Comm: 0.00	Labor: 73.00	Parts: 0.0	0	Total:	73.00
Work Order: 2211844 Problem: check eng light on	Meter:	86687		In Date:	11/22/2022	Closed:	12/01/2022
Work Completed							
- Scan With Computer, Histor	y Code Large Evap Leak, Te	st, Test Drive, No)				
Problems Found							

Work Order: Problem:	2212772 pm/ Front right window inop	Meter:	86791		In Date:	12/21/2022	Closed:	01/06/2023
Work Com	npleted			Parts Issued			Qu	antity
- Preventiv	ve Maint. Service			Silicone Protectant/I	ubricant			1.00
- Replaced	d Passenger Front Window Regulat	or And Moto	or	Napagold Oil Filter				1.00
·	с с			Napa Quart 5w30				6.00
				Washer Fluid Concer	ntr			1.00
				Window Regulator				1.00
				Window Motor				1.00
	Hours: 3.50		Comm: 0.00	Labor: 255.50	Parts: 214	.65	Total:	470.15
Work Order: Problem:	2301854 1 - Detail Vehicle Wash Ticket(s)	Meter: Issued to: F			In Date:	02/24/2023	Closed:	02/24/2023
Work Com	npleted							
- 1 - Detai	il Vehicle Wash Ticket(s) Issued to:	Fleet						
	Hours: 0.00		Comm: 84.75	Labor: 0.00	Parts: 0.0	0	Total:	84.75
Work Order: Problem:	2303341 Damage to left rear fender	Meter:	87223		In Date:	02/28/2023	Closed:	04/04/2023
Work Com	npleted							
- Damage	to left rear fender							
	Hours: 0.00		Comm: 1,155.99	Labor: 0.00	Parts: 0.0	0	Total:	1,155.99
				Eabol: 0.00				
		Meter:			In Date:	06/20/2023		06/30/2023
	2306041 pm service	Meter:		Parts Issued		06/20/2023	Closed:	06/30/2023 antity
Problem: Work Com	2306041 pm service	Meter:				06/20/2023	Closed:	
Problem: Work Com	2306041 pm service	Meter:		Parts Issued		06/20/2023	Closed:	antity
Problem: Work Com	2306041 pm service	Meter:		Parts Issued Napa Quart 5w30	In Date:	06/20/2023	Closed:	antity 6.00
Problem: Work Com	2306041 pm service	Meter:		Parts Issued Napa Quart 5w30 Napagold Oil Filter	In Date:	06/20/2023	Closed:	6.00
Work Com	2306041 pm service	Meter:		Parts Issued Napa Quart 5w30 Napagold Oil Filter Washer Fluid Concer	In Date:	06/20/2023	Closed:	6.00 1.00 1.00

Work Order: 2307620 Problem: over heating	Meter: 88519		In Date:	07/31/2023	Closed:	08/09/2023
Work Completed		Parts Issued			Qı	uantity
- diagnose over heat - found leaking water	pump - replace water pump	Water Pump				1.00
service coolant - bleed coolant system and t		Px Grey Rtv Silicor	ne			1.00
- Stock Parts entry		Coolent				2.00
		Non-chlor Brake C	Clnr			2.00
Hours: 3.00	Comm: 0.00	Labor: 219.00	Parts: 109	9.03	Total:	328.03
Nork Order: 2307884 Problem: 1 - Detail Vehicle Wash Ticket(s	Meter: 88519) Issued to: dispatch		In Date:	08/08/2023	Closed:	08/08/202
) Issued to: dispatch		In Date:	08/08/2023	Closed:	08/08/2023
Problem: 1 - Detail Vehicle Wash Ticket(s Work Completed) Issued to: dispatch	Labor: 0.00	In Date: Parts: 0.0			08/08/2023 84.75
Work Completed - 1 - Detail Vehicle Wash Ticket(s) Issued to:) Issued to: dispatch	Labor: 0.00			Total:	08/08/2023 84.75 08/24/2023
Problem: 1 - Detail Vehicle Wash Ticket(s Work Completed - 1 - Detail Vehicle Wash Ticket(s) Issued to: Hours: 0.00 Nork Order: 2308445) Issued to: dispatch dispatch Comm: 84.75	Labor: 0.00	Parts: 0.0	0	Total:	84.75
Problem: 1 - Detail Vehicle Wash Ticket(s Work Completed - 1 - Detail Vehicle Wash Ticket(s) Issued to: Hours: 0.00 Vork Order: 2308445 Problem: check engine light/ FL tire low) Issued to: dispatch comm: 84.75 Meter: 88625		Parts: 0.0	0	Total:	84.75
Problem: 1 - Detail Vehicle Wash Ticket(s Work Completed - 1 - Detail Vehicle Wash Ticket(s) Issued to: Hours: 0.00 Nork Order: 2308445 Problem: check engine light/ FL tire low Work Completed) Issued to: dispatch c dispatch Comm: 84.75 Meter: 88625 - no problems found - test o		Parts: 0.0	0	Total:	84.75

Work Order:2309444Meter:88850Problem:engine races first 1/2 hour/ back up camera inop

In Date: 09/18/2023 **Closed:** 10/05/2023

Work Completed		Parts Issued		Quantity
- Check Engine Races For First 1/2 Hour, Tes	Cover		1.00	
- Replaced Squeaking Drive Belts		Clip Ret		4.00
- C/s Back Up Camera Is Innop, Verified Cam	nera Works Intermittently,	Bumper Lip		1.00
Replaced Back Up Camera				2.00
- Replaced L/f Inner Fender Liner, Replaced	Back-up Camera		1.00	
Replaced Front Bumper Splash Shield, Replace	ced Bottom Lip On Front	Idler Pulley		1.00
Bumper		V-belt		1.00
- Repaired 1 Tire		A/c Belt		1.00
		Belt		1.00
		Deflector		1.00
		Guard		1.00
Hours: 5.00	Comm: 0.00	Labor: 365.00	Parts: 866.29	Total: 1,231.29
/ork Order: 2311486	Meter: 89154		In Date: 11/16/202	3 Closed: 12/15/202

Comm: 0.00

Problem: overheat light came on/ AC intermittent

Work Completed

- C/s Overheat Light Came On, Replaced Thermostat, Flushed Cooling System

- C/s Ac Intermittent, Replaced Evaporator Core

Hours: 14.50

- Pm Service

Parts Issued		Quantity
Peak Global Antifrz		1.00
Thermostat		1.00
Evaporator		1.00
Kit O		1.00
Napa Quart 5w30		6.00
Napagold Oil Filter		1.00
20in Exactfit-beam		1.00
26in Exactfit-beam		1.00
Labor: 1,058.50	Parts: 440.80	Total: 1,499.30

1/13/2025	
9:22:18 AM	

Work Order:	2400287	Meter:	89245		In Date:	01/09/2024	Closed:	01/10/2024
Problem:	under cowling coming off							
Work Com	pleted							
- Secure Fr	ont Lower Valance That Came O	ff						
	Hours: 1.00		Comm: 0.00	Labor: 73.00	Parts: 0.0	0	Total:	73.00
Work Order:	2400660	Meter:	89342		In Date:	01/22/2024	Closed:	01/23/2024
Problem:	low tire pressure							
Work Com	pleted							
- Repair Ti	re And Reset Tpm							
	Hours: 1.00		Comm: 0.00	Labor: 73.00	Parts: 0.0	0	Total:	73.00
Work Order: Problem:	2405395 pm service	Meter:	91859		In Date:	05/31/2024	Closed:	06/06/2024
Work Com	pleted			Parts Issued			Qı	antity
- Preventiv	e Maint. Service			Napagold Oil Filter				1.00
- Rotate, H	ligh Speed Balance, And Nitro Fo	our Tires		Napa Quart 5w30				6.00
				Washer Fluid Concer	ntr			1.00
				20in Exactfit-beam				1.00
				26in Exactfit-beam				1.00
	Hours: 3.00		Comm: 0.00	Labor: 219.00	Parts: 55.	84	Total:	274.84
Work Order: Problem:	2405573 1 - Detail Vehicle Wash Ticket(s	Meter: s) Issued to: D			In Date:	06/05/2024	Closed:	06/06/2024
Work Com	pleted							
- 1 - Detail	Vehicle Wash Ticket(s) Issued to	: Dispatch						

1/13/2025 9:22:18 AM	F	alm Beach County Fleet Manag 10196720 2015 FOR	D TAURUS Car, Full S			
Work Order: 2406433	Met	er: 92221		In Date: 07/0)3/2024 Closed:	07/31/2024
Problem: check engi	ne light					
Work Completed			Parts Issued		Q	uantity
- C/s Check Engine Light Is On, P219a Code Air/fuel Ratio Imbalance,			Spakplug			4.00
1 1 5		de No Change To Fuel Trim	Separator			1.00
Numbers, Further Diag	Needed		Gasket			1.00
Н	ours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 112.99	Total:	258.99
Nork Order: 2407811 Problem: Transition		er: 92221		In Date: 08/1	4/2024 Closed:	08/14/2024
Work Completed						
- Transition Prep Char	ge					
н	ours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 0.00	Total:	146.00
Fotal Hours: 149.00	Total Labor	: 9.996.00	Total Comm: 8,2	20.92 Tota	al Parts: 7,909.64	